

1 Local Configuration File ctaip.ini

The most important hardware and system settings are defined for each terminal in the CTAIP.INI file of the c:\ctaip directory.



Changes to the configuration file ctaip.ini are only enabled after rebooting the terminal software.

1.1 Basic configuration

Entry	Comment
Section [system]	

Entry	Comment
Section [system]	
Usr=21	Distinct terminal number
Hypath=d:\hydra\ Hypath=/usr/hydra/	HYDRA server path: Windows NT: -> DOS notation, the drive is the local drive of the server on which HYDRA or xMES is installed Unix: -> Unix notation
Hostname=192.9.200.24	Internet address of the server
Offlinetimeout=600	In offline mode, the interval after which online access should be attempted the next time. The interval is specified in seconds
Showcursor=on	Show or hide mouse pointer in terminal application: on: mouse pointer active off: mouse pointer inactive
Loadfile=ctnet\win\ctaip.txt	Configuration file for downloading the application from the server. The path is relative to the server directory (i.e. within "hypath")
Watchdog=on	ON: Watchdog is activated OFF: Watchdog is not activated
Demo=off	'on': Offline demo mode; always off in the production environment
parameters=-t	The -t parameter switches off the virtual keyboard
TMOUT_C=xxx	Timeout for CONNECT to the server If not specified, default = 10 seconds → Increase to 20 seconds for routing
TMOUT_S=xxx	Timeout for SEND to the server If not specified, default = 10 seconds → Increase to 20 seconds for routing
TMOUT_R=xxx	Timeout for RECEIVE of the server If not specified, default = 120 seconds

Entry	Comment
TMOUT_F=xxx	Timeout for FILESERVER operations to the server If not specified, default = 10 seconds → Increase to 20 seconds for routing
Section [barcode]	Configuration of customized barcode prefixes.
BarKenn90=MNR4 ... BarKenn99=ANR3	BarKenn90 > defines the prefix (here: 90); The ID from the dialog (= acronym) is assigned.
Section [comports]	
Com1=0 com2=MSS com3=BAR Com3=LEGIC Com4=RFLESER	Assignment of serial interfaces to the connected devices MSS – machine interface BAR, LEGIC, RFLESER – various reading devices
Section [MSS-INIT]	
ZAEHLER= 1 2 3 4 5 6 7 8	Assignment of physical inputs of the MSS (machine interface) to logical counters (ZAEHLER) according to configuration: The first connector (labeled “0” on the MSS) corresponds to the logical counter no. 1 Please note: MSS1 has only 8 inputs If digital inputs are also to be used with MSS1, configuration should be changed as follows: ZAEHLER= 1 2 3 4 IN= 5 6 7 8
IN= 9 10 11 12 13 14 15	Assignment of physical MSS inputs to logical inputs as per configuration: The ninth connector (labeled “8” on the MSS) corresponds to the logical input no. 1
CHARGE= 5 6	For batch recording: Inputs for automatic batch changes In this case, the connectors 5 and 6 are the inputs for the automatic batch change.
MSSZyklusBerechnung=ON MSSZyklusReferenz=0	Activates reading out of cycle time values from the machine interface (MSS). Reference for cycle calculation (smallest time unit of the MSS). The default value is 0, if the parameter is not specified. 0 corresponds to 100 ms. 2 corresponds to 20 ms.
CalculateCycle=ON	The terminal itself calculates the actual cycle. If the connected control does not provide a determined actual cycle, then a calculated actual cycle can be displayed: This calculated value is also available for DS100 terminals. Please note: The calculation cannot provide exact values.
WochenEnde_ProdCheck=ON	This function prevents the weekend automatic from affecting the “production” status and the workplace from being set to status 999. ON is set by default In case WochenEnde_ProdCheck=OFF, the automatism switches to status 999.

Entry	Comment
sFrom999ToNotAttributed=OFF	Only affects HYDRA-MDE machines with operation mode = "no monitoring". If the weekend automatic function is enabled this option prevents the machine from switching to the "not assigned" status when the weekend automatic ends. Reasons: The "not assigned" status may not be set manually for machines that are configured with the "no monitoring" option. The "not assigned" status is normally only set for machines with operation mode = "cyclic monitoring" or "monitoring by operating signal".
Section [ext. software]	
Button=Editor WindowName=Editor SearchParts=On	Configuration of the button in the top line: A previously started program can be called to the foreground at the push of a button. Button: button caption WindowName: Name of the program (e.g. from the taskbar). SearchParts=On: parts of WindowName are sufficient SearchParts=Off: WindowName must be entered completely. The option "SearchParts=On" is recommended for programs such as MSWord that change the title bar subject to the document that is currently being loaded.
ProgFileName=c:\Programme\wincmd\Wincmd32.exe	The program that is started if the program mentioned above cannot be called to the foreground.
AutoStart=on	This option starts the program (ProgFileName) when starting the terminal program.
Section [PDV]	
Modus=PDV Modus=PDV,BDE	Operation as interface IOP↔DOS terminal (standard) Operation as shop floor terminal with PDV
Terminals=121,122,123	CTDOS terminals "connected" by LAN. Only required with Mode=PDV
PDVTerminalDir=c:\hsrv\spool\ PDVIOPTDir=c:\IOPSim\	Directory for communication with CTDOS terminals Directory for communication with the IOP
For debug purposes only: InfoFenster=100 SlowDown=600	Number of lines of the "current" window (presentation of last PDV actions) Slow down, to make events "visible"
;Supported barcodes	
FieldWNRBarcodeOnly=Y	If this entry is set the tool number may only be entered using a scanner.
FieldNestBarcodeOnly=Y	If this entry is set the cavity number may only be entered using a scanner.
FieldNummBarcodeOnly=Y	If this entry is set the number may only be entered using a scanner.
FieldKNRBarcodeOnly=Y	If this entry is set the badge number may only be entered using a scanner.
BarcodeWNR=	This field specifies which acronym is entered into the tool number field by the scanner.

Entry	Comment
BarcodeNest=	This field specifies which acronym is entered into the cavity number field by the scanner.
BarcodeNumm=	This field specifies which acronym is entered into the number field by the scanner.