VICTA

DATE: 11/11/65

# SERVICE BULLETIN NO. 51

ADDENDUM "A"

THIS ADDENDUM CLARIFIES THE APPLICATION OF SERVICE BULLETINS NO. 51 AND NO. 20.

Service Bulletin No. 51, issue 1 cancelled Service Bulletin No. 20, issue 2. However, Service Bulletin No. 20, issue 3 was later inadvertently issued, but only repeated information already contained in Service Bulletin 51, issue 2.

For this reason, Service Bulletin No. 51, issue 2 is to be considered as current, and any reference to Service Bulletin No. 20, issue 3 be altered to Service Bulletin 51, issue 2.

D.C.A. APPROVED

AVIATION DIVISION

NORSLEY ROAD, MILPERRA, N.S.W., AUSTRALIA.

VICSTA

DATE: 26.2.65

# SERVICE BULLETIN NO. 52

SUBJECT: Installation of cooling shroud around fuel filter and re-routing of engine compartment fuel lines (Mod. No. B216.)

PURPOSE: To prevent low indicated fuel pressure during take-off in high ambient temperature conditions.

REASON: Service experience has shown that during hot weather operation, fuel pressure indication may fall to zero during take-off.

EQUIPMENT AFFECTED: Airtourer 100 (all aircraft)

COMPLIANCE: Within next 25 hours flying.

DETAILS: Refer to rework drawing No. 02-03115.

(i) Remove propeller and cowls as detailed in chapters 31 and 41 of the maintenance manual.

(ii) Remove filter.

(iii) Fit drip tray, part No. 02-35000/2.

(iv) Replace filter using gasket (part No. 02-48036/1 between mounting flange and firewall.

(v) Fit filter shroud assembly (part No. 02-35002/1).

(vi) Re-route and clip the pressure line from the electric fuel pump and the delivery line to the engine driven pump as shown.

(vii) Plug the centres of all the "pop" rivets through the firewall with Selley's Fireproof putty or other approved fireproofing compound.

(viii) With the electric fuel pump on, loosen flexible line connection at the carburettor inlet and allow pump to clear all air from the filter. Remove this flexible line from the carburettor inlet and check that the electric pump will deliver one imperial pint in less than 25 seconds. For low output check suction side for leaks and check pump condition. Re-connect flexible line to carburettor.

(ix) Refit cowl and propeller.

(x) Fit scoop (part No. 02-44024/1) and duct assembly (part No. 02-44025/1). Cut hole through fibre-glass cowl as shown.

(xi) Fit flexible ducting and clip at each end.

(xii) Run engine and check for leaks.

(xiii) Paint finish external parts as required.



AVIATION DIVISION

MORGLEY ROAD, MILPERRA, N.S.W., AUSTRALIA.

PARTS REQUIRED: Mod kit B216/1 consisting of:-

| PART NO. | DESCRIPTION | NO. OFF |
|---|---|---|
| 02-44024/1 | Scoop Assembly | 1 |
| 02-33025/1 | Duct Assembly | 1 |
| HOS4-C32-70 | Flexible duct | 1 |
| 02-42006/1 | Bracket - stand off | 1 |
| 02-35000/2 | Drip tray | 1 |
| CLI4-9 | Hose clips | 2 |
| TPL/0429BS | Rivet "pop" $\frac{1}{8}$" dia. | 26 |

PARTS REMOVED:

| PART NO. | DESCRIPTION | NO. OFF |
|---|---|---|
| AN 742-14C | Clamp | 2 |

DRAWINGS REQUIRED: Drawing No. 02-03115 Retrofit - fuel filter cooling.

SPECIAL TOOLS REQUIRED: Nil

EFFECT ON WEIGHT & C.G. Nil

PUBLICATIONS EFFECTED: Nil

LABOUR INVOLVED: 3 manhours.

D. C. A. APPROVED.



AVIATION DIVISION HORSLEY ROAD, MILPERRA, N.S.W., AUSTRALIA.

WIGTA

DATE:

# SERVICE BULLETIN NO.

AVIATION DIVISION

MORSLEY ROAD, MILPERRA, N.S.W., AUSTRALIA.

WICKA

DATE: 3.3.65

# SERVICE BULLETIN NO. 53

SUBJECT: Installation of cooling shroud around fuel filter (Mod.No.B216.)

PURPOSE: To prevent possibility of low indicated fuel pressure during take-off in high ambient temperature conditions.

REASON: Service experience has shown that in the AT 100 during hot weather operation, fuel pressure indication may fall to zero during take-off. As the fuel systems of the Airtourer 100 and 115 are similar, the modification is proposed for the Airtourer 115 also.

EQUIPMENT AFFECTED: Airtourer 115 (all aircraft)

COMPLIANCE: Within next 25 hours flying.

DETAILS: Refer to rework drawing No. 02-03115.

(i) Remove propeller and cowls as detailed in chapters 31 and 41 of the maintenance manual.

(ii) Remove filter.

(iii) Fit drip tray, part No. 02-35000/2.

(iv) Replace filter using gasket (part No. 02-48036/1 between mounting flange and firewall.

(v) Fit filter shroud assembly (part No. 02-35002/1).

(vi) Plug the centres of all the "pop" rivets through the firewall with Selleys Fireproof putty or other approved fireproofing compound.

(vii) With the electric fuelpump on, loosen flexible line connection at the carburettor inlet and allow pump to clear all air from the filter. Remove this flexible line from the carburettor inlet and check that the electric pump will deliver one imperial pint in less than 25 seconds. For low output check suction side for leaks and check pump condition. Re-connect flexible line to carburettor.

(viii) Refit cowl and propeller.

(ix) Fit scoop (part No. 02-44024/1) and duct assembly (part No. 02-44025/1). Cut hole through fibre-glass cowl as shown.

(x) Fit flexible ducting and clip at each end.

(xi) Run engine and check for leaks.

(xii) Paint finish external parts as required.



AVIATION DIVISION HORSLEY ROAD, MILPERRA, N.S.W., AUSTRALIA.

VICTA

DATE: 3.3.65

# SERVICE BULLETIN NO. 53.

PARTS REQUIRED: Mod Kit E216/2 consisting of:-

| PART NO. | DESCRIPTION | NO. OFF |
|---|---|---|
| 02-44024/1 | Scoop Assembly | 1 |
| 02-33025/1. | Duct Assembly | 1 |
| H034-032-70 | Flexible duct | 1 |
| 02-35000/2 | Drip tray | 1 |
| CL14-9 | Hose clips | 2 |
| TPL/0429BS | Rivet "pop" ⅛" dia. | 26 |

PARTS REMOVED: Nil.

DRAWINGS REQUIRED: Drawing No. 02-03115 Retrofit - fuel filter cooling.

SPECIAL TOOLS REQUIRED: Nil.

EFFECT ON WEIGHT & C.G: Nil.

PUBLICATIONS AFFECTED: Nil.

LABOUR INVOLVED: 3 manhours.

D.C.A. APPROVED.



AVIATION DIVISION NORSLEY ROAD, MILPERRA, N.S.W., AUSTRALIA.

VICTA

DATE: 3.65.

# SERVICE BULLETIN NO. 53

Amendment

AMENDMENT TO SERVICE BULLETIN No. 53.

| | | |
|---|---|---|
| Para (ii) | to read: | Remove Filter E replace existing union at base of filter with AN-822-2. |
| Para (v) | to read: | Cut Spring Clip Hinge Pin supplied with shroud into halves and loop ends. Re-assemble shroud assembly and fit half hinge pins. Lockwire pins through loops. |

ADD TO PARTS LIST: AN-822-2 UNION 90° 1 OFF

D.C.A. APPROVED.

AVIATION DIVISION

HORSLEY ROAD, MILPERRA, N.S.W., AUSTRALIA.

WICTA

DATE: 9th April,

# SERVICE BULLETIN NO. A.54

SUBJECT: Mandatory Inspection of Nose Leg Spring Characteristics.

EQUIPMENT AFFECTED: All Airtourer 115 Aircraft.

REASON: Springs of incorrect load rating may have been fitted in production.

CONFIGURATION: Empty aircraft with no occupants or luggage.

INSPECTION:

(1) With propeller in vertical position and the aircraft on hard level ground, raise nose wheel clear of ground by 3". It is suggested that this be done by pushing down on the tailplane.

(2) Release aircraft and allow to settle.

(3) Measure clearance of propeller tip from ground and record.

(4) Repeat this procedure three times to even out the effects of friction.

(5) Remove spinner and hang 100 lb. weight on crankshaft behind propeller.

(6) Repeat the previous test three (3) times again measuring the propeller ground clearance.

(7) If the difference between propeller ground clearance with and without the weight exceeds 4" an incorrect spring has been fitted.

(8) The spring should be replaced at the first 100 hrs. and the Victa Service Department should be contacted for the replacement component.

(9) Meanwhile continued operation should be carried out using some caution. The following types of operation should be avoided if possible.

(a) Run ups exceeding 1800 rpm on brakes - elevator must be held in full up position in this configuration.

(b) Sudden application of brakes particularly on uneven ground.

NOTE: As the softness of the nose spring is only considered a problem under slowly applied loads, this commonsense approach will ensure satisfactory operation until the spring is replaced.

D.C.A. Approved.

E. Barden.

VICTA

DATE: 9th Apri

# SERVICE BULLETIN NO. A.54

SUBJECT: Mandatory Inspection of Nose Leg Spring Characteristics.

EQUIPMENT AFFECTED: All Airtourer 115 Aircraft.

REASON: Springs of incorrect load rating may have been fitted in production

CONFIGURATION: Empty aircraft with no occupants or luggage.

INSPECTION:

(1) With propeller in vertical position and the aircraft on hard level ground, raise nose wheel clear of ground by 3". It is suggested that this be done by pushing down on the tailplane.

(2) Release aircraft and allow to settle.

(3) Measure clearance of propeller tip from ground and record.

(4) Repeat this procedure three times to even out the effects of friction.

(5) Remove spinner and hang 100 lb. weight on crankshaft behind propeller.

(6) Repeat the previous test three (3) times again measuring the propeller ground clearance.

(7) If the difference between propeller ground clearance with and without the weight exceeds 4" an incorrect spring has been fitted.

(8) The spring should be replaced at the first 100 hrs. and the Victa Service Department should be contacted for the replacement component.

(9) Meanwhile continued operation should be carried out using some caution. The following types of operation should be avoided if possible.

(a) Run ups exceeding 1800 rpm on brakes - elevator must be held in full up position in this configuration.

(b) Sudden application of brakes particularly on uneven ground.

NOTE: As the softness of the nose spring is only considered a problem under slowly applied loads, this commonsense approach will ensure satisfactor operation until the spring is replaced.

D.C.A. Approved.

E. Barden.