Complaint Number:





# Report 8D

Generated By: Christine Hulme Generated On: 16 Nov 2011

### I. COMPLAINT INFORMATION

Origination Date	20 Oct 2011		
Sales Name	Mark Jones	Sales Office	Ashton
Telephone	07919005137	Fax Number	
Email	mark.jones@scapa.com		
Customer Complaint Ref			
Customer Name	Finesse Medical Ltd		
SAP Customer Number	125449	Customer Order N°	
Customer Part Number			
1) Invoices And Items	s On Complaint		
(a) SAP Invoice Number	9100222942	Invoice Date	19 Apr 2010
- Material	150715	Batch	
	Material Description		
	M6016/877 slit roll 225mm x 1m		
(b) SAP Invoice Number	9100245810	Invoice Date	14 Jul 2011
- Material	150715	Batch	
	Material Description M6016/877 slit roll 225mm x 1m		1

### 2) Problem Description

 $FM625\ 473700\ B081\ B083\ 380mts\ 1895108\ -\ visible\ contamination\ under\ PU\ film\ side\ of\ each\ roll.$ 

FM893 552605 C092 C096 C178 C179 1,000mts 2046141 - 5 rolls have a line running through the material. Line is a straight non-adhered normally running parallel to edge of roll.

Actions	Requested	From	The	Customer

3) Containment Actions

# II. EVALUATION AND ACTION

Sample/photo Received	No					
Date						
Process Owner	Christine Hulme					
Team Leader	jmangan					
Is Complaint Valid?	Yes Return The Goods	No	Dispose The Goods	Yes		
Comments						
1) Analysis						
	v what appear to be dust particles on the adhe	esive side of the film. Some san	nples show what is a dry			
line in the adhesive coating						
Author	John Mangan	Date	15 Nov 2011			
2) Root Causes						
The contamination could be from a number of sources.  Lines in the adhesive are caused by debris or and obstruction in the coating head. This can be due to adhesive gelling up in the coating head or dust/debris from the carrier being coated entering the coating head.						
Author	John Mangan	Date	15 Nov 2011			
3) Possible Solutions						
Author		Date				
	0 " 1 "					
4) Implemented Perm	1 Corrective Actions					
Since the production of this batch, new cleaning schedules have been introduced and implemented. The standard of cleanliness has						
been raised and the likely causes of contamination have been reduced.						
There is no immediate corrective action for lines in the adhesive, as the root cause is not truely understood and it is not as						
simple as filters on the adhesive line as there is a number of methods for debris to enter the coating head.						
Author	John Mangan	Date	15 Nov 2011			
Estimated Date		Implementation Date				
Validation Date						
5) Corrective Actions Validation						
Complaints about contamin	ation are not as common, improvement in cle	aing and cleaning schedules is	continuing.			
Author	John Mangan	Date	15 Nov 2011			

# 6) Preventive Actions

Author		Date		
Estimated Date		Implementation Date		
Validation Date				
Validation Date				
7) Review Of Docum	entation			
•				
(a) MSR				
	No			
Reviewed?	No			
Reference		Date		
receive		Bate		
(b) Flow chart, control plan	n, work inspection instructions			
Reviewed?	No			
Reference		Date		
Releielice		Date		
(c) FMEA				
Reviewed?	No			
Reference		Date		
(d) Customer angelification				
(d) Customer specification				
Reviewed?	No			
Reference		Date		

8) Congratulate The Team