

# Rapport 8D

Généré Par: Sylviane Carras Généré Le: 01 Jul 2011

## I. COMPLAINT INFORMATION / IDENTIFICATION DE LA RECLAMATION

Date De La Réclamation	19 May 2011		
Nom correspondant commercial	Paul Bican	Sales Office (Bureau Commercial)	Valence
Téléphone	+33 (0)4 66 20 00 26	No. Fax	-
Email	paul.bican@scapa.com		
Référence réclamation client			
Nom Du Client	Nexans France Paillart		
Numero De Client SAP	105187	N° Commande Client	
Rfrence Article Client			
1) Factures Et Article	es Sur La Réclamation		
2) Description Du Problème Identifié Par Le Client			

Nexans has received one pad with splices which is prohibited into their specification

Product: SFR10/103 in 20mm

Item code 160182 Batch number: 4558/11

I have no information regarding the delivery note or invoice number only the batch number

Actions demandées au client

### 3) Actions Conservatoires Sur Le Process

II. EVALUATION ET ACTIONS					
Echantillons/Photos Reçus	Yes				
Date	23 May 2011				
Responsable Processus	Sylviane Carras				
Responsable Action	pward				
Réclamation justifiée?	Yes	Retour marchandise	No	Destruction marchandise	Yes
Commentaires					
1) Analyse					
Customer is complaining in respect of Scapa SFR10/103 20mm x 800m (item 160182) due to a splice joint being incorporated in a pad. The Photo provided by the customer appears to show two pieces of SFR10/103 tape with splice joint included. The affected material relates to goods supplied via Scapa sales order 535825/10 for 103 pads of 160182; batch number is 4558/11 which was made on 24/02/2011. It is understood that one pad has been identified by the customer so far.  Scapa understand that they need to supply SFR10/103 pads to this customer without splice joint per customer specification STA FRPA0251 section 2. A formal instruction (document TRD 684) has previously been issued to Production which includes the requirement for joint free pads; a copy of this instruction is attached to the Scapa Complaints system for reference.  Scapa are to investigate this incident.  Can Scapa Customer Care please arrange for the customer to send these samples to Scapa for review as part of this concern investigation and to confirm provenance of the splice. Please mark samples for the attention of Mr P. Ward (Quality Dept) with reference number C100151.  ==================================					
Auteur	Philip Ward		Date	20 May 2011	
2) Causes					
From investigation it appears that some of the Production Operatives on the CWT Conversion plant appear to have ignored the formal instruction (TRD684) that states "pads must be splice-free", and have packed pads that included splices. This was done with good intention to maximize OD of the pad.					
Auteur	Philip Ward		Date	27 Jun 2011	
3) Solutions Possibles					

- 1. Quality Brief to be held with all relevant Production Operatives and Production Supervison, with the meeting to be led by the site QA Officer.
- 2. The samples and photos from the customer are to be shown to Production Operatives as part of Quality Brief.
- 3. Following the Quality Brief, all relevant Production Operatives are to sign-off an agreement that they fully understand that SRF10/103 pads for Nexans France must not contain splices.

Auteur	Philip Ward	Date	27 Jun 2011

#### 4) Mise En Place Actions Correctives Permanentes

- 1. Quality Brief was held on 23.06.2011 with all CWT plant Production Operatives and Production Supervison, with the meeting being led by the site QA Officer.
- 2. The samples and photos from the customer are to be shown to CWT plant Production Operatives as part of Quality Brief. The samples and photos were shown to the Production Operatives as a point of discussion during the brief.
- 3. Following the Quality Brief, all CWT plant Production Operatives have signed-off an agreement that they fully understand that SRF10/103 pads for Nexans France must not contain splices. The sign-off by the Production Operatives is effective from 24/06/2011.

Auteur	Philip Ward	Date	27 Jun 2011
Date Estimée	27 Jun 2011	Date De Mise En Place	27 Jun 2011
Date De Validation	27 Jun 2011		

### 5) Validation Des Actions Correctives

Scapa has implemented the above actions.

Following the Quality Brief, all CWT plant Production Operatives have signed-off an agreement that they fully understand that SRF10/103 pads for Nexans France must not contain splices. The sign-off by the Production Operatives is effective from 24/06/2011. QA to random check conversion activity for SFR10/103 pads, for an interim period.

\*\*\*\*\*\*

Commenté?

No

Can the customer please check stock of affected batch 4558/11 at their premises. It is assumed the balance of this material has been consumed by the customer; can they please check their stocks as confirmation.

Auteur Philip Ward Date 27 Jun 2011

#### 6) Actions Préventives

System update: None applies; TRD 684 clearly states that SRF10/103 pads for Nexans France must not contain splices.			
Other items potentially affected: above corrective action will apply to all sizes of SFR10/103 pads supplied to Nexans France.			
Monitoring: QA to random check conversion activity for SFR10/103 pads, for an interim period.			
Auteur	Philip Ward	Date	27 Jun 2011
Date Estimée	27 Jun 2011	Date De Mise En Place	27 Jun 2011
Date De Validation	27 Jun 2011		
7) Mise à Jour Documentation			
(a) MSR			
Commenté?	No		
Référence		Date	
(b) Révision logigrammes/plans de surveillance/instructions de fabrication et de contrôle			
Commenté?	No		
Référence		Date	
(c) Révision AMDEC			

Référence		Date	
(d) Spécification client			
Commenté?	No		
Référence		Date	

8) Félicitations à Toute L'équipe