

101405



Report 8D

Generated By: Kerry Sykes Generated On: 04 Oct 2011

I. COMPLAINT INFORMATION

Origination Date	28 Sep 2011		
Sales Name	Andrew Sampson	Sales Office	Ashton
Telephone	+44 (0)161 301 7400	Fax Number	+44 (0)161 301 7445
Email	andrew.sampson@scapa.com		
Customer Complaint Ref			
Customer Name	Flowstrip Limited		
SAP Customer Number	100009	Customer Order N°	
Customer Part Number			
1) Invoices And Items	s On Complaint		
(a) SAP Invoice Number	9100248231	Invoice Date	09 Sep 2011
- Material	138652	Batch	
	Material Description		
	3159 Silver 1220mm x 1400m Plain		

2) Problem Description

3159 silver
BN 15765/1
Order 15166
Delivery note 81067674

Differential tension across the width, creases/folds, delamination, ripping out, badly marked surface. Loss of yield 50m for which Debit note 2699 raised.

3159 silver
BN 15765/4
Order 15166
Delivery note 81067674

Creases/folds, differential tension, badly marked surface, delamination, ripping out. Loss of yield 30m, added onto Debit note 2699.

Actions	Requested	From	The	Customer

3) Containment Actions

II. EVALUATION AND ACTION

Sample/photo Received	No				
Date					
Process Owner	Kerry Sykes				
Team Leader	pbarrow				
Is Complaint Valid?	Yes	Return The Goods		Dispose The Goods	
·	163	Neturn The Goods		Dispose The Goods	
Comments					
1) Analysis					
Customer is complaining in badly marked surface.	respect of Scapa 31	59 silver 1400m jumbo ro	oll (item 138652) due to de	elamination/ripping-out, and	
				jumbo rolls of 138652 were sup	oplied
via Scapa sales order 5715 customer show delamination	· · ·	•	ouri due to loss of yield.	Filolos provided by the	
************************ Can Customer Care please arrange suitable credit for the affected material, due to loss of yield as experienced by the					
customer.					
Author	Philip Ward		Date	04 Oct 2011	
2) Root Causes					
The delamination and rippin adhesive, causing a localize				feed of resin into the	
Author	Philip Ward		Date	04 Oct 2011	
3) Possible Solutions					
1. Brief all of the Adhesive	Coating Line crews f	or the concerns being ex	perience by Flowstrip		
 Review Resin feed system for functionality and check for potential errors. Compile comprehensive action plan to address all concerns/problems being experienced by Flowstrip. 					
Author	Philip Ward		Date	04 Oct 2011	
, tautoi	Timp Train		Bute	01 00(2011	
4) Implemented Perm Corrective Actions					
1. Brief Adhesive Coating Line for the concerns being experience by Flowstrip. Done by site Quality Manager during weeks 38 &					
 Resin feed system checked for functionality and appears to be OK. Brackets added to resin feed system to attempt to prevent 					
clogging or loss of material. Done during week 38.					
3. Compile comprehensive action plan to address all concerns/problems being experienced by Flowstrip. Action plan is currently being compiled.					
Author	Philip Ward		Date	04 Oct 2011	
Estimated Date	04 Oct 2011		Implementation Date	04 Oct 2011	

5) Corrective Actions Validation					
Resin feed system checked for functionality and appears to be OK. Brackets added to resin feed system to attempt to prevent					
clogging or loss of material	. Done during week 38.				
Author	Philip Ward	Date	04 Oct 2011		
6) Preventive Actions	3				
Comprehensive action plan to be compiled to address all concerns/problems being experienced by Flowstrip with Cloth SPL jumbos; actions to be referenced in complaint C101323 when available.					
Author	Philip Ward	Date	04 Oct 2011		
Estimated Date	04 Oct 2011	Implementation Date	04 Oct 2011		
Validation Date	04 Oct 2011				
7) Review Of Documentation					
(a) MSR					
Reviewed?	No				
Reference		Date			
(b) Flow chart, control plan	n, work inspection instructions				
Reviewed?	No				
Reference		Date			
(c) FMEA					
Reviewed?	No				
Reference		Date			
(d) Customer specification					
Reviewed?	No				

Date

8) Congratulate The Team

Reference

Validation Date

04 Oct 2011