Total No. of Questions : 6]	SEAT No.	:
P5079	[Tot:	al No. of Pages : 2

T.E./Insem.-627

T.E. (Electrical) (Semester - I) **ELECTRICAL MACHINES-II** (2015 Pattern)

Time: 1 Hour] [Max. Marks: 30

Instructions to the candidates:

- Answer Q.1 or Q.2, Q.3 or Q.4, Q.5 or Q.6.
- 2) Neat diagrams must be drawn wherever necessary.
- 3) Figures to the right indicate full marks.
- 4) Use of electronic pocket calculator is allowed.
- Differentiate between smooth cylindrical & salient pole rotor used in *Q1*) a) large alternators.
 - A 3 phase 16 pole synchronous generator has resultant air gap flux of 0.06 wb per pole. The flux is distributed sinusoidally over the pole. The stator has 2 slots per pole per phase. And 4 conductors per slot are accommodated. The coil span is 150° electrical. Calculate the phase value of induced emf when the machine runs at 375 rpm.

- A 5 kvA 200v star connected 3 phase salient pole alternator with direct **Q2)** a) axis & quadrature axis reactance of 12Ω & 7Ω respectively, delivers full load current at unity p.f. calculate the excitation voltage. Negglect armature resistance.
 - In case of synchronous generator, explain the effect of armature reaction b) at [6]
 - i) Zero p.f. lag.
 - Zero p.f. lead. ii)

A 1200 kvA, 3300V, 50Hz 3 phase star connected alternator has effective **Q3)** a) armature resistance of 0.25Ω per phase. A field current of 40A produces a short circuit current of 200 A and an open circuit emf of 1100V line to line. [8]

Calculate the voltage regulation at full load

- i) 0.8 p.f. lag.
- 0.8 p.f. lead
- Define short circuit ratio (SCR) in case of synchronous generator. [2] b)

OR

- Explain synchronization of 3 phase alternator by dark lamp method. [4] **Q4)** a)
 - A 2 mvA, 3 phase, 8 pole alternator is connected to 6000 V, 50 Hz b) busbar & has synchronous reactance of 4\Omega/phase. Calculate synchronising torque & synchronizing power per mechanical degree of rotor displacement at no load. Consider normal excitation. [6]
- **Q5)** a) State different methods of starting 3 phase synchronous motor. Explain any one. [4]
 - A 3 phase 6600 V, 50Hz star connected synchronous motor takes 50A b) current. The resistance & synchronous reactance per phase are 1Ω & 20Ω respectively. Calculate the power supplied to the motor & induced emf at 0.8 p.f. lag.

OR

Compare 3 phase synchronous motor with 3 phase Induction motor. *Q6*) a)

[4]

ation.
Indition. With neat phasor diagram, explain the operation of synchronous motor b) at constant load and variable excitation condition. [6]

