
# Turtle Robot Board Assembly (V2)

Assemble in order indicated.

#### 1. Resistors:

- No polarity
- •100 ohm = brown-blackk-brown-gold
- •330 ohm = orange-orange-brown-gold
- •10K ohm = brown-black-orange-gold



### 7. Headers:

- .White JST: Slots outward
- •Black 2-position: Openings outward
- •Servo 3-position: long legs up

#### 2. IC socket:

- •Match divot on left side.
- •Insert chip after Step 7.

# 3. Button:

- Match legs to holes
- •Press to snap in place



**6.Switch:**•No polarity

## 4. LEDS / IR / Detector:

- •LED (D13, D7): long leg is positive. Square Pad
- •Bend IR emitter & detector so they face the front:
  - •Clear IR Emitter (D11, D10): long leg is positive. Square Pad
  - •Black IR Detector (A0, A1): Long leg emmiter ("E").

## 5. Capacitors:

- •1 uF no polarity "104"
- •10 uF long leg positive
- •100 uF long leg positive