

Implementation guide — OVN-2026-01 oven control

How to turn the files in this folder into a running panel: the GX Works3 project, the GT Designer3 project, and the order to commission them in.

Written for someone who knows MELSOFT but has not seen this project before. Follow it top to bottom. The steps marked **CRITICAL** are the ones that cause silent, hard-to-diagnose faults if skipped.

Part A — Before you start

A.1 Software

Tool	Version	For
GX Works3	1.065T or later	FX5U-32MT/ES program
GT Designer3 (GOT2000), part of GT Works3	Version 1.170C or later	GT2107-WTBD screens

Older GX Works3 releases do not carry the full FX5U parameter set. If your release predates the versions above, check that FX5U appears in the New Project dialogue before going further.

A.2 What you have been given

```
oven-control-system/
+-- 01-electrical-schematic/
| \-- OVN-2026-01_...Electrical-Schematic.pdf 13 A3 sheets, Rev 3
+-- 02-plc-program/
| +- st/P00_Common.st ... P07_Indication.st the program, 8 blocks
| +- labels/global_labels.xlsx 158 labels, paste into GX Works3
| +- labels/global_labels_PASTE.txt same, tab-separated, no header
| +- labels/global_labels_GXW3.txt same, UTF-16 for the importer
| +- labels/global_labels.csv same, for reading only
| +- labels/device_comments_xy.csv X/Y comments
| +- docs/cpu-parameters.md every parameter to set
| +- docs/functional-description.md what the program does and why
| +- docs/device-map.md full device allocation
| +- docs/event-codes.md SD log event codes
| \-- docs/commissioning-test-plan.md site test sheet
\-- 03-hmi-program/
+-- OVN-2026-01_HMI-Screen-Design.pdf 10 screens at 800 × 480
+-- screens/out/*.png the same, as images
+-- docs/object-schedule.csv every object and its device
+-- docs/alarm-list.csv 14 alarms + operator actions
+-- docs/device-crossref.csv 64 devices, and where used
+-- docs/got-configuration.md project settings
\-- docs/hmi-test-plan.md site test sheet
```

A.3 Hardware to have on the bench

- FX5U-32MT/ES with an **SD memory card** fitted (NZ1MEM-2GBSD or similar)
- GT2107-WTBD with the **GT11-50BAT** battery fitted
- Ethernet switch or a crossover lead, and a USB lead for the GOT
- Laptop set to **192.168.3.10 / 255.255.255.0**

Part B — GX Works3: building the PLC project

B.1 Create the project

1. Project → New
2. Series **FX5CPU**, Type **FX5U**, Program Language **ST**
3. OK. GX Works3 creates a scan program called MAIN.
4. Project → Save As → OVN-2026-01_PLC.gx3

B.2 Get the 158 global labels into the project

Four files are supplied for this. **Method 1 works everywhere — use it first.**

File	For
global_labels.xlsx	Method 1 , clipboard paste. Excel workbook.
global_labels_PASTE.txt	Method 1 without Excel. Tab-separated, no header.
global_labels_GXW3.txt	Method 2 , the file importer. UTF-16 tab-delimited.
global_labels.csv	Reading and diffing only. Do not import this one.

*If you import the plain .csv GX Works3 answers "No imported information found in the file." It is not a corrupt file and the columns are not wrong. MELSOFT's label importer only reads **UTF-16, tab-delimited** — the format its own export writes. A comma-delimited ASCII file parses to zero rows.*

Method 1 — paste into the grid (recommended)

Bypasses the importer completely. Under two minutes.

1. Navigation window → Label → Global Label → Global1
2. Open global_labels.xlsx (or global_labels_PASTE.txt in Notepad)
3. Select the **data rows only — not the header** — and copy
 - In Excel: click row 2, Ctrl+Shift+End, Ctrl+C
 - In Notepad: Ctrl+A, Ctrl+C (that file has no header)
4. In GX Works3, click the **Label Name cell of row 1** — the first editable cell, not the grey row-number column
5. Ctrl+V
6. Confirm **158 rows**, and that no cell is flagged red

The columns arrive in the grid's own order: Label Name, Data Type, Class, Assign (Device/Label), Constant, Comment

Method 2 — the file importer

Only if you would rather not paste.

1. In the Global Label editor choose the import command
2. Select global_labels_GXW3.txt — the UTF-16 file, **not the .csv**
3. At "Import the content of specified file" click **Yes**
4. Confirm 158 rows

If this still reports nothing imported, your GX Works3 release wants a slightly different column set. Export a blank template from the same dialogue, send it over, and the file will be regenerated to match it exactly. Do not spend time hand-editing — Method 1 is faster than diagnosing it.

Check the paste landed properly

Spot-check three rows that exercise the awkward data types:

Label	Data Type	Assign
gTick100ms	Bit	M0
gSlotElapsed	Double Word [Signed](1..6)	D4000
gAlmBits	Bit(0..15)	M700

gAlmBits and gAlmMem are **arrays that deliberately overlay** the named alarm labels at M700 and M720. Two names for one device is intended — the array lets the summary loop in P06_Alarms stay short, and lets the GOT watch the block as one alarm range. GX Works3 will not object.

B.3 Create the eight program blocks

1. Navigation → Program → Scan → right-click → Add New Data
2. Type **Program Block**, Language **ST**, name it P00_Common
3. Repeat for all eight, using these names exactly:

```
P00_Common P01_Security P02_Door P03_Blowers
P04_Heater P05_SlotTimers P06_Alarms P07_Indication
```

4. Open each block and paste in the matching .st file, whole.
5. Delete the default MAIN block if your project created one — the eight blocks above replace it.

B.4 Local labels — CRITICAL

Three blocks use a loop counter. Without it they will not compile.

Program block	Label	Class	Data Type	Lines that need it
P05_SlotTimers	i	VAR	Word [Signed]	30
P06_Alarms	i	VAR	Word [Signed]	4
P07_Indication	i	VAR	Word [Signed]	11

Pick **Word [Signed]** from the Data Type dropdown — do not type INT.

A POU's local variables live in the label editor pane, not in the code, so there is no VAR ... END_VAR block in the program body to paste. These three rows are the only hand-typed labels in the whole project. Miss one and the build reports "*Undefined label is used*" once for every line in that block that touches the loop counter — 25 to 30 errors from a single missing row.

Open each block's **local label** editor (the pane above the ST code) and add the row. No other block has local labels.

B.5 Execution order — CRITICAL

Navigation → Program → Scan. Drag the blocks until the order reads:

```

1 P00_Common 5 P04_Heater
2 P01_Security 6 P05_SlotTimers
3 P02_Door 7 P06_Alarms
4 P03_Blowers 8 P07_Indication

```

This is not cosmetic. P02_Door produces the door interlock signal that P03_Blowers consumes, and P06_Alarms compares outputs that P03/P04 have already resolved. Out of order, the blowers act on a stale door state and the contactor feedback alarms chatter.

B.6 Latch ranges — CRITICAL

Parameter → FX5UCPU → CPU Parameter → Memory/Device Setting → Device/Label Memory Area Setting → Device Setting

Device	Latch (1) start	Latch (1) end
M	M4000	M4095
D	D4000	D4499

Skip this and everything appears to work on the bench — then the first power cut wipes every cure timer, every counter and both passcodes, and the defaults silently rewrite themselves. It is the worst failure mode in the project because nothing announces it.

Everything outside those ranges is volatile **on purpose**: the blower run requests must not survive a power cut, or a restored supply would restart a motor on its own (IEC 60204-1).

B.7 Ethernet

Parameter → FX5UCPU → Module Parameter → Ethernet Port

Item	Value
IP address	192.168.3.250
Subnet mask	255.255.255.0
Communication data code	Binary

Then External Device Configuration → drag in a **MELSOFT Connection** and leave its default port. That is what the GOT will connect to.

B.8 Input response time

CPU Parameter → Input Response Time — leave every point at the **10 ms** default.

Do not raise it. The door chatter detector has to see the real transitions on X5; the program filters that input three different ways in software, one per job. Raising the hardware filter masks the very fault the alarm exists to find.

B.9 Data logging to the SD card

Tool → Logging Function (the exact menu name varies slightly by release).

Item	Value
Logging type	Trigger logging

Item	Value
Trigger	device M59 (gEventPulse), rising edge
Sampled devices	D12, D13, D14
Time stamp	enabled
Format	CSV
Storage	SD card
File switching	by date, one file per day
Saved files	8 (7 days plus today)

This is the traceability record — every slot start, every early reset with the minutes it was cut short, every login, every counter reset. See 02-plc-program/docs/event-codes.md.

B.10 Device comments

Navigation → Device → Device Comment → Global Comment, then import labels/device_comments_xy.csv. Optional, but it makes monitoring the I/O readable.

B.11 Build

Convert → Rebuild All.

Expect **0 errors**. If you get type errors on arithmetic lines, your GX Works3 release wants typed literals — the code already uses DINT#1, DINT#60 and so on for exactly this reason, so a failure here means something was pasted incompletely. Re-paste the whole file.

B.12 Download and first run

1. Connect over Ethernet, Online → Write to PLC
2. Select **Program, Parameter, Global Label and Device Comment**
3. Write, then power-cycle the CPU
4. Online → Set Clock — the clock stamps every log entry
5. Put the CPU in **RUN**

B.13 Prove the first run — CRITICAL

On the very first RUN the program writes its defaults into the latched area, then sets M4022 so it never does so again. Check it took:

Device	Should read	Meaning
M4022	ON	defaults written
D4100	60	heat-up watchdog, min
D4101	600	door watchdog, s
D4108	7200	cure time, s
D4110	2468	maintenance passcode
D4111	1357	quality passcode
M4021	ON	cure timers pause on a fault

Device	Should read	Meaning
M4020	OFF	heater airflow interlock, disabled

Then power-cycle once more and check D4110 still reads 2468. If it has gone to 0, your latch range from B.6 did not take — go back and fix it before doing anything else.

Change both passcodes before handover and issue them to the two teams separately, in writing. Also set a project password: Project → Security → User Authentication.

Part C — GT Designer3: building the HMI project

C.1 Create the project

1. Project → New
2. GOT Type: the **800 × 480 wide** GT21 group, Model **GT2107-WTBD**
3. Colour setting **65536 colours**
4. Controller: Manufacturer **MITSUBISHI ELECTRIC**, Controller Type **MELSEC iQ-F, I/F Ethernet**
5. Save as OVN-2026-01_HMI.gtx

C.2 Communications

Common → Controller Setting → CH1

Item	Value
GOT IP	192.168.3.18
Subnet	255.255.255.0
PLC IP	192.168.3.250
Port	leave the driver default (usually 5562) unless it disagrees with the FX5U

Leave the default port. Change it only if the GOT reports a connection error and the FX5U's MELSOFT Connection entry shows something different.

C.3 Build the common header and footer first

Every screen shares them, so build them once as a **template base screen** or a **set overlay window** and reuse it. Doing this after the ten screens means ten edits every time the navigation changes.

Header (y 0–56) and footer (y 424–480) are drawn on every page of OVN-2026-01_HMI-Screen-Design.pdf. The footer's six tabs are HOME, SLOTS, COUNTERS, ALARMS, HISTORY, LOGIN.

C.4 Create the ten base screens

Screen → New → Base Screen, numbered exactly:

No.	Title	Role
1000	Overview	—
1100	Cure slot timers	—
1200	Counters	—
1300	Alarms	—
1400	Manual test	MAINTENANCE
1500	Settings	MAINTENANCE
1600	Login	—
1700	Early reset	MAINTENANCE
1800	Counter reset	QUALITY

No.	Title	Role
1900	Event history	—

Startup screen: **1000**.

C.5 Place the objects

Work from 03-hmi-program/docs/object-schedule.csv with the matching page of the screen-design PDF open beside it. The CSV has one row per object:

Screen, Object type, Name, Device, Action, Role required, Notes

151 objects across the ten screens. The PDF is drawn at the panel's true 800 × 480, so positions can be read straight off it.

Conventions that apply throughout:

- Every command bit (M800–M835) is **momentary**. The PLC clears each one after acting on it, so a latched bit would repeat the command.
- Manual-test buttons on 1400 are **momentary while touched** — never latched.
- Numeric inputs on 1500 get **range checking** per the range column shown on the screen. The PLC does not police these.
- **Confirm dialogue** on every destructive switch: all six early resets and both counter resets. Suggested text: *"This is recorded against your login. Continue?"*

C.6 Security — CRITICAL, and not the obvious way

Do not use GOT security levels for the two roles. GOT levels are hierarchical: a level-3 user automatically holds level-1 and level-2 rights. Maintenance and quality must not inherit from each other — that inheritance is exactly what the separation of duties exists to prevent — so the check lives in the PLC and the GOT only collects the passcode.

On screen 1600:

1. A numeric input writes the typed code to D27, display format masked (*).
2. The **MAINTENANCE** button is one switch with **two actions on one touch**:
 - Word write: D27 ← the keypad value
 - Bit set: M829
3. The **QUALITY** button is the same, setting M835 instead.

One touch matters: the code then exists in D27 for a single PLC scan, and the PLC clears it the moment it has compared it.

On the protected screens: use M58 (maintenance) or M60 (quality) as the security/display condition on **every switch on the screen**, not only on the screen-change button. A screen condition on its own can be walked past with a direct screen-change command.

Set an inactivity **screen return to 1000** of 5 minutes, to match the PLC's auto-logout.

C.7 Alarms

Common → Alarm → Advanced User Alarm

Item	Value
Observation	bit device block, M700 – M713 , 14 points
Alarm text	import docs/alarm-list.csv
Detail text	the <i>Operator action</i> column
History	GOT internal memory, battery backed
History size	512 records

The ACCEPT switch on screen 1300 sets M824.

C.8 History and USB export

The **EXPORT TO USB** button on screen 1900 exports the **GOT's own alarm history**, using the standard alarm-history CSV output to the USB drive.

It does **not** export the PLC's 7-day event log. That log lives on the SD card in the FX5U and comes out by pulling the card or reading it with GX Works3. Screen 1900 says so on the face of it, deliberately, so nobody hands over a USB stick believing it holds the traceability record.

C.9 Panel settings

Common → GOT Environmental Setting

Item	Value
Backlight off	30 min, wake on touch
Screen saver	none
Buzzer	on, touch feedback only
Utility call	two-point touch, top corners
Language	English

Two-point utility call matters: a single-point call gets opened by accident by someone leaning on the panel.

C.10 Test offline, then download

1. Tools → Simulator → Activate with the GX Works3 simulator running. You can walk the whole navigation, the login flow and the alarm list without any hardware.
2. Communication → Write to GOT, over USB for the first download.
3. Fit the **GT11-50BAT** battery and set the GOT clock. Without the battery the alarm history and clock are lost at every power-down.

Part D — Commissioning order

Do it in this sequence. Each stage depends on the one before.

Stage	What	Sheet to sign
1	Panel wiring against the schematic, heater feeder isolated	schematic Rev 3
2	PLC I/O proving, blowers, door interlock, door watchdogs	PLC plan §1–3
3	Counters and slot timers, with the cure time shortened	PLC plan §4
4	Restore the cure time to 7200 s and the watchdog to 60 min	PLC plan §4.8, §5.8
5	Heater, with the feeder now live, including the -B3 trip	PLC plan §5
6	Manual test and security	PLC plan §6–7
7	HMI: comms, screens, roles, alarms, export	HMI plan §1–8
8	Handover	both plans, final section

Test plans: 02-plc-program/docs/commissioning-test-plan.md 03-hmi-program/docs/hmi-test-plan.md

The one test not to skip is **HMI plan §5**, the separation of duties: log in as maintenance, cut a cure short, then try to clear the counter that recorded it. It must be refused. That single sequence is the whole traceability requirement, proved end to end.

Part E — When it goes wrong

Symptom	Cause	Fix
"No imported information found in the file"	The plain .csv was imported. MELSOFT reads UTF-16 tab-delimited only	Paste from global_labels.xlsx instead, or import global_labels_GXW3.txt (B.2)
Import runs but cells are flagged red	Column set differs by GX Works3 release	Export a blank template and send it over; or just use the paste method (B.2)
Type errors on + DINT#1 lines	Block pasted incompletely	Re-paste the whole .st file
"Undefined label is used", many errors, all in P05_SlotTimers, P06_Alarms or P07_Indication	The local label i is not declared in that POU. 30, 4 and 11 lines respectively use it, so one missing row makes dozens of errors	Add the one row per POU (B.4). Errors confined to these three blocks mean the global labels imported correctly
"Undefined label is used" in every POU including P00_Common	The global labels did not import	B.2
Counters and timers zero after a power cut	Latch range not set	B.6, then re-prove with B.13
Passcodes revert to 2468 / 1357	Same cause — M4022 is not latched	B.6
Blowers hesitate or the feedback alarms chatter	Program blocks out of order	B.5
Door chatter alarm never fires	Input response time raised above 10 ms	B.8
GOT will not connect	IP, subnet, or no MELSOFT Connection in the FX5U	B.7, C.2
A command repeats itself	An HMI switch is latched, not momentary	C.5
Quality can reach the maintenance screens	GOT security levels used instead of the PLC bits	C.6 — rebuild that part
Cure timer not counting	Oven not fit to cure; M62 is on	Expected. Clear the fault; see alarm 13

Regenerating the drawings

Everything in this folder is generated. If a device rating changes, edit the source and rebuild — do not edit the PDF.

```
cd 01-electrical-schematic && python3 build.py && python3 make_pdf.py
cd 02-plc-program/labels && python3 make_labels.py # also the checker
cd 02-plc-program && python3 test/test_logic.py # 127 tests
cd 03-hmi-program/screens && python3 build.py
```

make_labels.py is a checker as well as a generator: it fails if a label used in the ST is undeclared, if two labels collide on a device, or if latched data strays outside the latch range. Run it after any change to the program.

Part F — Outstanding

Two items are still open and neither blocks the build.

1. **Motor and element nameplates.** The ratings on schematic sheets 02, 03 and 04 assume 1.5 kW blowers at 3.5 A and 3 × 6 kW elements. Send the actual nameplates and the breaker, overload and cable sizes get corrected.
2. gSetHtrNeedsAir (**M4020**) is built, tested and **off**. Turning it on makes the heater require a blower running, or the door open. It is off because the specified door behaviour deliberately runs the heater with both blowers stopped. Running 18 kW of elements with no airflow and the door shut is the case it protects against. Decide before FAT — it is a one-bit change.

Handover pack

- ■ Both passcodes changed and issued separately, in writing
- ■ D4108 = 7200 and D4100 = 60 confirmed after commissioning
- ■ SD card fitted, one day's log read back
- ■ GT11-50BAT fitted, both clocks set
- ■ GX Works3 and GT Designer3 projects backed up and password-protected
- ■ 'HOT SURFACES — HEATER LIVE' label fitted at the oven door
- ■ -B3 high-limit function test recorded and diarised for every PM