

B787 QRH Memory Items

Source: Hawaiian Airlines QRH Revision 7, January 19, 2026. These are the recall items only, the steps above the dashed line in each checklist, recited cold before referencing the QRH. Reference (look-up) steps below the dashed line are omitted. Ten checklists carry memory items.

CABIN ALTITUDE

QRH 2.1

Condition: Cabin altitude is excessive.

- 1 Don the oxygen masks.
- 2 Establish crew communications.
- 3 Check the cabin altitude and rate.
- 4 If the cabin altitude is uncontrollable:

PASS OXYGEN switch: **Push to ON and hold for 1 second**

Without delay, descend to the lowest safe altitude or **10,000 feet**, whichever is higher.

To descend:

- Move the thrust levers to idle
- Extend the speedbrakes
- If structural integrity is in doubt, limit airspeed and avoid high maneuvering loads
- Descend at Vmo/Mmo

ABORTED ENGINE START L, R

QRH 7.1

Condition: On the ground, an aborted engine start is needed.

- 1 FUEL CONTROL switch (affected side): **CUTOFF**

DUAL ENG FAIL/STALL

QRH 7.2

Condition: Engine speed for both engines is below idle.

- 1 FUEL CONTROL switches (both): **CUTOFF, then RUN**
- 2 RAM AIR TURBINE switch: **Push and hold for 1 second**

ENG AUTOSTART L, R

QRH 7.3

Condition: Autostart did not start the engine.

- 1 FUEL CONTROL switch (affected side): *Confirm* **CUTOFF**

ENG LIMIT EXCEED L, R

QRH 7.4

Condition: An engine limit exceedance occurs.

- 1 A/T ARM switch (affected side): *Confirm* **OFF**
- 2 Thrust lever (affected side): *Confirm* **Retard** until ENG LIMIT EXCEED message blanks or the thrust lever is at idle

ENG SURGE L, R

QRH 7.7

Condition: An engine surge or stall that requires crew action is detected.

- 1 A/T ARM switch (affected side): *Confirm* **OFF**
- 2 Thrust lever (affected side): *Confirm* **Retard** until the ENG SURGE message blanks or the thrust lever is at idle

ENG SVR DAMAGE/SEP L, R

QRH 7.10

Condition: Airframe vibrations with abnormal engine indications, or engine separation.

- 1 A/T ARM switch (affected side): **Confirm OFF**
- 2 Thrust lever (affected side): **Confirm Idle**
- 3 FUEL CONTROL switch (affected side): **Confirm CUTOFF**
- 4 Engine fire switch (affected side): **Confirm Pull**

FIRE ENG L, R

QRH 8.2

Condition: Fire is detected in the affected engine.

- 1 Choose one:
 - On the ground: Go to step 13
 - In flight: Go to step 2
- 2 A/T ARM switch (affected side): **Confirm OFF**
- 3 Thrust lever (affected side): **Confirm Idle**
- 4 FUEL CONTROL switch (affected side): **Confirm CUTOFF**
- 5 Engine fire switch (affected side): **Confirm Pull**
- 6 If the FIRE ENG message stays shown:
Engine fire switch (affected side): **Rotate to the stop and hold for 1 second**

STABILIZER

QRH 9.1

Condition: Stabilizer movement without a signal to trim, or the stabilizer is failed.

- 1 STAB cutout switches (both): **CUTOUT**
- 2 Do not exceed the current airspeed.

AIRSPEED UNRELIABLE

QRH 10.1

Condition: The airspeed or Mach indications disagree with AOA calculated airspeed.

- 1 Autopilot disconnect switch: **Push**
- 2 A/T ARM switches (both): **OFF**
- 3 F/D switches (both): **OFF**
- 4 Set the following gear up pitch attitude and thrust:
 - Flaps extended: **10 deg and 85% N1**
 - Flaps up: **4 deg and 70% N1**

Shared scaffold: ENG LIMIT EXCEED, ENG SURGE, ENG SVR DAMAGE/SEP, and FIRE ENG (in flight) all open A/T ARM switch Confirm OFF, then Thrust lever Confirm. SVR DAMAGE and FIRE ENG then both go FUEL CONTROL Confirm CUTOFF, Engine fire switch Confirm Pull. Learn the common opening once, then the divergences.