Troubleshooting Charts – Clutch, Expansion

Jan 17, 2023

Clutch

Symptom	Condition	Possible Cause	Remedy
No attraction.	Wiring normal.	Coil open.	Replace.
	No attraction even when cooler switch is ON.	Wiring parts open, wiring or connection defective (ground, fuse).	Reconnect or replace open wiring parts.
		Switch parts contact defective, malfunction (thermostat, stabilizer relay, cooler switch).	Repair or replace.
	At switch ON, rotor shows movement, and attracts when pushed.	Rotor to stator clearance too large.	Repair or replace.
Slips.	Clutch slips when rotating.	• Battery voltage low. • Oil on clutch face. • Coil layer short.	• Recharge battery. • Clean off oil. • Replace.

Expansion Valve

Symptom	Condition	Possible Cause	Remedy
Valve outlet not cold.	Temperature difference at outlet and inlet cannot be sensed.	• Heat sensitizing tube gas leakage. • Amount of refrigerant in cycle insufficient.	• Replace expansion valve. • Repair gas leakage point and charge refrigerant.
Valve inlet cold or frosted.	High pressure piping from receiver outlet feels cold.	Receiver clogged.	Replace.
	Frosts.	Expansion valve inside clogged.	Replace expansion valve and receiver.

Passenger Vehicles

Commercial Vehicles

Find My Part **Where to Buy**





Find My Part **Where to Buy**

Passenger Vehicles



Find My Part



Where to Buy

Commercial Vehicles



Find My Part



Where to Buy

MovinCool

Robotics

Commercial/Industrial

Automatic Data Capture

EdgeCool

MovinCool

Robotics

Privacy Policy

Terms of Use

Do Not Sell or Share My Personal Information

Site Map

Privacy Policy

Terms of Use

Do Not Sell or Share My Personal Information

Site Map

©2026 DENSO Products and Services Americas, Inc. All rights reserved.
First Time Fit, Endurovision, Iridium Power, Iridium Racing, Platinum TT and Iridium TT are registered trademarks of DENSO.