

BOKARO STEEL PLANT — ILLUSTRATIVE SAMPLE

Standard Operating Procedure

SOP No: BSP-RMHP-002

Title: Safe Maintenance of Belt Conveyors

Department: Raw Material Handling

Revision: 01

Date: 30-Jul-2024

1. PURPOSE

To prevent entanglement and crush injuries during cleaning and maintenance of belt conveyors in the Raw Material Handling Plant (RMHP).

2. HAZARDS

- Entanglement at head, tail and snub pulleys
- Nip points between belt and idlers
- Falling material from transfer points
- Coal and ore dust

3. GENERAL RULES

- Never clean, adjust or remove spillage from a running conveyor
- Never cross over or under a conveyor except at designated crossovers
- Pull-cord (emergency stop) switches must be tested every week; distance between pull-cord switches maximum 30 metres
- Guards must be refitted before restart

4. MAINTENANCE PROCEDURE

Step 1 — Stop the conveyor and apply LOTO at the MCC as per BSP-EL-005.

Step 2 — Operate the local pull-cord and the zero-speed switch check to confirm the belt cannot move.

Step 3 — Relieve belt tension at the gravity take-up by securing the counterweight.

Step 4 — Carry out the work; use belt clamps when cutting or splicing the belt.

Step 5 — Remove tools, refit guards, remove LOTO and give a pre-start warning siren of 30 seconds.

5. PPE

- Safety helmet, safety boots, goggles, dust mask (FFP2 or better)
- Close-fitting clothing; no loose sleeves near moving parts