

GAS_DETECTOR_CALIBRATION_SOP_SCANNED
BOKARO STEEL PLANT — ILLUSTRATIVE SAMPLE
Standard Operating Procedure
SOP No: BSP-GS-006
Title: Portable Gas Detector Bump Test and Calibration
Department: Safety and Environment
Revision: 01
Date: 04-Mar-2024

1. PURPOSE

To make sure portable gas detectors give correct readings before they are used.

2. BUMP TEST

- A bump test must be done before every shift or every use
- Expose the detector to the test gas for 30 seconds
- The detector must alarm for CO, H₂S, O₂ and LEL sensors
- If any sensor fails the bump test, do NOT use the detector; send it for calibration

3. CALIBRATION

- Full calibration every 30 days at the Gas Safety Laboratory
- Calibration gas cylinders must be within expiry date
- Calibration label on the detector must show the due date

4. ALARM SETTINGS

- CO low alarm: 20 ppm, CO high alarm: 50 ppm
- O₂ low alarm: 19.5 %, O₂ high alarm: 23.5 %
- LEL alarm: 10 %

5. CONTACT

Gas Safety Laboratory: Ext. 2315