

## BOKARO STEEL PLANT — ILLUSTRATIVE SAMPLE

### Standard Operating Procedure

SOP No: BSP-SAF-014

Title: Permit-to-Work System

Department: Safety and Environment

Revision: 03

Date: 09-Feb-2024

#### 1. PURPOSE

To control hazardous non-routine work through a written permit that confirms hazards are identified and controlled.

#### 2. TYPES OF PERMIT

- Hot Work Permit — welding, gas cutting, grinding in hazardous areas
- Confined Space Entry Permit — see BSP-SAF-009
- Height Work Permit — see BSP-SAF-011
- Electrical Isolation Permit — see BSP-EL-005
- Gas Line Work Permit — work on BFG, COG or LDG lines

#### 3. ROLES

- Permit Issuer: shift in-charge of the area (Executive level)
- Permit Receiver: supervisor of the team doing the work
- Safety Officer: countersigns permits for confined space and gas line work

#### 4. PERMIT PROCEDURE

Step 1 — Receiver prepares the job safety analysis (JSA) and applies for the permit.

Step 2 — Issuer inspects the site, confirms isolations and gas tests, and signs.

Step 3 — Receiver briefs every team member in a toolbox talk; each member signs the permit.

Step 4 — Permit copy is displayed at the work site.

Step 5 — On completion, the receiver confirms the area is safe and the issuer closes the permit.

#### 5. VALIDITY

- A permit is valid for one shift (maximum 8 hours) and must be renewed at shift change
- A permit becomes invalid immediately if any alarm sounds or conditions change

#### 6. HOT WORK CONDITIONS

- Flammable gas below 1% of LEL within 15 metres
- Fire extinguisher and fire watcher present during work and for 30 minutes after