

Pipeline Physical Integrity Log

[FIELD DOCUMENT - DIGITIZED VIA ARCHIVE SCAN]

1. Maintenance Field Log

Log Reference ID:	FL-9918-B
Facility Block:	High-Pressure Steam Pipe Loop (Line B-12)
Field Technician:	J. Ramos
Date/Time of Entry:	Sept 09, 2026 - 14:15 Local

2. On-Site Inspection Notes

Manual ultrasonic wall-thickness test performed at elbow joint J-14. Noticeable scaling present on pipe exterior insulation blanket. Insulation stripped back to allow contact probe testing.

3. Ultrasonic Thickness Measurements

Test Point Location	Design Nominal	Measured Minimum	Action Required
Point A (Outer Radius)	12.70 mm	12.45 mm	Monitor
Point B (Inner Radius)	12.70 mm	10.12 mm	SCHEDULE REPLACEMENT
Point C (Straight Pipe)	12.70 mm	12.61 mm	None

4. Core Field Recommendations

CRITICAL: Inner radius wall thinning exceeds allowable erosion allowance due to high-velocity condensate impingement. Recommend scheduling pipe segment cutout and replacement during upcoming scheduled maintenance window.