Lockout/Tagout Procedure

Lockout/Tagout Procedure (SOP-LOTO-01)

Plant applicability: PLANT-NORTH, PLANT-SOUTH
Document type: safety

Purpose
Prevent unexpected energization of equipment during service. This procedure is mandatory f
or any work that places a technician inside a guarded envelope.

Authorized Employees
Only technicians with current Kestrel LOTO certification may apply locks. Escorts must rem
ain outside the envelope.

Energy Isolation Sequence
1. Notify affected operators and place the machine in STOP.
2. Shut down using the normal stopping procedure on the HMI.
3. Isolate the main electrical disconnect. Attempt a start to verify isolation.
4. Isolate pneumatic supply and bleed residual pressure to 0 bar.
5. Isolate hydraulic power (press assets). Verify gauge reads 0 bar.
6. Apply personal lock and completed tag on each energy source.
7. Verify zero energy with a meter before contacting components.
8. Perform the maintenance task.
9. Remove tools, restore guards, remove locks in reverse order, and notify operations.

Group Lockout
For multi-person jobs use the group lock box. Each worker applies a personal lock to the b
ox. The box may not be opened until all personal locks are removed.

Prohibited Actions
- Never loan your lock or use another person’s lock.
- Never remove a lock that is not yours.
- Never rely on a software interlock as the sole isolation method.