Home Survey Inspection Report

Level 2 Home Survey

16 Example Avenue, Anytown, AN1 2YT

Property Address	16 Example Avenue, Anytown, AN1 2YT
Client Name	Mr & Mrs Sample Client 5
Inspection Date	1 July 2026
Report Generated	10 October 2026, 9:30 AM

This report is for the sole use of the named client and should not be relied upon by any third party.

Table of Contents

1 About Inspection 5 items

2 About Property 22 items

3 E Outside Property 11 items

4 H Grounds 4 items

5 F Inside Property 10 items

6 G Services 8 items

7 I Issues 3 items

8 J Risks 6 items

9 Capture floor/site plan sketches 1 items

About Inspection

Party Disclosure

I suspect that a conflict-of-interest issue may exist in this transaction as defined by current RICS Valuation Standards and the RICS Rules of Conduct. I am known to one or more persons connected to the property owner or to an interest in the property.

Weather

Weather: At the time of my inspection, the weather was rainy, following a period of rainy weather. Weather conditions can influence the visibility of certain defects, particularly those associated with roof coverings, rainwater goods, and dampness.

Property Status

Status: At the time of my inspection, the property was occupied. The property was partly furnished, and floor surfaces were uncovered, which limited inspection of concealed areas.

OverAll Opinion

Reasonable: I am pleased to advise you that this property is believed to be a reasonable proposition for purchase at £390,500.00 [Three Hundred and Ninety Thousand Five Hundred Pounds].

In my opinion, the property represents a reasonable proposition for purchase at the agreed price, subject to the findings and recommendations contained within this report. Future maintenance and repair should be anticipated in accordance with the property's age, construction, and level of ongoing maintenance.

Reasonable with repair: This property is believed to be a reasonable proposition for purchase, given that you are prepared to cover the costs and accept the inconvenience of dealing with any repairs or improvement works reported. These defects are considered normal in properties of this age and construction. Provided that the works are carried out to a good standard, I cannot foresee any problems regarding a future resale of the property in normal market conditions.

Property Facing

Orientation: The front elevation of the property faces approximately west. References to orientation within this report assume the reader is standing facing the front of the property.

About Property

Property Type

Other: sample detail 5

Providing bedrooms: Five

Property Built

Year built: The property is understood to have been built in 1965. This assessment is based on available information, the apparent age and style of construction, and a visual inspection only. Unless documentary evidence is available, the stated age should be regarded as an approximation. Where the construction date cannot be confirmed, the age assessment is based upon the property's apparent style and construction.

Year built: The property is understood to have been built in 2010 onwards. This assessment is based on available information, the apparent age and style of construction, and a visual inspection only. Unless documentary evidence is available, the stated age should be regarded as an approximation. Where the construction date cannot be confirmed, the age assessment is based upon the property's apparent style and construction.

Year Extended

Not Extended: From observable physical evidence, the property does not appear to have been extended.

Year Converted

Not converted: The property has not been converted.

Known date: The year of conversion is 1965. Your legal adviser should confirm that all statutory local authority consents and approvals are in place.

Flat Maisonettes

Flat information: The property is located on the third floor of a two storey building. The property is accessed via a communal door to the rear elevation of the property.

Accommodation

The accommodation comprises: Lower ground, Ground, First, Second, Third, Other and Roof space. The accommodation schedule contained within this report is provided for identification purposes only.

Floor	Living	Beds	Bath / shower	WC	Kitchen	Utility	Conserv.	Other
Lower ground	2	2	2	2	2	2	2	2 sample detail 5
Ground	2	2	2	2	2	2	2	2 sample detail 5
First	2	2	2	2	2	2	2	2 sample detail 5
Second	2	2	2	2	2	2	2	2 sample detail 5
Third	2	2	2	2	2	2	2	2 sample detail 5
Other	2	2	2	2	2	2	2	2 sample detail 5
Roof space	2	2	2	2	2	2	2	2 sample detail 5

Construction

Type: The property is believed to be constructed using traditional masonry, solid wall, cavity wall, timber frame, concrete wall, precast concrete panels, system-built and sample detail 5 construction.

Construction has been identified from visible inspection only and has not been confirmed by opening concealed elements.

Other: sample detail 5

External walls: The external walls are constructed of solid brick, cavity brick, timber frame, steel frame, rendered masonry and sample detail 5 construction.

Internal walls: Internal walls are formed in solid masonry, timber stud partitions, lath and plaster and sample detail 5.

Floors: Floors are of suspended timber, beam and block and sample detail 5 construction.

Windows: Windows are fitted with timber, aluminium, steel and sample detail 5 frames incorporating single, double, triple glazing and secondary glazing, where applicable.

Listed Building

Listed building: The property is understood to be a listed building. Where the property is listed, your legal adviser should advise you regarding the implications for future alterations, repairs, and maintenance.

Energy

Energy performance: According to the available Energy Performance Certificate: Energy Efficiency Rating: F. Potential Rating: F. This information has not been independently verified.

Other services: The property is fitted with photovoltaic (solar PV) panels, solar water heating panels, battery storage and sample detail 5. Where renewable energy systems are present, your legal adviser should confirm ownership, maintenance obligations, guarantees and any agreements with electricity providers.

Location

Location: The property is situated within a well-established residential area, modern residential development, mixed residential and commercial area, rural location, village setting and suburban location.

Density: The surrounding development is considered low.

Facilities

Facilities: Local amenities observed within reasonable proximity include schools, shops, medical facilities, bus services, parks and sample detail 5. The availability, quality and suitability of local amenities have not been investigated as part of this inspection.

Remote area - The property is in a remote area and likely to be far away from some of the usual facilities and amenities. Also, because of the location of the property, it is recommended that you contact the utility company to be certain regarding the nature of the drainage connection.

Local Environment

The property is in a location that could be affected by electromagnetic fields from an electricity substation or pylons located near the property. In addition to being unsightly, it may cause noise and disturbance, or interference may deter some future buyers, thus limiting saleability. The possible effects of electromagnetic fields have been the subject of media coverage. The Health Protection Agency (HPA), an independent body with responsibility for advising on electromagnetic fields, has advised that following the studies in 2000 and 2001, there may be risks, in specified circumstances, to the health of certain categories of people. Public perception may, however, affect marketability and future value of the property. If required, technical information can be obtained from the HPA or local electricity company.

The property is situated close to the sea, river, a canal, reservoir, or in a low-lying area, and may be susceptible to occasional or seasonal flooding. Your legal adviser should make further enquiries and advise you whether the building has been flooded in the past or is at risk of flooding. Enquiries should also be made to the Environment Agency.

Private Road

Other: sample detail 5

Noisy Area

Noise: The property is located adjacent to, or close to, major roads, commercial premises, industrial premises, public open space and sample detail 5. Such features may influence future enjoyment or marketability and should be considered before purchase.

Area

Conservation area: The property is suspected to be in an established conservation area. Your legal adviser should advise you on the implications of the property being situated in this location.

Garden

Fencing: Boundaries are formed by timber fencing, brick wall, hedging, wire mesh, concrete sections and metal railings.

Rear garden: The rear garden is laid to lawn, paving, timber decking, gravel, stones and sample detail 5.

Fencing: Boundaries are formed by brick wall, block wall, hedging, wire mesh, metal railings and sample detail 5.

Communal garden: The communal garden is laid to lawn, artificial lawn, paving, timber decking, stones, hardstanding and sample detail 5.

Topography

Topology: The property occupies steeply sloping ground.

Area Parking

No Parking: The property does not come with parking.

Paid parking: Pay and display parking operates in the immediate area.

Front Garden

Front garden: The front garden is laid to lawn, paving, timber decking, gravel, stones and sample detail 5.

Fencing: Boundaries are formed by brick wall, block wall, hedging, wire mesh, metal railings and sample detail 5.

Rear Garden

Rear garden: The rear garden is laid to lawn, artificial lawn, timber decking, gravel, stones and hardstanding.

Fencing: Boundaries are formed by timber fencing, block wall, hedging, wire mesh, concrete sections and sample detail 5.

Communal Garden

Fencing: Boundaries are formed by timber fencing, brick wall, hedging, wire mesh, concrete sections and metal railings.

Ground Parking

Type: The property comes with residential, private, allocated, off-street, underground facility and sample detail 5 parking.

Gated Community

Gated development: No

E Outside Property

Limitations

My inspection of the exterior was carried out from ground level and other reasonably accessible positions.

My inspection was restricted by the surrounding elements, including the layout of the area, and available vantage points from which I was able to view the property.

Restricted Access: There was no direct access to the rear of the building. For this reason, I cannot make any detailed comments regarding the condition of the uninspected walls, roof slopes, rainwater goods, etc. You should accept the risk that some defects may exist in these unseen areas.

Chimney Stacks

Not Applicable: The property does not incorporate the element(s) referred to in this section. No further comments are necessary.

Dummy chimney breast: The property is installed with false or dummy chimney(s) with no internal brick breast. These are hollow, non-structural features usually built using timber or metal framing and covered with plasterboard or brick slips to mimic a traditional chimney stack.

Description: The chimney stack(s) are constructed of brick, stone and rendered masonry. The chimney stack(s) appear replaced. Pots: The chimney stack(s) are fitted with clay pots, metal flues, cowls, caps and sample detail 5. Number: The property has multiple stacks(s).

Location: The chimney stack(s) are located to the front, side, centre and sample detail 5.

Flashings: The waterproofing between the chimney stack and the roof covering (called the flashing) appears to be formed in lead substitute, mortar, bricks and tiles. Condition: Where visible, the flashings appear in defective condition. Defective flashings may allow water penetration and should be repaired by an appropriately qualified roofing contractor. Flaunching: The cement bedding around the base of the chimney pot (called flaunching) appears to be formed in mortar, concrete, tiles and sample detail 5. Condition: Where visible, the flaunching appears in defective condition. Defective flaunching may permit water penetration and reduce the stability of chimney pots. Repairs should be undertaken as part of routine maintenance or sooner where deterioration is significant. Pointing. Condition: The mortar joints to the chimney stack appear in good, reasonable, weathered, poor and sample detail 5 condition(s). Weathered or eroded pointing should be renewed to reduce further deterioration and water penetration. Damaged chimney pots: The chimney pots appear weathered, cracked, damaged and missing. Damaged or insecure chimney pots should be repaired or replaced to maintain weather resistance and safety.

Condition: Where visible, the chimney stack(s) appear in reasonable condition, consistent with their age and construction.

No repair: No significant defects requiring immediate attention were identified unless otherwise stated below. Routine inspection and maintenance should be expected as part of normal property ownership.

Shared chimney: The chimney stack is believed to be shared with the neighbouring property or properties. The owner of the neighbouring property or properties may have some legal rights over this shared chimney. Your legal adviser should confirm ownership, maintenance responsibilities and any legal rights affecting the shared structure.

Leaning chimney: The chimney stack appears significantly leaning. Where significant movement is evident, further investigation by an appropriately qualified structural engineer or roofing contractor is recommended before legal commitment.

No repair required: No repair is currently needed. The property must be maintained in the normal way. Over time, brick or stone chimneys can distort and lean over. In the worst cases, the stack can become unstable. At present, this movement is small, and no action is required now. However, this problem can get worse, so the chimney should be periodically inspected, and you should plan to have the chimney rebuilt at a future time if the movement continues. Where significant movement is evident, further investigation by an appropriately qualified structural engineer or roofing contractor is recommended before legal commitment.

Not fully inspected: The chimney stack(s) could not be fully inspected because of height, restricted access, adjacent buildings and health and safety restrictions. I cannot fully comment on their condition. Comments are limited to those areas visible from accessible inspection positions.

Removed chimney or pots: The chimney stack(s) or pots to the front, rear, side and centre have been removed, altered and covered over with roofing. You should ask your legal adviser to confirm whether the removed chimney stack(s) received appropriate statutory approvals where required from the local council and advise on the implications.

Aerials and satellite dishes: An aerial is attached to the chimney stack. Where secure, no action is currently required. Chimney Defects: One or more chimney defects were observed, including: loose flashings, missing flashings, cracked flaunching, missing mortar, damaged pointing, loose chimney pots, broken chimney pots, vegetation growth, loose aerial fixings and loose satellite dish fixings. Repairs should be undertaken by an appropriately qualified roofing contractor to prevent further deterioration and water penetration.

Repair flashing: The waterproofing between the chimney stack and the roof covering is damaged or defective. This should be repaired soon, depending on the severity of the defect. The roof covering and chimney stack may have to be disturbed to repair the flashing, and this can increase the extent of the work.

Repair flaunching: The cement bedding around the base of the chimney pot (called flaunching) is damaged or defective. This should be repaired now. The roof covering and chimney stack may have to be disturbed to repair the flashing, and this can increase the amount of the work. The owner of the neighbouring property may have some legal rights over the shared chimney. You should check with your legal adviser before any work is done.

Causing damp: This is causing damp penetration to the adjoining building elements.

Repair pot: One or several pots fitted to the main building chimney stack are broken and partly missing. To replace the pot, you will have to renew the cement bedding around the base, called the flaunching, which holds the pot in place. The chimney pot may also be connected to a chimney flue that serves a heating appliance below, and a suitable replacement must be used.

Repointing: Some of the mortar between the bricks or stonework (called pointing) is damaged or defective. This should be repaired now. The roof covering and chimney stack may have to be disturbed to repair the flashing, and this can increase the amount of the work.

Poor chimney condition: The chimney stack(s) on the rear, side and centre of the building are in poor condition. This is a safety hazard. Although this can be repaired, it may be economical to rebuild the whole stack. This should be done now. If the chimney is no longer used by heating appliances below, it may be economical to reduce the chimney height to below roof level and extend the roof covering over it.

Repair soon: This should be repaired soon.

Repair aerials and satellite dishes: An aerial or satellite dish attached to the property is loose, rusted, damaged and sample detail 5.

Repair aerials and satellite dishes: An aerial or satellite dish attached to the property is rusted, damaged, dangling and sample detail 5.

Condition rating is: 1.

The element(s) are performing their intended function, and no significant defects were observed. Routine maintenance appropriate to the age and construction should be expected.

sample detail 5

You should ask the management company whether any repairs to the chimney stack(s) have been carried out previously or are currently proposed. Your legal adviser should confirm responsibility for repairs to the chimney stack(s) with the management company and ensure that an adequate sinking or reserve fund is in place to meet the cost of future repairs or replacement, should the need arise. This may help reduce the risk of unexpected repair costs or increases in the service charge.

Roof Covering

Dry weather: It was more difficult to detect leakages to the chimney stacks, roof covering, and rainwater goods because it was not raining at the time of my inspection.

Description: The pitched roof covering to the extension, porch, bay window and sample detail 5 is formed in original clay tiles, replacement clay tiles, concrete tiles, artificial slate, fibre cement slates, aluminium sheets, composite slate and sample detail 5.

Condition: Where visible, the covering appears in reasonable condition. No repair required: No significant defects requiring immediate attention were identified unless otherwise stated below. The roof covering appears to be adequately performing its function. Routine maintenance appropriate to the age of the roof covering should be expected.

Old roof covering: The roof covering over the building is old and may have reached, or be nearing, the end of its useful life and will need to be stripped and renewed soon. If re-covered in heavier materials the timbers may need to be strengthened to comply with current Building Regulations. Further, although functioning satisfactorily, older roof coverings should be expected to require increased maintenance and eventual replacement as part of their normal service life.

Asbestos: Parts of the roof covering and verge may contain asbestos. This type of asbestos base product is not normally a cause for concern according to the Health and Safety Executive. However, it should not be disturbed, sanded, or drilled without taking suitable safety precautions. When the slates are eventually replaced, a licensed removal contractor will need to be instructed, and this could be costly. Therefore, quotations for this work should be obtained before purchase commitment. Because of the possible asbestos content, you should get advice from a contractor experienced in this type of work or an asbestos specialist before any work is carried out.

Flat roof coverings: The flat roof covering over the building is formed in mineral felt, high-performance felt, single-ply membrane, GRP fibreglass, asphalt, fibreglass and sample detail 5.

Condition: Where visible, the covering appears in reasonable condition.

Flat felt roof coverings have a comparatively short life and will require regular maintenance checks. Even though the general condition of the felt may appear satisfactory for its type and age, repairs or replacement must be expected in the future. It is difficult to predict when this will be required as felt roofs can break down with little warning, even when visually appearing sound.

No repair required: No significant defects requiring immediate attention were identified unless otherwise stated below. The flat roof covering appears to be adequately performing its function. Routine maintenance appropriate to the age of the roof covering should be expected.

Old roof covering: The flat roof covering over the building is old and may have reached, or be nearing, the end of its useful life and will need to be stripped and renewed soon. If re-covered in heavier materials, the timbers may need to be strengthened to comply with current Building Regulations. Further, although functioning satisfactorily, older roof coverings should be expected to require increased maintenance and eventual replacement as part of their normal service life.

Description: The mansard roof covering to the main building, extension, porch and sample detail 5 is formed in original clay tiles, concrete tiles, natural slate, artificial slate, fibre cement slates, composite slate, asbestos sheet and sample detail 5.

Description: The sample detail 5 roof covering to the main building, extension, porch and bay window is formed in original clay tiles, replacement clay tiles, natural slate, artificial slate, fibre cement slates, aluminium sheets, asbestos sheet and sample detail 5.

Flashings: The waterproofing at the junction of the roof covering and wall (called the flashing) appears to be formed in lead, mortar, clay tiles, bitumen tape, lead substitute and sample detail 5. Condition: Where visible, the flashings appear in reasonable condition. Defective flashings should be repaired to reduce the risk of water penetration. No repair required: No significant defects requiring immediate attention were identified unless otherwise stated below. Routine maintenance appropriate to the age of the roof covering should be expected.

Ridge tiles: The covering along the top of the roof structure, called the ridge tiles, is assumed to be formed in concrete and sample detail 5.

Condition: Where visible, they appear in good condition. Loose or defective ridge tiles should be rebedded or mechanically fixed as appropriate. No repair required: No significant defects requiring immediate attention were identified unless otherwise stated below. Routine maintenance appropriate to the age of the ridge tiles should be expected.

Hip tiles: The covering along the junction of the roof slopes, called the hip tiles, is assumed to be formed in concrete and sample detail 5.

Condition: Where visible, they appear in reasonable condition. Repairs should be undertaken where movement or deterioration is evident. No repair required: No significant defects requiring immediate attention were identified unless otherwise stated below. Routine maintenance appropriate to the age of the hip tiles should be expected.

Valley Gutters: The valley gutters are formed in lead, mortar and sample detail 5.

Condition: Where visible, they appear in blocked condition. Blocked or defective valley gutters should be cleared, repaired, or replaced as necessary to ensure effective drainage and prevent water penetration into the building. No repair required: No significant defects requiring immediate attention were identified unless otherwise stated below. Routine maintenance appropriate to the age of the guttering should be expected.

Parapet walls: The parapet wall(s) are constructed of brick, stone, rendered masonry and sample detail 5.

Coping: The parapet coping is formed in stone, concrete, engineering brick, metal and sample detail 5.

Condition: Where visible, these elements appear in poor condition. Defective copings or pointing should be repaired to prevent water penetration. No repair required: No significant defects requiring immediate attention were identified unless otherwise stated below. Routine maintenance appropriate to the age of the wall should be expected.

Roof line deflection: Minor undulation or deflection to all, front and side roof slopes were observed. Such distortion is not uncommon in properties of this age and, unless accompanied by evidence of progressive movement, is not necessarily of structural significance.

No repair required: No repair is currently needed, and this is not considered to be structurally significant. The timber used in older roofs can gradually change shape or distort during normal use. Also, heavier replacement tiles can cause minor deflection to the roof line in some instances. This does not currently appear to be a problem and is considered normal for this type of roof. Should further deflection or distortion occur, you should arrange for inspection by a qualified person.

Leaking: The roof covering has extensive defects that are likely to allow water penetration into the building and may present a safety risk. Urgent repair is required. You should instruct a suitably qualified roofing contractor to carry out a detailed inspection, identify the full extent of the defects, and undertake the necessary remedial works without delay.

Roof Spreading: The roof slopes to front, side and rear of the building appear uneven or undulating, and the adjoining wall appears distorted, cracked, bowing or leaning outwards. These are visual indicators that may be consistent with roof spread and suggest that the roof timber structure may require strengthening. I recommend that you instruct a suitably qualified structural engineer or roofing specialist to carry out further investigation and advise on any necessary remedial work without undue delay (see section J1 - Risk to Building).

Repair Flat roof: The flat roof covering is weathered, blistered, split, worn, ponding, damaged and sample detail 5. Repairs or replacement should be undertaken before further deterioration results in water penetration. To replace the covering, the work will have to meet the requirements of the building regulations. This may increase the amount of repair work.

Repair parapet: The rendering, copping, flashing and sample detail 5 of the parapet(s) of the roof are damaged, loose, partly missing, poorly secured and sample detail 5. This should be repaired soon. Adjacent parts of the roof covering may have to be disturbed to repair the verge tiles, and this can increase the amount of repair work.

Safety hazard: This is a safety hazard, and parts of the parapet wall may fall to the ground and cause injury to people or property damage (see section J3 - Risk to People).

Repair verge: The tiles, slates, clips and caps items along the edge of the roof, called the verge, are damaged, cracked and sample detail 5. This should be repaired soon and, if significant, repaired promptly. Adjacent parts of the roof covering may have to be disturbed to repair the verge, and this can increase the amount of repair work. This should be repaired soon.

Repair valley gutters: The valley gutter at the junction of the roofs to all, side and rear of the building is blocked and poorly aligned. This should be repaired now. Adjacent parts of the roof covering may have to be disturbed to repair the gutter, and this can increase the amount of repair work. This should be repaired soon.

Repair flashing: The waterproofing at the junction of the roof covering and wall is damaged or defective. This should be repaired now. The roof covering may have to be disturbed to repair the flashing, and this can increase the amount of the work. The owner of the neighbouring property may have some legal rights over the shared chimney. You should check with your legal adviser before any work is done.

Causing damp: This is causing damp penetration to the adjoining building elements, and you must arrange to repair this urgently. Further defects and damage may be revealed from an intrusive or closer inspection by a qualified person.

Repair ridge tiles: The covering along the top of the roof structure called, the ridge tiles, is damaged or defective. This should be repaired now. The roof covering may have to be disturbed to repair the flashing, and this can increase the amount of the work. The owner of the neighbouring property may have some legal rights over the shared chimney. You should check with your legal adviser before any work is done.

Repair hip tile: The covering along the slope of the roof structure (called the hip tiles) is damaged or defective. This should be repaired soon. The roof covering may have to be disturbed to repair the flashing, and this can increase the amount of the work. The owner of the neighbouring property may have some legal rights over the shared chimney. You should check with your legal adviser before any work is done.

Not Inspected: The roof covering(s) could not be inspected due to access restrictions and the height and configuration of the building. Consequently, I am unable to comment on their composition or condition. As the roof is exposed to the weather, it should be inspected regularly and maintained as necessary to identify and address any defects at an early stage.

Condition rating is: 3.

Significant defects requiring urgent repair or further investigation were identified. Appropriate remedial works should be undertaken without delay. Where the extent of the defect cannot be determined during a visual inspection, further investigation by an appropriately qualified person is recommended before legal commitment.

sample detail 5

You should ask the management company whether any repairs to the roof covering have been carried out previously or are currently proposed. Your legal adviser should confirm responsibility for repairs to the roof covering with the management company and ensure that an adequate sinking or reserve fund is in place to meet the cost of future repairs or replacement, should the need arise. This may help reduce the risk of unexpected repair costs or increases in the service charge.

Roof fit for purpose, End of useful life.

Rain Water Goods

Dry weather: It was more difficult to detect leakages to the chimney stacks, roof covering, and rainwater goods because it was not raining at the time of my inspection.

Description: The rainwater goods comprise cast iron, aluminium, steel, concrete and sample detail 5 gutters, downpipes, hoppers, and associated fittings.

Condition: Where visible, the rainwater goods appear in reasonable condition, consistent with their age and type. No parts of the rainwater installation were dismantled or tested. The adequacy of underground drainage has not been assessed as part of this inspection. No repair required: No significant defects requiring immediate attention were identified unless otherwise stated below. The rainwater goods appear to be adequately performing their function. Routine maintenance appropriate to the age and type of the rainwater goods should be expected.

Shared Rainwater Goods: The rainwater goods are believed to be shared with the adjoining property. Your legal adviser should confirm ownership, maintenance responsibilities and any rights or obligations affecting the shared installation (See Section **I3**).

General Maintenance: Rainwater goods should be inspected and cleared at regular intervals, particularly during the autumn and following severe weather. Routine maintenance will assist in preventing blockages, overflow, water penetration, and premature deterioration.

Blocked Gutters: Vegetation, moss, leaves, or other debris were observed within sections of the guttering. The gutters should be cleared as part of routine maintenance to maintain effective rainwater disposal.

Blocked Gullies: One or more drainage gullies serving the rainwater system appear fully blocked. Blocked gullies may result in localised flooding and water penetration to adjacent building elements. The gullies should be cleared and maintained regularly.

Damaged Sections: Sections of the gutters or downpipes are cracked, distorted, split, missing and sample detail 5. This should be repaired now. Repairs or replacement should be undertaken to maintain the weather resistance of the building.

Leakage: Staining to fittings and adjoining elements and localised dampness indicate previous or current leakage from the rainwater goods. The affected sections should be checked for watertightness and repaired soon or repaired now, depending on the severity of the defect. Repairs should be undertaken to prevent further deterioration of adjacent building elements.

Not Inspected: The rainwater goods could not be inspected due to access restrictions and the height and configuration of the building. Consequently, I am unable to comment on their composition or condition. As the roof is exposed to the weather, it should be inspected regularly and maintained as necessary to identify and address any defects at an early stage.

Defective Connections: One or more gutter or downpipe joints and connections are loose, leaking, displaced, defective and sample detail 5. This should be repaired soon. Repairs should be undertaken to maintain the effectiveness of the rainwater system.

Corrosion: Sections of the rainwater goods exhibit light corrosion. Corroded sections should be repaired or replaced where necessary to maintain satisfactory performance. This should be repaired promptly if the damage is significant.

Condition rating is: 2.

Defects requiring repair or maintenance were identified. Although these are not considered urgent, repairs should be carried out to prevent further deterioration.

sample detail 5

You should ask the management company whether any repairs to the rainwater goods have been carried out previously or are currently proposed. Your legal adviser should confirm responsibility for repairs to the rainwater goods with the management company and ensure that an adequate sinking or reserve fund is in place to meet the cost of future repairs or replacement, should the need arise. This may help reduce the risk of unexpected repair costs or increases in the service charge.

Main Walls

The external walls to sample detail 5 comprise a mixture of solid brick wall, cavity block wall, cavity stud wall and sample detail 5 construction. The different wall types should be considered separately when planning future maintenance or alterations.

Description: The external walls of the main building and extension(s) are constructed of cavity brick. Condition: Where visible, the walls appear in reasonable condition, consistent with their age and type of construction. No repair required: No significant defects requiring immediate attention were identified unless otherwise stated below. The external walls appear to be adequately performing their function. Routine maintenance appropriate to the age and construction of the building should be expected. Painted Walls: The external wall surfaces, or parts of them, have been painted. Painting masonry can reduce its ability to breathe, trapping moisture within the wall. Rainwater may penetrate through fine cracks in the paint but be unable to evaporate freely, increasing the risk of dampness, frost damage and spalling of bricks or render over time. High internal humidity can also contribute to moisture becoming trapped within the wall construction. Painted external masonry also requires regular maintenance, as the finish will deteriorate and require periodic preparation and repainting to maintain its weather resistance and appearance. When future redecoration is undertaken, breathable masonry paint should be used where appropriate to minimise the risk of moisture becoming trapped.

Description: The external walls of the extension(s) and sample detail 5 are constructed of rendered masonry. Condition: Where visible, the walls appear in reasonable condition, consistent with their age and type of construction. No repair required: No significant defects requiring immediate attention were identified unless otherwise stated below. The external walls appear to be adequately performing their function. Routine maintenance appropriate to the age and construction of the building should be expected. Painted Walls: The external wall surfaces, or parts of them, have been painted. Painting masonry can reduce its ability to breathe, trapping moisture within the wall. Rainwater may penetrate through fine cracks in the paint but be unable to evaporate freely, increasing the risk of dampness, frost damage and spalling of bricks or render over time. High internal humidity can also contribute to moisture becoming trapped within the wall construction. Painted external masonry also requires regular maintenance, as the finish will deteriorate and require periodic preparation and repainting to maintain its weather resistance and appearance. When future redecoration is undertaken, breathable masonry paint should be used where appropriate to minimise the risk of moisture becoming trapped.

Description: The external walls of the main building and extension(s) are constructed of pebble dash masonry. Condition: Where visible, the walls appear in reasonable condition, consistent with their age and type of construction. No repair required: No significant defects requiring immediate attention were identified unless otherwise stated below. The external walls appear to be adequately performing their function. Routine maintenance appropriate to the age and construction of the building should be expected. Painted Walls: The external wall surfaces, or parts of them, have been painted. Painting masonry can reduce its ability to breathe, trapping moisture within the wall. Rainwater may penetrate through fine cracks in the paint but be unable to evaporate freely, increasing the risk of dampness, frost damage and spalling of bricks or render over time. High internal humidity can also contribute to moisture becoming trapped within the wall construction. Painted external masonry also requires regular maintenance, as the finish will deteriorate and require periodic preparation and repainting to maintain its weather resistance and appearance. When future redecoration is undertaken, breathable masonry paint should be used where appropriate to minimise the risk of moisture becoming trapped.

Cladding: The external wall finish or cladding comprises facing brickwork, natural or reconstituted stone, timber cladding, plastic panelling boards, fibre cement boards, uPVC cladding, fibre cement panels, composite cladding panels, hanging tiles (including shingle or plain tiles), aluminium cladding panels, terracotta cladding tiles and sample detail 5.

EWS1 Cladding: The external walls are predominantly cladded with a brick-slip, brick-effect outer face, terracotta tiles, compressed composite boards, aluminium panels, glass reinforced concrete (GRC) panels, hanging tiles (including shingle or plain tiles) and aluminium cladding panels, etc. This type of construction typically comprises fixing the cladding materials to a metal support frame secured to the primary structure, with a ventilated cavity and non-combustible mineral wool insulation behind. The inner leaf is commonly formed of concrete, blockwork or a metal framing system incorporating sheathing board and plasterboard lining. EWS1 form required: The external wall construction observed during my inspection indicates that a detailed assessment of the external wall system may be required to confirm compliance with current fire safety requirements. My inspection was limited to a visual assessment only and did not include opening up, intrusive investigations or a fire safety appraisal of the cladding system. Where required, confirmation of the fire performance of the external wall system can only be provided by a suitably qualified fire safety professional following a detailed assessment and, where applicable, the issue of a valid EWS1 form. Your legal adviser should make further enquiries of the seller, freeholder or managing agent and obtain copies of any current EWS1 form, fire risk assessments relating to the external wall system, and details of any planned, ongoing or completed remediation works before exchange of contracts or completion of the purchase. Neither the surveyor nor this practice has assessed the external wall system for compliance with fire safety legislation or lender requirements and accepts no liability to you or any third party for any loss, delay, remediation costs or other financial consequences arising directly or indirectly from the fire performance of the external wall system, the requirement for or content of an EWS1 form, or any current or future remedial works.

Moisture metre readings: Random moisture readings were taken to accessible internal wall surfaces using a hand-held electronic moisture meter. No damp found: No readings were obtained that suggest abnormal moisture levels at the time of inspection.

Damp-proof course: The walls have a barrier against dampness rising from the ground (called a damp-proof course or DPC is partially visible; one would normally be expected for a property of this age and type. The DPC is assumed to consist of plastic, slates, engineering bricks and sample detail 5. The adequacy of concealed damp-proof courses cannot be confirmed during a visual inspection.

DPC Treatment noted: I noted evidence of damp proof course treatment, wall ventilation apparatus, ventilation holes and sample detail 5 in the property. You should ask your legal adviser to check whether there has been a dampness problem before and if a valid guarantee or warranty covers this work. If not, you should ask an appropriately qualified person to inspect the property, assess its condition, and identify what repairs are required. Once the repairs have been completed, this person should issue a certificate of 'structural worthiness.' You should ask your insurance company if this problem would affect your ability to get insurance cover for this property.

Removed wall: An external wall to the lounge, kitchen, bedroom and sample detail 5 appears to have been removed as part of previous alterations. This work should have been carried out with Building Regulations approval and should have included adequate structural support for the remaining wall above the openings. Due to the internal floor and ceiling finishes, I was unable to confirm whether suitable structural support has been provided. I strongly recommend that your legal adviser obtains confirmation that the necessary Building Regulations approval was obtained for these alterations. If the required approval cannot be confirmed, or the work was not properly supervised, there is a risk that additional structural support may be required. This could result in further investigation, remedial works, additional costs, and disruption. Defect noted: I noted cracking, distortions and sample detail 5 in the surrounding wall surfaces. However, due to the concealed nature of the structure behind the wall and the floor and ceiling finishes, I was unable to confirm whether adequate structural support has been provided. You should instruct a suitably qualified structural engineer to carry out further investigation and advise on the adequacy of the structural alterations and any remedial works that may be required.

Extensions and alterations: Evidence was noted that external alterations have been carried out to the property. These include wall removal, new openings, replacement lintels, building extension works and sample detail 5. Your legal adviser should confirm that all appropriate statutory approvals and completion certificates have been obtained where required.

Differential Thermal Movement: Some of the observed cracking is consistent with differential thermal settlement or movement between the replacement windows and doors and the surrounding wall construction. This occurs because the varied materials expand and contract at varying rates as temperatures change, resulting in minor cracking around openings. The cracking appears longstanding and is not considered indicative of significant structural movement.

Thin wall: The external wall to the front, rear and side walls of the main building, extension and sample detail 5 is not thick enough and vulnerable to damp problems and heat loss. This substandard construction should be improved soon. In some cases, rebuilding the wall to modern standards may be the only economic option.

Cavity Wall Insulation: There is evidence that cavity wall insulation has been installed. Your legal adviser should verify the type of insulation used, the date of installation, and whether any guarantees or warranties are available. If it is confirmed that foam cavity wall insulation has been installed, please note that this type of insulation has been associated with problems in some properties. These may include deterioration of the insulation over time, allowing moisture to bridge the cavity and resulting in internal dampness, or contributing to the accelerated corrosion of wall ties where conditions are conducive. The availability of any guarantees or warranties should also be confirmed.

Tree defects noted: There are trees located close to the property, and I noted defects that may be associated with their influence, including cracking, distortion, heave and sample detail 5. Although the cause cannot be confirmed during a visual inspection, further investigation by a suitably qualified structural engineer and, where appropriate, an arboriculturist is recommended to establish whether the trees are contributing to the observed defects and to advise on any necessary remedial works.

Spalled Brickwork: A few bricks exhibit significant deterioration (this is called spalling). Damaged bricks should be replaced where deterioration is sufficient to affect the weather resistance of the wall.

Causing damp: This is allowing damp to get into the building. These should be repaired now.

Repair render: Parts of the render coating to the building are cracked, eroded, missing and damaged. The defective pointing should be renewed using a mortar appropriate to the age, type, and construction of the building. This may comprise lime-based mortar or Portland cement mortar, as appropriate. Weathered or defective pointing should be renewed as part of routine maintenance to help reduce water penetration and minimise further deterioration.

Hazard: Rendering pieces are likely to fall and cause harm to people who may be nearby. This is a hazard, and this repair should be carried out urgently.

Causing damp: This is allowing damp to get into the building. These should be repaired now. Repair pointing: The mortar between the bricks (known as the pointing) to parts of the building is eroded, cracked, loose, missing, damaged, other. The defective pointing should be renewed using a mortar appropriate to the age, type, and construction of the building. This may comprise lime-based mortar or Portland cement mortar, as appropriate. Weathered or defective pointing should be renewed as part of routine maintenance to help reduce water penetration and minimise further deterioration. Causing damp: This is allowing damp to get into the building. These should be repaired now. Repair render: Parts of the render coating to the building are cracked, eroded, loose, missing, damaged. The defective pointing should be renewed using a mortar appropriate to the age, type, and construction of the building. This may comprise lime-based mortar or Portland cement mortar, as appropriate. Weathered or defective pointing should be renewed as part of routine maintenance to help reduce water penetration and minimise further deterioration. Hazard: Rendering pieces are likely to fall and cause harm to people who may be nearby. This is a hazard, and this repair should be carried out urgently. Causing damp: This is allowing damp to get into the building. These should be repaired now.

Repair pointing: The mortar between the bricks (known as the pointing) to parts of the building is eroded, cracked, loose, damaged and sample detail 5. The defective pointing should be renewed using a mortar appropriate to the age, type, and construction of the building. This may comprise lime-based mortar or Portland cement mortar, as appropriate. Weathered or defective pointing should be renewed as part of routine maintenance to help reduce water penetration and minimise further deterioration.

Causing damp: This is allowing damp to get into the building. These should be repaired now. Repair pointing: The mortar between the bricks (known as the pointing) to parts of the building is eroded, cracked, loose, missing, damaged, other. The defective pointing should be renewed using a mortar appropriate to the age, type, and construction of the building. This may comprise lime-based mortar or Portland cement mortar, as appropriate. Weathered or defective pointing should be renewed as part of routine maintenance to help reduce water penetration and minimise further deterioration. Causing damp: This is allowing damp to get into the building. These should be repaired now.

Wall Ties defects: Parts of the walls to the side of the property show evidence of previous cavity wall tie repairs. No further repairs appear necessary based on my visual inspection, and the property should be maintained in the normal way. You should ask your legal adviser to confirm whether any guarantees, warranties or completion certificates are available for these works. If satisfactory documentation is not available, you should instruct a suitably qualified specialist to inspect the walls and confirm that the repairs remain satisfactory.

Lintel defect: The lintel (the beam supporting the masonry above a door or window opening), including a brick arch where applicable, in the front, rear and sample detail 5 wall of the back addition, extension, bay window and sample detail 5 is damaged, cracked, or distorted.

Significant defect: The defects observed are significant and have caused, or are likely to cause, movement or damage to the adjoining masonry. Further investigation by a suitably qualified contractor is recommended. Repairs may include repairing or replacing the lintel or rebuilding the brick arch, together with making good the surrounding masonry. The extent of the work required may increase once the lintel has been exposed.

Lintel defect: The lintel (the beam supporting the masonry above a door or window opening), including a brick arch where applicable, in the front, side, rear and sample detail 5 wall of the main building, back addition, extension and sample detail 5 is damaged, cracked, or distorted.

Windowsill defect: The windowsill(s) to the front, side, rear and sample detail 5 wall of the main building, back addition, extension and sample detail 5 is damaged, cracked, distorted and sample detail 5.

Minor Defect: Localised defects were observed. Repairs should be carried out to prevent further deterioration and maintain effective weather protection.

The external walls have been inspected visually and by touch from the outside and internally where exposed. No opening up or destructive investigation has been undertaken. The composition of the wall material cannot be fully confirmed without causing damage to the walls. Condition rating is: 1. The element(s) are performing their intended function, and no significant defects were observed. Routine maintenance appropriate to the age and construction should be expected. sample detail 5 General Maintenance: External walls should be inspected periodically as part of routine maintenance. Prompt repair of defective pointing, render, sealants, and isolated masonry defects will assist in maintaining the weather resistance and structural integrity of the building. You should ask the management company whether any repairs to the external walls have been carried out previously or are currently proposed. Your legal adviser should confirm responsibility for repairs to the external walls with the management company and ensure that an adequate sinking or reserve fund is in place to meet the cost of future repairs or replacement, should the need arise. This may help reduce the risk of unexpected repair costs or increases in the service charge.

Windows

Description: The windows are formed of replacement, original, PVCu, timber, old style timber sash, modern uPVC sash, aluminium, composite and sample detail 5 framed units. Glazing: The glazing comprises single glazing, double glazing, triple glazing, secondary glazing and sample detail 5. BS EN noted: Visible British Standard, BS EN, or other permanent safety markings were identified on the accessible glazing. The presence of visible markings indicates that safety glazing has been installed. Where confirmation is required, your legal adviser should verify any available certification relating to replacement windows. Condition: Where visible and operated during the inspection, the windows appear in reasonable condition, consistent with their age and type. No defects noted: No significant defects requiring immediate attention were identified unless otherwise stated below. Routine maintenance appropriate to the age of window material should be expected. The windows appear to have been fully replaced or partially replaced. Where replacement windows have been installed, your legal adviser should confirm that the installation was carried out under an appropriate FENSA, CERTASS, or Building Regulation approval scheme where applicable. Any available guarantees or warranties should also be obtained. Double-hung sash windows are expensive to maintain and tend to be ill-fitting and allow heat loss. From time to time, it is important to employ a joiner to inspect the sash windows, check the cords, and ease them before redecoration. This is best done in conjunction with the redecoration cycle. Glazing seals: The external sealant around the window frames appears in reasonable condition. Defective sealant should be renewed to reduce the risk of water penetration.

Roof Velux Windows: Type: The property incorporates roof windows, roof skylights, Velux roof windows and sample detail 5. These are formed in timber, PVCu and aluminium construction with double and triple glazing. Condition: Where visible, they appear in reasonable condition.

Windowsills: The windowsills are formed in PVCu, timber, brick, concrete and sample detail 5 material. Condition: Where visible, they appear in reasonable condition. Repairs should be undertaken where deterioration is sufficient to affect weather resistance.

Sill defect: The windowsill projection beyond the face of the wall does not appear to be adequate, properly installed, cracked and defective. This is allowing water ingress to adjoining walls and may be causing dampness. You should promptly arrange for further investigation and repair by a qualified professional to prevent further damage.

Operation: The windows selected for operation opened and closed with difficulty. Windows should be inspected and maintained regularly. Moving parts, hinges, locks, and drainage channels should be cleaned, lubricated, and adjusted where necessary. Timber windows should be redecorated periodically to maintain protection against weathering. Sealants should be inspected and renewed where deterioration becomes evident.

Defective Operation One or more windows were found to: stick during operation, fail to close correctly, fail to lock securely, have damaged hinges, have defective handles and have defective locking mechanisms. Repairs or adjustment should be undertaken to maintain security and weather resistance.

Failed Glazed Units: One or more double-glazed units exhibit misting and failed seals. Although this does not usually affect structural performance, replacement of the affected glazing units should be anticipated.

Damaged Glazing: One or more panes are cracked, chipped and damaged. Damaged glazing should be replaced to maintain safety, security, and weather resistance. Hazard: One or more panes are damaged, and this presents a health and safety hazard. The damage should be promptly repaired by a qualified professional.

Timber Windows: Where timber windows are present, paint deterioration, minor decay and sample detail 5 issues may occur as part of their normal service life. Regular decoration and maintenance should be undertaken to prolong their lifespan.

Repair windows: The window(s) in the lounge, dining room, bedroom and sample detail 5 have damaged lock(s), are difficult to open, are badly worn, are rotten, have broken glass, are in disrepair, are severely damaged, present a safety or security risk and have other defects. Where the defects are minor and do not present a safety or security risk, repairs should be carried out soon to prevent further deterioration. Where the defects affect the weather-tightness, security, or safe operation of the windows, repairs should be undertaken without delay. Severely damaged windows should be repaired or replaced immediately.

Fire Trap Risk: The design of the window(s) does not provide a suitable means of escape in the event of a fire. The affected window(s) in the lounge, dining room, bedroom and sample detail 5 have no opening, creating a potential safety hazard. To reduce this hazard, you should seek advice from an appropriately qualified person regarding suitable remedial measures.

Not every part of the windows was inspected in detail. The inspection was limited to those parts that were readily accessible without causing damage or moving furnishings. Only a representative sample of accessible windows was opened and closed during the inspection. Windows obscured by curtains, blinds, shutters, furniture, stored items, or fitted security devices could not be fully inspected. Double-glazed units cannot be assessed for thermal performance during a visual inspection. Condition rating is: 1. The element(s) are performing their intended function, and no significant defects were observed. Routine maintenance appropriate to the age and construction should be expected. sample detail 5

Outside Doors

Only a representative sample of accessible doors was opened and closed during the inspection. Doors obstructed by security devices, stored items, furniture, or other restrictions could not be fully inspected. The operation and performance of locks, alarms and security systems were not assessed. Not every part of the external doors was inspected in detail. The inspection was limited to those parts that were readily accessible without causing damage or moving furnishings.

Description: The property incorporates replacement, original, front, rear, side, patio, bi-fold and sample detail 5 doors.

The external doors are formed of PVCu, composite, aluminium and steel material.

Glazing: The glazed sections comprise single glazing, double glazing, decorative glazing and sample detail 5. The presence of safety glazing cannot be confirmed by visual inspection unless permanently marked.

BS EN noted: No visible British Standard, BS EN, or other permanent safety markings were identified on the accessible glazing. The absence of visible markings does not necessarily indicate that safety glazing has not been installed. Where confirmation is required, your legal adviser should verify any available certification relating to replacement windows. BS EN noted: Visible British Standard, BS EN, or other permanent safety markings were identified on the accessible glazing. The presence of visible markings indicates that safety glazing has been installed. Where confirmation is required, your legal adviser should verify any available certification relating to replacement windows.

Condition: Where visible and operated during the inspection, the doors appear in reasonable condition, consistent with their age and type. No defects noted: No significant defects requiring immediate attention were identified unless otherwise stated below. Routine maintenance appropriate to the door material should be expected.

The doors appear to have been fully replaced or partially replaced. Where replacement doors have been installed, your legal adviser should confirm that the installation was carried out under an appropriate FENSA, CERTASS, or Building Regulation approval scheme where applicable. Any available guarantees or warranties should also be obtained.

Glazing seals: The external sealant around the door frames appears in reasonable condition. Defective sealant should be renewed to reduce the risk of water penetration.

Thresholds: The door thresholds appear in reasonable condition. Minor wear is consistent with normal use. Defective thresholds should be repaired where deterioration affects weather resistance or safe operation.

Operation: The doors selected for operation opened and closed freely. Doors should be inspected and maintained regularly. Moving parts, hinges, locks, and drainage channels should be cleaned, lubricated, and adjusted where necessary. Timber doors should be redecorated periodically to maintain protection against weathering. Sealants should be inspected and renewed where deterioration becomes evident.

Security: The doors are fitted with mortice locks, cylinder locks, night latches and combination of locking systems. The level of security appears adequate based upon a visual inspection only. The effectiveness of locks and security devices has not been evaluated.

Defective Operation One or more external doors were found to: stick during operation, fail to close correctly, require adjustment, have defective handles, have defective locking mechanisms, be distorted and have localised decay. Repairs or adjustment should be undertaken to maintain security, weather resistance, and ease of operation.

Timber Doors: Where timber external doors are present, localised weathering, paint deterioration and surface splitting may occur as part of their normal service life. Regular decoration and maintenance should be undertaken to prolong their lifespan.

Patio and French Doors: The property incorporates sliding patio doors, French doors and bi-fold doors. The running gear, hinges and locking mechanisms should be inspected and maintained periodically.

General Maintenance: External doors should be inspected and maintained regularly. Moving parts, hinges, locks, handles, and seals should be cleaned, lubricated, and adjusted where necessary. Timber doors should be redecorated periodically to maintain protection against weathering. Flexible sealants should be inspected and renewed where deterioration becomes evident.

Repair doors: The door(s) in the lounge, bedroom, kitchen and sample detail 5 have damaged lock(s), have missing lock(s), are difficult to open, are badly worn, have broken glass, have failed glazing, are in disrepair, are severely damaged and have other defects. Where the defects are minor and do not present a safety or security risk, repairs should be carried out soon to prevent further deterioration. Where the defects affect the weather-tightness, security, or safe operation of the doors, repairs should be undertaken without delay. Severely damaged doors should be repaired or replaced immediately.

Condition rating is: 1.

sample detail 5

Conservatory and Porches

Conservatory: The conservatory(s) is located to the front, side, rear and sample detail 5 of the building. The walls comprise single-glazed, double-glazed, triple-glazed, timber framed, aluminium framed, steel framed and sample detail 5 wall sections.

Building Regulations: The conservatory appears to be a later addition to the property. Your legal adviser should confirm whether any necessary Building Regulation approval or exemption applies, together with any guarantees or warranties available.

Roof: The roof is formed in polycarbonate sheets, solid insulated panels, roofing tiles and sample detail 5 materials.

Doors and Windows: The conservatory comprises single-glazed, double-glazed, triple-glazed, timber, aluminium and steel-framed door(s), and window(s).

Floor: The floor is of solid concrete, suspended timber and sample detail 5 construction, and the floor is covered with timber, carpet, tiles, laminated flooring and sample detail 5 covering(s).

Condition: Where visible and operated during the inspection, the doors appear in reasonable condition, consistent with their age and type. Conservatories require routine maintenance appropriate to their age and construction. Glazing, roof coverings, sealants, rainwater goods, and external decorations should be inspected periodically and repaired where necessary to maintain weather resistance and serviceability. No defects noted: No significant defects requiring immediate attention were identified unless otherwise stated below. Routine maintenance appropriate to the conservatory material should be expected.

BS EN noted: Visible British Standard, BS EN, or other permanent safety markings were identified on the accessible glazing. The presence of visible markings indicates that safety glazing has been installed. Where confirmation is required, your legal adviser should verify any available certification relating to replacement windows.

Building Joint Defects: Defects were noted to the junction between the conservatory and the main building. The defects may include cracked mortar pointing, sealants and weatherproof junction details or other defects. Repairs should be carried out to maintain a weathertight seal and reduce the risk of water penetration and further deterioration.

Unstable Structure: Evidence of movement, distortion, or deflection was observed. Further investigation by an appropriately qualified contractor is recommended where structural movement appears significant.

Porch: The porch(s) located to the front, side and sample detail 5 of the building. The walls comprise single-glazed, triple-glazed, uPVC framed, timber framed, aluminium framed and sample detail 5 wall sections.

Building Regulations: The porch appears to be a later addition to the property. Your legal adviser should confirm whether any necessary Building Regulation approval or exemption applies, together with any guarantees or warranties available.

Roof: The roof is formed in glass, polycarbonate sheets, solid insulated panels and sample detail 5 materials.

Doors and Windows: The porch comprises double-glazed, triple-glazed, uPVC, timber and steel-framed door(s), and window(s).

Floor: The floor is of solid concrete and sample detail 5 construction, and the floor is covered with timber, tiles, laminated flooring, vinyl and sample detail 5 covering(s).

Condition: Where visible and operated during the inspection, the doors appear in reasonable condition, consistent with their age and type. Porches require routine maintenance appropriate to their age and construction. Glazing, roof coverings, sealants, rainwater goods, and external decorations should be inspected periodically and repaired where necessary to maintain weather resistance and serviceability. No defects noted: No significant defects requiring immediate attention were identified unless otherwise stated below. Routine maintenance appropriate to the porch material should be expected.

No BS EN noted: No visible British Standard, BS EN, or other permanent safety markings were identified on the accessible glazing. The absence of visible markings does not necessarily indicate that safety glazing has not been installed. Where confirmation is required, your legal adviser should verify any available certification relating to replacement windows.

Unstable Structure: Evidence of movement, distortion, deflection was observed. Further investigation by an appropriately qualified contractor is recommended where structural movement appears significant.

Repair conservatory: The conservatory door(s), glazing, roof, floor, wall(s) and sample detail 5 are cracked, rotten, leaking, damp, have failed, present a safety hazard and sample detail 5. These defects should be repaired in the near future. However, where the defects are severe or extensive, repairs should be carried out immediately.

Not Applicable: The property does not incorporate the element(s) referred to in this section. No further comments are necessary.

Condition rating is: 2.

sample detail 5

E8 Other Joinery and Finishes

Condition rating is: 2.

Repair: The soffits, barge boards, verge clips and timber cladding to the main building, back addition, bay window, garage and sample detail 5 are rotted, damaged, poorly secured, incomplete and sample detail 5. Repairs should be carried out as soon as practicable to restore their integrity and prevent further deterioration, moisture ingress, or the risk of sections becoming detached. Any decayed timber should be cut out and replaced, defective fixings renewed, and all exposed timber surfaces properly prepared, treated, and redecorated to provide long-term protection.

Hazards: The above defect is a safety hazard. This should be repaired now.

Not Inspected: The usual external works at eaves level (the edges of the roof where the guttering is fixed) could not be inspected due to the height and configuration of the building. Consequently, I am unable to comment on their condition. These elements are typically formed in timber and should be regularly inspected, maintained, and redecorated as necessary to protect them from weathering, prevent decay, and prolong their service life.

Timber Weathering: Exposed timber joinery exhibits minor weathering. Where deterioration is limited, routine preparation and redecoration should prevent further decay. Otherwise, where decay is advanced, localised repair or replacement may be necessary.

Timber Decay: Localised wet rot, surface decay and timber deterioration was observed. The affected timber should be repaired or replaced, and the source of moisture addressed where necessary.

Defective Joinery One or more defects were observed, including: loose soffits, damaged bargeboards, open joints, defective fixings, localised timber decay, distorted joinery and minor impact damage Repairs should be undertaken to prevent further deterioration and maintain weather resistance.

Inspected: The usual external works at eaves level (the edges of the roof where the guttering is fixed) could not be inspected due to the height and configuration of the building. Consequently, I am unable to comment on their condition. These elements are typically formed in timber and should be regularly inspected, maintained, and redecorated as necessary to protect them from weathering, prevent decay, and prolong their service life. Inspected: Inspection was carried out from ground level and other reasonably accessible positions. High-level joinery was inspected using binoculars where appropriate. Concealed sections behind gutters, roof coverings or other finishes could not be inspected. No opening up or dismantling of components was undertaken. This section relates to external joinery and finishes not covered elsewhere within this report, including fascias, soffits, bargeboards, eaves joinery, verge clips, cladding, decorative timberwork, or other associated external finishes. Only those areas that were readily visible and safely accessible at the time of inspection have been assessed. Redecoration should be undertaken periodically in accordance with the manufacturer's recommendations and the exposure of the property.

Condition rating is: 3.

Description: The external eaves-level joinery comprises PVCu, aluminium, asbestos board, cement board, slates and sample detail 5 materials. Localised repairs or redecoration should be undertaken where deterioration is evident. Routine inspection and maintenance appropriate to the material should be expected throughout its service life.

Decorations: The external painted or stained finishes appear in reasonable condition. External decorations are intended to provide weather protection as well as appearance.

Condition: Where visible, these elements appear in reasonable condition, consistent with their age and construction. No defects noted: No significant defects requiring immediate attention were identified unless otherwise stated below. Routine maintenance appropriate to the joinery material should be expected.

Asbestos Cement Components: Some external joinery or soffit components may comprise asbestos cement products. Where these remain in good condition and are left undisturbed, they do not normally present a significant health risk. Before carrying out repairs, alterations or removal, specialist advice should be obtained.

General Maintenance: External joinery should be inspected periodically as part of routine property maintenance. Timber components should be redecorated at appropriate intervals to maintain protection against weathering. Sealants, fixings, and joints should be inspected regularly and renewed where deterioration becomes evident. Prompt attention to isolated defects will help prevent more extensive repairs.

As this is a leasehold property, your legal adviser should confirm, before the exchange of contracts, the provisions within the lease relating to the maintenance and external redecoration of the building, including when such works are due to be carried out and who is responsible for the cost. You should also ask the management company whether any repairs or external redecoration works have been undertaken previously, whether any are currently planned, and whether any associated costs are likely to be payable by leaseholders.

E9 Other Outside Property

Description: Where applicable, the external communal areas comprise communal entrances, parking areas, footpaths, landscaped areas, boundary structures, CCTV, lighting, bin stores and cycle stores.

Condition: Where visible, these appear in reasonable condition, consistent with their age and use. General wear associated with normal use was observed where appropriate.

Carport: The property incorporates a timber, aluminium and masonry carport.

Roof: The roof is of pitched and flat construction and covered with tiles, slates, felt sheet, metal sheeting and sample detail 5 material.

Walls: The walls or balustrades are formed in bricks, timber, steel, glass and sample detail 5 materials.

Floor: The floor is formed in concrete, block paving, tarmac and gravel finish.

Condition: Where visible, the structure appears in reasonable condition. Routine maintenance appropriate to its age and construction should be expected. No defects noted: No significant defects requiring immediate attention were identified unless otherwise stated below. Routine maintenance appropriate to the carport material should be expected.

Porch Canopy: The property incorporates a porch canopy constructed of timber, concrete, plastic and sample detail 5 material.

Roof: The roof covering comprises slates, felt, polycarbonate and plastic material.

Condition: Where visible, the canopy appears in reasonable condition. Repairs should be undertaken where deterioration affects structural stability or weather resistance. No defects noted: No significant defects requiring immediate attention were identified unless otherwise stated below. Routine maintenance appropriate to the porch canopy material should be expected.

Roof Terrace: The property incorporates a roof terrace. The structure is formed in timber, concrete, steel and sample detail 5 materials.

Roof: The roof is of pitched and flat construction and covered with tiles, slates, felt, metal sheeting and sample detail 5 materials.

Walls: The walls or balustrades are formed in bricks, steel, glass, aluminium and sample detail 5 materials.

Floor: The floor is formed in concrete, block paving, gravel and sample detail 5 finish.

Drains: The drains are laid with bitumen, felt and sample detail 5, other appear well drained, unobstructed and obstructed. Poorly drained or obstructed drainage channels can allow rainwater to pond or overflow, resulting in water penetration into adjacent building elements, deterioration of finishes, and an increased risk of slips. Any defective, blocked, or damaged drainage channels should be cleared and repaired promptly to ensure they continue to function effectively.

Condition: Where visible, the structure appears in reasonable condition. Routine maintenance appropriate to its age and construction of the roof terrace should be expected. No defects noted: No significant defects requiring immediate attention were identified unless otherwise stated below. Routine maintenance appropriate to the roof terrace material should be expected.

Balcony: The property incorporates Juliet balcony(s) formed in steel, aluminium, glass, other materials. Condition: Where visible, it appears in good, reasonable, fair, poor, very poor condition. Guarding should remain securely fixed and free from significant corrosion or damage. No defects noted: No significant defects requiring immediate attention were identified unless otherwise stated below. Routine maintenance appropriate to the Juliet balcony material should be expected. Balcony: The property incorporates a timber, steel and concrete balcony(s).

Walls: The walls or balustrades are formed in bricks, timber, steel, aluminium and sample detail 5 materials.

Floor: The floor is formed in block paving, tarmac, gravel and sample detail 5 finish.

Drains: The drains are laid with bitumen, concrete and sample detail 5 materials, other appear poorly drained, unobstructed and obstructed. Poorly drained or obstructed drainage channels can allow rainwater to pond or overflow, resulting in water penetration into adjacent building elements, deterioration of finishes, and an increased risk of slips. Any defective, blocked, or damaged drainage channels should be cleared and repaired promptly to ensure they continue to function effectively.

Condition: Where visible, the structure appears in reasonable condition. Routine maintenance appropriate to its age and construction should be expected. No defects noted: No significant defects requiring immediate attention were identified unless otherwise stated below. Routine maintenance appropriate to the balcony material should be expected.

Juliet Balcony: The property incorporates Juliet balcony(s) formed in steel, aluminium and glass materials.

Condition: Where visible, it appears in reasonable condition. Guarding should remain securely fixed and free from significant corrosion or damage. No defects noted: No significant defects requiring immediate attention were identified unless otherwise stated below. Routine maintenance appropriate to the Juliet balcony material should be expected.

External Staircase: The property incorporates an external staircase constructed of concrete, steel, brick and sample detail 5 materials.

Element (s): The handrails, landing, and steps are formed in steel, aluminium and sample detail 5 materials.

Condition: Where visible, the staircase appears in reasonable condition. No defects noted: No significant defects requiring immediate attention were identified unless otherwise stated below. Routine maintenance appropriate to the staircase material should be expected.

Other External Structures: Other external structures include cycle stores, garden walls, pergolas, gazebos, storage compounds and sample detail 5 ancillary structures.

Condition: Where visible, these appear in reasonable condition. Routine maintenance appropriate to their age and construction installation should be expected. No defects noted: No significant defects requiring immediate attention were identified unless otherwise stated below. Routine maintenance appropriate to the installation material should be expected.

Retaining Walls: The property incorporates brick, stone, concrete and gabion retaining walls.

Condition: Where visible, these appear in reasonable condition. No defects noted: No significant defects requiring immediate attention were identified unless otherwise stated below. Routine maintenance appropriate to the retaining wall material should be expected.

Defects noted: Evidence of movement, bulging, damage and sample detail 5 was noted to parts or all retaining walls. You should arrange for further investigation by an appropriately qualified person. Retaining walls are designed to support the considerable weight of the ground behind them. Where the retaining wall is in poor condition, it may no longer be performing its intended function effectively. Repairs or replacement can be costly, as any new retaining wall must be designed and constructed to adequately resist the retained ground. You should instruct an appropriately qualified structural specialist to inspect the wall without delay and provide recommendations for any necessary remedial works. Where the retaining wall is shared with, or forms a boundary with, a neighbouring property, responsibility for repair and maintenance may be shared or otherwise affected by legal rights and obligations. Before any work is undertaken, your legal adviser should investigate ownership, maintenance responsibilities and any associated rights or liabilities, and explain the implications to you.

Walls: The balcony, roof terrace, staircase and sample detail 5 wall(s) are cracked, are damaged, are unstable and have eroded render. Repairs should be carried out as soon as practicable to prevent further deterioration and maintain their structural integrity. Any movement-related cracking should be investigated if considered progressive.

Repairs Roof: The flashing, roof tile, sheet, or slate covering of the roof over the carport, balcony and canopy is missing, slipped, lifted, in disrepair, leaking, damaged, dilapidated and sample detail 5. Repairs should be undertaken as soon as practicable by a competent roofing contractor to prevent water ingress, further deterioration, and the risk of loose materials becoming dislodged.

Floor: The floor surface, timbers, or decking of the balcony, carport and roof terrace is split, cracked and sample detail 5. The defective areas should be repaired promptly to maintain a weatherproof surface, prevent water penetration into the structure below, and reduce the risk of trip hazards.

Drains: The balcony, carport, roof terrace and sample detail 5 drains are too small, poorly drained, damaged and sample detail 5, resulting in rainwater ponding. Standing water can accelerate deterioration of the waterproof covering and increase the risk of water penetration into the building. The drainage outlets should be cleared, repaired, or upgraded as necessary to ensure efficient disposal of rainwater, and thereafter maintained regularly.

Metal Stairs: The surfaces of the steps or landing are split, cracked, partly rotted and defective. Repairs should be carried out as soon as practicable to remove the safety hazard, prevent further deterioration, and maintain safe access.

Decorations: The decorations to the stairway are peeling, flaking and damaged. The affected surfaces should be properly prepared and redecorated as soon as practicable. Where corrosion or timber decay is present, the underlying defects should be treated or repaired before redecoration.

Handrails: The handrail(s) of the balcony, Juliet balcony, terrace and sample detail 5 are inadequate, incomplete, loose, corroded, rotten and sample detail 5 and may not provide adequate protection against falls. This presents a safety risk. The defective handrail(s) should be repaired, replaced, or redecorated with a suitably designed and securely fixed handrail that complies with current safety standards.

The inspection was limited to those parts that were safely accessible at the time of inspection. No opening up, testing or dismantling of concealed elements was undertaken. Comments relate only to the visible condition of the structures inspected. This section relates to external features not reported elsewhere within this report, including carports, porches, balconies, Juliet balconies, roof terraces, external staircases, retaining walls, communal areas, and other ancillary external structures. Only those elements that were readily visible and safely accessible at the time of inspection have been assessed.

Condition rating is: 2.

sample detail 5

General Maintenance: External ancillary structures should be inspected periodically as part of routine property maintenance. Rainwater disposal, structural stability, guarding, fixings, waterproofing and external finishes should be maintained to reduce the risk of deterioration and ensure continued safe use.

It is assumed that the common parts are maintained under appropriate maintenance contracts and are the responsibility of the management company. Your legal adviser should obtain full details and refer to Section **I3** – Issues for Your Legal Adviser. Your legal adviser should also confirm that the person responsible for managing the building has complied with all applicable statutory requirements relating to asbestos. Where communal facilities are provided, your legal adviser should confirm: the identity of the management company, responsibility for maintenance and repairs, current service charges and reserve fund contributions, any planned major works, and any outstanding maintenance liabilities.

Inadequate lock

Inadequate Lock: The locking arrangements to the main, rear, side, patio, French doors, bi-fold doors and sample detail 5, do not meet current security standards and present a security risk. The locks should be upgraded at the earliest opportunity to improve the security of the property.

H Grounds

Limitations

The inspection of the grounds was visual only. Underground services, buried structures, and concealed defects could not be inspected or confirmed as part of this inspection.

No inspection restrictions: There were no unusual restrictions affecting my inspection of the grounds within the apparent ownership of the property.

Restricted access: Access to the rear or external elevations of the property was not available. Consequently, I was unable to inspect or comment on the condition or composition of the rear grounds. Comments are limited to those external areas that were visible and accessible at the time of the inspection.

H1 Garage

Garage

Condition rating is: 1.

sample detail 5

No garage: There are no garages on the property; no further comments required.

Not Inspected: Because access keys were not provided by the vendor or estate agent, or the provided keys could not open the garage, I was unable to inspect the garage(s) and therefore unable to comment about the internal condition of the garage(s) and roof timber or structure.

Converted garage: The garage has been converted into an office, a workshop and sample detail 5. The conversion was inspected visually only. Your legal adviser should verify that any necessary planning permission (where required), Building Regulations approval and completion certificates are available, together with any relevant warranties or guarantees.

Description: The property incorporates a garage in a block of garages, an attached, an integral, garage, undercroft and sample detail 5 garage(s).

Walls: The garage is constructed of single skin brick, cavity brick, prefabricated concrete, timber frame, steel frame and sample detail 5 wall(s). Where the garage comprises single skin brick walls, it should be noted that these are susceptible to dampness because they are not usually insulated.

Roof: The roof is of pitched, flat and sample detail 5 construction and is covered with clay tiles, slates, felt sheets, asbestos sheets, rubber membrane, GRP fibreglass, asphalt, metal sheets and plastic sheets material.

Garage Floor: The garage floor is constructed of concrete and sample detail 5 material. Minor cracking and surface wear are common and do not necessarily indicate structural movement.

Garage Doors: The garage is fitted with a electrically operated up-and-over, roller shutter, side-hinged door and rear or side door constructed of steel, timber, uPVC, GRP (fibreglass) and sample detail 5 material. The door(s) appeared serviceable at the time of my inspection. Routine maintenance is recommended.

Condition: Where visible, the garage appears in reasonable condition. Routine maintenance appropriate to the age and construction of the garage should be expected.

No defects noted: No significant defects requiring immediate attention were identified unless otherwise stated below.

Flat felt roofs have a limited-service life compared with pitched roof coverings and require regular inspection and maintenance. Although the covering may appear satisfactory at the time of inspection, repairs or replacement should be anticipated as it approaches the end of its serviceable life.

The roof covering material appears to contain asbestos. If left in good condition and undisturbed, it presents a low health risk. However, any disturbance, repair or removal should only be undertaken following advice from a suitably qualified asbestos specialist. The presence of asbestos-containing materials may affect future marketability.

Garage Defects

Minor defects: Defects were noted in the garage, including a leaking roof, cracked walls, rotten window frame(s), cracked glazing, damaged door(s) and sample detail 5. Repairs are recommended in the near future to prevent further deterioration.

Significant defects: Serious defects were noted in the garage, including a badly leaking roof, badly cracked or unstable walls, beetle infestation, damaged glazing, door(s) in disrepair and sample detail 5. Prompt investigation and repair are required to address the defects and prevent further deterioration or safety risks.

Safety hazard: The current condition of some of the elements of the garage is a safety hazard. You should resolve observed issues now.

H2 Other

Other

Condition rating is: 1.

sample detail 5

Grounds: The subject property is set within hilly grounds.

Gardens

Description: The outside areas comprise front garden, rear garden, side garden, courtyard garden, patio and sample detail 5.

Grounds: The surfaces comprise lawn, block paving, concrete, gravel, timber decking, composite decking, stone paving and sample detail 5. Where decking is installed, it should be inspected regularly as deterioration may create a safety hazard.

Fence: The boundaries comprise timber fencing, brick walls, stone walls, concrete sections, wire and metal railings. Boundary ownership cannot be confirmed during a visual inspection. Your legal adviser should confirm ownership and maintenance responsibilities from the title documentation and the vendor(s).

Condition: Where visible, the garage appears in reasonable condition. Routine maintenance appropriate to the age and construction of the garage should be expected.

No defects noted: No significant defects requiring immediate attention were identified unless otherwise stated below.

Hardstanding areas: The paths and hardstanding area appear level and reasonably level, and exhibit no unevenness. Minor settlement is common and may be addressed during routine maintenance. Where areas of uneven paving, trip hazards, or surface deterioration are present, adequate repairs and removal of damaged sections should be undertaken where necessary to maintain safe use.

Large Outbuilding

Outbuilding: The property incorporates a workshop, annex, summer house, office and sample detail 5 permanent structure (s).

Construction: The structure(s) is formed of blocks, timber, steel, prefabricated concrete, composite boards and sample detail 5 materials.

Roof: The roof is of pitched, flat, lean-to and sample detail 5 construction and is covered with clay tiles, concrete tiles, slates, rubber membrane, metal sheets and sample detail 5 material.

Doors and windows: The outbuilding(s) are fitted with door(s) and/or window(s) formed of aluminium, metal and sample detail 5 framed units. These appeared serviceable at the time of my inspection. Routine maintenance is recommended.

Condition: Where visible, the building appears in reasonable condition. Routine maintenance appropriate to the age and construction of the outbuilding should be expected.

Shared Access

Shared Garden: The communal/shared garden is shared with neighbouring property or properties. Your legal adviser should confirm your rights of use, maintenance responsibilities and any associated obligations or restrictions.

Grounds: The communal/shared garden is paved, decked, artificially lawned, laid with stones and laid with tile chippings.

Fence: The boundary fences are formed in timber, concrete, wire mesh, hedges and shrubs.

No Fencing: The communal/shared garden of the property does not have fencing.

Shared Areas: The property benefits from a shared driveway, shared garden, communal parking, communal gardens and sample detail 5 access.

Condition: Where visible, the shared areas appear in reasonable condition. Routine maintenance appropriate to the age and construction should be expected. Your legal adviser should confirm your rights of use, maintenance responsibilities and any associated obligations or restrictions.

Private road: The road serving the property appears to be private and may not be maintained at public expense. Your legal adviser should confirm its status, together with any rights of access, maintenance responsibilities, and associated liabilities.

Shrinkable Clay

Subsoil: The exact nature of the subsoil has not been investigated as part of this survey. However, the subsoil in the area may include shrinkable clay. Where present, this type of subsoil can be susceptible to seasonal moisture changes, which may result in movement due to shrinking during dry periods and expansion during wetter conditions. Your legal adviser should confirm, where applicable, ownership of the shared areas, rights of access, maintenance responsibilities, service charge liabilities, and any restrictions affecting their use.

Fence

Repair fence: Parts of the boundary fencing are cracked, broken, leaning, loose in places, severely damaged, rotten and sample detail 5. You should arrange to repair or replace the affected fencing soon. However. if the damage is significant, repair should be carried out promptly and may be expensive.

Shed

Sheds: There is timber, brick, aluminium and sample detail 5 shed(s) located within the grounds of the property. The roof(s) are pitched, flat and sample detail 5, and covered with felt, tiles and metal sheets materials.

Condition: Where visible, the shed(s) appear in reasonable condition. Routine maintenance appropriate to the age and construction of the shed should be expected. However, where the shed is in poor condition, you should arrange to repair or replace the shed.

Outbuilding

Repair outbuilding: Parts of the workshop, annex, summer house, office and sample detail 5 permanent outbuilding are damaged, is unstable, is rotted in places, have missing sections and sample detail 5. This should be repaired soon, and if the defects are significant or present a hazard, it should be promptly repaired.

Retaining Walls

Retaining Wall: The retaining wall(s) is cracked, leaning, distorted, unstable, damaged and in poor condition and may present a potential safety hazard. As retaining walls support significant ground loads, failure could result in substantial damage and costly repairs. An appropriately qualified specialist should inspect the wall without delay and recommend any necessary remedial works. If the retaining wall is shared with the neighbouring property owner, they may have some rights. Before any work is done, you should ask your legal adviser to investigate this matter and explain the implications.

Nearby Trees: One or more trees are located close to the property. Tree roots can, in certain ground conditions, influence foundations, particularly where mature trees are close to buildings and during prolonged dry periods.

No defects: No significant detrimental effects on the property were noted to date, although the trees should be regularly pruned to restrict future growth and minimise the risk of defects occurring.

H3 Other Area

Other Area

Condition rating is: 3.

sample detail 5

Right of Way: The property benefits from and/or is subject to shared rights of way over a driveway, footpath, entrance lobby and sample detail 5. Your legal adviser should confirm the rights of access, maintenance responsibilities and any associated.

Knotweed

Found: Japanese knotweed was identified within or adjacent to the property boundary. This invasive plant can damage hard landscaping and, in some circumstances, affect structures. It may also affect mortgageability, insurability, marketability, and value. I recommend that you arrange for further inspection by a remediation specialist who is a member of a recognised body so that you can get advice about future management and control and an insurance-backed guarantee.

Management D: Japanese knotweed was observed on neighbouring land within approximately three metres of the property boundary. Although no damage was evident to the subject property, the infestation should be monitored, and your legal adviser should make appropriate enquiries where necessary.

Flooding: The property is in an area that may be at risk of flooding due to its proximity to a river, canal, the coast and low-lying land. Your legal adviser should make appropriate enquiries and, where necessary, obtain an environmental or flood risk report.

EMF

Electromagnetic Fields (EMF): Electromagnetic Fields: The property is located close to an electricity substation, high-voltage overhead power lines and sample detail 5, which may give rise to concerns regarding electromagnetic fields. Such installations may also generate noise and can affect the property's marketability. Further information can be obtained from the electricity network operator or the UK Health Security Agency (formerly the Health Protection Agency). The property is located close to electricity infrastructure that may give rise to concerns regarding electromagnetic fields.

F Inside Property

Limitations

It was not practical to inspect parts of the property that were covered, concealed or otherwise inaccessible without causing damage or disturbance, such as lifting carpets or removing fixed fittings. Consequently, no assurance can be given regarding the condition of these concealed areas. This report relates only to those parts of the property that were reasonably accessible at the time of the inspection.

Where the roof space is inaccessible due to the absence of a suitable access hatch or the presence of other obstructions, I am unable to assess the type, presence, adequacy or condition of the insulation or concealed roof timbers. Where available, the Energy Performance Certificate (EPC) may provide additional information regarding the insulation within the roof space.

The inspection was visual and non-invasive. Floor coverings were not lifted, furniture and stored items were not moved, and no opening up or destructive investigation was undertaken. Comments relate only to the condition observed at the time of the inspection.

Limitations: The inspection of the internal accommodation was limited by fitted floor coverings, stored items, fixed fittings, restricted access, locked rooms, limited lighting and health, and safety considerations.

Where roof space access was available, only those areas that could be inspected safely from the access hatch and boarded areas were examined. Insulation, stored items, roof timbers, and restricted headroom may have limited the inspection. Inaccessible areas have not been inspected.

Roof Not Fully Inspected: I could not fully inspect the roof timber because of limited roof height; the floor was not safe to walk on, floor was boarded, excessive storage, insulation and sample detail 5 at the time of my inspection. No comments can be made regarding unseen elements.

Unsafe floor: I could not fully inspect the roof timbers because the floor was unsafe to walk on at the time of my inspection.

F1 Roof Structure

The roof structure was inspected from the roof access hatch where available and from those areas that were safely accessible at the time of the inspection.

Condition rating is: 2.

sample detail 5

You should ask the management company whether any repairs to the roof structure have been carried out previously or are currently proposed. Your legal adviser should confirm responsibility for repairs to the rainwater goods with the management company and ensure that an adequate sinking or reserve fund is in place to meet the cost of future repairs or replacement, should the need arise. This may help reduce the risk of unexpected repair costs or increases in the service charge.

Description: The roof structure is formed in prefabricated trussed rafters, steel and sample detail 5 construction.

Condition: Where visible, the roof structure appears in reasonable condition, consistent with its age and construction. No defects noted: No significant defects requiring immediate attention were identified unless otherwise stated below. Routine maintenance appropriate to the roof structure material should be expected.

Spray foam insulation: Spray foam insulation has been applied to the underside of the roof, fully or partially concealing the roof structure and preventing a full inspection of the roof covering and timbers. Consequently, I am unable to assess the condition of the concealed elements, and defects such as timber decay, wet rot, insect attack, or roof leaks may be hidden. Spray foam can restrict ventilation, trap moisture, and increase the risk of timber deterioration. It may also adversely affect the property's mortgageability, insurability and future saleability, as many lenders and insurers require specialist reports or removal of the insulation before accepting the property. Before committing to the purchase, you should: Obtain written confirmation from your mortgage lender and insurer that the property is acceptable. Instruct an independent specialist to carry out an intrusive inspection and advise whether the spray foam should be removed. Ensure that necessary remedial works or removal are completed, or that the cost is reflected in the purchase price. No opinion can be given on the condition of the concealed roof structure, and I cannot accept responsibility for defects hidden by the spray foam insulation.

Evidence of Water Penetration: Water staining or dampness was observed on roof timbers, underlay, or adjacent structural elements. The source should be identified and repaired to prevent further deterioration.

Capped Soil Vent Pipe: A capped soil and vent pipe was noted terminating within the roof space. This arrangement is not considered appropriate, as any leakage or escape of foul gases could discharge into the roof space. The pipe should be inspected by a suitably qualified plumber to establish its purpose and condition. Where it forms part of the drainage ventilation system, it should be appropriately extended and terminated to the outside air in accordance with current requirements. Any redundant pipework should be removed or suitably sealed.

General Maintenance: Roof spaces should remain adequately ventilated and free from unnecessary stored items that may restrict inspection or ventilation. Roof timbers should be inspected whenever significant roofing works are undertaken. Prompt attention to water penetration will reduce the risk of timber decay and associated structural deterioration.

Water Storage Tanks: The roof space contains plastic, galvanised steel, fibreglass and sample detail 5 cold water storage tanks.

Condition: Where visible, the tank appears in reasonable condition. No defects noted: No evidence of leakage or significant defects was observed at the time of inspection unless otherwise stated. Routine maintenance appropriate to the tank material should be expected.

Water Tank Insulation: The water tank and associated pipework appear uninsulated. Improving insulation may reduce the risk of freezing and heat loss. The absence of, or inadequate, insulation could result in condensation, dampness or leakage to the ceiling or surrounding areas.

Missing or Inadequate tank cover: The plastic, galvanised metal and sample detail 5 cold water tank cover(s) are missing or inadequate. This should be replaced soon.

Disused Water Tank: Plastic, asbestos cement and sample detail 5 disused water storage tank(s) remain within the roof space. Removal may be considered during future maintenance where it is no longer required.

No Wood-boring: No visible evidence of active wood-boring insect infestation was observed in the accessible roof timbers. Roof space is intrinsically a dusty place, and such evidence may be concealed by dust and insulation. Historic flight holes may be present and are not necessarily indicative of active infestation.

Timber Decay: Evidence of wet rot, fungal decay and sample detail 5 timber decay was observed. The source of moisture should be identified and promptly rectified before repairs are undertaken. Ventilation to the roof space should be maintained to prevent conditions favourable to rot.

Thin Timbers: Parts of the original timber structure are too small, and this could affect the stability of the roof structure. You should ask an appropriately qualified person to inspect the roof and recommend a repair scheme.

Heavy tiles sagging: The roof covering is too heavy and has caused the roof structure to distort, sag, or cause nearby walls to crack. You should ask an appropriately qualified person or roofing specialist to inspect the roof to determine the extent of the problem and specify any necessary remedial works.

Chimney Breast Alterations: Evidence was observed that a chimney breast has been removed, partially removed, altered and rendered within the roof space.

Not inspected: Part of the chimney breast within the roof space has been removed. I could not confirm whether the remaining masonry is adequately supported due to limited visibility. Inadequate support can compromise the building's structural stability. Your legal adviser should confirm that the necessary Building Regulations approval was obtained. If this cannot be confirmed, or there is any doubt about the adequacy of the support, you should instruct a suitably qualified professional to inspect the remaining structure and provide recommendations before committing to the purchase.

Minor Chimney Damp: Minor dampness from water penetration was noted to the rendered chimney breast within the roof space. This is not uncommon in a property of this age and construction, as a damp-proof course would not normally have been provided to the chimney. The moisture is likely to have been exacerbated by defects in the flashing where the roof abuts the chimney stack. This is not considered a significant concern at present, but the flashing should be inspected and repaired if necessary, during routine roof maintenance or when the roof covering is next renewed.

Partially missing: The party wall within the roof space is incomplete, leaving gaps that could allow fire to spread between this and the neighbouring property. The wall should be extended to the underside of the roof covering and all gaps suitably fire-stopped as soon as possible. As the party wall may be subject to legal rights and obligations under the Party Wall etc. Act 1996, you should consult your legal adviser before arranging any works, particularly where the proposed work may affect the adjoining property.

Underlay present: The underside of the roof covering incorporates traditional bituminous felt, breathable membrane and timber boards, which should provide a secondary barrier to driving rain and snow, where visible. Where visible, the underlay appears in fair condition. Where no underlay is present, this is likely to reflect the age and type of construction and is not necessarily a defect. However, installing a suitable breathable underlay when the roof covering is next renewed would improve weather protection and thermal performance. No defects noted: No significant defects requiring immediate attention were identified unless otherwise stated below. Routine maintenance appropriate to the underlay material should be expected.

Defects noted: The roof underlay is worn, missing and damaged in places, reducing its effectiveness as a secondary barrier against wind-driven rain and dust. I recommend that a qualified roofing contractor inspect the roof covering to confirm its weathertightness and carry out any necessary repairs. Ongoing routine maintenance appropriate to the roof covering should be expected.

Condensation noted: The roof space has no or insufficient ventilation, resulting in condensation and mould growth on some of the timbers or roof underlay. Additional ventilation should be provided to improve air circulation, reduce condensation, and help maintain the condition of the roof timbers. Significantly damaged or rotted timbers should be replaced.

Thermal Insulation: The roof space floor insulation appears adequate, limited, insufficient and poorly fitted based upon the visible areas only. The thickness and continuity of insulation cannot be confirmed without disturbing the insulation. Reference should also be made to the Energy Performance Certificate where available.

Inadequate/no insulation: The loft insulation is below the current recommended standard of 270–300 mm or is absent. This can lead to heat loss, higher heating costs, and an increased risk of condensation and mould. I recommend upgrading the insulation to current standards, ensuring roof ventilation is not obstructed.

Roof Movement: Evidence of deflection, sagging and sample detail 5 was observed. Observed roof movement is normal, significant, severe, presents a hazard and sample detail 5. Further investigation by an appropriately qualified roofing contractor is recommended where movement appears significant or presents a hazard.

Structural Alterations: Evidence of structural alterations to the roof space was observed, including loft conversion, altered roof members, removed struts, replacement supports, additional timber supports and sample detail 5 alterations. The adequacy of structural support cannot be confirmed during a visual inspection. Your legal adviser should confirm that appropriate statutory approvals and completion certificates were obtained where applicable.

Timber defects: Localised distortion, splitting, cracking, alterations and sample detail 5 were observed. Repairs or further investigation should be undertaken where structural adequacy is uncertain.

Roof Not Fully Inspected: I could not fully inspect the roof timber because of limited roof height, the floor was not safe to walk on, excessive storage, insulation, underlining and sample detail 5 at the time of my inspection. No comments can be made regarding unseen elements.

Unsafe floor: I could not fully inspect the roof timbers because the floor was unsafe to walk on at the time of my inspection.

F2 Ceilings

The ceilings have been inspected from within the rooms only. No opening up or destructive investigation has been undertaken.

Condition rating is: 2.

sample detail 5

Description: The ceilings are formed in plaster, plasterboard, lath and plaster and sample detail 5 ceilings. The ceiling finishes comprise painted, textured coating, papered, tiled, wallpapered, decorative panelled and sample detail 5 finishes.

Condition: Where visible, the ceilings appear in reasonable condition, consistent with their age and construction. No defects noted: No significant defects requiring immediate attention were identified unless otherwise stated below. Routine maintenance appropriate to the ceiling material should be expected.

The ceilings are fully or partially made of older plaster supported on thin wooden strips (called ‘lath and plaster’), typical of properties built before the 1940s. While no significant defects were noted at the time of inspection, these ceilings can deteriorate with age as the plaster loses its bond with the timber laths. They are susceptible to vibration and disturbance, and localised repairs are likely to be required over time, particularly during redecoration or alteration works. Repairs can be difficult and may dislodge adjacent plaster, making complete ceiling replacement more economical in some cases.

Parts of the ceilings within the property may contain asbestos-containing materials. In their current condition, these are not normally considered a significant risk if left undisturbed. However, they should not be drilled, sanded, cut, or otherwise disturbed without appropriate precautions. If future refurbishment or replacement is planned, the material should be assessed beforehand and, if asbestos is confirmed, removed by a licensed contractor. This can add significantly to the cost of future works.

General Maintenance: Ceilings should be inspected periodically for signs of cracking, distortion, or water penetration. Prompt repair of roof leaks, plumbing defects and condensation problems will reduce the likelihood of damage to internal ceiling finishes. Routine redecoration should be expected throughout the normal life of the property.

Minor cracking: Minor shrinkage or settlement cracking was observed in the ceiling finishes. Such cracking is common in properties of this age and type and is not considered structurally significant. The cracks may be adequately filled with appropriate material and redecorated during routine maintenance.

Polystyrene Ceiling Tiles: Parts of the ceilings are covered with polystyrene tiles, which present a fire safety risk. Polystyrene is highly flammable and, if ignited, can contribute to the rapid spread of fire while releasing dense, toxic smoke and harmful fumes that can significantly increase the risk to occupants. Although these tiles may have been acceptable when installed, they no longer meet modern fire safety expectations. They should be removed as soon as practicable by a competent contractor. Be aware that removal may damage the underlying ceiling, particularly if the tiles have been firmly bonded, and repairs or complete replacement of the ceiling finish may be required.

Heavy decorative covering: The ceilings are covered with heavy lining paper, decorative finishes, or similar coverings. No significant defects were evident at the time of inspection; however, these finishes can conceal minor cracking or other imperfections. Their removal during future redecoration may damage the underlying plaster, and you should allow for localised repairs or re-plastering.

Significant unevenness: Significant bowing, undulations and unevenness were noted on the ceiling surfaces. Further investigation should be undertaken where structural movement is suspected.

Wet water staining: Localised water staining was noted to the ceiling in the lounge, bedroom, kitchen, bathroom and sample detail 5. The moisture is suspected to originate from the loft space, roof, bathroom and another concealed source. The source of the leak should be identified and repaired before the affected ceilings are redecorated.

Ornamental plaster repair: The ceiling incorporates ornamental plaster features, some of which were found to be loose, cracked, unstable, partially missing and sample detail 5. These defects present a safety hazard, as sections may become detached and fall. A suitably qualified plastering contractor should inspect the affected areas and carry out appropriate repairs or replacement without delay. Localised repairs may be possible; however, where deterioration is extensive, complete replacement of the affected ornamental plasterwork may be necessary, resulting in more extensive and costly remedial works.

F3 Walls and Partitions

My inspection was limited by fixed furniture, kitchen units, bathroom fittings, large appliances, stored items, tiled finishes, decorative wall coverings, and fitted cupboards, which prevented full inspection of the concealed areas. The condition of hidden wall construction, lintels, structural supports, and other concealed elements could not be confirmed without opening the structure, which is outside the scope of a Level 2 Home Survey. No comment can be made on the condition of these concealed areas, and defects may exist that were not visible at the time of my inspection.

Condition rating is: 1.

sample detail 5

Description: The walls are formed in solid masonry, plasterboard partitions, lath and plaster and sample detail 5 construction. The wall finish comprises paint, plaster, wallpaper, tiling, textured coating, decorative panelling and sample detail 5 finishes.

Condition: Where visible, the walls and partitions appear in reasonable condition, consistent with their age and construction. Routine redecoration appropriate to the age and condition of the property should be expected. No defects noted: No significant defects requiring immediate attention were identified unless otherwise stated below. Routine maintenance appropriate to the wall material should be expected.

The walls are fully or partially made of older plaster supported on thin wooden strips, called lath and plaster, typical of properties built before the 1940s. While no significant defects were noted at the time of inspection, these walls can deteriorate with age as the plaster loses its bond with the timber laths.

Some internal walls have a textured decorative coating, which may contain small amounts of asbestos. If disturbed during repair, refurbishment or removal, asbestos fibres could be released and present a health risk. Before undertaking any work that may disturb the coating, you should consider having it assessed and, if asbestos is confirmed or suspected, ensure any work is carried out by a suitably competent contractor in accordance with current guidance.

General Maintenance: Internal walls should be inspected periodically for signs of cracking, dampness, or movement. Minor cracking and decorative defects should be repaired during routine maintenance. Maintaining adequate heating and ventilation will assist in reducing the risk of condensation and mould growth.

Condensation: Evidence of condensation and localised mould growth was observed on wall surfaces, ceilings or window reveals, in the lounge, bedrooms, bathrooms and kitchens area(s). Condensation is commonly associated with occupancy patterns, heating, insulation, and ventilation. Maintaining a suitable balance between heating and ventilation should assist in reducing condensation. Extractor fans may be installed, and windows opened regularly.

No Damp: Random moisture readings were taken to accessible wall surfaces using a hand-held electronic moisture meter. No elevated moisture readings were recorded at the time of inspection.

Significant cracking: Significant cracking was observed on some of the walls. Further investigation is recommended where cracking appears progressive or is associated with distortion.

Internal Alterations: Evidence was observed that an internal wall has been removed, partially removed, altered and new opening created. Where an internal wall has been removed or altered, other parts of the property must be properly supported.

Defects noted: An original internal wall has been removed to form an opening at sample detail 5. Distortion, inadequate support and sample detail 5 issues were noted around the altered area. While no significant progressive movement was evident at the time of inspection, the structural adequacy of the alteration cannot be confirmed during a visual inspection. Your legal adviser should verify that Building Regulations approval and a completion certificate were obtained for the work. If satisfactory documentation is unavailable, I recommend further investigation by a suitably qualified structural engineer. This may require opening parts of the structure, with the owner's agreement, to confirm that adequate support has been provided.

F4 Floors

The condition of concealed floor timbers, floor voids, joists, sleeper walls, and foundations cannot be confirmed without lifting floor finishes or opening the structure. Only the visible performance of the floors was assessed during normal use. The inspection was limited by fitted floor coverings, furniture, stored items, fixed kitchen units, bathroom fittings, or restricted access. The floor construction has been inspected from within the property only. Floor coverings were not lifted, and no opening up or destructive investigation was undertaken.

Condition rating is: 3.

sample detail 5

Description: The floors are formed in solid concrete, suspended timber and sample detail 5 construction. The floor finishes comprise floorboards, tiles, ceramic tiles, laminate flooring, wood flooring, stone tiles and sample detail 5 finishes.

Condition: Where visible, the floors appear in reasonable condition, consistent with their age and construction. No defects noted: No significant defects requiring immediate attention were identified unless otherwise stated below. Routine maintenance appropriate to the flooring material should be expected.

No Creaking floor: I walked over the accessible suspended floor surfaces and found them to be firm and level underfoot, with no evidence of excessive springiness or distortion. This is based on a visual inspection only, and the condition of concealed floor timbers cannot be confirmed without opening up the structure.

No Cracked Tiles: The floor tiles appear in fair condition. Where visible, the floor tiles in the kitchen, bathroom, toilet, conservatory and porch areas showed no evidence of cracking at the time of my inspection. No repairs are currently required. Routine maintenance only is recommended.

Loose Floorboards: Loose and creaking floor finishes were noted and will require local repair or renewal. Removal of floor coverings may reveal additional defects requiring attention.

Timber decay noted: Decay was noted to the staircase timbers, bathroom floor, kitchen floor and basement floor joists areas. The full extent of the decay could not be determined during this visual inspection, and additional concealed defects may be present. Further investigation by a suitably qualified timber specialist is recommended, and you should obtain a report and quotations for any necessary remedial works before committing to the purchase.

Wood Boring Noted: Evidence of historic wood-boring insect activity was observed in the property, lounge, bathrooms, kitchens and sample detail 5 areas. Further inspection of active activity by an appropriately qualified timber specialist is recommended where activity appears active or widespread. Otherwise, for historic activity, further enquiries should be made to the vendor regarding history, treatment work, and guarantee certificates.

Dampness noted: Although I could not see the full extent of the dampness problem in the lounge, bedroom, kitchen, bathroom and sample detail 5 areas, I suspect the dampness is caused by faulty plumbing, leaking sealants and sample detail 5. You should ask an appropriately qualified person to inspect the floor and identify the full extent of the problems.

Underfloor Ventilation: Where applicable, the suspended timber floor is provided with limited underfloor ventilation. Adequate ventilation is important in reducing the risk of condensation and timber decay. Where ventilation appears restricted or limited, improvements should be considered during future maintenance works.

Repair timber floor: The timber floor to the lounge, bedroom, kitchen, hallway and sample detail 5 is poorly supported, uneven, springy, loose, incomplete, damp, insect infested, rotten and sample detail 5, and the defect(s) is considered significant. This is common with floors of this age and construction, and these should be repaired soon. However, where the defect is significant, repair must be carried out promptly by a qualified professional.

Laminate/Wood floor defects: The laminate or wood flooring to the lounge, kitchen, bathroom, utility room and hallway areas are worn, damaged, incomplete, cracked, lifted and sample detail 5. These should be repaired or replaced soon.

Excessive floor vibration: The floor was found to vibrate excessively underfoot, suggesting inadequate support and/or deterioration of the timber structure, such as fungal decay or wood-boring insect attack. The exact cause could not be confirmed within the scope of this inspection. You should instruct a suitably qualified contractor to inspect the floor structure, including the underfloor void where accessible, determine the cause, and carry out any necessary repairs before purchase commitment.

Sloping floor: The floor to the lounge, bedroom, bathroom, utility room, hallway and sample detail 5 rooms are slightly sloping. This is commonly associated with long-standing settlement, historic movement, or deflection of the floor structure. Where the slope is slight, and there is no evidence of ongoing movement or associated structural defects, it is unlikely to be of structural significance, and no repairs are considered necessary. Where the slope is significant, or accompanied by cracking or distortion, further investigation by a suitably qualified building contractor is recommended to determine the cause and specify any necessary remedial works before purchase commitment.

F5 Fireplaces and Chimneys

This section relates to visible fireplaces, chimney breasts, and associated flues within the property. The inspection was limited to a visual assessment only. Fireplaces, flues, and appliances were not assessed, dismantled, or operated unless otherwise stated. The internal condition of chimney flues, liners and concealed structural elements cannot be confirmed during a visual inspection. No smoke testing, CCTV survey or opening up was undertaken. Combustion appliances should be provided with adequate permanent ventilation in accordance with current standards. The adequacy of ventilation has not been assessed during this inspection.

Condition rating is: 2.

sample detail 5

General Maintenance: Fireplaces, flues, and combustion appliances should be inspected and serviced regularly by appropriately qualified contractors. Unused flues should be adequately ventilated to reduce the risk of condensation and dampness. Where fireplaces are no longer required, appropriate capping and ventilation should be maintained.

Description: The property incorporates open fireplaces, gas fires, electric fires, wood-burning stoves, multi-fuel stoves and decorative fireplaces.

Condition: Where visible, the fireplace(s) and chimney breast(s) appear in reasonable condition, consistent with their age and construction. If the flues are to be used, they should be inspected and assessed by an appropriately qualified chimney specialist before use. No defects noted: No significant defects requiring immediate attention were identified unless otherwise stated below. Routine maintenance appropriate to the fireplaces, chimney breasts and flues material should be expected.

Unvented blocked fireplace: The fireplace(s) in the lounge, dining room, kitchen, hallway and sample detail 5 have been sealed, but no ventilation to the redundant flue was evident. Unventilated flues can trap moisture, increasing the risk of dampness, condensation, and deterioration of the chimney structure. A suitably qualified contractor should inspect the flue and install appropriate permanent ventilation, such as ventilating air bricks or flue vents, where required. This work should be carried out soon to reduce the risk of moisture-related defects.

Removed Chimney Breasts: Evidence was observed that a chimney breast has been partially removed and removed. The adequacy of concealed structural support cannot be confirmed during a visual inspection. Your legal adviser should confirm that appropriate Building Regulation approval and completion certification were obtained where applicable. Where structural adequacy is uncertain, further investigation by an appropriately qualified structural engineer is recommended.

Defects noted: The chimney breast has been removed from the lounge, bedroom, kitchen, bathroom, hallway and sample detail 5. The adjacent construction is cracked, distorted and sample detail 5. I saw evidence that indicates this has not been done properly. You should ask an appropriately qualified person to investigate this problem and recommend any repairs. This may involve removing parts of the floor and wall, and you should discuss this with the property owner.

Boiler Flues: Where a heating appliance discharges through an external wall or roof, the visible flue terminal appears secure, adequately positioned, and free from obvious obstruction. The installation has not been assessed.

Fireplace defects: One or more of the following defects were observed: cracked fire surround, loose fireplace components, cracked chimney breast, distorted fireplace opening and localised damp staining. Repairs should be undertaken where deterioration affects safety or continued use. If you plan to use the fireplace again, you should ask an appropriately qualified person to inspect and repair the fireplace. Although I do not know the full extent of the work required, you should plan for complete replacement. You should not use the fireplace until this has been done.

Dampness: Localised damp staining was observed on the chimney breast. This may be associated with condensation, defective flashings, unused flues, or moisture penetration. The source should be identified and repaired before internal redecoration is undertaken.

F6 Built In Fittings

The inspection was limited by stored items, fixed appliances, contents of cupboards, restricted access, or locked cupboards. Wall and floor surfaces concealed behind fitted units could not be inspected. No comment can therefore be made regarding the condition of concealed areas.

Condition rating is: 2.

sample detail 5

Worktop(s): The utility room and sample detail 5 worktops comprise solid timber, granite, quartz, stone, compressed composite, marble, steel and sample detail 5 material.

Fittings: The kitchen, utility room and sample detail 5 units are formed in timber, vinyl-wrapped timber and laminated MDF materials.

Condition: Where visible, they appear in reasonable condition. Routine adjustment and maintenance should be expected with normal use. No defects noted: No significant defects requiring immediate attention were identified unless otherwise stated below. Routine maintenance appropriate to the built-in fittings should be expected.

Kitchen Sink: The kitchen and sample detail 5 sink(s) is formed in stainless steel, composite, stone and sample detail 5 material. Where visible, it appears in reasonable condition. The sink was inspected visually only and was not assessed for leakage or drainage performance.

Built-in Appliances: The property incorporates oven, hob, extractor hood, dishwasher, refrigerator, freezer, washing machine and sample detail 5 built-in appliances. These appliances have not been assessed. Their condition, safety and serviceability are outside the scope of this inspection.

Extractor Fan: The kitchen extractor fan was not operating at the time of inspection. Its effectiveness cannot be confirmed without normal use. Regular cleaning of grease filters and vents should be undertaken to maintain efficient operation.

General Maintenance: Built-in fittings should be maintained as part of normal property ownership. Sealants should be inspected periodically and renewed where deterioration becomes evident. Cupboard hinges, runners, and door furniture should be adjusted or replaced where necessary. Water leaks should be repaired promptly to prevent damage to adjoining units and finishes.

Fittings defects: One or more cupboard doors or drawers require adjustment, repair, replacement due to wear or damage.

Sealant defects: The sealant around the sink or at the wall joints with the worktop is cracked, damaged, moulded and worn. Defective sealant should be renewed to reduce the risk of water penetration into adjacent units.

Defects: One or more of the following defects were observed: damaged cupboard doors, loose hinges, damaged worktops, worn finishes, cracked wall tiles, damaged plinths, water-damaged units and misaligned drawers. Repairs should be undertaken as part of normal maintenance.

F7 Woodwork

Condition rating is: 1.

sample detail 5

Description: The joinery items comprise internal doors, door frames, skirting boards, architraves, balustrades, handrails, window boards, timber cladding, cupboards, built-in joinery and sample detail 5 timber components.

Condition: Where visible and operated during the inspection, they appear in reasonable condition. Routine adjustment and maintenance appropriate to their age and construction should be expected. No defects noted: No significant defects requiring immediate attention were identified unless otherwise stated below. Routine maintenance appropriate to the timber joinery should be expected.

Creaking stairs: The staircase creaks when walked on. This is commonly caused by the natural shrinkage and movement of timber over time, which can loosen joints and fixings. In the absence of other signs of structural weakness, this is not normally a safety concern. However, the staircase should be overhauled, with loose joints and fixings repaired as part of routine maintenance to reduce movement and prevent further deterioration.

No handrails: The staircase has open risers (open treads), which present a safety hazard, particularly to young children, due to the risk of falling through or becoming trapped between the treads. Although open-riser staircases may have been acceptable when installed, they do not provide the same level of safety as modern enclosed staircases. A suitably qualified contractor should assess the staircase and install appropriate infill panels or other suitable guarding to improve safety. This work should be carried out without delay where young children are likely to occupy or visit the property.

Out of square door/frames: Some internal doors and frames are distorted, and the door(s) do not shut properly. This may have been affected by past settlement. As far as can be seen from this single inspection, the movement appears to be longstanding and is consistent with properties of this age and type of construction. I did not note any signs of current or ongoing movement that warrant any further investigation or structural repairs. The door(s) and their frames should be adjusted, repaired, refitted so that it closes properly.

Door operation: The internal doors selected for operation opened and closed with difficulty. No defects noted: No significant defects requiring immediate attention were identified unless otherwise stated below. Routine maintenance appropriate to the timber joinery material should be expected.

One or more internal doors do not close properly or operate with resistance. This is commonly caused by normal wear and tear, minor distortion, settlement, or worn hinges, latches, or other ironmongery. In most cases, adjustment or minor repairs will restore satisfactory operation. Where defects are more severe or the door is damaged, replacement may be required. Repairs should be undertaken as part of routine maintenance.

Defect noted: One or more internal joinery elements, including doors, locks, door frames, architraves, the staircase, balustrades, handrails, timber cladding, cupboards, built-in joinery and sample detail 5, were found to be worn, loose, poorly fitted, inadequately secured, missing, affected by decay and sample detail 5. Where the defects are minor, repairs can be undertaken as part of routine maintenance. Otherwise, where the defects are significant or affect safety, security or normal operation, repairs or replacement should be carried out without delay by a suitably qualified contractor.

Wood-Boring Insects: I found minor and significant evidence of active and historic wood-boring insect activity in parts of the staircase, skirting, under stairs, cupboards and sample detail 5 in the sample detail 5. The extent of any concealed damage could not be determined during this visual inspection. Where activity is historic, no treatment may be necessary if the timber is dry and the infestation is inactive. Where active infestation is suspected, or significant timber deterioration is present, a suitably qualified timber specialist should inspect the affected areas, confirm the extent of the infestation, and carry out any necessary treatment and repairs without delay.

F8 Bathroom Fittings

The inspection was limited by stored items, fixed furniture, bath panels, boxed-in pipework, restricted access, or sealed fittings. Concealed plumbing, waste pipework, and waterproofing systems could not be inspected. No comment can therefore be made regarding concealed defects. The inspection was limited to a visual assessment only. Sanitary fittings, plumbing installations, and drainage systems were not dismantled or pressure assessed.

Condition rating is: 1.

sample detail 5

Description: The property incorporates a family bathroom(s), shower room(s), ensuite bathroom(s), separate toilet(s), utility room and sample detail 5.

Sanitary ware: These are fitted with a combination of sanitaryware including a bathtub(s), shower(s), wash hand basin(s), bidet(s), mains pressure shower, electric shower, thermostatic shower, wet room and sample detail 5 installation.

Wall finishes: Wall finishes comprise stone tiles, water-resistant wall panels, painted plaster and sample detail 5 finishes.

Condition: Where visible, the bathroom fittings appear in reasonable condition, consistent with their age and use. No defects noted: No significant defects requiring immediate attention were identified unless otherwise stated below. Routine maintenance appropriate to the fittings should be expected.

General Maintenance: Bathroom fittings should be maintained as part of normal property ownership. Sealants should be inspected regularly and renewed where deterioration becomes evident. Adequate heating and ventilation should be maintained to reduce condensation and mould growth. Plumbing leaks should be repaired promptly to minimise water damage to adjoining finishes and concealed building elements.

Fan not working: The extractor fan(s) installed in the shower room(s), ensuite shower room(s), ensuite bathroom(s) and separate toilet(s) were not working at the time of inspection. This can lead to poor ventilation, excessive condensation, mould growth, and deterioration of internal finishes. The defective fan(s) should be repaired or replaced as soon as practicable to ensure adequate ventilation and help prevent further moisture-related defects.

Sealants: Sealant around the bath, shower tray, basin, and sanitary fittings appears in reasonable condition. Defective or deteriorated sealant should be renewed to reduce the risk of water penetration into concealed areas.

Defects: One or more of the following defects were observed: defective sealant, cracked sanitary ware, damaged wall tiles, loose floor tiles, poor ventilation, condensation, mould growth, damaged fittings, damaged bathtub panel and minor plumbing leaks. Repairs should be undertaken as part of normal property maintenance.

F9 Other

Condition rating is: 3.

sample detail 5

General Maintenance: Ancillary internal areas should be inspected periodically as part of routine property maintenance. Adequate heating and ventilation should be maintained to minimise condensation. Minor decorative defects and isolated repairs should be addressed before deterioration becomes more extensive. Stored items should not obstruct inspection hatches, ventilation openings, or access to services.

Description: Internal communal parts to the property comprise entrance lobby, hallway, staircases, lift lobby, fire lobby, balcony, common room and sample detail 5.

No defects noted: No significant defects requiring immediate attention were identified unless otherwise stated below. Routine maintenance appropriate to the installations should be expected.

Cellar/Basement Not inspected: The property has a cellar or basement, but it could not be inspected due to restricted access, no access and sample detail 5. No comment can therefore be made on its condition.

Walls: The property incorporates a cellar, basement and the walls are formed in bricks, stone, loose soil and sample detail 5 materials.

Floor: The floor is constructed of solid concrete, stone, loose soil and sample detail 5.

Condition: Where visible, the cellar appears in reasonable condition. Minor dampness may be expected in older cellars below ground level and does not necessarily indicate a defect. No defects noted: No significant defects requiring immediate attention were identified unless otherwise stated below. Routine maintenance is recommended.

Not in use: The property has a cellar which is currently unused. No significant defects were apparent from the limited inspection. Routine maintenance is recommended.

Unsuitable: The cellar or basement should not be regarded as habitable accommodation due to low headroom, difficult access, poor ventilation and sample detail 5. It should only be used as ancillary storage space.

Flooded: The cellar or basement was significantly flooded due to defective drainage or groundwater ingress. An appropriately qualified drainage or building specialist should investigate the cause and recommend remedial works.

Damp: Dampness was noted on the lower walls, upper walls, throughout the cellar and exposed floor joists. Further investigation by a suitably qualified damp and timber specialist is recommended to establish the cause and specify appropriate repairs.

Waterproofing failure: The extent of dampness suggests failure or absence of an effective waterproofing system. Remedial works are likely to be disruptive and potentially costly. You should ask a suitably qualified specialist to investigate and provide recommendations. Your legal adviser should also confirm whether any waterproofing guarantees or warranties remain in force.

Timber decay: Decay was noted in exposed floor joists within the cellar. This is a serious defect that may affect the structural integrity of the floor above. A suitably qualified timber and damp specialist should inspect the affected timbers and recommend appropriate repairs.

Repair: The landing, balcony, hallway, shared lobby, common room and sample detail 5 areas are damaged, creaking, badly cracked, sloping, in disrepair and sample detail 5. These should be repaired soon, and if the defect is considered significant, it should be promptly investigated by a qualified person and repaired.

G Services

Limitations

Services are concealed within the structure and cannot be fully inspected during a Home Survey. The inspection is visual only, and services are not assessed for safety, operation, efficiency, capacity, compliance with current regulations, or remaining service life. Comments are limited to the visible parts of the installation. Unless otherwise stated, services should be assumed to require routine maintenance appropriate to their age and use. Where there is any doubt about the condition or safe operation of a service installation, further inspection by an appropriately qualified specialist should be obtained before legal purchase commitment. It has been assumed that the necessary statutory compliance certificates, inspection records, and approvals are available where required. These documents have not been inspected as part of this survey and should be verified by your legal adviser before exchange of contracts. Where the condition or safety of a service installation cannot be assessed from a visual inspection, I may recommend further investigation by an appropriately qualified specialist and apply an appropriate Condition Rating. The inspection was limited by one or more of the following access restrictions, boxed-in services, stored items, fixed fittings, locked cupboards, floor coverings, or health and safety considerations. Concealed pipework, wiring, ductwork, and underground services could not be inspected.

G1 Electricity

sample detail 5

Metre: There is a mains electricity supply connected to the property, and the meter unit is located in an outside box, in the entrance hall, in the kitchen, in the garage and sample detail 5.

Metre not found: I did not find the electric meter. Please ask the vendor about the location of the mains electricity meter, as you must know where it is located.

Consumer unit: There is a consumer unit(s) installed in the entrance hall, in the kitchen, in the garage and in a communal cupboard.

Not found: I did not find the consumer unit(s). Please ask the vendor about the location of the fuse box, as you must know where it is located.

RCD Protection: The consumer unit incorporates RCD protection, surge protection and no visible RCD protection. The operation of protective devices has not been assessed.

Dated or Old: The installation appears to comprise dated or older electrical components and would require upgrading to current standards.

General Maintenance: Where the installation appears dated, altered, or poorly maintained, an Electrical Installation Condition Report (EICR) should be obtained before legal commitment.

Solar photovoltaic (PV) system: The property is fitted with photovoltaic (PV) panels installed on the roof slope(s). These generate electricity for use within the property, with any surplus potentially exported to the National Grid. No significant defects were apparent from the limited visual inspection. Routine maintenance should be carried out in accordance with the manufacturer's recommendations.

Battery storage/Inverter: A solar battery and/or inverter is in the loft and sample detail 5. These components were not assessed, and no comment can be made on their operation, performance, or remaining service life.

Electricity Repair

Poor Standards: The electrical system is below current standards because there are exposed wires, cracked fixtures, DIY work and sample detail 5 issues, and this is a safety hazard. You should ask an appropriately qualified person to inspect the electrical system and carry out required repairs or replacement(s). Although I do not know the extent of the repair and improvement works required, you should plan for partial or complete replacement.

Electrical installations should be inspected and assessed at intervals not exceeding ten years for owner-occupied properties, or on a change of ownership, in accordance with current guidance. If satisfactory evidence of a recent Electrical Installation Condition Report (EICR) is unavailable, you should instruct an appropriately qualified electrician, such as a NICEIC or NAPIT registered contractor, to inspect and test the installation, confirm its condition and safety, and provide a quotation for any necessary remedial works.

Condition rating is: 1.

G2 Gas and Oil

Testing: The gas installation and appliances were not assessed during this inspection. If satisfactory evidence of recent inspection or servicing is unavailable, a Gas Safe (or OFTEC for oil-fired systems) registered engineer should inspect and test the installation before legal purchase commitment and recommend any necessary remedial works.

Certification: The homeowner should be able to provide appropriate servicing and inspection records for the heating system and associated appliances, including boilers, fires, and other fixed heating appliances. Your legal adviser should verify that these documents are available before exchange of contracts.

sample detail 5

Capped gas: The gas supply is capped off. You should ask an appropriately qualified person to inspect the gas installation system.

Metre not found: I did not find the gas meter. Please ask the vendor about the location of the gas meter, as you must know where it is located.

Dated or Old: The installation appears dated or older and may require upgrading to current standards.

Oil tank: The property is served by an oil-fired heating system with a plastic, metal and sample detail 5 fuel storage tank located at the front garden, side garden, rear garden and sample detail 5. No significant defects were apparent from the limited visual inspection, and routine maintenance is recommended. Oil-fired appliances, associated equipment and storage tanks should be installed, serviced, and inspected annually by an OFTEC-registered engineer. Where the tank is located close to a watercourse, open drain or environmentally sensitive area, secondary containment (a bund) may be required to reduce the risk of pollution in the event of a leak. Where there is any doubt regarding the condition, installation or compliance of the oil storage tank or associated equipment, an OFTEC-registered engineer should inspect the installation and recommend any necessary remedial works before legal purchase commitment.

Old tank: Although I could see no problems with the existing tank, it is older, has a single skin (modern ones have a double skin) and no secondary containment. If your property is close to a stream or watercourse, when the tank is replaced, you will have to meet the current requirements. If you want to be sure, you should ask an appropriately qualified person to inspect the oil installation system now.

Condition rating is: 3.

G3 Water

sample detail 5

Stopcock found: There is an independent mains water supply to the property. The stopcock within the property is located under the stairs, in the bathroom, in the hall, in the garage and sample detail 5. Visible pipework and fittings were inspected where accessible. The water installation was not pressure assessed.

Lead rising: The visible incoming water supply pipe is lead. Lead pipework was commonly used before 1970 and may allow small amounts of lead to enter the drinking water, particularly in soft water areas, presenting a potential health risk (see Section J3 – Risks). You should obtain advice from your water supplier and consider replacing the lead pipework to eliminate this risk. Further information is available from the Drinking Water Inspectorate. You should obtain advice from your water supplier and arrange for replacement of the lead pipework where appropriate. Further guidance is available from the Drinking Water Inspectorate.

The visible water supply pipework comprises plastic and/or copper. Much of the plumbing is concealed within the structure, and the routing, support, joints, and condition of hidden pipework could not be assessed during this visual inspection. If there are any concerns regarding the plumbing installation or its condition, you should obtain further advice from a suitably qualified plumber before legal purchase commitment.

Condition rating is: 1.

G4 Heating

sample detail 5

No heating: The property does not have a fixed heating system. Although no repair is currently required, the absence of fixed heating may result in cold rooms, condensation, and mould growth. It is also likely to adversely affect the property's Energy Performance Certificate (EPC) rating and may impact its marketability. You should consider installing a suitable fixed heating system.

Heating not found: I was unable to locate the boiler or heating system. Please ask the vendor about the location of the boiler or heating system, as you must know where it is located.

Communal heating: The property is heated centrally by a communal heating system. I could not inspect the system due to access restrictions and cannot comment on the type and condition.

Heat emitters: The boiler is connected to radiators, ceiling vents, wall vents and sample detail 5 as heat emitters; their capacity, efficiency, and lifespan are not readily ascertained. I recommend these are serviced and demonstrated to yourselves, so you are satisfied with their performance under variable operational requirements.

Old boiler: Although no significant defects were apparent from the limited visual inspection, the boiler is older. Older boilers are less efficient and may become increasingly unreliable and costly to maintain. You should anticipate replacement as the boiler approaches the end of its serviceable life.

Forced Air Heating: The property is heated by a forced air heating system with the main unit located in the loft, garage, cupboard and basement. Warm air is distributed throughout the property via a network of ducts and vents. The installation was inspected visually only, and no operational testing or assessment of efficiency was undertaken. The property must be maintained in the normal way.

Air Source Heat Pump: Air Source Heat Pump: The property is heated by an air source heat pump with the internal unit located in the kitchen, garage and sample detail 5 and the external unit located to the side and rear of the property. The installation was inspected visually only. No operational testing or assessment of performance, efficiency or controls was undertaken.

Ground Source Heat Pump: Ground Source Heat Pump: The property is heated by a ground source heat pump with the internal unit located in the utility room, garage and sample detail 5. The associated ground collectors or boreholes are below ground and could not be inspected. The installation was inspected visually only. No operational testing or assessment of performance, efficiency or controls was undertaken.

Heating Repair

Repair: The radiator(s) in the lounge, bedroom and bathroom areas are leaking and damaged and may be causing damp to nearby elements. Although this is not yet serious, the problem can quickly get worse and damage other parts of the property. You should ask an appropriately qualified person to check this now and promptly resolve the situation. Where a significant leak has occurred causing damage to other parts of the property, this may indicate more widespread defects within the installation. A suitably qualified plumber/heating engineer should investigate the cause, carry out any necessary repairs, and inspect the remainder of the system without delay.

Any inspection, servicing or repair of the heating installation should be carried out by a Gas Safe registered engineer (or an OFTEC registered engineer for oil-fired systems). Appropriate servicing or commissioning records should be provided for the boiler, heating system, and any fixed heating appliances. Your legal adviser should verify that these records, together with any available warranties or guarantees, are available before legal purchase commitment.

Condition rating is: 2.

G5 Water Heating

sample detail 5

Not found. I was unable to locate the water heating system. Please ask the vendor about the location of the water heating system, as it is important that you know where it is located.

Communal water heating: The property has hot water centrally by a communal water heating system, gas-powered. It is likely to be metered or supplied as part of combined services. I could not inspect the system due to access restrictions and cannot comment on the type and condition.

Water heating: The hot water is provided by the combination boiler, conventional boiler, sealed boiler system, electrical boiler and sample detail 5 installed in the airing cupboard, utility room, bedroom, garage and loft. The property must be maintained in the normal way.

Electric Immersion: The hot water is provided by an insulated cylinder located in the airing cupboard, utility room, bedroom, garage and loft. The installation was inspected visually only. No operational testing or assessment of efficiency was undertaken.

Poor cylinder insulation: The hot water cylinder is not properly insulated. Hot water tanks store water for long periods, and there will be a waste of energy if these tanks and the adjacent pipes are not properly insulated. This should be insulated soon.

Point-of-use: Hot water is provided by individual electric point-of-use water heaters serving individual outlets or appliances. The installation was inspected visually only. No operational testing or assessment of performance, efficiency or remaining service life was undertaken. The installation was inspected visually only. No operational testing or assessment of efficiency was undertaken.

Solar water heating: The property is provided with a solar water heating (solar thermal) system to supplement the domestic hot water supply. The installation was inspected visually only, and no operational testing or assessment of performance was undertaken. Routine maintenance should be carried out in accordance with the manufacturer's recommendations. The installation appears to have been professionally completed; however, this cannot be confirmed during a visual inspection. Your legal adviser should verify that any required Building Regulations approval, commissioning documentation and any available warranties or guarantees are provided.

Solar thermal (hot water): The property is fitted with solar thermal panels installed on the roof slope(s). These use solar energy to heat water for the domestic hot water system. No significant defects were apparent from the limited visual inspection. Routine maintenance should be carried out in accordance with the manufacturer's recommendations. The installation appears to have been professionally completed; however, this cannot be confirmed during a visual inspection. Your legal adviser should verify that appropriate planning permission (where required), Building Regulations approval, commissioning certificates and any applicable MCS certification are available (see Section **I1** – Regulations). They should also confirm whether transferable warranties or guarantees exist for the installation (see Section **I2** – Guarantees). If the necessary approvals or certification are unavailable, further investigation should be undertaken before legal purchase commitment.

Condition rating is: 2.

G6 Drainage

sample detail 5

Cesspit (Cesspool): The property is connected to a cesspit (cesspool), which is an underground storage tank that collects foul waste and requires regular emptying by a licensed waste contractor. The installation was inspected visually only, and no assessment of its condition or capacity was undertaken. Your legal adviser should confirm ownership, maintenance responsibilities, and any records of regular emptying.

Public Sewer: The property is connected to the public sewer. The drainage system is either combined (foul and surface water sharing the same pipework) or separate (foul and surface water discharged through separate pipework). Parts of the drainage system may pass through neighbouring properties or surrounding lands.

No defects noted: No significant defects requiring immediate attention were identified unless otherwise stated below. Routine maintenance appropriate to the frame material should be expected.

Inspection Chamber: The inspection chamber cover(s) were lifted where possible. No blockage, recent blockage, significant defect and sample detail 5 was noted. The chambers should be inspected periodically to ensure they remain free flowing.

Not Inspected: The inspection chamber cover(s) could not be lifted, and the condition of the underground drainage system could not be assessed. Further inspection by a suitably qualified drainage contractor is recommended if required.

Shared Drainage: It is assumed that parts of the underground drainage system are shared with neighbouring property or properties. Your legal adviser should confirm your rights and responsibilities for maintenance and repair. Your legal adviser should confirm your responsibilities for the maintenance and repair of any shared drainage system.

Soil and Vent Pipe: The soil and vent pipe is visible at the rear, side and sample detail 5 of the property and is constructed of plastic, cast iron, asbestos cement and sample detail 5 material.

Visible/Partially Visible: The soil and vent pipe is fully concealed or concealed within the building, with only limited sections visible in the roof space and sample detail 5. The visible sections appeared satisfactory. The condition of concealed sections could not be assessed.

Drainage Repair

Inspection Chamber Cover: The inspection chamber cover(s) are broken, poorly secured and sample detail 5 and presents a safety hazard. It should be repaired or replaced without delay. The inspection chamber cover presents a safety hazard and should be repaired or replaced.

Inspection Chamber Walls: The inspection chamber walls are cracked, crumbling, damaged and sample detail 5. Repairs are recommended to prevent debris from entering and obstructing the drainage system.

Drain Channels: The drainage channels within the inspection chamber are cracked, poorly formed and sample detail 5. Repairs are recommended to prevent further deterioration and reduce the risk of blockages.

Soil and Vent Pipe Defects: The soil and vent pipe is damaged, corroded, leaking and inadequately supported. Repairs are recommended. Depending on its condition, replacement with a modern plastic system may be more economical.

Tree Root Ingress: Tree roots were noted within the inspection chamber, indicating defects in the underground drainage system. If left untreated, root ingress is likely to worsen and cause recurring blockages. A suitably qualified drainage contractor should investigate and recommend repairs.

Gullies: The above-ground rainwater and waste pipes discharge into gullies connected to the underground drainage system. The gullies are damaged, uncovered, completely blocked and sample detail 5. They should be cleared and repaired, as necessary. Blocked gullies can result in overflowing water and dampness to adjacent walls.

Asbestos Cement Soil Stack: The soil and vent pipe is constructed of asbestos cement. Provided it remains in good condition and is left undisturbed, it presents a low health risk. If alteration, removal, or replacement is proposed, advice should first be obtained from a suitably qualified asbestos specialist.

Inspection of the accessible inspection chamber(s) cannot confirm the condition of the concealed drainage system. Hidden defects may still be present and can only be identified by specialist testing, such as a CCTV drain survey.

Condition rating is: 1.

G7 Common Services

Not applicable: Other than the possibility of the drainage system being shared, there are no other common services to this property.

Description: Communal services and installations, including shared drainage, cleaning, lifts, communal heating, hot water systems, vehicular access, parking areas and sample detail 5 were not specifically assessed as part of this inspection. These installations are normally subject to maintenance contracts. Your legal adviser should confirm that appropriate maintenance arrangements are in place and establish your responsibilities for any associated service charges or future repair costs.

Condition rating is: 3.

I Issues

I1 Regulation

Property Alterations – Whether extensions, alterations, conversions, or structural modifications have the necessary Planning Permission, Building Regulation approval, Completion Certificates, and any other statutory consents.

New Build Property: Your legal adviser should confirm whether the property benefits from a recognised new home warranty (such as NHBC, LABC, Premier Guarantee or equivalent), the remaining period of cover, the extent of the protection provided, and whether all relevant completion certificates and warranty documentation are available.

Roof Alterations and Loft Conversions – Whether roof replacements, structural roof alterations or loft conversions have the necessary statutory approvals and completion certificates.

Converted Building: The property forms part of a building that has been converted from its original use into residential accommodation. Your legal adviser should confirm that the conversion and any subsequent alterations received the necessary Planning Permission (where required), Building Regulation approval, and Completion Certificate. They should also confirm that any associated guarantees, warranties, and statutory documentation are available and advise on any implications for the property's value, marketability, and mortgageability.

Replacement Windows and Doors – Whether replacement installations comply with Building Regulations and have appropriate certification.

Electrical Installation – Whether a recent Electrical Installation Condition Report (EICR) is available.

Gas Installation – Whether recent gas safety inspections and servicing records are available.

Asbestos – Whether asbestos surveys or asbestos management information are available where asbestos-containing materials are suspected.

Mining and Ground Stability – Mining, ground stability, or other relevant environmental searches where appropriate.

Trees – Whether Tree Preservation Orders, Conservation Area restrictions or other legal constraints apply.

Rights of Way and Easements – Rights of access, easements, wayleaves, covenants, and any other rights affecting the property.

Boundaries – Boundary ownership and maintenance responsibilities from the title documentation.

Private Roads and Shared Access – Maintenance responsibilities and associated financial obligations.

Drainage – The drainage arrangement, maintenance responsibilities, and compliance with current regulations where applicable.

Leasehold Property – Remaining lease term, ground rent, service charges, reserve fund contributions, planned major works, lease restrictions and repair obligations.

Freehold Property – Any restrictive covenants, estate charges or management arrangements affecting the property.

I2 Guarantees

Where applicable, your legal adviser should obtain copies of available guarantees, warranties, certificates, and supporting documentation relating to:

Window/doors: Replacement windows and external doors (including FENSA, CERTASS or Building Regulation certification).

Boiler: Boiler installations, servicing, commissioning documentation, and heating system warranties.

Structural alterations: Structural alterations, roof replacements, loft conversions and associated structural calculations or guarantees.

Timber treatment: Timber treatment works, including treatment specifications and contractor details.

Cavity insulation: Cavity wall insulation installation certificates, guarantees, and warranties.

Spray foam: Spray foam insulation installation details, guarantees and warranties, together with confirmation of any lender requirements.

Renewable energy: Renewable energy installations, including solar PV, solar thermal, battery storage, air source heat pumps, and ground source heat pumps, together with installation certificates, ownership details, maintenance agreements, warranties and any lease or finance agreements.

I3 Other Matters

Freehold Property: The property is understood to be held on a freehold basis. Your legal adviser should confirm the tenure, that vacant possession will be available on completion, and whether the title is subject to any restrictive covenants, easements, rights of way, or other matters that could affect the use, enjoyment, marketability, or value of the property. Your legal adviser should also confirm whether there are any estate rent charges, maintenance contributions, management company obligations, or other ongoing financial liabilities associated with the property. Where the property forms part of a managed estate or private development, enquiries should be made regarding the management arrangements, service or estate charges, planned maintenance works, and any outstanding financial liabilities or disputes.

Leasehold Property: Your legal adviser should also confirm the amount of any ground rent, service charges, reserve fund contributions, and whether these are reasonable. They should investigate the lease for any onerous covenants, restrictions, or unusual obligations that could affect the property's value, marketability, or future sale. Enquiries should be made of the landlord or managing agent to establish whether there are any outstanding service charges, planned major works, disputes, or significant future expenditure. Confirmation should also be obtained that appropriate buildings insurance and management arrangements are in place.

Share of Freehold Property: Where the property is held with a share of the freehold, your legal adviser should confirm the ownership structure, the remaining lease term, rights and obligations under the lease, responsibility for repairs and maintenance, service charges, reserve fund contributions, management arrangements, any restrictive covenants, and whether there are any planned major works or ongoing disputes affecting the building.

Flying Freehold: Where the property includes or is affected by a flying freehold, your legal adviser should confirm the extent of the flying freehold and ensure that adequate rights of support, shelter, protection, access for inspection, maintenance and repair are contained within the title. They should also confirm that there are no restrictions which could adversely affect the property's marketability or mortgageability, and that suitable indemnity insurance or other legal protection is available where required.

Rights of Way: The property may be affected by rights of way or other third-party rights. Your legal adviser should confirm whether any such rights exist and advise on any implications for the use, enjoyment, marketability, and value of the property.

Party Wall: The property shares one or more walls or structural elements with neighbouring property. Your legal adviser should explain any legal implications, including those arising under the Party Wall etc. Act 1996, where applicable, particularly if you intend to undertake structural alterations or certain repair works.

Tenanted Property: The property appears to be, or may be, occupied by a tenant. Your legal adviser should confirm whether the property will be sold with vacant possession on completion and advise on any tenancy agreements or occupiers' rights that may affect the purchase.

General Legal Enquiries: Your legal adviser should raise any additional enquiries considered appropriate following review of this report, the contract documentation, and the property title. The matters identified above arise from a visual inspection only and are intended to assist your legal adviser during the conveyancing process. They should not be regarded as a comprehensive list of legal enquiries, and your legal adviser should make any additional investigations considered appropriate.

J Risks

Risks

This section highlights risks identified during the visual inspection that may affect the property, its occupants or future maintenance. The comments are based solely on the condition observed at the time of the inspection. The Home Survey is a visual inspection only and cannot identify every potential risk. Where appropriate, further investigation by an appropriately qualified person is recommended.

J1 Risk To Building

Water Penetration: Evidence of roof leakage, penetrating damp, condensation and localised dampness was observed. The source should be identified and repaired to prevent further deterioration.

Timber Decay: Evidence of dry rot and localised timber decay was observed. The source of moisture should be identified and repaired before remedial timber works are undertaken.

Wood-Boring Insects: Evidence of active or historic wood-boring insect activity was observed. Further investigation by an appropriately qualified timber specialist is recommended where activity appears active or widespread.

Condensation: Evidence of condensation, surface mould growth and limited ventilation was observed. Maintaining appropriate heating and ventilation should assist in reducing condensation.

Drainage: Evidence of blocked gullies, standing water, poor surface drainage and localised ponding was observed. Maintenance or further investigation should be undertaken where necessary.

Tree defects: One or more trees are located close to the property. Detrimental effects on the property were noted. You should contact a qualified person for further investigation and advice.

The cement bedding around the base of the chimney pot (called flaunching) is damaged or defective and is causing damp penetration to the adjoining building elements (see section E1 - Chimney Stacks).

One or more chimney stack(s) is in poor condition. This is a safety hazard. Further investigation and repair should be arranged immediately (see section E1 - Chimney Stacks).

The roof slopes to the front, side and rear of the building appear uneven or undulating, and the adjoining wall appears distorted, cracked, bowing or leaning outwards (see section E2 - Roof Coverings).

One or more defects affecting the rainwater gutters, downpipes, associated fittings, and drainage arrangements were noted (see section E3 - Rainwater Goods).

One or more small beams that span across the top of the window or door opening, including brick arch (called a lintel), is damaged, cracked, distorted (see section E4 - Main Walls).

J3 Risk To People

Trip Hazards: Potential trip hazards were identified, including uneven paving, raised thresholds, uneven floor surfaces, loose floor coverings and damaged decking. Repairs should be undertaken to reduce the risk of injury.

Damaged Stairs: The staircase requires some repairs based upon a visual inspection. Where loose handrails, damaged balustrades or uneven treads are present, these should be repaired promptly. Also, defective guarding should be repaired without delay.

Electrical Safety: Visible defects were identified. Further inspection by a qualified electrician is recommended before legal commitment.

Gas Safety: Gas appliances and installations were not assessed. Where there is any doubt regarding their age, condition or maintenance history, inspection by a Gas Safe registered engineer is recommended before legal commitment.

Mould Growth: Localised mould growth associated with condensation was observed. Maintaining adequate heating and ventilation should assist in reducing further mould growth.

General Advice: The inspection identified matters requiring repair, maintenance, or further investigation. These should be considered before legal commitment and reflected in your future maintenance planning. Buildings require regular inspection and maintenance throughout their service life. Prompt attention to isolated defects will normally reduce the likelihood of more extensive deterioration and costly future repairs. Where specialist inspections have been recommended within this report, these should be obtained before legal commitment where practicable.

The design of one or more windows does not provide a suitable means of escape for occupants in the event of a fire (see section E5 - Windows).

Trip Hazards: Potential trip hazards were identified, including uneven paving, damaged steps, raised thresholds, uneven floor surfaces, loose floor coverings, damaged decking, other. Repairs should be undertaken to reduce the risk of injury.

The electrical system is below current standards because of observed defects, and this is a safety hazard (see section G1 - Electricity).

J2 Risk To Grounds

Sloping Ground: The property may be situated on moderately sloping ground. Sloping sites are more susceptible to drainage problems, erosion, ground movement, and retaining wall issues if not properly maintained. Regular monitoring and routine maintenance of drainage systems, external ground levels, and retaining structures (where present) are recommended to help minimise future risks.

Retaining Walls: Evidence of movement, bulging, cracking, deterioration was observed. Further investigation should be undertaken where structural stability appears affected and appropriate repair or rebuild organised.

Parts of the boundary fencing to the front, rear and communal garden are broken, leaning, loose in places, badly damaged and rotted in places. Defective boundary structures should be repaired where deterioration affects stability or security.

J4 Other

Airport: The property is located close to an airport and/or flight path. Aircraft operations may result in noise and disturbance, which could affect the enjoyment, marketability, and value of the property.

Train Station: The property is located close to a railway station. Associated rail operations, passenger activity, traffic, and noise may affect the enjoyment, marketability, and value of the property.

Motorway: The property is located close to a motorway. Traffic noise, air quality, and associated activity may affect the enjoyment, marketability, and value of the property.

Repair or improve the property

Further Investigations and Repairs: Where repairs or further investigations are recommended, you should obtain quotations from suitably qualified and reputable contractors before exchanging contracts. The results of these investigations, together with advice from your legal adviser, may influence your decision to proceed or the price you are prepared to pay. Until these enquiries have been completed, the extent and cost of any necessary remedial works cannot be confirmed. Proceeding with the purchase before obtaining this information means accepting the risk that additional defects or costs may become apparent after completion.

Capture floor/site plan sketches

K1 Valuation assumptions

Market Value: The opinion of market value reflects market conditions at the date of inspection and valuation. In some locations, limited housing supply and strong buyer demand may result in competitive bidding and prices above asking levels. Should market conditions change, or the property's condition deteriorate, its resale value may be adversely affected.

Flats: Unless confirmed otherwise by your legal adviser, the valuation has been prepared on the assumption that the property is held on a lease with an unexpired term of approximately 90 years and that there are no onerous lease terms or unusual liabilities that would adversely affect its value.