

AIRBUS INDUSTRIE
PRODUCT SUPPORT DIRECTORATE
1 Rond Point Maurice BELLONTE
31707 BLAGNAC CEDEX FRANCE

Tel: (33) 61-93-33-33 Telex: AIRBU 530526 F

SERVICE BULLETIN SUMMARY

This summary is for information only and is not DGAC approved for modification of the aircraft.

MODIFICATION No. None

ATA SYSTEM: 21

TITLE: AIR CONDITIONING - INSTALL FLEXIBLE DUCT P/N 21010017201 (FR20)

REASON/DESCRIPTION/OPERATIONAL CONSEQUENCES

Further to embodiment of Mod. 21058/P1357, NWA Aircraft MSN 031 and 034 were delivered with a too short flexible duct D21010017210. This Service Bulletin proposes to replace the flexible duct D21010017210 by a longer flexible duct D21010017201 corresponding to the Mod. 21058/P1357 definition.

EFFECTIVITY

This Service Bulletin is applicable to the following operators :

NWA

SERVICE BULLETIN/MODIFICATION TO BE ACCOMPLISHED PREVIOUSLY OR SIMULTANEOUSLY

None.

REFERENCES/REPERCUSSIONS

TFU None. LIFE LIMIT None.

OEB None. LINE MAINTENANCE AFFECTED

AOT None. NO

SIL None. OTHERS None.

5 DATE : Nov 07/89 SERVICE BULLETIN No. : A320-21-1024

REVISION No.: PAGE : 1 of 2

Printed in France

© A320

SERVICE BULLETIN SUMMARY

NATURE OF THE MODIFICATION

AIRCRAFT : Yes

EQUIPMENT : No

HARD : No

SOFT : No

OBRM : No

COMPLIANCE

Optional

MANPOWER

Manhours : 2

Elapsed Time (hours): 2

MATERIAL INFORMATION

Aircraft Data

Qty per A/C:

1 Flexible duct

Equipment Data

None

APPENDICES

Drawing D21210053

DATE: Nov 07/89 SERVICE BULLETIN No.: A320-21-1024

REVISION No.: PAGE : 2 of 2



AIRBUS INDUSTRIE
PRODUCT SUPPORT DIRECTORATE
1 Rond Point Maurice BELLONTE
31707 BLAGNAC CEDEX FRANCE

Tel: (33) 61-93-33-33 Telex: AIRBU 530526F SERVICE BULLETIN

MODIFICATION No. None

ATA SYSTEM: 21

TITLE: AIR CONDITIONING - INSTALL FLEXIBLE DUCT P/N 21010017201 (FR20)

1. PLANNING INFORMATION

A. EFFECTIVITY

(1) Aircraft Models: 320-211

(2) Aircraft

Customer and MSN Qty of Kits Fleet No. 211024A01

NWA 301,303 031, 034 2

This Service Bulletin is applicable only on A/C listed above.

(3) Spares

Flexible duct D2101001721000

B. REASON

Further to embodiment of Mod. 21058/P1357, NWA Aircraft MSN 031 and 034 were delivered with a too short flexible duct D21010017210. This Service Bulletin proposes to replace the flexible duct D21010017210 by a longer flexible duct D21010017201 corresponding to the Mod. 21058/P1357 definition.

C. DESCRIPTION

Accomplishment of this Service Bulletin consists in carrying out the following jobs on the aircraft:

(1) In avionics compartment aft of frame 20 on left side, replacement of the existing flexible duct by a longer flexible duct.

5 DATE: Nov 07/89 SERVICE BULLETIN No.: A320-21-1024

REVISION No. PAGE: 1 of 5

Printed in France

© A320

D. APPROVAL

This Service Bulletin is approved by Direction Générale de l'Aviation Civile - FRANCE (D.G.A.C).

E. MANPOWER

	mannours		
Gain access	0.5		
Modification	1		
Close-up	0.5		
TOTAL MANHOURS	2		
ELASPED TIME (HOURS)	2		

NOTE: This Service Bulletin assumes that the aircraft has been placed in a maintenance status. The manhours/elasped time estimates do not include preparation for the modification, non-productive elasped time, or administrative functions.

F. MATERIAL - COST AND AVAILABILITY

Refer to para. 3. MATERIAL INFORMATION.

G. TOOLING - PRICE AND AVAILABILITY

None.

H. WEIGHT AND BALANCE

None

I. REFERENCES

5 DATE : Nov 07/89

Aircraft Maintenance Manual: 06-41-52, 12-34-24, 24-41-00. Drawing D21210053

J. PUBLICATIONS AFFECTED

Illustrated Parts Catalog: 21-26-01

Printed in France SERVICE BULLETIN No. : A320-21-1024

REVISION No.

PAGE : 2



SERVICE BULLETIN

2. ACCOMPLISHMENT INSTRUCTIONS

A. GENERAL

- (1) Preparation
 - (a) De-energize the aircraft electrical circuits (Ref. AMM 24-41-00, P. Block 201) and electrically ground the aircraft (Ref. AMM 12-34-24, P. Block 201).
 - (b) Put the access platform in position.
 - (c) Open the avionics compartment access door No. 824 (Ref. AMM 06-41-52).

B. MODIFICATION

In avionics compartment, aft of frame 20 on left side:

Refer to Drawing D21210053 Sheet 1 and 2

(1) Remove:

1 Flexible duct

Item O (discard)

NOTE: The attachment hardware will be reused.

(2) Install the new flexible duct D2101001720100 Item 0 with the hardware retained at the removal.

C. TEST

None.

D. CLOSE-UP

- (1) Close the avionics compartment access door No. 824 (Ref.AMM 06-41-52).
- (2) Remove the access platforms.
- (3) Disconnect the aircraft electrical ground connection (Ref. AMM 12-34-24, P. Block 201).

DATE: Nov 07/89 SERVICE BULLETIN No.: A320-21-1024

REVISION No.: PAGE: 3-4

A320-21-1024

A. LIST OF COMPONENTS

I T NEW PART No. E M	QTY	DESCRIPTION	I T E M	OLD PART No.	I N T	INSTRUCTIONS/ DISPOSITION
Kit No. 211024	A01					
D2101001720100	1	Flexible duct		2101001721000		*

* Spares Purchase order

B. SPECIAL TOOLS

None.

C. LIST OF MATERIALS - OPERATOR SUPPLIED

None

D. PARTS TO BE RE-IDENTIFIED BY OPERATOR

None



AIRBUS INDUSTRIE
PRODUCT SUPPORT DIRECTORATE
1 Rond Point Maurice BELLONTE
31707 BLAGNAC CEDEX FRANCE

Tel: (33) 61-93-33-33 Telex: AIRBU 530526F SERVICE BULLETIN

MODIFICATION No. None

ATA SYSTEM: 21

TITLE: AIR CONDITIONING - INSTALL FLEXIBLE DUCT P/N 21010017201 (FR20)

IS BEING HEREWITH SUBMITTED TO YOU FOR REVIEW

Please fill:

... REJECTED

... WILL BE EMBODIED

... EFFECTIVITY

This SB can only be incorporated in your "customized" documentation within the agreed time schedule in so far as this sheet is returned to us on purchase date and signed by a duly authorized and empowered officer or representative.

FROM :
AIRLINE :
•••••
NAME :
•••••
DATE :
19

Please return to:

AIRBUS INDUSTRIE
PRODUCT SUPPORT DIRECTORATE
1 Rond Point Maurice BELLONTE
31707 BLAGNAC CEDEX FRANCE

Att.: AI/SP - Technical Publications
Department

5 DATE : Nov 07/89

SERVICE BULLETIN No.: A320-21-1024

REVISION No.

PAGE : 1 of 1