16K Model Resin - Clear

Post-Processing Instructions

Print

- On most 405nm LCD printers (Elegoo, Anycubic, Phrozen, etc.), good starting settings for printing this resin at a 50um layer height is a 13s burn layer exposure and 3.5s layer exposure.

Wash

- Carefully remove parts from the build plate and, if necessary, remove supports. Place parts in a sonicator or a vortex mixer filled with cleaning solution or solvent of your choice.
- Run the machine for 2 minutes.
- Remove the part and spray with compressed air to loosen up any resin trapped in cracks, crevices, and channels.
- Place parts back into cleaning solution and run for another 2 minutes.
- Repeat this process until the parts come out clean. Set on a clean napkin to allow the cleaning solution to evaporate and dry the parts.

Cure

- Our 16K Model Resin is a clear resin. To maximize clarity of finished prints, place parts in a 365nm cure box and run for 10 minutes.
- Parts will come out tinted slightly yellow/brown. Remove parts and place in a 40C oven for an hour or longer until the parts lose the tint.

16K Model Resin - Clear

Post-Processing Instructions

Tips

- For maximum clarity, sanding and buffing will improve surface smoothness.
- Alternatively, a clear coat spray paint or clear dip coat will bring about optical clarity if desired.
- Avoid placing parts in direct sunlight to avoid yellowing.