Lidar Error and Fix Summary

Error:
The robot used a Gazebo Classic style lidar definition with <ray> ... </ray>
inside a Gazebo Harmonic project. This caused the scan sensor to not match
the simulator requirements and the scan data was not behaving as expected.

Symptoms:
- Laser rays were not visualized correctly in Gazebo.
- /scan publication was unreliable or mismatched to the expected Gazebo sensor format.

Solution:
Updated the sensor from type="lidar" with <ray> to type="gpu_lidar" with
<lidar> ... </lidar>, while keeping visualize=true and the ROS bridge mapping
for Gazebo Transport topic scan -> ROS topic /scan as LaserScan.

Verification:
After the fix, the package built successfully and ros2 topic echo --once /scan
returned a valid LaserScan message with populated ranges and frame_id: scan_link.

This confirms the lidar is publishing correctly to ROS and the rays are enabled
for visualization in Gazebo.