

SENIOR DESIGN PROJECT – FINAL REPORT

P2021-16

IDENTIFICATION AND IMPROVEMENT OF FACTORS AFFECTING WORKER PERFORMANCE IN ÖREN KABLO

By

Ahmet Kaan DOĞAN

Ayda AHMETOĞLU

Hüsniye Ece KURT

Mustafa Mert KILIÇ

Sevinç Canan ÖZ

Supervised By

Prof. Fatma Canan ÇİLİNGİR

Assoc. Prof. Cemal Deniz YENİGÜN

Department of Industrial Engineering İstanbul Bilgi University 2021 The system, process or product addressed in this project;

has multiple components and includes various subsystems	4
concerns more than one discipline	4
requires solving complex problems for its analysis and design	4

This project has been designed under the following realistic constraints and conditions (all or that apply) which are discussed in a separate paragraph in the conclusion section.

Economic Considerations	
Environmental Considerations	
Sustainability	
Applicability	
Ethical Considerations	4
Social and Political Considerations	

We hereby certify that this pro-	oject is our own	work, except where indicated by
referencing.		1 —
Ahmet Kaan DOĞAN		1009
Ayda AHMETOĞLU		- Johl Jave
Hüsniye Ece KURT		Ece Kunta Mars Holiz
Mustafa Mert KILIÇ		Mar D'Avlez
Sevinç Canan ÖZ		<u>— Lunan</u>
This project is designed for fulf	illment of prograr	m requirements.
Prof. Fatma Canan Çilingir	(Supervisor)	
Assoc Prof Cemal Deniz Yenigiin	(Supervisor)	

1.	INTRODUCTION	9
	1.1. Overview	9
	1.2. About Ören Kablo	9
	1.3. Problem Definition	11
2.	LITERATURE REVIEW	12
	2.1. Risk Analysis Method	13
	2.1.1. Failure Mode and Effects Analysis (FMEA) Definition	13
	2.1.2. Auxiliary Elements Used in FMEA Analysis	13
	2.1.3. FMEA Implementation Steps	14
	2.2. Ergonomic Risk Assessment Tools	14
	2.2.1. Ovako Working Posture Analyzing System (OWAS) Method	14
	2.2.2. The National Institute for Occupational Safety and H	Iealth
	(NIOSH) Lifting Equation Method	16
	2.3. Work Measurement Techniques	20
	2.3.1. Work Sampling Defined	20
	2.3.2. When is Work Sampling Appropriate?	21
	2.3.3. Work sampling is an 8 step process: [9-10]	21
3.	METHODOLOGY	23
	3.1. FMEA	23
	3.2. OWAS	23
	3.3. NIOSH	24
	3.4. Work Sampling	24
4.	METHOD IMPLEMENTATION	25
	4.1. Data Analysis for Work sampling	25
	4.1.1. Determination of Sample Size	25
	4.1.2. Determination the Number of Observations Per Day	25
	4.1.3. Determination of Performance Rate	26
	4.1.4. Determination of Allowances	27
	4.2. FMEA Implementation	28
	4.2.1. Determination of Severity Score	28
	4.2.2. Determination of Detection Score	29
_	4.2.3. Determination of Occurrence Score	30
5.	DISCUSSION & RESULTS	32
	5.1. FMEA	32
	5.2. OWAS	33
	5.3. NIOSH	40
	5.4. WORK SAMPLING	43
	5.4.1. Machine Base Observations for EC 400 CAT 6 5.4.2. Allowances	45
	5.4.2. Allowances 5.4.3. Finding normal time & Standard Time	50 51
6.	CONCLUSION	51 54
0.	6.1. Checklist	5 4
7.	RECOMMENDATIONS	57 57
8.	COVID-19 EXPERIENCES IN OREN CABLE	57 58
9.	REFERENCES REFERENCES	50 60
10.	APPENDIX	62
10.	10.1. Work Sampling Sheets	62

LIST OF FIGURES

Figure 1.2.a: Scheme of the cable manufacturing process

Figure 1.2.b: Scheme of the EC400 CAT 6 U/UTP cable manufacturing process

Figure 1.3.a: Fishbone for low worker performance

Figure 2.2.1.a: Classification of postures with OWAS

Fig. 2.2.1.b: OWAS evaluation and result interpretation

Figure 2.2.2.a: Representation of NIOSH Variables

Figure 2.2.2.b: Representation of Angle

Figure 2.3.3.a: Standard Deviation

Figure 2.3.3.b: Sample size

Figure 2.3.3.c: Confidence intervals

Figure 2.3.3.d: Normal Time

Figure 2.3.3.e: Standard Time

Figure 5.2.a: Posture of label pasting on Reel

Figure 5.2.b: Posture of reel drag on reel

Figure 5.2.c: Roller Cradle

Figure 5.2.d: Posture of putting reel-1

Figure 5.2.e: Posture of putting reel-2

Fig. 5.2.f: Posture of carrying reel-1

Fig. 5.2.g: Posture of carrying reel-2

Figure 5.2.h: Hydraulic lift

Fig. 5.2.i: Posture of measuring

Fig. 5.3.a: Posture of lifting reel

Figure 5.3.b: Posture of lifting reel to second row

LIST OF TABLES

- *Table 2.2.2.a: Interpretation of Lifting Index*
- Table 2.2.2.b: Horizontal Multiplier Factor Spreadsheet
- Table 2.2.2.c: Vertical Multiplier Factor Spreadsheet
- Table 2.2.2.d: Distance Multiplier Factor Spreadsheet
- Table 2.2.2.e: Angle Multiplier Factor Spreadsheet
- Table 2.2.2.f: Coupling Multiplier Factor Spreadsheet
- Table 2.2.2.g: Frequency Multiplier Factor Spreadsheet
- Table 4.1.2.a: Work sampling data collection sheet
- Table 4.1.3.a: Average daily performance ratings for KULE (KNG-06) machine
- Table 4.1.3.b: Average daily performance ratings for CAT (KNG-08) machine
- Table 4.1.4.a: Allowance table Table 4.2.1.a: Severity rating chart
- Table 4.2.2.a: Detection Ranking Chart
- Table 4.2.3.a: Occurrence rating chart
- Table 4.2.3.b: Marking error data for 2020
- Table 4.2.3.c: Marking error data for 2021
- Table 4.2.3.d: Part of final FMEA table, marking error
- Table 5.1.a: Final FMEA Table
- Table 5.2.a: OWAS application results for label pasting
- Table 5.2.b: OWAS application results for reel drag
- Table 5.2.c: Technical specifications of roller cradle
- Table 5.2.d: OWAS application results for putting reel-1
- *Table 5.2.e: OWAS application results for putting reel-2*
- Table 5.2.f: OWAS application results for carrying reel-1
- Table 5.2.g: OWAS application results for carrying reel-2
- Table 5.2.h: Technical specifications for lifting apparatus
- Table 5.2.i: OWAS application results for measuring
- *Table 5.3.a: NIOSH application results for lifting reel*
- Table 5.3.b: NIOSH application results for lifting reel to first row on the palette
- *Table 5.3.c: NIOSH application results for lifting reel to second row*
- Table 5.3.d: NIOSH application results for lifting reel to third row
- Table:5.3.e: NIOSH application result after adjustments made
- Table 5.4.a: Activity categories
- Table 5.4.b: Idle times values

- Table 5.4.c: Sample worker data for one
- Table 5.4.1.a: EC 400 CAT 6 observations for KULE (KNG-06) Machine
- Table 5.4.1.b: EC 400 CAT 6 observations for CAT (KNG-08) Machine
- Table 5.4.1.c: Working (EC 400 CAT 6) Proportions for KULE (KNG-06) Machine
- Table 5.4.1.d: Working (EC 400 CAT 6) Proportions for CAT (KNG-08) Machine
- Table 5.4.1.e: Working & Idle Proportion for Both Machines
- Table 5.4.1.f: Number of EC CAT 6 Observations for Both Machines
- Table 5.4.1.g: Total Error Rate for Both Machines
- Table 5.4.1.h: Error Rate for CAT (KNG-08) Machine
- Table 5.4.1.i: Error Rate for KULE (KNG-06) Machine for Type of 1000m Reel
- Table 5.4.1.j: Error Rate for KULE (KNG-06) Machine for Type of 5000m Reel
- Table 5.4.1.k: Error Rate for KULE (KNG-06) Machine Type of 6000m Reel
- Table 5.4.2.a: Idle category observations for EC 400 CAT6 for KULE (KNG-06) Machine
- Table 5.4.2.b: Idle category observations for EC 400 CAT 6 for CAT(KNG-08) Machine
- Table 5.4.3.a: Normal & standard time for KULE (KNG-06) machine for type of 1000m EC 400 CAT 6 Reel
- Table 5.4.3.b: Normal & standard time for KULE (KNG-06) machine for type of 5000 & 6000 m EC 400 CAT 6 Reel
- Table 5.4.3.c: Normal & standard time for CAT (KNG-08) machine for type of 500 m EC 400 CAT 6 Reel

1. INTRODUCTION

1.1. Overview

Business efficiency relies on multiple variables, such as worker's productivity, facility planning, production planning, quality of communication, cost control and human-oriented management. All requirements should be considered together in order to be a profitable and productive business and correct solutions should be pursued. Quality is one of the most important details that all companies try to develop and protect. Today, worker performance and environmental factors should be considered in order to maintain this quality. In this study, we will define the problems that we may encounter in the company that we are working on, investigate the causes of these problems and offer the necessary actions.

We picked a cable production company called Ören Kablo to work on and focused on the measuring department which is the final step of the assembly line, due to the firm's request. In this department, cables are cut according to customers' specs from bigger reels that were previously manufactured and winded in house.

We decided to pick a sample product to analyse and improve that can set an example for all other cable types. Our analysis on past data revealed that the most demanded cable by customers is EC 400 CAT6 U/UTP and its subcategories.

The factory may lack worker performance efficiency. We have to take into account the worker performances in the measuring department. We can provide performance efficiency to the worker and improve the process by making ergonomic improvements. Our main focus will be to increase worker and machine productivity. On the other hand, there are some difficulties about detecting the errors of measuring, workers and employees could not get used to the system, so systemized data flow into the system could not be possible. These missing data cause the company to have difficulty in identifying the error rates and the reasons behind these errors. We want to detect and prevent possible errors in the measuring department. Another point we will focus on is to reduce the loads on the musculoskeletal systems of the employees and to calculate the standard time with work sampling.

1.2. About Ören Kablo

Ören Kablo is the first coaxial cable manufacturer founded by Rıza Reçber in 1979 and has been operating as a family company since its establishment. Ören Kablo, who carries out its production activities in its manufacturing facilities located in the Silivri Ortaköy

Industrial Area, recognizes the broad variety of manufacturing products, for example, signal order links, satellite TV, advanced satellite, fire warning cables, information links, CAT5, CAT6 LAN links and intelligent TV links; and simultaneously, offers to the utilization of its customers the low fume and flame retarding adaptations of "halogen free" link, which is otherwise called "flame resistant link".




Figure 1.2.a: Scheme of the cable manufacturing process

<u>Isolation</u>: A plastic protective sheath is covered around the conductive wire in order to prevent the conductive wires from touching each other, to prevent short circuits and to protect the cables from external factors.

Bending: In order to reduce Electromagnetic interference (EMI), radio frequency interference (RFI) and crosstalk on the electronic signal, conductive wires that are isolated are combined with the help of wicks.

<u>Hooping</u>: The materials that distinguish one element from another in cable production are separator tapes and coils. In addition to its function as a separator, aluminium foil or spool is pulled on the outside of the conductive wire in order to take on functions such as fire barrier, moisture barrier and shield.

<u>Braiding</u>: In order to prevent the signals carried by the cable from being affected by electromagnetic disturbances in the environment where the cable is located, to increase the mechanical strength and to provide flexibility, a screen is drawn.

<u>Sheathing</u>: It is the sheath process made to the outside of the cable to protect the cable from external factors.

Measuring: At the end of the whole process, it is the part where the order is cut and packaged in desired sizes. There are 4 types of machines used in the measuring department. One of them is the automatic machine BMAC (KNG-01), the other two are the

semi-automatic CAT (KNG-08) and AYMAK (KNG-07), and the last is the manual KULE (KNG-06) machine.




Figure 1.2.b: Scheme of the EC400 CAT 6 U/UTP cable manufacturing process

The company supplies its raw materials in line with the order received from the customer before starting the production stages. Then, the conductive (copper) raw material, which is ready to be processed, first enters the insulation line. In this line, a protective insulating sheath is placed over the wire. Then, these sheathed wires are twisted around this wick with the help of an insulating cord to form a round and flexible cable. Then, our twisted cable is covered with a protective sheath by passing to the outer sheath line. As the last process, it is cut to the size requested by the customer, packaged and ready to install.

The outer sheath of 1 meter of the cable we have shown has a weight of 12.52 grams, an insulation weight of 3.71 grams, a copper weight of 17.28 grams, and the weight of the roving 2.76 grams. In total, 1 meter corresponds to 36,271 gr. When we consider it based on kilometres, the total weight of our cable and the weight of our reel is 44 kg/km. Here, the weight of our empty reel turns out to be 7,729 kg.

Empty Reel Weight: Total Weight - Weight of Cable Based on Km

$$= 44-36,271 = 7,729 \text{ kg}$$

1.3. Problem Definition

Firms carry out many studies and developments in order to increase the worker's efficiency. This requirement has also emerged in Ören Kablo. The management complained about the low performance of the workers and guided us to work in this field. The company, which has been operating as a family company since its establishment, needs improvements in the production process on the way to institutionalization. This requirement has arisen due to

low performance of workers, the lack of planning about standardized machine speed variations in the production process and unsuitable ergonomic conditions. As a result of this situation, the purpose of our project is to increase the efficiency of the measurement process in Ören Kablo and the efficiency of the workers working in this field, to increase the satisfaction and to create the most comfortable and optimum working conditions during working hours by analysing the ergonomic factors in detail. Quality of measurements may be related to performance issues. We will also deal with quality problems, one of the factors of performance and productivity. We created a fishbone diagram to understand the reasons for low worker performances in the company. It has been noted that low performance may decrease due to factors such as workers, environment, machine etc.




Figure 1.3.a: Fishbone for low worker performance

2. LITERATURE REVIEW

Our main focus is to increase worker performance, improve ergonomic factors, and detect and prevent possible errors in the measuring department. Many studies in the literature have shown us that the FMEA technique is used in many companies to detect errors.

In order to determine musculoskeletal risks and take preventive measures, OWAS posture analysis method can be applied for ergonomic evaluation. OWAS is widely used for posture analysis because of its simple application and its suitability for every business.

After the observations done in the company, ergonomic risk analysis methods, standard time and work sampling methods have been used which have been decided as a

better method to implement and achieve precise results and reduce the differences between operating speeds of machines.

2.1. Risk Analysis Method

2.1.1. Failure Mode and Effects Analysis (FMEA) Definition

FMEA is a scientific technique that appeared on November 9, 1949 under the name of "Procedures for the Analysis of Error Type, Effects and Risk", which was made to determine the effects of system errors in the US army. [1]

As can be understood from the name, FMEA technique detects errors and takes preventative measures, which provides a computable and algorithmic perspective; this will form the basis of our article. With this method, errors are investigated down to the root causes that cause these errors. It examines potential errors that may occur from the design phase of a product, including the production phase of that product.

2.1.2. Auxiliary Elements Used in FMEA Analysis

<u>Item</u>: An "item" is the focus of the FMEA project.

<u>Function</u>: A "function" is what is supposed to be achieved by the object or procedure, usually to a specified output or requirement level.

<u>Failure Mode</u>: A "failure mode" is the manner in which the object or procedure can fail to fulfill the intended purpose and related specifications or produce them.

Effect: An "effect" is the consequence of the failure on the system or end user.

<u>Severity</u>: A "severity" is a ranking number associated with the most serious effect for a given failure mode.

Occurrence: An "occurrence" is a rating number synonymous with the chance that in the object being evaluated, the failure mode and its associated cause will be present.

<u>Detection</u>: A 'detection' is a rating number correlated with the best control from the detection-type controls set, depending on the detection scale criterion.

<u>Cause</u>: A "cause" is the specific reason for the failure, preferably found by asking "why" until the root cause is determined.

<u>Risk Priority Number (RPN)</u>: "RPN" is a numerical ranking of the risk of each potential failure mode/cause, made up of the arithmetic product of the three elements:

RPN = Severity * Occurrence * Detection.

If RPN < 40 does not need any regulation.

RPN is between 40 and 100 improvements should be made.

RPN >100, necessary arrangements should be made as soon as possible.

There are four basic types of FMEA in the literature: Design FMEA, Service FMEA, System FMEA and Process FMEA [2]. This study focuses on the "Process FMEA" method. Process FMEA is the analysis made in order to eliminate the types of errors that may occur in the production or assembly processes and to examine why the processes cause this error.

2.1.3. FMEA Implementation Steps

First of all, the purpose and scope of the study is determined. FMEA technique reveals a team approach as a tool that allows all relevant personnel and units to exchange ideas within the framework of the study [3].

The process to be improved is examined. By analysing the subsystems that make up the error types, the root causes that cause the error are determined and how the error types occur is determined.

After examining the process, a risk assessment is made. In order to eliminate the main causes of the error, RPN values of each main cause are calculated first. Errors with the highest Risk Priority Number will be the first step in intensifying corrective implementations and will continue in turn. Corrective actions are applied sequentially according to the calculated RPN values.

2.2. Ergonomic Risk Assessment Tools

2.2.1. Ovako Working Posture Analyzing System (OWAS) Method

The Ovako Working Posture Assessment System (OWAS) was formulated in Finland, specifically in the OVAKO OY company, a leading European producer of steel bars and profiles. This system was used to evaluate the workload in the repair process of smelting furnaces

OWAS is an observational working posture analysis method that helps to determine the load on the musculoskeletal system of the employee and the bad postures caused by the system. OWAS method successfully used in different industrial applications; ergonomic evaluation of the postural load, reducing the load on the musculoskeletal system, development and planning of working environments, working methods, machinery and tools used, occupational health examinations, it is implemented to ensure safety and efficiency. [4]




Figure 2.2.1.a: Classification of postures with OWAS [5]

The body postures of the employees are classified according to the power consumed. In the OWAS method, 252 standard stance and load combinations are obtained when 4 back, 3 arm, 7 leg stances and 3 different load levels are taken into account.

		Legs																				
Back Arm	Arms	1			2		3	3		4		5		6		7						
Back	AIIIIS	Load			Load		Load			Load		Load		Load			Load					
		1	2	3	1	2	3	1	2	3	1	2	3	1	2	3	1	2	3	1	2	3
	1	1	1	1	1	1	1	1	1	1	2	2	2	2	2	2	1	1	1	1	1	1
1	2	1	1	1	1	1	1	1	1	1	2	2	2	2	2	2	1	1	1	1	1	1
	3	1	1	1	1	1	1	1	1	1	2	2	3	2	2	3	1	1	1	1	1	2
	1	2	2	3	2	2	3	2	2	3	3	3	3	3	3	3	2	2	2	2	3	3
2	2	2	2	3	2	2	3	2	3	3	3	4	4	3	4	4	3	3	4	2	3	4
	3	3	3	4	2	2	3	3	3	3	3	4	4	4	4	4	4	4	4	2	3	4
	1	1	1	1	1	1	1	1	1	2	3	3	3	4	4	4	1	1	1	1	1	1
3	2	2	2	3	1	1	1	1	1	2	4	4	4	4	4	4	3	3	3	1	1	1
	3	2	2	3	1	1	1	2	3	3	4	4	4	4	4	4	4	4	4	1	1	1
	1	2	3	3	2	2	3	2	2	3	4	4	4	4	4	4	4	4	4	2	3	4
4	2	3	3	4	2	3	4	3	3	4	4	4	4	4	4	4	4	4	4	2	3	4
	3	4	4	4	2	3	4	3	3	4	4	4	4	4	4	4	4	4	4	2	3	4

1-No actions required 2-Corrective actions required in the near future 3-Corrective actions should be done as soon as possible 4-Corrective actions for improvement required immediately

Fig. 2.2.1.b: OWAS evaluation and result interpretation [6]

Four risk groups are used to categorize the posture combinations found. The experts' predictions of the health risks posed by each working posture and combination of postures on the musculoskeletal system are used to classify these positions.

Category 1: Working postures have no negative consequences for the musculoskeletal system. There is no need for an ergonomic setup for these postures.

Category 2: The musculoskeletal system is negatively affected by working postures. Future plans should include required ergonomic arrangements.

Category 3: The musculoskeletal system is obviously harmed by working postures. Working stops should make the required ergonomic arrangements as soon as possible.

Category 4: The musculoskeletal structure is severely harmed by working postures. The required ergonomic arrangements for these postures should be made right away.

2.2.2. The National Institute for Occupational Safety and Health (NIOSH) Lifting Equation Method

The National Institute for Occupational Safety and Health (NIOSH) was established in Section 22 of the Occupational Safety and Health (OSH) Act of 1970 and placed in the Department of Health and Human Services (HHS). As the service sector grew in the 1980s, NIOSH led pioneering research on emerging safety and health concerns. These included indoor environmental quality in office buildings, job-related musculoskeletal injuries, work-place violence, latex allergy among health care workers, and risks of occupational exposures to bloodborne pathogens. As the workplace changed, NIOSH continued to adapt its research. [7]

Definition of the NIOSH Lifting Equation

With the NIOSH lifting equation (empirical), we will determine the ergonomic risks of employees during lifting and carrying the reels. The aim is to determine in advance the risk that will cause lower back discomfort due to lifting / lowering.

Recommended Weight Limit (RWL): Indicates what is the recommended weight under these conditions.

RWL = LC (23) \times HM \times VM \times DM \times AM \times FM \times CM

- LC, the Load Constant,
- HM, the Horizontal Multiplier factor,
- VM, the Vertical Multiplier factor,
- DM, the Distance Multiplier factor,
- AM, the Asymmetric Multiplier factor.
- FM, the Frequency Multiplier factor,
- CM, the Coupling Multiplier factor.

Lifting Index Value	Risk Implication	Recommended Action				
(Exposure Level)						
LI ≤1.0	Very Low	None in general for the healthy working population				
1.0 <li td="" ≤1.5<=""><td>Low</td><td>In particular pay attention to low frequency/high load conditions to</td>	Low	In particular pay attention to low frequency/high load conditions to				
		extreme or static postures. Include all factors in redesigning tasks or				
		workstations and consider efforts to lower the LI to values ≤ 1.0				
1.5 <li td="" ≤2.0<=""><td>Moderate</td><td>Redesign tasks and workplaces according to priorities to reduce</td>	Moderate	Redesign tasks and workplaces according to priorities to reduce				
		the LI, followed by analysis of results to confirm effectiveness.				
2.0 <li≤3.0< td=""><td>High</td><td>Changes to the task to reduce the LI should be a high priority.</td></li≤3.0<>	High	Changes to the task to reduce the LI should be a high priority.				
LI>3.0	Very High	Changes to the task to reduce the LI should be made immediately.				
For Any level						
of Risk/Exposure	Identify any work	ers who may have special needs or vulnerabilities in lofting tasks and assign				
	or design the work	accordingly. Training workers on recognizing and eliminating material				
	handling hazards is regarded as beneficial. Limiting the weight to be lifted, to less than the					
	Reference Mass m	nay also be considered.				

Table 2.2.2.a: Interpretation of Lifting Index [8]

Lifting Index (LI): Shows how high the risk is.

Horizontal Location of the Hands (H): Distance of hands on the load from midpoint between ankles

HM = 1	for	H<=25 cm
HM = 25/H	for	25 cm < H <=63 cm
HM = 0	for	63 cm > H

Table 2.2.2.b: Horizontal Multiplier Factor Spreadsheet




Figure 2.2.2.a: Representation of NIOSH Variables

Vertical Location of the Hands (V): Starting height of the hands from the ground.

VM = 1 - (0.003*(V-75))	for	V<=175 cm
VM = 0	for	V >175 cm

Table 2.2.2.c: Vertical Multiplier Factor Spreadsheet

Distance(D): Vertical travel distance of the lift.

DM = 1	for	D<=25 cm		
DM = 0.82 + (4.5/D)	for	25 cm < D<=175 cm		
DM = 0	for	175 cm >D		

Table 2.2.2.d: Distance Multiplier Factor Spreadsheet

Asymmetric Angle (A): Angle of the load in relation to the body.

AM =(1-0.0032*A)	for	A <=135° cm
AM = 0	for	A >135° cm

Table 2.2.2.e: Angle Multiplier Factor Spreadsheet




Figure 2.2.2.b: Representation of Angle

Coupling (C): Quality of the grasp or handhold based on the type of handles available.

Coupling Multiplier

Coupling	Coupling Multiplier				
Туре	V< 30 inches (75 cm)	V ≥ 30 inches (75 cm)			
Good	1.00	1.00			
Fair	0.95	1.00			
Poor	0.90	0.90			

Table 2.2.2.f: Coupling Multiplier Factor Spreadsheet

Frequency (F): Time between lifts or frequency of lifting.

	Frequency Multiplier Table											
		Work Duration										
Frequency Lifts/min	≤1	1	> 1 but ≤	2 Hours	> 2 but ≤ 8 Hours							
	V < 30	V ≥ 30	V < 30	V ≥ 30	V < 30	V ≥ 30						
≤ 0.2	1.00	1.00	.95	.95	.85	.85						
0.5	.97	.97	.92	.92	.81	.81						
1	.94	.94	.88	.88	.75	.75						
2	.91	.91	.84	.84	.65	.65						
3	.88	.88	.79	.79	.55	.55						
4	.84	.84	.72	.72	.45	.45						
5	.80	.80	.60	.60	.35	.35						
6	.75	.75	.50	.50	.27	.27						
7	.70	.70	.42	.42	.22	.22						
8	.60	.60	.35	.35	.18	.18						

9	.52	.52	.30	.30	.00	.15
10	.45	.45	.26	.26	.00	.13
11	.41	.41	.00	.23	.00	.00
12	.37	.37	.00	.21	.00	.00
13	.00	.34	.00	.00	.00	.00
14	.00	.31	.00	.00	.00	.00
15	.00	.28	.00	.00	.00	.00
> 15	.00	.00	.00	.00	.00	.00

Table 2.2.2.g: Frequency Multiplier Factor Spreadsheet

Load (L): Determine the weight of the object lifted.

2.3. Work Measurement Techniques

For determining standard time, following methods have been examined:

- → Direct time study (DTS)
- → Predetermined motion time system (PMTS)
- → Standard data systems (SDS)
- → Work sampling

Two of these are evaluated as appropriate to our work environment:

- Work sampling
- Direct time study (DTS)

After a detailed discussion with the supervisors of this research, we decided that work sampling fits best to this project; considering the company preferences and available conditions

2.3.1. Work Sampling Defined

Work sampling is a technique that utilizes a predefined number of instantaneous observations in a period, of a process/workers/machines. It is a statistical technique for determining the proportions of time spent by subjects in various defined categories of activity.

- Subjects = workers, machines
- Categories of activity = setting up a machine, producing parts, idle, etc.

- For statistical accuracy
- Observations must be taken at random times
- Period of the study must be representative of the types of activities performed by the subjects

2.3.2. When is Work Sampling Appropriate?

When sufficient time is available to perform the study,

When several weeks usually required for a work sampling study,

When multiple subjects,

When work sampling suited to studies involving more than one subject,

When long cycle times for the jobs covered by the study,

When nonrepetitive work cycles,

When jobs consist of various tasks rather than a single repetitive task.

2.3.3. Work sampling is an 8 step process: [9-10]

Defining the purpose and target:

Defining a purpose and then detecting the related work equipment and workers.

Determining the workflow types:

Defining the workflow types and their detailed explanation.

Route planning:

Planning the trip in the field, on a map.

Determine observation amount / sample size:

With a determined error rate, calculating the sample size with the given formula.

N: Number of observations desired (sample size)

- z: The number of standard deviations at the desired level of confidence
- p: Occurrence rate in the sample
- q: The rate of not being in the sample
- h: Absolute error amount (sample size accuracy limits, precision)

σ : Standard deviation of the element distribution

$$\sigma = \sqrt{\frac{p \, q}{N}} \qquad \qquad \sigma = \frac{h}{z}$$

Figure 2.3.3.a: Standard Deviation

$$N = \frac{p(1-p)}{\left(\frac{h}{z}\right)^2}$$

$$N = \frac{z^2 p(1-p)}{h^2}$$

Desired Confidence Level %	Z value
90.0	1.65
95.0	1.96
95.4	2.00
99.0	2.58
99.7	3.00

Figure 2.3.3.b: Sample size

Figure 2.3.3.c: Confidence intervals

Determine random observation times:

Generating random numbers and converting them to date/hour and using it as the individual observation times.

Do the observations as planned:

Observation phase

Pre-evaluation:

If the p value is acceptable, continue to evaluation; if not, determine new values and repeat again

Evaluation:

Evaluate the final results of the work sampling process.

Analyst judges the performance or pace of the worker relative to the definition of standard performance used by the organization

- Standard performance PR = 100%
- Slower pace than standard PR < 100%
- Faster pace than standard PR > 100%

$$T_{ni} = \frac{p_i(TT)(\overline{PR_i})}{Q_i} \qquad T_{stdi} = T_{ni}(1 + A_{pfd})$$

Figure 2.3.3.d: Normal Time

Figure 2.3.3.e: Standard Time

3. METHODOLOGY

3.1. FMEA

The company's measuring department is the last department of the production line. It is possible to detect many errors here and it is the last detection part of the error as the finished product is out of production. According to the feedback received from the company, we applied the FMEA technique in the measuring department to detect and prevent the problems encountered in this department. For the FMEA part, we determined the new error types we received and asked the experts to rate these error types' severity and detection scores. Since the company has started to keep more smooth and healthy data in the last months compared to the previous months, we easily obtained the occurrence values. We found the RPN values that are important to us by processing them together with the detection and severity values we received from the experts. The RPN values for incorrect marking, sheath surface dirt / rough, open on sheath surface, colour tone difference error types are excessive and precautionary measures should be taken.

3.2. OWAS

While applying the OWAS method, we determined the appropriate angles and took photos of the workers during our company visits to determine the postures (back, arm, leg and weight) required to apply the OWAS method. Then analyzed the collected data with software. OWAS analysis was evaluated according to figures 2.2.1.a and 2.2.1.b, the positions were evaluated and the risk priority numbers were determined. With the classification of the results, the need for improvement has been proven; the company has been informed and recommendations have been made.

3.3. NIOSH

We applied the equation to the MT (Carrying reel) process of the workers to determine if lifted weights damage the postures and find the RWL (recommended weight limit). This equation is not viable for processes involving dragging and walking.

We intended to use oxygen consumption to determine the energy expenditure of the workers during shifts but because of the pandemic followed by a lockdown, we couldn't conduct this study.

For the application of the NIOSH equation, we first took measurements which are vertical distance, horizontal distance, angle etc. (*Figure 2.2.2.a*). Then we formulised our values accordingly to put them in the main equation, which gave the RWL value. Then, dividing the reel weight to RWL resulted in the LI. This LI value shows if the process of reel carrying is convenient or not.

3.4. Work Sampling

Another topic that has worked on is to find the standard time for 2 machines (CAT and KULE) that have been worked on. After the literature survey, work sampling has been decided as the best fitting method to use in this case (jobs consist of various tasks instead of one repetitive task). One reason to pick this method is that the labour in the measuring department is separated into multiple processes (i.e. labelling, measuring, reel placing etc.). Because of the Covid-19 pandemic and lockdown that came after, we had limited time to research and work sampling's research phase was quicker than direct time study. Instead of using direct time study and determining the machine up-times with a stopwatch, we used a pre-prepared template to write down the results of the observed machines in random times and in an unordered fashion.

Two observed machines have different characteristics. The CAT machine has been used mostly on small reels and shorter measurements, whereas KULE has been used mostly on larger reels and longer measurements (e.g. 1000m and over). Thus, different calculations are conducted on these 2 different machines.

After testing whether the number of observations was sufficient by determining an error rate for our observations, we started our standard time operations. We did the necessary procedures for the EC 400 CAT 6 cable and found our standard times with the allowance values we determined. During the cutting of 5000m and 6000m cables, we detected an error

input and realized that it did not give us the correct values. We pulled the standard times for this length of cables from 1000m with a simple ratio.

4. METHOD IMPLEMENTATION

4.1. Data Analysis for Work sampling

4.1.1. Determination of Sample Size

In the first week, we went to the factory and made 124 observations. We observed the cases where CAT 6 cable was processed in the working category 39 times. Thus, we calculated the number of observations we need to make by taking our p-value 39/124 = 0.31.

According to the information we have obtained from the company, our confidence interval is 95%. So we found a sample size value of n, taking the error rate as 5% that gave accurate results which was acceptable, thus we concluded the observation phase. Detailed observation tables that include the relevant data can be found in the appendix.

Values used to calculate observation amount:

- p=0.31
- z = 1.96
- h=0.05

(See in Table 2.3.3.b, Table 2.3.3.c)

$$P * (1-P) * Z^2 / H^2 = (0.3145) * (1-0.3145) * (1.96^2) / (0.05^2)$$

= (0.2156) * (3.8416) / (0.0025) = 331.30 \(\xi\$ 332 number of observations.

4.1.2. Determination the Number of Observations Per Day

Daily observation amount calculated by dividing total observation amount to 7 (332 / 5 = 67). Activities shown in template (*Table 4.1.2.a*) categorised as working or idle. (M, MT, ME, MAT, GH, GMH, MAG, MS as working category & MB, IB, MA, K, MAB as idle category). Workers have been assigned to machines and data that related to machines has entered the template accordingly.

Date: / / 2021				Work	Sampli	ng Data Col	lection				Page	of
Period of Study						Activity Category(AC)						
Observer						1. Measuring	(M)	8.Reel di	agging(MS)	9. Waiting for	reel (MI	3)
Department: Measur	ing Departme	nt				2. Carrying re	el (MT)			10. Waiting fo	t work o	rder (İB)
Notes: KNG-01(Oton	natik), KNG-	04(Man	uel), KNG-0	б(Kule-Manı	ıel),	3. Label pastir	ng on reel(ME)		11. The machi (MA)	ine is out	of order
KNG-07(Aymak-Automatic), KNG-08(Cat-Semi automatic)					4. Putting Rec				12. Arbitrary	pause (K)	
GH-1/GMH-1	GH-2/GMH-2	GH-3/G	GH-4/GMH-4	GH-5/GMH-5	GH-6/G	5. Entered err	or check (GH	-1,2,3,4,5,	6)	13. Waiting fo	r goods(!	MAB)
On the sheath surface	Marking	Attach	Sheath color		No	6. Not entered						
(open, rough)	error	ment occur	is distorted	No wicks	lower end	7. Went to tak	e a reel (MAC	;)				
						Wor	kers					
Observation Time	Tekin	Tekin M. (KNG-06) Ruşen T. (KN		NG-04) Murat U. (KNG- 08)		Necdet G. (KNG-07)						
	AC	PR	C	AC	PR	С	AC	PR	С	AC	PR	C
AC: Activity Categor												
C: Cable Type												

Table 4.1.2.a: Work sampling data collection sheet

To test if the observation amount is enough, machine-based observations have started. We collected data from the machines (KNG-05, KNG-06, KNG-07, KNG-08) on randomly selected hours, starting from a different machine each time, randomly. We pulled the data related to EC 400 CAT6 processing from all observations.

4.1.3. Determination of Performance Rate

Another parameter to decide was performance rates. We rated the workers considering the workers' physical working speeds, compared to reference normal speeds (PR = %100).

We let the performance rate of the worker working on semi-automatic machines %100 due to the judgement of stationary and inactive labour-time while measuring and labelling processes (M, ME), since the worker cannot have a performance that varies with the machine speed, we fixed the performance rate for the jobs we specified. During these processes, workers were waiting near the machine to process' completion. Yet things were different on the manual machine. During the processes, workers had to actively use the machine while measuring (M), thus performance rates were given in accordance with the machine speed. Performance rates given considering the working speed for the machine-unrelated processes such as reel dragging or carrying (MS, MT, MAG). Performance rates were set in 5 step increments like 85, 90, 95. Results categorised in this manner.

Performance Rate for KULE (KNG-06):

On the manual machine KULE (KNG-06), we let the normal speed of the worker (85 meter / minute) as 100% performance rate. As for operation ME (Label pasting on reel) has constant speed, performance rate is 100%. Other activities' (such as MT,

MAT, MS and so) performance rate have been proportional to the normal speed of the workers.

Machine: KULE (KNG-06)	11.02.21	24.02.21	<u>25.02.21</u>	03.03.21	Average Performance Rate
Working	110	110	100	100	105

Table 4.1.3.a: Average daily performance ratings for KULE (KNG-06) machine Performance Rate for CAT (KNG-08):

- Only difference of the Kule machine is because of it's being a semi-automatic, performance rate of it has taken constant 100% for the measuring process.

Machine: CAT (KNG-08)	09.02.21	02.03.21	03.03.21	08.03.21	Average Performance Rate
Working	100	110	95	100	100

Table 4.1.3.b: Average daily performance ratings for CAT (KNG-08) machine

4.1.4. Determination of Allowances

Another parameter needed for work sampling was allowances. Situations mentioned in the table considered and percentages given accordingly. We took our allowance values from the ILO's tables that are in the course notes and adjusted them according to the workers and gave the following values:

	KULE(KNG-06)	CAT (KNG-08)
Energy Output	0.0%	6.0%
Posture	1.0%	1.0%
Notions	5.0%	0.0%
Visual Fatigue	2.0%	0.0%
Thermal Conditions	0.0%	0.0%
Atmospheric Conditions	0.0%	0.0%
Other Influences of Environment	1.0%	1.0%
Personal Time	2.5%	2.5%
Delays	5.4%	0.0%
Total	16.9%	10.5%

Table 4.1.4.a: Allowance table

This table shows the allowances of workers during shifts. We found total allowances 16.9% and 10.5% for KULE (KNG-06) and CAT (KNG-08) machines. We will use these allowance values in our standard time calculations.

4.2. FMEA Implementation

Since we were able to work in the company and as a result of the firm's efforts to keep detailed and regular data, we made additions and strikes in our FMEA table for this period. Some error types were removed from the table and ratings were updated as a result of interviews with company experts. We will explain our calculation methods for occurrence values below.

4.2.1. Determination of Severity Score

We made a rating for the table of severity according to the feedback we received from company experts. We worked like this in the past period. We only updated the degrees for this period.

	CRITERION: Intensity of Impact This	CRITERION: Severity of Impact	
	rating is a potential error ultimate	This rating is a potential the ultimate	
	customer of its kind and / or cause	customer of the error type and / or cause	
	production / assembly failure It happens	production / assembly failure. It happens	
	when it happens. Ultimate customer	when it happens. Final customer always	
	must come first. If both come true the	has the first degree. If both if it happens,	
	high one Use the severity value.	the higher the violence Use the value.	
Effect	(Customer Effect)	(Production / Assembly Effect)	Degree
	Safety related malfunction, not in	Or the worker (machine or equipment) can	
	compliance with laws a malfunction.	endanger itself without warning.	
Dangerous	Error any warning occurs without.		10
	Safety related malfunction, not in		
	compliance with laws a malfunction.	Or the worker (machine or equipment) by	
Serious	The error occurs with a warning.	giving a warning can throw.	9
	Product can become unusable and loses	The entire production can be scrapped and	
Immense	function.	can take over 1 hour to be reworked.	8
	Product is usable but with a low		
		Part of the product may be scrapped and	
Considerable	substantially reduced.	can take up to 1 hour to be reprocessed.	7
	Product is usable but ease of use and		
	compliance components are		
	unavailable. Consumer satisfaction	Very little of it could be scrapped and	
Important	reduced.	repair could take a short time.	6

	Product is usable but ease of use and compliance components work with low	The product is reprocessed without being	
Minor	performance. Consumer is not content.	scrapped.	5
	Low impact on product performance or process. Defect can be detected by	The product is reprocessed without being	
Inferior	many consumer (%75)	scrapped.	4
Insignificant	Insignificant effect on product performance or process. Defect can be detected by some consumer (%50)	The product is reprocessed without being scrapped.	3
Negligible	Negligible impact on product performance or process. Defect can be detected by few consumer (%25)	There is no problem with the product to be scrapped. Processed again if required	2
No Effect	Does not affect product performance or process.	It has little or no effect on the process.	1

Table 4.2.1.a: Severity rating chart

4.2.2. Determination of Detection Score

We made a rating for the table of detection according to the feedback we received from company experts. We worked like this in the past period. We only updated the degrees for this period.

DETECTION	CRITERION	DEGREE
Nearly Impossible	Existing controls cannot detect the error	10
Too Hard	Existing controls have reduced chance of detection	9
Hard	Existing controls have a hard time to detect the error	8
Very Low Probability	Existing controls have little ability to detect the type of error	7
Low Probability	Existing controls might detect the error with a low chance	6
Medium Probability	Existing controls may detect the error	5
More than Medium	Existing controls have slightly more ability to detect the type of error	4
High	Existing controls have high ability to detect the type of error	3
Very High	Existing controls have very high ability to detect the type of error	2

Almost Certain	The ability of existing controls to detect the type of error is	1	
Amost Certain	almost certain.	1	

Table 4.2.2.a: Detection Ranking Chart

4.2.3. Determination of Occurrence Score

We obtained our occurrence table as a result of our literature search. We think it is also suitable for our own work.

ERROR RATE CLASSIFICATION	ERROR RATE IN EVERY 1000 METERS	DEGREE
Too High: Continuous Error	More than 100 in a 1000	10
100 High. Continuous Error	50 in a 1000	9
High: Frequent Error	20 in a 1000	8
Tright. Frequent Error	10 in an 1000	7
Medium Frequency Error	5 in an 1000	6
Production Trequency Error	2 in an 1000	5
Low Frequency Error	1 in an 1000	4
Eow Frequency Effor	0.5 in an 1000	3
Too Low Frequency Error	0.2 in an 1000	2
Too Dow Frequency Effor	Less than 0.01 in a 1000	1

Table 4.2.3.a: Occurrence rating chart

- Calculation of Incorrect Marking Error Occurrence for 2020

During this period, we created our occurrence rating based on the more detailed and accurate data we received from the company. We can see below how the occurrence degree is calculated for the marking error. We also calculated occurrence values of other error types in this way.

Tarih ↓₁	Vardiya 💂	Malzeme Adı	Hata Kategorisi	Hatalı Mikt	Üretim Mikta	Sipariş No 🔻
2.10.2020 00:00	08-20	EC400 Cat 6 U/UTP HFFR Dca 23 AWG Grey	MARKALAMA YANLIŞ	200	108700	209616
9.10.2020 00:00	08-20	EC400 Cat 6 U/UTP HFFR Dca 23 AWG White	MARKALAMA YANLIŞ	100	104100	209615
19.10.2020 00:00	20-08	OEM EC400 Cat 6 F/UTP HFFR Eca 23AWG Ivory	MARKALAMA YANLIŞ	4500	31780	209608
30.10.2020 00:00	08-20	EC400 Cat 6 U/UTP HFFR Eca 23 AWG Yellow	MARKALAMA YANLIŞ	100	12465	210511
17.12.2020 00:00	20-08	EC400 Cat 6 U/UTP HFFR Eca 23 AWG Orange	MARKALAMA YANLIŞ	50	159910	210760

Table 4.2.3.b: Marking error data for 2020

209616 work order had 200 m marking error in the morning shift,

209615 work order had 100 m marking error in the morning shift,

209608 work order had 4500 m marking error in the night shift,

210511 work order had 100 m marking error in the morning shift,

210760 work order had 50 m marking error in the night shift,

Total defective amount (m) = 4.950

Total production (m) = 705.307

Occurrence = 4.950/705.037 = 0.007

This occurrence value we found corresponds to the value of 6 in our occurrence table.

- Calculation of Incorrect Marking Error Occurrence for 2021

Tarih	-	Varc ▼	Malzeme Adı	Hata Kategorisi	↓ T	Hatalı Miktar 🔻	Üretim Miktarı	Sipariş No
07.01.20	021 00:00	08-20	EC400 Cat 6 U/UTP HFF	MARKALAMA YANLIŞ		100	10000	211110
11.01.20	021 00:00	08-20	EC400 Cat 6 U/UTP PVC	MARKALAMA YANLIŞ		100	12000	211191
18.01.20	021 00:00	08-20	EC400 Cat 6 U/UTP HFF	MARKALAMA YANLIŞ		100	350000	211101
18.01.20	021 00:00	20-08	EC400 Cat 6 U/UTP HFF	MARKALAMA YANLIŞ		3694	350000	211101
			OEM EC400 Cat 6 F/UTP	,		100	25000	211515
07.03.20	021 00:00	08-20	OEM EC400 Cat 6 F/UTP	MARKALAMA YANLIŞ		70	25000	211515

Table 4.2.3.c: Marking error data for 2021

211110 work order had 100 m marking error in the morning shift,

211191 work order had 100 m marking error in the morning shift,

211101 work order had 3794 m marking error in the night shift,

211515 work order had 170 m marking error in the morning shift,

Total defective amount (m) = 4.164

Total production (m) = 634.000

Occurrence = 4164 / 634000 = 0.007

This occurrence value we found corresponds to the value of 6 in our occurrence table.

In order to see how the scores are applied to our final FMEA table, we wanted to specify a part of our FMEA table here just for the marking error.

B			Current State							
Potential Types of Errors	Incorrect Quantity (m) 2020	Incorrect Quantity (m) 2021	Severity		Occurren ce 2020	Occurren ce 2021	Occuren ce 2021	Detection	RPN 2020	RPN 2021
Marking Error	4950	4164	7	0.007	6	0.007	6	3	126	126

Table 4.2.3.d: Part of final FMEA table, marking error

Marking Incorrect RPN 2020 = S*O*D = 7 * 6 * 3 = 126 **Marking Incorrect RPN 2021** = S*O*D = 7 * 6 * 3 = 126

5. DISCUSSION & RESULTS

5.1. FMEA

After conducting our extensive research on the types of errors we received from the company, we found the number of meters of the total production that these errors occurred and gave the occurrence values. Then we scored severity and detection parts in line with the information we received from the company experts, and found our relevant RPN values as follows:

	Potential			Current State					
Process Step	Types of Errors	Incorrect Quantity (m) 2020	Incorrect Quantity (m) 2021	Severity	Occurre nce 2020	Occurre nce 2021	Detecti on	RPN 2020	RPN 2021
M	Marking Incorrect	4950	4164	7	6	6	3	26	126
	Sheath Surface Dirt / Rough	2600	10000	7	6	8	7	294	392
	Open on Sheath Surface	1100	11450	7	5	8	7	45	392
S U R E M E N T	Cable Attachment	4000	0	8	6	1	2	96	16
	No Wick	20	0	6	1	1	4	24	24
	Colour Tone Difference	150	16570	6	1	8	4	24	192
	Forgetting to Put Out the Lower Ends	5986	10090	6	7	8	2	84	96
	Total Production (m)	705037	634000		l	l	1	1	L

Table 5.1.a: Final FMEA Table

Reasons and Solution Offers for Errors

1- Marking Incorrect: An error occurs as a result of an incorrect worker typing into the printer. worker carelessness and negligence. They enter the marking information (Senkron

ERP) to the system from the design department. workers get the marking information from the system, trying to minimize the error in this way. Intermediate control staff in the quality control department should check frequently during sheath pulling.


- 2- Sheath Surface Dirt / Rough: It can be sourced from raw materials. As a result of the incorrect entry of the worker, temperature error or incorrect wall thickness may occur in the extruder lines. By attaching a piece like a sieve to the end of the raw material, it is tried to clean the dirt formed in the raw material. The worker should be given the necessary machine and raw material training. Raw material measurements should be made in the incoming quality control tests for newly arrived raw materials. A PVC Test Extruder (30 and 45) machine can be recommended.
- 3- Open on Sheath Surface: It is caused by raw materials. It is caused by similar reasons with dirt and roughness defects. By attaching a piece like a sieve to the end of the raw material, it is tried to clean the dirt formed on the raw material.
- 4- Cable Attachment: Originating from the isolation stage or the twisting stage, by the worker. Training and seminars should be given to increase the worker's attention and awareness of the problems that arise as a result of their mistakes.
- 5- Colour Tone Difference: Dye is thrown into the raw material according to the dye code and the amount is adjusted, it may occur due to the worker's inability to adjust the amount. It may be due to the mixing of the paint existing in the previous production with the paint in the new production. workers' attention can be increased.
- 6- Forgetting to Put Out the Lower Ends: Lower end removal process; when there is attached production in the bending phase or in the isolated phase, these ends are removed from the edge of the reel. In order to control the quality of the additional part, the broken part, the end must be removed. A wage cut is applied to workers, in the 3rd warning. Holes are drilled in the edges of the reels to remove the attachments.
- 7- No Wick: This type of error is almost never encountered. For this reason, there is no need for a suggestion or change.

5.2. OWAS

Different analysis conducted based on our work sampling activity categories (*Table 4.1.2.a*) (e.g. labelling, measuring, putting the reel on etc.).

Label pasting on reel (ME)








Table 5.2.a:

OWAS application results for label

ME is a process where the labels are attached after the measuring end. Rating for back is calculated as 1 (standing straight). For arms, the rating is again 1 (both arms are at shoulder level). Legs have the rating of 2 (standing on two straight legs). Finally, the weight rating is 1 (under 10kg) because the reel is still attached to the machine and does not impose any weight on the worker. According to these ratings, results are categorised as Category 1 which states there's no need to take immediate precautions.

Reel Drag (MS)



Figure 5.2.b:
Posture of reel drag on reel

Name of the worker	Tekin
Company	Ören
Department	Measuring
Function	MS
Task	1 ▼ MS
Time in this task	100 %
Back	2 - Bent
Arms	1 - Both arms below shoulder level
Legs	7 - Walking
Load	3 - Greater than 20 Kg (44 lb)
Result	3 - Corrective actions should be done as soon as possible

Table 5.2.b:

OWAS application results for reel drag

For analysis made for the reel dragging process, rating for back is calculated as 2 (bent). For arms, the rating is again 1 (both arms are at shoulder level). Legs have the rating of 7 (walking). Finally, the weight rating is 3 (greater than 20 kg) because the reel is still not attached to the machine and the worker carries the entire load. According to these ratings, results are categorised as Category 3 which states there's corrective actions should be done as soon as possible.

Recommendation for Dragging the Reel

In order to reduce the load on the musculoskeletal system of the worker in the process of dragging the reel, we recommend the use of a simple carrying apparatus (*Figure 5.2.c*) called the roller cradle. The reel to be transported is placed in this apparatus in a short time such as 15-20 seconds and can be carried easily with a very little pushing force. As a result of our research, we have found the cost of the roller cradle as 1900 & + VAT.

Product Code	TV.0102	
Lifting Capacity (kg/a pair)	800	
Loading Diameter (mm)	600-1250	
Loading Width(mm)	930	
Weight(kg/unit)	70	
Length(mm)	1700	
Width(mm)	1350	
Height(mm)	850	

Table 5.2.c: Technical specifications of roller cradle



Figure 5.2.c: Roller Cradle [11]

Putting Reel On (MAT)

We examined the putting reel on activity in two different situations.

- MAT-1



Figure 5.2.d: Posture of putting reel-1 for putting reel-1




Table 5.2.d: OWAS application results

For the first analysis made by putting the reel on process, rating for back is calculated as 2 (bent). For arms, the rating is again 1 (both arms are at shoulder level). Legs have the rating of 3 (standing on one straight leg). Finally, the weight rating is 1 (under 10kg) because the empty reel applies a low degree of weight to the worker. According to these ratings, results are categorised as Category 2 which states there's corrective actions required in the near future.

- MAT-2



Figure 5.2.e: Posture of putting reel-2

Name of the worker	Murat
Company	Ören
Department	Measuring
Function	MAT
Task	2 MAT
Time in this task	50 %
Back	1 - Straight
Arms	1 - Both arms below shoulder level
Legs	2 - Standing on two straight legs
Load	1 - Less than 10 kg (22 lb)
Result	1 - No actions required

Table 5.2.e: OWAS application results for putting reel-2

For the second analysis made by putting the reel on process, rating for back is calculated as 1 (standing straight). For arms, the rating is again 1 (both arms are at shoulder level). Legs have the rating of 2 (standing on two straight legs). Finally, the weight rating is 1 (under 10kg) because the empty reel applies a low degree of weight to the worker. According to these ratings, results are categorised as Category 1 which states there's no need to take immediate precautions.

Carrying the Reel (MT)

We examined the carrying of the reel in two different situations.

- MT-1



Fig. 5.2.f: Posture of carrying reel-1




Table 5.2.f: OWAS application results for carrying reel-1

For the first analysis made carrying the reel process, rating for back is calculated as 2 (bent). For arms, the rating is again 1 (both arms are at shoulder level). Legs have the rating of 2 (standing on two straight legs). Finally, the weight rating is 3 (greater than 20 kg) because the worker carries the entire load. According to these ratings, results are categorised as Category 3 which states there's corrective actions should be done as soon as possible.

- MT-2






Fig. 5.2.g: Posture of carrying reel-2 results for

Table 5.2.4.g: OWAS application carrying reel-2

For the second analysis made carrying the reel process, rating for back is calculated as 4 (bent and twisted). For arms, the rating is again 1 (both arms are at shoulder level). Legs have the rating of 2 (standing on two straight legs). Finally, the weight rating is 3 (greater than 20 kg) because the reel is not attached to the machine and the worker carries the entire load. According to these ratings, results are categorised as Category 3 which states there's corrective actions should be done as soon as possible.

Recommendation for Carrying the Reel

We must ensure that the employee's back stays straight in order to reduce the load on the back. For this reason, we want the pallet to be adjusted according to the height that the worker will place, and in this way we want to reduce the load on the back. For this reason, we recommend placing a lifting device (*Figure 5.2.h*) under the pallet. For each placement height, the pallet will be raised or lowered, thereby reducing the amount of load on the back. We will see the effects of this proposition more clearly in the NIOSH implementation.



Figure 5.2.h: Hydraulic lift [12]

When we shared this recommended lifting device and the predicted results with the company officials, positive feedback was obtained. It was stated that this application can be implemented. This product can be found on websites for 1800 dollars. However, we think it can be manufactured at a more affordable price. In addition, as a result of our research, we have found the cost of the same machine (TEMHA Makine) as 9700\$\darksquare\$ +VAT.

Model		UL600	UL1000	UL1500
Load capacity	Kg	600	1000	1500
Platform size LxW	Mm	1450x985	1450x1140	1600x1180
Net weight	Kg	207	280	380

Table 5.2.h: Technical specifications for lifting apparatus

Measuring (M)




Fig. 5.2.i: Posture of measuring

Table 5.2.i: OWAS application results for measuring

For the analysis made measuring process, rating for back is calculated as 1 (standing straight). For arms, the rating is again 1 (both arms are at shoulder level). Legs have the

rating of **2** (standing on two straight legs). Finally, the weight rating is **1** (under 10kg) because the reel is still attached to the machine and does not impose any weight on the worker. According to these ratings, results are categorised as Category **1** which states there's no need to take immediate precautions.

5.3. NIOSH

We examined the NIOSH equation for 4 separate cases. The NIOSH equations of removing the reel from the mechanism and then placing it on the 1st, 2nd and 3rd rows on the pallet were examined.




Fig. 5.3.a: Posture of lifting reel




Table 5.3.a: NIOSH application results for lifting reel

We can see the measurements we made for the removal of the reel from the mechanism and the results we obtained in figure 1, the RWL was determined as 13.6 kg, so our LI value was 1.838. As a result of our literature research, these values can neither be considered as risky or risk-free. We can say that it has a moderate risk level. Necessary arrangements can be made.

- Calculating LI value for First row on the palette:




Table 5.3.b: NIOSH application results for lifting reel to first row on the palette

We see that our RWL value is 12.289 and our LI value is 2.034, as we have a high displacement in reel placement to the first row on the pallet, which indicates a high degree of risk. The necessary arrangements should be made as soon as possible.

- Second row on the palette:




Figure 5.3.b: Posture of lifting for lifting reel to second row



Table 5.3.c: NIOSH application results reel to second row

We see that our RWL value is 13,158 for reel placement in the second row on the pallet, and our LI value is 1.9, which indicates a medium risk. Necessary arrangements can be made.

- Third row on the palette:




Table 5.3.d: NIOSH application results for lifting reel to third row

We see that our RWL value is 13,844 for reel placement in the third row on the pallet and our LI value is 1.806, which indicates a medium risk. Necessary arrangements can be made.

- After adjustments are made:




Table:5.3.e: NIOSH application result after adjustments made

In order to reduce the displacement to zero, we need to match the height at which the reel will be placed with our vertical height. For this, we recommend a lifting device as we recommend in the OWAS application. This lifting apparatus (*Figure 5.2.h*) to be placed under the pallet will adjust the height of the pallet according to where the reel will be placed. On the other hand, we want to minimize our risk by reducing the stress on the musculoskeletal system by reducing the horizontal distance, which is an important variable. For this reason, our displacement will always be 0 and we will reduce our horizontal distance from 30 cm to 25 cm. After these changes, our RWL value rises to 18.377 and our LI value rises to 1.36, which shows us a low risk. It has been proven that, in some cases, situations that may be included in the high risk category can be reduced to the low risk category if the changes we recommend are implemented.

5.4. WORK SAMPLING

Our purpose in doing work sampling was to find the standard times of the processing times of the operation process in the measuring department and compare them with the times realized for those operation processes at Ören Kablo to find out how inefficient it is. Our work sampling study took 4 weeks. During these 4 weeks, we made 1515 observations by visiting the shop floor 429 times, covering 7 working days, and we observed the EC 400 CAT 6 cable process 216 times in these days. Detailed observation tables that include the relevant data can be found in the appendix.

ACTIVITY CATEGORY	# OF OBS. FOR EC400 CAT 6		# OBS. FOR ALL CABLES
M (Measuring)	121		592
MT (Carrying reel)	12		64
ME (Label pasting on reel)	31		298
MAT (Putting Reel on)	12	80	67
MAG (Went to take a reel)	2		11
MS (Reel dragging)	2		4
MB (Waiting for a reel)	0		6
IB (Waiting for work order)	0		116
MA (The machine is out of order)	0	3	67
K (Arbitrary pause)	21	ا ا	133
MAB (Waiting for goods)	12		153
GH-1 (Entered error check- On the sheath surface (open, rough))	0	3	0

GH-2 (Entered error check- Marking error)	0	0
GH-3 (Entered error check- Attachment occur)	0	0
GH-4 (Entered error check- Sheath color is distorted)	1	1
GH-5 (Entered error check- No wicks)	0	0
GH-6 (Entered error check- No lower end)	0	0
GMH-1 (Not entered error check- On the sheath surface (open, rough))	2	4
GMH-2 (Not entered error check- Marking error)	0	0
GMH-3 (Not entered error check-Attachment occur)	0	0
GMH-4 (Not entered error check- Sheath color is distorted)	0	0
GMH-5 (Not entered error check- No Wick)	0	0
GMH-6 (Not entered error check- No lower end)	0	0
TOTAL	216	1.515
Total number of visits to shop floor		429

Table 5.4.a: Activity categories

- Greens and magentas are included in working activities.
- Oranges are included in idle activities.

Table 5.4.1.a shows our processing on both EC 400 CAT 6 and other cables.

All Cables				
Personal Idle Times	8.78%			
Delay Times	22.57%			

Table 5.4.b: Idle times values

We have:

- 133 K (Arbitrary pause) in 1515 observations for all cables.

So, personal idle time is 133 / 1515 = 8.78%

Delays are (MB + IB + MA + MAB) / Total Obs. = (6 + 116 + 67 + 153) / 1515 =
 22.57%. Values above 15% signals a problem and needs intervention by the planning department of the company.

We think these problems are causing overtime;

Üretim No	Tarih 🕌	Vardiya 👵	Operasyon 🛫	Üretim M.	Makina	¥	Üretim Süresi	Mamül Adı	Persone
192968-40-1	18.01.2020 08:52	08-20	Metraj	2100	(KNG-06)	KULE	72	LİYCY 7x2,50 mm² (70 % Braiding) Erco	Tekin M
192964-60-1	18.01.2020 08:52	08-20	Metraj	2100	(KNG-06)	KULE	72	LİYCY 5x2,50 mm² (70 % Braiding) Erco	Tekin M
195357-20-3	18.01.2020 08:52	08-20	Metraj	36000	(KNG-06)	KULE	1242	EC400 Cat 6 U/UTP HFFR Dca 23 AWG Grey	Tekin M
193563-60-1	18.01.2020 15:43	08-20	Metraj	4170	(KNG-06)	KULE	85	-RHEYFLEX 500 YCY-JZ 4G4,00 mm² (%55 Coverage)	Tekin M
194919-60-1	18.01.2020 15:43	08-20	Metraj	14000	(KNG-06)	KULE	284	OEM Def-Stan 7-2-8A PVC/PE Duct Grade	Tekin M
193559-40-1	18.01.2020 15:43	08-20	Metraj	2000	(KNG-06)	KULE	41	-RG213 U Koaks 50 Ohm 100m	Tekin M

Table 5.4.c: Sample worker data for one day

In *Table 5.3.e*, we want to show that sometimes workers work overtime and we assume that causes inefficiency and increase in error rate. For example:

72+72+1242+85+41+284 = 1796 minutes ≈ 30 hours, Tekin M. worked for 30 hours.

5.4.1. Machine Base Observations for EC 400 CAT 6

Below are the representations of observations for each machine, daily.

Machine: KULE(KNG-06)	11.02.21	24.02.21	25.02.21	03.03.21	Total
M (Measuring)	15	7	17	7	46
MT (Carrying reel)	0	1	0	0	1
ME (Label pasting on reel)	0	2	1	4	7
MAT (Putting Reel on)	1	2	1	1	5
MAG (Went to take a reel)	0	0	0	0	0
MS (Reel dragging)	0	0	1	0	1
MB (Waiting for a reel)	0	0	0	0	0
IB (Waiting for work order)	0	0	0	0	0
MA (The machine is out of order)	0	0	0	0	0
K (Arbitrary pause)	4	0	5	2	11
MAB (Waiting for goods)	7	1	2	2	12
GH-1 (Entered error check- On the sheath surface (open, rough))				2	2
GMH-4 (Not entered error check-					
Sheath color is distorted)			1		1
Number of Observations	5	62	56	63	239

Table 5.4.1.a: EC 400 CAT 6 observations for KULE (KNG-06) Machine

- EC 400 CAT 6 Cable in the KULE (KNG-06) machine was observed on 11.02.2021, 24.02.2021, 25.02.2021, 03.03.2021 dates with a total of 239 number of observations for all cables.

Machine : CAT (KNG-08)	09.02.21	02.03.21	03.03.21	08.03.21	Total
M (Measuring)	12	25	19	19	75
MT (Carrying reel)	2	2	4	3	11
ME (Label pasting on reel)	7	5	8	4	24
MAT (Putting Reel on)	2	0	3	2	7
MAG (Went to take a reel)	0	0	0	2	2

MS (Reel dragging)	0	0	1	0	1
MB (Waiting for a reel)	0	0	0	0	0
IB (Waiting for work order)	0	0	0	0	0
MA (The machine is out of order)	0	0	0	0	0
K (Arbitrary pause)	1	2	7	0	10
MAB (Waiting for goods)	0	0	0	0	0

Number of Observations	66	61	63	63	253

Table 5.4.1.b: EC 400 CAT 6 observations for CAT (KNG-08) Machine

- EC 400 CAT 6 Cable in CAT (KNG-08) machine was observed on 09.02.2021, 02.03.2021, 03.03.2021, 08.03.2021 dates with a total of 253 number of observations for all cables.

Daily Working & Idle Observations for Kule (KNG-06) Machine

Machine: KULE (KNG-06)	11.02.21	24.02.21	25.02.21	03.03.21	<u>Total</u>
Working activity proportion of EC400 CAT 6	0.28	0.19	0.38	0.22	0.26
Idle activity proportion for EC 400 CAT 6	0.19	0.02	0.13	0.06	0.10
Processing other types of cable	0.53	0.79	0.49	0.72	0.64

Table 5.4.1.c: Working (EC 400 CAT 6) Proportions for KULE (KNG-06) Machine

Daily working and idle ratios have been found. Below is a sample calculation for 11.02.21. Rest of the table has been filled similarly.

On 11.02.2021 total working activities (green ones) were 16 in 58 (*Table 5.4.1.a*) observations. So, the working proportion for that day is $16 / 58 = 0.2759 \approx 0.28$. Idle proportion is $11 / 58 = 0.1897 \approx 0.19$.

Total working activities (green ones) are 16+12+21+14=63 in 239 (*Table 5.4.1.a*) observations. So:

- Working proportions for KULE (KNG-06) machine is $63 / 239 = 0.2636 \approx 0.26$
- Idle is $11+1+7+4=23/239=0.096 \approx 0.10$.

Machine:CAT(KNG-08)	09.02.21	02.03.21	03.03.21	08.03.21	<u>Total</u>
Working activity proportion of EC400 CAT 6	0.35	0.52	0.56	0.48	0.47
Idle activity proportion for EC 400 CAT 6	0.02	0.03	0.11	0.00	0.04
Processing other types of cable	0.63	0.45	0.33	0.52	0.49

Table 5.4.1.d: Working (EC 400 CAT 6) Proportions for CAT (KNG-08) Machine

Total working activities (green ones) are 23 + 32 + 35 + 30 = 120 in 253 observations (*Table 5.4.b*). So:

- Working proportions for Kule Machines (KNG-06) is $120 / 253 = 0.474 \approx 0.47$
- Idle is $1 + 2 + 7 = 10 / 253 = 0.039 \approx 0.04$.

	I
121	M (Measuring)
12	MT (Carrying reel)
31	ME (Label pasting on reel)
12	MAT (Putting Reel on)
2	MAG (Went to take a reel)
2	MS (Reel dragging)
0	MB (Waiting for a reel)
0	IB (Waiting for work order)
0	MA (The machine is out of order)
21	K (Arbitrary pause)
12	MAB (Waiting for goods)
	GH-1 (Entered error check- On the sheath
1	surface (open, rough)
	GMH-4 (Not entered error check- Sheath
2	color is distorted)

KULE (KNG-06) & CAT (KNG-08)	TOTAL
Working category CAT	0.37
Idle times at CAT processing	0.07
Processing other types of cable	0.56

Table 5.4.1.e: Working & Idle Proportion for Both Machines

- Total working activities is 121 + 12 + 31 + 12 + 2 + 2 + 1 + 2 = 183 in 492 observations. So, the working proportion is 183 / 492 = 0.372 = 0.37 for both machines.
- Idle proportion is $21 + 12 = 33 / 492 = 0.067 \approx 0.07$.

Date	09.02	11.02	24.02	25.02	02.03	03.03	08.03	TOTAL
Number of Obs.	66	58	62	56	61	126	63	492
	CAT	KULE	KULE	KULE	CAT	KULE & CAT	CAT	

Table 5.4.1.f: Number of EC 400 CAT 6 Observations for Both Machines

The table shows the dates when the EC 400 CAT 6 cable was put into operation. While the operations related to EC 400 CAT 6 cable were observed in one machine on 9, 11, 24, 25 February and 2, 8 March, it was observed in two machines on 3 March. For this reason, the number of observations (63 + 63 = 126) has been collected for both machines separately.

- EC 400 CAT 6 observations for both machines.
- Only on 03.03.2021 both machines were working.

Finding Error Rates for CAT (KNG-08) & KULE (KNG-06) Machine by Observation Numbers

	P	(1-P)	P*(1-P)	N
	0.370	0.630	0.233	492
H ²	0.0018	0.0427		
\mathbb{Z}^2	3.84			

Table 5.4.1.g: Total Error Rate for Both Machines

With 95% confidence interval and 492 observations. As shown in the *Table 5.4.1.e* process ratios for both machines have taken 0.37.

- We have H^2 as P * (1-P) * Z^2 / N = 0.233 * 3.84 / 492 = 0.0018 = H^2
- So, the square root of it gives us an error rate. $\sqrt{0.0018} = 0.0427 \approx 0.04$.

After the processes and observations, we include a four percent error rate in our EC 400 CAT 6 observations.

Error Rate for CAT (KNG-08) Machine Type of 500m Reel

		P	(1-P)	P*(1-P)	N
		0.474	0.526	0.249	253
	H^2	0.0038	0.0615		
Ī	Z^2	3.84			

Table 5.4.1.h: Error Rate for CAT (KNG-08) Machine

With %95 confidence interval and 253 observations. We took the ratio 0.474 for working of the CAT (KNG-08) machine as shown in *Table 5.4.1.d.*

- We have H^2 as $P * (1-P) * Z^2 / N = 0.249 * 3.84 / 253 = 0.0038 = <math>H^2$
- So, the square root of it gives us an error rate. $\sqrt{0,0038} = 0.0615 \approx 0.06$.

We include a six percent error rate in our EC 400 CAT 6 observations.

After the processes and observations, if we assumed a 5% error, then the observation amount would be 383. However, under the pandemic restrictions we didn't have a healthy research environment.

Error Rate for KULE(KNG-06) Machine Type of 1000m Reel

	P	(1-P)	P*(1-P)	N
	0.276	0.724	0.200	58
H ²	0.0132	0.1150		
\mathbb{Z}^2	3.84	0.12		

Table 5.4.1.i: Error Rate for KULE (KNG-06) Machine for Type of 1000m Reel

As we show in the table ($Table\ 5.4.1.a$), we processed our working rate as 15 + 1 = 16/58 = 0.276 for the KULE (KNG-06) machine on 11.02.21 (We only took the date as reference 11.02.2021 because the 1000-meter reel was metered that day). Metering operations are carried out on 1000, 5000, 6000 meters of reels in the tower machine. In order to find more reliable data in our standard time processes, we have taken into account both our operations and our observations separately for reels of different lengths with 95% confidence interval and 58 observations.

- We have H^2 as $P * (1-P) * Z^2 / N = 0.200 * 3.84 / 58 = 0.0132 = H^2$
- So, the square root of it gives us an error rate. $\sqrt{0.0132} = 0.1150 \approx 0.12$.

As a result of the observations and procedures, we include twelve percent error rate in our EC 400 CAT 6 observations.

Error Rate for KULE(KNG-06) Machine Type of 5000m Reel

	P	(1-P)	P*(1-P)	N
	0.294	0.706	0.208	119
H ²	0.0067	0.0819		
Z^2	3.84	0.08		

Table 5.4.1.j: Error Rate for KULE (KNG-06) Machine for Type of 5000m Reel

- We have H^2 as $P * (1-P) * Z^2 / N = 0.208 * 3.84 / 119 = 0.0067 = <math>H^2$
- So the square root of it gives us an error rate. $\sqrt{0,0067} = 0.0819 \approx 0.08$.

As a result of the observations and procedures, we include eight percent error rate in our EC 400 CAT 6 observations.

Error Rate for KULE (KNG-06) Machine Type of 6000m Reel

	P	(1-P)	P*(1-P)	N
	0.194	0.806	0.156	62
H^2	0.0097	0.0983		
\mathbb{Z}^2	3.84	0.10		

Table 5.4.1.k: Error Rate for KULE (KNG-06) Machine Type of 6000m Reel

With 95% confidence interval and 62 observations. As we have shown in *Table 5.4.1.a*, we have processed our working rate of 24.02.21 (only because 6000m of reel is measured per day) for KULE (KNG-06) machine as 7+1+2+2=12/62=0.194.

- We have H^2 as $P * (1-P) * Z^2 / N = 0.806 * 3.84 / 62 = 0.0097 = <math>H^2$
- So, the square root of it gives us an error rate. $\sqrt{0.0097} = 0.0983 \approx 0.10$

As a result of the observations and procedures, we include ten percent error rate in our EC 400 CAT 6 observations.

5.4.2. Allowances

In the tables below, we can see the realization frequencies of the idle activities for the KULE (KNG-06) and CAT (KNG-08) machines during the observations. For example, out of a total of 58 observations made on 11.02.2021, 4 were shown as arbitrary pause (K) and 7 as waiting for goods (MAB). The remainder of the table is also filled in as indicated according to the results of the observations.

Machine: KULE (KNG-06)	11.02.21	24.02.21	25.02.21	03.03.21	Total
MB (Waiting for a reel)	0	0	0	0	0
IB (Waiting for work order)	0	0	0	0	0
MA (The machine is out of order)	0	0	0	0	0
K (Arbitrary pause)	4	0	5	2	11
MAB (Waiting for goods)	7	1	3	2	13
Number of Observations	58	62	56	63	KULE

Table 5.4.2.a: Idle category observations for EC 400 CAT 6 for KULE (KNG-06)

Machine

Table 5.4.2.a shows the idle categories for KULE (KNG-06) machine.

From the table:

- Personal idle time (K) on total is 4 + 5 + 2 = 11 / 239 = 4.6%
- Delays on total are (MB + $\dot{I}B$ + MA + MAB) 7 + 1 + 3 + 2 = 13 / 239= 5.4%

Machine : CAT (KNG-08)	09.02.21	02.03.21	03.03.21	08.03.21	Total
MB (Waiting for a reel)	0	0	0	0	0
IB (Waiting for work order)	0	0	0	0	0
MA (The machine is out of order)	0	0	0	0	0
K (Arbitrary pause)	1	2	7	0	10
MAB (Waiting for goods)	0	0	0	0	0
Number of Observations	66	61	63	63	CAT

Table 5.4.2.b: Idle category observations for EC 400 CAT 6 for CAT(KNG-08) Machine Table 5.4.2.b shows the idle categories for CAT (KNG-08) machine.

From the table:

- Personal idle time (K) on total is 1 + 2 + 7 = 10 / 253 = 4.0%
- Delays on total are (MB + $\dot{I}B$ + MA + MAB) 0 / 239 = 0%.

We found the percentage of personal needs in proportion to total is 4.6% and 4.0% instead of 2.5% -which the ILO accepts- for KULE (KNG-06) and CAT (KNG-08) machines respectively. This is how we can explain the low performance caused by lack of supervision.

5.4.3. Finding normal time & Standard Time

KULE (KNG-06)	Reel (1000m)
P (Proportion of working time)	0.26
TT (Total time)	2880 min
PR (Average Performance Rating)	1.05
Total measurement	80000 m
Q (Total length of the cable)	80 km
Tn (Normal time)	9.828 min/km
Tstd (Standard time)	9.662 min/km

Table 5.4.3.a: Normal & standard time for KULE (KNG-06) machine for type of 1000m EC 400 CAT 6 Reel

Table 5.4.3.a shows the normal time and standard time values found for the EC 400 CAT 6 cable with 1000, 5000 and 6000 meters of metering for the KULE (KNG-08) machine. However, we encountered error checks during the metering process on 5000 and 6000 meters reels. These checks also gave us incorrect values for our standard time calculations. Since we didn't have a chance to make more observations, we first calculated our standard time calculations for a 1000 meter reel. After that, we estimated the standard times for 5000 and

6000 meters reels based on that 1000 meter reel, which yielded more realistic results. For 1000 meters:

- P = 0.26 EC 400 CAT 6 working activity on all days for the KULE machine (*Table 5.4.1.c.*)
- TT = 48 hr * 60 min = 2880 min total observation time
- PR = 1.05 Average performance rate for all days (*Table 4.1.3.a*)
- Total measurement = (10 unit * 1000 m + 8 unit * 5000 m + 5 unit * 6000 m) = 80,000 m
- Q = (80,000 m * 1 km / 1000 m) = 80 km
- Tn = ((TT * PR * P) / Q) = ((2880 min * 1.05 * 0.26) / 80 km) = 9.828 min / km
- Tstd = (Tn / (1 Allowances [Table 2.3.3.c])) = (9.828 min/km / (1 0.0169)) = 9.662 min/km
- ❖ Standard time of a 1000 m reel in KULE (KNG-08) machines is 9.662 minute per (1000m) reel.

KULE (KNG-06)	Reel (5000m)	Reel (6000m)
Tn (Normal time)	49.03 min	58.84 min
Tstd (Standard time)	49.87 min	59.85 min

Table 5.4.3.b: Normal & standard time for KULE (KNG-06) machine for type of 5000 & 6000 m EC 400 CAT 6 Reel

The *Table 5.4.3.b* shows the normal and standard times of the 5000 and 6000 meter reels in the KULE (KNG-06) machine.

- <u>To calculate normal times:</u>

5000 m : 9.828 min/km* 5 km = 49.14 minute

6000 m : 9.828 min/km * 6 km = 58.97 minute

- <u>To calculate standard times:</u>

5000 m : 9.662 min/km * 5 km = 48.31 minute

6000 m : 9.662 min/km * 6 km = 57.97 minute

❖ Standard time of the 5000 m reel in KULE (KNG-08) machines is 48.31 minute per (5000m) reel.

❖ Standard time of the 6000 m reel in KULE (KNG-08) machines is 57.97 minute per (6000m) reel.

CAT (KNG-08)	Reel (500m)
P (Proportion of working time)	0.47
TT (Total time)	2880 min
PR (Average Performance Rating)	1
R (Number of Reel)	206 unit
Q (Total length of the cable)	103 km
Tn (Normal time)	6.57 min
Tstd (Standard time)	6.50 min

Table 5.4.3.c: Normal & standard time for CAT (KNG-08) machine for type of 500 m EC 400 CAT 6 Reel

- P = 0.47 CAT (KNG-08) working activity on all days for the CAT(KNG-08) machine (Table 5.4.1.d)
- TT = 48 hr * 60 min = 2880 min total observation time
- PR = 1.00 Average performance rate for all days (*Table 4.3.1.b*)
- Q = (206 reel * 500 m * (1 km / 1000 m)) = 103 km
- Tn = ((TT * PR * P) / Q) = ((2880 min * 1 * 0.47) / 103 km) = 13.14 min / km
- Tn (for 1 unit: 500 m) = (13.14 min / km / 2) = 6.57 min
- Tstd (for 1 unit: 500 m) = (Tn / (1 Allowances [Table 2.3.3.c])) = (6.57 / (1 0.0105)) = 6.50 min
- ❖ Standard time of 500m reel in CAT (KNG-08) Machines is 6.50 minutes per (500m) reel.

In the observations we made for the CAT (KNG-08) machine in a total of 4 days (09.02.2021, 02.03.2021, 03.03.2021, 08.03.202), we calculated the production process of the 500 m type of reels according to the data we pulled from the planning. The total made is 41 + 54 + 57 + 4 = 156 reels. We extracted the information that these 156 reels were metered for 1309 minutes, and this gave us the information that each reel was completed in $1309/156 = 8.39 \approx 9$ minutes.

For the KULE (KNG-06) machine, we calculated the production process of the 1000 m type of reels according to the data we pulled from the planning, in the observations we made in one day (11.02.2021). The total made is 10 reels. We extracted the information that

these 10 reels were metered in 123 minutes from the data we have, and this gave us the information that each machine was completed in 123/10 = 12.3 = 13 minutes.

We have observed that the metering operations for both CAT (KNG-08) and KULE (KNG-06) machines are higher than the standard times. We clearly see that the reason for this inefficiency is due to idle times such as arbitrary pause (K) and waiting for goods (MAB) during the day.

6. CONCLUSION

Before carrying out our work in the measuring department for our project, all employees in both that department and the planning department were met one by one. The content and purpose of our project was explained. After these interviews and permits, the necessary measurements and photographs were taken and all the operations were carried out after these steps. In all our works, we aimed to solve the inefficiency problems of the company in the measuring department and to protect the health of the workers, and we made some suggestions in line with the results we found by working on this subject.

While doing our FMEA studies, we categorized the errors that occurred during manufacturing. We have formed our severity and detection rating for these error categories based on the tables we have specified in our literature. For our occurrence rating, we calculated the occurrence values over the data recorded by the company and took our occurrence values corresponding to these values from our occurrence table, which we specified in the literature. As a result of these ratings, we have observed that marking errors, dirt on the sheath surface, roughness and opening, and the cable colour differences are problems that need to be resolved. Based on these results, we offered our solutions.

For the error that is open, dirt, and rough in the surface, the worker should be given the necessary machine and raw material training. Raw material measurements should be made in the incoming quality control tests for newly arrived raw materials. A PVC Test Extruder (30 and 45) machine can be recommended. For the other error types, training and seminars should be given to increase the worker's attention and awareness of the problems that arise as a result of their mistakes.

In order to examine the postures of employees in OWAS studies, we made examinations by separating them according to our categories in the work sampling. These categories are label pasting on reel, reel dragging, putting reel on, carrying the reel and

measuring. We took the photos, videos and measurements required to carry out the OWAS study during our company visits. Afterwards, as mentioned in the literature, we examined the back, arm and leg postures of the employees and the loads they were exposed to. We made a rating on our evaluation table stated in the literature and presented our suggestions in sections where posture problems exist. During our factory visits and interviews with workers, we have observed that all our workers have low back and back disorders. We even observed that one of our workers had spinal cord constriction.

We advocate using a basic carrying equipment (Figure 5.2.c) called the roller cradle to lessen the strain on the worker's musculoskeletal system while dragging the reel. In order to lessen the weight on the back, we must ensure that the employee's back remains straight when carrying the reel. As a result, we want the pallet to be changed according to the height at which the worker will lay it, reducing the load on the back. For this reason, we recommend placing a lifting device (*Figure 5.2.h*) under the pallet. For each placement height, the pallet will be raised or lowered, thereby reducing the amount of load on the back.

Since the NIOSH equation only focuses on lifting an object, we used this equation for our reel lifting part. We analyzed this part under 4 headings: lifting the reel, placing it in the first, second and third rows on the pallet. We obtained the photos, videos and measurements required for the application of the equation during our company visits. As a result of applying the variables obtained from the measurements to the equation, our recommended weight limit (RWL) for the lifting part of the reel is 13.59 kg and our LI value is 1.838. According to this value, we evaluate this situation as medium risk. For the case of placing the reel on the first pallet, our RWL value is 12,289 kg and our LI value is 2.034, which is in the high risk category. For the case where the reel is placed on the second pallet, we evaluate our RWL value as 13.15 and our LI value as 1.9. This shows that there is a medium risk. Our RWL value for the placement of the reel on the third pallet is 13.844 and our LI value is 1.806 and we can consider it as a medium risk.

To achieve zero displacement, we must match the height at which the reel will be put with our vertical height. We propose a lifting device for this, like we do in the OWAS application. This lifting apparatus (Figure 5.2.h), which will be positioned under the pallet, will adjust the height of the pallet based on the location of the reel. On the other hand, we wish to reduce the stress on the musculoskeletal system by minimizing the horizontal distance, which is an essential variable. For this reason, our displacement will always be 0 and we will reduce our horizontal distance from 30 cm to 25 cm. After these changes, our RWL

value rises to 18.377 and our LI value rises to 1.36, which shows us a low risk. It has been proven that, in some cases, situations that may be included in the high risk category can be reduced to the low risk category if the changes we recommend are implemented.

Based on the information we obtained from our observations and data, we saw that a worker sometimes worked continuously for more than 30 hours. While such hours of working could be shown as a cause of inefficiency in itself, we could also say that this reason was also related to the waiting times of the workers. As we have shown in the allowance tables, we found the workers' personal idle time (K) as 8.78%, delay time (MB + IB + MA + MAB) as 22.57%, which as a rule of thumb should not have been more than 15%. These values are more than 15%, so the presence of delays causes overtime.

Another conducted study was work sampling. Purpose of this study is finding standard time with random observations of the workers and machines, then categorising it. We did two instances of calculations because the machines were working with different sizes and measures of wire. Our observations took 4 weeks and the standard times calculated resulted differently than what we pulled from the data for 1000, 5000 and 6000 meters reels, which showed the processes are happening with delay.

3 different sizes of reels are processed on the KULE machine (1000, 5000, 6000). We calculated standard time for each of these sizes, however there was some error handling during the measuring of the 5000 and 6000 meters reels, which means the worker slows down the machine and works at a slow pace. Thus, standard time calculations for these sizes of reels gave false results. With no more observation chance, we estimated the standard time of 5000 and 6000 meters cables from the 1000 meter reel.

On the KULE machine, standard time for a 1000 meter reel was calculated 9.662 minutes, however pulled data showed 12.3 minutes for the same operation. Same appeared for the CAT machine. Calculated standard time was 6.50 minutes yet the data showed 8.39 minutes.

We have observed that the metering operations for both CAT (KNG-08) and KULE (KNG-06) machines are higher than the standard times. We clearly see that the reason for this inefficiency is due to idle times such as arbitrary pause (K) and waiting for goods (MAB) during the day.

6.1. Checklist

The following topics were discussed in our project:

- o Economic Considerations
- Environmental Considerations
- Sustainability
- Applicability
- Ethical Considerations
- Social and Political Considerations

For ethical considerations, before starting our project, the stages of the project were explained to all the workers and company experts working at the factory, and necessary permissions were obtained to take photos of the workplace and workers to be used in some stages of our project. For applicability and economic considerations; as a result of our meetings with the company officials, we received feedback that the hydraulic lift and reel cradle existing in our proposals could be applied. At the same time, economic evaluations regarding these suggestions were made with the company and were deemed appropriate. The PVC extruder machines in our recommendations have a very long service life it will be beneficial in terms of sustainability. Also, thanks to the PVC extruder machine, the mistakes will be prevented, that is, the scrap will be reduced, and it will provide economic benefits to the company. Environmental factors in the factory, especially corona conditions (you can find our article about this in Section 8), were examined in line with the content of our project. working conditions of workers; it has been researched under titles such as sound, ambient temperature, noise level, cleanliness and order of the workplace and rated to be used in the relevant parts of the project. Social and Political considerations are not addressed in our project because these factors are not needed for this project.

7. RECOMMENDATIONS

Following section includes some deductions and suggestions to those who want to conduct studies that follow similar methods.

First difficulty we met was the insufficient data structure. Study we conducted had to be consistent and correct. We utilised the incomplete data with maximum care and evaluated the accuracy of the results of this study and how consistent and realistic the problems encountered in the company were reflected in our work. Company experts' opinions were both guiding and certifying at this point. That's how we overcame the difficulties that originated from working with incomplete data.

Company started to improve data collection after this project began, which was important for the FMEA part of this project. Because of that, there were no problems related to incompleteness of the data. This provided a solid ground for FMEA study, which yielded consistent and concrete results. We'd like to emphasise the importance of data that is kept correctly and complete is essential for studies.

Our study shows that most of the tardiness is caused by other departments that come before the measuring department. Main reason for the sheath imperfections are production processes, that's why studies like FMEA should be conducted in other departments (e.g. sheath, isolation, bending etc.)

Methods we implemented took a lot of time and we couldn't conduct a study that included the pulse rates of workers. This study should be a complementary work for the work sampling's oxygen intake part.

Another important inference that all our studies show us is that the human factor is one of the most important. We can examine this factor in 2 ways; The first is the health problems that the working conditions may cause on the workers, the second is that the errors caused by the carelessness of the workers are a very common situation and this should be solved. Also we believe that these two problems create a cause-effect relationship between each other.

8. COVID-19 EXPERIENCES IN OREN CABLE

As in all over the world, some measures were taken in Ören Kablo within the scope of Covid-19. Requirements to wear a mask, distance rules in common areas, fire controls when entering the factory are some of these. In addition to these (although not very often on the blue collar side), disinfectants are placed in the work areas. Although Ören is a cable company, from the moment you enter the factory, there is a lack of air or any cable, burns, etc. you do not encounter the smell. This is due to the high factory height and also to the extremely good ventilation system of the factory. However, despite all these precautions, we observed that there were some defects and non-compliance at times.

As part of our work, we had to go to the field and observe all the time, and after a while we had the chance to observe the working styles of the employees in their most natural

state. In this way, we have observed that some rules are not followed. It was one of the most important events that caught our attention, not only for the measuring department, but also that employees in almost all departments did not wear their masks correctly (sometimes never). We could not come to a conclusion as to whether this was due to the inadequate training provided by the factory under Covid-19 or a deliberate situation by the employees. However, whatever the reason, incorrectly worn masks may have bad consequences for the factory in the future.

Another situation that draws our attention as a result of our observations is smoking inside the factory. This situation, which we observed only in one worker, is not only a threat to Covid-19, but also poses a great danger to wooden reels, cables and other tools in the factory.

Another situation that we see not being followed is the distance rule in common areas. The company has determined the rules of distance with certain signs to common areas such as the cafeteria and has drawn some boundaries. For example, it was written and clearly stated which of the chairs around the tables should remain empty. However, at times (both blue collar and white collar) these writings are ignored. In addition, although attention was paid to the use of masks in the service and cars used by white-collar and blue-collar workers, no changes were made in capacity utilization.

As seen in many people, the rules brought by the pandemic turn into boredom after a while and reduce the determination to comply with the rules. This situation has been observed in many employees who have to work within a certain working hour every day. Some of the rule violations we mentioned above may seem like small things, but as the whole world deals with this pandemic, these violations can turn into greater dangers for the factory. Certain measures can be taken for this. For example, every employee can handle the contamination situation more safely, at least for himself and other employees, as a corona test every 2 weeks.

9. REFERENCES

- [1] Arabian-Hoseynabadi, H., Oraee, H., & Tavner, P. J. (2010). Failure Modes and Effects Analysis (FMEA) for wind turbines. *International Journal of Electrical Power & Energy Systems*, 32(7), 817–824. https://doi.org/10.1016/j.ijepes.2010.01.019
- [2] Stamatis, D. H. (2003). Failure mode and effect analysis FMEA from theory to execution. ASQC Quality Press.
- [3]Chrysler Co., Ford Motor Co. and General Motors Co. (1995) Potential Failure Mode and Effects Analysis (FMEA): Reference Manual. https://www.lehigh.edu/~intribos/Resources/SAE FMEA.pdf. 23.03.2017.
- [4] Taylor & Francis. (1986). The ergonomics of working postures: the proceedings of the First International Occupational Ergonomics Symposium, Zadar, Yugoslavia, 15-17 April 1985.
- [5] Loupajarvi T., Ergonomic analysis of workplace and postural load, ergonomics, Longman Publishers, United Kingdom, 1990.
- [6] Mahachandra, M., Prastawa, H., & Susilo, D. Y. (2018). Working posture analysis of sweet whey powder handling at CV Cita Nasional warehouse using OVAKO Working Posture Analysis (OWAS). *SHS Web of Conferences*, *49*, 02013. https://doi.org/10.1051/shsconf/20184902013
- [7] Howard, J. (2020). NIOSH: A Short History. *American Journal of Public Health*, *110*(5), 629–630. https://doi.org/10.2105/ajph.2019.305478
- [8] Fox, R. R., Lu, M.-L., Occhipinti, E., & Jaeger, M. (2019). Understanding outcome metrics of the revised NIOSH lifting equation. *Applied Ergonomics*, *81*, 102897. https://doi.org/10.1016/j.apergo.2019.102897
- [9]Timur, H., (1984), İş Ölçümü, İş Planlaması, Verimlilik, Türkiye ve Orta Doğu Amme İdaresi Enstitüsü Yayınları, [Business Measurement, Business Planning, Productivity, Turkey and the Middle East Public Administration Institute Publications] No: 207, Ankara.
- [10]MPM-REFA, (1988),İş Etüdü Yöntem Bilgisi, Veri Saptamanın Temel Kavramları, [Work Study Methodology, Basic Concepts of Data Identification], MPM Publications, 2nd Book, Ankara.

[11]"Makara Taşıma Ve Açma Arabası: Kablo Makarası Kaldırma Ekipmanları." *Makara Taşıma Ve Açma Arabası* | *Kablo Makarası Kaldırma Ekipmanları*, www.temhamakine.com/u-103-makara-tasima-ve-acma-arabasi.html.

[12]"1800.0US \$: U Tipi Hidrolik Makaslı Kaldırma Platformu Malzeme Taşıma Kaldırma Tezgahları: Hydraulic Lift: Table Lift Scissor Lift - AliExpress." *Aliexpress.com*, tr.aliexpress.com/item/32611397194.html.

10. APPENDIX

10.1. Work Sampling Sheets

Observation						Worl	ærs					
Time		Tekin M			Rușe			Murat			Nec det	
1 mile	AC	PR	C	AC	PR	C	AC	PR	C	AC	PR	C
08:25	M		CAT 07	M		HQ 113	ME		CAT 6	M		HQ 103
08:31	ME		CAT 07	ME		HQ 113	M	100%	CAT 6	M		HQ 103
08:35	MAT		CAT 07	K		HQ 113	M	100%	CAT 6	ME		HQ 103
08:42	M		CAT 07	M		HQ 113	M	100%	CAT 6	M		HQ 103
08:43	M		CAT 07	M		HQ 113	M	100%	CAT 6	ME		HQ 103
08:51	MAT		CAT 07	K		HQ 113	MAT	90%	CAT 6	MAT		HQ 103
08:54	K		CAT 07	K		HQ 113	K		CAT 6	K		HQ 103
09:01	M		CAT 07	M		HQ 113	M	100%	CAT 6	M		HQ 103
09:25	M		CAT 07	ME		HQ 113	M	100%	CAT 6	M		HQ 103
09:32	MT		CAT 07	ME		HQ 113	M	100%	CAT 6	M		HQ 103
09:45	M		CAT 07	ME		HQ 113	M	100%	CAT 6	ME		HQ 103
09:47	ME		CAT 07	ME		HQ 113	ME	100%	CAT 6	M		HQ 103
09:51	MT		CAT 07	M		HQ 113	MAT		CAT 6	M		HQ 103
10:03	MT		HQ 163	M		HQ 113	ME	100%	CAT 6	M		HQ 103
10:07	M		HQ 163	M		HQ 113	M	100%	CAT 6	M		HQ 103
10:10	M		HQ 163	M		HQ 113	M	100%	CAT 6	MAT		HQ 103
10:18	MAT		HQ 163	ME		HQ 113	MT	90%	CAT 6	ME		HQ 103
10:22	MAT		HQ 163	M		HQ 113	ME	100%	CAT 6	K		HQ 103
10:30	M		HQ 163	MT		HQ 113	M	100%	CAT 6	M		HQ 103
10:34	M		HQ 163	MAT		HQ 113	MT	90%	CAT 6	ME		HQ 103
10:58	M		HQ 163	MT		CAT 7 S/FTP	M	100%	CAT 6	MA		HQ 103
11:00	M		HQ 163	MAT		CAT 7 S/FTP	ME	100%	CAT 6	MA		HQ 103
11:09	M		HQ 163	K		CAT 7 S/FTP	ME	100%	CAT 6	MA		HQ 103
11:14	M		HQ 163	MT		CAT 7 S/FTP	ME	100%	CAT 6	MA		HQ 103
11:17	M		HQ 163	M		CAT 7 S/FTP	ME	100%	HQ 103	MA		HQ 103
11:42	MT		HQ 163	M		CAT 7 S/FTP	M	100%	HQ 103	MA		HQ 103
11:53	K		HQ 163	K		CAT 7 S/FTP	ME	100%	HQ 103	MA		HQ 103
11:55	K		HQ 163	K		CAT 7 S/FTP	K		HQ 103	K		HQ 103
13:11	K		HQ 163	K		CAT 7 S/FTP	K		HQ 103	K		HQ 103

13:16	M	HQ 163	M	CAT 7 S/FTP	M		HQ 103	M	HQ 103
13:28	M	HQ 163	M	CAT 7 S/FTP	M		HQ 103	MA	HQ 103
13:30	M	HQ 163	M	CAT 7 S/FTP	ME	100%	HQ 103	MA	HQ 103
13:34	ME	HQ 163	M	CAT 7 S/FTP	K		HQ 103	MA	HQ 103
13:37	MAT	HQ 163	ME	CAT 7 S/FTP	K		HQ 103	MA	HQ 103
13:41	ME	HQ 163	MS	CAT 7 S/FTP	M	100%	HQ 103	MA	HQ 103
13:43	M	HQ 163	MT	CAT 7 S/FTP	M	100%	HQ 103	MA	HQ 103
13:46	M	HQ 163	MAB	CAT 7 S/FTP	M	100%	HQ 103	MA	HQ 103
13:51	M	HQ 163	MAB	CAT 7 S/FTP	M	100%	HQ 103	MA	HQ 103
13:58	MT	HQ 163	MS	CAT 7 S/FTP	M	100%	HQ 103	MA	HQ 103
14:15	MA	HQ 163	M	CAT 7 S/FTP	M	100%	HQ 103	MA	HQ 103
14:17	MA	HQ 163	ME	CAT 7 S/FTP	M	100%	HQ 103	MA	HQ 103
14:25	MA	HQ 163	M	CAT 7 S/FTP	M	100%	HQ 103	MA	HQ 103
14:54	ME	HQ 163	M	CAT 7 S/FTP	MT	90%	HQ 103	MA	HQ 103
14:57	M	HQ 163	M	CAT 7 S/FTP	M	100%	HQ 103	MA	HQ 103
14:59	ME	HQ 163	ME	CAT 7 S/FTP	M	100%	HQ 103	MA	HQ 103
15:03	M	HQ 163	M	CAT 7 S/FTP	M	100%	HQ 103	MA	HQ 103
15:08	ME	HQ 163	M	CAT 7 S/FTP	M	100%	HQ 103	MA	HQ 103
15:09	MT	HQ 163	M	CAT 7 S/FTP	M	100%	HQ 103	MA	HQ 103
15:12	M	HQ 163	MAB	CAT 7 S/FTP	ME	100%	HQ 103	MA	HQ 103
15:18	M	HQ 163	MT	CAT 7 S/FTP	MT	90%	HQ 103	MA	HQ 103
15:31	M	HQ 163	MT	LIH(CIH)	M	100%	HQ 103	MA	HQ 103
15:34	M	HQ 163	M	LIH(CIH)	ME	100%	HQ 103	MA	HQ 103
15:40	M	HQ 163	M	LIH(CIH)	MT	90%	HQ 103	MA	HQ 103
15:42	ME	HQ 163	M	LIH(CIH)	M	100%	HQ 103	MA	HQ 103
15:47	MT	HQ 163	M	LIH(CIH)	M	100%	HQ 103	MA	HQ 103
15:51	MT	HQ 163	ME	LIH(CIH)	M	100%	HQ 103	MA	HQ 103
15:54	M	HQ 163	ME	LIH(CIH)	M	100%	HQ 103	MA	HQ 103
16:21	K	HQ 163	K	LIH(CIH)	MA		HQ 103	MA	HQ 103
16:23	K	HQ 163	K	LIH(CIH)	MT	90%	HQ 103	MA	HQ 103
16:28	ME	HQ 163	M	LIH(CIH)	MAB		HQ 103	MA	HQ 103
16:36	M	HQ 163	MT	LIH(CIH)	MAB		HQ 103	MA	HQ 103
16:40	MT	HQ 163	M	LIH(CIH)	MAB		HQ 103	MA	HQ 103

16:41	MAT	HQ 163	M	LIH(CIH)	MAB		HQ 103	MA	HQ 103
16:46	ME	HQ 163	M	LIH(CIH)	MAB		HQ 103	MA	HQ 103
16:49	M	HQ 163	MAT	LIH(CIH)	MAB		HQ 103	MA	HQ 103
16:55	M	HQ 163	ME	LIH(CIH)	MT	90%	HQ 103	MA	HQ 103

Observation						Worker	5					
Observation Time		Teki	n M.		Rușen ?	Γ.		Murat	J.		Necd et (G.
Time	AC	PR	С	AC	PR	C	AC	PR	C	AC	PR	C
08:21	M		T-H(st)H 2*2*0.8	M		HQ 163	ME		HD 113 Cu	MA		
08:24	M		T-H(st)H 2*2*0.8	M		HQ 163	M		HD 113 Cu	MA		
08:26	M		T-H(st)H 2*2*0.8	M		HQ 163	M		HD 113 Cu	MA		
08:34	M		T-H(st)H 2*2*0.8	M		HQ 163	MT		HD 113 Cu	MA		
08:38	M		T-H(st)H 2*2*0.8	M		HQ 163	M		HD 113 Cu	MA		
08:41	M		T-H(st)H 2*2*0.8	ME		HQ 163	M		HD 113 Cu	MA		
08:42	M		T-H(st)H 2*2*0.8	ME		HQ 163	ME		HD 113 Cu	MA		
08:56	K		T-H(st)H 2*2*0.8	K		HQ 163	K		HD 113 Cu	MA		
09:20	M		T-H(st)H 2*2*0.8	MAT		HQ 163	K		HD 113 Cu	MA		
09:27	M		T-H(st)H 2*2*0.8	M		HQ 163	K		HD 113 Cu	MA		
09:30	MT		T-H(st)H 2*2*0.8	M		HQ 163	M		HD 113 Cu	MA		
09:35	M		T-H(st)H 2*2*0.8	MT		HQ 163	M		HD 113 Cu	MA		
09:38	M		T-H(st)H 2+2+0.8	M		HQ 163	M		HD 113 Cu	MA		
09:40	M		T-H(st)H 2*2*0.8	M		HQ 163	M		HD 113 Cu	MA		
09:54	M		T-H(st)H 2*2*0.8	M		HQ 163	M		HD 113 Cu	MA		
10:15	ME		T-H(st)H 2+2+0.8	M		HQ 163	K		HD 113 Cu	MA		
10:43	K		T-H(st)H 2*2*0.8	M		HQ 163	M		HD 113 Cu	MA		
10:44	K		T-H(st)H 2+2+0.8	M		HQ 163	M		HD 113 Cu	MA		
11:03	ME		T-H(st)H 2*2*0.8	M		HQ 163	M		HD 113 Cu	MA		
11:07	M		T-H(st)H 2+2+0.8	MT		HQ 163	K		HD 113 Cu	MA		
11:13	M		T-H(st)H 2*2*0.8	M		HQ 163	ME		HD 113 Cu	MA		
11:40	K		T-H(st)H 2+2+0.8	K		HQ 163	M		HD 113 Cu	MA		
11:44	K		T-H(st)H 2*2*0.8	M		HQ 163	M		HD 113 Cu	MA		
11:45	K		T-H(st)H 2+2+0.8	M		HQ 163	M		HD 113 Cu	MA		
11:57	K		T-H(st)H 2*2*0.8	K		HQ 163	M		HD 113 Cu	MA		
11:59	K		T-H(st)H 2+2+0.8	K		HQ 163	ME		HD 113 Cu	M		HQ 103
13:09	MAT		T-H(st)H 2+2+0.8	ME		HQ 163	M		HD 113 Cu	M		HQ 103
13:10	M		T-H(st)H 2*2*0.8	M		HQ 163	M		HD 113 Cu	M		HQ 103
13:18	MAT		T-H(st)H 2*2*0.8	K		HQ 163	MT		HD 113 Cu	M		HQ 103

13 22 M					 				
13:31 M	13:22	M	T-H(st)H 2*2*0.8	MT	HQ 163	M	HD 113 Cu	M	HQ 103
13:40 ME	13:26	M	T-H(st)H 2*2*0.8	M	HQ 163	ME	HD 113 Cu	M	HQ 103
13:56 ME	13:31	M	T-H(st)H 2*2*0.8	M	HQ 163	M	HD 113 Cu	M	HQ 103
13:58 MT	13:40	ME	T-H(st)H 2*2*0.8	MT	HQ 163	M	HD 113 Cu	M	HQ 103
14:02 MAT	13:56	ME	T-H(st)H 2*2*0.8	MAT	HQ 163	M	HD 113 Cu	M	HQ 103
14:05 K	13:58	MT	T-H(st)H 2*2*0.8	ME	HQ 163	ME	HD 113 Cu	M	HQ 103
14:13 K T-H(s)H 2*2*0.8 MAT HQ 168 MAT HD 113 Cu M HQ 103 14:17 K TKS 168 M HQ 168 M HD 113 Cu M HQ 103 14:31 M TKS 168 MT HQ 168 M HD 113 Cu M HQ 103 14:37 ME TKS 168 K HQ 168 ME HD 113 Cu M HQ 103 14:42 ME TKS 168 M HQ 168 MT HD 113 Cu M HQ 103 14:48 MAT TKS 168 M HQ 168 M HD 113 Cu M HQ 103 14:55 ME TKS 168 M HQ 168 K HD 113 Cu M HQ 103 14:56 MT TKS 168 M HQ 168 K HD 113 Cu M HQ 103 15:04 M TKS 168 M HQ 168 K HD 113 Cu M HQ 103 15:05 M <t< td=""><td>14:02</td><td>MAT</td><td>T-H(st)H 2*2*0.8</td><td>M</td><td>HQ 163</td><td>M</td><td>HD 113 Cu</td><td>M</td><td>HQ 103</td></t<>	14:02	MAT	T-H(st)H 2*2*0.8	M	HQ 163	M	HD 113 Cu	M	HQ 103
14:17 K TKS 163 M HQ 168 M HD 113 Cu M HQ 103 14:31 M TKS 169 MT HQ 168 M HD 113 Cu M HQ 103 14:37 ME TKS 169 K HQ 168 ME HD 113 Cu M HQ 103 14:42 ME TKS 169 M HQ 168 MT HD 113 Cu M HQ 103 14:48 MAT TKS 168 M HQ 168 M HD 113 Cu M HQ 103 14:55 ME TKS 168 M HQ 168 K HD 113 Cu M HQ 103 14:56 MT TKS 168 M HQ 168 K HD 113 Cu M HQ 103 15:04 M TKS 168 M HQ 168 K HD 113 Cu M HQ 103 15:05 M TKS 168 M HQ 168 K HD 113 Cu M HQ 103 15:11 M TKS 168 <td>14:05</td> <td>K</td> <td>T-H(st)H 2*2*0.8</td> <td>MAT</td> <td>HQ 163</td> <td>M</td> <td>HD 113 Cu</td> <td>M</td> <td>HQ 103</td>	14:05	K	T-H(st)H 2*2*0.8	MAT	HQ 163	M	HD 113 Cu	M	HQ 103
14:31 M TKS 168 MT HQ 168 M HD 113 Cu M HQ 103 14:37 ME TKS 169 K HQ 168 ME HD 113 Cu M HQ 103 14:42 ME TKS 169 M HQ 168 MT HD 113 Cu M HQ 103 14:48 MAT TKS 169 M HQ 168 K HD 113 Cu M HQ 103 14:55 ME TKS 169 M HQ 168 K HD 113 Cu M HQ 103 14:56 MT TKS 169 M HQ 168 K HD 113 Cu M HQ 103 15:04 M TKS 169 M HQ 168 K HD 113 Cu M HQ 103 15:05 M TKS 169 M HQ 168 K HD 113 Cu M HQ 103 15:11 M TKS 169 ME HQ 168 MT HD 113 Cu M HQ 103 15:21 M TKS 169<	14:13	K	T-H(st)H 2*2*0.8	MAT	HQ 163	MAT	HD 113 Cu	M	HQ 103
14:37 ME TKS 168 K HQ 168 ME HD 113 Cu M HQ 103 14:42 ME TKS 168 M HQ 168 MT HD 113 Cu M HQ 103 14:48 MAT TKS 168 M HQ 168 M HD 113 Cu M HQ 103 14:55 ME TKS 168 M HQ 168 K HD 113 Cu M HQ 103 14:56 MT TKS 168 M HQ 168 K HD 113 Cu M HQ 103 15:04 M TKS 168 M HQ 168 K HD 113 Cu M HQ 103 15:05 M TKS 168 M HQ 168 MT HD 113 Cu MT HQ 103 15:11 M TKS 168 ME HQ 168 K HD 113 Cu MT HQ 103 15:21 M TKS 168 M HQ 168 ME HD 113 Cu M HQ 103 15:25 ME TKS 1	14:17	K	TK\$ 163	M	HQ 163	M	HD 113 Cu	M	HQ 103
14:42 ME TK\$ 163 M HQ 163 MT HD 113 Cu M HQ 103 14:48 MAT TK\$ 163 M HQ 163 M HD 113 Cu M HQ 103 14:55 ME TK\$ 163 M HQ 163 K HD 113 Cu M HQ 103 14:56 MT TK\$ 163 M HQ 163 K HD 113 Cu M HQ 103 15:04 M TK\$ 163 M HQ 163 K HD 113 Cu M HQ 103 15:05 M TK\$ 163 M HQ 163 MT HD 113 Cu MT HQ 103 15:05 M TK\$ 163 ME HQ 163 K HD 113 Cu MT HQ 103 15:11 M TK\$ 163 ME HQ 163 K HD 113 Cu M HQ 103 15:21 M TK\$ 163 M HQ 163 ME HD 113 Cu M HQ 103 15:25 ME TK\$ 16	14:31	M	TKS 163	MT	HQ 163	M	HD 113 Cu	M	HQ 103
14:48 MAT TKS 168 M HQ 168 M HD 113 Cu M HQ 103 14:55 ME TKS 168 M HQ 168 K HD 113 Cu M HQ 103 14:56 MT TKS 168 M HQ 168 K HD 113 Cu M HQ 103 15:04 M TKS 168 M HQ 168 K HD 113 Cu M HQ 103 15:05 M TKS 168 M HQ 168 MT HD 113 Cu MT HQ 103 15:11 M TKS 168 ME HQ 168 K HD 113 Cu M HQ 103 15:21 M TKS 168 M HQ 168 ME HD 113 Cu M HQ 103 15:25 ME TKS 168 K HQ 168 M HD 113 Cu M HQ 103 15:27 M TKS 168 K HQ 168 M HD 113 Cu M HQ 103 15:38 M TKS 168 <td>14:37</td> <td>ME</td> <td>TKS 163</td> <td>K</td> <td>HQ 163</td> <td>ME</td> <td>HD 113 Cu</td> <td>M</td> <td>HQ 103</td>	14:37	ME	TKS 163	K	HQ 163	ME	HD 113 Cu	M	HQ 103
14:55 ME TKS 163 M HQ 163 K HD 113 Cu M HQ 103 14:56 MT TKS 163 M HQ 163 K HD 113 Cu M HQ 103 15:04 M TKS 163 M HQ 163 K HD 113 Cu K HQ 103 15:05 M TKS 163 M HQ 163 MT HD 113 Cu MT HQ 103 15:11 M TKS 163 ME HQ 163 K HD 113 Cu M HQ 103 15:21 M TKS 163 M HQ 163 ME HD 113 Cu M HQ 103 15:25 ME TKS 163 K HQ 163 M HD 113 Cu M HQ 103 15:25 ME TKS 163 K HQ 163 M HD 113 Cu M HQ 103 15:27 M TKS 163 K HQ 163 M HD 113 Cu M HQ 103 15:38 M TKS 163 <td>14:42</td> <td>ME</td> <td>TKS 163</td> <td>M</td> <td>HQ 163</td> <td>MT</td> <td>HD 113 Cu</td> <td>M</td> <td>HQ 103</td>	14:42	ME	TKS 163	M	HQ 163	MT	HD 113 Cu	M	HQ 103
14:56 MT TKS 168 M HQ 168 K HD 113 Cu M HQ 103 15:04 M TKS 168 M HQ 168 K HD 113 Cu K HQ 103 15:05 M TKS 168 M HQ 168 MT HD 113 Cu MT HQ 103 15:11 M TKS 168 ME HQ 168 K HD 113 Cu M HQ 103 15:21 M TKS 168 M HQ 168 ME HD 113 Cu M HQ 103 15:25 ME TKS 168 K HQ 168 M HD 113 Cu M HQ 103 15:27 M TKS 168 K HQ 168 M HD 113 Cu M HQ 103 15:38 M TKS 168 K HQ 168 M HD 113 Cu MA HQ 103 15:59 K TKS 168 K HQ 168 ME HD 113 Cu K HQ 103 16:25 M TKS 168 <td>14:48</td> <td>MAT</td> <td>TKS 163</td> <td>M</td> <td>HQ 163</td> <td>M</td> <td>HD 113 Cu</td> <td>M</td> <td>HQ 103</td>	14:48	MAT	TKS 163	M	HQ 163	M	HD 113 Cu	M	HQ 103
15:04 M TKS 168 M HQ 168 K HD 113 Cu K HQ 103 15:05 M TKS 168 M HQ 168 MT HD 113 Cu MT HQ 103 15:11 M TKS 168 ME HQ 168 K HD 113 Cu M HQ 103 15:21 M TKS 168 M HQ 168 ME HD 113 Cu M HQ 103 15:25 ME TKS 168 K HQ 168 M HD 113 Cu M HQ 103 15:27 M TKS 168 K HQ 168 M HD 113 Cu M HQ 103 15:38 M TKS 168 K HQ 168 M HD 113 Cu MA HQ 103 15:53 K TKS 168 K HQ 168 ME HD 113 Cu MA HQ 103 15:59 K TKS 168 K HQ 168 K HD 113 Cu K HQ 103 16:25 M TKS 168 <td>14:55</td> <td>ME</td> <td>TKS 163</td> <td>M</td> <td>HQ 163</td> <td>K</td> <td>HD 113 Cu</td> <td>M</td> <td>HQ 103</td>	14:55	ME	TKS 163	M	HQ 163	K	HD 113 Cu	M	HQ 103
15:05 M TKS 168 M HQ 168 MT HD 113 Cu MT HQ 103 15:11 M TKS 168 ME HQ 168 K HD 113 Cu M HQ 103 15:21 M TKS 168 M HQ 168 ME HD 113 Cu M HQ 103 15:25 ME TKS 168 K HQ 168 M HD 113 Cu M HQ 103 15:27 M TKS 168 K HQ 168 M HD 113 Cu M HQ 103 15:38 M TKS 168 M HQ 168 M HD 113 Cu MA HQ 103 15:53 K TKS 168 K HQ 168 ME HD 113 Cu MA HQ 103 15:59 K TKS 168 K HQ 168 K HD 113 Cu K HQ 103 16:25 M TKS 168 ME HQ 168 M HD 113 Cu MA HQ 103 16:31 ME TKS 168<	14:56	MT	TKS 163	M	HQ 163	K	HD 113 Cu	M	HQ 103
15:11 M TKS 168 ME HQ 168 K HD 113 Cu M HQ 103 15:21 M TKS 168 M HQ 168 ME HD 113 Cu M HQ 103 15:25 ME TKS 168 K HQ 168 M HD 113 Cu M HQ 103 15:27 M TKS 168 K HQ 168 M HD 113 Cu M HQ 103 15:38 M TKS 168 M HQ 168 M HD 113 Cu MA HQ 103 15:53 K TKS 168 K HQ 168 ME HD 113 Cu MA HQ 103 15:59 K TKS 168 K HQ 168 K HD 113 Cu K HQ 103 16:25 M TKS 168 ME HQ 168 M HD 113 Cu M HQ 103 16:31 ME TKS 168 ME HQ 168 M HD 113 Cu MA HQ 103 16:38 ME TKS 168<	15:04	M	TKS 163	M	HQ 163	K	HD 113 Cu	K	HQ 103
15:21 M TKS 168 M HQ 168 ME HD 113 Cu M HQ 103 15:25 ME TKS 168 K HQ 168 M HD 113 Cu M HQ 103 15:27 M TKS 168 K HQ 168 M HD 113 Cu M HQ 103 15:38 M TKS 168 M HQ 168 M HD 113 Cu MA HQ 103 15:59 K TKS 168 K HQ 168 M HD 113 Cu M HQ 103 16:25 M TKS 168 ME HQ 168 M HD 113 Cu M HQ 103 16:31 ME TKS 168 ME HQ 168 M HD 113 Cu MA HQ 103 16:32 MAT TKS 168 ME HQ 168 M HD 113 Cu MA HQ 103 16:38 ME TKS 168 ME HQ 168 M HD 113 Cu MA HQ 103 16:41 ME TKS	15:05	M	TKS 163	M	HQ 163	MT	HD 113 Cu	MT	HQ 103
15:25 ME TKS 168 K HQ 168 M HD 113 Cu M HQ 103 15:27 M TKS 168 K HQ 168 M HD 113 Cu M HQ 103 15:38 M TKS 168 M HQ 168 ME HD 113 Cu MA HQ 103 15:59 K TKS 168 K HQ 168 K HD 113 Cu M HQ 103 16:25 M TKS 168 ME HQ 168 M HD 113 Cu M HQ 103 16:31 ME TKS 168 ME HQ 168 M HD 113 Cu MA HQ 103 16:32 MAT TKS 168 ME HQ 168 M HD 113 Cu MA HQ 103 16:38 ME TKS 168 ME HQ 168 M HD 113 Cu MA HQ 103 16:41 ME TKS 168 MAT HQ 168 M HD 113 Cu MA HQ 103	15:11	M	TK\$ 163	ME	HQ 163	K	HD 113 Cu	M	HQ 103
15:27 M TKS 168 K HQ 168 M HD 113 Cu M HQ 103 15:38 M TKS 168 M HQ 168 M HD 113 Cu MA HQ 103 15:53 K TKS 168 K HQ 168 ME HD 113 Cu MA HQ 103 15:59 K TKS 168 K HQ 168 K HD 113 Cu K HQ 103 16:25 M TKS 168 ME HQ 168 M HD 113 Cu M HQ 103 16:31 ME TKS 168 ME HQ 168 M HD 113 Cu MA HQ 103 16:32 MAT TKS 168 ME HQ 168 M HD 113 Cu MA HQ 103 16:38 ME TKS 168 M HQ 168 M HD 113 Cu MA HQ 103 16:41 ME TKS 168 MAT HQ 168 M HD 113 Cu MA HQ 103	15:21	M	TKS 163	M	HQ 163	ME	HD 113 Cu	M	HQ 103
15:38 M TKS 163 M HQ 163 M HD 113 Cu MA HQ 103 15:53 K TKS 163 K HQ 163 ME HD 113 Cu MA HQ 103 15:59 K TKS 163 K HQ 163 K HD 113 Cu K HQ 103 16:25 M TKS 163 ME HQ 163 M HD 113 Cu M HQ 103 16:31 ME TKS 163 M HQ 163 M HD 113 Cu MA HQ 103 16:32 MAT TKS 163 ME HQ 163 M HD 113 Cu MA HQ 103 16:38 ME TKS 163 M HQ 163 M HD 113 Cu MA HQ 103 16:41 ME TKS 163 MAT HQ 163 M HD 113 Cu MA HQ 103	15:25	ME	TKS 163	K	HQ 163	M	HD 113 Cu	M	HQ 103
15:53 K TKS 163 K HQ 163 ME HD 113 Cu MA HQ 103 15:59 K TKS 163 K HQ 163 K HD 113 Cu K HQ 103 16:25 M TKS 163 ME HQ 163 M HD 113 Cu M HQ 103 16:31 ME TKS 163 M HQ 163 M HD 113 Cu MA HQ 103 16:32 MAT TKS 163 ME HQ 163 M HD 113 Cu MA HQ 103 16:38 ME TKS 163 M HQ 163 M HD 113 Cu MA HQ 103 16:41 ME TKS 163 MAT HQ 163 M HD 113 Cu MA HQ 103	15:27	M	TKS 163	K	HQ 163	M	HD 113 Cu	M	HQ 103
15:59 K TKS 168 K HQ 168 K HD 113 Cu K HQ 103 16:25 M TKS 168 ME HQ 168 M HD 113 Cu M HQ 103 16:31 ME TKS 168 M HQ 168 M HD 113 Cu MA HQ 103 16:32 MAT TKS 163 ME HQ 168 M HD 113 Cu MA HQ 103 16:38 ME TKS 163 M HQ 168 M HD 113 Cu MA HQ 103 16:41 ME TKS 168 MAT HQ 168 M HD 113 Cu MA HQ 103	15:38	M	TKS 163	M	HQ 163	M	HD 113 Cu	MA	HQ 103
16:25 M TKS 168 ME HQ 168 M HD 113 Cu M HQ 103 16:31 ME TKS 168 M HQ 168 M HD 113 Cu MA HQ 103 16:32 MAT TKS 168 ME HQ 168 M HD 113 Cu MA HQ 103 16:38 ME TKS 168 M HQ 168 M HD 113 Cu MA HQ 103 16:41 ME TKS 168 MAT HQ 168 M HD 113 Cu MA HQ 103	15:53	K	TKS 163	K	HQ 163	ME	HD 113 Cu	MA	HQ 103
16:31 ME TKS 168 M HQ 168 M HD 113 Cu MA HQ 103 16:32 MAT TKS 168 ME HQ 168 M HD 113 Cu MA HQ 103 16:38 ME TKS 163 M HQ 168 M HD 113 Cu MA HQ 103 16:41 ME TKS 168 MAT HQ 168 M HD 113 Cu MA HQ 103	15:59	K	TKS 163	K	HQ 163	K	HD 113 Cu	K	HQ 103
16:32 MAT TKS 168 ME HQ 168 M HD 113 Cu MA HQ 103 16:38 ME TKS 168 M HQ 168 M HD 113 Cu MA HQ 103 16:41 ME TKS 168 MAT HQ 168 M HD 113 Cu MA HQ 103	16:25	M	TKS 163	ME	HQ 163	M	HD 113 Cu	M	HQ 103
16:38 ME TKS 163 M HQ 163 M HD 113 Cu MA HQ 103 16:41 ME TKS 163 MAT HQ 163 M HD 113 Cu MA HQ 103	16:31	ME	TKS 163	M	HQ 163	M	HD 113 Cu	MA	HQ 103
16:41 ME TKS 163 MAT HQ 163 M HD 113 Cu MA HQ 103	16:32	MAT	TKS 163	ME	HQ 163	M	HD 113 Cu	MA	HQ 103
	16:38	ME	TKS 163	M	HQ 163	M	HD 113 Cu	MA	HQ 103
16:45 M TKS 168 MT HQ 168 M HD 113 Cu MA HQ 103	16:41	ME	TKS 163	MAT	HQ 163	M	HD 113 Cu	MA	HQ 103
	16:45	M	TKS 163	MT	HQ 163	M	HD 113 Cu	MA	HQ 103

16:46	M	TKS 163	MAT	HQ 163	M	HD 113 Cu	MA	HQ 103
16:53	ME	TKS 163	MAT	HQ 163	MT	HD 113 Cu	MA	HQ 103
16:57	MAT	TKS 163	M	HQ 163	M	HD 113 Cu	MA	HQ 103
16:58	M	TKS 163	M	HQ 163	M	HD 113 Cu	MT	HQ 103

Observation						Worla	rs					
Time		Tekin l			Rușei			Murat U	_		Necdet	
Time	AC	PR	С	AC	PR	C	AC	PR	С	AC	PR	С
08:50	ME		HD 163	ME		HD 163	İZİNLİ			M		HD 063
08:57	K		HD 163	K		HD 163	İZİNLİ			K		HD 063
08:58	K		HD 163	K		HD 163	IZINLI			K		HD 063
09:22	MAT		HD 163	M		HD 163	IZINLI			MAT		HD 063
09:25	MAT		HD 163	ME		HD 163	İZİNLİ			MAT		HD 063
09:33	M		Pronet	M		HD 163	İZİNLİ			ME		HD 063
09:40	ME		Pronet	M		HD 163	İZİNLİ			M		HD 063
09:42	MAT		Pronet	M		HD 163	IZINLI			M		HD 063
09:57	K		Pronet	MAT		Pronet 6*0.22	İZİNLİ			K		HD 063
10:02	K		Pronet	MAT		Pronet 6*0.22	İZİNLİ			K		HD 063
10:12	MB		Pronet	M		Pronet 6*0.22	İZİNLİ			MB		HD 063
10:13	MB		Pronet	ME		Pronet 6*0.22	IZINLI			MB		HD 063
10:19	MB		Pronet	M		Pronet 6*0.22	IZINLI			M		HD 063
10:27	MB		Pronet	M		Pronet 6*0.22	İZİNLİ			M		HD 063
10:39	K		Pronet	K		Pronet 6*0.22	İZİNLİ			M		HD 063
10:44	K		Pronet	K		Pronet 6*0.22	İZİNLİ			M		HD 063
10:52	K		Pronet	M		Pronet 6*0.22	IZINLI			M		HD 063
10:54	K		Pronet	ME		Pronet 6*0.22	İZİNLİ			ME		HD 063
11:03	K		Pronet	MAT		Pronet 6*0.22	İZİNLİ			ME		HD 063
11:11	K		Pronet	M		Pronet 6*0.22	İZİNLİ			M		HD 063
11:21	K		Pronet	M		Pronet 6*0.22	IZINLI			M		HD 063
11:34	K		Pronet	M		Pronet 6*0.22	IZINLI			ME		HD 063
11:37	K		Pronet	MAT		Pronet 6*0.22	İZİNLİ			M		HD 063
11:39	K		Pronet	M		Pronet 6*0.22	İZİNLİ			M		HD 063
11:54	K		Pronet	M		Pronet 6*0.22	İZİNLİ			K		HD 063
11:58	K		Pronet	M		Pronet 6*0.22	IZINLI			K		HD 063
13:09	MAB		Pronet	M		Pronet 6*0.22	İZİNLİ			M		HD 063
13:24	MAB		Pronet	M		Pronet 6*0.22	İZİNLİ			M		HD 063
13:26	MAB		Pronet	ME		Pronet 6*0.22	İZİNLİ			ME		HD 063
13:31	MAB		Pronet	M		Pronet 6*0.22	IZINLI			M		HD 063
13:42	M		Pronet	ME		Pronet 6*0.22	IZINLI			M		HD 063
13:56	M	100	CAT 6	ME		Pronet 6*0.22	İZİNLİ			MAT		HD 063
14:01	M	115	CAT 6	M		Pronet 6*0.22	İZİNLİ			MAT		HD 063
14:05	M	100	CAT 6	M		Pronet 6*0.22	İZİNLİ			M		HD 063
14:09	M	100	CAT 6	ME		Pronet 6*0.22	IZINLI			M		HD 063
14:11	M	120	CAT 6	MAT		Pronet 6*0.22	İZİNLİ			ME		HD 063

14:17	M	120	CAT 6	M	Pronet 6*0.22	iziNLi	M	HD 063
14:18	M	110	CAT 6	ME	Pronet 6*0.22	IZINLI	M	HD 063
14:33	M	120	CAT 6	M	Pronet 6*0.22	IZINLI	M	HD 063
14:38	M	120	CAT 6	M	Pronet 6*0.22	iziNLi	K	HD 063
14:46	M	100	CAT 6	ME	Pronet 6*0.22	İZİNLİ	M	HD 063
14:47	M	115	CAT 6	M	Pronet 6*0.22	IZINLI	M	HD 063
15:04	M	110	CAT 6	M	Pronet 6*0.22	IZINLI	M	HD 063
15:18	M	115	CAT 6	MT	Pronet 6*0.22	İZİNLİ	M	PVC
15:27	MAB		CAT 6	M	Pronet 6*0.22	İZİNLİ	M	PVC
15:36	MAB		CAT 6	M	Pronet 6*0.22	İZİNLİ	M	PVC
15:46	MAB		CAT 6	M	Pronet 6*0.22	IZINLI	ME	PVC
15:52	MAB		CAT 6	ME	Pronet 6*0.22	izinli	MT	PVC
15:54	MAB		CAT 6	M	Pronet 6*0.22	İZİNLİ	M	PVC
15:54	MAB		CAT 6	M	Pronet 6*0.22	İZİNLİ	M	PVC
15:58	MAB		CAT 6	M	Pronet 6*0.22	IZINLI	M	PVC
16:19	M	100	CAT 6	M	Pronet 6*0.22	IZINLI	M	PVC
16:26	K		CAT 6	ME	Pronet 6*0.22	İZİNLİ	MAT	PVC
16:35	K		CAT 6	ME	Pronet 6*0.22	İZİNLİ	MT	PVC
16:42	K		CAT 6	ME	Pronet 6*0.22	izinli	K	PVC
16:48	K		CAT 6	M	Pronet 6*0.22	IZINLI	K	PVC
16:51	MAT	95	CAT 6	MAT	Pronet 6*0.22	izinli	M	PVC
16:53	M	100	CAT 6	M	Pronet 6*0.22	izinli	M	PVC

Observation						Work	ers					
Observation Time		Tekin	M.		Rușen?			Murat V	U.		Necdet (; .
Time	AC	PR	С	AC	PR	С	AC	PR	С	AC	PR	С
09:17	MAT	95	CAT 6	MT		CCTV	İB			ME		CCTV
09:26	M	120	CAT 6	M		CCTV	İB			ME		CCTV
09:32	M	120	CAT 6	MAT		CCTV	İB			ME		CCTV
09:33	M	120	CAT 6	M		CCTV	İB			İB		CCTV
09:36	MAT	95	CAT 6	M		CCTV	İB			İB		CCTV
09:41	M	105	CAT 6	MAT		CCTV	İB			İB		CCTV
09:44	M	130	CAT 6	MAT		CCTV	İB			İB		CCTV
10:06	MT	100	CAT 6	ME		CCTV	İB			İB		CCTV
10:08	M	120	CAT 6	M		CCTV	İB			İB		CCTV
10:28	M	120	CAT 6	M		CCTV	İB			İB		CCTV
10:33	ME	100	CAT 6	M		CCTV	İB			İB		CCTV
10:40	ME	100	CAT 6	ME		CCTV	İB			İB		CCTV
10:55	MAB		CAT 6	M		CCTV	İB			İB		CCTV
11:00	MAT		FE 180	ME		CCTV	İB			İB		CCTV
11:02	İB		FE 180	ME		CCTV	İB			İB		CCTV
11:06	M		FE 180	ME		CCTV	İB			İB		CCTV
11:07	M		FE 180	MT		CCTV	İB			İB		CCTV
11:11	MT		FE 180	MT		CCTV	İB			İB		CCTV
11:23	MAT		FE 180	MAT		CCTV	İB			İB		CCTV
11:33	M		FE 180	ME		CCTV	İB			İB		CCTV
11:37	M		FE 180	M		CCTV	İB			İB		CCTV
11:43	M		FE 180	M		CCTV	İB			İB		CCTV
11:45	M		FE 180	ME		CCTV	İB			İB		CCTV
11:46	M		FE 180	M		CCTV	İB			İB		CCTV
11:51	MT		FE 180	M		CCTV	İB			İB		CCTV
11:54	ME		FE 180	ME		CCTV	İB			İB		CCTV
13:30	MT		FE 180	ME		CCTV	İB			M		CCTV
13:35	MAB		FE 180	M		CCTV	İB			M		CCTV
13:36	MAB		FE 180	M		CCTV	İB			M		CCTV
13:42	M		FE 180	M		CCTV	İB			MT		CCTV

13:44 ME							
	FE 180	M	CCTV	İB		M	CCTV
14:00 M	FE 180	K	CCTV	İB		K	CCTV
14:08 İB		ME	CCTV	İB		M	CCTV
14:14 İB		ME	CCTV	İB		M	CCTV
14:18 İB		ME	CCTV	İB		M	CCTV
14:20 İB		ME	CCTV	İB		ME	CCTV
14:22 İB		ME	CCTV	İB		MΕ	CCTV
14:26 İB		ME	CCTV	İB		ME	CCTV
14:27 İB		ME	CCTV	İB		M	CCTV
14:30 İB		ME	CCTV	İB		ME	CCTV
14:44 İB		ME	CCTV	İB		M	CCTV
14:47 İB		ME	CCTV	İB		M	CCTV
14:48 İB		MT	CCTV	İB		MΕ	CCTV
15:00 İB		ME	CCTV	İB		ME	CCTV
15:03 İB		ME	CCTV	İB		K	CCTV
15:05 İB		ME	CCTV	İB		K	CCTV
15:09 İB		ME	CCTV	İB		M	CCTV
15:19 İB		K	CCTV	İB		MAT	CCTV
15:20 İB		K	CCTV	İB		M	CCTV
15:28 İB		MAB		İB		MAT	CCTV
15:30 İB		MAB		İB		M	CCTV
15:48 İB		MAB		İB		M	CCTV
15:51 İB		MAB		İB		M	CCTV
15:53 İB		MAB		İB		M	CCTV
15:57 İB		MAB		İB		ME	CCTV
16:20 İB		MAB		İB		M	CCTV
16:24 İB		MAB		İB		K	CCTV
16:26 İB		MAB		İB		K	CCTV
16:34 İB		MAB		İB		ME	CCTV
16:38 İB		MAB		İB		M	CCTV
16:43 İB		MAB		İB		ME	CCTV
16:50 İB		MAB		İB		M	CCTV

Observation						Wor	rkers					
Time		Tekin M	ſ.		Rușen T	r.		Murat V	I.		Necdet	G.
	AC	PR	C	AC	PR	C	AC	PR	C	AC	PR	C
08:50	K		CAT6	K		HD063	ME		HD103	MAG		CCTV
08:53	K		CAT6	K		HD063	ME		HD103	MT		CCTV
08:57	K		CAT6	K		HD063	K		HD103	K		CCTV
09:21	M	120	CAT6	M		HD063	MA		HD103	MAG		CCTV
09:26	M	120	CAT6	M		HD063	MA		HD103	MAG		CCTV
09:36	ME	100	CAT6	M		HD063	MA		HD103	M		JE-H180
09:42	M	120	CAT6	M		HD063	MA		HD103	M		JE-H180
09:53	M	120	CAT6	ME		HD063	MA		HD103	M		JE-H180
09:54	M	120	CAT6	ME		HD063	MA		HD103	M		JE-H180
10:07	M	105	CAT6	M		HD063	MA		HD103	M		JE-H180
10:12	M	100	CAT6	M		HD063	MA		HD103	M		JE-H180
10:23	M	110	CAT6	ME		HD063	MMA		HD103	ME		JE-H180
10:25	M	110	CAT6	ME		HD063	MAB		HD103	M		JE-H180
10:28	M	100	CAT6	M		HD063	MAB		HD103	M		JE-H180
10:34	MS	100	CAT6	ME		HD063	MAB		HD103	ME		JE-H180
10:45	MAT	95	CAT6	M		HD063	MT		HD103	ME		JE-H180
10:49	M	120	CAT6	M		HD063	MT		HD103	M		JE-H180
10:55	M	120	CAT6	M		HD063	MAT		HD103	ME		JE-H180
10:57	MAB		CAT6	M		HD063	MAB		HD103	M		JE-H180
11:04	MAB		CAT6	ME		HD063	MAB		HD103	ME		JE-H180
11:10	MAB		CAT6	M		HD063	M		HD103	M		JE-H180
11:13	M	55	CAT6	MAT		HD063	M		HD103	M		JE-H180
11:20	M	70	CAT6	ME		HD063	M		HD103	M		JE-H180
11:22	M	70	CAT6	M		HD063	M		HD103	ME		JE-H180
11:28	M	70	CAT6	M		HD063	ME		HD103	ME		
11:58	M	70	CAT6	M		HD063	MAT		HD103	MAT		
13:31	K		CAT6	K		HD063	K		HD103	K		
13:35	K		CAT6	M		HD063	MAT		HD103	K		
13:40	MAB			ME		HD063	M		HD103	M		
13:46	MAB			M		HD063	M		HD103	ME		

13:44	ME	FE 180	M	CCTV	İB		M	CCTV
14:00	M	FE 180	K	CCTV	İB		K	CCTV
14:08	İB		ME	CCTV	İB		M	CCTV
14:14	İB		ME	CCTV	İB		M	CCTV
14:18	İB		ME	CCTV	İB		M	CCTV
14:20	İB		ME	CCTV	İB		ME	CCTV
14:22	İB		ME	CCTV	İB		ME	CCTV
14:26	İB		ME	CCTV	İB		ME	CCTV
14:27	İB		ME	CCTV	İB		M	CCTV
14:30	İB		ME	CCTV	İB		ME	CCTV
14:44	İB		ME	CCTV	İB		M	CCTV
14:47	İB		ME	CCTV	İB		M	CCTV
14:48	İB		MT	CCTV	İB		ME	CCTV
15:00	İB		ME	CCTV	İB		ME	CCTV
15:03	İB		ME	CCTV	İB		K	CCTV
15:05	İB		ME	CCTV	İB		K	CCTV
15:09	İB		ME	CCTV	İB		M	CCTV
15:19	İB		K	CCTV	İB		MAT	CCTV
15:20	İΒ		K	CCTV	İB		M	CCTV
15:28	İB		MAB		İB		MAT	CCTV
15:30	İB		MAB		İB		M	CCTV
15:48	İB		MAB		İB		M	CCTV
15:51	İB		MAB		İB		M	CCTV
15:53	İB		MAB		İB		M	CCTV
15:57	İB		MAB		İB		ME	CCTV
16:20	İB		MAB		İB		M	CCTV
16:24	İB		MAB		İB		K	CCTV
16:26	İB		MAB		İB		K	CCTV
16:34	İB		MAB		İB		ME	CCTV
16:38	İB		MAB		İB		M	CCTV
16:43	İB		MAB		İB		ME	CCTV
16:50	İB		MAB		İB		M	CCTV

02/03/2021

Observation Time		Tekin M	ſ.		Rușen T	1.		Ferdi K		ErdalŞ.			
THUE	AC	PR	С	AC	PR	С	AC	PR	С	AC	PR	C	
08:36	M		HSLH-OZ	M		CCTV	MAT		JE-HST	MT		HQ113	
08:40	M		HSLH-OZ	M		CCTV	M		JE-HST	M		HQ113	
	ME		HSLH-OZ	ME			M			M			
08:42						CCTV			JE-HST			HQ113	
08:50	MT		HSLH-OZ	M		CCTV	K		JE-HST	MT		HQ113	
09:19	M		HSLH-OZ	ME		CCTV	M		JE-HST	M		HQ113	
09:21	M		HSLH-OZ	ME		CCTV	M		JE-HST	M		HQ113	
09:34	MAB		HSLH-OZ	M		CCTV	ME		JE-HST	M		HQ113	
09:42	MAB		HSLH-OZ	M		CCTV	ME		JE-HST	M		HQ113	
09:46	MAB		HSLH-OZ	M		CCTV	M		JE-HST	M		HQ113	
09:55	MAB		HSLH-OZ	M		CCTV	MT		JE-HST	ME		HQ113	
09:58	MAB		HSLH-OZ	ME		CCTV	M		JE-HST	ME		HQ113	
10:05	MAB		HSLH-OZ	ME		CCTV	MT		JE-HST	MT		HQ113	
	_												
10:11	MAB		HSLH-OZ	MT		CCTV	M		JE-HST	M	_	HQ113	
10:21	MAB		HSLH-OZ	ME		CCTV	M		JE-HST	ME		HQ113	
10:23	MAB		HSLH-OZ	ME		CCTV	M		JE-HST	M		HQ113	
10:24	MAB		HSLH-OZ	M		CCTV	M		JE-HST	M		HQ113	
10:34	MAB		HSLH-OZ	M		CCTV	M		JE-HST	M		HQ113	
10:42	MAB		HSLH-OZ	ME		CCTV	ME		JE-HST	MAT		HQ113	
10:49	MAB		HSLH-OZ	ME		CCTV	MT		JE-HST	M		HQ113	
10:57	MAB		HSLH-OZ	ME		CCTV	ME		JE-HST	ME		HQ113	
11:00	MAB		HSLH-OZ	M		CCTV	M		JE-HST	M			
												HQ113	
11:04	MAB		HSLH-OZ	M		CCTV	M		JE-HST	ME	_	HQ113	
11:11	MAB		HSLH-OZ	ME		CCTV	M		JE-HST	MAT		HQ113	
11:18	MAB		HSLH-OZ	K		CCTV	MAT		JE-HST	M		HQ113	
11:19	MT		HSLH-OZ	M		CCTV	MAT		JE-HST	M		HQ113	
11:27	M		HSLH-OZ	ME		CCTV	K		JE-HST	M	100	CAT 6	
11:35	ME		HSLH-OZ	MAT		CCTV	M		JE-HST	ME	100	CAT 6	
11:46	MAB		HSLH-OZ	ME		CCTV	M		JE-HST	M	100	CAT 6	
13:30	MAB		HSLH-OZ	ME		CCTV	M		JE-HST	M	100	CAT 6	
13:34	MAB		HSLH-OZ	M		CCTV	M		JE-HST	M	100	CAT 6	
13:44	2412												
	MAB		HSLH-OZ	ME		CCTV	M		JE-HST	M	100	CAT 6	
13:46	MAB		HSLH-OZ	M		CCTV	M		JE-HST	MT	100 95	CAT 6	
13:46 13:47			$\overline{}$										
	MAB		HSLH-OZ	M		CCTV	M		JE-HST	MT		CAT 6	
13:47	MAB MAB		HSLH-OZ HSLH-OZ	M ME		CCTV CCTV	M K		JE-HST JE-HST JE-HST	MT K		CAT 6 CAT 6 CAT 6	
13:47 13:50 14:02	MAB MAB MAB		HSLH-OZ HSLH-OZ HSLH-OZ	M ME M M		CCTV CCTV CCTV	M K MAG MT		JE-HST JE-HST JE-HST JE-HST	MT K K ME	95	CAT 6 CAT 6 CAT 6 CAT 6	
13:47 13:50 14:02 14:06	MAB MAB MAB MAB MAB		HSLH-OZ HSLH-OZ HSLH-OZ HSLH-OZ	M ME M M K		CCTV CCTV CCTV CCTV	M K MAG MT ME		JE-HST JE-HST JE-HST JE-HST JE-HST	MT K K ME M	95 100 100	CAT 6 CAT 6 CAT 6 CAT 6 CAT 6	
13:47 13:50 14:02 14:06 14:16	MAB MAB MAB MAB MAB MAB		HSLH-OZ HSLH-OZ HSLH-OZ HSLH-OZ HSLH-OZ HSLH-OZ	M ME M M K ME		CCTV CCTV CCTV CCTV CCTV	M K MAG MT ME ME		JE-HST JE-HST JE-HST JE-HST JE-HST JE-HST	MT K K ME M	95 100 100 100	CAT 6	
13:47 13:50 14:02 14:06 14:16 14:28	MAB MAB MAB MAB MAB MAB MAB		HSLH-OZ HSLH-OZ HSLH-OZ HSLH-OZ HSLH-OZ HSLH-OZ HSLH-OZ	M ME M M K ME		CCTV CCTV CCTV CCTV CCTV CCTV	M K MAG MT ME ME ME		JE-HST JE-HST JE-HST JE-HST JE-HST JE-HST JE-HST	MT K K ME M M M	95 100 100 100 100	CAT 6	
13:47 13:50 14:02 14:06 14:16 14:28 14:31	MAB MAB MAB MAB MAB MAB MAB MAB MAB		HSLH-OZ HSLH-OZ HSLH-OZ HSLH-OZ HSLH-OZ HSLH-OZ HSLH-OZ HSLH-OZ	M ME M M K ME M M		CCTV CCTV CCTV CCTV CCTV CCTV CCTV	M K MAG MT ME ME ME MAG		JE-HST JE-HST JE-HST JE-HST JE-HST JE-HST JE-HST JE-HST	MT K K ME M M M M	95 100 100 100 100 100	CAT 6	
13:47 13:50 14:02 14:06 14:16 14:28 14:31 14:37	MAB HSLH-OZ HSLH-OZ HSLH-OZ HSLH-OZ HSLH-OZ HSLH-OZ HSLH-OZ	M ME M M K ME M M		CCTV CCTV CCTV CCTV CCTV CCTV CCTV CCTV	M K MAG MT ME ME MAG MAG MT		JE-HST JE-HST JE-HST JE-HST JE-HST JE-HST JE-HST JE-HST JE-HST JE-HST JE-HST	MT K K ME M M M M M M M MT	95 100 100 100 100 100 95	CAT 6			
13:47 13:50 14:02 14:06 14:16 14:28 14:31 14:37 14:42	MAB HSLH-OZ HSLH-OZ HSLH-OZ HSLH-OZ HSLH-OZ HSLH-OZ HSLH-OZ HSLH-OZ	ME ME M K ME M M M M M M M M M M M M M M		CCTV CCTV CCTV CCTV CCTV CCTV CCTV CCTV	M K MAG MT ME MAG MAG MT K		JE-HST JE-HST JE-HST JE-HST JE-HST JE-HST JE-HST JE-HST JE-HST JE-HST JE-HST JE-HST JE-HST	MT K K ME M M M M M M MT ME	95 100 100 100 100 100 95 100	CAT 6			
13:47 13:50 14:02 14:06 14:16 14:28 14:31 14:37	MAB HSLH-OZ HSLH-OZ HSLH-OZ HSLH-OZ HSLH-OZ HSLH-OZ HSLH-OZ	M ME M M K ME M M		CCTV CCTV CCTV CCTV CCTV CCTV CCTV CCTV	M K MAG MT ME ME MAG MAG MT		JE-HST JE-HST JE-HST JE-HST JE-HST JE-HST JE-HST JE-HST JE-HST JE-HST JE-HST	MT K K ME M M M M M M M MT	95 100 100 100 100 100 95	CAT 6			
13:47 13:50 14:02 14:06 14:16 14:28 14:31 14:37 14:42	MAB HSLH-OZ HSLH-OZ HSLH-OZ HSLH-OZ HSLH-OZ HSLH-OZ HSLH-OZ HSLH-OZ	ME ME M K ME M M M M M M M M M M M M M M		CCTV CCTV CCTV CCTV CCTV CCTV CCTV CCTV	M K MAG MT ME MAG MAG MT K		JE-HST JE-HST JE-HST JE-HST JE-HST JE-HST JE-HST JE-HST JE-HST JE-HST JE-HST JE-HST JE-HST	MT K K ME M M M M M M MT ME	95 100 100 100 100 100 95 100	CAT 6			
13:47 13:50 14:02 14:06 14:16 14:28 14:31 14:37 14:42 14:45	MAB HSLH-OZ HSLH-OZ HSLH-OZ HSLH-OZ HSLH-OZ HSLH-OZ HSLH-OZ HSLH-OZ HSLH-OZ HSLH-OZ	M ME M M K ME M M M M M M M M M M M M ME		CCTV CCTV CCTV CCTV CCTV CCTV CCTV CCTV	M K MAG MT ME ME MAG MAG MAG MT K MT		JE-HST JE-HST JE-HST JE-HST JE-HST JE-HST JE-HST JE-HST JE-HST JE-HST JE-HST JE-HST JE-HST JE-HST	MT K K ME M M M M M M M MT ME	95 100 100 100 100 100 95 100	CAT 6			
13:47 13:50 14:02 14:06 14:16 14:28 14:31 14:37 14:42 14:45 14:49	MAB HSLH-OZ HSLH-OZ HSLH-OZ HSLH-OZ HSLH-OZ HSLH-OZ HSLH-OZ HSLH-OZ HSLH-OZ HSLH-OZ HSLH-OZ	M ME M M K ME M M M M M M M M M M M M M		CCTV CCTV CCTV CCTV CCTV CCTV CCTV CCTV	M K MAG MT ME MAG MAG MT K MT K MT ME		JE-HST JE-HST JE-HST JE-HST JE-HST JE-HST JE-HST JE-HST JE-HST JE-HST JE-HST JE-HST JE-HST JE-HST JE-HST	MT K K ME M M M M M M M M M M M M M M M M	95 100 100 100 100 100 95 100 100	CAT 6			
13:47 13:50 14:02 14:06 14:16 14:28 14:31 14:37 14:42 14:45 14:45 15:01 15:05	MAB Z HSLH-OZ HSLH-OZ HSLH-OZ HSLH-OZ HSLH-OZ HSLH-OZ HSLH-OZ HSLH-OZ HSLH-OZ HSLH-OZ HSLH-OZ HSLH-OZ HSLH-OZ HSLH-OZ HSLH-OZ	M ME M M K ME M M M M M M M ME ME M M ME ME ME M M ME		CCTV CCTV CCTV CCTV CCTV CCTV CCTV CCTV	M K MAG MT ME MAG MT K MT K MT ME MT ME MT ME MT ME MT ME MT ME MT MT ME MT ST IE-HST IE-HST IE-HST IE-HST IE-HST IE-HST IE-HST IE-HST IE-HST IE-HST IE-HST IE-HST IE-HST IE-HST IE-HST IE-HST IE-HST IE-HST	MT K K ME M M M M M M M MT ME M M M ME	95 100 100 100 100 95 100 100 100 100	CAT 6					
13:47 13:50 14:02 14:06 14:16 14:28 14:31 14:37 14:42 14:45 14:49 15:01 15:05 15:11	MAB Z HSLH-OZ HSLH-OZ HSLH-OZ HSLH-OZ HSLH-OZ HSLH-OZ HSLH-OZ HSLH-OZ HSLH-OZ HSLH-OZ HSLH-OZ HSLH-OZ HSLH-OZ HSLH-OZ HSLH-OZ HSLH-OZ	M ME M M K ME M M M M M M ME ME M M ME ME ME M M ME		CCTV CCTV CCTV CCTV CCTV CCTV CCTV CCTV	M K MAG MT ME MAG MT K MT M M M M M M M M M M M M M M M M		JE-HST JE-HST	MT K K ME M M M M M M M MT ME M M M M M M M M	95 100 100 100 100 95 100 100 100 100 100	CAT 6 CAT 6 CAT 6 CAT 6			
13:47 13:50 14:02 14:06 14:16 14:28 14:31 14:37 14:42 14:45 14:49 15:01 15:05 15:11 15:24	MAB Z HSLH-OZ HSLH-OZ HSLH-OZ HSLH-OZ HSLH-OZ HSLH-OZ HSLH-OZ HSLH-OZ HSLH-OZ HSLH-OZ HSLH-OZ HSLH-OZ HSLH-OZ HSLH-OZ HSLH-OZ HSLH-OZ HSLH-OZ HSLH-OZ HSLH-OZ	M ME ME ME ME ME ME ME ME ME ME ME ME ME		CCTV CCTV CCTV CCTV CCTV CCTV CCTV CCTV	M K MAG MT ME MAG MT K MT ME MT ME M M MT ME M M MT ME M M M M		IE-HST IE-HST	MT K K ME M M M M M MT ME M M M MT ME M M M M	95 100 100 100 100 95 100 100 100 100 100 100	CAT 6 CAT 6 CAT 6 CAT 6 CAT 6 CAT 6			
13:47 13:50 14:02 14:06 14:16 14:28 14:31 14:37 14:42 14:45 14:49 15:01 15:05 15:11 15:24 15:25	MAB Z HSLH-OZ	M ME M M K ME M M M M M ME ME ME M M M M		CCTV CCTV CCTV CCTV CCTV CCTV CCTV CCTV	M K MAG MT ME MAG MT K MT ME MT ME MT ME MT -HST IE-HST	MT K K ME M M M M M MT ME M M M M M M M M M M	95 100 100 100 100 100 95 100 100 100 100 100 100 100	CAT 6 CAT 6					
13:47 13:50 14:02 14:06 14:16 14:28 14:31 14:37 14:42 14:45 14:49 15:01 15:05 15:11 15:24 15:25 15:38	MAB Z HSLH-OZ	M ME ME ME ME ME ME ME ME ME ME ME ME ME		CCTV CCTV CCTV CCTV CCTV CCTV CCTV CCTV	M K MAG MT ME MAG MT K MT ME MT ME MT MT MT ME MT MT ME MT MT ME MT MT ME MT MT ME MT MT ME MT MT ME MT MT MT ME MT T IE-HST	MT K K ME M M M M M MT ME M M M M M M M M M M	95 100 100 100 100 100 100 100 10	CAT 6 CAT 6					
13:47 13:50 14:02 14:06 14:16 14:28 14:31 14:37 14:42 14:45 14:49 15:01 15:05 15:11 15:24 15:25 15:38 15:40	MAB Z HSLH-OZ	M ME ME ME ME ME ME ME ME ME ME ME ME ME		CCTV CCTV CCTV CCTV CCTV CCTV CCTV CCTV	M K MAG MT ME MAG MT K MT ME MT ME MT MT ME MT MT ME MT ME MT T IE-HST	MT K K ME M M M M M MT ME M M M M M M M M M M	95 100 100 100 100 100 100 100 10	CAT 6 CAT 6					
13:47 13:50 14:02 14:06 14:16 14:28 14:31 14:37 14:42 14:45 14:49 15:01 15:05 15:11 15:24 15:25 15:38	MAB Z HSLH-OZ	M ME ME ME ME ME ME ME ME ME ME ME ME ME		CCTV CCTV CCTV CCTV CCTV CCTV CCTV CCTV	M K MAG MT ME MAG MT K MT ME MT ME MT MT MT ME MT MT ME MT MT ME MT MT ME MT MT ME MT MT ME MT MT ME MT MT MT ME MT T IE-HST	MT K K ME M M M M M MT ME M M M M M M M M M M	95 100 100 100 100 100 100 100 10	CAT 6 CAT 6					
13:47 13:50 14:02 14:06 14:16 14:28 14:31 14:37 14:42 14:45 14:49 15:01 15:05 15:11 15:24 15:25 15:38 15:40	MAB Z HSLH-OZ	M ME ME ME ME ME ME ME ME ME ME ME ME ME		CCTV CCTV CCTV CCTV CCTV CCTV CCTV CCTV	M K MAG MT ME MAG MT K MT ME MT ME MT MT ME MT MT ME MT ME MT T IE-HST	MT K K ME M M M M M MT ME M M M M M M M M M M	95 100 100 100 100 100 100 100 10	CAT 6 CAT 6					
13:47 13:50 14:02 14:06 14:16 14:28 14:31 14:37 14:42 14:45 14:49 15:01 15:05 15:11 15:24 15:25 15:38 15:40 15:47	MAB Z HSLH-OZ	M ME ME ME ME ME ME ME ME ME ME ME ME ME		CCTV CCTV CCTV CCTV CCTV CCTV CCTV CCTV	M K MAG MT ME MAG MT K MT ME MT ME MT M ME MT M ME MT M ME MT M ME MT M M ME MT M M M M		IE-HST IE-HST	MT K K ME M M M M M MT ME M M M M M M M M M M	95 100 100 100 100 100 100 100 10	CAT 6 CAT 6			
13:47 13:50 14:02 14:06 14:16 14:28 14:31 14:37 14:42 14:45 14:49 15:01 15:05 15:11 15:24 15:25 15:38 15:40 15:47 15:52 16:21	MAB Z HSLH-OZ	M ME ME ME ME ME ME ME ME ME ME ME ME ME		CCTV CCTV CCTV CCTV CCTV CCTV CCTV CCTV	M K MAG MT ME MAG MT K MT ME MT M M M M M M M M M M M M M		IE-HST IE-HST	MT K K ME M M M M MT ME M M M M M M M M M M M	95 100 100 100 100 100 100 100 10	CAT 6 CAT 6			
13:47 13:50 14:02 14:06 14:16 14:28 14:31 14:37 14:42 14:45 14:49 15:01 15:05 15:11 15:24 15:25 15:38 15:40 15:47 15:52 16:21 16:34	MAB Z HSLH-OZ	M ME ME ME ME ME ME ME ME ME ME ME ME ME		CCTV CCTV CCTV CCTV CCTV CCTV CCTV CCTV	M K MAG MT ME MAG MT K MT ME MT M M M M M M M M M M M M M M M		IE-HST IE-HST	MT K K ME M M M M MT ME M M M M M M M M M M M	95 100 100 100 100 100 100 100 10	CAT 6 CAT 6			
13:47 13:50 14:02 14:06 14:16 14:28 14:31 14:37 14:42 14:45 14:49 15:01 15:05 15:11 15:24 15:25 15:38 15:40 15:47 15:52 16:21 16:34 16:39	MAB Z HSLH-OZ	M ME ME ME ME ME ME ME ME ME ME ME ME ME		CCTV CCTV CCTV CCTV CCTV CCTV CCTV CCTV	M K MAG MT ME MAG MT K MT ME MT M M M M M M M M M M M M M M M		IE-HST IE-HST	MT K K ME M M M M MT ME M M M M M ME M M M M M	95 100 100 100 100 100 100 100 10	CAT 6 CAT 6			
13:47 13:50 14:02 14:06 14:16 14:28 14:31 14:37 14:42 14:45 14:49 15:01 15:05 15:11 15:24 15:25 15:38 15:40 15:47 15:52 16:21 16:34 16:39 16:40	MAB Z HSLH-OZ	M ME ME ME ME ME ME ME ME ME ME ME ME ME		CCTV CCTV CCTV CCTV CCTV CCTV CCTV CCTV	M K MAG MT ME MAG MT ME MT ME MT M M M M M M M M M M M M		IE-HST IE-HST	MT K K ME M M M M MT ME M M M M M M M M M M M	95 100 100 100 100 100 100 100 10	CAT 6 CAT 6			
13:47 13:50 14:02 14:06 14:16 14:28 14:31 14:37 14:42 14:45 14:49 15:01 15:05 15:11 15:24 15:25 15:38 15:40 15:47 15:52 16:21 16:34 16:39 16:40 16:51	MAB MAB MAB MAB MAB MAB MAB MAB MAB MAB		HSLH-OZ HSLH-OZ	M ME ME ME ME ME ME ME ME ME ME ME ME ME		CCTV CCTV CCTV CCTV CCTV CCTV CCTV CCTV	M K MAG MT ME MAG MT ME MT ME MT M M M M M M M M M M M M		JE-HST JE-HST	MT K K ME M M M M MT ME M M M M M ME M M M M M	95 100 100 100 100 100 100 100 10	CAT 6 CAT 6	
13:47 13:50 14:02 14:06 14:16 14:28 14:31 14:37 14:42 14:45 14:49 15:01 15:05 15:11 15:24 15:25 15:38 15:40 15:47 15:52 16:21 16:34 16:39 16:40	MAB Z HSLH-OZ	M ME ME ME ME ME ME ME ME ME ME ME ME ME		CCTV CCTV CCTV CCTV CCTV CCTV CCTV CCTV	M K MAG MT ME MAG MT ME MT ME MT M M M M M M M M M M M M		IE-HST IE-HST	MT K K ME M M M M MT ME M M M M M M M M M M M	95 100 100 100 100 100 100 100 10	CAT 6 CAT 6			

03/03/2021

	Workers													
Observation Time	Tekin M.			Rușen T.			Ferdi K.			Erdal Ş.				
Time	AC	PR	С	AC	PR	C	AC	PR	С	AC	PR	C		
08:49	M		OemDef 16-2-8A PVC	M		CCTV	M		RG6A++PVC	MAT	90	CAT 6		
08:50	M		OemDef 16-2-8A PVC	M		CCTV	M		RG6A++PVC	MAT	90	CAT 6		
08:54	ME		OemDef 16-2-8A PVC	M		CCTV	MT		RG6A++PVC	ME	100	CAT 6		
08:57	M		OemDef 16-2-8A PVC	K		CCTV	ME		RG6A++PVC	MAT	95	CAT 6		
09:32	M		OemDef 16-2-8A PVC	MT		CCTV	ME		RG6A++PVC	M	100	CAT 6		
09:34	M		OemDef 16-2-8A PVC	M		CCTV	M		RG6A++PVC	M	100	CAT 6		
09:37	MAG		OemDef 16-2-8A PVC	ME		CCTV	M		RG6A++PVC	M	100	CAT 6		
09:40	MT		OemDef 16-2-8A PVC	M		CCTV	MT		RG6A++PVC	M	100	CAT 6		
09:41	M		OemDef 16-2-8A PVC	M		CCTV	M		RG6A++PVC	M	100	CAT 6		
09:44	M		OemDef 16-2-8A PVC	M		CCTV	MAT		RG6A++PVC	M	100	CAT 6		
09:50	ME		OemDef 16-2-8A PVC	ME		CCTV	M		RG6A++PVC	ME	100	CAT 6		
10:23	M		OemDef 16-2-8A PVC	M		CCTV	M		RG6A++PVC	M	100	CAT 6		
10:24	M		OemDef 16-2-8A PVC	M		CCTV	ME		RG6A++PVC	M	100	CAT 6		
10:35	M		OemDef 16-2-8A PVC	ME		CCTV	M		RG6A++PVC	M	100	CAT 6		
10:36	M		OemDef 16-2-8A PVC	ME		CCTV	M		RG6A++PVC	M	100	CAT 6		
10:39	ME		OemDef 16-2-8A PVC	M		CCTV	M		RG6A++PVC	ME	100	CAT 6		
10:47	M		OemDef 16-2-8A PVC	ME		CCTV	M		RG6A++PVC	MS	90	CAT 6		
10:54	MAB		OemDef 16-2-8A PVC	ME		CCTV	M		RG6A++PVC	ME	100	CAT 6		
10:56	MAB		OemDef 16-2-8A PVC	ME		CCTV	M		RG6A++PVC	M	100	CAT 6		
10:57	MAB		OemDef 16-2-8A PVC	M		CCTV	M		RG6A++PVC	ME	100	CAT 6		
11:10	M		OemDef 16-2-8A PVC	M		CCTV	M		RG6A++PVC	MT	90	CAT 6		
11:12	M		OemDef 16-2-8A PVC	M		CCTV	M		RG6A++PVC	ME	100	CAT 6		
11:13	M		OemDef 16-2-8A PVC	M		CCTV	MAG		RG6A++PVC	M	100	CAT 6		
11:19	ME		OemDef 16-2-8A PVC	MT		CCTV	MAG		RG6A++PVC	M	100	CAT 6		
11:21	M		OemDef 16-2-8A PVC	ME		CCTV	MAG		RG6A++PVC	M	100	CAT 6		
11:23	M		OemDef 16-2-8A PVC	ME		CCTV	MAG		RG6A++PVC	M	100	CAT 6		
11:25	M		OemDef 16-2-8A PVC	ME		CCTV	MT		RG6A++PVC	M	100	CAT 6		
11:44	K		OemDef 16-2-8A PVC	ME		CCTV	MT		RG6A++PVC	M	100	CAT 6		
11:49	K		OemDef 16-2-8A PVC	K		CCTV	K		RG6A++PVC	K		CAT 6		
11:56	K		OemDef 16-2-8A PVC	K		CCTV	K		RG6A++PVC	K		CAT 6		

13:20	M	120	CAT 6	ME	CCTV	ME	RG6A++PV	MT	90	CAT 6
13:34	ME	100	CAT 6	ME	CCTV	M	RG6A++PV	ME	100	CAT 6
13:38	K		CAT 6	ME	CCTV	M	RG6A++PV	MT	90	CAT 6
13:45	M	100	CAT 6	ME	CCTV	MAT	RG6A++PV	M	100	CAT 6
13:48	M	100	CAT 6	ME	CCTV	M	RG6A++PV	ME	100	CAT 6
13:49	M	100	CAT 6	ME	CCTV	ME	RG6A++PV	MT	90	CAT 6
14:00	K		CAT 6	ME	CCTV	M	RG6A++PV	M	100	CAT 6
14:10	GMH-1	70	CAT 6	ME	CCTV	M	RG6A++PV	K		CAT 6
14:12	GMH-1	70	CAT 6	ME	CCTV	ME	RG6A++PV	K		CAT 6
14:15	M	120	CAT 6	ME	CCTV	MT	RG6A++PV	K		CAT 6
14:18	ME	100	CAT 6	K	CCTV	MAT	RG6A++PV	K		CAT 6
14:19	ME	100	CAT 6	K	CCTV	M	RG6A++PV	K		CAT 6
14:27	MAT	90	CAT 6	K	CCTV	M	RG6A++PV	MAT		YSLY
14:36	M	120	CAT 6	ME	CCTV	M	RG6A++PV	M		YSLY
14:37	ME	100	CAT 6	ME	CCTV	ME	RG6A++PV	M		YSLY
14:49	MAB		CAT 6	MT	CCTV	MAT	RG6A++PV	M		YSLY
15:13	MAB		CAT 6	M	CCTV	M	RG6A++PV	M		YSLY
15:15	M	120	CAT 6	ME	CCTV	M	RG6A++PV	ME		YSLY
15:27	K			M	CCTV	M	RG6A++PV	K		YSLY
15:34	K			M	CCTV	ME	RG6A++PV	MAG		YSLY
15:37	K			ME	CCTV	M	RG6A++PV	MAG		YSLY
15:42	MAB			M	CCTV	M	RG6A++PV	MAG		YSLY
15:45	MAB			M	CCTV	M	RG6A++PV	MAG		YSLY
15:46	MAB			M	CCTV	M	RG6A++PV	MAT		YSLY
15:49	MAB			ME	CCTV	M	RG6A++PV	M		YSLY
15:50	MAB			M	CCTV	ME	RG6A++PV	M		YSLY
15:53	MAB			M	CCTV	M	RG6A++PV	M		YSLY
16:20	MAB			K	CCTV	M	RG6A++PV	ME		YSLY
16:22	MAB			K	CCTV	M	RG6A++PV	M		YSLY
16:44	MAB			M	CCTV	M	RG6A++PV	ME		YSLY
16:48	MAB			M	CCTV	MT	RG6A++PV	M		YSLY
16:52	MAB			ME	CCTV	M	RG6A++PV	ME		YSLY
16:55	MAB			M	CCTV	ME	RG6A++PV	MT		YSLY

<u>08/03/2021</u>

Observation	Workers													
Time	Tekin M.			Rușen T.				Murat	U.	Necdet G.				
Time	AC	PR	C	AC	PR	C	AC	PR	С	AC	PR	C		
08:31	M		HD 113	İZİNLİ			M		CAT 6	MA				
08:35	ME		HD 113	İZİNLİ			ME		CAT 6	MA				
08:36	MT		HD 113	IZINLI			M		CAT 6	MA				
08:40	MAT		HD 113	IZINLI			MAT		CAT 6	MA				
08:44	M		HD 113	İZİNLİ			M		CAT 6	MA				
08:45	M		HD 113	İZİNLİ			M		CAT 6	MA				
08:55	M		HD 113	İZİNLİ			ME		CAT 6	MA				
08:57	M		HD 113	IZINLI			M		CAT 6	MA				
09:16	ME		HD 113	İZİNLİ			M		CAT 6	MA				
09:30	M		HD 113	İZİNLİ			M		CAT 6	MA				
09:36	ME		HD 113	İZİNLİ			ME		CAT 6	MA				
09:47	M		HD 113	IZINLI			MT		CAT 6	MA				
10:11	M		HD 113	IZINLI			M		CAT 6	MA				
10:27	M		HD 113	İZİNLİ			M		CAT 6	MA				
10:38	ME		HD 113	İZİNLİ			M		CAT 6	MA				
10:39	M		HD 113	İZİNLİ			M		CAT 6	MA				
10:44	M		HD 113	IZINLI			M		CAT 6	MA				
10:48	ME		HD 113	İZİNLİ			M		CAT 6	MA				
10:55	M		HD 113	İZİNLİ			ME		CAT 6	MA				
10:56	M		HD 113	İZİNLİ			M		CAT 6	MA				
11:09	M		HD 113	İZİNLİ			M		CAT 6	MA				
11:13	MAT		HD 113	İZİNLİ			M		CAT 6	MA				
11:18	M		HD 113	İZİNLİ			MAT		CAT 6	MA				
11:20	ME		HD 113	İZİNLİ			M		CAT 6	MA				
11:21	M		HD 113	İZİNLİ			MAG		CAT 6	MA				
11:24	M		HD 113	İZİNLİ			MAG		CAT 6	MA				
11:26	M		HD 113	İZİNLİ			MT		CAT 6	MA				
11:50	ME		HD 113	İZİNLİ			MT		CAT 6	MA				
11:55	M		HD 113	İZİNLİ			M		CAT 6	MA				
11:58	K		HD 113	İZİNLİ			M		CAT 6	MA				
13:32	M		HD 113	İZİNLİ			MAB			MA				
13:42	ME		HD 113	İZİNLİ			MAB			MA				

13:50	M	HD 113	İZİNLİ	MAB	MA	
14:05	M	HD 113	İZİNLİ	MAB	MA	
14:08	M	HD 113	İZİNLİ	MAB	MA	
14:11	ME	HD 113	İZİNLİ	MAB	MA	
14:17	M	HD 113	İZİNLİ	MAB	MA	
14:22	GMH-1	HD 113	İZİNLİ	MAB	MA	
14:23	GMH-1	HD 113	İZİNLİ	MAB	MA	
14:30		HD 113	İZİNLİ	MAB	MA	
14:37	ME	HD 113	İZİNLİ	MAB	MA	
14:39	ME	HD 113	İZİNLİ	MAB	MA	
14:42	MAT	HD 113	İZİNLİ	MAB	MA	
14:46	M	HD 113	İZİNLİ	MAB	MA	
14:47	ME	HD 113	İZİNLİ	MAB	MA	
14:49	MAB	HD 113	İZİNLİ	MAB	MA	
15:07	MAB	HD 113	İZİNLİ	MAB	MA	
15:20	M	HD 113	İZİNLİ	MAB	MA	
15:31	K	HD 113	İZİNLİ	MAB	MA	
15:34	K	HD 113	İZİNLİ	MAB	MA	
15:36	K	HD 113	İZİNLİ	MAB	MA	
15:44	MAB	HD 113	İZİNLİ	MAB	MA	
15:49	MAB	HD 113	İZİNLİ	MAB	MA	
15:51	MAB	HD 113	İZİNLİ	MAB	MA	
15:52	MAB	HD 113	İZİNLİ	MAB	MA	
15:54	MAB	HD 113	İZİNLİ	MAB	MA	
15:58	MAB	HD 113	İZİNLİ	MAB	MA	
16:18	MAB	HD 113	İZİNLİ	MAB	MA	
16:23	MAB	HD 113	İZİNLİ	MAB	MA	
16:46	MAB	HD 113	İZİNLİ	MAB	MA	
16:48	MAB	HD 113	İZİNLİ	MAB	MA	
16:55	MAB	HD 113	İZİNLİ	MAB	MA	
16:56	MAB	HD 113	İZİNLİ	MAB	MA	