TOP GLOVE SDN. BHD

WORK INSTRUCTION Finished Product Testing: Ash Content Test

Purposes/Function/Objective

-To determine % ash content in glove.

Materials/ Chemicals/ Tools/Equipment

- 1) Analytical balance
- 2)Scissor
- 3) Furnaces oven
- 4) Aluminium foil
- 5) Crucible

Specification

Calculation:-Where is:

W1= glove weigh (small pieces
W2= weight of crucible + glove sample before heated.

W3= weight of crucible + glove sample after heated.

(Review step no 5, after switch off the oven, the heat temp. automatically will cool down.)

Form/s:


LA/F18

References:

- nil

(Effective Date: 02/05/2011)

Procedures



Cut glove into small pieces



Weigh sample 5.0g (W1)



Wrap 5.0g sample with aluminum foil and put into the crucible (W3)



Put the crucible into furnace oven with temp setting at 550°C



1)Close oven cover and wait until temperature drop to 200°C.
2)After temp.is at 200 oven and wait another 4 or 5 hour

before take out the sample

6

Take out the sample after 4 or 5 hour and weigh the sample again (W3)



Calculation:
% of Ash Content =
W1 - [W2-W3] x 100
W1

Prepared by:	Verified by:	Approved by:
Noor Azura Binti Azman	Al-Fadilah Mohamad	Noor Akilah Saidin
QA/MQC Asst Supervisor	QA Executive II	QA Deputy General Manager