

Join/Commission Device

The Secure Liberty 101 device does not have initial Auto-Join functionality, the 'HAN' join needs to be initiated by a manual button press as detailed below;



- Press **0** on the Keypad to bring up the 'Start Commissioning' display and press button **A**.
- The display will show 'Switch Test', press button **B** (no 2A aux switch on this meter type).
- The 'Joining HAN' display will appear with a flashing HAN signal indicator, if HAN joins the display will show 'Comm Status – Complete' and HAN icon will remain solid.
- If HAN has not Joined the following 'No WAN-Auto Join' display will appear and requires button **B** press.
- The 'Comm Status Fail' screen will show then default back to meter display. Re-attempt the HAN Join process by Pressing **0**.



Join/Commission – Appendix

Note* If YES is selected via button A on the 'No WAN-Auto Join' display during the commissioning process, the device will attempt to Join for approx. 45secs and if un-successful the 'Start Commissioning' manual join option via pressing '0' will no longer be evident on the meter display.

In order to retrieve this function, the following actions need applied;

- The Meter terminal cover needs to be backed off before pressing button **A** to bring up the 'Select Mode' Menu.
- Press **1** on the Keypad for 'Vend Mode' and the 'Enter Token' display will appear.
- The following digits need to be input **00000-20** followed by pressing button **B**.
- Press **2** to select 'Leave HAN' which will show 'In Progress' before returning to the default Meter display screen.
- Re-instate the terminal cover securely and Press **0** to confirm the 'Start Commissioning' display is present.

The Above actions must only be carried out in the event the 'No WAN Auto Join' YES has been selected against SP instruction and followed in-line with Company Procedures

