



BIRDS Satellite battery Pack Development

Ву

Hari

Initial Version 1.0

Materials:

- 1. NiMH Batteries set
- 2. Battery Heater
- 3. Temperature sensor
- 4. Crimp
- 5. 4 pin Connector
- 6. 10 pin Connector
- 7. Kapton tape
- 8. Shrinkable tube
- 9. Soldering station
- 10. Multimeter
- 11. Cable
- 12. Crimper
- 13. Space grade cable
- 14. Battery box
- 15. Wire stripper




SPH-002T-P0.5



GAG10K3976B1

Thermistor NTC



PSAなしタイプ	PSAありタイプ	幅	長さ	ワット密度の総ワット数		
製品型番	製品型番	インチ (cm)	インチ (cm)	2.5 W/インチ ²	5 W/インチ ²	10 W/インチ ²
KHLVA-0502/(*)	KHLVA-0502/(*)-P	0.5 (1)	2 (5)	_	5	10
KHLVA-0504/(*)	KHLVA-0504/(*)-P	0.5 (1)	4 (10)	5	10	20
KHLVA-101/(*)	KHLVA-101/(*)-P	1 (3)	1 (3)	_	5	10
KHLVA-102/(*)	KHLVA-102/(*)-P	1 (3)	2 (5)	5	10	20
KHLVA-103/(*)	KHLVA-103/(*)-P	1 (3)	3 (8)	7.5	15	30
KHLVA-104/(*)	KHLVA-104/(*)-P	1 (3)	4 (10)	10	20	40
KHLVA-105/(*)	KHLVA-105/(*)-P	1 (3)	5 (13)	12.5	25	50
KHLVA-202/(*)	KHLVA-202/(*)-P	2 (5)	2 (5)	10	20	40
KHLVA-203/(*)	KHLVA-203/(*)-P	2 (5)	3 (8)	15	30	60
KHLVA-204/(*)	KHLVA-204/(*)-P	2 (5)	4 (10)	20	40	80
KHLVA-205/(*)	KHLVA-205/(*)-P	2 (5)	5 (13)	25	50	100
KHLVA-303/(*)	KHLVA-303/(*)-P	3 (8)	3 (8)	22.5	45	90

https://www.jp.omega.com/heaters/pdf/KHRA-KHLVA-KHA-SERIES.pdf




PHR-4



Test: Before using it, please confirm.



Use kapton tape both terminal of Thermistor




Before to put heater check the of heater


Heater test

Sensor test

Step1: Wrap Kapton tape all around entire battery box.




Inside



Outside BIRDS battery box



Kapton tape




Step:2 Used the Teflon for heat dissipation and insulation purpose


Step 4: Place the heater on the surface of the battery box and stable it with kapton tape.



Step 3: Replace space grade cable



Step 5: Place the batteries Set A and Set B inside the box





Step 6: Connect and solder the space grade cable to the thermistor, which is placed in the middle of the batteries.

Step 7: Make sure the battery to EPS board (hot side) harness is 15 cm long.

Example: one cable length is 2.5 cm

Step 8: Crimp and connect cables with Connectors





points

And

Battery terminal connection

10 pin connector: 1 to 4 pins for (-) terminal 7 to 10 pins for +terminal Please follow the schematic diagram

