Heat Exchanger E-201 Tube Bundle Inspection Report

Report ID: IR-E201-2026-08-20

Inspection date: 2026-08-20

Unit: R-100

Inspection scope: Tube bundle and shell inlet nozzle

Tube wall thickness

Rows 12–15 measured 3.8–4.2 mm; minimum allowable tube wall thickness: 4.6 mm.

Corrosion findings

Localised pitting corrosion at the shell inlet nozzle; maximum pitting depth: 1.8 mm.

Heat Exchanger E-201 Tube Bundle Inspection Report

Channel-head inspection

Channel-head gasket shows degradation; replacement recommended before return to service.

No approval status is stated in this report.

Inspection record

Report reference: IR-E201-2026-08-20

Inspection date: 2026-08-20