NORTH ZONE REFINERY - INSPECTION REPORT

Report ID: IR-E201-2026-08-20

Equipment: E-201 Heat Exchanger

Inspection findings

Tube wall thickness: Rows 12-15 measured 3.8-4.2 mm.

Minimum allowable tube wall thickness: 4.6 mm.

Localised pitting corrosion at the shell inlet nozzle; maximum depth 1.8 mm.

The report does not state an approval status.

RECHECK WELD JOINT 4B

- field inspector

Channel-head gasket degradation. Replacement recommended before return to service.

Inspector annotation is retained as source evidence.