02/17/26 6050478/1

03/10/26 Final

118445 118455

Sarah Weed/Toy*W*

KALISPELL TOYOTA
2845 HWY 93 SOUTH
CONTACT TATUM AT HYUNDAI
KALISPELL, MT 59901 406-755-6060

KM8R7DHE2NU379380

02/18/26

2022 HYUNDAI PALISADE OTHER

Email: tatum.mccluskey@kaltoy.com

#1 - DIAG: DIAGNOSE CUSTOMER CONCERN AND DOCUMENT SOURCE OF CAUSE WITH ESTIMATE OF NEEDED PARTS AND LABOR FOR REPAIR

OTHER DIAGNOSIS - C/S: VEHICLE TOWED OVER FROM KAL ISPELL TOYOTA. POINT OF CONTACT ROBBIE AUS 715.550 .0550. CUSTOMER STATES NO START ON VEHICLE. CHECKE D FUSES, FUSES WERE FINE. TRIED CAPTIVE RESET, DID NOT WORK. CHECK AND ADVISE.

Caused by

Cylinder #4 Ignition Coil internally shorted

Tech: JOSEPH CLINCH (JEC) 588.39

Installed 27310-3L030 :COIL-IGNITION 1@142.56 142.56

Verified vehicles engine cranks and does not start. Scanned all systems retrieving the following codes in history state; ABSESC: C160648, C110213, Airbag: B111600, OCS: B111216. Found fuel alcohol content reading 5%. Fuel hydrometer (specific gravity reading at 60F is 0.710 light (vapor lock). Scanned all systems again and found no communication with IBU-IMMO. Opened HTSS case #2026021802038. Call and viewed with TL. TL Advised to "check for spark, if ignition system is operating normally, drain the fuel and replace with fuel from a top tier known good source, and retest". Checked and found no

02/17/26 6050478/2

03/10/26 Final

118445 118455

Sarah Weed/Toy*W*

KALISPELL TOYOTA
2845 HWY 93 SOUTH
CONTACT TATUM AT HYUNDAI
KALISPELL, MT 59901 406-755-6060

KM8R7DHE2NU379380

02/18/26

2022 HYUNDAI PALISADE OTHER

spark from IG coils 2, 4, 6. Found PCB block
sensor 4 15A fuse open. Found cyl. #4 IG coil
internally shorted. Installed new cyl.#4 Ig coil
and 15A sensor 4 fuse. Cleared codes. Performed
engine adaptive value reset. Tested and confirmed
proper operation. Repair Complete.
Sub Total: 730.95

#2 - RECALL: COMPLETE FACTORY CAMPAIGN/RECALL TO SPEC
C/S: TBW -SW UD AUDIO 2.0/AVN 5TH GEN 24-01-045H-2
Caused by
A software update is available for multiple
vehicles equipped with either Display Audio 2.0V
or the AVN 5th Gen Wide system.
Tech: JOSEPH CLINCH (JEC) Warranty
Performed Software Verification and found the
software version reading
LX2.USA.S5W_M.V011.006.240313 already up to date.
NO software update is required. SCTBW Complete.
Op. Code: 40D059I1 - Op. Time: 0.2M/H

#4 - RECALL: COMPLETE FACTORY CAMPAIGN/RECALL TO SPEC
C/S: 9C9 -ECU SW UPDATE EMISSIONS IMPRV 26-01-010H
Caused by
Certain Palisade (LX2) vehicles equipped with
3.8L GDI Lambda II engines may not meet
engine-out NOx (Nitrogen Oxides) and Particulate

02/17/26 6050478/3

03/10/26 Final

118445 118455

Sarah Weed/Toy*W*

KALISPELL TOYOTA
2845 HWY 93 SOUTH
CONTACT TATUM AT HYUNDAI
KALISPELL, MT 59901 406-755-6060

KM8R7DHE2NU379380

02/18/26

2022 HYUNDAI PALISADE OTHER

Matter (PM) emission standards.
Tech: JOSEPH CLINCH (JEC) Warranty
Performed Engine ECU software event #1332 LX2 ECU UPGRADE Lambda II 3.8 EMISSION LOGIC IMPROVEMENT. Performed required STUI documentation. Performed an All-Systems Fault Code search and erased DTC history that had incidentally occurred from the ECU update. Started engine and confirmed proper operation of the vehicle. Performed Emissions Label Application. Performed required STUI documentation. SC9C9 Complete. Op. Code: 50D289R0 - Op. Time: 0.4M/H

#5 - WASH: FREE EXTERIOR HAND WASH AND RINSE WITH ANY SERVICE
FREE EXTERIOR WASH AND RINSE WITH ANY SERVICE
Tech: House Wash Person (999)
Sub Total: .00

#6 - MPI-MAINT: MULTI POINT INSPECTION-DEALER MAINTENANCE
SCHEDULED MAINTENANCE
Tech: JOSEPH CLINCH (JEC)
Sub Total: .00

Purchase Order:25T1192B

02/17/26 6050478/4

03/10/26 Final

118445 118455

Sarah Weed/Toy*W*

KALISPELL TOYOTA
2845 HWY 93 SOUTH
CONTACT TATUM AT HYUNDAI
KALISPELL, MT 59901 406-755-6060

KM8R7DHE2NU379380

02/18/26

2022 HYUNDAI PALISADE OTHER

Please Note: #TOY CREATED 2026-02-17 05:24:00PM TAKEN BY SARAH WEED

```
*************************************************************
* OIL CHANGE UP TO 5 QTS SYNTHETIC OIL AND TIRE     ROTATE *
* IF NEEDED WITH FULL MULTIPOINT INSPECTION  $89.99!!!     *
* STARTING 7/1/24 EXCLUDES CERTAIN MODELSAND DIESELS       *
*************************************************************
```

	588.39
	142.56
	.00
	.00
	.00
	.00
	.00
	.00
	.00
	730.95
A/R:KALI005 KALISPELL TOYOTA	730.95

|6050478i~

02/17/26 6050478/1

03/10/26 Final

118445 118455

Sarah Weed/Toy*W*

KALISPELL TOYOTA
2845 HWY 93 SOUTH
CONTACT TATUM AT HYUNDAI
KALISPELL, MT 59901 406-755-6060

KM8R7DHE2NU379380

02/18/26

2022 HYUNDAI PALISADE OTHER

Email: tatum.mccluskey@kaltoy.com

#1 - DIAG: DIAGNOSE CUSTOMER CONCERN AND DOCUMENT SOURCE OF CAUSE WITH ESTIMATE OF NEEDED PARTS AND LABOR FOR REPAIR

OTHER DIAGNOSIS - C/S: VEHICLE TOWED OVER FROM KAL ISPELL TOYOTA. POINT OF CONTACT ROBBIE AUS 715.550 .0550. CUSTOMER STATES NO START ON VEHICLE. CHECKE D FUSES, FUSES WERE FINE. TRIED CAPTIVE RESET, DID NOT WORK. CHECK AND ADVISE.

Caused by

Cylinder #4 Ignition Coil internally shorted

Tech: JOSEPH CLINCH (JEC) 588.39

Installed 27310-3L030 :COIL-IGNITION 1@142.56 142.56

Verified vehicles engine cranks and does not start. Scanned all systems retrieving the following codes in history state; ABSESC: C160648, C110213, Airbag: B111600, OCS: B111216. Found fuel alcohol content reading 5%. Fuel hydrometer (specific gravity reading at 60F is 0.710 light (vapor lock). Scanned all systems again and found no communication with IBU-IMMO. Opened HTSS case #2026021802038. Call and viewed with TL. TL Advised to "check for spark, if ignition system is operating normally, drain the fuel and replace with fuel from a top tier known good source, and retest". Checked and found no

02/17/26 6050478/2

03/10/26 Final

118445 118455

Sarah Weed/Toy*W*

KALISPELL TOYOTA
2845 HWY 93 SOUTH
CONTACT TATUM AT HYUNDAI
KALISPELL, MT 59901 406-755-6060

KM8R7DHE2NU379380

02/18/26

2022 HYUNDAI PALISADE OTHER

spark from IG coils 2, 4, 6. Found PCB block
sensor 4 15A fuse open. Found cyl. #4 IG coil
internally shorted. Installed new cyl.#4 Ig coil
and 15A sensor 4 fuse. Cleared codes. Performed
engine adaptive value reset. Tested and confirmed
proper operation. Repair Complete.
Sub Total: 730.95

#2 - RECALL: COMPLETE FACTORY CAMPAIGN/RECALL TO SPEC
C/S: TBW -SW UD AUDIO 2.0/AVN 5TH GEN 24-01-045H-2
Caused by
A software update is available for multiple
vehicles equipped with either Display Audio 2.0V
or the AVN 5th Gen Wide system.
Tech: JOSEPH CLINCH (JEC) Warranty
Performed Software Verification and found the
software version reading
LX2.USA.S5W_M.V011.006.240313 already up to date.
NO software update is required. SCTBW Complete.
Op. Code: 40D059I1 - Op. Time: 0.2M/H

#4 - RECALL: COMPLETE FACTORY CAMPAIGN/RECALL TO SPEC
C/S: 9C9 -ECU SW UPDATE EMISSIONS IMPRV 26-01-010H
Caused by
Certain Palisade (LX2) vehicles equipped with
3.8L GDI Lambda II engines may not meet
engine-out NOx (Nitrogen Oxides) and Particulate

02/17/26 6050478/3

03/10/26 Final

118445 118455

Sarah Weed/Toy*W*

KALISPELL TOYOTA
2845 HWY 93 SOUTH
CONTACT TATUM AT HYUNDAI
KALISPELL, MT 59901 406-755-6060

KM8R7DHE2NU379380

02/18/26

2022 HYUNDAI PALISADE OTHER

Matter (PM) emission standards.
Tech: JOSEPH CLINCH (JEC) Warranty
Performed Engine ECU software event #1332 LX2 ECU UPGRADE Lambda II 3.8 EMISSION LOGIC IMPROVEMENT. Performed required STUI documentation. Performed an All-Systems Fault Code search and erased DTC history that had incidentally occurred from the ECU update. Started engine and confirmed proper operation of the vehicle. Performed Emissions Label Application. Performed required STUI documentation. SC9C9 Complete. Op. Code: 50D289R0 - Op. Time: 0.4M/H

#5 - WASH: FREE EXTERIOR HAND WASH AND RINSE WITH ANY SERVICE
FREE EXTERIOR WASH AND RINSE WITH ANY SERVICE
Tech: House Wash Person (999)
Sub Total: .00

#6 - MPI-MAINT: MULTI POINT INSPECTION-DEALER MAINTENANCE
SCHEDULED MAINTENANCE
Tech: JOSEPH CLINCH (JEC)
Sub Total: .00

Purchase Order:25T1192B

02/17/26 6050478/4

03/10/26 Final

118445 118455

Sarah Weed/Toy*W*

KALISPELL TOYOTA
2845 HWY 93 SOUTH
CONTACT TATUM AT HYUNDAI
KALISPELL, MT 59901 406-755-6060

KM8R7DHE2NU379380

02/18/26

2022 HYUNDAI PALISADE OTHER

Please Note: #TOY CREATED 2026-02-17 05:24:00PM TAKEN BY SARAH WEED

```
*************************************************************
* OIL CHANGE UP TO 5 QTS SYNTHETIC OIL AND TIRE     ROTATE *
* IF NEEDED WITH FULL MULTIPOINT INSPECTION  $89.99!!!     *
* STARTING 7/1/24 EXCLUDES CERTAIN MODELSAND DIESELS       *
*************************************************************
```

	588.39
	142.56
	.00
	.00
	.00
	.00
	.00
	.00
	.00
	730.95
A/R:KALI005 KALISPELL TOYOTA	730.95

|6050478i~

KALISPELL TOYOTA
2845 HWY 93 SOUTH
CONTACT TATUM AT HYUNDAI
KALISPELL, MT 59901 59901

406-755-6060

02/17/26 6050478/1
03/10/26 Original
118445 118455

2022 HYUNDAI PALISADE Sarah Weed 1331

KM8R7DHE2NU379380 OTHER 02/18/26

Email: tatum.mccluskey@kaltoy.com

#1 - MR DIAG: DIAGNOSE CUSTOMER CONCERN AND DOCUMENT SOURCE OF CAUSE WITH ESTIMATE OF NEEDED PARTS AND LABOR FOR REPAIR C

OTHER DIAGNOSIS - C/S: VEHICLE TOWED OVER FROM KAL ISPELL TOYOTA. POINT OF CONTACT ROBBIE AUS 715.550 .0550. CUSTOMER STATES NO START ON VEHICLE. CHECKE D FUSES, FUSES WERE FINE. TRIED CAPTIVE RESET, DID NOT WORK. CHECK AND ADVISE.

Caused by

Cylinder #4 Ignition Coil internally shorted

Work by Tech JEC/CLIN	3.00hrs @ 196.13	588.39	90.00
27310-3L030 : COIL-IGNITION	1@142.56	142.56	85.88

Verified vehicles engine cranks and does not start. Scanned all systems retrieving the following codes in history state; ABSESC: C160648, C110213, Airbag: B111600, OCS: B111216. Found fuel alcohol content reading 5%. Fuel hydrometer (specific gravity reading at 60F is 0.710 light (vapor lock). Scanned all systems again and found no communication with IBU-IMMO. Opened HTSS case #2026021802038. Call and viewed with TL. TL Advised to "check for spark, if ignition system is operating normally, drain the fuel and replace with fuel from a top tier known good source, and retest". Checked and found no spark from IG coils 2, 4, 6. Found PCB block sensor 4 15A fuse open. Found cyl. #4 IG coil internally shorted. Installed new cyl.#4 Ig coil and 15A sensor 4 fuse. Cleared codes. Performed engine adaptive value reset. Tested and confirmed proper operation. Repair Complete.

#5 - MR WASH: FREE EXTERIOR HAND WASH AND RINSE WITH ANY SERVICE C

FREE EXTERIOR WASH AND RINSE WITH ANY SERVICE

KALISPELL TOYOTA
2845 HWY 93 SOUTH
CONTACT TATUM AT HYUNDAI
KALISPELL, MT 59901 59901

406-755-6060

02/17/26 6050478/2
03/10/26 Original
118445 118455

2022 HYUNDAI PALISADE Sarah Weed 1331

KM8R7DHE2NU379380 OTHER 02/18/26

Work by Tech 999/999 0.00hrs @

#6 - MR MPI-MAINT: MULTI POINT INSPECTION-DEALER MAINTENANCE C
SCHEDULED MAINTENANCE
Work by Tech JEC/CLIN 0.00hrs @

Purchase Order: 25T1192B

Account	Description	Control	Reference	Amount
4500	SVC CUST MECH LBR HYUNDAI	6050478	6050478	-588.39
2470	WORK IN PROCESS	JCLIN	6050478	-90.00
6500	C/S SVC CUST MECH LBR HYUN VEH	6050478	6050478	90.00
4600	P&A RO HYUNDAI VEHICLES	6050478	6050478	-142.56
6600	C/S P&A RO HYUNDAI VEHICLES	6050478	6050478	85.88
2420	INVENTORY P&A HYUNDAI	6050478	6050478	-85.88
2200	RECEIVABLES SVC/PART/BODY	KALI005	6050478	730.95

588.39 90.00
142.56 85.88

730.95 175.88

A/R:KALI005 KALISPELL TOYOTA

KALISPELL TOYOTA
2845 HWY 93 SOUTH
CONTACT TATUM AT HYUNDAI
KALISPELL, MT 59901 59901

406-755-6060

02/17/26 6050478/1
03/10/26 Original
118445 118455

2022 HYUNDAI PALISADE Sarah Weed 1331

KM8R7DHE2NU379380 OTHER 02/18/26

Email: tatum.mccluskey@kaltoy.com

#1 - MR DIAG: DIAGNOSE CUSTOMER CONCERN AND DOCUMENT SOURCE OF CAUSE WITH ESTIMATE OF NEEDED PARTS AND LABOR FOR REPAIR C

OTHER DIAGNOSIS - C/S: VEHICLE TOWED OVER FROM KAL
ISPELL TOYOTA. POINT OF CONTACT ROBBIE AUS 715.550
.0550. CUSTOMER STATES NO START ON VEHICLE. CHECKE
D FUSES, FUSES WERE FINE. TRIED CAPTIVE RESET, DID
NOT WORK. CHECK AND ADVISE.
Caused by
Cylinder #4 Ignition Coil internally shorted

Work by Tech JEC/CLIN	3.00hrs @ 196.13	588.39	90.00
27310-3L030 : COIL-IGNITION	1@142.56	142.56	85.88

Verified vehicles engine cranks and does not start. Scanned all systems retrieving the following codes in history state; ABSESC: C160648, C110213, Airbag: B111600, OCS: B111216. Found fuel alcohol content reading 5%. Fuel hydrometer (specific gravity reading at 60F is 0.710 light (vapor lock). Scanned all systems again and found no communication with IBU-IMMO. Opened HTSS case #2026021802038. Call and viewed with TL. TL Advised to "check for spark, if ignition system is operating normally, drain the fuel and replace with fuel from a top tier known good source, and retest". Checked and found no spark from IG coils 2, 4, 6. Found PCB block sensor 4 15A fuse open. Found cyl. #4 IG coil internally shorted. Installed new cyl.#4 Ig coil and 15A sensor 4 fuse. Cleared codes. Performed engine adaptive value reset. Tested and confirmed proper operation. Repair Complete.

#2 - MR RECALL: COMPLETE FACTORY CAMPAIGN/RECALL TO SPEC W

C/S: TBW -SW UD AUDIO 2.0/AVN 5TH GEN 24-01-045H-2
Caused by

		02/17/26	6050478/2
KALISPELL TOYOTA 2845 HWY 93 SOUTH CONTACT TATUM AT HYUNDAI KALISPELL, MT 59901 59901	406-755-6060	03/10/26 118445	Original 118455

2022 HYUNDAI PALISADE Sarah Weed 1331

KM8R7DHE2NU379380 OTHER 02/18/26

A software update is available for multiple vehicles equipped with either Display Audio 2.0V or the AVN 5th Gen Wide system.

Work by Tech JEC/CLIN 0.20hrs @ 158.84 31.77 6.00

Performed Software Verification and found the software version reading LX2.USA.S5W_M.V011.006.240313 already up to date. NO software update is required. SCTBW Complete. Op. Code: 40D059I1 - Op. Time: 0.2M/H

#4 - MR RECALL: COMPLETE FACTORY CAMPAIGN/RECALL TO SPEC W

C/S: 9C9 -ECU SW UPDATE EMISSIONS IMPRV 26-01-010H

Caused by

Certain Palisade (LX2) vehicles equipped with 3.8L GDI Lambda II engines may not meet engine-out NOx (Nitrogen Oxides) and Particulate Matter (PM) emission standards.

Work by Tech JEC/CLIN 0.40hrs @ 158.84 63.54 12.00

Performed Engine ECU software event #1332 LX2 ECU UPGRADE Lambda II 3.8 EMISSION LOGIC IMPROVEMENT. Performed required STUI documentation. Performed an All-Systems Fault Code search and erased DTC history that had incidentally occurred from the ECU update. Started engine and confirmed proper operation of the vehicle. Performed Emissions Label Application. Performed required STUI documentation. SC9C9 Complete. Op. Code: 50D289R0 - Op. Time: 0.4M/H

#5 - MR WASH: FREE EXTERIOR HAND WASH AND RINSE WITH ANY SERVICE C

FREE EXTERIOR WASH AND RINSE WITH ANY SERVICE

Work by Tech 999/999 0.00hrs @

#6 - MR MPI-MAINT: MULTI POINT INSPECTION-DEALER MAINTENANCE C

SCHEDULED MAINTENANCE

KALISPELL TOYOTA
2845 HWY 93 SOUTH
CONTACT TATUM AT HYUNDAI
KALISPELL, MT 59901 59901

406-755-6060

02/17/26 6050478/3
03/10/26 Original
118445 118455

2022 HYUNDAI PALISADE

Sarah Weed 1331

KM8R7DHE2NU379380 OTHER

02/18/26

Work by Tech JEC/CLIN 0.00hrs @

Purchase Order: 25T1192B

Account	Description	Control	Reference	Amount
4500	SVC CUST MECH LBR HYUNDAI	6050478	6050478	-588.39
2470	WORK IN PROCESS	JCLIN	6050478	-90.00
6500	C/S SVC CUST MECH LBR HYUN VEH	6050478	6050478	90.00
4600	P&A RO HYUNDAI VEHICLES	6050478	6050478	-142.56
6600	C/S P&A RO HYUNDAI VEHICLES	6050478	6050478	85.88
2420	INVENTORY P&A HYUNDAI	6050478	6050478	-85.88
2200	RECEIVABLES SVC/PART/BODY	KALI005	6050478	730.95
4540	SVC WARR CLAIM MECH LABOR	6050478	6050478	-95.31
2470	WORK IN PROCESS	JCLIN	6050478	-18.00
6540	C/S SVC WARR CLAIM MECH LABOR	6050478	6050478	18.00
2220	WARRANTY REC HYUNDAI	6050478	6050478	95.31

95.31 588.39 108.00
142.56 85.88

95.31 730.95 193.88

A/R:KALI005 KALISPELL TOYOTA

WARRANTY REPAIR ORDER

KALISPELL TOYOTA
2845 HWY 93 SOUTH
CONTACT TATUM AT HYUNDAI
KALISPELL, MT 59901

Work Phone	R/O Open Date	R/O Number
	02/17/26	6050478/1
Home Phone	**R/O Close Date**	**Cross Reference #**
406-755-6060		
Body	**Mileage In**	**Mileage Out**
	118445	118455

Year	Make	Model	License Number	Service Advisor
2022	HYUNDAI	PALISADE		Sarah Weed

Vehicle Identification Number	Color		Delivery Date	In-Service Date
KM8R7DHE2NU379380	OTHER			02/18/26

DESCRIPTION OF SERVICE AND PARTS	COST	AMOUNT
Email: tatum.mccluskey@kaltoy.com		
#2 - RECALL: COMPLETE FACTORY CAMPAIGN/RECALL TO SPEC C/S: TBW -SW UD AUDIO 2.0/AVN 5TH GEN 24-01-045H-2 Cause: A software update is available for multiple vehicles equipped with either Display Audio 2.0V or the AVN 5th Gen Wide system. Tech: JEC/ 0.20hrs @ 158.8	6.00	31.77
Performed Software Verification and found the software version reading LX2.USA.S5W_M.V011.006.240313 already up to date. NO software update is required. SCTBW Complete. Op. Code: 40D059I1 - Op. Time: 0.2M/H Sub-Total Labor: 6.00 31.77		
#4 - RECALL: COMPLETE FACTORY CAMPAIGN/RECALL TO SPEC C/S: 9C9 -ECU SW UPDATE EMISSIONS IMPRV 26-01-010H Cause: Certain Palisade (LX2) vehicles equipped with 3.8L GDI Lambda II engines may not meet engine-out NOx (Nitrogen Oxides) and Particulate Matter (PM) emission standards. Tech: JEC/ 0.40hrs @ 158.8	12.00	63.54
Performed Engine ECU software event #1332 LX2 ECU UPGRADE Lambda II 3.8 EMISSION LOGIC IMPROVEMENT. Performed required STUI documentation. Performed an All-Systems Fault Code search and erased DTC history that had incidentally occurred from the ECU update. Started engine and confirmed proper operation of the vehicle. Performed Emissions Label Application. Performed required STUI documentation. SC9C9 Complete. Op. Code: 50D289R0 - Op. Time: 0.4M/H Sub-Total Labor: 12.00 63.54		

ACCOUNT #			
	LABOR	18.00	95.31
	PARTS		.00
METHOD	SUBLET		.00
	SHOP SUPPLIES		.00
	SALES TAX OR TAX I.D.		.00
RECEIPT #	DEDUCTIBLE		.00
	TOTAL DUE	18.00	95.31

SIGNATURE X

KALISPELL TOYOTA
2845 HWY 93 SOUTH
CONTACT TATUM AT HYUNDAI
KALISPELL MT 59901

Home Phone	R/O Open Date	R/O Number
406-755-6060	2/17/26	6050478
Work Phone	**Time Received**	**Time Promised**
	18:25	2/18 19:00
Key Tag #	**Current Mileage**	**Mileage Out**
Toy	118445	

Year	Make	Model	Body	Engine Code	Service Advisor
2022	HYUNDAI	PALISADE			Sarah Weed
Vehicle Identification Number		**Color**	**License Number**	**Delivery Date**	**In-Service Date**
KM8R7DHE2NU379380		OTHER			2/18/26

Email:

#1 - DIAG: DIAGNOSE CUSTOMER CONCERN AND DOCUMENT SOURCE OF CAUSE WITH ESTIMATE OF NEEDED PARTS AND LABOR FOR REPAIR C C
OTHER DIAGNOSIS - C/S: VEHICLE TOWED OVER FROM KAL C
ISPELL TOYOTA. POINT OF CONTACT ROBBIE AUS 715.550 C
.0550. CUSTOMER STATES NO START ON VEHICLE. CHECKE C
D FUSES, FUSES WERE FINE. TRIED CAPTIVE RESET, DID C
NOT WORK. CHECK AND ADVISE. C

HTSS# 20260218020038

#2 - RECALL: COMPLETE FACTORY CAMPAIGN/RECALL TO SPEC W
C/S: TBW -SW UD AUDIO 2.0/AVN 5TH GEN 24-01-045H-2 W

#3 - RECALL: COMPLETE FACTORY CAMPAIGN/RECALL TO SPEC W
C/S: 283 -1ST/2ND ROW SEAT BELT BUCKLE(25-01-085H) W

#4 - RECALL: COMPLETE FACTORY CAMPAIGN/RECALL TO SPEC W
C/S: 9C9 -ECU SW UPDATE EMISSIONS IMPRV 26-01-010H W

WRO

#5 - WASH: FREE EXTERIOR HAND WASH AND RINSE WITH ANY SERVICE C
FREE EXTERIOR WASH AND RINSE WITH ANY SERVICE C

#6 - MPI-MAINT: MULTI POINT INSPECTION-DEALER MAINTENANCE C
SCHEDULED MAINTENANCE C
#TOY CREATED 2026-02-17 05:24:00PM TAKEN BY SARAH
WEED

"I hereby authorize the repair work above to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in the vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto."

Any warranties on products sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties, express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it liability in connection with the sale of said products. Any Limitation contained herein does not apply where prohibited by law.

(C) 2010 DEALERTRACK SYSTEMS, Inc. - Dealership Application Group (800)945-1028

Customer Signature

STRAIGHT TIME (HOURS)	FLAT RATE	R/O NO.	TIME	OFF 2
# 1		OPER. NO. EMP. NO. C124		ON

STRAIGHT TIME (HOURS)	FLAT RATE	R/O NO.	TIME	OFF 4
# 1	Diag	OPER. NO. EMP. NO. C124	3.0	ON

STRAIGHT TIME (HOURS)	FLAT RATE	R/O NO.	TIME	OFF 6
# 1	repair	OPER. NO. EMP. NO. C124	1.0	ON

IG Coil and 15A Fuse Sensor 4 Install Complete
Totall Labor 4.0hrs

STRAIGHT TIME (HOURS)	FLAT RATE	R/O NO.	TIME	OFF 7
# 4		OPER. NO. EMP. NO. C124	.4	ON

SC 9C9 Complete - Op Code: 50D289R0 - Op Time: 0.4 m/H

STRAIGHT TIME (HOURS)	FLAT RATE	R/O NO.	TIME	OFF 10
# 2		OPER. NO. EMP. NO. C124	.2	ON

SC TBW Complete - Op Code: 40D059I1 - Op Time: 0.2 m/H

HYUNDAI MOTOR AMERICA

Vehicle Infomation

Basic Vehicle Information

VIN	KM8R7DHE2NU379380	**Model**	PALISADE (LX2) 3.8L 2022 Automatic
Warranty Start Date	10/30/2021 (4 years, 4 months, 12 d ays)	**Extra Warranty**	// TWISTED SEAT BELT REPLACEMENT 25 -BE-006H // SEAT BELT BUCKLE INSP/R EP (25-BE-010H) // SELF-LVLNG RR SH OCK ABSORBER 25-SS-004H
Original Owner	OROZCO, LEIGH J	**DMV Transfer Date**	
Current Owner	OROZCO, LEIGH J	**Selling Dealer**	MS038 BARNES CROSSING HYUNDAI
Date Wholesale	10/25/2021	**Date Retailed**	10/30/2021
Wholesale Dealer	MS038 BARNES CROSSING HYUNDAI	**Retailed Dealer**	MS038 BARNES CROSSING HYUNDAI
Retail Flag	Y	**Production Date**	09/03/2021
Emission Type	50-STATE	**Allocation Date**	09/09/2021
IQS / CSI / VDS / others		**Branded / Warranty Info**	
Customer Loyalty	2 Hyundai vehicle(s)	**Service Interval**	Normal
Dealer Case Management	No Open Cases	**Fleet Type**	RETAIL

Detail Vehicle Information

Specifications

Year	2022	**Short Model**	J1472A65
Accessory Code	01	**Engine Number**	G6DNMS353298
Interior Color	NBX - BLACK	**Exterior Color**	R2F - RAINFOREST

Factory Installed Accessories

CODE	DESCRIPTION
No Data	

Port Installed Accessories

CODE	DESCRIPTION
C1	*Cargo Package
CF	*Carpeted Floor Mats
CV	*Cargo Cover
FK	*First Aid Kit
RP	*Rear Bumper Appliqué
WL	*Wheel Locks

Campaign Not Performed (3 Found)

Campaign Code	Recall	Campaign Description	Campaign Start Date	Vin Activation Date	Campaign Bulletins
9C9		ECU SW UPDATE EMISSIONS IMPRV 26-01-01 0H	02/02/2026	02/02/2026	
292	Y	REMEDY NOT YET AVAILABLE	01/23/2026	01/23/2026	
283	Y	1ST/2ND ROW SEAT BELT BUCKLE(25-01-085 H)	11/24/2025	09/12/2025	

Over The Air Software Update Not Performed

Event ID	Scheduled Status	Code	Description	Start Date	VIN Act. Date
No Data					

Extended Factory Warranty

Ext Warranty	Ext Warranty Description	Published Date	Bulletins

TXX1	TWISTED SEAT BELT REPLACEMENT 25-BE-006H		
Z06	SEAT BELT BUCKLE INSP/REP (25-BE-010H)		
Z12	SELF-LVLNG RR SHOCK ABSORBER 25-SS-004H		

Blue Link Information

Blue Link Enrollment Status	CANCELLED	**Maintenance Alert**	
Blue Link Equipped	Gen2	**Last Service Check**	N/A for Gen2
Monthly Vehicle Report	10/28/2024 08:30 AM CST	**SVR Status**	N

Blue Link Outstanding Alerts (1 Found)

Last Report Date	Alert Start Date	Mileage	Code Description	Type	Customer Notification Status	Date of Action
01/21/2024	01/21/2024	79637	NO_DTC N/A - (MIL-ON) 2A	SCHEDULED ALERT		

Service Contract (1 Found)

Designator	Contract Number	Contract Plan	Last Name	First Name	Start Date	Coverage Term	Start Mileage	Coverage Mileage	Description	Administrator Information
HCI	45252897	HYHC	OROZCO	LEIGH	10/30/2021	36	5	36,000	HCM - NON-TURBO MY2021	(Complimentary Maintenance)

HCM Claim Overview

Status	Open Mileage	Open Time	Dealer	Claim #	RO #	RO Date	Mileage	Services
Claimed	7,500 miles Open 6,500~8,500 miles	12 months Open 11~13 months	MS038	570500	825705	01/25/2022	8,001	Tire Rot, Oil Change, MPI
Claimed	15,000 miles Open 14,000~16,000 miles	24 months Open 23~25 months	MS038	703500	377035	04/22/2022	16,372	Tire Rot, Oil Change, MPI
Open	22,500 miles Open 21,500~23,500 miles	36 months Open 35~36 months						
Open	30,000 miles Open 29,000~31,000 miles							

Warranty Claim History (8 Found)

Dealer Code	Claim Number	Repair Order	Repair Date	Repair Mileage	Operation Description
MS038	07849A	207849	11/19/2025	115,019	CAMP TBW:AVN S/W UPDATE
MS038	148874	148874	06/27/2023	62,831	CAMP 243:DRIVER'S SIDE WIPER A RM REP.
MS038	34481F	134481	12/19/2022	51,243	RADIATOR ASSY
MS038	34482F	134482	12/19/2022	51,238	CAMP P31:TOW HITCH HARNESS FUS E REM.
MS038	113872	113872	03/14/2022	12,403	CAMP 975:FRONT DOOR LWR GARNIS H EDGE PART CUT/GRIN
MS038	13872B	113872	03/14/2022	12,403	SENSOR-ABS REAR WHEEL SPEED (L H)
MS038	09612A	109612	01/21/2022	7,999	CAMP T7N:FUEL CAP INSPECTION
MS038	103056	103056	10/30/2021	34	PRE-DELIVERY INSPECTION/SERVIC E

Product List(0 Found)

productName	orderType	eventDate

No Data

Certificate Installation Status(0 Found)

productName	orderType	certStatus	statusSide	orderDt	orderCompleteDt
No Data					

Prior Approval Request History (0 Found)

Dealer Code	PA Number	Repair Order	Request Date	Request Mileage	Repair Group Description
No Data					

Over The Air Software Update History

Event ID	Scheduled Status	Download Status	Installation Status	Code	Description
No Data					

Service Contract Claim History (2 Found)

Contract Type	Contract Numbe	Dealer Code	Claim Number	Repair Order	Repair Date	Repair Mileage	Operation Description
HYHC	45252897	MS038	703500	377035	04/22/2022	16,372	
HYHC	45252897	MS038	570500	825705	01/25/2022	8,001	

Maintenance History (13 Found)

Dealer Code	RO#	R.O Date	Mileage	Dealer Phone#	Customer Pay	Internal Pay

MT014	6050478	02/17/2026	118,445	406-755-5274	Yes	No
MS038	6207849	11/19/2025	115,019	662-844-1383	Yes	No
MS038	6179862	10/09/2024	97,689	662-844-1383	No	Yes
MS038	8024085	05/09/2024	72,003	662-844-1383	Yes	No
MS038	6156768	10/19/2023	72,002	662-844-1383	Yes	No
MS038	6148874	06/27/2023	62,831	662-844-1383	Yes	No
MS038	6145967	05/12/2023	58,896	662-844-1383	Yes	No
MS038	8019375	01/06/2023	51,246	662-844-1383	Yes	No
MS038	6135415	01/04/2023	51,237	662-844-1383	Yes	No
MS038	6124621	07/28/2022	32,075	662-844-1383	Yes	No
MS038	6122528	06/30/2022	24,509	662-844-1383	Yes	No
MS038	6103078	10/30/2021	39	662-844-1383	No	Yes
MS038	6102775	10/28/2021	5	662-844-1383	No	Yes

Blue Link Alert History (4 Found)

Last Report Date	Alert Start Date	Mileage	Code Description	Type	Date Cleared
03/14/2022	03/04/2022	12404	C241613 Anti-Lock Braking System SAFETY - (MIL-ON) 2A	VEHICLE ALERT	12404
03/14/2022	03/04/2022	12404	C136081 Smart Cruise Control ELECTRICAL - (MIL-ON) 2B	VEHICLE ALERT	12404
04/19/2022	04/08/2022	16373	C136081 Smart Cruise Control ELECTRICAL - (MIL-ON) 2B	VEHICLE ALERT	16373

04/19/2022	04/08/2022	16373	C241613 Anti-Lock Braking System SAFETY - (MIL-ON) 2A	VEHICLE ALERT	16373

Appt: March 5th @ 1:30

HYUNDAI

CLARK HYUNDAI
2955 US-93 S, Kalispell, MT 59901
Phone: (406) 755-5274

PICKING TICKET

TERMS: Parts returned for credit must be accompanied by invoice and subject to 20% restocking charge.

DISCLAIMER OF WARRANTIES: All warranties on the products sold hereby are those made by the manufacturer. The seller, CLARK HYUNDAI, hereby expressly disclaims all warranties, either expressed or implied, including any implied warranty of merchantability or fitness for a particular purpose, and CLARK HYUNDAI, neither assumes nor authorizes any other person to assume for it any liability in connection with the sale. A Service Charge of 1-1/2% per month (A.P.R. - 18%) will be made on all accounts 30 days past due. Title to the property herein described, and any additions or substitutions, shall remain in the seller's name until paid in full and the purchaser agrees to pay all expenses, charges, and costs, including collection costs and a reasonable attorney's fee, in the event it becomes necessary for seller to place this account for collection. Net, 10 days end of month.

YOUR PURCHASE ORDER	TERMS	INVOICE DATE	INVOICE NUMBER / PG.
Verbal	Payment Due Upon Rec	02/17/26	6050478 1

SOLD TO
KALISPELL TOYOTA
2845 HWY 93 SOUTH
CONTACT TATUM AT HYUNDAI
KALISPELL, MT 59901
406-755-6060

SHIP TO

SHIP VIA	SALESPERSON NAME	DRIVER'S INITIALS
Repair Order	COLTON SCHROEDER	

QTY.	PART NUMBER / DESCRIPTION	BIN	NET	AMOUNT
1/0	27310-3L030 : COIL-IGNITION	EP	142.56	142.56

Done

ACCOUNT #	METHOD

DATE PRINTED	03/04/26	TIME	16:35:30

PARTS	142.56
FREIGHT	
C.O.D. CHARGE	
SALES TAX OR TAX I.D.	
SPECIAL ORDER DEPOSIT	
TOTAL	142.56

AMOUNT COLLECTED _____

FORM OF PAYMENT _____

YOUR SIGNATURE ACKNOWLEDGES RECEIPT OF PARTS.

X

(C) 2010 DEALERTRACK SYSTEMS, Inc. - Dealership Application Group