CUSTOMER SERVICE BULLETIN

Radio Shaek CUSTOMER SERVICE BULLETIN

Bulletin No. 4556-**Ø**2

Description PROFILE FORMS

Model Model II/12 16

Stock No. 26-4556 Ver. 02. 04. 02

Date September 8, 1983

Page 1 of 1

400 Atrium—One Tandy Center, Fort Worth, Texas 76102

Problem

Underline does not stop where it is specified to stop.

* * THE FOLLOWING PATCHES ARE REQUIRED! * *

Solution

Apply the following patches to correct the problem.

PATCH FORM/EFC A=5630 F=03DDE5E1EDB0E5 C=2A745119C31F52

PATCH FORM/EFC A=5637 F=DDE1FD7EØØ6F26ØØED C=3E5FD5CFD12A745119

PATCH FORM/EFC A=564Ø F=4B7F49Ø9E5D5E1 C=CB7EC238527BB7

PATCH FORM/EFC A=5647 F=D1732372E5D113FD C=CA3852Ø62Ø3E12CF

PATCH FORM/EFC A=564F F=23C325 C=C33852

PATCH FORM/EFC A=51FA F=C3ØE52 C=C33Ø56

PATCH FORM/EFC A=5235 F=3E5FCF C=C33756

To change the version number apply the following patch.

PATCH FORM/EFC A=3F6Ø F="02.04.02" C="02.04.03"

After patches from this Bulletin have been applied, the version number will be $\emptyset2.04.03$. Please make the necessary entry in your Version Log.