CUSTOMER SERVICE BULLETIN

Radio Shack CUSTOMER SERVICE BULLETIN

Bulletin No. 4540-02 (Correction 1)

Description Statistical Analysis

Model II

Stock No. 26-4540 Version 2.0

Date March 4, 1982

Page 1 of 2

400 Atrium—One Tandy Center, Fort Worth, Texas 76102

Problem

When using the Time Series Analysis module of this package, you are placed in underline mode if your printer has underline capabilities.

Solution

The problem is corrected by following the steps listed below.

- Backup the diskette(s) and make the changes on the Backup copy of the program.
- 2. In BASIC load the program by typing LOAD"TIMES/BAS".
- 3. Make the following corrections:

CHANGES (Retype the line or refer to the Edit section of the owners manual)

```
Old Line: 662Ø NEXTLL:PRINT" ";STRING$(78,"-"):PRINT:SYSTEM"DUAL
```

OFF":PRINICHR\$(254);:IFPO\$="Y"THENLPRINT" ":PO\$="N"

New Line: 662Ø NEXTLL:PRINT" ";STRING\$(78,"-"):PRINT:SYSTEM"DUAL OFF":LPRINTCHR\$(14);:PRINTCHR\$(254);:IFPO\$="Y"THENLPRINT" ":PO\$="N"

Old Line: 686Ø PRINTSTRING\$(79,"-"):PRINT:SYSTEM"DUAL OFF":PRINTCHR\$(254);:IFPO\$="Y"THENPO\$="N":LPRINT" "

New Line: 6860 PRINTSTRING\$(79,"-"):PRINT:SYSTEM"DUAL

OFF":LPRINTCHR\$(14);:PRINTCHR\$(254);:IFPO\$="Y"THENPO\$="N":LPRINT" "

Old Line: 7195 PRINTSTRING\$(79,"-"):SYSTEM"DUAL OFF":PRINTCHR\$(254);

New Line: 7195 PRINTSTRING\$(79,"-"):SYSTEM"DUAL

OFF":LPRINTCHR\$(14);:PRINTCHR\$(254);

CUSTOMER SERVICE BULLETIN

Subject .

Statistical Analysis

#4540-02 (Correction 1) Page ____

 $\frac{2}{2}$ Of $\frac{2}{2}$

Old Line: 7700 SYSTEM"DUAL OFF":CLS:IFPO\$="Y"THENPO\$="N":LPRINT" " New Line: 7700 SYSTEM"DUAL OFF": LPRINTCHR\$(14);:CLS :IFPO\$="Y"THENPO\$="N":LPRINT" "

- 4. Type SAVE"TIMES/BAS" to save the changes in the program.
- 5. At TRSDOS READY, make a backup copy of the corrected diskette.