

FLT

Build Guide

All of the SMD components on the PCB have already been assembled. So, this is a real quick and easy build.

1. Start by placing the 2x5 power header. Therefore, you need a little adjustment of the little black plastic on the legs. I like to use tweezers for this task. Place it on the long side of the legs between them and use a little pressure to adjust the black plastic till the small side of the legs is just a little survived when you put it through the Main PCB. The placement of the power header is on the downside of the main PCB (where the SMD parts are located). The header should be soldered from the top side. Solder one pin first and check if the header sits flush with the PCB. If so, you could solder the other pins. If not, reheat the solder joint and adjust the header. Now the topside should look nearly flush.
2. Now it is time to prepare the rest or the THT parts. Place the six jack sockets, the three potentiometers and LED from component side. The placement of each component is marked on the PCB. Mind the orientation for the LEDs. **Place but do not solder yet!**
3. Tighten the knurled nuts from the jacks and the hex nuts from the potentiometer. Have a look if everything is aligned.
4. Now turn the module over and solder the jack sockets and potentiometers from the SMD side. **Wait with the LED!**
5. Now have a look at the LED, if it hits the translucent spot behind the panel. Solder one pin first and have a look again. If needed re-heat and adjust the LED. If the LED faces the spot, solder the second pin. Cut the protruding legs.

Congratulations, your build is done!