

XORGON

Build Guide

All of the SMD components on the PCB have already been assembled. So, this is a real easy build.

1. Start by placing the 2x5 power header. The placement of the power header is on the downside of the main PCB. The header should be soldered from top side. Solder one pin first and check if the header sits flush with the PCB. If so, you could solder the other pins. If not, reheat the solder joint and adjust the header.
2. If you use 3296W trimpots instead of 3296X, you should place and solder them now. Place one 100R trimpot on the most left and most right placemarks. The five left spots (all the middle ones, except for the outermost one on each side) are 100K trimpots. If you use 3296X trimpots you could start directly with point 3 of this guide. Part placement stays the same.
3. Now it is time to prepare the rest or the THT parts. Place the three slide potentiometers, the twenty-eight jack sockets, the six potentiometers, two LED and the On-On switch from component side. The placement of each component is marked on the PCB. Mind the orientation for the LEDs. **Place but do not solder yet!**
4. Tighten the knurled nuts from the jacks and the hex nuts from the potentiometer. Have a look if everything is aligned.
5. Now turn the module over and solder the jack sockets, slider, switch and potentiometers from the SMD side. **Wait with the LED!**
6. Now have a look at the LED, if it hits the translucent spot behind the panel. Solder one pin first and have a look again. If needed re-heat and adjust the LED. If the LED faces the spot, solder the second pin. Cut the protruding legs.

Congratulations, your build is done!