

ROS2 rack box · Assembly instructions

Second box, rack style: the Pico board, the Pi and the converter stand on edge, side by side. 78 × 95 × 145 mm (1.07 L). The Pi sits low and the converter high, so its heat does not rise into the Pi. It takes a Pi 4 or a Pi 5: only the back frame changes. OLED, logo, switch and XT60 are on the main face; the Pi's USB and an HDMI panel jack at the back. Every screw goes into an insert. Before printing, measure what the README lists.

Up-to-date guide, STL and sources:
https://github.com/BeskarCode/ROS2D2/tree/main/hardware/caja_ros2_rack






Size next to the R2

Schematic R2 and the box at the same scale.

Exploded view



Hardware and parts

Printed parts

`pared_multicolor_bambu.3mf`	Main face with the logo in 4 colours (AMS: white, navy, blue, grey)
`pared_monocolor.stl`	or: single-colour main face, engraved logo
`con_leds/pared_led_multicolor_bambu.3mf`	or: main face with a hole over each LED of the Pico board, logo lower down and the connector names (AMS: white, navy, blue, grey)
`con_leds/pared_led_monocolor.stl`	or: the LED face in one colour, logo and names engraved
`con_leds/guias_luz.stl`	Light pipes (optional, only with the LED face): one piece in translucent PLA (or clear PETG), outer ends on the bed, 100 % infill
`con_leds/prueba_luz.stl`	Light test rod: print it first and hold it on a lit LED to see whether your filament lets enough light through
`base.stl`	Base: floor, back, central divider
`tapa.stl`	Shell (roof + side + narrow front)
`marco_pi4.stl`	Back frame for the Pi 4 (Ethernet at the top)


`marco_pi5.stl`	or: back frame for the Pi 5 (Ethernet at the bottom)
`pulsador.stl`	DISPLAY push rod

Qty	Part	Step
19×	M3 heat-set insert (5.7 mm long, 4.0 mm hole)	1
9×	M3 × 8 countersunk screw (ISO 10642)	4, 6, 7
8×	M3 × 6 button head screw (ISO 7380)	3, 5
2×	M3 × 6 socket head cap screw (DIN 912)	2
4×	M2.5 × 6 screw	3
4×	M4 × 12 screw (or what the R2's mount needs)	8
4×	M2.5 heat-set insert (5 mm long, 3.6 mm hole)	1


Other parts

1	KCD1 rocker switch (panel hole 19.2 × 13 mm)
1	XT60E-F panel connector (AMASS)
1	micro-USB 2.0 to USB-A cable, 90° side angle, 30 cm (see «Angled plugs»)
—	0.5 mm² wire for the 5 V to terminal J1, 1 mm² for the 24 V
1	Edge grommet strip for the 35 × 10 mm slot
1	USB-C male pigtail (5 V to the Pi), 90° up/down angle, 15–20 cm; 3 A for a Pi 4, 5 A for a Pi 5
1	Angled 90° micro-HDMI male to HDMI female panel-mount cable with 2 M3 screws, 30 cm (measure its flange: `hdmi_*`)

Inside (no shell)




Wiring



Angled plugs: which way the cable goes

1 · Angled micro-USB (Pico → Pi) · both boxes

Looking at the Pico's parts side, its USB at the top (as it sits on the sensor board):



✗ **towards you (the parts side):**
hits the sensors' Dupont plugs

✗ **backwards (behind the board):**
hits the divider in box C


When buying:

· micro-USB 2.0 (not 3.0), 30 cm (fits both boxes).
· SIDE angle: the cable leaves sideways, along the connector's long side (not up or down).
· micro-USB only goes in one way: compare the photo with your Pico and check the cable will end up on the LEFT.
("left"/"right" mean different things to different brands)

---

2 · Angled USB-C pigtail (converter → Pi) · box C


The Pi seen from the narrow front: standing, parts and fan to the right, USB-C at the bottom:



When buying:

· 90° angled USB-C male pigtail (loose wires), rated 3 A (the Pi 4 wants 5 V / 3 A), 15–20 cm.
· "Up/down" angle: the cable leaves square to the connector's wide face. USB-C is reversible: turn it so the cable goes towards the fan.
· The first box takes the same cable (or a straight one): there the USB-C faces the roof, cable towards the middle.

1 Heat-set inserts




19× M3 insert

4× M2.5 insert

With the iron at about 220 °C press the inserts in straight and flush. On the main face, 7 M3: 4 in the columns, 2 in the bottom tabs and 1 in the top tab; plus 2 M3 from outside in the XT60's holes. On the base, 10 M3: 2 on top of the divider, 2 in the divider for the converter, 2 in the floor blocks and 4 from outside the back (2 for the frame, 2 for the HDMI); and the 4 M2.5 in the Pi's standoffs.


2 Converter onto the divider, high



2× M3 × 6 socket head

On edge, at the very top, its base plate against the divider, fins outwards, wires to the front: they go through the top pass in the divider to the Pico side. Its heat rises out of the roof without passing the Pi. Check its holes (`conv_holes`) with a caliper first.

3 Raspberry Pi, frame and HDMI



4× M2.5 × 6 4× M3 × 6

Pi 4 or Pi 5 on its 4 standoffs, low down, USB and Ethernet in the back window, USB-C at the bottom. Plug in the angled USB-C (5 V from the converter, down in front of the Pi) and the angled micro-HDMI into HDMI 0; that cable runs under the Pi through the divider's bottom pass. Screw on, from outside, the frame for your Pi (`marco_pi4` or `marco_pi5`) and the HDMI panel jack.


4 XT60 and switch on the main face



2× M3 × 8 countersunk

From outside, low down: the XT60E-F turned on its side with 2 screws into the inserts, and the switch snapped in.


5 Push rod and Pico board



4× M3 × 6

With the LED face, the light pipes are optional (without them the LEDs show through the holes). If you fit them, they go in before hanging the board: from inside, slide the 10 rods into their holes and push the frame against the wall until the 4 hooks click. Slide the rod into its guide from inside. Before screwing, offer the board up without screws onto the 4 columns, parts towards the wall: it must sit on all four without rocking; if it rocks, a rod touches its LED: sand its tip. Then screw it on. To take it out, open the hooks two at a time with a small screwdriver. If you ever use J4 (EXP), its cable goes round the PWR rod. Tighten the 5 V in terminal J1, plug the angled micro-USB into the Pico and connect the sensors: their cables leave through the slot at the top.


6 Main face onto the base



2× M3 × 8 countersunk

The 24 V (XT60 → switch → converter) run up in front of the Pico board and cross through the divider's top pass; the 5 V to terminal J1 come back through the same pass and over the board. Screw the face on from under the floor.

7 Shell



5× M3 × 8 countersunk

Lower it from above and fit the 3 roof screws and the 2 side screws. Air comes in through the low vents (front and side, by the Pi) and leaves through the high ones and the roof.

8 USB and onto the R2



4× M4 × 12

Bring the micro-USB out of the notch in the back into a Pi USB port. Screw the box to the R2 through its 4 ears.