

SOLIDWORKS API (.NET VBA C#) — Reference

(321/337): View (part 1 of 10)

SOLIDWORKS API Documentation (converted from CHM)

IView (part 1 of 10) (Type)

SOLIDWORKS API Help

[Send comments](#) on this topic.

IView Interface

[See Also](#) [Members](#) [Example](#)



[SolidWorks.Interop.sldworks Namespace](#) : IView Interface

Represents drawing views found in a drawing document.

NOTE: Click the **Members** link, located near the top of the topic, to see this interface's methods and properties.

.NET Syntax

Visual Basic (Declaration)

```
Public Interface IView
```

Visual Basic (Usage)



```
Dim instance As IView
```

C#

```
public interface IView
```

C++/CLI

```
public interface class IView
```

Visual Basic for Applications (VBA) Syntax

See [View](#).

Example

[Insert Spline in Drawing \(C++\)](#)
[Set View Display Mode \(C++\)](#)
[Autodimension Selected Drawing View \(VBA\)](#)
[Get Base Views \(VBA\)](#)
[Get Drawing View Names and Types \(VBA\)](#)
[Insert Alternate Position View \(VBA\)](#)
[Reposition Drawing Views to Avoid Overlap \(VBA\)](#)
[Get Notes from New or Existing Title Block \(C#\)](#)
[Get Notes from New or Existing Title Block \(VB.NET\)](#)
[Get Notes from New or Existing Title Block \(VBA\)](#)
[Insert Weldment Cut List Table \(VBA\)](#)
[Insert Weldment Cut List Table \(VB.NET\)](#)
[Insert Weldment Cut List Table \(C#\)](#)
[Insert Weld Table \(VBA\)](#)
[Insert Weld Table \(VB.NET\)](#)
[Insert Weld Table \(C#\)](#)
[Get Break Line Data \(VBA\)](#)
[Get Break Line Data \(VB.NET\)](#)
[Get Break Line Data \(C#\)](#)
[Insert Hole Table \(VBA\)](#)
[Insert Hole Table \(VB.NET\)](#)
[Insert Hole Table \(C#\)](#)

Remarks

A drawing document can consist of one or more drawing sheets. Each drawing sheet typically contains one or more drawing views. Each drawn view is an oriented snapshot of a particular SOLIDWORKS model and a particular configuration of the model.

The IView object lets you determine the particular model and configuration being viewed and to get information about all the objects in a drawing sheet or drawing view, as well as the drawing view bounds, and transforms.

Accessors

[IBreakLine::GetView](#)

[IDetailCircle::GetDetailView](#)

[IDetailCircle::GetView](#)

[IDrawingComponent::View](#)

[IDrawingDoc::ActiveDrawingView](#) and [IDrawingDoc::IActiveDrawingView](#)
[IDrawingDoc::CreateAuxiliaryViewAt2](#) and [IDrawingDoc::ICreateAuxiliaryViewAt2](#)
[IDrawingDoc::CreateDetailViewAt3](#) and [IDrawingDoc::ICreateDetailViewAt3](#)
[IDrawingDoc::CreateDrawViewFromModelView3](#)
[IDrawingDoc::CreateRelativeView](#)
[IDrawingDoc::CreateSectionViewAt4](#) and [IDrawingDoc::ICreateSectionViewAt4](#)
[IDrawingDoc::CreateUnfoldedViewAt3](#)
[IDrawingDoc::CreateViewport3](#)
[IDrawingDoc::DropDrawingViewFromPalette](#)
[IDrawingDoc::GetFirstView](#) and [IDrawingDoc::IGetFirstView](#)
[IDrSection::GetSectionView](#) and [IDrSection::IGetSectionView](#)
[IDrSection::GetView](#) and [IDrSection::IGetView](#)
[IMacroFeatureData::GetSelections3](#) and [IMacroFeatureData::IGetSelections3](#)
[IProjectionArrow::GetProjectedView](#) and [IProjectionArrow::IGetProjectedView](#)
[IProjectionArrow::GetView](#) and [IProjectionArrow::IGetView](#)
[ISelectData::View](#)
[ISelectionMgr::GetSelectedObjectsDrawingView2](#)
[ISheet::GetViews](#)
[ISilhouetteEdge::GetView](#)
[IView::GetBaseView](#) and [IView::IGetBaseView](#)
[IView::GetDependentViews](#) and [IView::IGetDependentViews](#)
[IView::GetNextView](#) and [IView::IGetNextView](#)
[IView::InsertAlternateView](#)

 Access Diagram

[View](#)

 See Also

[IView Members](#)
[SolidWorks.Interop.sldworks Namespace](#)
[IDrawingDoc Interface](#)
[IDrSection Interface](#)

IView Interface Methods

[See Also](#)

 [SolidWorks.Interop.sldworks Namespace](#) : IView Interface

For a list of all members of this type, see [IView members](#).

 Public Methods

Name	Description
 AlignDrawingView	Specifies the alignment of this auxiliary drawing view.
 AlignWithView	Sets view alignment.
 AutoInsertCenterMarks	Obsolete. Superseded by IView.AutoInsertCenterMarks2 .
 AutoInsertCenterMarks2	Automatically inserts the specified center marks in this view.
 Crop	Obsolete. Superseded by IView.Crop2 .
 Crop2	Crops this view using the selected closed sketch profile.
 EnumHiddenComponents	Obsolete. Superseded by IView.EnumHiddenComponents2 .
 EnumHiddenComponents2	Gets the hidden components enumeration in this drawing view.
 EnumSectionLines	Obsolete. Superseded by IView.EnumSectionLines2 .

 EnumSectionLines2	Gets the section lines enumeration in the view.
 GetAlignment	Gets the alignment information of this view.
 GetAnnotationCount	Gets the number of annotations in this view.
 GetAnnotations	Gets the annotations in this view.
 GetAnnotationsByType	Gets the annotations of the specified type in this view.
 GetArcCount	Gets the number of arcs in this view.
 GetArcs	Obsolete. Superseded by IView.GetArcs4 and IView.IGetArcs4 .
 GetArcs2	Obsolete. Superseded by IView.GetArcs4 and IView.IGetArcs4 .
 GetArcs3	Obsolete. Superseded by IView.GetArcs4 and IView.IGetArcs4 .
 GetArcs4	Gets all of the information for all of the arcs added by a user in this drawing view.
 GetBaseView	Gets the base (parent) view used to create this view.
 GetBendLineCount	Gets the number of bendlines in a flat-pattern drawing view .
 GetBendLines	Gets the bendlines in a flat-pattern drawing view .
 GetBendNoteAttributeString	Gets the internal string that is used to format the text of the specified bend note attribute in this drawing view of a sheet metal part.
 GetBendNoteTextFormat	Gets the text format of all bend notes in this drawing view of a sheet metal part.
 GetBodiesCount	Gets the number of bodies of a multibody part in the drawing view.
 GetBomTable	Gets the BOM table found in this drawing view.
 GetBreakLineCount	Obsolete. Superseded by IView.GetBreakLineCount2 .
 GetBreakLineCount2	Gets the number of breaks lines and breaks in this view.
 GetBreakLineInfo	Obsolete. Superseded by IView.GetBreakLineInfo2 .
 GetBreakLineInfo2	Gets information for all of the break lines in this view.
 GetBreakLines	Gets the all of the breaks in this view.
 GetBreakOutSectionCount	Gets the number of broken-out sections in this view.
 GetBreakOutSections	Gets all of the broken-out sections in this view.
 GetCenterLineCount	Gets the number of centerlines on this drawing view.
 GetCenterLines	Gets all of the centerline annotations on this drawing view.
 GetCenterLineSketch	Gets the sketch that contains all of the centerline information for this view.
 GetCenterMarkCount	Obsolete. Superseded by IView.GetCenterMarkCount2 .
 GetCenterMarkCount2	Gets the number of center marks that are features in the view.
 GetCenterMarkInfo	Gets information about each center mark that is a feature in the view.
 GetCenterMarks	Gets all of the center marks that are features in the view.
 GetCorresponding	Gets the object in this drawing view that corresponds to the specified part or assembly object.
 GetCorrespondingEntity	Gets the entity in this drawing view that corresponds to the specified part or assembly entity.
 GetCThreadCount	Gets the number of cosmetic threads in this drawing view.
 GetCThreadQuality	Gets the cosmetic thread display quality in this view.
 GetCThreads	Gets all of the cosmetic threads on this drawing view.
 GetDatumOriginCount	Gets the number of datum origins on this drawing view.
 GetDatumOrigins	Gets all of the datum origins on this drawing view.
 GetDatumPoints	Obsolete. Superseded by IView.GetDatumPoints2 and IView.IGetDatumPoints2 .
 GetDatumPoints2	Gets all of the information about all the datum points in this view.
 GetDatumPointsCount	Gets the number of datum points in this view.
 GetDatumTagCount	Gets the number of datum tags on this drawing view.
 GetDatumTags	Gets all of the datum tags on this drawing view.

		
	GetDatumTargetSymCount	Gets the number of datum target symbols on this drawing view.
	GetDatumTargetSyms	Gets all of the datum target symbols on this drawing view.
	GetDependentViewCount	Gets the number of all, or only the specified, dependent views (i.e., alternate position, detail, section, etc.) in this view.
	GetDependentViews	Gets either all, or only the specified, dependent views in this view.
	GetDesignTableExtent	Gets the size and location of the design table associated with this drawing view.
	GetDetail	Gets the detail circle for this detail view.
	GetDetailCircleCount	Obsolete. Superseded by IView.GetDetailCircleCount2 .
	GetDetailCircleCount2	Gets the number of detail circles in the drawing view.
	GetDetailCircleInfo	Obsolete. Superseded by IView.GetDetailCircleInfo2 and IView.IGetDetailCircleInfo2 .
	GetDetailCircleInfo2	Gets all of the information about each detail circle in the view.
	GetDetailCircles	Gets the detail circles in this view.
	GetDetailCircleStrings	Gets an array of strings; each string represents the text label for a detail circle in this view.
	GetDimensionCount	Obsolete. Superseded by IView.GetDimensionCount4 .
	GetDimensionCount2	Obsolete. Superseded by IView.GetDimensionCount4 .
	GetDimensionCount3	Obsolete. Superseded by IView.GetDimensionCount4 .
	GetDimensionCount4	Gets the number of display dimensions in the current drawing sheet or the current drawing view.
	GetDimensionDisplayInfo	Obsolete. Superseded by IView.GetDimensionDisplayInfo5 and IView.IGetDimensionDisplayInfo5 .
	GetDimensionDisplayInfo2	Obsolete. Superseded by IView.GetDimensionDisplayInfo5 and IView.IGetDimensionDisplayInfo5 .
	GetDimensionDisplayInfo3	Obsolete. Superseded by IView.GetDimensionDisplayInfo5 and IView.IGetDimensionDisplayInfo5 .
	GetDimensionDisplayInfo4	Obsolete. Superseded by IView.GetDimensionDisplayInfo5 and IView.IGetDimensionDisplayInfo5 .
	GetDimensionDisplayInfo5	Gets the display dimension information for the current drawing sheet or the current drawing view.
	GetDimensionDisplayInfoSize	Obsolete. Superseded by IView.GetDimensionDisplayInfoSize2 .
	GetDimensionDisplayInfoSize2	Gets the number of the dimension lines n the current drawing sheet or the current drawing view.
	GetDimensionDisplayString	Obsolete. Superseded by IView.GetDimensionDisplayString4 and IView.IGetDimensionDisplayString4 .
	GetDimensionDisplayString2	Obsolete. Superseded by IView.GetDimensionDisplayString4 and IView.IGetDimensionDisplayString4 .
	GetDimensionDisplayString3	Obsolete. Superseded by IView.GetDimensionDisplayString4 and IView.IGetDimensionDisplayString4 .
	GetDimensionDisplayString4	Obsolete. Superseded by IView.GetDimensionDisplayString5 .
	GetDimensionDisplayString5	Gets all of the dimension text in the current drawing sheet or the current drawing view.
	GetDimensionIds	Obsolete. Superseded by IView.GetDimensionIds4 and IView.IGetDimensionIds4 .
	GetDimensionIds2	Obsolete. Superseded by IView.GetDimensionIds4 and IView.IGetDimensionIds4 .
	GetDimensionIds3	Obsolete. Superseded by IView.GetDimensionIds4 and IView.IGetDimensionIds4 .
	GetDimensionIds4	Gets the dimension names from the current drawing sheet or the current drawing view.
	GetDimensionInfo	Obsolete. Superseded by IView.GetDimensionInfo6 and IView.IGetDimensionInfo6 .
	GetDimensionInfo2	Obsolete. Superseded by IView.GetDimensionInfo6 and IView.IGetDimensionInfo6 .
	GetDimensionInfo3	Obsolete. Superseded by IView.GetDimensionInfo6 and IView.IGetDimensionInfo6 .
	GetDimensionInfo4	Obsolete. Superseded by IView.GetDimensionInfo6 and IView.IGetDimensionInfo6 .
	GetDimensionInfo5	Obsolete. Superseded by IView.GetDimensionInfo6 and IView.IGetDimensionInfo6 .
	GetDimensionInfo6	Obsolete. Superseded by IView.GetDimensionInfo7 .
	GetDimensionInfo7	Gets all of the dimension information in the current drawing sheet or the current drawing view.
	GetDimensionString	Obsolete. Superseded by IView.GetDimensionString4 and IView.IGetDimensionString4 .
	GetDimensionString2	Obsolete. Superseded by IView.GetDimensionString4 and IView.IGetDimensionString4 .
	GetDimensionString3	Obsolete. Superseded by IView.GetDimensionString4 and IView.IGetDimensionString4 .

		
	GetDimensionString4	Gets the strings containing the text associated with each dimension in the current drawing sheet or the current drawing view.
	GetDisplayData	Obsolete. Superseded by IView.GetDisplayData3 and IView.IGetDisplayData3 .
	GetDisplayData2	Obsolete. Superseded by IView.GetDisplayData3 and IView.IGetDisplayData3 .
	GetDisplayData3	Obsolete. Superseded by IView.GetDisplayData4 .
	GetDisplayData4	Gets the the IDisplayData object for this drawing view containing only those model items that are visible in the view.
	GetDisplayDimensionCount	Gets the number of display dimensions in this drawing view.
	GetDisplayDimensions	Gets all of the display dimension on this drawing view.
	GetDisplayEdgesInShadedMode	Gets whether to display the edges in this when the drawing view is in shaded mode.
	GetDisplayMode	Obsolete. Superseded by IView.GetDisplayMode2 .
	GetDisplayMode2	Gets the current display mode of the view.
	GetDisplayTangentEdges	Obsolete. Superseded by IView.GetDisplayTangentEdges2 .
	GetDisplayTangentEdges2	Gets the current tangent edge display mode of the drawing view.
	GetDowelSymbolCount	Gets the number of dowel symbols in this drawing view.
	GetDowelSymbols	Gets all of the dowel symbols on this drawing view.
	GetEllipseCount	Gets the number of ellipses in the view.
	GetEllipses	Obsolete. Superseded by IView.GetEllipses5 and IView.IGetEllipses5 .
	GetEllipses2	Obsolete. Superseded by IView.GetEllipses5 and IView.IGetEllipses5 .
	GetEllipses3	Obsolete. Superseded by IView.GetEllipses5 and IView.IGetEllipses5 .
	GetEllipses4	Obsolete. Superseded by IView.GetEllipses5 and IView.IGetEllipses5 .
	GetEllipses5	Gets all of the ellipses added by a user in this drawing view.
	GetFaceHatchCount	Gets the number of face hatches in the view.
	GetFaceHatches	Gets the face hatches in the view.
	GetFacetedHlrDisplay	Gets whether HLR/HLV (Hidden Lines Removed/Hidden Lines Visible) edges should be displayed faceted in the view.
	GetFirstAnnotation	Obsolete. Superseded by IView.GetFirstAnnotation3 .
	GetFirstAnnotation2	Obsolete. Superseded by IView.GetFirstAnnotation3 .
	GetFirstAnnotation3	Gets the first annotation in this drawing view.
	GetFirstBlockInstance	Obsolete. Not superseded.
	GetFirstCenterLine	Gets the first centerline in this view.
	GetFirstCenterMark	Obsolete. Superseded by IView.GetFirstCenterMark2 .
	GetFirstCenterMark2	Gets the first center mark in the view.
	GetFirstCenterOfMass	Gets the first center of mass in this view.
	GetFirstCThread	Gets the first cosmetic thread in the view.
	GetFirstCustomSymbol	Obsolete. Not superseded.
	GetFirstDatumOrigin	Gets the first datum origin in this drawing view.
	GetFirstDatumTag	Gets the first datum tag in the view.
	GetFirstDatumTargetSym	Gets the first datum target symbol in the view.
	GetFirstDisplayDimension	Obsolete. Superseded by IView.GetFirstDisplayDimension5 .
	GetFirstDisplayDimension2	Obsolete. Superseded by IView.GetFirstDisplayDimension5 .
	GetFirstDisplayDimension3	Obsolete. Superseded by IView.GetFirstDisplayDimension5 .
	GetFirstDisplayDimension4	Obsolete. Superseded by IView.GetFirstDisplayDimension5 .
	GetFirstDisplayDimension5	Obsolete. Superseded by IView.GetFirstDisplayDimension6 .
	GetFirstDisplayDimension6	Gets the first display dimension in this drawing view.

		
	GetFirstDowelSymbol	Gets the first dowel symbol in the view.
	GetFirstGTOL	Gets the first geometric tolerance in this view.
	GetFirstMultiJogLeader	Obsolete. Superseded by IView.GetFirstMultiJogLeader2 .
	GetFirstMultiJogLeader2	Gets the first multi-jog leader in the view.
	GetFirstNote	Obsolete. Superseded by IView.GetFirstNote2 .
	GetFirstNote2	Gets the first note in the view.
	GetFirstRevisionCloud	Obsolete. Superseded by IView.GetFirstRevisionCloud2 .
	GetFirstRevisionCloud2	Gets the first revision cloud annotation in this view.
	GetFirstSFSymbol	Gets the first surface-finish symbols in the view.
	GetFirstTableAnnotation	Obsolete. Superseded by IView.GetFirstTableAnnotation2 .
	GetFirstTableAnnotation2	Gets the first table annotation in this view.
	GetFirstWeldBead	Gets the first weld bead annotation in this view.
	GetFirstWeldSymbol	Gets the first weld symbol in the view.
	GetGTolCount	Gets the number of geometric tolerances in this drawing view.
	GetGTols	Gets all of the geometric tolerances on this drawing view.
	GetHiddenComponents	Gets the hidden components in this drawing view.
	GetKeepLinkedToBOM	Gets whether this drawing view is linked to a BOM or weldment cut-list table.
	GetKeepLinkedToBOMName	Gets the name of the BOM or weldment cut-list table feature to which this drawing view is linked.
	GetLineCount	Obsolete. Superseded by IView.GetLineCount2 .
	GetLineCount2	Gets the number of lines in this view with an option to include or exclude crosshatch lines.
	GetLines	Obsolete. Superseded by IView.GetLines4 and IView.IGetLines4 .
	GetLines2	Obsolete. Superseded by IView.GetLines4 and IView.IGetLines4 .
	GetLines3	Obsolete. Superseded by IView.GetLines4 and IView.IGetLines4 .
	GetLines4	Gets all of the lines in the view with an option to include or exclude crosshatch lines.
	GetMirrorViewOrientation	Gets whether this view is mirrored.
	GetMultiJogLeaderCount	Gets the number of multi-jog leaders on this drawing view.
	GetMultiJogLeaders	Gets all of the multi-jog leaders in this drawing view.
	GetName2	Gets the name of this drawing view displayed in the FeatureManager design tree.
	GetNextView	Gets the next drawing view in the drawing.
	GetNoteCount	Gets the number notes in this drawing view.
	GetNotes	Gets the notes in this drawing view.
	GetOrientationName	Gets the predefined name of this view.
	GetOutline	Gets the bounding box for a view (sheet or drawing) in meters on the drawing page.
	GetParabolaCount	Gets the number of parabolas in the view.
	GetParabolas	Obsolete. Superseded by IView.GetParabolas2 and IView.IGetParabolas2 .
	GetParabolas2	Gets all of the information about all of the parabolas in this view.
	GetPolyLineCount	Obsolete. Superseded by IView.GetPolyLineCount5 .
	GetPolyLineCount2	Obsolete. Superseded by IView.GetPolyLineCount5 .
	GetPolyLineCount3	Obsolete. Superseded by IView.GetPolyLineCount5 .
	GetPolyLineCount4	Obsolete. Superseded by IView.GetPolyLineCount5 .
	GetPolyLineCount5	Gets the number of polylines in this view with an option to include or exclude crosshatch lines.
	GetPolylines	Obsolete. Superseded by IView.GetPolylines6 and IView.IGetPolylines6 .

		
	GetPolyLines2	Obsolete. Superseded by IView.GetPolyLines6 and IView.IGetPolyLines6 .
	GetPolyLines3	Obsolete. Superseded by IView.GetPolyLines6 and IView.IGetPolyLines6 .
	GetPolyLines4	Obsolete. Superseded by IView.GetPolyLines6 and IView.IGetPolyLines6 .
	GetPolyLines5	Obsolete. Superseded by IView.GetPolyLines6 and IView.IGetPolyLines6 .
	GetPolyLines6	Obsolete. Superseded by IView.GetPolyLines7 .
	GetPolyLines7	Gets all of the polylines in the view with an option to include or exclude crosshatch lines.
	GetPolyLinesAndCurves	Gets the arcs, ellipses, splines, and polylines in the view with an option to include or exclude crosshatch lines.
	GetPolyLinesAndCurvesCount	Gets the number of lines, including arcs, ellipses, splines, and polylines, in the view with the option to include or exclude cross hatch lines.
	GetProjectionArrow	Gets the projection arrow for this projected view.
	GetProjectionLineCount	Gets the number of projection lines (arrows) in this drawing view.
	GetProjectionLines	Gets the projection lines (arrows) in this drawing view.
	GetReferencedModelName	Gets the name of the model that is referenced in the drawing view.
	GetRelatedTangentEdgeCount	Gets the number of visible tangent edges for the specified bendline in a flat-pattern drawing view .
	GetRelatedTangentEdges	Gets the visible tangent edges for the specified bendline in a flat-pattern drawing view .
	GetRevisionCloudCount	Gets the number of revision cloud annotations in this view.
	GetRevisionClouds	Gets all of the revision cloud annotations in this view.
	GetSection	Gets the section for this section view.
	GetSectionLineCount	Obsolete. Superseded by IView.GetSectionLineCount2 .
	GetSectionLineCount2	Gets the number of section lines in the view.
	GetSectionLineInfo	Obsolete. Superseded by IView.GetSectionLineInfo2 and IView.GetSectionLineInfo2 .
	GetSectionLineInfo2	Gets all of the information about the section lines in the view.
	GetSectionLines	Gets the section lines in the view.
	GetSectionLineStrings	Gets an array of strings; each string represents the text label for a section line in this view.
	GetSFSymbolCount	Gets the number of surface finish symbols on this drawing view.
	GetSFSymbols	Gets all of the surface finish symbols in this drawing view.
	GetSketch	Gets the sketch used by this view.
	GetSketchPictureCount	Gets the number of sketch pictures imported to this view when a drawing is created from a part.
	GetSketchPictures	Gets all of the sketch pictures imported to this view when a drawing is created from a part.
	GetSMBoundingBoxDisplayData	Obsolete. Superseded by IView.GetSMBoundingBoxDisplayData2 .
	GetSMBoundingBoxDisplayData2	Gets the boundary-box sketch display data of a flat-pattern drawing view.
	GetSolidHatchCount	Gets the number of visible solid-fill hatches in a detail, break, or crop view and the size of the array for their boundary data.
	GetSolidHatchInfo	Gets the boundary data for all visible solid-fill hatches in a detail, break, or crop view.
	GetSplineCount	Gets the number of splines in the view.
	GetSplines	Obsolete. Superseded by IView.GetSplines3 and IView.IGetSplines3 .
	GetSplines2	Obsolete. Superseded by IView.GetSplines3 and IView.IGetSplines3 .
	GetSplines3	Gets all of the splines added by a user in the drawing view.
	GetTableAnnotationCount	Gets the number of table annotations in this drawing view.
	GetTableAnnotations	Gets all of the table annotations on this drawing view.
	GetTemporaryAxes	Gets the information of the temporary axes displayed in this view.
	GetTemporaryAxesCount	Gets the number of temporary axes in this view.
	GetUniqueName	Gets the unique name of this section view.
	GetUseParentDisplayMode	Gets whether the view is using its parent settings or if it is using its own local settings.

		
	GetUserPoints	Obsolete. Superseded by IView.GetUserPoints2 and IView.IGetUserPoints2 .
	GetUserPoints2	Gets all of the information about all of the user points in this view.
	GetUserPointsCount	Gets the number of user points in the view.
	GetViewXform	Gets the transform from model space origin to drawing space origin.
	GetVisible	Gets the visibility of this drawing view.
	GetVisibleComponentCount	Gets the number of visible components in this drawing view.
	GetVisibleComponents	Gets the visible components in this drawing view.
	GetVisibleDrawingComponents	Gets all of the unobscured drawing components in this drawing view of an assembly drawing.
	GetVisibleEntities	Obsolete. Superseded by IView.GetVisibleEntities2 .
	GetVisibleEntities2	Gets the visible entities of the specified type for the specified component in this drawing view.
	GetVisibleEntityCount	Obsolete. Superseded by IView.GetVisibleEntityCount2 .
	GetVisibleEntityCount2	Gets the number of visible entities of the specified type for the specified component in this drawing view.
	GetWeldBeadCount	Gets the number of weld beads on this drawing view.
	GetWeldBeads	Gets all of the weld beads on this drawing view.
	GetWeldSymbolCount	Gets the number of weld symbols on this drawing view.
	GetWeldSymbols	Gets all of the weld symbols on this drawing view.
	GetWitnessEntitiesCount	Gets the number of virtual sharp witness lines in this drawing view.
	GetWitnessGeomInfo	Gets the geometry data for all of the virtual sharp witness lines in this drawing view.
	GetXform	Gets the matrix used for displaying this drawing view.
	HasDesignTable	Gets whether this drawing view has a design table associated with it.
	IGetAnnotations	Gets the annotations in this view.
	IGetArcs	Obsolete. Superseded by IView.GetArcs4 and IView.IGetArcs4 .
	IGetArcs2	Obsolete. Superseded by IView.GetArcs4 and IView.IGetArcs4 .
	IGetArcs3	Obsolete. Superseded by IView.GetArcs4 and IView.IGetArcs4 .
	IGetArcs4	Gets all of the information for all of the arcs added by a user in this drawing view.
	IGetBaseView	Gets the base (parent) view used to create this view.
	IGetBendLines	Gets the bendlines in a flat-pattern drawing view .
	IGetBodies	Gets the bodies of a multibody part in the drawing view.
	IGetBomTable	Gets the BOM table found in this drawing view.
	IGetBreakLineInfo	Obsolete. Superseded by IView.IGetBreakLineInfo2 .
	IGetBreakLineInfo2	Gets information for all of the break lines in this view.
	IGetBreakLines	Gets the all of the breaks in this view.
	IGetBreakOutSections	Gets all of the broken-out sections in this view.
	IGetCenterLines	Gets all of the centerlines on this drawing view.
	IGetCenterMarkInfo	Gets information about each center mark that is a feature in the view.
	IGetCenterMarks	Gets all of the center marks that are features in the view.
	IGetCThreads	Gets all of the cosmetic threads on this drawing view.
	IGetDatumOrigins	Gets all of the datum origins on this drawing view.
	IGetDatumPoints	Obsolete. Superseded by IView.GetDatumPoints2 and IView.IGetDatumPoints2 .
	IGetDatumPoints2	Gets all of the information about all the datum points in this view.
	IGetDatumTags	Gets all the datum tags on this drawing view.
	IGetDatumTargetSyms	Gets all of the datum target symbols on this drawing view.

		
	IGetDependentViews	Gets either all, or only the specified, dependent views in this view.
	IGetDesignTableExtent	Gets the size and location of the design table associated with this drawing view.
	IGetDetail	Gets the detail circle for this detail view.
	IGetDetailCircleInfo	Obsolete. Superseded by IView.GetDetailCircleInfo2 and IView.IGetDetailCircleInfo2 .
	IGetDetailCircleInfo2	Gets all of the information about each detail circle in the view.
	IGetDetailCircles	Gets the detail circles in this view.
	IGetDetailCircleStrings	Gets an array of strings; each string represents the text label for a detail circle in this view.
	IGetDimensionDisplayInfo	Obsolete. Superseded by IView.GetDimensionDisplayInfo5 and IView.IGetDimensionDisplayInfo5 .
	IGetDimensionDisplayInfo2	Obsolete. Superseded by IView.GetDimensionDisplayInfo5 and IView.IGetDimensionDisplayInfo5 .
	IGetDimensionDisplayInfo3	Obsolete. Superseded by IView.GetDimensionDisplayInfo5 and IView.IGetDimensionDisplayInfo5 .
	IGetDimensionDisplayInfo4	Obsolete. Superseded by IView.GetDimensionDisplayInfo5 and IView.IGetDimensionDisplayInfo5 .
	IGetDimensionDisplayInfo5	Gets the display dimension information for the current drawing sheet or the current drawing view.
	IGetDimensionDisplayString	Obsolete. Superseded by IView.GetDimensionDisplayString4 and IView.IGetDimensionDisplayString4 .
	IGetDimensionDisplayString2	Obsolete. Superseded by IView.GetDimensionDisplayString4 and IView.IGetDimensionDisplayString4 .
	IGetDimensionDisplayString3	Obsolete. Superseded by IView.GetDimensionDisplayString4 and IView.IGetDimensionDisplayString4 .
	IGetDimensionDisplayString4	Gets all of the dimension text in the current drawing sheet or the current drawing view.
	IGetDimensionIds	Obsolete. Superseded by IView.GetDimensionIds4 and IView.IGetDimensionIds4 .
	IGetDimensionIds2	Obsolete. Superseded by IView.GetDimensionIds4 and IView.IGetDimensionIds4 .
	IGetDimensionIds3	Obsolete. Superseded by IView.GetDimensionIds4 and IView.IGetDimensionIds4 .
	IGetDimensionIds4	Gets the dimension names from the current drawing sheet or the current drawing view.
	IGetDimensionInfo	Obsolete. Superseded by IView.GetDimensionInfo6 and IView.IGetDimensionInfo6 .
	IGetDimensionInfo2	Obsolete. Superseded by IView.GetDimensionInfo6 and IView.IGetDimensionInfo6 .
	IGetDimensionInfo3	Obsolete. Superseded by IView.GetDimensionInfo6 and IView.IGetDimensionInfo6 .
	IGetDimensionInfo4	Obsolete. Superseded by IView.GetDimensionInfo6 and IView.IGetDimensionInfo6 .
	IGetDimensionInfo5	Obsolete. Superseded by IView.GetDimensionInfo6 and IView.IGetDimensionInfo6 .
	IGetDimensionInfo6	Obsolete. Superseded by IView.GetDimensionInfo7 .
	IGetDimensionString	Obsolete. Superseded by IView.GetDimensionString4 and IView.IGetDimensionString4 .
	IGetDimensionString2	Obsolete. Superseded by IView.GetDimensionString4 and IView.IGetDimensionString4 .
	IGetDimensionString3	Obsolete. Superseded by IView.GetDimensionString4 and IView.IGetDimensionString4 .
	IGetDimensionString4	Gets the strings containing the text associated with each dimension in the current drawing sheet or the current drawing view.
	IGetDisplayData	Obsolete. Superseded by IView.GetDisplayData3 and IView.IGetDisplayData3 .
	IGetDisplayData2	Obsolete. Superseded by IView.GetDisplayData3 and IView.IGetDisplayData3 .
	IGetDisplayData3	Gets the the IDisplayData object for this drawing view containing only those model items that are visible in the view.
	IGetDisplayDimensions	Gets all of the display dimensions on this drawing view.
	IGetDowelSymbols	Gets all of the dowel symbols on this drawing view.
	IGetEllipses	Obsolete. Superseded by IView.GetEllipses5 and IView.IGetEllipses5 .
	IGetEllipses2	Obsolete. Superseded by IView.GetEllipses5 and IView.IGetEllipses5 .
	IGetEllipses3	Obsolete. Superseded by IView.GetEllipses5 and IView.IGetEllipses5 .
	IGetEllipses4	Obsolete. Superseded by IView.GetEllipses5 and IView.IGetEllipses5 .
	IGetEllipses5	Gets all of the ellipses added by a user in this drawing view.
	IGetFaceHatches	Gets the face hatches in the view.
	IGetFirstAnnotation	Obsolete. Superseded by IView.GetFirstAnnotation3 .

		
	IGetFirstAnnotation2	Obsolete. Superseded by IView.GetFirstAnnotation3 .
	IGetFirstCenterOfMass	Gets the first center of mass in this view.
	IGetFirstCThread	Gets the first cosmetic thread in the view.
	IGetFirstCustomSymbol	Obsolete. Not superseded.
	IGetFirstDatumTag	Gets the first datum tag in the view.
	IGetFirstDatumTargetSym	Gets the first datum target symbol in the view.
	IGetFirstDisplayDimension	Obsolete. Superseded by IView.GetFirstDisplayDimension5 .
	IGetFirstDisplayDimension2	Obsolete. Superseded by IView.GetFirstDisplayDimension5 .
	IGetFirstDisplayDimension3	Obsolete. Superseded by IView.GetFirstDisplayDimension5 .
	IGetFirstDowelSymbol	Gets the first dowel symbol in the view.
	IGetFirstGTOL	Gets the first geometric tolerance in this view.
	IGetFirstMultiJogLeader	Gets the first multi-jog leader in the view.
	IGetFirstNote	Gets the first note in the view.
	IGetFirstRevisionCloud	Gets the first revision cloud annotation in this view.
	IGetFirstSFSymbol	Gets the first surface-finish symbols in the view.
	IGetFirstWeldSymbol	Gets the first weld symbol in the view.
	IGetGTols	Gets all of the geometric tolerances on this drawing view.
	IGetLines	Obsolete. Superseded by IView.GetLines4 and IView.IGetLines4 .
	IGetLines2	Obsolete. Superseded by IView.GetLines4 and IView.IGetLines4 .
	IGetLines3	Obsolete. Superseded by IView.GetLines4 and IView.IGetLines4 .
	IGetLines4	Gets all of the lines in the view with an option to include or exclude crosshatch lines.
	IGetMultiJogLeaders	Gets all of the multi-jog leaders in this drawing view.
	IGetNextView	Gets the next drawing view in the drawing.
	IGetNotes	Gets the notes in this drawing view.
	IGetOutline	Gets the bounding box for a view (sheet or drawing) in meters on the drawing page.
	IGetParabolas	Obsolete. Superseded by IView.GetParabolas2 and IView.IGetParabolas2 .
	IGetParabolas2	Gets all of the information about all of the parabolas in this view.
	IGetPolylines	Obsolete. Superseded by IView.GetPolyLines6 and IView.IGetPolyLines6 .
	IGetPolylines2	Obsolete. Superseded by IView.GetPolyLines6 and IView.IGetPolyLines6 .
	IGetPolylines3	Obsolete. Superseded by IView.GetPolyLines6 and IView.IGetPolyLines6 .
	IGetPolylines4	Obsolete. Superseded by IView.GetPolyLines6 and IView.IGetPolyLines6 .
	IGetPolylines5	Obsolete. Superseded by IView.GetPolyLines6 and IView.IGetPolyLines6 .
	IGetPolylines6	Obsolete. Superseded by IView.IGetPolylines7 .
	IGetPolylines7	Gets all of the polylines in the view with an option to include or exclude crosshatch lines
	IGetPolyLinesAndCurves	Gets the arcs, ellipses, splines, and polylines in the view with an option to include or exclude crosshatch lines.
	IGetProjectionArrow	Gets the projection arrow for this projected view.
	IGetProjectionLines	Gets the projection lines (arrows) in this drawing view.
	IGetRelatedTangentEdges	Gets the visible tangent edges for the specified bendline in a flat-pattern drawing view .
	IGetRevisionClouds	Gets all of the revision cloud annotations in this view.
	IGetSection	Gets the section for this section view.
	IGetSectionLineInfo	Obsolete. Superseded by IView.GetSectionLineInfo2 and IView.IGetSectionLineInfo2 .
	IGetSectionLineInfo2	Gets all of the information about the section lines in the view.

		
	IGetSectionLines	Gets the section lines in the view.
	IGetSectionLineStrings	Gets an array of strings; each string represents the text label for a section line in this view.
	IGetSFSymbols	Gets all of the surface finish symbols in this drawing view.
	IGetSketch	Gets the sketch used by this view.
	IGetSketchPictures	Gets all of the sketch pictures imported to this view when a drawing is created from a part.
	IGetSMBoundingBoxDisplayData	Gets the boundary-box sketch display data of a flat-pattern drawing view.
	IGetSolidHatchInfo	Gets the boundary data for all visible solid-fill hatches in a detail, break, or crop view.
	IGetSplines	Obsolete. Superseded by IView.GetSplines3 and IView.IGetSplines3 .
	IGetSplines2	Obsolete. Superseded by IView.GetSplines3 and IView.IGetSplines3 .
	IGetSplines3	Gets all of the splines added by a user in the drawing view.
	IGetTableAnnotations	Gets all of the table annotations in this drawing view.
	IGetTemporaryAxes	Gets the information of the temporary axes displayed in this view.
	IGetUserPoints	Obsolete. Superseded by IView.GetUserPoints2 and IView.IGetUserPoints2 .
	IGetUserPoints2	Gets all of the information about all of the user points in this view.
	IGetViewXform	Gets the transform from model space origin to drawing space origin.
	IGetVisibleComponents	Gets the visible components in this drawing view.
	IGetVisibleEntities	Obsolete. Superseded by IView.IGetVisibleEntities2 .
	IGetVisibleEntities2	Gets the visible entities of the specified type for the specified component in this drawing view.
	IGetWeldBeads	Gets all of the weld beads on this drawing view.
	IGetWeldSymbols	Gets all of the weld symbols on this drawing view.
	IGetWitnessGeomInfo	Gets the geometry data for all of the virtual sharp witness lines in this drawing view.
	IGetXform	Gets the matrix used for displaying this drawing view.
	InsertBomTable	Inserts a Bill of Materials (BOM) table for this drawing view using Microsoft Excel.
	ImportAnnotations	Imports the specified annotations into this drawing view.
	InsertAlternateView	Inserts an Alternate Position View of the currently selected drawing view.
	InsertBendTable	Inserts a bend table for this drawing view.
	InsertBomTable	Inserts a Bill of Materials (BOM) table for this drawing view using Microsoft Excel.
	InsertBomTable2	Obsolete. Superseded by IView.InsertBomTable3 .
	InsertBomTable3	Obsolete. Superseded by IView.InsertBomTable4 .
	InsertBomTable4	Obsolete. Superseded by IView.InsertBomTable5 .
	InsertBomTable5	Obsolete. Superseded by IView.InsertBomTable6 .
	InsertBomTable6	Inserts a bill of materials (BOM) table for this drawing view using SOLIDWORKS table functionality.
	InsertBreak	Obsolete. Superseded by IView.InsertBreak2 .
	InsertBreak2	Obsolete. Superseded by IView.InsertBreak3 .
	InsertBreak3	Inserts the specified type of break at the specified location in this drawing view.
	InsertCutListPropertyNote	Inserts a note that contains all of the cut list item properties of a sheet metal part.
	InsertHoleTable	Obsolete. Superseded by IView.InsertHoleTable2 .
	InsertHoleTable2	Obsolete. Superseded by IView.InsertHoleTable3 .
	InsertHoleTable3	Inserts a hole table in this drawing view.
	InsertPunchTable	Inserts a punch table in the flat pattern drawing view of a sheet metal part.
	InsertViewAsBlock	Creates a sketch block from this view and aligns the specified manipulator point with the specified sketch block position on the drawing sheet.
	InsertWeldmentTable	Inserts a weldment cut-list table into this drawing view.

		
	InsertWeldTable	Inserts a weld table into this drawing view.
	IsBroken	Gets whether the drawing view is displayed with a break.
	IsCropped	Get whether this drawing view is cropped.
	ISelectEntity	Selects an entity in this drawing view.
	ISetBodies	Sets the bodies of a multibody part to include in the view.
	ISetXform	Sets the matrix used for display of this drawing view.
	IsExploded	Gets whether the drawing view is currently showing the assembly as exploded or collapsed.
	IsFlatPatternView	Gets whether a drawing view is a flat-pattern drawing view.
	IsLightweight	Gets whether the drawing view is lightweight.
	IsModelBreakState	Gets whether this drawing view is a Model Break View.
	IsModelLoaded	Gets whether the model is loaded in this drawing view.
	IsModelOutOfDate	Gets whether the model in this drawing view is up-to-date with the current model.
	IsPerspectiveView	Gets whether this drawing view is showing a perspective view of the model.
	LoadModel	Loads the model if the model has not already been loaded for this drawing view.
	MergeBendTags	Merges or unmerges bend tags in drawings of sheet metal parts.
	RemoveAlignment	Removes the alignment from this drawing view.
	ReplaceViewWithBlock	Converts this view into a sketch block with the specified manipulator location.
	ReplaceViewWithSketch	Converts this view into a sketch.
	ResetSketchVisibility	Resets the visibility of the sketches in the drawing view so that the drawing view reflects the model.
	SelectEntity	Selects an entity in this drawing view.
	SetBendNoteTextFormat	Sets the text format of all bend notes in this drawing view of a sheet metal part.
	SetDisplayMode	Obsolete. Superseded by IView.SetDisplayMode3 .
	SetDisplayMode2	Obsolete. Superseded by IView.SetDisplayMode3 .
	SetDisplayMode3	Obsolete. Superseded by IView.SetDisplayMode4 .
	SetDisplayMode4	Sets the display mode of this drawing view.
	SetDisplayTangentEdges	Obsolete. Superseded by IView.SetDisplayTangentEdges2 .
	SetDisplayTangentEdges2	Sets the tangent edge display mode of the drawing view.
	SetKeepLinkedToBOM	Sets whether this drawing view is linked to the specified BOM or weldment cut-list table.
	SetLightweightToResolved	Changes the drawing view from lightweight to resolved.
	SetMirrorViewOrientation	Sets whether to mirror this view.
	SetName2	Sets the name of this drawing view, as displayed in the FeatureManager design tree.
	SetResolvedToLightweight	Changes the drawing view from resolved to lightweight.
	SetViewPosition	Moves this drawing view.
	SetVisible	Sets the visibility of this drawing view.
	SetXform	Sets the matrix used for display of this drawing view.
	ShowExploded	Shows an exploded assembly in this drawing view.
	ShowModelBreakState	Sets whether to display the specified Model Break View.
	UpdateViewDisplayGeometry	Updates the displayed geometry for a drawing view.
	UseDefaultAlignment	Restores the default alignment for this drawing view.

[Top](#)

IView Interface Members

[See Also](#) [Properties](#) [Methods](#)

[SolidWorks.Interop.sldworks Namespace](#) : IView Interface

The following tables list the members exposed by [IView](#).

Public Properties

Name	Description
 Angle	Gets or sets the rotation angle of the view.
 Bodies	Gets or sets the bodies of a multibody part to show in the drawing view.
 BreakLineGap	Gets or sets the width of the gap for a break line.
 CropViewJaggedOutline	Gets or sets whether to use a jagged outline in this cropped drawing view.
 CropViewJaggedShapeIntensity	Gets or sets the shape intensity of the jagged outline in this cropped drawing view.
 CropViewNoOutline	Gets or sets whether to show an outline in this cropped drawing view.
 DisableAutoUpdate	Gets or sets whether to disable the automatic update of this view.
 DisplayState	Gets or sets the name of the display state for this drawing view.
 EmphasizeOutline	Gets or sets whether the outlines of section views are emphasized in this drawing view.
 FlipView	Gets or sets whether to flip a flat-pattern view of a sheet metal part.
 FocusLocked	Gets or sets whether or not focus is locked on this view.
 HiddenEdges	Gets the hidden edges in the drawing view or sets the hidden edges in the drawing view to be visible.
 IPosition	Gets or sets the X and Y location of the model view's geometric center, relative to the drawing sheet origin.
 IScaleRatio	Gets or sets the scale of the drawing view, returning the results in ratio format (n:n).
 LinkParentConfiguration	Gets or sets whether to link a projected or auxiliary view with the parent configuration.
 ModelToViewTransform	Gets the math transform to go from model to drawing view space. NOTE: This property is a get-only property. Set is not implemented.
 Name	Obsolete. Superseded by IView::GetName2 and IView::SetName2
 Position	Gets or sets the X and Y location of the model view's geometric center, relative to the drawing sheet origin.
 PositionLocked	Gets or sets whether this drawing view's position is locked.
 ProjectedDimensions	Gets or sets whether dimensions in this view are true or projected.
 ReferencedConfiguration	Gets or sets the configuration referenced by this drawing view.
 ReferencedConfigurationID	Gets the persistent reference ID of the configuration referenced in this drawing view.
 ReferencedDocument	Gets the document referenced by this drawing view.
 RootDrawingComponent	Obsolete. Superseded by IView::RootDrawingComponent2 .
 RootDrawingComponent2	Gets the root component of this drawing view.
 ScaleDecimal	Gets or sets the scale of the drawing view, returning the results in decimal format.
 ScaleHatchPattern	Gets or sets whether to scale the hatch pattern to the drawing view.
 ScaleRatio	Gets or sets the scale of the drawing view, returning the results in ratio format (n:n).
 Sheet	Gets the sheet on which this drawing view exists.
 ShowSheetMetalBendNotes	Gets or sets whether to show sheet metal bend notes.
 SuppressState	Gets or sets the view suppress state.
 Type	Gets the drawing view type.
UseParentScale	Gets or sets the drawing view's scale to match the parent drawing view's scale.



[UseSheetScale](#)

Gets or sets whether the scale of the drawing view is the same as the scale of the drawing sheet on which this view is located.

[Top](#)

Public Methods

Name	Description
 AlignDrawingView	Specifies the alignment of this auxiliary drawing view.
 AlignWithView	Sets view alignment.
 AutoInsertCenterMarks	Obsolete. Superseded by IView.AutoInsertCenterMarks2 .
 AutoInsertCenterMarks2	Automatically inserts the specified center marks in this view.
 Crop	Obsolete. Superseded by IView.Crop2 .
 Crop2	Crops this view using the selected closed sketch profile.
 EnumHiddenComponents	Obsolete. Superseded by IView.EnumHiddenComponents2 .
 EnumHiddenComponents2	Gets the hidden components enumeration in this drawing view.
 EnumSectionLines	Obsolete. Superseded by IView.EnumSectionLines2 .
 EnumSectionLines2	Gets the section lines enumeration in the view.
 GetAlignment	Gets the alignment information of this view.
 GetAnnotationCount	Gets the number of annotations in this view.
 GetAnnotations	Gets the annotations in this view.
 GetAnnotationsByType	Gets the annotations of the specified type in this view.
 GetArcCount	Gets the number of arcs in this view.
 GetArcs	Obsolete. Superseded by IView.GetArcs4 and IView.IGetArcs4 .
 GetArcs2	Obsolete. Superseded by IView.GetArcs4 and IView.IGetArcs4 .
 GetArcs3	Obsolete. Superseded by IView.GetArcs4 and IView.IGetArcs4 .
 GetArcs4	Gets all of the information for all of the arcs added by a user in this drawing view.
 GetBaseView	Gets the base (parent) view used to create this view.
 GetBendLineCount	Gets the number of bendlines in a flat-pattern drawing view .
 GetBendLines	Gets the bendlines in a flat-pattern drawing view .
 GetBendNoteAttributeString	Gets the internal string that is used to format the text of the specified bend note attribute in this drawing view of a sheet metal part.
 GetBendNoteTextFormat	Gets the text format of all bend notes in this drawing view of a sheet metal part.
 GetBodiesCount	Gets the number of bodies of a multibody part in the drawing view.
 GetBomTable	Gets the BOM table found in this drawing view.
 GetBreakLineCount	Obsolete. Superseded by IView.GetBreakLineCount2 .
 GetBreakLineCount2	Gets the number of breaks lines and breaks in this view.
 GetBreakLineInfo	Obsolete. Superseded by IView.GetBreakLineInfo2 .
 GetBreakLineInfo2	Gets information for all of the break lines in this view.
 GetBreakLines	Gets the all of the breaks in this view.
 GetBreakOutSectionCount	Gets the number of broken-out sections in this view.
 GetBreakOutSections	Gets all of the broken-out sections in this view.
 GetCenterLineCount	Gets the number of centerlines on this drawing view.
 GetCenterLines	Gets all of the centerline annotations on this drawing view.
 GetCenterLineSketch	Gets the sketch that contains all of the centerline information for this view.
 GetCenterMarkCount	Obsolete. Superseded by IView.GetCenterMarkCount2 .

	GetCenterMarkCount2	Gets the number of center marks that are features in the view.
	GetCenterMarkInfo	Gets information about each center mark that is a feature in the view.
	GetCenterMarks	Gets all of the center marks that are features in the view.
	GetCorresponding	Gets the object in this drawing view that corresponds to the specified part or assembly object.
	GetCorrespondingEntity	Gets the entity in this drawing view that corresponds to the specified part or assembly entity.
	GetCThreadCount	Gets the number of cosmetic threads in this drawing view.
	GetCThreadQuality	Gets the cosmetic thread display quality in this view.
	GetCThreads	Gets all of the cosmetic threads on this drawing view.
	GetDatumOriginCount	Gets the number of datum origins on this drawing view.
	GetDatumOrigins	Gets all of the datum origins on this drawing view.
	GetDatumPoints	Obsolete. Superseded by IView.GetDatumPoints2 and IView.IGetDatumPoints2 .
	GetDatumPoints2	Gets all of the information about all the datum points in this view.
	GetDatumPointsCount	Gets the number of datum points in this view.
	GetDatumTagCount	Gets the number of datum tags on this drawing view.
	GetDatumTags	Gets all of the datum tags on this drawing view.
	GetDatumTargetSymCount	Gets the number of datum target symbols on this drawing view.
	GetDatumTargetSyms	Gets all of the datum target symbols on this drawing view.
	GetDependentViewCount	Gets the number of all, or only the specified, dependent views (i.e., alternate position, detail, section, etc.) in this view.
	GetDependentViews	Gets either all, or only the specified, dependent views in this view.
	GetDesignTableExtent	Gets the size and location of the design table associated with this drawing view.
	GetDetail	Gets the detail circle for this detail view.
	GetDetailCircleCount	Obsolete. Superseded by IView.GetDetailCircleCount2 .
	GetDetailCircleCount2	Gets the number of detail circles in the drawing view.
	GetDetailCircleInfo	Obsolete. Superseded by IView.GetDetailCircleInfo2 and IView.IGetDetailCircleInfo2 .
	GetDetailCircleInfo2	Gets all of the information about each detail circle in the view.
	GetDetailCircles	Gets the detail circles in this view.
	GetDetailCircleStrings	Gets an array of strings; each string represents the text label for a detail circle in this view.
	GetDimensionCount	Obsolete. Superseded by IView.GetDimensionCount4 .
	GetDimensionCount2	Obsolete. Superseded by IView.GetDimensionCount4 .
	GetDimensionCount3	Obsolete. Superseded by IView.GetDimensionCount4 .
	GetDimensionCount4	Gets the number of display dimensions in the current drawing sheet or the current drawing view.
	GetDimensionDisplayInfo	Obsolete. Superseded by IView.GetDimensionDisplayInfo5 and IView.IGetDimensionDisplayInfo5 .
	GetDimensionDisplayInfo2	Obsolete. Superseded by IView.GetDimensionDisplayInfo5 and IView.IGetDimensionDisplayInfo5 .
	GetDimensionDisplayInfo3	Obsolete. Superseded by IView.GetDimensionDisplayInfo5 and IView.IGetDimensionDisplayInfo5 .
	GetDimensionDisplayInfo4	Obsolete. Superseded by IView.GetDimensionDisplayInfo5 and IView.IGetDimensionDisplayInfo5 .
	GetDimensionDisplayInfo5	Gets the display dimension information for the current drawing sheet or the current drawing view.
	GetDimensionDisplayInfoSize	Obsolete. Superseded by IView.GetDimensionDisplayInfoSize2 .
	GetDimensionDisplayInfoSize2	Gets the number of the dimension lines n the current drawing sheet or the current drawing view.
	GetDimensionDisplayString	Obsolete. Superseded by IView.GetDimensionDisplayString4 and IView.IGetDimensionDisplayString4 .
	GetDimensionDisplayString2	Obsolete. Superseded by IView.GetDimensionDisplayString4 and IView.IGetDimensionDisplayString4 .
	GetDimensionDisplayString3	Obsolete. Superseded by IView.GetDimensionDisplayString4 and IView.IGetDimensionDisplayString4 .
	GetDimensionDisplayString4	Obsolete. Superseded by IView.GetDimensionDisplayString5 .
	GetDimensionDisplayString5	Gets all of the dimension text in the current drawing sheet or the current drawing view.

		
	GetDimensionIds	Obsolete. Superseded by IView.GetDimensionIds4 and IView.IGetDimensionIds4 .
	GetDimensionIds2	Obsolete. Superseded by IView.GetDimensionIds4 and IView.IGetDimensionIds4 .
	GetDimensionIds3	Obsolete. Superseded by IView.GetDimensionIds4 and IView.IGetDimensionIds4 .
	GetDimensionIds4	Gets the dimension names from the current drawing sheet or the current drawing view.
	GetDimensionInfo	Obsolete. Superseded by IView.GetDimensionInfo6 and IView.IGetDimensionInfo6 .
	GetDimensionInfo2	Obsolete. Superseded by IView.GetDimensionInfo6 and IView.IGetDimensionInfo6 .
	GetDimensionInfo3	Obsolete. Superseded by IView.GetDimensionInfo6 and IView.IGetDimensionInfo6 .
	GetDimensionInfo4	Obsolete. Superseded by IView.GetDimensionInfo6 and IView.IGetDimensionInfo6 .
	GetDimensionInfo5	Obsolete. Superseded by IView.GetDimensionInfo6 and IView.IGetDimensionInfo6 .
	GetDimensionInfo6	Obsolete. Superseded by IView.GetDimensionInfo7 .
	GetDimensionInfo7	Gets all of the dimension information in the current drawing sheet or the current drawing view.
	GetDimensionString	Obsolete. Superseded by IView.GetDimensionString4 and IView.IGetDimensionString4 .
	GetDimensionString2	Obsolete. Superseded by IView.GetDimensionString4 and IView.IGetDimensionString4 .
	GetDimensionString3	Obsolete. Superseded by IView.GetDimensionString4 and IView.IGetDimensionString4 .
	GetDimensionString4	Gets the strings containing the text associated with each dimension in the current drawing sheet or the current drawing view.
	GetDisplayData	Obsolete. Superseded by IView.GetDisplayData3 and IView.IGetDisplayData3 .
	GetDisplayData2	Obsolete. Superseded by IView.GetDisplayData3 and IView.IGetDisplayData3 .
	GetDisplayData3	Obsolete. Superseded by IView.GetDisplayData4 .
	GetDisplayData4	Gets the the IDisplayData object for this drawing view containing only those model items that are visible in the view.
	GetDisplayDimensionCount	Gets the number of display dimensions in this drawing view.
	GetDisplayDimensions	Gets all of the display dimension on this drawing view.
	GetDisplayEdgesInShadedMode	Gets whether to display the edges in this when the drawing view is in shaded mode.
	GetDisplayMode	Obsolete. Superseded by IView.GetDisplayMode2 .
	GetDisplayMode2	Gets the current display mode of the view.
	GetDisplayTangentEdges	Obsolete. Superseded by IView.GetDisplayTangentEdges2 .
	GetDisplayTangentEdges2	Gets the current tangent edge display mode of the drawing view.
	GetDowelSymbolCount	Gets the number of dowel symbols in this drawing view.
	GetDowelSymbols	Gets all of the dowel symbols on this drawing view.
	GetEllipseCount	Gets the number of ellipses in the view.
	GetEllipses	Obsolete. Superseded by IView.GetEllipses5 and IView.IGetEllipses5 .
	GetEllipses2	Obsolete. Superseded by IView.GetEllipses5 and IView.IGetEllipses5 .
	GetEllipses3	Obsolete. Superseded by IView.GetEllipses5 and IView.IGetEllipses5 .
	GetEllipses4	Obsolete. Superseded by IView.GetEllipses5 and IView.IGetEllipses5 .
	GetEllipses5	Gets all of the ellipses added by a user in this drawing view.
	GetFaceHatchCount	Gets the number of face hatches in the view.
	GetFaceHatches	Gets the face hatches in the view.
	GetFacettedHlrDisplay	Gets whether HLR/HLV (Hidden Lines Removed/Hidden Lines Visible) edges should be displayed faceted in the view.
	GetFirstAnnotation	Obsolete. Superseded by IView.GetFirstAnnotation3 .
	GetFirstAnnotation2	Obsolete. Superseded by IView.GetFirstAnnotation3 .
	GetFirstAnnotation3	Gets the first annotation in this drawing view.
	GetFirstBlockInstance	Obsolete. Not superseded.
	GetFirstCenterLine	Gets the first centerline in this view.

		
	GetFirstCenterMark	Obsolete. Superseded by IView.GetFirstCenterMark2 .
	GetFirstCenterMark2	Gets the first center mark in the view.
	GetFirstCenterOfMass	Gets the first center of mass in this view.
	GetFirstCThread	Gets the first cosmetic thread in the view.
	GetFirstCustomSymbol	Obsolete. Not superseded.
	GetFirstDatumOrigin	Gets the first datum origin in this drawing view.
	GetFirstDatumTag	Gets the first datum tag in the view.
	GetFirstDatumTargetSym	Gets the first datum target symbol in the view.
	GetFirstDisplayDimension	Obsolete. Superseded by IView.GetFirstDisplayDimension5 .
	GetFirstDisplayDimension2	Obsolete. Superseded by IView.GetFirstDisplayDimension5 .
	GetFirstDisplayDimension3	Obsolete. Superseded by IView.GetFirstDisplayDimension5 .
	GetFirstDisplayDimension4	Obsolete. Superseded by IView.GetFirstDisplayDimension5 .
	GetFirstDisplayDimension5	Obsolete. Superseded by IView.GetFirstDisplayDimension6 .
	GetFirstDisplayDimension6	Gets the first display dimension in this drawing view.
	GetFirstDowelSymbol	Gets the first dowel symbol in the view.
	GetFirstGTOL	Gets the first geometric tolerance in this view.
	GetFirstMultiJogLeader	Obsolete. Superseded by IView.GetFirstMultiJogLeader2 .
	GetFirstMultiJogLeader2	Gets the first multi-jog leader in the view.
	GetFirstNote	Obsolete. Superseded by IView.GetFirstNote2 .
	GetFirstNote2	Gets the first note in the view.
	GetFirstRevisionCloud	Obsolete. Superseded by IView.GetFirstRevisionCloud2 .
	GetFirstRevisionCloud2	Gets the first revision cloud annotation in this view.
	GetFirstSFSymbol	Gets the first surface-finish symbols in the view.
	GetFirstTableAnnotation	Obsolete. Superseded by IView.GetFirstTableAnnotation2 .
	GetFirstTableAnnotation2	Gets the first table annotation in this view.
	GetFirstWeldBead	Gets the first weld bead annotation in this view.
	GetFirstWeldSymbol	Gets the first weld symbol in the view.
	GetGTolCount	Gets the number of geometric tolerances in this drawing view.
	GetGTols	Gets all of the geometric tolerances on this drawing view.
	GetHiddenComponents	Gets the hidden components in this drawing view.
	GetKeepLinkedToBOM	Gets whether this drawing view is linked to a BOM or weldment cut-list table.
	GetKeepLinkedToBOMName	Gets the name of the BOM or weldment cut-list table feature to which this drawing view is linked.
	GetLineCount	Obsolete. Superseded by IView.GetLineCount2 .
	GetLineCount2	Gets the number of lines in this view with an option to include or exclude crosshatch lines.
	GetLines	Obsolete. Superseded by IView.GetLines4 and IView.IGetLines4 .
	GetLines2	Obsolete. Superseded by IView.GetLines4 and IView.IGetLines4 .
	GetLines3	Obsolete. Superseded by IView.GetLines4 and IView.IGetLines4 .
	GetLines4	Gets all of the lines in the view with an option to include or exclude crosshatch lines.
	GetMirrorViewOrientation	Gets whether this view is mirrored.
	GetMultiJogLeaderCount	Gets the number of multi-jog leaders on this drawing view.
	GetMultiJogLeaders	Gets all of the multi-jog leaders in this drawing view.
	GetName2	Gets the name of this drawing view displayed in the FeatureManager design tree.

		
	GetNextView	Gets the next drawing view in the drawing.
	GetNoteCount	Gets the number notes in this drawing view.
	GetNotes	Gets the notes in this drawing view.
	GetOrientationName	Gets the predefined name of this view.
	GetOutline	Gets the bounding box for a view (sheet or drawing) in meters on the drawing page.
	GetParabolaCount	Gets the number of parabolas in the view.
	GetParabolas	Obsolete. Superseded by IView.GetParabolas2 and IView.IGetParabolas2
	GetParabolas2	Gets all of the information about all of the parabolas in this view.
	GetPolyLineCount	Obsolete. Superseded by IView.GetPolyLineCount5
	GetPolyLineCount2	Obsolete. Superseded by IView.GetPolyLineCount5
	GetPolyLineCount3	Obsolete. Superseded by IView.GetPolyLineCount5
	GetPolyLineCount4	Obsolete. Superseded by IView.GetPolyLineCount5
	GetPolyLineCount5	Gets the number of polylines in this view with an option to include or exclude crosshatch lines.
	GetPolylines	Obsolete. Superseded by IView.GetPolyLines6 and IView.IGetPolyLines6
	GetPolylines2	Obsolete. Superseded by IView.GetPolyLines6 and IView.IGetPolyLines6
	GetPolylines3	Obsolete. Superseded by IView.GetPolyLines6 and IView.IGetPolyLines6
	GetPolylines4	Obsolete. Superseded by IView.GetPolyLines6 and IView.IGetPolyLines6
	GetPolylines5	Obsolete. Superseded by IView.GetPolyLines6 and IView.IGetPolyLines6
	GetPolylines6	Obsolete. Superseded by IView.GetPolylines7
	GetPolylines7	Gets all of the polylines in the view with an option to include or exclude crosshatch lines.
	GetPolyLinesAndCurves	Gets the arcs, ellipses, splines, and polylines in the view with an option to include or exclude crosshatch lines.
	GetPolyLinesAndCurvesCount	Gets the number of lines, including arcs, ellipses, splines, and polylines, in the view with the option to include or exclude cross hatch lines.
	GetProjectionArrow	Gets the projection arrow for this projected view.
	GetProjectionLineCount	Gets the number of projection lines (arrows) in this drawing view.
	GetProjectionLines	Gets the projection lines (arrows) in this drawing view.
	GetReferencedModelName	Gets the name of the model that is referenced in the drawing view.
	GetRelatedTangentEdgeCount	Gets the number of visible tangent edges for the specified bendline in a flat-pattern drawing view .
	GetRelatedTangentEdges	Gets the visible tangent edges for the specified bendline in a flat-pattern drawing view .
	GetRevisionCloudCount	Gets the number of revision cloud annotations in this view.
	GetRevisionClouds	Gets all of the revision cloud annotations in this view.
	GetSection	Gets the section for this section view.
	GetSectionLineCount	Obsolete. Superseded by IView.GetSectionLineCount2
	GetSectionLineCount2	Gets the number of section lines in the view.
	GetSectionLineInfo	Obsolete. Superseded by IView.GetSectionLineInfo2 and IView.GetSectionLineInfo2
	GetSectionLineInfo2	Gets all of the information about the section lines in the view.
	GetSectionLines	Gets the section lines in the view.
	GetSectionLineStrings	Gets an array of strings; each string represents the text label for a section line in this view.
	GetSFSymbolCount	Gets the number of surface finish symbols on this drawing view.
	GetSFSymbols	Gets all of the surface finish symbols in this drawing view.
	GetSketch	Gets the sketch used by this view.
	GetSketchPictureCount	Gets the number of sketch pictures imported to this view when a drawing is created from a part.
	GetSketchPictures	Gets all of the sketch pictures imported to this view when a drawing is created from a part.

		
	GetSMBoundaryBoxDisplayData	Obsolete. Superseded by IView.GetSMBoundaryBoxDisplayData2 .
	GetSMBoundaryBoxDisplayData2	Gets the boundary-box sketch display data of a flat-pattern drawing view.
	GetSolidHatchCount	Gets the number of visible solid-fill hatches in a detail, break, or crop view and the size of the array for their boundary data.
	GetSolidHatchInfo	Gets the boundary data for all visible solid-fill hatches in a detail, break, or crop view.
	GetSplineCount	Gets the number of splines in the view.
	GetSplines	Obsolete. Superseded by IView.GetSplines3 and IView.IGetSplines3 .
	GetSplines2	Obsolete. Superseded by IView.GetSplines3 and IView.IGetSplines3 .
	GetSplines3	Gets all of the splines added by a user in the drawing view.
	GetTableAnnotationCount	Gets the number of table annotations in this drawing view.
	GetTableAnnotations	Gets all of the table annotations on this drawing view.
	GetTemporaryAxes	Gets the information of the temporary axes displayed in this view.
	GetTemporaryAxesCount	Gets the number of temporary axes in this view.
	GetUniqueName	Gets the unique name of this section view.
	GetUseParentDisplayMode	Gets whether the view is using its parent settings or if it is using its own local settings.
	GetUserPoints	Obsolete. Superseded by IView.GetUserPoints2 and IView.IGetUserPoints2 .
	GetUserPoints2	Gets all of the information about all of the user points in this view.
	GetUserPointsCount	Gets the number of user points in the view.
	GetViewXform	Gets the transform from model space origin to drawing space origin.
	GetVisible	Gets the visibility of this drawing view.
	GetVisibleComponentCount	Gets the number of visible components in this drawing view.
	GetVisibleComponents	Gets the visible components in this drawing view.
	GetVisibleDrawingComponents	Gets all of the unobscured drawing components in this drawing view of an assembly drawing.
	GetVisibleEntities	Obsolete. Superseded by IView.GetVisibleEntities2 .
	GetVisibleEntities2	Gets the visible entities of the specified type for the specified component in this drawing view.
	GetVisibleEntityCount	Obsolete. Superseded by IView.GetVisibleEntityCount2 .
	GetVisibleEntityCount2	Gets the number of visible entities of the specified type for the specified component in this drawing view.
	GetWeldBeadCount	Gets the number of weld beads on this drawing view.
	GetWeldBeads	Gets all of the weld beads on this drawing view.
	GetWeldSymbolCount	Gets the number of weld symbols on this drawing view.
	GetWeldSymbols	Gets all of the weld symbols on this drawing view.
	GetWitnessEntitiesCount	Gets the number of virtual sharp witness lines in this drawing view.
	GetWitnessGeomInfo	Gets the geometry data for all of the virtual sharp witness lines in this drawing view.
	GetXform	Gets the matrix used for displaying this drawing view.
	HasDesignTable	Gets whether this drawing view has a design table associated with it.
	IGetAnnotations	Gets the annotations in this view.
	IGetArcs	Obsolete. Superseded by IView.GetArcs4 and IView.IGetArcs4 .
	IGetArcs2	Obsolete. Superseded by IView.GetArcs4 and IView.IGetArcs4 .
	IGetArcs3	Obsolete. Superseded by IView.GetArcs4 and IView.IGetArcs4 .
	IGetArcs4	Gets all of the information for all of the arcs added by a user in this drawing view.
	IGetBaseView	Gets the base (parent) view used to create this view.
	IGetBendLines	Gets the bendlines in a flat-pattern drawing view .
	IGetBodies	Gets the bodies of a multibody part in the drawing view.

		
	IGetBomTable	Gets the BOM table found in this drawing view.
	IGetBreakLineInfo	Obsolete. Superseded by IView.IGetBreakLineInfo2 .
	IGetBreakLineInfo2	Gets information for all of the break lines in this view.
	IGetBreakLines	Gets the all of the breaks in this view.
	IGetBreakOutSections	Gets all of the broken-out sections in this view.
	IGetCenterLines	Gets all of the centerlines on this drawing view.
	IGetCenterMarkInfo	Gets information about each center mark that is a feature in the view.
	IGetCenterMarks	Gets all of the center marks that are features in the view.
	IGetCThreads	Gets all of the cosmetic threads on this drawing view.
	IGetDatumOrigins	Gets all of the datum origins on this drawing view.
	IGetDatumPoints	Obsolete. Superseded by IView.GetDatumPoints2 and IView.IGetDatumPoints2 .
	IGetDatumPoints2	Gets all of the information about all the datum points in this view.
	IGetDatumTags	Gets all the datum tags on this drawing view.
	IGetDatumTargetSyms	Gets all of the datum target symbols on this drawing view.
	IGetDependentViews	Gets either all, or only the specified, dependent views in this view.
	IGetDesignTableExtent	Gets the size and location of the design table associated with this drawing view.
	IGetDetail	Gets the detail circle for this detail view.
	IGetDetailCircleInfo	Obsolete. Superseded by IView.GetDetailCircleInfo2 and IView.IGetDetailCircleInfo2 .
	IGetDetailCircleInfo2	Gets all of the information about each detail circle in the view.
	IGetDetailCircles	Gets the detail circles in this view.
	IGetDetailCircleStrings	Gets an array of strings; each string represents the text label for a detail circle in this view.
	IGetDimensionDisplayInfo	Obsolete. Superseded by IView.GetDimensionDisplayInfo5 and IView.IGetDimensionDisplayInfo5 .
	IGetDimensionDisplayInfo2	Obsolete. Superseded by IView.GetDimensionDisplayInfo5 and IView.IGetDimensionDisplayInfo5 .
	IGetDimensionDisplayInfo3	Obsolete. Superseded by IView.GetDimensionDisplayInfo5 and IView.IGetDimensionDisplayInfo5 .
	IGetDimensionDisplayInfo4	Obsolete. Superseded by IView.GetDimensionDisplayInfo5 and IView.IGetDimensionDisplayInfo5 .
	IGetDimensionDisplayInfo5	Gets the display dimension information for the current drawing sheet or the current drawing view.
	IGetDimensionDisplayString	Obsolete. Superseded by IView.GetDimensionDisplayString4 and IView.IGetDimensionDisplayString4 .
	IGetDimensionDisplayString2	Obsolete. Superseded by IView.GetDimensionDisplayString4 and IView.IGetDimensionDisplayString4 .
	IGetDimensionDisplayString3	Obsolete. Superseded by IView.GetDimensionDisplayString4 and IView.IGetDimensionDisplayString4 .
	IGetDimensionDisplayString4	Gets all of the dimension text in the current drawing sheet or the current drawing view.
	IGetDimensionIds	Obsolete. Superseded by IView.GetDimensionIds4 and IView.IGetDimensionIds4 .
	IGetDimensionIds2	Obsolete. Superseded by IView.GetDimensionIds4 and IView.IGetDimensionIds4 .
	IGetDimensionIds3	Obsolete. Superseded by IView.GetDimensionIds4 and IView.IGetDimensionIds4 .
	IGetDimensionIds4	Gets the dimension names from the current drawing sheet or the current drawing view.
	IGetDimensionInfo	Obsolete. Superseded by IView.GetDimensionInfo6 and IView.IGetDimensionInfo6 .
	IGetDimensionInfo2	Obsolete. Superseded by IView.GetDimensionInfo6 and IView.IGetDimensionInfo6 .
	IGetDimensionInfo3	Obsolete. Superseded by IView.GetDimensionInfo6 and IView.IGetDimensionInfo6 .
	IGetDimensionInfo4	Obsolete. Superseded by IView.GetDimensionInfo6 and IView.IGetDimensionInfo6 .
	IGetDimensionInfo5	Obsolete. Superseded by IView.GetDimensionInfo6 and IView.IGetDimensionInfo6 .
	IGetDimensionInfo6	Obsolete. Superseded by IView.GetDimensionInfo7 .
	IGetDimensionString	Obsolete. Superseded by IView.GetDimensionString4 and IView.IGetDimensionString4 .
	IGetDimensionString2	Obsolete. Superseded by IView.GetDimensionString4 and IView.IGetDimensionString4 .

		
	IGetDimensionString3	Obsolete. Superseded by IView.GetDimensionString4 and IView.IGetDimensionString4 .
	IGetDimensionString4	Gets the strings containing the text associated with each dimension in the current drawing sheet or the current drawing view.
	IGetDisplayData	Obsolete. Superseded by IView.GetDisplayData3 and IView.IGetDisplayData3 .
	IGetDisplayData2	Obsolete. Superseded by IView.GetDisplayData3 and IView.IGetDisplayData3 .
	IGetDisplayData3	Gets the the IDisplayData object for this drawing view containing only those model items that are visible in the view.
	IGetDisplayDimensions	Gets all of the display dimensions on this drawing view.
	IGetDowelSymbols	Gets all of the dowel symbols on this drawing view.
	IGetEllipses	Obsolete. Superseded by IView.GetEllipses5 and IView.IGetEllipses5 .
	IGetEllipses2	Obsolete. Superseded by IView.GetEllipses5 and IView.IGetEllipses5 .
	IGetEllipses3	Obsolete. Superseded by IView.GetEllipses5 and IView.IGetEllipses5 .
	IGetEllipses4	Obsolete. Superseded by IView.GetEllipses5 and IView.IGetEllipses5 .
	IGetEllipses5	Gets all of the ellipses added by a user in this drawing view.
	IGetFaceHatches	Gets the face hatches in the view.
	IGetFirstAnnotation	Obsolete. Superseded by IView.GetFirstAnnotation3 .
	IGetFirstAnnotation2	Obsolete. Superseded by IView.GetFirstAnnotation3 .
	IGetFirstCenterOfMass	Gets the first center of mass in this view.
	IGetFirstCThread	Gets the first cosmetic thread in the view.
	IGetFirstCustomSymbol	Obsolete. Not superseded.
	IGetFirstDatumTag	Gets the first datum tag in the view.
	IGetFirstDatumTargetSym	Gets the first datum target symbol in the view.
	IGetFirstDisplayDimension	Obsolete. Superseded by IView.GetFirstDisplayDimension5 .
	IGetFirstDisplayDimension2	Obsolete. Superseded by IView.GetFirstDisplayDimension5 .
	IGetFirstDisplayDimension3	Obsolete. Superseded by IView.GetFirstDisplayDimension5 .
	IGetFirstDowelSymbol	Gets the first dowel symbol in the view.
	IGetFirstGTOL	Gets the first geometric tolerance in this view.
	IGetFirstMultiJogLeader	Gets the first multi-jog leader in the view.
	IGetFirstNote	Gets the first note in the view.
	IGetFirstRevisionCloud	Gets the first revision cloud annotation in this view.
	IGetFirstSFSymbol	Gets the first surface-finish symbols in the view.
	IGetFirstWeldSymbol	Gets the first weld symbol in the view.
	IGetGTols	Gets all of the geometric tolerances on this drawing view.
	IGetLines	Obsolete. Superseded by IView.GetLines4 and IView.IGetLines4 .
	IGetLines2	Obsolete. Superseded by IView.GetLines4 and IView.IGetLines4 .
	IGetLines3	Obsolete. Superseded by IView.GetLines4 and IView.IGetLines4 .
	IGetLines4	Gets all of the lines in the view with an option to include or exclude crosshatch lines.
	IGetMultiJogLeaders	Gets all of the multi-jog leaders in this drawing view.
	IGetNextView	Gets the next drawing view in the drawing.
	IGetNotes	Gets the notes in this drawing view.
	IGetOutline	Gets the bounding box for a view (sheet or drawing) in meters on the drawing page.
	IGetParabolas	Obsolete. Superseded by IView.GetParabolas2 and IView.IGetParabolas2 .
	IGetParabolas2	Gets all of the information about all of the parabolas in this view.
	IGetPolyLines	Obsolete. Superseded by IView.GetPolyLines6 and IView.IGetPolyLines6 .

		
	IGetPolyLines2	Obsolete. Superseded by IView.GetPolyLines6 and IView.IGetPolyLines6 .
	IGetPolyLines3	Obsolete. Superseded by IView.GetPolyLines6 and IView.IGetPolyLines6 .
	IGetPolyLines4	Obsolete. Superseded by IView.GetPolyLines6 and IView.IGetPolyLines6 .
	IGetPolyLines5	Obsolete. Superseded by IView.GetPolyLines6 and IView.IGetPolyLines6 .
	IGetPolyLines6	Obsolete. Superseded by IView.IGetPolyLines7 .
	IGetPolyLines7	Gets all of the polylines in the view with an option to include or exclude crosshatch lines
	IGetPolyLinesAndCurves	Gets the arcs, ellipses, splines, and polylines in the view with an option to include or exclude crosshatch lines.
	IGetProjectionArrow	Gets the projection arrow for this projected view.
	IGetProjectionLines	Gets the projection lines (arrows) in this drawing view.
	IGetRelatedTangentEdges	Gets the visible tangent edges for the specified bendline in a flat-pattern drawing view .
	IGetRevisionClouds	Gets all of the revision cloud annotations in this view.
	IGetSection	Gets the section for this section view.
	IGetSectionLineInfo	Obsolete. Superseded by IView.GetSectionLineInfo2 and IView.IGetSectionLineInfo2 .
	IGetSectionLineInfo2	Gets all of the information about the section lines in the view.
	IGetSectionLines	Gets the section lines in the view.
	IGetSectionLineStrings	Gets an array of strings; each string represents the text label for a section line in this view.
	IGetSFSymbols	Gets all of the surface finish symbols in this drawing view.
	IGetSketch	Gets the sketch used by this view.
	IGetSketchPictures	Gets all of the sketch pictures imported to this view when a drawing is created from a part.
	IGetSMBoundingBoxDisplayData	Gets the boundary-box sketch display data of a flat-pattern drawing view.
	IGetSolidHatchInfo	Gets the boundary data for all visible solid-fill hatches in a detail, break, or crop view.
	IGetSplines	Obsolete. Superseded by IView.GetSplines3 and IView.IGetSplines3 .
	IGetSplines2	Obsolete. Superseded by IView.GetSplines3 and IView.IGetSplines3 .
	IGetSplines3	Gets all of the splines added by a user in the drawing view.
	IGetTableAnnotations	Gets all of the table annotations in this drawing view.
	IGetTemporaryAxes	Gets the information of the temporary axes displayed in this view.
	IGetUserPoints	Obsolete. Superseded by IView.GetUserPoints2 and IView.IGetUserPoints2 .
	IGetUserPoints2	Gets all of the information about all of the user points in this view.
	IGetViewXform	Gets the transform from model space origin to drawing space origin.
	IGetVisibleComponents	Gets the visible components in this drawing view.
	IGetVisibleEntities	Obsolete. Superseded by IView.IGetVisibleEntities2 .
	IGetVisibleEntities2	Gets the visible entities of the specified type for the specified component in this drawing view.
	IGetWeldBeads	Gets all of the weld beads on this drawing view.
	IGetWeldSymbols	Gets all of the weld symbols on this drawing view.
	IGetWitnessGeomInfo	Gets the geometry data for all of the virtual sharp witness lines in this drawing view.
	IGetXform	Gets the matrix used for displaying this drawing view.
	IInsertBomTable	Inserts a Bill of Materials (BOM) table for this drawing view using Microsoft Excel.
	ImportAnnotations	Imports the specified annotations into this drawing view.
	InsertAlternateView	Inserts an Alternate Position View of the currently selected drawing view.
	InsertBendTable	Inserts a bend table for this drawing view.
	InsertBomTable	Inserts a Bill of Materials (BOM) table for this drawing view using Microsoft Excel.
	InsertBomTable2	Obsolete. Superseded by IView.InsertBomTable3 .

		
	InsertBomTable3	Obsolete. Superseded by IView.InsertBomTable4 .
	InsertBomTable4	Obsolete. Superseded by IView.InsertBomTable5 .
	InsertBomTable5	Obsolete. Superseded by IView.InsertBomTable6 .
	InsertBomTable6	Inserts a bill of materials (BOM) table for this drawing view using SOLIDWORKS table functionality.
	InsertBreak	Obsolete. Superseded by IView.InsertBreak2 .
	InsertBreak2	Obsolete. Superseded by IView.InsertBreak3 .
	InsertBreak3	Inserts the specified type of break at the specified location in this drawing view.
	InsertCutListPropertyNote	Inserts a note that contains all of the cut list item properties of a sheet metal part.
	InsertHoleTable	Obsolete. Superseded by IView.InsertHoleTable2 .
	InsertHoleTable2	Obsolete. Superseded by IView.InsertHoleTable3 .
	InsertHoleTable3	Inserts a hole table in this drawing view.
	InsertPunchTable	Inserts a punch table in the flat pattern drawing view of a sheet metal part.
	InsertViewAsBlock	Creates a sketch block from this view and aligns the specified manipulator point with the specified sketch block position on the drawing sheet.
	InsertWeldmentTable	Inserts a weldment cut-list table into this drawing view.
	InsertWeldTable	Inserts a weld table into this drawing view.
	IsBroken	Gets whether the drawing view is displayed with a break.
	IsCropped	Get whether this drawing view is cropped.
	ISelectEntity	Selects an entity in this drawing view.
	ISetBodies	Sets the bodies of a multibody part to include in the view.
	ISetXform	Sets the matrix used for display of this drawing view.
	IsExploded	Gets whether the drawing view is currently showing the assembly as exploded or collapsed.
	IsFlatPatternView	Gets whether a drawing view is a flat-pattern drawing view.
	IsLightweight	Gets whether the drawing view is lightweight.
	IsModelBreakState	Gets whether this drawing view is a Model Break View.
	IsModelLoaded	Gets whether the model is loaded in this drawing view.
	IsModelOutOfDate	Gets whether the model in this drawing view is up-to-date with the current model.
	IsPerspectiveView	Gets whether this drawing view is showing a perspective view of the model.
	LoadModel	Loads the model if the model has not already been loaded for this drawing view.
	MergeBendTags	Merges or unmerges bend tags in drawings of sheet metal parts.
	RemoveAlignment	Removes the alignment from this drawing view.
	ReplaceViewWithBlock	Converts this view into a sketch block with the specified manipulator location.
	ReplaceViewWithSketch	Converts this view into a sketch.
	ResetSketchVisibility	Resets the visibility of the sketches in the drawing view so that the drawing view reflects the model.
	SelectEntity	Selects an entity in this drawing view.
	SetBendNoteTextFormat	Sets the text format of all bend notes in this drawing view of a sheet metal part.
	SetDisplayMode	Obsolete. Superseded by IView.SetDisplayMode3 .
	SetDisplayMode2	Obsolete. Superseded by IView.SetDisplayMode3 .
	SetDisplayMode3	Obsolete. Superseded by IView.SetDisplayMode4 .
	SetDisplayMode4	Sets the display mode of this drawing view.
	SetDisplayTangentEdges	Obsolete. Superseded by IView.SetDisplayTangentEdges2 .
	SetDisplayTangentEdges2	Sets the tangent edge display mode of the drawing view.
	SetKeepLinkedToBOM	Sets whether this drawing view is linked to the specified BOM or weldment cut-list table.

		
	SetLightweightToResolved	Changes the drawing view from lightweight to resolved.
	SetMirrorViewOrientation	Sets whether to mirror this view.
	SetName2	Sets the name of this drawing view, as displayed in the FeatureManager design tree.
	SetResolvedToLightweight	Changes the drawing view from resolved to lightweight.
	SetViewPosition	Moves this drawing view.
	SetVisible	Sets the visibility of this drawing view.
	SetXform	Sets the matrix used for display of this drawing view.
	ShowExploded	Shows an exploded assembly in this drawing view.
	ShowModelBreakState	Sets whether to display the specified Model Break View.
	UpdateViewDisplayGeometry	Updates the displayed geometry for a drawing view.
	UseDefaultAlignment	Restores the default alignment for this drawing view.

[Top](#)

See Also

[IView Interface](#)
[SolidWorks.Interop.sldworks Namespace](#)
[IDrawingDoc Interface](#)
[IDrSection Interface](#)

SOLIDWORKS API Help

[Send comments on this topic.](#)

IView Interface Properties

[See Also](#)



[SolidWorks.Interop.sldworks Namespace](#) : IView Interface

For a list of all members of this type, see [IView members](#).

Public Properties

Name	Description
 Angle	Gets or sets the rotation angle of the view.
 Bodies	Gets or sets the bodies of a multibody part to show in the drawing view.
 BreakLineGap	Gets or sets the width of the gap for a break line.
 CropViewJaggedOutline	Gets or sets whether to use a jagged outline in this cropped drawing view.
 CropViewJaggedShapeIntensity	Gets or sets the shape intensity of the jagged outline in this cropped drawing view.
 CropViewNoOutline	Gets or sets whether to show an outline in this cropped drawing view.
 DisableAutoUpdate	Gets or sets whether to disable the automatic update of this view.
 DisplayState	Gets or sets the name of the display state for this drawing view.
 EmphasizeOutline	Gets or sets whether the outlines of section views are emphasized in this drawing view.
 FlipView	Gets or sets whether to flip a flat-pattern view of a sheet metal part.
 FocusLocked	Gets or sets whether or not focus is locked on this view.
 HiddenEdges	Gets the hidden edges in the drawing view or sets the hidden edges in the drawing view to be visible.
 IPosition	Gets or sets the X and Y location of the model view's geometric center, relative to the drawing sheet origin.
 IScaleRatio	Gets or sets the scale of the drawing view, returning the results in ratio format (n:n).
 LinkParentConfiguration	Gets or sets whether to link a projected or auxiliary view with the parent configuration.
 ModelToViewTransform	Gets the math transform to go from model to drawing view space. NOTE: This property is a get-only property. Set is not implemented.
 Name	Obsolete. Superseded by IView::GetName2 and IView::SetName2
Position	Gets or sets the X and Y location of the model view's geometric center, relative to the drawing sheet origin.

		
	PositionLocked	Gets or sets whether this drawing view's position is locked.
	ProjectedDimensions	Gets or sets whether dimensions in this view are true or projected.
	ReferencedConfiguration	Gets or sets the configuration referenced by this drawing view.
	ReferencedConfigurationID	Gets the persistent reference ID of the configuration referenced in this drawing view.
	ReferencedDocument	Gets the document referenced by this drawing view.
	RootDrawingComponent	Obsolete. Superseded by IView.RootDrawingComponent2 .
	RootDrawingComponent2	Gets the root component of this drawing view.
	ScaleDecimal	Gets or sets the scale of the drawing view, returning the results in decimal format.
	ScaleHatchPattern	Gets or sets whether to scale the hatch pattern to the drawing view.
	ScaleRatio	Gets or sets the scale of the drawing view, returning the results in ratio format (n:n).
	Sheet	Gets the sheet on which this drawing view exists.
	ShowSheetMetalBendNotes	Gets or sets whether to show sheet metal bend notes.
	SuppressState	Gets or sets the view suppress state.
	Type	Gets the drawing view type.
	UseParentScale	Gets or sets the drawing view's scale to match the parent drawing view's scale.
	UseSheetScale	Gets or sets whether the scale of the drawing view is the same as the scale of the drawing sheet on which this view is located.

[Top](#)

 See Also

[IView Interface](#)
[SolidWorks.Interop.sldworks Namespace](#)
[IDrawingDoc Interface](#)
[IDrSection Interface](#)

SOLIDWORKS API Help

[Send comments on this topic.](#)

AlignDrawingView Method (IView)

[See Also](#) [Example](#)



[SolidWorks.Interop.sldworks Namespace](#) > [IView Interface](#) : AlignDrawingView Method (IView)

Specifies the alignment of this auxiliary drawing view.

 .NET Syntax

Visual Basic (Declaration)

```
Function AlignDrawingView( _  
    ByVal AlignViewType As System.Integer _  
) As System.Boolean
```

Visual Basic (Usage)



```
Dim instance As IView  
Dim AlignViewType As System.Integer  
Dim value As System.Boolean  
  
value = instance.AlignDrawingView(AlignViewType)
```

C#

```
System.bool AlignDrawingView(  
    System.int AlignViewType  
)
```

C++/CLI

```
System.bool AlignDrawingView(  
&    System.int AlignViewType
```

)

NOTE: See [Differences Between Unmanaged C++ and C++/CLI Code](#).

Parameters

AlignViewType

Type of alignment as defined by [swAlignDrawingViewTypes_e](#)

Return Value

True if auxiliary drawing view alignment is set, false if not

Visual Basic for Applications (VBA) Syntax

See [View::AlignDrawingView](#).

Example

[Align Auxiliary Drawing View \(VBA\)](#)
[Align Auxiliary Drawing View \(VB.NET\)](#)
[Align Auxiliary Drawing View \(C#\)](#)

See Also

[IView Interface](#)
[IView Members](#)
[IView::AlignWithView Method \(\)](#)
[IView::GetAlignment Method \(\)](#)
[IView::RemoveAlignment Method \(\)](#)
[IView::UseDefaultAlignment Method \(\)](#)

Availability

SOLIDWORKS 2014 FCS, Revision Number 22.0

SOLIDWORKS API Help

[Send comments](#) on this topic.

AlignWithView Method (IView)

[See Also](#) [Example](#)



[SolidWorks.Interop.sldworks Namespace](#) > [IView Interface](#) : AlignWithView Method (IView)

Sets view alignment.

.NET Syntax

Visual Basic (Declaration)

```
Function AlignWithView( _  
    ByVal AlignType As System.Integer, _  
    ByVal BaseView As View _  
) As System.Boolean
```

Visual Basic (Usage)

```
Dim instance As IView  
Dim AlignType As System.Integer  
Dim BaseView As View  
Dim value As System.Boolean  
  
value = instance.AlignWithView(AlignType, BaseView)
```

C#

```
System.bool AlignWithView(  
    System.int AlignType,  
    View BaseView  
)
```

C++/CLI

```
System.bool AlignWithView(  
& System.int AlignType,
```

& View^ [BaseView](#)
)

NOTE: See [Differences Between Unmanaged C++ and C++/CLI Code](#).

Parameters

AlignType

Type of alignment to set as defined by [swAlignViewTypes_e](#)

BaseView

[View](#) with which to align, if aligning with another view

Return Value

True if view alignment is set, false if not

Visual Basic for Applications (VBA) Syntax

See [View::AlignWithView](#).

Example

[Align Drawing Views \(C#\)](#)

[Align Drawing Views \(VB.NET\)](#)

[Align Drawing Views \(VBA\)](#)

Remarks

AlignType tells how to align this view.

If AlignType is set to...	Then BaseView...
swAlignViewHorizontalCenter	must be specified as the view with which to align.
swAlignViewVerticalCenter	must be specified as the view with which to align.
swAlignViewHorizontalOrigin	must be specified as the view with which to align.
swAlignViewVerticalOrigin	must be specified as the view with which to align.
swNoViewAlignment	is ignored.
swDefaultViewAlignment	is ignored.

See Also

[IView Interface](#)

[IView Members](#)

[IView::GetAlignment Method](#)

[IView::RemoveAlignment Method](#)

[IView::UseDefaultAlignment Method \(\)](#)

[IView::AlignDrawingView Method \(\)](#)

Availability

SOLIDWORKS 2004 FCS, Revision Number 12.0

SOLIDWORKS API Help

[Send comments on this topic.](#)

Angle Property (IView)

[See Also](#)



[SolidWorks.Interop.sldworks Namespace](#) > [IView Interface](#) : Angle Property (IView)

Gets or sets the rotation angle of the view.

.NET Syntax

Visual Basic (Declaration)

Property Angle As System.Double

```
Dim instance As IView
Dim value As System.Double

instance.Angle = value

value = instance.Angle
```

C#

```
System.double Angle {get; set;}
```

C++/CLI

```
property System.double Angle {
    System.double get();
    void set ( & System.double value);
}
```

NOTE: See [Differences Between Unmanaged C++ and C++/CLI Code](#).

Property Value

Rotation angle in radians of the view

Visual Basic for Applications (VBA) Syntax

See [View::Angle](#).

See Also

[IView Interface](#)
[IView Members](#)

Availability

SOLIDWORKS 2001 FCS, Revision Number 9.0

SOLIDWORKS API Help

[Send comments on this topic.](#)

AutoInsertCenterMarks Method (IView)

[See Also](#)



[SolidWorks.Interop.sldworks Namespace](#) > [IView Interface](#) : AutoInsertCenterMarks Method (IView)

Obsolete. Superseded by [IView::AutoInsertCenterMarks2](#).

.NET Syntax

Visual Basic (Declaration)

```
Function AutoInsertCenterMarks( _
    ByVal InsertType As System.Integer, _
    ByVal InsertOption As System.Integer, _
    ByVal LinearSlotCenter As System.Boolean, _
    ByVal ArcSlotCenter As System.Boolean, _
    ByVal UseDocumentDefaults As System.Boolean, _
    ByVal Size As System.Double, _
    ByVal ExtendedLines As System.Boolean, _
    ByVal CenterLineFont As System.Boolean, _
    ByVal Angle As System.Double _
) As System.Boolean
```

Visual Basic (Usage)

Copy Code

```
Dim instance As IView
Dim InsertType As System.Integer
Dim InsertOption As System.Integer
Dim LinearSlotCenter As System.Boolean
```

```

Dim ArcSlotCenter As System.Boolean
Dim UseDocumentDefaults As System.Boolean
Dim Size As System.Double
Dim ExtendedLines As System.Boolean
Dim CenterLineFont As System.Boolean
Dim Angle As System.Double
Dim value As System.Boolean

```

```

value = instance.AutoInsertCenterMarks(InsertType, InsertOption, LinearSlotCenter, ArcSlotCenter,
UseDocumentDefaults, Size, ExtendedLines, CenterLineFont, Angle)

```

C#

```

System.bool AutoInsertCenterMarks(
    System.int InsertType,
    System.int InsertOption,
    System.bool LinearSlotCenter,
    System.bool ArcSlotCenter,
    System.bool UseDocumentDefaults,
    System.double Size,
    System.bool ExtendedLines,
    System.bool CenterLineFont,
    System.double Angle
)

```

C++/CLI

```

System.bool AutoInsertCenterMarks(
    & System.int InsertType,
    & System.int InsertOption,
    & System.bool LinearSlotCenter,
    & System.bool ArcSlotCenter,
    & System.bool UseDocumentDefaults,
    & System.double Size,
    & System.bool ExtendedLines,
    & System.bool CenterLineFont,
    & System.double Angle
)

```

NOTE: See [Differences Between Unmanaged C++ and C++/CLI Code](#).

Parameters

InsertType

Features for which to insert center marks as defined in [swAutoInsertCenterMarkTypes_e](#)

InsertOption

Center mark options as defined in [swCenterMarkConnectionLine_e](#)

LinearSlotCenter

True to add center marks to slot centers, false to add them to slot ends

ArcSlotCenter

True to add center marks to arc centers, false to add them to arc ends

UseDocumentDefaults

True to use the display attribute defaults specified in [Document Properties > Centerlines/Center Marks](#), false to use the display attributes set by this method

Size

Size of center mark; valid only if UseDocumentDefaults is false

ExtendedLines

True to extend lines from center mark points, false to not; valid only if UseDocumentDefaults is false

CenterLineFont

True to use the centerline font, false to not; valid only if UseDocumentDefaults is false

Angle

Rotation angle for the center mark; a positive angle rotates the center mark counterclockwise

Return Value

True if successful, false if not

Visual Basic for Applications (VBA) Syntax

See [View::AutoInsertCenterMarks](#).

Remarks

Call this method on each active view in which you want to insert center marks.

Before calling this method:

1. Call [IDrawingDoc::ActivateView](#) with the name of the view to activate.
2. Call [IDrawingDoc::ActiveDrawingView](#) to get a handle on the activated view.

Call [IDrawingDoc::InsertCenterMark3](#) if you want to insert one center mark in one view.

See Also

[IView Interface](#)
[IView Members](#)
[IView::GetCenterMarkCount2 Method](#)
[IView::GetCenterMarkInfo Method](#)
[IView::GetCenterMarks Method](#)

Availability

SOLIDWORKS 2012 FCS, Revision Number 20.0

SOLIDWORKS API Help

[Send comments](#) on this topic.

AutoInsertCenterMarks2 Method (IView)

[See Also](#) [Example](#)



[SolidWorks.Interop.sldworks Namespace](#) > [IView Interface](#) : AutoInsertCenterMarks2 Method (IView)

Automatically inserts the specified center marks in this view.

.NET Syntax

Visual Basic (Declaration)

```
Function AutoInsertCenterMarks2( _  
    ByVal InsertType As System.Integer, _  
    ByVal InsertOption As System.Integer, _  
    ByVal LinearSlotCenter As System.Boolean, _  
    ByVal ArcSlotCenter As System.Boolean, _  
    ByVal UseDocumentDefaults As System.Boolean, _  
    ByVal Size As System.Double, _  
    ByVal Gap As System.Double, _  
    ByVal ExtendedLines As System.Boolean, _  
    ByVal CenterLineFont As System.Boolean, _  
    ByVal Angle As System.Double _  
) As System.Boolean
```

Visual Basic (Usage)



```
Dim instance As IView  
Dim InsertType As System.Integer  
Dim InsertOption As System.Integer  
Dim LinearSlotCenter As System.Boolean  
Dim ArcSlotCenter As System.Boolean  
Dim UseDocumentDefaults As System.Boolean  
Dim Size As System.Double  
Dim Gap As System.Double  
Dim ExtendedLines As System.Boolean  
Dim CenterLineFont As System.Boolean  
Dim Angle As System.Double  
Dim value As System.Boolean
```

```
value = instance.AutoInsertCenterMarks2(InsertType, InsertOption, LinearSlotCenter, ArcSlotCenter,  
UseDocumentDefaults, Size, Gap, ExtendedLines, CenterLineFont, Angle)
```

C#

```
System.bool AutoInsertCenterMarks2(  
    System.int InsertType,  
    System.int InsertOption,  
    System.bool LinearSlotCenter,  
    System.bool ArcSlotCenter,  
    System.bool UseDocumentDefaults,  
    System.double Size,  
    System.double Gap,  
    System.bool ExtendedLines,  
    System.bool CenterLineFont,
```

```
        System.double Angle
    )
}
```

C++/CLI

```
System.bool AutoInsertCenterMarks2(
& System.int InsertType,
& System.int InsertOption,
& System.bool LinearSlotCenter,
& System.bool ArcSlotCenter,
& System.bool UseDocumentDefaults,
& System.double Size,
& System.double Gap,
& System.bool ExtendedLines,
& System.bool CenterLineFont,
& System.double Angle
)
```

NOTE: See [Differences Between Unmanaged C++ and C++/CLI Code](#).

Parameters

InsertType

Features for which to insert center marks as defined in [swAutoInsertCenterMarkTypes_e](#)

InsertOption

Center mark options as defined in [swCenterMarkConnectionLine_e](#)

LinearSlotCenter

True to add center marks to slot centers, false to add them to slot ends

ArcSlotCenter

True to add center marks to arc centers, false to add them to arc ends

UseDocumentDefaults

True to use the display settings specified in [Tools > Options > Document Properties > Centerlines/Center Marks](#), false to use the display settings set by this method

Size

Size of center mark; valid only if UseDocumentDefaults is false

Gap

Size of gap between the center mark and extension line; valid only if UseDocumentDefaults is false and the [Tools > Options > Document Properties > Centerlines/Center Marks > Scale by view scale](#) check box is clear (see [Remarks](#))

ExtendedLines

True to extend lines from center mark points, false to not; valid only if UseDocumentDefaults is false

CenterLineFont

True to use the centerline font, false to not; valid only if UseDocumentDefaults is false

Angle

Rotation angle for the center mark; a positive angle rotates the center mark counterclockwise

Return Value

True if successful, false if not

Visual Basic for Applications (VBA) Syntax

See [View::AutoInsertCenterMarks2](#).

Example

[Automatically Insert Center Marks \(C#\)](#)

[Automatically Insert Center Marks \(VB.NET\)](#)

[Automatically Insert Center Marks \(VBA\)](#)

Remarks

Call this method on each active view in which you want to insert center marks.

Before calling this method:

1. Call [IDrawingDoc::ActivateView](#) with the name of the view to activate.
2. Call [IDrawingDoc::ActiveDrawingView](#) to get a handle on the activated view.

Call [IDrawingDoc::InsertCenterMark3](#) if you want to insert one center mark in one view.

To...	Call...
Get the Tools > Options > Document Properties > Centerlines/Center Marks > Scale by view scale setting	IModelDocExtension::GetUserPreferenceToggle swUserPreferenceToggle_e .swDetailingCenterMarkScaleByViewScale, swUserPreferenceOption_e .swDetailingNoOptionSpecified
Set the Tools > Options > Document Properties > Centerlines/Center Marks > Scale by view scale setting	IModelDocExtension::SetUserPreferenceToggle swUserPreferenceToggle_e .swDetailingCenterMarkScaleByViewScale, swUserPreferenceOption_e .swDetailingNoOptionSpecified, <value>

See Also

[IView Interface](#)

[IView Members](#)

[IView::GetCenterMarkCount2 Method \(\)](#)

[IView::GetCenterMarkInfo Method \(\)](#)
[IView::GetCenterMarks Method \(\)](#)

Availability

SOLIDWORKS 2016 FCS, Revision Number 24.0

SOLIDWORKS API Help

[Send comments](#) on this topic.

Bodies Property (IView)

[See Also](#) [Example](#)



[SolidWorks.Interop.sldworks Namespace](#) > [IView Interface](#) : Bodies Property (IView)

Gets or sets the bodies of a multibody part to show in the drawing view.

.NET Syntax

Visual Basic (Declaration)

Property Bodies As System.Object

Visual Basic (Usage)



```
Dim instance As IView
Dim value As System.Object

instance.Bodies = value
value = instance.Bodies
```

C#

```
System.object Bodies {get; set;}
```

C++/CLI

```
property System.Object^ Bodies {
    System.Object^ get();
    void set ( & System.Object^ value);
}
```

NOTE: See [Differences Between Unmanaged C++ and C++/CLI Code](#).

Property Value

[Bodies](#) of a multibody part

Visual Basic for Applications (VBA) Syntax

See [View::Bodies](#).

Example

[Set Body for View \(C#\)](#)
[Set Body for View \(VB.NET\)](#)
[Set Body for View \(VBA\)](#)

See Also

[IView Interface](#)
[IView Members](#)
[IView::GetBodiesCount Method](#)
[IView::IGetBodies Method](#)
[IView::ISetBodies Method](#)

Availability

SOLIDWORKS 2010 FCS, Revision Number 18.0

SOLIDWORKS API Help

[Send comments](#) on this topic.

BreakLineGap Property (IView)

[See Also](#)



[SolidWorks.Interop.sldworks Namespace](#) > [IView Interface](#) : BreakLineGap Property (IView)

Gets or sets the width of the gap for a break line.

.NET Syntax

Visual Basic (Declaration)

Property BreakLineGap As System.Double

Visual Basic (Usage)



```
Dim instance As IView
Dim value As System.Double

instance.BreakLineGap = value

value = instance.BreakLineGap
```

C#

```
System.double BreakLineGap {get; set;}
```

C++/CLI

```
property System.double BreakLineGap {
    System.double get();
    void set ( & System.double value);
}
```

NOTE: See [Differences Between Unmanaged C++ and C++/CLI Code](#).

Property Value

Value for gap

Visual Basic for Applications (VBA) Syntax

See [View::BreakLineGap](#).

See Also

[IView Interface](#)
[IView Members](#)
[GetBreakLineCount Method](#)
[IView::GetBreakLineInfo Method](#)
[IView::GetBreakLines Method](#)
[IView::IGetBreakLineInfo Method](#)
[IView::IGetBreakLines Method](#)
[IView::InsertBreak Method](#)

Availability

SOLIDWORKS 2007 FCS, Revision Number 15.0

SOLIDWORKS API Help

[Send comments on this topic.](#)

Crop Method (IView)

[See Also](#) [Example](#)



[SolidWorks.Interop.sldworks Namespace](#) > [IView Interface](#) : Crop Method (IView)

Obsolete. Superseded by [IView::Crop2](#).

.NET Syntax

Visual Basic (Declaration)

Function Crop() As System.Integer

Visual Basic (Usage)



```
Dim instance As IView
Dim value As System.Integer

value = instance.Crop()
```

C#

```
System.int Crop()
```

C++/CLI

```
System.int Crop();
```

NOTE: See [Differences Between Unmanaged C++ and C++/CLI Code](#).

Return Value

Crop view status as defined in [swCropViewErrors_e](#)

Visual Basic for Applications (VBA) Syntax

See [View::Crop](#).

Example

[Crop View \(VBA\)](#)
[Crop View \(VB.NET\)](#)
[Crop View \(C#\)](#)

See Also

[IView Interface](#)
[IView Members](#)

Availability

SOLIDWORKS 2005 FCS, Revision Number 13.0

SOLIDWORKS API Help

[Send comments](#) on this topic.

Crop2 Method (IView)

[See Also](#) [Example](#)



[SolidWorks.Interop.sldworks.Namespace](#) > [IView Interface](#) : Crop2 Method (IView)

Crops this view using the selected closed sketch profile.

.NET Syntax

Visual Basic (Declaration)

```
Function Crop2( _
    ByVal JaggedOutline As System.Boolean, _
    ByVal NoOutline As System.Boolean, _
    ByVal ShapeIntensity As System.Integer _
) As System.Integer
```

Visual Basic (Usage)



```
Dim instance As IView
Dim JaggedOutline As System.Boolean
Dim NoOutline As System.Boolean
Dim ShapeIntensity As System.Integer
Dim value As System.Integer

value = instance.Crop2(JaggedOutline, NoOutline, ShapeIntensity)
```

C#

```
System.int Crop2(
    System.bool JaggedOutline,
    System.bool NoOutline,
    System.int ShapeIntensity
)
```

C++/CLI

```
System.int Crop2(
    & System.bool JaggedOutline,
    & System.bool NoOutline,
    & System.int ShapeIntensity
)
```

NOTE: See [Differences Between Unmanaged C++ and C++/CLI Code](#).

Parameters

JaggedOutline

True to use a jagged outline, false to not; only valid if NoOutline is false

NoOutline

True to not show an outline, false to show an outline

ShapeIntensity

Shape intensity of the jagged outline; valid range is 1 (most) to 5 (least); only valid if JaggedOutline is true

Return Value

Crop view status as defined in [swCropViewErrors_e](#)

Visual Basic for Applications (VBA) Syntax

See [View::Crop2](#).

Example

[Crop Drawing View Using Jagged Outline \(C#\)](#)

[Crop Drawing View Using Jagged Outline \(VB.NET\)](#)

[Crop Drawing View Using Jagged Outline \(VBA\)](#)

See Also

[IView Interface](#)

[IView Members](#)

[IView::IsCropped Method\(\)](#)

[IView::CropViewJaggedOutline Property\(\)](#)

[IView::CropViewJaggedShapeIntensity Property\(\)](#)

[IView::CropViewNoOutline Property\(\)](#)

Availability

SOLIDWORKS 2017 FCS, Revision Number 25.0

SOLIDWORKS API Help

[Send comments on this topic.](#)

CropViewJaggedOutline Property (IView)

[See Also](#) [Example](#)



[SolidWorks.Interop.sldworks Namespace](#) > [IView Interface](#) : CropViewJaggedOutline Property (IView)

Gets or sets whether to use a jagged outline in this cropped drawing view.

.NET Syntax

Visual Basic (Declaration)

```
Property CropViewJaggedOutline As System.Boolean
```

Visual Basic (Usage)

```
Dim instance As IView
```

```
Dim value As System.Boolean
```

```
instance.CropViewJaggedOutline = value
```



```
value = instance.CropViewJaggedOutline
```

C#

```
System.bool CropViewJaggedOutline {get; set;}
```

C++/CLI

```
property System.bool CropViewJaggedOutline {  
    System.bool get();  
    void set ( & System.bool value);  
}
```

NOTE: See [Differences Between Unmanaged C++ and C++/CLI Code](#).

Property Value

True to use a jagged outline, false to not (see **Remarks**)

Visual Basic for Applications (VBA) Syntax

See [View::CropViewJaggedOutline](#).

Example

[Crop Drawing View Using Jagged Outline \(C#\)](#)
[Crop Drawing View Using Jagged Outline \(VB.NET\)](#)
[Crop Drawing View Using Jagged Outline \(VBA\)](#)

Remarks

Call [IView::IsCropped](#) to find out if this drawing view is cropped.

IView::CropViewJaggedOutline is only available when [IView::CropViewNoOutline](#) is false.

To set the intensity of the jagged outline, call [IView::CropViewJaggedShapeIntensity](#).

See Also

[IView Interface](#)
[IView Members](#)
[IView::Crop2 Method \(\)](#)

Availability

SOLIDWORKS 2017 FCS, Revision Number 25.0

SOLIDWORKS API Help

[Send comments](#) on this topic.

CropViewJaggedShapeIntensity Property (IView)

[See Also](#) [Example](#)



[SolidWorks.Interop.sldworks Namespace](#) > [IView Interface](#) : CropViewJaggedShapeIntensity Property (IView)

Gets or sets the shape intensity of the jagged outline in this cropped drawing view.

.NET Syntax

Visual Basic (Declaration)

```
Property CropViewJaggedShapeIntensity As System.Integer
```

Visual Basic (Usage)



```
Dim instance As IView  
Dim value As System.Integer  
  
instance.CropViewJaggedShapeIntensity = value  
  
value = instance.CropViewJaggedShapeIntensity
```

C#

```
System.int CropViewJaggedShapeIntensity {get; set;}
```

C++/CLI

```
property System.int CropViewJaggedShapeIntensity {  
    System.int get();  
    void set ( & System.int value);  
}
```

NOTE: See [Differences Between Unmanaged C++ and C++/CLI Code](#).

Property Value

Shape intensity of the jagged outline; valid range is 1 (most) to 5 (least) (see **Remarks**)

Visual Basic for Applications (VBA) Syntax

See [View::CropViewJaggedShapeIntensity](#).

Example

[Crop Drawing View Using Jagged Outline \(C#\)](#)
[Crop Drawing View Using Jagged Outline \(VB.NET\)](#)
[Crop Drawing View Using Jagged Outline \(VBA\)](#)

Remarks

Call [IView::IsCropped](#) to find out if this drawing view is cropped.

IView::CropViewJaggedShapeIntensity is only available when [IView::CropViewJaggedOutline](#) is true and [IView::CropViewNoOutline](#) is false.

See Also

[IView Interface](#)
[IView Members](#)
[IView::Crop2 Method \(\)](#)

Availability

SOLIDWORKS 2017 FCS, Revision Number 25.0

SOLIDWORKS API Help

[Send comments on this topic.](#)

CropViewNoOutline Property (IView)

[See Also](#) [Example](#)



[SolidWorks.Interop.sldworks Namespace](#) > [IView Interface](#) : CropViewNoOutline Property (IView)

Gets or sets whether to show an outline in this cropped drawing view.

.NET Syntax

Visual Basic (Declaration)

```
Property CropViewNoOutline As System.Boolean
```

Visual Basic (Usage)



```
Dim instance As IView  
Dim value As System.Boolean  
  
instance.CropViewNoOutline = value  
value = instance.CropViewNoOutline
```

C#

```
System.bool CropViewNoOutline {get; set;}
```

C++/CLI

```
property System.bool CropViewNoOutline {  
    System.bool get();  
    void set ( & System.bool value);  
}
```

NOTE: See [Differences Between Unmanaged C++ and C++/CLI Code](#).

Property Value

True to not show an outline, false to show an outline

Visual Basic for Applications (VBA) Syntax

See [View::CropViewNoOutline](#).

Example

[Crop Drawing View Using Jagged Outline \(C#\)](#)
[Crop Drawing View Using Jagged Outline \(VB.NET\)](#)
[Crop Drawing View Using Jagged Outline \(VBA\)](#)

Remarks

Call [IView::IsCropped](#) to find out if this drawing view is cropped.

See Also

[IView Interface](#)
[IView Members](#)
[IView::Crop2 Method \(\)](#)
[IView::CropViewJaggedOutline Property \(\)](#)
[IView::CropViewJaggedShapeIntensity Property \(\)](#)

Availability

SOLIDWORKS 2017 FCS, Revision Number 25.0

SOLIDWORKS API Help

[Send comments on this topic.](#)

DisableAutoUpdate Property (IView)

[See Also](#)



[SolidWorks.Interop.sldworks Namespace](#) > [IView Interface](#) : DisableAutoUpdate Property (IView)

Gets or sets whether to disable the automatic update of this view.

.NET Syntax

Visual Basic (Declaration)

Property DisableAutoUpdate As System.Boolean

Visual Basic (Usage)



```
Dim instance As IView  
Dim value As System.Boolean  
  
instance.DisableAutoUpdate = value  
value = instance.DisableAutoUpdate
```

C#

```
System.bool DisableAutoUpdate {get; set;}
```

C++/CLI

```
property System.bool DisableAutoUpdate {
    System.bool get();
    void set ( & System.bool value);
}
```

NOTE: See [Differences Between Unmanaged C++ and C++/CLI Code](#).

Property Value

True to disable the automatic update, false to not

Visual Basic for Applications (VBA) Syntax

See [View::DisableAutoUpdate](#).

See Also

[IView Interface](#)
[IView Members](#)

Availability

SOLIDWORKS 2020 SP5, Revision Number 28.5

SOLIDWORKS API Help

[Send comments on this topic.](#)

DisplayState Property (IView)

[See Also](#) [Example](#)



[SolidWorks.Interop.sldworks Namespace](#) > [IView Interface](#) : DisplayState Property (IView)

Gets or sets the name of the display state for this drawing view.

.NET Syntax

Visual Basic (Declaration)

```
Property DisplayState As System.String
```

Visual Basic (Usage)



```
Dim instance As IView
Dim value As System.String

instance.DisplayState = value
value = instance.DisplayState
```

C#

```
System.string DisplayState {get; set;}
```

C++/CLI

```
property System.String^ DisplayState {
    System.String^ get();
    void set ( & System.String^ value);
}
```

NOTE: See [Differences Between Unmanaged C++ and C++/CLI Code](#).

Property Value

Name of the display state

Visual Basic for Applications (VBA) Syntax

See [View::DisplayState](#).

Example

[Get Display State for Each Drawing View \(C#\)](#)
[Get Display State for Each Drawing View \(VB.NET\)](#)
[Get Display State for Each Drawing View \(VBA\)](#)

See Also

[IView Interface](#)
[IView Members](#)

Availability

SOLIDWORKS 2017 FCS, Revision Number 25.0

SOLIDWORKS API Help

[Send comments](#) on this topic.

EmphasizeOutline Property (IView)

[See Also](#) [Example](#)



[SolidWorks.Interop.sldworks Namespace](#) > [IView Interface](#) : EmphasizeOutline Property (IView)

Gets or sets whether the outlines of section views are emphasized in this drawing view.

.NET Syntax

Visual Basic (Declaration)

```
Property EmphasizeOutline As System.Boolean
```

Visual Basic (Usage)



```
Dim instance As IView  
Dim value As System.Boolean  
  
instance.EmphasizeOutline = value  
value = instance.EmphasizeOutline
```

C#

```
System.bool EmphasizeOutline {get; set;}
```

C++/CLI

```
property System.bool EmphasizeOutline {  
    System.bool get();  
    void set ( & System.bool value);  
}
```

NOTE: See [Differences Between Unmanaged C++ and C++/CLI Code](#).

Property Value

True if the outlines of section views are outlined, false if not

Visual Basic for Applications (VBA) Syntax

See [View::EmphasizeOutline](#).

Example

[Create Section View and Get Some Data \(C#\)](#)
[Create Section View and Get Some Data \(VB.NET\)](#)
[Create Section View and Get Some Data \(VBA\)](#)

See Also

[IView Interface](#)
[IView Members](#)

Availability

SOLIDWORKS 2017 FCS, Revision Number 25.0

EnumHiddenComponents Method (IView)

[See Also](#)



[SolidWorks.Interop.sldworks Namespace](#) > [IView Interface](#) : EnumHiddenComponents Method (IView)

Obsolete. Superseded by [IView::EnumHiddenComponents2](#).

.NET Syntax

Visual Basic (Declaration)

```
Function EnumHiddenComponents() As EnumComponents
```

Visual Basic (Usage)



```
Dim instance As IView  
Dim value As EnumComponents  
  
value = instance.EnumHiddenComponents()
```

C#

```
EnumComponents EnumHiddenComponents()
```

C++/CLI

```
EnumComponents^ EnumHiddenComponents();
```

NOTE: See [Differences Between Unmanaged C++ and C++/CLI Code](#).

Visual Basic for Applications (VBA) Syntax

See [View::EnumHiddenComponents](#).

See Also

[IView Interface](#)
[IView Members](#)

EnumHiddenComponents2 Method (IView)

[See Also](#)



[SolidWorks.Interop.sldworks Namespace](#) > [IView Interface](#) : EnumHiddenComponents2 Method (IView)

Gets the hidden components enumeration in this drawing view.

.NET Syntax

Visual Basic (Declaration)

```
Function EnumHiddenComponents2() As EnumComponents2
```

Visual Basic (Usage)



```
Dim instance As IView  
Dim value As EnumComponents2  
  
value = instance.EnumHiddenComponents2()
```

C#

```
EnumComponents2 EnumHiddenComponents2()
```

C++/CLI

```
EnumComponents2^ EnumHiddenComponents2();
```

NOTE: See [Differences Between Unmanaged C++ and C++/CLI Code](#).

Return Value

[Hidden component enumeration](#)

Visual Basic for Applications (VBA) Syntax

See [View::EnumHiddenComponents2](#).

See Also

[IView Interface](#)
[IView Members](#)
[IView::GetHiddenComponents Method](#)
[IView::GetVisibleComponentCount Method](#)
[IView::GetVisibleComponents Method](#)
[IView::IGetVisibleComponents Method](#)

Availability

SOLIDWORKS 2001Plus FCS, Revision Number 10.0

SOLIDWORKS API Help

[Send comments on this topic](#).

EnumSectionLines Method (IView)

[See Also](#)



[SolidWorks.Interop.sldworks Namespace](#) > [IView Interface](#) : EnumSectionLines Method (IView)

Obsolete. Superseded by [IView::EnumSectionLines2](#).

.NET Syntax

Visual Basic (Declaration)

```
Function EnumSectionLines() As EnumDrSections
```

Visual Basic (Usage)



```
Dim instance As IView  
Dim value As EnumDrSections  
  
value = instance.EnumSectionLines()
```

C#

```
EnumDrSections EnumSectionLines()
```

C++/CLI

```
EnumDrSections^ EnumSectionLines();
```

NOTE: See [Differences Between Unmanaged C++ and C++/CLI Code](#).

Return Value

[Section lines enumeration](#)

Visual Basic for Applications (VBA) Syntax

See [View::EnumSectionLines](#).

Remarks

This method returns the section lines regardless of whether the view is visible. If the view is hidden, then the section lines are still returned.

See Also

[IView Interface](#)
[IView Members](#)
[IView::GetSectionLineCount2 Method](#)
[IView::GetSectionLines Method](#)
[IView::GetSectionLineStrings Method](#)

Availability

SOLIDWORKS 2000 FCS, Revision Number 8.0

SOLIDWORKS API Help

[Send comments](#) on this topic.

EnumSectionLines2 Method (IView)

[See Also](#)



[SolidWorks.Interop.sldworks Namespace](#) > [IView Interface](#) : EnumSectionLines2 Method (IView)

Gets the section lines enumeration in the view.

.NET Syntax

Visual Basic (Declaration)

```
Function EnumSectionLines2( _  
    ByVal IgnoreSuppressed As System.Boolean _  
) As EnumDrSections
```

Visual Basic (Usage)



```
Dim instance As IView  
Dim IgnoreSuppressed As System.Boolean  
Dim value As EnumDrSections  
  
value = instance.EnumSectionLines2(IgnoreSuppressed)
```

C#

```
EnumDrSections EnumSectionLines2(  
    System.bool IgnoreSuppressed  
)
```

C++/CLI

```
EnumDrSections^ EnumSectionLines2(  
& System.bool IgnoreSuppressed  
)
```

NOTE: See [Differences Between Unmanaged C++ and C++/CLI Code](#).

Parameters

IgnoreSuppressed
True to ignore suppressed section lines, false to include them

Return Value

[Section lines enumeration](#)

Visual Basic for Applications (VBA) Syntax

See [View::EnumSectionLines2](#).

Remarks

This method returns section lines whether the view is visible or not. If the view is hidden, then the section lines are still returned.

See Also

[IView Interface](#)
[IView Members](#)
[IView::GetSectionLineCount2 Method \(\)](#)
[IView::GetSectionLines Method \(\)](#)
[IView::GetSectionLineStrings Method \(\)](#)

