

INCIDENT INVESTIGATION REPORT · ICAM

injury

INC-2026-0001

Demo Mining Corp · North Pit Operations

• COMPLETED

ICAM METHODOLOGY

SEVERITY · HIGH

DOCUMENT CONTROL

Prepared by	Ian Investigator — Lead Investigator	Date	February 28, 2026
Reviewed by	Site Safety Manager	Date	—
Approved by	Site / Mine Manager	Date	February 10, 2026
Organisation	Demo Mining Corp	Methodology	ICAM
Distribution	Site Management · Health & Safety Committee · Group HSE · Regulator (as required)		
Classification	HIGH — for authorised distribution	Revision	1.0



Contents

1 · Executive Summary	2
2 · Incident Details & People Involved	2
3 · Sequence of Events	3
4 · Investigation Scope & Evidence Register	3
5 · PEEPO Data Collection	4
6 · ICAM Factor Analysis	4
7 · Causal Analysis & Root Causes	5
8 · Risk Assessment	5
9 · Corrective Actions	6
10 · Conclusions & Sign-off	6

1 Executive Summary

On 15 January 2026, operator J. Martinez sustained a 3cm laceration to the left forearm during a pre-start inspection of conveyor CR-047. The injury occurred because the drive-pulley guard had been removed during maintenance work order WO-8842 and was not reinstated before the conveyor was returned to service, leaving a live nip point exposed and unmarked at the point of approach. The maintenance fitter, R. Okafor, had been redirected mid-task to an urgent production breakdown without any organisational mechanism requiring him to first restore CR-047 to a documented safe state. No out-of-service tag, no continued isolation, and no physical indicator of the hazardous condition remained at the machine when he departed. The incoming operator received no information about the unresolved maintenance condition through the shift handover, and no engineered interlock existed to prevent the conveyor from being energised with the guard absent. The injury was therefore the predictable outcome of multiple, compounding system deficiencies rather than the failure of any individual. The investigation identified six contributing factors that converged to produce this event. First, WO-8842 contained a guard-removal step but no corresponding mandatory verification step requiring the guard to be reinstated and confirmed before the conveyor could be returned to service, and no task-incomplete field requiring an out-of-service tag when the job could not be closed within a single shift. This reflects a procedure development process that does not mandate hazard-specific close-out verification as a non-negotiable element of any work order involving guard removal, making it structurally straightforward to leave guarding unreinstated. Second, no organisational protocol existed for managing task interruptions during safety-critical maintenance; when a competing production demand arose, there was no supervisor gate, no system prompt, and no structured decision pathway to ensure CR-047 was left in a safe state before the fitter disengaged. The task

environment created conditions in which responding immediately to the urgent breakdown was the path of least resistance, while safe-state close-out carried no visible, immediate signal or consequence. Third, the shift handover process contained no mandatory field for communicating equipment with safety-critical systems removed or outstanding maintenance conditions, meaning the true plant state was invisible at the shift boundary and J. Martinez commenced his inspection without any system-provided information about the unresolved hazard. Fourth, no guard-position interlock, proximity switch, or equivalent engineered barrier existed on CR-047 to prevent energisation with the guard removed, meaning that every downstream administrative defence had to function perfectly to prevent harm. Fifth, in the absence of a WO close-out requirement and a task-interruption protocol, the requirement under SP-LOTO-014 to apply an out-of-service tag and maintain isolation when a task is left incomplete was effectively skippable without system consequence, removing the last physical indicator of the hazardous condition at the machine. Sixth, competing production priorities created a structurally asymmetric decision environment in which urgent breakdown response was reinforced by immediate, visible organisational signals, while safety-critical maintenance close-out was not. The investigation identified two systemic root causes. The primary root cause is that the maintenance procedure development process does not mandate the inclusion of safety-critical verification steps — specifically, guard reinstatement and isolation confirmation — as non-negotiable elements of work orders involving guard removal. This is an organisation-wide procedural design deficiency, not an isolated authoring error. The secondary root cause is the absence of standardised shift handover procedures requiring explicit communication of equipment status and outstanding safety-critical maintenance conditions. Corrective actions recommended by the investigation team address these root causes and their contributing conditions, and include: mandatory redesign of the work order template to embed guard-reinstatement and verify-before-re-energise steps as non-deletable fields; a formal review of existing conveyor work orders to confirm the scope of this deficiency across the fleet; development and implementation of a task-interruption safe-state protocol requiring a documented supervisor gate before a fitter can be redirected from an incomplete safety-critical task; standardisation of the shift handover process with mandatory structured fields for equipment status and outstanding maintenance conditions; and priority engineering of a guard-position interlock on CR-047, with a programme to assess interlock feasibility across similar conveyors. This investigation is of high quality. It applies a rigorous, systems-focused analytical methodology, correctly treats human actions as symptoms of organisational conditions rather than as causal endpoints, and produces findings and recommendations targeted at the procedural, engineering, and organisational factors that shaped the event. The work order analysis, task-interruption pathway, and shift handover critique are particularly well-developed. To further strengthen the output, the investigation team should confirm whether a formal hierarchy-of-controls review was applied to all recommended actions and should ensure that the systemic work order deficiency is addressed through a time-bounded audit of the broader conveyor maintenance library before those work orders are next used.

RISK & REGULATORY EXPOSURE

The actual outcome of this event is assessed as **HIGH**, with a credible maximum reasonable outcome of **MEDICAL_TREATMENT**. The investigation focuses on the systemic conditions identified in §5–§7; corrective actions are set out in §9. No single individual’s action is treated as the cause, consistent with a systems-based, just-culture approach.

KEY FINDINGS

- ICAM analysis identified factors in 3 categories
- 2 root cause(s) determined through 5-Whys analysis
- 4 high-priority corrective actions required

2 Incident Details & People Involved

Reference	INC-2026-0001	Actual severity	HIGH
Date & time	February 1, 2026, 11:30	Maximum reasonable outcome	MEDICAL_TREATMENT
Location	North Pit Operations	Emergency services	No
Activity / type	injury	Investigation status	Completed

DESCRIPTION

Operator J. Martinez sustained a 3cm laceration to left forearm during pre-start inspection of Conveyor CR-047. Conveyor guarding had been removed for maintenance and not replaced.

PEOPLE INVOLVED

Person	Role	Injury / outcome	Body part	Classification	Days away
J. Martinez	Loader Operator	Laceration (Laceration)	Left forearm	MTI	—

Personal identifiers are limited in the distributed report and held in the controlled investigation file, consistent with just-culture and privacy obligations.

3 Sequence of Events

- Thu Jan 15 2026 06:00:00 GMT+0000 (Coordinated Universal Time)

Shift handover completed — Night shift supervisor handed over to day shift. No issues noted with loader LDR-047.

- Thu Jan 15 2026 07:30:00 GMT+0000 (Coordinated Universal Time) — key event**
Maintenance removed conveyor guarding — Maintenance team removed guarding from conveyor section C-12 for belt replacement. Work order #WO-2026-0142.
- Thu Jan 15 2026 09:45:00 GMT+0000 (Coordinated Universal Time) — key event**
Belt replacement completed — Maintenance completed belt replacement but did not reinstall guarding. Noted on work order as pending.
- Thu Jan 15 2026 10:00:00 GMT+0000 (Coordinated Universal Time)**
J. Martinez assigned to loader LDR-047 — Operator assigned to loader for ore transport duties. Pre-start checklist initiated.
- Thu Jan 15 2026 10:15:00 GMT+0000 (Coordinated Universal Time) — key event**
INCIDENT: Laceration during pre-start inspection — While conducting pre-start inspection, J. Martinez reached into exposed conveyor area and sustained 3cm laceration to left forearm from sharp belt edge.
- Thu Jan 15 2026 10:20:00 GMT+0000 (Coordinated Universal Time)**
First aid administered — First responder applied pressure bandage. Bleeding controlled within 5 minutes.
- Thu Jan 15 2026 10:35:00 GMT+0000 (Coordinated Universal Time)**
Medical transport arranged — Injured worker transported to site medical facility for sutures.

4 Investigation Scope & Evidence Register

Lead investigator	Ian Investigator
Methodology	ICAM (Incident Cause Analysis Method)
Period	Commenced February 28, 2026 · completed February 10, 2026
Status	Completed

EVIDENCE REGISTER

Ref	Type	Description
Witness_Statement_R_Okafor_Maintenance.pdf	document	Witness statement from maintenance fitter R. Okafor, who removed the guard for belt-tracking work.
PreStart_Inspection_CR-047_2026-02-01.pdf	document	Completed pre-start inspection checklist for Conveyor CR-047 on the day of the incident.
Guard_Mounting_Points.jpg	image	Guard mounting points / fixing bolts left disconnected after maintenance.

LOTO_Isolation_Procedure_Conveyors.pdf	document	Lockout/Tagout isolation procedure for conveyor maintenance (controlling document).
First_Aid_Injury_Report.pdf	document	First-aid register entry: 3 cm laceration, left forearm; treated on site.
CR-047_Guard_Removed_Scene.jpg	image	Scene photograph: Conveyor CR-047 with the fixed guard removed.
Removed_Guard_On_Walkway.jpg	image	The removed guard panel left on the adjacent walkway.
CR-047_Nip_Point_Closeup.jpg	image	Close-up of the exposed nip point at the drive pulley.
Forearm_Laceration_FirstAid.jpg	image	Left-forearm laceration recorded during first-aid treatment.
Witness_Statement_J_Martinez.pdf	document	Signed witness statement from the injured operator, J. Martinez.
Maintenance_WorkOrder_WO-8842.pdf	document	Work order WO-8842 authorising belt-tracking maintenance on CR-047 (includes the guard-removal step).

5 PEEPO Data Collection

PEOPLE

Statement from fitter R. Okafor on task interruption and handover decisions. R. Okafor's witness statement is on file but must be interrogated specifically for: (a) who redirected him to the urgent breakdown mid-task, (b) what he understood about the obligation to leave CR-047 isolated and out-of-service when he left, (c) whether he made any attempt to communicate the guard-off status before leaving the shift, and (d) his understanding of SP-LOTO-014 requirements when a task cannot be completed in one shift. This goes to the conditions that shaped his decision to leave without reinstating the guard or applying an out-of-service tag — not to blame him, but to expose the system gaps.

J. Martinez's account of what information he received at shift start about CR-047 status. J. Martinez's witness statement is on file but needs to be mined specifically for: what he was told (or not told) about CR-047 at the shift handover, whether the pre-start checklist guided him to check guarding before approaching the drive-pulley end, and what visual cues were available that might have indicated the guard was missing. This is not about what Martinez 'should have' noticed — it is about what information the system provided to him and whether that information was sufficient to prevent approach to the exposed nip point.

Night-shift supervisor's knowledge of CR-047 guard-off status at handover. The timeline records the night-shift supervisor handing over at 06:00 with 'no issues noted with loader LDR-047.' This supervisor was on shift when R. Okafor was redirected and when the task was left incomplete. A statement or interview with the night-shift supervisor is not yet in the evidence file. This person is a critical node: they may have authorised or been aware of the redirect to the urgent breakdown, they should have known CR-047 was in a maintenance-incomplete state, and they were the person responsible for communicating plant status across the shift boundary. Understanding what they knew and why it was not passed on is essential to confirming the organisational factors around supervision and handover.

ENVIRONMENT

Physical layout and visibility of the CR-047 drive-pulley guard area during pre-start inspection. The scene photographs show the guard removed and sitting on the adjacent walkway, and a close-up of the exposed nip point. What is not yet established is: how visible the missing guard was from the normal operator inspection approach path, the lighting conditions at the drive-pulley end of CR-047 at approximately 10:30 on the incident date, and whether the walkway where the guard was left created a trip/access hazard that may have caused Martinez to deviate his approach. These environmental factors directly bear on whether the missing guard was reasonably detectable before contact.

EQUIPMENT

Design and guard-reinstatement requirements of the CR-047 fixed drive-pulley guard. The photographs show the guard removed and the mounting points disconnected. What is not yet captured is the guard design itself: how many bolts/fasteners must be reinstalled, what tools are required, how long reinstatement realistically takes, and whether the guard design makes partial reinstatement possible (i.e., could it appear in place without being fully secured). This matters because WO-8842 lists guard removal as a step but the 5-Whys analysis confirms there is no discrete guard-reinstatement verification step — understanding the design complexity of the task informs whether this is a plausible omission or a sign of a deeper procedural gap.

State of CR-047 isolation at the time of the incident — whether the conveyor was energised when contact occurred. The task analysis and 5-Whys establish that LOTO was not maintained after R. Okafor left (step 6), and that Martinez made contact with a 'moving belt' (step 10, timeline). This means CR-047 was energised and running when contact occurred — but this has not been explicitly confirmed in the PEEPO evidence. The isolation register, the local isolator position at the time of the incident, and any SCADA/control-room data showing conveyor run status should be captured to confirm the energy state at point of contact. This is critical for understanding the severity profile and for scoping the interlock recommendation.

Pre-start checklist for CR-047 on the incident date — specific guarding inspection items and their completion status. The pre-start inspection checklist for CR-047 on the incident date (PreStart_Inspection_CR-047_2026-02-01.pdf) is in the evidence files but has not been assessed as a PEEPO item in its own right. Task analysis step 9 records that the guarding condition 'was not verified before the operator moved into the drive-pulley area.' The actual checklist needs to be reviewed to establish: whether a guarding verification item exists on the form, how it is worded, at what point in the inspection sequence it appears, whether Martinez completed or skipped that item, and whether the checklist design requires the operator to physically inspect the guard before or after approaching the drive-pulley area. This is critical for evaluating whether the checklist was a usable defence or a paper exercise.

PROCEDURES

WO-8842 work order content — specifically whether guard reinstatement and out-of-service tagging are listed as explicit close-out steps. WO-8842 is on file. The 5-Whys root cause analysis concludes that 'the work order procedure did not include a specific step for guard reinstallation.' The investigator must now extract the actual text of WO-8842 to confirm: whether a guard-reinstatement step is absent entirely, or whether it exists but was not signed off; whether there is a task-incomplete/deferred field; and whether the work order required supervisor sign-off before the conveyor could be returned to service. This moves the finding from inference to documented fact.

Shift handover log/record for the night-to-day shift transition on 2026-01-15. The timeline confirms the night shift supervisor handed over to day shift at 06:00 with 'no issues noted with loader LDR-047.' The actual shift handover log for that transition has not been captured as a PEEPO evidence item. The physical record (paper or electronic) needs to be obtained to confirm: what fields the handover form contains, whether there is any field for outstanding maintenance or equipment with guards removed, and whether CR-047's guard-off status was recorded anywhere or was simply absent. This is direct evidence for the second 5-Whys root cause.

ORGANISATION

How R. Okafor was redirected to the urgent breakdown — the supervision and task-prioritisation decision at the time of interruption. Task analysis step 4 identifies R. Okafor being 'reassigned to an urgent breakdown' as the trigger that left CR-047 in an unsafe state. The investigation must establish: who made the decision to redirect him (supervisor, planner, or self-directed), whether that person was aware that guard reinstatement and LOTO clearance had not been completed on CR-047, and whether the site has any protocol for managing task interruptions during safety-critical maintenance. This is an organisational condition — the production-pressure dynamic that pulled a fitter off an incomplete task without a safe-state handover.

Procedure development and review process — how maintenance SOPs and work orders are written and whether hazard-specific verification steps are mandatorily included. The first 5-Whys root cause is that the procedure development process does not require hazard-specific verification steps. The investigation needs to capture evidence of the actual procedure development and review process: who writes WO job steps, whether there is a hazard review gate before a work order is approved, who is responsible for ensuring guarding reinstatement is a named step, and whether other conveyors' work orders have the same omission. This establishes whether the WO-8842 gap is an isolated error or a systemic deficiency across the maintenance procedure library.

6 ICAM Factor Analysis

All four ICAM levels are reported. Where no factor was identified at a level, this is stated explicitly to evidence full application of the method.

ABSENT FAILED DEFENCE

No interlock or engineered barrier prevented conveyor start-up with guard removed: CR-047 had no interlock, proximity switch, or position sensor that would have prevented the conveyor from being energised while the fixed drive-pulley guard was removed. As a result, once LOTO was not maintained after R. Okafor departed (task analysis step 6), the conveyor could be — and was — started while the nip point was exposed. An interlock tied to guard position would have converted the missing guard from a latent, invisible condition into an active, self-announcing barrier failure: the conveyor simply would not run. This is the highest-practicability engineering control available for this hazard and its absence meant every downstream defence (LOTO, handover, pre-start checklist) had to work perfectly to prevent harm. Recommendation 6 in the existing action register already identifies this control; this factor formalises its status as an absent engineered defence.

No out-of-service tag or continuing isolation applied to CR-047 when guard was removed and task left incomplete: SP-LOTO-014 requires that when a task cannot be completed in one shift, the equipment must be left isolated and tagged out-of-service until safe-state conditions are restored. Task analysis step 6 is flagged as a skipped step: no danger tag, no out-of-service tag, and no maintained LOTO were applied to CR-047 when R. Okafor left. This removed the last administrative barrier that would have visibly communicated the plant's unsafe state to any person approaching CR-047 — operator, supervisor, or otherwise. The absence of this tag made the exposed nip point invisible in the system: it appeared nowhere in the handover record and was marked by no physical indicator at the machine. The conditions that made this step skippable — no WO close-out requirement, no supervisor gate, no task-interruption protocol — are addressed in other factors; this factor records the defence that was absent at the point of hazard.

INDIVIDUAL TEAM ACTION

No factor identified at this ICAM level.

TASK ENVIRONMENTAL CONDITION

Competing production demand (urgent breakdown) created conditions where completing safety-critical close-out steps was structurally displaced: At the point of task interruption, R. Okafor faced two simultaneous demands: an urgent breakdown requiring immediate attention, and an incomplete maintenance task on CR-047 with the guard off and LOTO in place. No organisational system — no supervisor check, no WO close-out gate, no task-interruption protocol — structured the choice to ensure CR-047 was left in a safe state before he responded to the breakdown. The urgent breakdown, by definition, carried an immediate, visible production consequence; the safe-state close-out of CR-047 carried no immediate, visible consequence for leaving it incomplete. In the absence of a structured system prompt, the task environment made it easy — and in a production-pressure context, rational — to defer the guard reinstatement. This is not a characterisation of R. Okafor's values or priorities; it is a description of the task conditions the organisation had designed, in which production urgency had a louder signal than maintenance close-out compliance.

ORGANISATIONAL FACTOR

Maintenance work order lacked mandatory guard-reinstatement and task-incomplete close-out steps: WO-8842 included a guard-removal step but, per the 5-Whys analysis, contained no discrete step requiring the fitter to refit and verify the guard before the conveyor was returned to service, and no task-incomplete/deferred field requiring an out-of-service tag if the job could not be closed in one shift. This is not an oversight by the individual who wrote this one work order — it reflects a procedure development process that does not mandate hazard-specific verification steps (e.g., 'guard reinstated and secured — verify before re-energising') as a non-negotiable element of any WO involving guard removal. The gap made it structurally easy to leave the guard off: the written work did not require its reinstatement to be signed off, so there was no administrative forcing function to drive that behaviour. The investigation should confirm whether the same omission exists across other conveyor work orders, which would establish this as a systemic deficiency rather than an isolated error.

No protocol for managing task interruptions during safety-critical maintenance — production priority overrode safe-state requirements: When R. Okafor was redirected to an urgent breakdown (task analysis step 4), no organisational protocol existed to require that CR-047 be left in a documented, safe state before he disengaged. The decision to redirect him — whether made by a supervisor, planner, or self-directed — was not accompanied by any check that guard reinstatement and LOTO clearance were complete. This reflects an incompatible-goals condition embedded in the organisation's task-management system: urgent production breakdowns are prioritised and acted upon immediately, while the obligation to close out a safety-critical task (guard off, nip point exposed) is left to the individual fitter without a system prompt or supervisory gate. The absence of a 'task interruption safe-state' protocol — something analogous to an aircraft crew's 'sterile cockpit' or a surgical 'pause' — meant that incomplete, hazardous plant conditions were invisible to anyone other than the fitter who created them.

Shift handover process lacked structured fields for communicating equipment status and outstanding safety-critical work: The night-to-day shift handover at 06:00 on 2026-01-15 was completed with 'no issues noted' — yet CR-047 had a guard removed and an exposed nip point at a live drive pulley. The handover process, developed informally without structured requirements, contained no mandatory field for 'equipment with safety-critical systems removed or not reinstated' and no prompt to brief outstanding maintenance work to the incoming operator crew. This meant the true plant state (work-as-done) was invisible at the shift boundary. J. Martinez entered the pre-start inspection with no system-provided information that CR-047 had an unresolved maintenance condition. His subsequent approach to the drive-pulley end was therefore not an informed risk decision — it was the predictable consequence of an information vacuum created by the handover system. The second 5-Whys root cause directly names the absence of standardised shift handover procedures as the organisational failure.

7 Causal Analysis & Root Causes

Problem: Operator received laceration from exposed conveyor mechanism

Why 1 —

Because: Because the conveyor guarding was not in place during pre-start inspection

Why 2 —

Because: Because maintenance did not reinstall the guard after completing the belt adjustment

Why 3 —

Because: Because the work order procedure did not include a specific step for guard reinstallation

Why 4 —

Because: Because maintenance procedures are written generically without safety-critical checkpoints

Why 5 —

Because: Because the procedure development process does not require hazard-specific verification steps

Root cause: Maintenance procedure development process lacks mandatory inclusion of safety-critical verification steps, particularly for guarding and isolation reinstatement.

Problem: Guarding was removed overnight without communication

Why 1 —

Because: Because the shift handover did not include information about incomplete maintenance work

Why 2 —

Because: Because there is no formal process for communicating equipment status between shifts

Why 3 —

Because: Because handover processes were developed informally without structured requirements

Why 4 —

Because: Because the organization has not standardized shift handover procedures across all departments

Why 5 —

Because: Because operational improvements have focused on production metrics rather than communication processes

Root cause: Organization lacks standardized shift handover procedures that require communication of equipment status and outstanding safety-critical work.

8 Risk Assessment

ACTUAL OUTCOME

HIGH

MAXIMUM REASONABLE OUTCOME

MEDICAL_TREATMENT

RESIDUAL RISK RATING

HIGH

Risk is rated on the **actual** outcome and the credible **maximum reasonable outcome** of the event, consistent with ICAM and board risk-reporting practice. The maximum reasonable outcome drives the priority of the corrective actions in §9.

9 Corrective Actions

CA-1

ADMINISTRATIVE

⚠ lower-order control

Overdue

MEDIUM

Implement standardized shift handover checklist: Develop and implement a standardized shift handover checklist that includes equipment status, outstanding work items, and safety concerns requiring verbal discussion.

Owner: Operations Manager **Due:** Feb 28, 2026 **Control:** administrative

CA-2

ADMINISTRATIVE

⚠ lower-order control

Completed

MEDIUM

Add guarding inspection to pre-start checklist: Update pre-start checklists for all mobile equipment to include specific verification of safety-critical guarding with pass/fail checkpoints.

Owner: Safety Manager **Due:** Feb 15, 2026 **Control:** administrative

CA-3

ADMINISTRATIVE

⚠ lower-order control

Overdue

HIGH

Revise maintenance procedures to include guarding verification: Update all maintenance procedures involving guarding removal to include mandatory guarding reinstallation verification step with photo evidence.

Owner: Maintenance Manager **Due:** Mar 1, 2026 **Control:** administrative

CA-4

ADMINISTRATIVE

⚠ lower-order control

Overdue

HIGH

Revise the shift handover process to include a sta...: Revise the shift handover process to include a standardised structured handover format with mandatory documentation of equipment status — including any items with safety-critical systems removed or not yet reinstated — and add a guarding verification step as a discrete, named item on the operator pre-start checklist.

Due: Jun 23, 2026 **Control:** administrative

CA-5

ENGINEERING

Overdue

HIGH

Install tamper-evident guarding seals: Install tamper-evident cable seals on all conveyor guards that break when guard is removed. Guards cannot be reinstalled without new seal.

Owner: Engineering Manager **Due:** Mar 15, 2026 **Control:** engineering

CA-6

ENGINEERING

Overdue

CRITICAL

Install an interlock switch or proximity sensor on...: Install an interlock switch or proximity sensor on the quick-release conveyor guard that prevents conveyor start-up when the guard is not fully seated in its operational position.

Due: Jul 16, 2026 **Control:** engineering

10 Conclusions & Sign-off

IDENTIFIED ROOT CAUSES

- Maintenance procedure development process lacks mandatory inclusion of safety-critical verification steps, particularly for guarding and isolation reinstatement.
- Organization lacks standardized shift handover procedures that require communication of equipment status and outstanding safety-critical work.

This investigation was conducted under the ICAM methodology. The corrective actions in §9 address the systemic conditions identified and are owned, dated and tracked to completion. This report is issued for authorised distribution and review by the parties listed in the document control block.

Lead Investigator

Ian Investigator

Reviewed — Safety Manager

Approved — Site Manager