

Block 00b — authorized corrective Copilot review receipt

Status at source generation: the six new findings have scoped code dispositions; **final-head hosted CI and artifact inspection are pending**. Block 00b is not accepted, merged, or released. The corrective review itself returned **Changes recommended**, and no further Copilot request is authorized by this receipt.

Identity and boundary

- PR: [#856](#), base release/715-stack-00-audit-base at 9cb72384fd14b2a688a70d17711a7923941d2290.
- Previous remediation head: 71ce20c7df2f2401b0d605a550e38418fb5f2034; its [exact-head CI](#) passed and its first 20 Copilot findings were individually dispositioned and resolved.
- User-authorized second [Copilot review 5298915862](#) was delivered on that head, with six inline comments and no additional body-only concrete finding. The review's overview describes the intended broad firmware diff. It is **Lite / Changes recommended** (three high, three medium).
- Corrective implementation: 3eb54b36cf703eb8f86e7e86b807cde86274e597 (12 paths, 146 additions / 31 deletions). The documentation-only containing head and final CI run are recorded in the PR and master ledger after qualification. Dependency pins and C-2 bootloader policy remain as recorded in the [first-review remediation report](#).

The existing PR is a broad integration exception; this receipt covers the six newly reported contracts and affected consumers. It does not independently requalify every unchanged path in the original integration replay. A resolved thread is a disposition, not an independent clean review.

Finding dispositions and security contracts

Comment	Disposition and value origin	Observer / phase / allowed result	Forbidden result and test
4089127891	Fixed. Runtime clears sign public key, alias, icon and verified metadata originate in a user-approved signer load. ClearSession, Initialize, flash reinitialization, accepted LoadDevice, reset start and non-dry-run recovery start clear the runtime signer set. Dry-run recovery is not wallet replacement.	Later host metadata calls may use a signer only during the current wallet session, after its load consent.	Trust surviving a session end or flash reopen, or stale alias/metadata reuse. Real ReviewHandlers.SessionEndClearsRuntimeSignerAndAlias and ReopeningFlashClearsRuntimeSigner invoke the FSM/storage paths and inspect the runtime keyring.
4089127918	Fixed. The Windows DLL export and Apple arm64 linker flags use set_property(... APPEND_STRING PROPERTY LINK_FLAGS ...), supported by the declared CMake 3.7.2 baseline. Both former target_link_options calls are removed.	CMake configures supported platform conditions without requiring a newer command.	Rejection of the Windows DLL configure from the unavailable command. Source mechanical check and final macOS CI cover the Apple branch; local complete MinGW configuration is blocked by missing nanopb generator. No Windows runtime qualification is claimed.
4089127945	Fixed. Host EthereumTxMetadata.key_id remains full-width until a range check; only values below METADATA_MAX_KEYS reach the uint8_t consumer.	A valid key selects only its intended slot before a metadata acknowledgment.	256 wrapping to slot 0 or any other out-of-range alias; ReviewHandlers.MetadataKeyIdRefusesNarrowingBeforeAck passes 4, 256 and UINT32_MAX to the actual handler and requires a failure.
4089127974	Fixed. BIP-85 was already specified in the pinned wire protocol and supplied as source, but could not run. Full firmware now compiles bip85.c, includes the handler, and dispatches GetBip85Mnemonic; shared sensitive display scratch has explicit declarations. Bitcoin-only still excludes this non-BTC addition.	An initialized, PIN-checked user can confirm an on-device child mnemonic, with Success only after pages; the mnemonic never enters a response.	Dormant wire command, incorrect derived words, success after cancellation, or residual display scratch. The real handler regression exercises cancellation and success/page cleanup; an independent Python BIP32/BIP39 oracle for the test mnemonic yields eternal siege creek hand combine grass name balance identify rude ozone truly at index 0. The path and HMAC construction follow BIP-85 . Physical OLED is a later release gate.

Comment	Disposition and value origin	Observer / phase / allowed result	Forbidden result and test
4089128007	Fixed by removing the unused public formatter and declaration. The active handler's <code>osmosis_format_amount</code> remains the only amount renderer; it preserves exact integer strings when the denomination's exponent is unknown.	User sees the value used by the active signing confirmation path.	A second, divergent <code>strtoull</code> formatter presented as active safety coverage. Existing Osmosis handler/native tests and final host tests exercise the active path.
4089128031	Fixed. <code>storage_init()</code> recomputes both firmware-too-old and Bitcoin-only locks from the flash buffer opened in this invocation.	A newer unsupported record remains non-destructively locked; a later supported/empty record in the same process is usable.	Old lock inheriting across flash reopen and silently discarding commits. <code>ReviewHandlers.StorageReinitializationRecomputesFirmwareLock</code> seeds a newer record, checks the refusal, reopens a normal buffer, then checks the lock and ability to load a wallet. The earlier newer-format flash-preservation test remains.

Final-run regression correction

CI [35948487332](#) built both variants, ARM, host integration, and the macOS library successfully. The full firmware suite ran 354 tests: 353 passed and one newly added BIP-85 success-path assertion failed. The handler succeeded and wiped display scratch; the test had treated `kkconfirm_drain()` as a count of confirmations when it counts two queued button events per confirmation. Twenty accepted confirmations queue 40 events; four observed screens leave 32. The one-line test correction asserts that exact count. The downstream report gate failed because the native suite failed. This run is failure evidence, not qualification; the follow-up must pass at its own final head.

Executed checks and limits

The focused full-emulator handler run passed **9 of 9 tests** after the initial code changes, including the BIP-85 oracle, session end, full-width key rejection and storage lock regression. A new flash-reopen signer assertion and the BIP-85 success/page-scratch assertion were added afterward; they require final-head CI. The independent Python BIP32/HMAC/BIP39 calculation reproduced the explicit child phrase above without calling firmware code. `actionlint`, formatting and diff-whitespace checks pass.

The local full/BTC Docker matrix could not start after the host disk filled; Docker's metadata database reports a read-only filesystem. Pruning unused Docker build cache was attempted and failed for the same reason. The host MinGW CMake configure reached compiler checks but stopped at the absent `nanopb` generator before the DLL target; it is not a Windows build pass. Final-head CI must demonstrate full/BTC native tests, host integration, ARM/SRAM, macOS shared library tests, report generation and release gates before these six dispositions are qualified. Earlier CI belongs to the earlier head and cannot qualify this commit.

The one-request-per-corrective-checkpoint limit is exhausted: review [5297484301](#) covered the earlier original candidate and review [5298915862](#) covered `71ce20c7d`. Any later source change makes the second verdict historical. Do not request a third review automatically or relabel either **Changes recommended** verdict as clean. Continue the batch from the canonical main ledger with audit acceptance pending.