

Stack 07 remediation and first-review retrospective —

2026-09-24

Scope, ownership and review identity

This is the full retrospective for the first Stack 07 Copilot round, including the defects found during remediation and predecessor integration. The main firmware worktree owns the SOP, master ledger and `audit-claims/715-07/OWNER.md`; agent 2 retains this claim. The earlier intake document is historical evidence, not the current status.

The owner authorized one immediate request on code-bearing [PR #837](#). Request time: 2026-09-24T02:20:47Z. [Review 5298993214](#) arrived at 02:29:47Z on historical head `4695a11444fa6a3bb990e59d000b8149bc5b74f3`, against historical Stack 06 base `b771669ba842d83790a69b6132f63cea82e5a861`. Its verdict was **Changes recommended**, effort Lite, with **13 comments: 11 high, one medium, one low**. The preliminary triage incorrectly read “11” as the total; this report corrects that counting error. The body repeats the same policy, binding, authentication, array and header concerns; it supplies no separate actionable finding beyond these 13 comments.

There has been **one Stack 07 request and no second request**. The owner requires remediation and this retrospective before considering any further round. The delivered review is historical and must never be represented as a review of the corrective candidate.

What went wrong

The failure was substantive. Reviewed calldata was not committed to the bytes eventually signed, a certified typed-data program could omit later display fields, and nested fixed-array validation was wrong. Header guards, direct-call range validation and the release narrative also escaped preflight. Parser unit coverage and successful links did not establish the complete signing contract.

The implementation distributed authority over several passes: authenticated definition replay, ABI or typed-data traversal, UI confirmation, and final signing. Tests validated each piece but did not prove that the values and schemas stayed identical between pieces. They also did not exercise a real signed catalog through every host/device continuation and cancellation path. That gap explains both the review's calldata finding and the additional schema, ownership, domain and identity defects found while repairing it.

The first request reviewed a historical branch while the predecessor audit was still changing. That made its result useful for discovery but insufficient for acceptance. Reconciliation later introduced a concrete interaction failure: Stack 06's stricter dispatcher aborted the new Stack 07 continuation messages. The ordinary host suite passed while six of seven new authenticated protocol tests failed. Only running the complete new workflow on the integrated predecessor exposed it. Those tests are now registered in the repository CI runner.

There was also an earlier wrong-PR review request during the Stack 05/07 transition. That was an execution error, not Stack 07 coverage. Before any future authorized request, record the explicit PR number, immutable head, actual base, claim owner and code-bearing diff together. This review budget does not authorize an automatic retry.

Disposition of every review comment

Comment	Disposition	Change or technical basis and executed evidence
4089197347	Fixed	The EIP-712 include guard now encloses every public declaration. The native test translation unit includes the header twice and compiles.
4089197364	Fixed	SHA-256 commits the validated selector and calldata. Every display replay and the actual signing pass must match it. Native chunk-boundary tests and a host mutation on the fourth/signing pass reject changed bytes.
4089197391	Fixed	Array-level count is checked before indexing the wire array. TypeNameRejectsArrayCountPastWireCapacity covers the direct helper boundary.

Comment	Disposition	Change or technical basis and executed evidence
4089197421	Fixed	Frames retain every declared dimension and consume the outermost, last-written dimension first. NestedFixedArrayChecksOuterAndInnerDimensions rejects wrong inner and outer lengths; disabling this check makes the test fail.
4089197450	Fixed	Only the canonical singleton empty root tuple is accepted; malformed empty nested structures remain invalid. ABI tests and the real selector-only signing host test pass.
4089197469	Refuted	Adding a bounded nonnegative child count to a negative int32 value cannot overflow either signed bound: the minimum is INT32_MIN and the maximum is below the bounded count. A still-negative result is refused. ExtremeNegativeIndexFailsWithoutArithmeticWrap checks INT32_MIN.
4089197498	Refuted as stated	The signed Merkle leaf hashes the entire program, including its identity header. Certificate scope must equal the signed chain and its public key must equal the loaded runtime key that verifies the signature. SignatureAuthenticatesHeaderAndRuntimeKeyContext signs a real envelope and rejects changed epoch, scope and key; AdvancedMode-off also fails. Host certificate alias is never displayed as authority; the approved runtime alias/fingerprint is used.
4089197515	Fixed, same root cause as 4089197450	The streamed catalog validator accepts the same canonical empty root. Catalog authentication and selector-only host signing cover both layers.
4089197543	Policy clarification	Ordinary streamed EIP-712 validates, displays and hashes every leaf and remains available in normal mode. Runtime-certified annotations and blind precomputed hashes require AdvancedMode. The PR's blanket "streaming behind AdvancedMode" description was inaccurate; the report preserves the actual established policy rather than disabling ordinary disclosed signing.
4089197567	Fixed	Every certified typed field is selected and confirmed. Repeated message walks must preserve the domain/message digest and schema commitments before signing. Host tests require both fields, identical ordinary/certified signatures, refusal of changed second-pass values, and cancellation at either field.
4089197583	Same policy clarification as 4089197543	The certified entry is AdvancedMode-gated; the ordinary fully disclosed stream is a separate contract. Native policy/authentication and host ordinary/certified tests cover the distinction.
4089197600	Fixed	ethereum_signing_init() again calls the full chain-ID validator. DirectSigningEntryRejectsChainIdAboveMaximum exercises the direct entry in addition to the FSM guard.
4089197619	Fixed	The alpha handoff is explicitly historical; it distinguishes the bounded 7.15 extraction from the complete alpha design. Correction originated in 1679e17dc.

These are nine fix comments covering eight distinct roots, two overlapping policy comments, and two technical refutations. Resolution means a pushed fix or a reasoned reply, not deleting or moving an anchor. GitHub thread status is recorded separately in the publication receipt.

Additional defects found and repaired locally

Defect	Prior behavior	Repair and evidence
Schema replay substitution	The host could change a named schema between discovery, type hashing and value traversal.	Canonical schema digests are retained and checked throughout the session. <code>RefusesSchemaChangesAfterDiscoveryAndHashing</code> fails when that protection is removed.
ABI program-view lifetime	Streaming state retained a pointer to a temporary caller program view.	The stream owns the small view by value; nodes remain owned by the workflow loader. Native coverage overwrites the caller view after initialization. Layout padding was reduced to retain the existing bounded workflow budget.
Signed domain constraints ignored	Matching type, chain and contract did not enforce descriptor name/version/salt or absence assertions.	The loader retains signed domain operations/literals; validated stream facts must satisfy each supported constraint before certified message review. Native equality/absence tests and host name/version/salt substitutions fail closed.
Runtime source and intent absent	Authenticated alias existed but was not shown; typed-data intent, including intent-only programs, could be omitted.	Show the approved runtime alias/fingerprint, "NOT verified by KeepKey", then intent. Preserve ordinary review. Host screen counts, cancellation cases and inspected OLED frames cover both fields and intent-only programs.
Integrated dispatch and cleanup	Stack 06's default abort rejected valid new continuations; EIP-712 stream cancellation was not part of common signing cleanup.	Phase-specific continuation admission; session boundaries and auto-lock clear typed state. Only validated active-workflow requests renew the deadline. Actual receive-path tests prove typed progress renews, <code>GetFeatures</code> polling eventually locks, and stale acknowledgements fail.

Main repair commits are 590d9901b and ec4c42509. Candidate code head is 34a36e700, integrating Stack 06 corrective head 8ed653517a63278891353bcf939a9c3108feacb2. Stack 06 acceptance remains its owner's decision; integration alone does not confer acceptance.

Security contract and falsification matrix

State/value and origin	Observer, variant and phases	Allowed and forbidden outputs; equivalent representations	Assertion/counterexample
Host calldata bytes	Firmware parser, user OLED, signer; full only; parse/review/replay/sign	Sign only the reviewed exact selector+arguments. Same ABI shape or formatted value is not sufficient equality.	Change a value only in the actual signing pass; reject. Change chunk boundaries without changing bytes; accept. Disable digest comparison; native test fails.
Host typed schema and values	Type-hash walker, user, signer; full only; discovery/hash/repeated fields	One canonical schema per name and one domain/message digest. Different schema or value encodings must not change signed meaning after consent.	Mutate named schema and second-pass message; reject. Disable each commitment independently in the focused mutation run; corresponding assertions fail.
Signed descriptor identity/domain	Catalog verifier and user; full only; preload/match/UI	Program header authenticated by leaf hash; runtime scope/key checked; signed equal/absent constraints enforced. Host alias cannot impersonate approved source.	Real signature fixture with changed epoch/scope/key; name/version/salt substitution; exact runtime alias observed on OLED.

State/value and origin	Observer, variant and phases	Allowed and forbidden outputs; equivalent representations	Assertion/counterexample
Runtime annotations and consent	User and signer; full only; source/intent/every field	Source/warning/intent and every field precede signature; annotations never remove ordinary review. Rejecting any protected screen returns no signature.	Decline source, warning, intent and each field; fresh ordinary session succeeds. Certified and ordinary signatures match for unchanged input.
Untrusted array counts/indices	Parser memory and signer; full only; type formatting/nested traversal	Wire bounds and every fixed dimension enforced before use. INT32_MIN must remain a rejected index.	Oversized count, wrong inner/outer fixed dimension, extreme negative index; dimension mutation test fails.
Workflow timer and state	Device lock/session state; full signing, both-product shared cleanup	Only validated progress renews. GetFeatures, malformed/stale acknowledgements, abort and unrelated commands cannot keep or revive signing.	Actual receive callback with valid typed progress near expiry, repeated polling to lock, session boundary loop and stale continuation refusal. Existing shared malformed/tiny receive tests run in both variants.
Product separation	Firmware link/message map; BTC-only	No ERC-7730 or streamed EIP-712 signing surface in BTC product.	Both ARM links, BTC native/host suites; new protocol suite explicitly skips BTC. Physical device execution remains unavailable.

The separate falsification pass deliberately removed calldata commitment, typed digest commitment, schema equality and inner fixed dimensions. All four selected tests failed, then the original source bytes were restored and rebuilt. The final full native suite passes with the protections restored. Negative-control XML/logs are preserved; failing a mutation is expected evidence, not a product failure.

Validation record and limits

Pinned builder: `kktech/firmware@sha256:7438e53933d47d53157ed6d96d864cb208597e62dce26235ace09d1063427fa2`. Host pin: `b745562be6a13cc83b2a547d7ef86637f4556dbb`. Candidate firmware/native results: full 598 passed; BTC 134 passed. Full and BTC ARM products link. RAM gap between `_ebss` and `_stack`: full 18,900 bytes, BTC 39,140 bytes, both above the 16,384-byte static floor. This is not a measured worst-case physical stack watermark.

Seven authenticated host regressions passed after the dispatch repair with OLED capture. Inspected images show “Audit signer (0C2C88B9)”, “NOT verified by KeepKey”, “Audit action”, “First value 42” and “Second value 7”. These use a public test mnemonic and throwaway signing key, not production credentials. The final broad host result and exact evidence hashes are recorded in the accompanying candidate receipt.

Failures retained in the evidence history: the initial Docker read-only/disk outage prevented execution; an initial mutation-script pattern assertion failed before mutations ran; reused native flash state failed a recovery precondition while fresh isolated runs passed; integrated authenticated contracts initially failed 6/7 before dispatch repair; and a final host invocation used `KK_STAGED_MISSING_CAPABILITIES` instead of the workflow's `KK_RELEASE_MISSING_CAPABILITIES`. The incorrect environment did not activate staged exclusions and produced later-block failures; corrected results must not overwrite that evidence or relabel excluded capabilities as covered.

No physical device was flashed, no production signing was performed, and no release was promoted. Full ERC-7730 v2 conformance and later release-stack capabilities remain outside this bounded extraction. Hosted exact-head CI and predecessor acceptance are separate statuses from these local checks. A historical green result or a resolved thread is never a current-head clean review.

Hosted qualification correction

First corrective hosted run 35962710863 on `e46aae5fd` passed all native, static, ARM and BTC integration jobs, but full integration stopped at the screenshot audit: `test_clearsign_erc20_approve_unlimited` passed its refusal assertion and captured zero screens, while the report incorrectly declared two. The frozen local preflight had inspected the new Stack 07 frames and JUnit validation, but did not replay the full existing screenshot declaration set after enabling `erc7730-runtime-review`. That omission belongs to this audit, not to an infrastructure explanation.

The firmware already refuses unlimited approval before any `ButtonRequest`. Published host correction `1d42a1fa401129da292a8b0fe4f6dc9bee727117` describes that exact screenless contract, removes the invalid full-sequence claim, and strengthens the actual wire test to require immediate Failure with no intervening `ButtonRequest`. Nearby generated report prose now correctly states AdvancedMode ON with annotations additional to ordinary raw review. No firmware policy,

assertion or screenshot gate was weakened. Seven focused refusal/report tests pass; replaying the corrected screenshot audit against the actual hosted artifact passes. Firmware source remains identical to the locally validated implementation. New-pin final hosted CI is recorded in the PR receipt.

Prevention: before the combined matrix, run the report-required screenshot audit across all newly enabled legacy cases, not only newly authored protocol tests. A successful wire test with no frames is valid only when the report declares a refusal contract and the wire assertion prohibits intervening approvals.

Prevention and next-round discipline

- Pin the claim, PR, actual predecessor and immutable head before any external request. Verify the diff is code-bearing and belongs to the named block.
- Write a property matrix across parse, replay, display, signing, failure and restart before treating unit counts as security evidence.
- Require at least one real authenticated protocol fixture for each new signing path, including every display field, an alternate-pass mutation and user decline. Keep these fixtures in the CI runner.
- On predecessor changes, inspect dispatch admission, shared abort routines, timers and retained state explicitly. Run the new workflow on that exact integration before freezing evidence.
- Freeze source before the expensive matrix; use the exact workflow capability variable and list every skip. Preserve failed runs and explain the correction.
- Keep report language aligned with policy: ordinary disclosed streaming, runtime-certified annotations and blind hashes are distinct contracts.
- Do not request another review to discover whether an untested repair worked. Complete the local checks, full retro, pushed dispositions and preflight first; then obtain the owner's explicit authorization for any further round.

Completion states

Implemented: confirmed code defects and additional integration findings repaired. Targeted behavior: native and seven protocol cases pass. Adversarial checks: four negative controls detected the removed protections. Integration: final full/BTC native and ARM complete; broad host results tracked in the candidate receipt. External review: one historical review delivered with findings; no current-head review requested. Findings dispositioned: technical dispositions above, publication/thread closure tracked separately. Release accepted: **no**.

Later predecessor reconciliation — Stack 06 `ff956077f`

This section was added after the complete first-round retrospective. Stack 06 moved from `8ed653517` to `ff956077f` with a global ERC-20 allowance guard and three native regressions; its audit remains separately owned and its final review checkpoint is still open. Stack 07 merged the new head without conflict. Source inspection found an interaction the earlier Stack 07 tests could not cover: certified calldata begins with only four selector bytes, while the new predecessor policy needs the complete 68-byte approval prefix before any confirmation. A certified `approve(address,uint256)` could otherwise show runtime annotation screens and then fail at the ordinary signing entry.

The bounded certified path now refuses every approval selector immediately after matching the preloaded definition and before definition replay or annotation screens. The preload is cleared. A new real signed-envelope host regression requires zero `ButtonRequests` and the explicit failure, then proves a finite 68-byte ordinary approval still reaches signing. This is deliberately narrower than supporting certified approval: the current selector-only continuation cannot satisfy the predecessor's pre-review allowance policy. A future implementation would need to validate the full prefix before UI and bind those exact bytes to the signing stream.

The updated report/receipt records full, BTC, ARM, host, protocol, OLED and SRAM results against this merged tree. Earlier review `5298993214` and its dispositions remain historical; this merge is not covered by that review. No second Copilot request follows from adding this section.

Final predecessor compatibility and SRAM repair — Stack 06 `efdeb678b`

The Stack 06 owner's third review found that its 8-entry `CoinTable` cap broke the bundled HDWallet default 10-entry request. Stack 06 restored its accepted predecessor's 24-entry cap at `efdeb678b`. Stack 07 merged that head without a source conflict, but the first full ARM link failed its 16 KiB reserve assertion: the shared FSM response union grew by 3,768 bytes, leaving 15,132 bytes alongside Stack 07's authenticated-workflow state. A conflict-free merge was therefore not a qualified integration.

The repair keeps the 24-entry wire contract. GetCoinTable copies and validates its request fields before placing the response in the already allocated decoded-request buffer. That buffer is cleared when the handler returns. The single-threaded transport does not dispatch another normal message during the handler, and outbound encoding uses its separate frame arena. Compile-time size and alignment assertions guard the response; the ordinary response union still bounds every other response via RESP_INIT. A new full/BTC wire regression verifies 10- and 24-entry full pages, the two-entry BTC page, invalid-range refusal and a valid follow-up. The inherited native CoinTable test, 602/135 firmware suites, broad host and both ARM links pass. Exact SRAM gates report 18,896 bytes full and 39,136 BTC, with a 7,664-byte largest frame in each.

The first standalone broad-host invocation lacked the child emulator binary required by five storage power-cycle tests, so those tests skipped; both variants passed all five when run separately with the rebuilt binary. The final broad invocation mounts that binary and executes the five inside the same 739-pass/92-skip full and 347-pass/484-skip BTC runs. This was a harness setup error, preserved here rather than counted as device coverage from a skip. The nine-case Stack 07 suite passes in full; BTC passes CoinTable and deliberately skips eight Ethereum cases. The report and exact-head CI receipt track the frozen final source.

Prevention: after every predecessor change, run both ARM links and resource gates before freezing a successor's report. Inspect shared protobuf response sizing when a predecessor raises a repeated-field cap. Use the workflow-equivalent child emulator mount for broad host validation so reboot tests do not silently change from pass to skip. Stack 06's own external review/acceptance remains separately owned; this integration does not turn the historical Stack 07 Copilot review into a current-head verdict.

First hosted run on the 24-entry predecessor — CI 36058831515

The first exact-head hosted attempt at 651db1062 failed its lint and static-analysis prerequisites; downstream build and test jobs were skipped, so that run cannot qualify the candidate. Hosted clang-format 20 reported one fsm.c macro token disagreement with the locally available clang-format 22. The static-analysis script runs cppcheck under bash -e; a nonzero cppcheck result ended the step before it printed the report, leaving only a generic exit-code annotation. Reproducing with Ubuntu cppcheck 2.13 exposed the actual findings: generated byte-array union members marked unused, two redundant has_end checks after equality validation, and a subtraction-based token bound that the analyzer interpreted as an unsigned-underflow comparison.

Code head 92774faeb uses clang-format 20's spelling, adds a compile-time size assertion for every generated response member so those members have an explicit use, and expresses the already validated CoinTable branches directly. The request still requires paired start/end fields before reclaiming decode storage. Ubuntu cppcheck 2.13 and local cppcheck 2.20 both report zero findings. Both ARM links and SRAM gates pass; fresh-flash native suites pass 602 full and 135 Bitcoin-only, and the current-source wire suite passes 9 full / 1 pass with 8 deliberate Bitcoin-only skips. An initial native rerun from the mounted build directory reused an emulator flash file and failed a recovery precondition; the isolated clean working directory used by CI passed. The failed run and harness error are retained here as process evidence, not counted as device failures or successful hosted qualification.

Prevention: run the exact CI formatter version and cppcheck version locally before freezing the head, especially for generated macros. Capture static-analysis output even when cppcheck exits nonzero so hosted failures identify their findings. Keep native test flash state isolated per run.

Second Copilot review and full retrospective — 2026-09-24

The owner authorized exactly one final current-head Copilot request on PR #837. Timeline event 31792648799 registered it at 21:41:08Z against 9e03d46ab9f9b39bdf891f364e5c94fc637b7509, with accepted Stack 06 base efdeb678bc33c616cf8048fb5773548f0da96fa7 and green exact-head CI 36061113501. Review 5310618825 arrived at 21:47:00Z with **Changes recommended** and seven inline findings: four P1 and three P2. Its body says “Findings: 4,” which describes the high-priority subset, not the total. This review is historical after the repairs below; it is not a clean review of the repair head. The request budget is spent, and no third request is authorized.

Comment	Priority	Disposition and evidence
4098815643	P1	Fixed. The FSM used the same CALldata phase for review and final signing replay, so a nonzero-argument certified transaction could loop instead of signing. A dedicated signing-pass bit sends final ACKs to ethereum_signing_txack, where the ABI stream and reviewed SHA-256 digest are still checked. The real signed-envelope success case matches the ordinary signature with four calldata passes; fourth-pass mutation still fails.

Comment	Priority	Disposition and evidence
4098815698	P1	Refuted. The cleanup at the END display opcode occurs after the final certified field has been selected, rendered and confirmed. <code>eip712_stream_definition_accepted()</code> resumes the message value walk; the catalog preload is no longer needed for those values. The real two-field certified fixture confirms both fields, observes both replayed leaves, and produces the ordinary signature. Declining either field fails.
4098815742	P1	Fixed. A definition identity mismatch while the workflow is IDLE, or an earlier typed-stream failure, could leave the preloaded envelope for a later request. Explicit cleanup now covers definition refusal and CANCELLED/FAIL pump exits. Wire regressions preload a signed definition, fail on a different chain ID or malformed primary type, then complete an ordinary request without inherited certified metadata.
4098815785	P1	Fixed. The ordinary stream could complete an empty message after only domain confirmations. A message with zero confirmed values now requires an explicit final consent screen before REQ_DONE; declining returns Failure without a signature. The wire test covers decline and acceptance. Nonempty messages keep their established leaf approvals.
4098815825, 4098815868	P2	Fixed. Restored <code>warn_unused_result</code> on both amount-format declarations; existing callers check the result. Both product builds pass.
4098815909	P2	Fixed. Removed duplicate data-hash state cleanup in <code>ethereum_signing_abort</code> ; one scrub remains.

The primary process failure was a missing **successful final replay** fixture. The old negative case changed the fourth pass and expected refusal; it passed without proving that an unchanged fourth pass could ever reach the signer. The state name CALldata hid the distinction between verification and signing. Future cross-phase tests must include a positive signature equality case and a mutation case for every replay transition, with the same nonzero payload.

The second gap was session-boundary reasoning. `erc7730_workflow_abort()` intentionally leaves preload untouched when the workflow is IDLE so a newly loaded definition survives until its next signing request. That is valid at the transaction entry but unsafe after a failed typed-data start. The repair clears the catalog at the specific failed terminal exits, and the tests immediately start another ordinary request to catch stale state. The related review comment about cleanup after the END display was investigated separately with a two-field replay rather than classified by proximity.

The third gap was a zero-leaf consent path. The schema and hash are valid for an empty primary struct, so a parser rejection would conflate protocol validity with consent. A final visible confirmation gives the user an explicit decision without altering canonical hashing. The negative test requires a Failure on decline, and the positive test requires a signature only after acceptance.

The two `warn_unused_result` findings and duplicate scrub are small but legitimate review regressions. They were repaired because they are simple to verify and improve future caller discipline. No second-review P1 is accepted as minor. The repaired head requires a fresh exact-head CI result and review-thread dispositions before a third review could be proposed to the owner. Neither the older green CI nor resolved historical threads can make this review clean.