Bombardier

Work Order #	2498069	**Aircraft SN #**	6111	**Customer #**	42082
Description	ACSN 6111 || 06/12/24/48/96 Month, 600 Hour, Paint, Interior	**Aircraft Reg #**	XA-SOL	**Customer Name**	Capella Flight LLC
Location	TUS-3050	**Model #**	650	**Proposal #**	BBD-12774
Service Center Reg #	KW3R646L	**A/C Hours**	1,735.4	**MWPWO #**	2498069
Status	INPRG	**A/C Cycles**	950	**SAP SO #**	281501
Lead	Tyler Poggi	**Supervisor**	Nickolas Pelletier	**CPM**	Bryan Carpentier

Sequence #	0002	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	3154408	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

0002	**WO #**	**3154408**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #	13276348	No Log Entry	
Work Preparation / Administration / Initiation				
Task / IRN # : WORK PREP				

Sequence #	0002	Aircraft SN #	6111	MWPWO #	2498069
WO #	3154408	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Performed visual walk-around form QA032 for details	B1013522 - Brandon Jennings Feb 02, 2026 09:09 PM	
	Visual Walk-Around Preliminary Inspection		Not Required	
	200	Complied With Inventory the Aircraft for Customer Items	B1001500 - Victor Gallego Feb 03, 2026 08:35 PM	
	Inventory the Aircraft for Customer Items		Not Required	
	300			
	Request the Log Books for the Aircraft From the Customer		Not Required	
	400	Protected the exterior of the aircraft as required.	B0161867 - Jeremy Kucera Feb 07, 2026 01:10 AM	
	Protect the Exterior of the Aircraft		Not Required	
	500	Complied With Protect the Interior of the Aircraft	B1001500 - Victor Gallego Feb 03, 2026 08:35 PM	
	Protect the Interior of the Aircraft		Not Required	

Sequence #	0003	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	2503650	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

0003	**WO #**	**2503650**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #	13276305	6 month inspection	
6 month inspection				
Task / IRN # : C3500055				

CHILD WORK ORDER DETAILS

	WO #	Description	Corrective Action	AMENDED
0003-1	2503920	Functional Test (Capacity Check) of the Main Battery		
0003-2	2503923	Functional Test (Capacity Check) of the APU Battery		

Sequence #	0003-1	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503920	Aircraft Reg #	XA-SOL	Parent WO #	2503650

0003-1	WO #	2503920	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Functional Test (Capacity Check) of the Main Battery	
Functional Test (Capacity Check) of the Main Battery				
Task / IRN # : 24-30-00-202				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with Removal of the Main Battery. REF CL-650 AMM 24-32-01-000-801	B0641378 - Calvin Ambrose Feb 04, 2026 05:38 PM	24-30
	Perform removal of Main Battery		B0143196 - Robert Bohner Feb 04, 2026 07:22 PM	
	200			24-30
	Perform Functional Test (Capacity Check) of the Main Battery			
	300			24-30
	Perform installation of Main Battery			
	400	Removed Tow Hitch from the Nose Door to FOM by pulling the locking T-pin and pressing down the spring loaded locks.	B0641378 - Calvin Ambrose Feb 04, 2026 05:38 PM	
	Remove Tow Hitch from the Nose Door to FOM.		Not Required	
	500			
	Install the Tow Hitch located in the Nose Door			

Sequence #	0003-1	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503920	Aircraft Reg #	XA-SOL	Parent WO #	2503650

REMOVE AND RE-INSTALL DETAILS

	Removed Part # Removed Serial #	Removed By	Removed - Part Description	Reference	Installed Part # Installed Serial #	Installed By
	Removed Status	**Removed Date-Time**	**Position**	**Installed Part Status**	**Installed Part Description**	**Installed Date-Time**
	601R59041-3 09052001ED6B6	B0641378 - Calvin Ambrose	BATTERY, MAIN, MODEL 1756-3	CL-650 AMM 24-32-01-000-801		
	SERVICEABLE	Feb 4, 2026 10:27 AM	MAIN			
	WY-602 8149	B0641378 - Calvin Ambrose	HEAD ATTACHMENT, TOWBAR			
	SERVICEABLE	Feb 4, 2026 10:35 AM	NOSE			

Bombardier

Sequence #	0003-2	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503923	Aircraft Reg #	XA-SOL	Parent WO #	2503650

0003-2	WO #	2503923	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Functional Test (Capacity Check) of the APU Battery	
Functional Test (Capacity Check) of the APU Battery				
Task / IRN # : 24-30-00-203				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with Removal of the APU Battery. REF CL-650 AMM 24-32-04-000-801.	B0641378 - Calvin Ambrose Feb 04, 2026 05:26 PM	24-30
	Perform removal of APU Battery		Not Required	
	200			24-30
	Perform Functional Test (Capacity Check) of the APU Battery			
	300			24-30
	Perform installation of APU Battery			

REMOVE AND RE-INSTALL DETAILS

	Removed Part # / Removed Serial #	Removed By	Removed - Part Description	Reference	Installed Part # / Installed Serial #	Installed By
	Removed Status	Removed Date-Time	Position	Installed Part Status	Installed Part Description	Installed Date-Time
	600-59151-11 09052001F098B	B0641378 - Calvin Ambrose	BATTERY, APU, MODEL 40178-24	CL-650 AMM 24-32-04-000-801		
	SERVICEABLE	Feb 4, 2026 10:17 AM	APU			

Sequence #	0004	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	2503649	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

0004	**WO #**	**2503649**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #	13276286	12 Month inspection	
12 Month inspection				
Task / IRN # : C3500005				

Sequence #	0004	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503649	Aircraft Reg #	XA-SOL	Parent WO #	2498069

CHILD WORK ORDER DETAILS

	WO #	Description	Corrective Action	AMENDED
0004-1	2503659	Lubrication of the Bent-Up Trailing Edge (BUTE) Door Hinge	Complied with task 27-50-00-206 Lubrication of the Bent-Up Trailing Edge (BUTE) Door Hinge IAW CL-650 AMM 12-20-04-640-810.	
0004-2	2503660	Operational Test of the Emergency Lights	Complied with TLMC Task 33-50-00-202, Operational test of the emergency lights. REF CL-650 AMM 33-51-00-710-801. Op Test Good.	
0004-3	2503661	General Visual Inspection of the Aft Equipment Compartment – Internal	Complied with Task 53-ZL-00-228. Performed General Visual Inspection of the Aft Equipment Compartment – Internal,in reference to CL-650 AMM 53-30-01-210-806. See finding 79228 for details.	
0004-4	2503666	Lubrication of the Ball Nut of the Flap Actuators	Complied with task 27-50-00-203 Lubrication of the Ball Nut of the Flap Actuators IAW CL-650 AMM 12-20-04-640-813.	
0004-5	2503667	Lubrication of the Flap Vane Actuator Rods	Complied with task 27-50-00-205, Lubrication of the L/H and R/H Flap Vane Actuator Rods, in accordance with CL650 AMM 12-20-04-640-809.	
0004-6	2503668	Functional test of the Emergency Lights Power-Supplies (ELPS)		
0004-7	4307834	*23-CARS-625-15(C) FUNCTIONAL CHECK OF CVR		
0004-8	4308904	*31-CARS-625-17 PERFORM FDR CORRELATION CHECK	PERFORM FDR CORRELATION CHECK, (DOWNLOAD OF FDR) in accordance with CL-650 AMM 31-31-00-970-801. SENT DOWNLOADED DATA TO VENDOR FDR CORRELATION CHECK Provided Vendor Report/Read out to Customer (see attachment). This complies with customer code 31-CARS-625-17 PERFORM FDR CORRELATION CHECK. No defects noted.	
0004-9	4308955	*NOM-022-SCT3-2011/12.2.2-1 DOWNLOAD AND ANALYSIS OF FDR	Provided FDR Download (performed under Maximo wo 4308904) to Vendor for readout. Report provided by Vendor after readout (see attachment). This complies with Customer task NOM-022-SCT3-2011/12.2.2-1 DOWNLOAD AND ANALYSIS OF FDR. No defects noted.	
0004-10	4309008	*NOM-022-SCT3-2011/12.2.2-2 DOWNLOAD AND ANALYSIS OF CVR		

Sequence #	0004	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503649	Aircraft Reg #	XA-SOL	Parent WO #	2498069

CHILD WORK ORDER DETAILS

	WO #	Description	Corrective Action	AMENDED
0004-11	4309479	*23-CARS-625-15(D) INTELLIGIBILITY CHECK OF CVR	Complied with *23-CARS-625-15(D) INTELLIGIBILITY CHECK OF CVR. IAW. CL-650 AMM 23-71-00-750-801. STEPS 1- 4. (GROUND PROCEDURE) Continue with step G	

Sequence #	0004-1	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503659	Aircraft Reg #	XA-SOL	Parent WO #	2503649

0004-1	WO #	2503659	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Lubrication of the Bent-Up Trailing Edge (BUTE) Door Hinge	
Lubrication of the Bent-Up Trailing Edge (BUTE) Door Hinge				
Task / IRN # : 27-50-00-206				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 27-50-00-206 Lubrication of the LH Bent-Up Trailing Edge (BUTE) Door Hinge IAW CL-650 AMM 12-20-04-640-810.	B0650736 - Jesus Gonzalez Atondo Feb 12, 2026 07:47 PM	12-20
	Perform LH Lubrication of the Bent-Up Trailing Edge (BUTE) Door Hinge		B1013522 - Brandon Jennings Feb 12, 2026 08:01 PM	
	200	Complied with task 27-50-00-206 Lubrication of the RH Bent-Up Trailing Edge (BUTE) Door Hinge IAW CL-650 AMM 12-20-04-640-810.	B0650736 - Jesus Gonzalez Atondo Feb 12, 2026 07:47 PM	12-20
	Perform RH Lubrication of the Bent-Up Trailing Edge (BUTE) Door Hinge		B1013522 - Brandon Jennings Feb 12, 2026 08:01 PM	
	300	Removed all tools, equipment, and unwanted materials from the work area.	B0650736 - Jesus Gonzalez Atondo Feb 12, 2026 07:47 PM	
	Remove all tools, equipment, and unwanted materials from the work area.		B1013522 - Brandon Jennings Feb 12, 2026 08:01 PM	

Sequence #	0004-2	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503660	Aircraft Reg #	XA-SOL	Parent WO #	2503649

0004-2	WO #	2503660	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Operational Test of the Emergency Lights	
Operational Test of the Emergency Lights				
Task / IRN # : 33-50-00-202				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with TLMC Task 33-50-00-202, Operational test of the emergency lights. REF CL-650 AMM 33-51-00-710-801. Op Test Good.	B0143855 - Marlon Zurita Feb 04, 2026 04:13 PM	33-00
	Perform Operational test of the emergency lights.		B0143196 - Robert Bohner Feb 04, 2026 04:48 PM	
	200	Complied with removal of all tools, equipment, and unwanted materials from the work area	B0641378 - Calvin Ambrose Feb 04, 2026 02:04 PM	
	Comply with removal of all tools, equipment, and unwanted materials from the work area		B0143196 - Robert Bohner Feb 04, 2026 04:48 PM	

Bombardier

Sequence #	0004-3	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503661	Aircraft Reg #	XA-SOL	Parent WO #	2503649

0004-3	WO #	2503661	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Aft Equipment Compartment – Internal	
General Visual Inspection of the Aft Equipment Compartment – Internal				
Task / IRN # : 53-ZL-00-228				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with Task 53-ZL-00-228. Performed General Visual Inspection of the Aft Equipment Compartment – Internal,in reference to CL-650 AMM 53-30-01-210-806. See finding 79228 for details.	B0638589 - Sean Dodder Feb 07, 2026 02:34 AM	53-30
	Perform General Visual Inspection of the Aft Equipment Compartment – Internal		B0623124 - Michael Stacy Feb 07, 2026 02:40 AM	
	200	Removed all tools, equipment, and unwanted materials from the work area.	B0638589 - Sean Dodder Feb 07, 2026 02:34 AM	
	Remove all tools, equipment, and unwanted materials from the work area.		B0623124 - Michael Stacy Feb 07, 2026 02:40 AM	

FINDINGS DETAILS

Finding #	Long Description	Status	Reported By / Date	Defect Source / Disposition	Defect Type	Priority	Follow-up WO #
79228	The Top Duct of the APU Inlet Assembly, has large sections of insulation torn off/broken, on both the front and aft side of the duct. Photos are included, location has streamer.	CLOSED	B0638589 - Sean Dodder Feb 6, 2026 7:29 PM	MAINTENANCE 300-QA002	OTHER	3	4750145-PSAP

Sequence #	0004-4	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503666	Aircraft Reg #	XA-SOL	Parent WO #	2503649

0004-4	WO #	2503666	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Lubrication of the Ball Nut of the Flap Actuators	
Lubrication of the Ball Nut of the Flap Actuators				
Task / IRN # : 27-50-00-203				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 27-50-00-203 Lubrication of the LH Ball Nut of the Flap Actuators IAW CL-650 AMM 12-20-04-640-813.	B0650736 - Jesus Gonzalez Atondo Feb 12, 2026 06:57 PM	12-20
	Lubrication of the Ball Nut of the L/H Flap Actuators		B1013522 - Brandon Jennings Feb 12, 2026 07:46 PM	
	200	Complied with task 27-50-00-203 Lubrication of the RH Ball Nut of the Flap Actuators IAW CL-650 AMM 12-20-04-640-813.	B0650736 - Jesus Gonzalez Atondo Feb 12, 2026 06:57 PM	12-20
	Lubrication of the Ball Nut of the R/H Flap Actuators		B1013522 - Brandon Jennings Feb 12, 2026 07:46 PM	
	300	Removed all tools, equipment, and unwanted materials from the work area.	B0650736 - Jesus Gonzalez Atondo Feb 12, 2026 06:57 PM	
	Remove all tools, equipment, and unwanted materials from the work area.		B1013522 - Brandon Jennings Feb 12, 2026 07:46 PM	

Sequence #	0004-5	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503667	Aircraft Reg #	XA-SOL	Parent WO #	2503649

0004-5	WO #	2503667	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Lubrication of the Flap Vane Actuator Rods	
Lubrication of the Flap Vane Actuator Rods				
Task / IRN # : 27-50-00-205				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 27-50-00-205, Lubrication of the L/H Flap Vane Actuator Rods, in accordance with CL650 AMM 12-20-04-640-809.	B0641903 - Felipe Mendoza Cervantes Feb 18, 2026 04:35 AM	12-20
	Lubrication of the L/H Flap Vane Actuator Rods		B0623124 - Michael Stacy Feb 19, 2026 12:59 AM	
	200	Complied with task 27-50-00-205, Lubrication of the R/H Flap Vane Actuator Rods, in accordance with CL650 AMM 12-20-04-640-809.	B0641903 - Felipe Mendoza Cervantes Feb 18, 2026 04:35 AM	12-20
	Lubrication of the R/H Flap Vane Actuator Rods		B0623124 - Michael Stacy Feb 19, 2026 12:59 AM	
	300	removed all tools equipment and unwanted materials from the work area.	B0641903 - Felipe Mendoza Cervantes Feb 18, 2026 04:35 AM	
	remove all tools equipment and unwanted materials from the work area.		B0623124 - Michael Stacy Feb 19, 2026 12:59 AM	

Sequence #	0004-6	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	2503668	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2503649

0004-6	**WO #**	**2503668**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		Functional test of the Emergency Lights Power-Supplies (ELPS)	
Functional test of the Emergency Lights Power-Supplies (ELPS)				
Task / IRN # : 33-50-00-201				

Sequence #	0004-6	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503668	Aircraft Reg #	XA-SOL	Parent WO #	2503649

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Performed Removal of the Emergency Lights Power Supplies	B1001648 - Steve Cardenas Mar 04, 2026 11:44 PM	33-50
	Perform Removal of the Emergency Lights Power Supplies		Not Required	
	200	Complied with Task 33-50-00-201, Functional test of the Emergency Lights Power-Supplies (ELPS), Ref: Cl-650 AMM Task 33−51−01−720−801, see CSO 4757935, 4757921, 4757940, 4757932 for work performed	B1001648 - Steve Cardenas Mar 04, 2026 11:53 PM	33-50
	Perform Functional Test of the Emergency Lights Power Supplies		B0161691 - Thomas Mitchell Mar 05, 2026 03:47 AM	
	300			33-50
	Perform Installation of the Emergency Lights Power Supplies			
	400	Removed ELPS at FS 280 IAW CL-650 AMM 33-51-01-000-801	B0619443 - Tyler Herrera Feb 10, 2026 05:50 PM	
	Remove ELPS at FS 280		Not Required	
	500	Installed ELPS at FS 280 REF: CL-650 AMM 33−51−01−400−801	B1001648 - Steve Cardenas Mar 04, 2026 11:30 PM	
	Install ELPS at FS 280		B0161691 - Thomas Mitchell Mar 05, 2026 03:47 AM	
	501	Installed INSPECTED ELPS at FS 280 REF: CL-650 AMM 33−51−01−400−801	B1001648 - Steve Cardenas Mar 04, 2026 11:42 PM	
	Admin correction to add status change Install ELPS at FS 280		B0161691 - Thomas Mitchell Mar 05, 2026 03:47 AM	
	600	Removed baggage bay Aft position ELPS IAW CL-650 AMM 33-51-01-000-801	B0619443 - Tyler Herrera Feb 11, 2026 02:47 PM	
	Remove baggage bay Aft position ELPS		Not Required	
	700	Installed baggage bay Aft position REF: CL-650 AMM 33−51−01−400−801	B1001648 - Steve Cardenas Mar 04, 2026 11:30 PM	
	Install baggage bay Aft position ELPS		B0161691 - Thomas Mitchell Mar 05, 2026 03:47 AM	

Sequence #	0004-6	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503668	Aircraft Reg #	XA-SOL	Parent WO #	2503649

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	701	Installed INSPECTED baggage bay Aft position ELPS REF: CL-650 AMM 33−51−01−400−801	B1001648 - Steve Cardenas Mar 04, 2026 11:42 PM	
	Admin correction to add status change Install baggage bay Aft position ELPS		B0161691 - Thomas Mitchell Mar 05, 2026 03:47 AM	
	800	Removed baggage bay fwd position ELPS IAW CL-650 AMM 33-51-01-000-801	B0619443 - Tyler Herrera Feb 11, 2026 02:47 PM	
	Remove baggage bay fwd position ELPS		Not Required	
	900	Installed baggage bay fwd position ELPS Ref: CL-650 AMM 33-51-01-400-801	B1001648 - Steve Cardenas Mar 04, 2026 11:30 PM	
	Install baggage bay fwd position ELPS		B0161691 - Thomas Mitchell Mar 05, 2026 03:47 AM	
	901	Installed INSPECTED baggage bay fwd position ELPS Ref: CL-650 AMM 33-51-01-400-801	B1001648 - Steve Cardenas Mar 04, 2026 11:42 PM	
	Admin correction to add status change Install baggage bay fwd position ELPS		B0161691 - Thomas Mitchell Mar 05, 2026 03:47 AM	
	1000	Removed ELPS behind galley door at FS 310 IAW CL-650 AMM 33-51-01-000-801	B0619443 - Tyler Herrera Feb 11, 2026 02:47 PM	
	Remove ELPS behind galley door at FS310		Not Required	
	1100			
	Install ELPS behind galley door at FS310			
	1200			
	Perform operational test of the emergency lights Ref: Cl-650 AMM Task 33−51−00−710−801			

Sequence #	0004-6	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503668	Aircraft Reg #	XA-SOL	Parent WO #	2503649

REMOVE AND RE-INSTALL DETAILS

	Removed Part # Removed Serial #	Removed By	Removed - Part Description	Reference	Installed Part # Installed Serial #	Installed By
	Removed Status	**Removed Date-Time**	**Position**	**Installed Part Status**	**Installed Part Description**	**Installed Date-Time**
	60-1321-1 26447	B0619443 - Tyler Herrera	UNIT, POWER SUPPLY, EMERGENCY	33-51-02-000-801	60-1321-1 26447	B1001648 - Steve Cardenas
	SERVICEABLE	Feb 10, 2026 12:03 PM	1	INSPECTED	UNIT, POWER SUPPLY, EMERGENCY	Mar 4, 2026 4:31 PM
	60-1321-1 26450	B0619443 - Tyler Herrera	UNIT, POWER SUPPLY, EMERGENCY	33-51-01-000-801	60-1321-1 26450	
	SERVICEABLE	Feb 11, 2026 7:41 AM	2	INSPECTED	UNIT, POWER SUPPLY, EMERGENCY	
	60-1321-1 26448	B0619443 - Tyler Herrera	UNIT, POWER SUPPLY, EMERGENCY	33-51-01-000-801	60-1321-1 26448	B1001648 - Steve Cardenas
	SERVICEABLE	Feb 11, 2026 7:44 AM	3	INSPECTED	UNIT, POWER SUPPLY, EMERGENCY	Mar 4, 2026 4:32 PM
	60-1321-1 26449	B0619443 - Tyler Herrera	UNIT, POWER SUPPLY, EMERGENCY	33-51-01-000-801	60-1321-1 26449	B1001648 - Steve Cardenas
	SERVICEABLE	Feb 11, 2026 7:45 AM	4	INSPECTED	UNIT, POWER SUPPLY, EMERGENCY	Mar 4, 2026 4:35 PM

FINDINGS DETAILS

Finding #	Long Description	Status	Reported By	Defect Source	Defect Type	Priority	Follow-up WO #
			Date	**Disposition**			
81354	ELPS Serial number 26450 Failed Cap check. Test attempted 3 times with no success. Recommend Power pack replacement.	CLOSED	B0143855 - Marlon Zurita	MAINTENANCE	OTHER	3	4808182-RDYPM
			Feb 20, 2026 7:32 AM	300-QA002			
81356	ELPS Serial number 26447 Failed Cap check. Test attempted 3 times with no success. Recommend Power pack replacement.	CLOSED	B0143855 - Marlon Zurita	MAINTENANCE	OTHER	3	4808201-RDYPM
			Feb 20, 2026 7:40 AM	300-QA002			
81357	ELPS Serial number 26449 Failed Cap check. Test attempted 3 times with no success. Recommend Power pack replacement.	CLOSED	B0143855 - Marlon Zurita	MAINTENANCE	OTHER	3	4808216-RDYPM
			Feb 20, 2026 7:43 AM	300-QA002			

Sequence #	0004-6	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	2503668	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2503649

TOOL INFORMATION

Tool ID	Tool Description	Calibration Due Date
TUSS4982	Torque screwdriver	Jul 30, 2026 5:00 PM

Sequence #	0004-7	Aircraft SN #	6111	MWPWO #	2498069
WO #	4307834	Aircraft Reg #	XA-SOL	Parent WO #	2503649

0004-7	WO #	4307834	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		*23-CVR-01 CVR INTELLIGIBILITY CHECK (EASA SIB 2009-28 REV 01)	
*23-CARS-625-15(C) FUNCTIONAL CHECK OF CVR				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			23-00
	23-CARS-625-15(C) FUNCTIONAL CHECK OF CVR			

Sequence #	0004-8	Aircraft SN #	6111	MWPWO #	2498069
WO #	4308904	Aircraft Reg #	XA-SOL	Parent WO #	2503649

0004-8	WO #	4308904	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Perform FDR Correlation Check	
*31-CARS-625-17 PERFORM FDR CORRELATION CHECK				
Task / IRN # : 31-CARS-625-17				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	PERFORM FDR CORRELATION CHECK, (DOWNLOAD OF FDR) in accordance with CL-650 AMM 31-31-00-970-801.	B0143864 - Aaric Cerna Feb 05, 2026 04:22 PM	31-00
	31-CARS-625-17 PERFORM FDR CORRELATION CHECK		B1013522 - Brandon Jennings Feb 05, 2026 04:57 PM	
	101	SENT DOWNLOADED DATA TO VENDOR FDR CORRELATION CHECK	B0143864 - Aaric Cerna Feb 06, 2026 04:33 PM	
	SEND DOWNLOADED DATA TO VENDOR FDR CORRELATION CHECK		B1013522 - Brandon Jennings Feb 06, 2026 05:07 PM	
	200	Provided Vendor Report/Read out to Customer (see attachment). This complies with customer code 31-CARS-625-17 PERFORM FDR CORRELATION CHECK. No defects noted.	B0143855 - Marlon Zurita Mar 05, 2026 07:42 PM	
	C/W disposition, provide data from vendor.		B1013522 - Brandon Jennings Mar 05, 2026 08:55 PM	
	300	Removed all tools, equipment, and unwanted materials from the work area.	B0143855 - Marlon Zurita Mar 05, 2026 07:42 PM	
	Remove all tools, equipment, and unwanted materials from the work area		B1013522 - Brandon Jennings Mar 05, 2026 08:55 PM	

Sequence #	0004-9	Aircraft SN #	6111	MWPWO #	2498069
WO #	4308955	Aircraft Reg #	XA-SOL	Parent WO #	2503649

0004-9	WO #	4308955	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Complied with Task NOM-022-SCT3-2011/12.2.2-1 - Download and Analysis of FDR. Provided FDR Download (Performed Under Maximo wo 4308904) to Vendor for Readout. Report Provided by Vendor after Readout. No Defects Noted.	
*NOM-022-SCT3-2011/12.2.2-1 DOWNLOAD AND ANALYSIS OF FDR				
Task / IRN # : NOM-022-SCT3-2011/12.2.2-1				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Provided FDR Download (performed under Maximo wo 4308904) to Vendor for readout. Report provided by Vendor after readout (see attachment). This complies with Customer task NOM-022-SCT3-2011/12.2.2-1 DOWNLOAD AND ANALYSIS OF FDR. No defects noted.	B0143855 - Marlon Zurita Mar 05, 2026 07:24 PM	31-00
	NOM-022-SCT3-2011/12.2.2-1 DOWNLOAD AND ANALYSIS OF FDR		B1013522 - Brandon Jennings Mar 05, 2026 08:57 PM	
	200	Removed all tools, equipment, and unwanted materials from the work area.	B0143855 - Marlon Zurita Mar 05, 2026 07:24 PM	
	Remove all tools, equipment, and unwanted materials from the work area		B1013522 - Brandon Jennings Mar 05, 2026 08:57 PM	

Bombardier

Sequence #	0004-10	Aircraft SN #	6111	MWPWO #	2498069
WO #	4309008	Aircraft Reg #	XA-SOL	Parent WO #	2503649

0004-10	WO #	4309008	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		*NOM-022-SCT3-2011/12.2.2-2 DOWNLOAD AND ANALYSIS OF CVR	
*NOM-022-SCT3-2011/12.2.2-2 DOWNLOAD AND ANALYSIS OF CVR				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task , *NOM-022-SCT3-2011/12.2.2-2 DOWNLOAD AND ANALYSIS OF CVR, in accordance with CL-650 AMM 23-71-00-970-801. Data sent to vendor.	B0143864 - Aaric Cerna Feb 06, 2026 04:14 PM	
	*NOM-022-SCT3-2011/12.2.2-2 DOWNLOAD AND ANALYSIS OF CVR		B1013522 - Brandon Jennings Feb 06, 2026 05:05 PM	
	200	Removed CVR IAW. CL-650 AMM 23-71-01-000-801.	B0143864 - Aaric Cerna Feb 06, 2026 04:13 PM	
	Remove CVR IAW. CL-650 AMM 23-71-01-000-801.		Not Required	
	300	INSTALLED CVR IAW. CL-650 AMM 23-71-01-400-801. see op. 400 for ops test.	B0143864 - Aaric Cerna Feb 06, 2026 04:13 PM	
	INSTALL CVR IAW. CL-650 AMM 23-71-01-400-801.		B1013522 - Brandon Jennings Feb 06, 2026 05:05 PM	
	400			
	Perform operational test of the CVR IAW CL-650 AMM 23-71-00-710-801			
	500			
	C/w disposition data from vendor to customer.			

Sequence #	0004-10	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4309008	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2503649

REMOVE AND RE-INSTALL DETAILS

	Removed Part # Removed Serial #	Removed By	Removed - Part Description	Reference	Installed Part # Installed Serial #	Installed By
	Removed Status	**Removed Date-Time**	**Position**	**Installed Part Status**	**Installed Part Description**	**Installed Date-Time**
	2100-1225-22 1231074	B0143864 - Aaric Cerna	RECORDER, COCKPIT VOICE	CL6750 AMM 23-71-01-000-801		
	SERVICEABLE	Feb 6, 2026 7:33 AM	RIGHT			

Sequence #	0004-11	Aircraft SN #	6111	MWPWO #	2498069
WO #	4309479	Aircraft Reg #	XA-SOL	Parent WO #	2503649

0004-11	WO #	4309479	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Intelligibility Check of CVR	
*23-CARS-625-15(D) INTELLIGIBILITY CHECK OF CVR				
Task / IRN # : 23-CARS-625-15(D)				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with *23-CARS-625-15(D) INTELLIGIBILITY CHECK OF CVR. IAW. CL-650 AMM 23-71-00-750-801. STEPS 1- 4. (GROUND PROCEDURE) Continue with step G	B0143864 - Aaric Cerna Feb 05, 2026 04:12 PM	23-00
	*23-CARS-625-15(D) INTELLIGIBILITY CHECK OF CVR		B0143196 - Robert Bohner Feb 05, 2026 04:23 PM	
	101	Complied with task Intelligibility test of CVR IAW. CL-650 AMM 23-71-00-750-801 STEP G to CLOSE.. Downloaded Data sent to vendor.	B0143864 - Aaric Cerna Feb 06, 2026 04:10 PM	
	Continue Intelligibility test of CVR IAW. CL-650 AMM 23-71-00-750-801 STEP G to CLOSE.		B1013522 - Brandon Jennings Feb 06, 2026 05:01 PM	
	200	Removed tools, equipment and all unwanted materials from work area	B0143864 - Aaric Cerna Feb 06, 2026 04:10 PM	
	Remove tools, equipment and all unwanted materials from work area		B1013522 - Brandon Jennings Feb 06, 2026 05:01 PM	

Sequence #	0005	Aircraft SN #	6111	MWPWO #	2498069
WO #	2498466	Aircraft Reg #	XA-SOL	Parent WO #	2498069

0005	WO #	2498466	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13276319	12 Month inspection STLMC tasks (605/650)	
12 Month inspection STLMC tasks (605/650)				

CHILD WORK ORDER DETAILS

	WO #	Description	Corrective Action	AMENDED
0005-1	2525052	STLMC - General visual inspection of the cabin placards		
0005-2	2525059	STLMC - Ops test of the galley tambour door switch	Complied with STLMC task 24-03-65-601 Ops test of the galley tambour door switch. Ref CL-650 SMM 24-03-00-710-801. Ne defects noted	
0005-3	2525069	STLMC - Operational Test of Ground Fault Interrupter (GFI) and Cabin Outlets	Complied with task 24-52-65-601, Operational Test of Ground Fault Interrupter (GFI) and Cabin Outlets, REF: CL650 SMM Task 24-25-00-710-801, system op checks good.	
0005-4	2525073	STLMC - Operational test of the floor mat activated solenoid valve	Complied with STLMC Task 38-10-65-610 Operational Test of the Floor Mat Activated Solenoid Valve Ref: CL-650 SMM TASK 38-10-00-710-802. No defects noted.	
0005-5	4307424	*12-15-65-601 SANITIZATION OF THE WATER SYSTEM	Complied with 12-15-65-601 SANITIZATION OF THE WATER SYSTEM. see op 100 - 200 for work performed	

Bombardier

Sequence #	0005-1	Aircraft SN #	6111	MWPWO #	2498069
WO #	2525052	Aircraft Reg #	XA-SOL	Parent WO #	2498466

0005-1	WO #	2525052	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		No Log Entry	
STLMC - General visual inspection of the cabin placards				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			11-00
	Perform General visual inspection of the cabin placards			

Bombardier

Sequence #	0005-2	Aircraft SN #	6111	MWPWO #	2498069
WO #	2525059	Aircraft Reg #	XA-SOL	Parent WO #	2498466

0005-2	WO #	2525059	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		STLMC - Ops test of the galley tambour door switch	
STLMC - Ops test of the galley tambour door switch				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with STLMC task 24-03-65-601 Ops test of the galley tambour door switch. Ref CL-650 SMM 24-03-00-710-801. Ne defects noted	B0141448 - Graciela Pino Feb 04, 2026 02:11 AM B0161867 - Jeremy Kucera Feb 04, 2026 02:14 AM	24-00
	Perform Ops test of the galley tambour door switch		B0161691 - Thomas Mitchell Feb 04, 2026 03:30 AM	
	200	Removed all tools, equipment and unwanted materials from the work area.	B1019231 - Ivan Bojorquez Feb 04, 2026 04:23 AM	
	Remove all tools, equipment and unwanted materials from the work area.		B0161691 - Thomas Mitchell Feb 04, 2026 04:45 AM	

Sequence #	0005-3	Aircraft SN #	6111	MWPWO #	2498069
WO #	2525069	Aircraft Reg #	XA-SOL	Parent WO #	2498466

0005-3	WO #	2525069	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		STLMC - Operational Test of Ground Fault Interrupter (GFI) and Cabin Outlets	
STLMC - Operational Test of Ground Fault Interrupter (GFI) and Cabin Outlets				
Task / IRN # : STLMC				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 24-52-65-601, Operational Test of Ground Fault Interrupter (GFI) and Cabin Outlets, REF: BD-100 SMM Task 24-25-00-710-801, system op checks good.	B0629148 - Robert Greaves Feb 04, 2026 04:25 AM	24-20
	Perform Operational Test of Ground Fault Interrupter (GFI) and Cabin Outlets		B0161691 - Thomas Mitchell Feb 04, 2026 05:11 AM	
	101	Complied with task 24-52-65-601, Operational Test of Ground Fault Interrupter (GFI) and Cabin Outlets, REF: CL650 SMM Task 24-25-00-710-801, system op checks good.	B0629148 - Robert Greaves Feb 04, 2026 05:05 AM	
	Admin correction to change aircraft type		B0161691 - Thomas Mitchell Feb 04, 2026 05:11 AM	
	200	Removed all tools, equipment, and unwanted materials from the work area	B1001648 - Steve Cardenas Feb 04, 2026 04:22 AM	
	Remove all tools, equipment, and unwanted materials from the work area		B0161691 - Thomas Mitchell Feb 04, 2026 05:11 AM	

Sequence #	0005-4	Aircraft SN #	6111	MWPWO #	2498069
WO #	2525073	Aircraft Reg #	XA-SOL	Parent WO #	2498466

0005-4	WO #	2525073	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		STLMC - Operational Test of the Floor mat Activated Solenoid Valve	
STLMC - Operational test of the floor mat activated solenoid valve				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with STLMC Task 38-10-65-610 Operational Test of the Floor Mat Activated Solenoid Valve Ref: CL-650 SMM TASK 38-10-00-710-802. No defects noted.	B1017798 - Hunter Van Der Heide Feb 04, 2026 04:09 AM B1019231 - Ivan Bojorquez Feb 04, 2026 03:26 AM	38-00
	Perform Operational test of the floor mat activated solenoid valve		B0161691 - Thomas Mitchell Feb 04, 2026 05:07 AM	
	200	Removed all tools, equipment and unwanted materials from the work area.	B1019231 - Ivan Bojorquez Feb 04, 2026 04:15 AM	
	Remove all tools, equipment and unwanted materials from the work area.		B0161691 - Thomas Mitchell Feb 04, 2026 05:07 AM	

Sequence #	0005-5	Aircraft SN #	6111	MWPWO #	2498069
WO #	4307424	Aircraft Reg #	XA-SOL	Parent WO #	2498466

0005-5	WO #	4307424	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		STLMC - Discard the Cabin Flashlight Batteries (Alkaline)	
*12-15-65-601 SANITIZATION OF THE WATER SYSTEM				
Task / IRN # : 25-63-65-615				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with STLMC Task 12-15-65-601 - Sanitization of the Water System - Ref: CL-650 SMM TASK 12-15-00-670-801. No defects Noted.	B1017798 - Hunter Van Der Heide Feb 04, 2026 05:46 AM B1019231 - Ivan Bojorquez Feb 04, 2026 05:13 AM	38-00
	12-15-65-601 SANITIZATION OF THE WATER SYSTEM		B0161691 - Thomas Mitchell Feb 04, 2026 06:04 AM	
	200	Removed all tools, equipment and unwanted materials from the work area.	B1019231 - Ivan Bojorquez Feb 04, 2026 05:13 AM	
	Remove all tools, equipment and unwanted materials from the work area.		B0161691 - Thomas Mitchell Feb 04, 2026 06:04 AM	

Sequence #	0006	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	2503656	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

0006	**WO #**	**2503656**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #	13276327	24 month inspection	
24 month inspection				
Task / IRN # : C3500024				

Sequence #	0006	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503656	Aircraft Reg #	XA-SOL	Parent WO #	2498069

CHILD WORK ORDER DETAILS

	WO #	Description	Corrective Action	AMENDED
0006-1	2503676	Operational test of the cabin power shut-off switch	Complied with TLMC Task 24-20-00-206, Operational test of the cabin power shut-off switch. REF CL-650 AMM 24-00-00-710-802. Op Test Good.	
0006-2	2503677	Operational Test of the Emergency Locator Transmitter (ELT) system	Complied with task 25-60-00-201 ops test of ELT IAW CL-650 AMM 25-62-00-710-801 Test good	
0006-3	2503680	Functional test (Weight Check) of the Portable Fire-Extinguisher Container	Complied with Task 26-20-00-205. Performed Functional test (Weight Check) of the Cockpit Portable Fire-Extinguisher Container, in reference to CL-650 AMM 26-23-01-720-802. Weight is 5.43 lbs, no defects noted.	
0006-4	2503683	Detailed Inspection of the Engine Fire-Extinguisher-Bottle Pressure Gauge	Complied with TLMC 26-21-04-201. Performed a Detailed Inspection of the Engine Fire-Extinguisher-Bottle Pressure Gauges Ref. CL-650 AMM 26-21-04-220-802. No defects noted.	
0006-5	2503684	Detailed Inspection of the Auxiliary Power Unit (APU) Fire-Extinguisher-Bottle Pressure Gauge	Complied with task 26-22-04-201, Perform Detailed Inspection of the Auxiliary Power Unit (APU) Fire-Extinguisher-Bottle Pressure Gauge. REF CL650 AMM 26-22-04-220-802. Pressure measured at 700 psi at 77 degrees Fahrenheit, pressure within green band no defects noted.	
0006-6	2503687	Servicing of the Visual Drains	Complied with TLMC Task 34-11-00-203, Servicing of the Visual Drains. REF CL-650 AMM 34-11-09-616-801. No defects noted.	
0006-7	2503689	General Visual Inspection of the oxygen indication system	Complied with TLMC task 35-00-00-208 Performed general visual inspection of the oxygen indication system REF CL-650 AMM 35-12-00-210-801. No defects noted.	
0006-8	2503690	Lubrication of the Emergency Exit Door	Complied with task 52-20-00-203, Perform Lubrication of the Emergency Exit Door, in accordance with CL650 AMM 12-20-04-640-805.	
0006-9	2503693	General Visual Inspection of the Mid-Fuselage Compartment-Lower Internal (FS589.0 to FS621.0)	Complied with task 53-ZL-00-217, Perform General Visual Inspection of the Mid-Fuselage Compartment-Lower Internal (FS589.0 to FS621.0), REF CL650 AMM 53-30-01-210-802. No defects noted.	

Sequence #	0006	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503656	Aircraft Reg #	XA-SOL	Parent WO #	2498069

CHILD WORK ORDER DETAILS

	WO #	Description	Corrective Action	AMENDED
0006-10	2503695	General Visual Inspection of the Flight Compartment - External	complied with task 53-ZL-00-220. Performed a General Visual Inspection of the Flight Compartment - External IAW CL 650 AMM 53-10-01-210-811. see findings for defects noted.	
0006-11	2503696	Detailed Inspection of the Emergency Locator Transmitter (ELT) Battery	Complied with task 25-60-00-203 detailed inspection of ELT battery IAW CL-650 AMM 25-62-01-220-801 No defects noted, battery expiration Oct 2027 Removed ELT IAW CL-650 AMM 25-62-01-000-801 Installed ELT IAW CL-650 AMM 25-62-01-400-801 Performed ops test of ELT IAW CL-650 AMM 25-62-00-710-801 Test good	
0006-12	2503699	Detailed Inspection of the Rudder and Elevator Control Cables in the Aft Equipment Compartment	Complied with task 27-00-00-206 of Detailed Inspection of the Rudder and Elevator Control Cables in the Aft Equipment Compartment. Ref: CL-650 AMM 27-00-00-220-806, no defects noted	
0006-13	2503701	Functional test of the Air Driven Generator (ADG) heater	Complied with task 24-20-00-207 Functional test of the Air Driven Generator (ADG) heater Ref CL 650 AMM 24-23-01-720-801. Functional Test Good	
0006-14	2503702	Operational test of the Air Driven Generator (ADG)		

Sequence #	0006-1	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503676	Aircraft Reg #	XA-SOL	Parent WO #	2503656

0006-1	WO #	2503676	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Operational Test of the Cabin Power Shut-Off Switch	
Operational test of the cabin power shut-off switch				
Task / IRN # : 24-20-00-206				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with TLMC Task 24-20-00-206, Operational test of the cabin power shut-off switch. REF CL-650 AMM 24-00-00-710-802. Op Test Good.	B0143855 - Marlon Zurita Feb 04, 2026 04:24 PM	24-00
	Perform Operational test of the cabin power shut-off switch		B0143196 - Robert Bohner Feb 04, 2026 04:46 PM	
	200	Complied with removal of all tools, equipment, and unwanted materials from the work area	B0641378 - Calvin Ambrose Feb 04, 2026 03:48 PM	
	Comply with removal of all tools, equipment, and unwanted materials from the work area		B0143196 - Robert Bohner Feb 04, 2026 04:46 PM	

Bombardier

Sequence #	0006-2	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503677	Aircraft Reg #	XA-SOL	Parent WO #	2503656

0006-2	WO #	2503677	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Operational Test of the Emergency Locator Transmitter (ELT) System	
Operational Test of the Emergency Locator Transmitter (ELT) system				
Task / IRN # : 25-60-00-201				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 25-60-00-201 ops test of ELT IAW CL-650 AMM 25-62-00-710-801 Test good	B0619443 - Tyler Herrera Feb 11, 2026 05:12 PM	25-00
	Perform Operational test- ELT system		B1013522 - Brandon Jennings Feb 11, 2026 05:19 PM	
	200	Removed tools and equipment from aircraft	B0619443 - Tyler Herrera Feb 11, 2026 05:12 PM	
	Remove tools and equipment		B1013522 - Brandon Jennings Feb 11, 2026 05:19 PM	

TOOL INFORMATION

Tool ID	Tool Description	Calibration Due Date
TUSS3748	ELT Test set	Sep 29, 2026 5:00 PM

Sequence #	0006-3	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503680	Aircraft Reg #	XA-SOL	Parent WO #	2503656

0006-3	WO #	2503680	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Functional test (Weight Check) of the Portable Fire-Extinguisher Container. Weight 5.43 lbs.	
Functional test (Weight Check) of the Portable Fire-Extinguisher Container				
Task / IRN # : 26-20-00-205				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with Task 26-20-00-205. Performed Functional test (Weight Check) of the Cockpit Portable Fire-Extinguisher Container, in reference to CL-650 AMM 26-23-01-720-802. Weight is 5.43 lbs, no defects noted.	B0638589 - Sean Dodder Feb 03, 2026 04:29 AM	26-20
	Perform Functional test (Weight Check) of the Portable Fire-Extinguisher Container		B0161691 - Thomas Mitchell Feb 03, 2026 04:52 AM	
	200	Re-Installed Cockpit Portable Fire Extinguisher, in reference to CL-650 AMM 26-23-01-400-801.	B0638589 - Sean Dodder Feb 03, 2026 04:29 AM	
	Removed Cockpit Portable Fire Extinguisher, in reference to CL-650 AMM 26-23-01-000-801.		B0161691 - Thomas Mitchell Feb 03, 2026 04:52 AM	
	300	Removed all tools, equipment, and unwanted materials from the work area.	B0638589 - Sean Dodder Feb 03, 2026 04:29 AM	
	Remove all tools, equipment, and unwanted materials from the work area.		B0161691 - Thomas Mitchell Feb 03, 2026 04:52 AM	

TOOL INFORMATION

Tool ID	Tool Description	Calibration Due Date
TUSS2392	Digital Scale	Jan 30, 2027 5:00 PM

Sequence #	0006-4	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503683	Aircraft Reg #	XA-SOL	Parent WO #	2503656

0006-4	WO #	2503683	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Engine Fire-Extinguisher-Bottle Pressure Gauge	
Detailed Inspection of the Engine Fire-Extinguisher-Bottle Pressure Gauge				
Task / IRN # : 26-21-04-201				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with TLMC 26-21-04-201. Performed a Detailed Inspection of the Engine Fire-Extinguisher-Bottle Pressure Gauges Ref. CL-650 AMM 26-21-04-220-802. No defects noted.	B0613291 - Eric Strong Feb 04, 2026 06:51 PM	26-20
	Perform Detailed Inspection of the Engine Fire-Extinguisher-Bottle Pressure Gauge		B1013522 - Brandon Jennings Feb 04, 2026 07:12 PM	
	200	Removed all tools equipment and unwanted materials.	B0613291 - Eric Strong Feb 04, 2026 06:51 PM	
	Remove all tools equipment and unwanted materials.		B1013522 - Brandon Jennings Feb 04, 2026 07:12 PM	

Bombardier

Sequence #	0006-5	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503684	Aircraft Reg #	XA-SOL	Parent WO #	2503656

0006-5	WO #	2503684	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Auxiliary Power Unit (APU) Fire-Extinguisher-Bottle Pressure Gauge	
Detailed Inspection of the Auxiliary Power Unit (APU) Fire-Extinguisher-Bottle Pressure Gauge				
Task / IRN # : 26-22-04-201				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 26-22-04-201, Perform Detailed Inspection of the Auxiliary Power Unit (APU) Fire-Extinguisher-Bottle Pressure Gauge. REF CL650 AMM 26-22-04-220-802. Pressure measured at 700 psi at 77 degrees Fahrenheit, pressure within green band no defects noted.	B1016542 - Carlos Ochoa Feb 11, 2026 12:49 AM	26-00
	Perform Detailed Inspection of the Auxiliary Power Unit (APU) Fire-Extinguisher-Bottle Pressure Gauge		B0623124 - Michael Stacy Feb 11, 2026 01:04 AM	
	200	Removed all tools, equipment, and unwanted materials.	B1016542 - Carlos Ochoa Feb 11, 2026 12:49 AM	
	Remove all tools, equipment, and unwanted materials.		B0623124 - Michael Stacy Feb 11, 2026 01:04 AM	

TOOL INFORMATION

Tool ID	Tool Description	Calibration Due Date
TUSS3416	Infrared Thermometer	Jun 29, 2026 5:00 PM

Sequence #	0006-6	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503687	Aircraft Reg #	XA-SOL	Parent WO #	2503656

0006-6	WO #	2503687	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Servicing of the Visual Drains	
Servicing of the Visual Drains				
Task / IRN # : 34-11-00-203				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with TLMC Task 34-11-00-203, Servicing of the Visual Drains. REF CL-650 AMM 34-11-09-616-801. No defects noted.	B0143855 - Marlon Zurita Feb 19, 2026 05:23 PM	34-10
	Perform Servicing of the Visual Drains		B1013522 - Brandon Jennings Feb 19, 2026 07:25 PM	
	200	Complied with removal of all tools, equipment, and unwanted materials from the work area	B0641378 - Calvin Ambrose Feb 19, 2026 03:34 PM	
	Comply with removal of all tools, equipment, and unwanted materials from the work area		B1013522 - Brandon Jennings Feb 19, 2026 07:25 PM	

Sequence #	0006-7	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503689	Aircraft Reg #	XA-SOL	Parent WO #	2503656

0006-7	WO #	2503689	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Oxygen Indication System	
General Visual Inspection of the oxygen indication system				
Task / IRN # : 35-00-00-208				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with TLMC task 35-00-00-208 Performed general visual inspection of the oxygen indication system REF CL-650 AMM 35-12-00-210-801. No defects noted.	B1002512 - Brandon Warne Feb 05, 2026 04:01 PM	35-10
	Perform General Visual Inspection of the oxygen indication system		B1013522 - Brandon Jennings Feb 05, 2026 04:19 PM	
	200	Removed all tools, equipment and materials from the work area.	B1002512 - Brandon Warne Feb 05, 2026 04:01 PM	
	Remove all tools, equipment and materials from the work area.		B1013522 - Brandon Jennings Feb 05, 2026 04:19 PM	

Sequence #	0006-8	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503690	Aircraft Reg #	XA-SOL	Parent WO #	2503656

0006-8	WO #	2503690	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Lubrication of the Emergency Exit Door	
Lubrication of the Emergency Exit Door				
Task / IRN # : 52-20-00-203				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 52-20-00-203, Perform Lubrication of the Emergency Exit Door, in accordance with CL650 AMM 12-20-04-640-805.	B0641903 - Felipe Mendoza Cervantes Feb 18, 2026 04:58 AM	12-20
	Perform Lubrication of the Emergency Exit Door		B0623124 - Michael Stacy Feb 19, 2026 01:00 AM	
	200	removed all tools equipment and unwanted materials from the work area.	B0641903 - Felipe Mendoza Cervantes Feb 18, 2026 04:58 AM	
	remove all tools equipment and unwanted materials from the work area.		B0623124 - Michael Stacy Feb 19, 2026 01:00 AM	

Sequence #	0006-9	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503693	Aircraft Reg #	XA-SOL	Parent WO #	2503656

0006-9	WO #	2503693	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Mid-Fuselage Compartment-Lower Internal (FS589.0 to FS621.0)	
General Visual Inspection of the Mid-Fuselage Compartment-Lower Internal (FS589.0 to FS621.0)				
Task / IRN # : 53-ZL-00-217				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 53-ZL-00-217, Perform General Visual Inspection of the Mid-Fuselage Compartment-Lower Internal (FS589.0 to FS621.0), REF CL650 AMM 53-30-01-210-802. No defects noted.	B1016542 - Carlos Ochoa Feb 13, 2026 01:04 AM	53-30
	Perform General Visual Inspection of the Mid-Fuselage Compartment-Lower Internal (FS589.0 to FS621.0)		B0623124 - Michael Stacy Feb 13, 2026 01:09 AM	
	200	Removed all tools, equipment, and unwanted materials.	B1016542 - Carlos Ochoa Feb 13, 2026 01:04 AM	
	Remove all tools, equipment, and unwanted materials.		B0623124 - Michael Stacy Feb 13, 2026 01:09 AM	

Sequence #	0006-10	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503695	Aircraft Reg #	XA-SOL	Parent WO #	2503656

0006-10	WO #	2503695	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Flight Compartment - External	
General Visual Inspection of the Flight Compartment - External				
Task / IRN # : 53-ZL-00-220				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	complied with task 53-ZL-00-220. Performed a General Visual Inspection of the Flight Compartment - External IAW CL 650 AMM 53-10-01-210-811. see findings for defects noted.	B0642326 - Austin McQuilkin Feb 04, 2026 02:26 PM	53-10
	Perform General Visual Inspection of the Flight Compartment - External		B1013522 - Brandon Jennings Feb 04, 2026 02:39 PM	
	200	Removed all tools, equipment, and unwanted materials from the work area.	B0642326 - Austin McQuilkin Feb 04, 2026 02:26 PM	
	Remove all tools, equipment, and unwanted materials from the work area.		B1013522 - Brandon Jennings Feb 04, 2026 02:39 PM	

FINDINGS DETAILS

Finding #	Long Description	Status	Reported By / Date	Defect Source / Disposition	Defect Type	Priority	Follow-up WO #
78823	further evaluation required to determin servicability of both pitot static probes and the pitot static head due to dents in the inlet.	CLOSED	B0642326 - Austin McQuilkin Feb 4, 2026 7:20 AM	MAINTENANCE 300-QA002	OTHER	3	4715617-PSAP
78824	multiple dents found on the L/H and R/H side of the nose fuselage zone requireing further evaluation to determine servicability.	CLOSED	B0642326 - Austin McQuilkin Feb 4, 2026 7:21 AM	MAINTENANCE 300-QA002	OTHER	3	4715599-RDYLT

Sequence #	0006-11	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503696	Aircraft Reg #	XA-SOL	Parent WO #	2503656

0006-11	WO #	2503696	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Emergency Locator Transmitter (ELT) Battery. Battery Expiration Oct 2027.	
Detailed Inspection of the Emergency Locator Transmitter (ELT) Battery				
Task / IRN # : 25-60-00-203				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 25-60-00-203 detailed inspection of ELT battery IAW CL-650 AMM 25-62-01-220-801 No defects noted, battery expiration Oct 2027	B0619443 - Tyler Herrera Feb 11, 2026 04:16 PM	25-00
	Perform Detailed Inspection of the Emergency Locator Transmitter (ELT) Battery		B1013522 - Brandon Jennings Feb 11, 2026 04:26 PM	
	200	Installed ELT IAW CL-650 AMM 25-62-01-400-801	B0619443 - Tyler Herrera Feb 11, 2026 04:16 PM	
	Removed ELT IAW CL-650 AMM 25-62-01-000-801		B1013522 - Brandon Jennings Feb 11, 2026 04:26 PM	
	300	Performed ops test of ELT IAW CL-650 AMM 25-62-00-710-801 Test good	B0619443 - Tyler Herrera Feb 11, 2026 05:13 PM	
	Perform ops test of ELT IAW CL-650 AMM 25-62-00-710-801		B1013522 - Brandon Jennings Feb 11, 2026 05:18 PM	
	400	Removed tools and equipment from aircraft	B0619443 - Tyler Herrera Feb 11, 2026 05:13 PM	
	Remove tools and equipment		B1013522 - Brandon Jennings Feb 11, 2026 05:18 PM	

Sequence #	0006-11	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503696	Aircraft Reg #	XA-SOL	Parent WO #	2503656

REMOVE AND RE-INSTALL DETAILS

	Removed Part # Removed Serial #	Removed By	Removed - Part Description	Reference	Installed Part # Installed Serial #	Installed By
	Removed Status	Removed Date-Time	Position	Installed Part Status	Installed Part Description	Installed Date-Time
	453-5060 252-02283	B0619443 - Tyler Herrera	C406-N MAIN ASSEMBLY	25-62-01-000-801	453-5060 252-02283	B0619443 - Tyler Herrera
	SERVICEABLE	Feb 11, 2026 8:33 AM	ONLY	SERVICEABLE	C406-N MAIN ASSEMBLY	Feb 11, 2026 9:13 AM

FINDINGS DETAILS

Finding #	Long Description	Status	Reported By	Defect Source	Defect Type	Priority	Follow-up WO #
			Date	Disposition			
79859	Found shield terminal lug broken on ELT connector when removing ELT for battery inspection.	CLOSED	B0619443 - Tyler Herrera	MAINTENANCE	OTHER	3	4755476-PSAP
			Feb 11, 2026 8:50 AM	300-QA002			
79875	Entered in Error	CLOSED	B0619443 - Tyler Herrera	MAINTENANCE	OTHER	3	
			Feb 11, 2026 10:08 AM	300-QA002			

TOOL INFORMATION

Tool ID	Tool Description	Calibration Due Date
TUSS4000	Torque	Oct 30, 2026 5:00 PM
TUSS3748	ELT Test set	Sep 29, 2026 5:00 PM

Sequence #	0006-12	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503699	Aircraft Reg #	XA-SOL	Parent WO #	2503656

0006-12	WO #	2503699	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Rudder and Elevator Control Cables in the Aft Equipment Compartment	
Detailed Inspection of the Rudder and Elevator Control Cables in the Aft Equipment Compartment				
Task / IRN # : 27-00-00-206				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 27-00-00-206 of Detailed Inspection of the Rudder and Elevator Control Cables in the Aft Equipment Compartment. Ref: CL-650 AMM 27-00-00-220-806, no defects noted	B1018409 - Areida Cruz Feb 14, 2026 03:25 PM	27-00
	Detailed Inspection of the Rudder and Elevator Control Cables in the Aft Equipment Compartment		B0142244 - Todd Bridges Feb 15, 2026 02:14 PM	
	200	Removed all tools, equipment, and unwanted materials from the work area	B1018409 - Areida Cruz Feb 14, 2026 03:25 PM	
	Remove all tools, equipment, and unwanted materials from the work area		B0142244 - Todd Bridges Feb 15, 2026 02:14 PM	
	300	Installed control pully access-covers Ref: CL-650 AMM 27-21-03-400-801	B1018409 - Areida Cruz Feb 14, 2026 07:14 PM	
	Install control pully access-covers		B0142244 - Todd Bridges Feb 15, 2026 02:14 PM	

TOOL INFORMATION

Tool ID	Tool Description	Calibration Due Date
TUSS400	Torque screwdriver	Oct 30, 2026 5:00 PM

Bombardier

Sequence #	0006-13	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503701	Aircraft Reg #	XA-SOL	Parent WO #	2503656

0006-13	WO #	2503701	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Functional Test of the Air Driven Generator (ADG) Heater	
Functional test of the Air Driven Generator (ADG) heater				
Task / IRN # : 24-20-00-207				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 24-20-00-207 Functional test of the Air Driven Generator (ADG) heater Ref CL 650 AMM 24-23-01-720-801. Functional Test Good	B0629148 - Robert Greaves Feb 06, 2026 04:05 AM	24-20
	Functional test of the Air Driven Generator (ADG) heater		B0623124 - Michael Stacy Feb 06, 2026 04:22 AM	
	200	Removed all tools, equipment and unwanted materials from the work area	B1001648 - Steve Cardenas Feb 06, 2026 04:34 AM	
	Remove all tools, equipment and unwanted materials from the work area		B0623124 - Michael Stacy Feb 06, 2026 04:35 AM	
	300	Closed CBP-2 ref: Cl-650 AMM Task 24-23-01-720-801	B1001648 - Steve Cardenas Feb 06, 2026 04:34 AM	
	Opened CBP-2 ref: Cl-650 AMM Task 24-23-01-720-801		B0623124 - Michael Stacy Feb 06, 2026 04:35 AM	

TOOL INFORMATION

Tool ID	Tool Description	Calibration Due Date
TUSS1017	Multimeter	Oct 30, 2026 5:00 PM

Sequence #	0006-14	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	2503702	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2503656

0006-14	**WO #**	**2503702**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		Operational Test of the Air Driven Generator (ADG)	
Operational test of the Air Driven Generator (ADG)				
Task / IRN # : 24-23-00-101				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			24-20
	Operational test of the Air Driven Generator (ADG)			

Sequence #	0007	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	2498530	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

0007	**WO #**	**2498530**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #	13276314	24 Month inspection STLMC tasks (605/650)	
24 Month inspection STLMC tasks (605/650)				

Sequence #	0007	Aircraft SN #	6111	MWPWO #	2498069
WO #	2498530	Aircraft Reg #	XA-SOL	Parent WO #	2498069

CHILD WORK ORDER DETAILS

	WO #	Description	Corrective Action	AMENDED
0007-1	2525079	STLMC - Discard of the Coffee Maker Water Inlet Filter		
0007-2	2525094	STLMC - Detailed inspection of the life vests	Do not work, PCW	
0007-3	2525096	STLMC - Restoration of the life vests (17 each)		
0007-4	2525099	STLMC - Functional test of the portable fire extinguisher (weight test)	Complied with Task 26-25-65-601. Performed Functional test (weight test) of the AFT Cabin portable fire extinguisher, in reference to CL-650 SMM 26-23-00-720-801. Weight is 12.2 lbs, no defects noted.	
0007-5	2525101	STLMC - Functional test of the portable fire extinguisher (weight test)	Complied with Task 26-25-65-601. Performed Functional test (weight test) of the FWD Cabin portable fire extinguisher, in reference to CL-650 SMM 26-23-00-720-801. Weight is 5.38 lbs, no defects noted.	
0007-6	2525104	STLMC - Operational test of the ordinance signs	Complied with Task 33-24-65-601. Performed Operational test of the ordinance signs, in reference to CL-650 SMM 33-24-00-710-801. No defects were noted.	
0007-7	2525106	STLMC - Operational test of the interior emergency lights	Complied with STLMC Task 33-52-65-601, Operational test of the interior emergency lights. REF CL-650 SMM (TR 33-20080701) 33-51-00-710-801. Op Test Good.	
0007-8	2525108	STLMC - General visual inspection of the portable O2 cylinder, regulator, mask		
0007-9	2525110	STLMC - General Visual Inspection of the Water Tank and Distribution Lines	Complied With STLMC Task No. 38-10-65-611 - General Visual Inspection of the Water Tank and Distribution Lines- Ref: CL-650 SMM TASK 38-10-00-210-801. See Finding #78763 for discrepancies noted. See Ops 200 - 1600 for additional work performed.	
0007-10	2525113	STLMC - GVI waste disposal system	Complied with Task Card 38-30-65-601. General Visual Inspection of the waste disposal system. Ref. CL650 SMM 38-30-00-210-801. No discrepancies noted at this time.	
0007-11	4309943	*25-63-65-602 DETAILED INSPECTION OF THE CABIN EMERGENCY EQUIPMENT	Complied with task 25-63-65-602 DETAILED INSPECTION OF THE CABIN EMERGENCY EQUIPMENT Ref CL-605 SMM 25-60-00-220-802	
0007-12	4310171	*38-40-65-601 RESTORATION (OVERHAUL) OF THE BLEED AIR FILTER/REGULATOR		

Sequence #	0007	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	2498530	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

CHILD WORK ORDER DETAILS

	WO #	Description	Corrective Action	AMENDED

Sequence #	0007-1	Aircraft SN #	6111	MWPWO #	2498069
WO #	2525079	Aircraft Reg #	XA-SOL	Parent WO #	2498530

0007-1	WO #	2525079	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		No Log Entry	
STLMC - Discard of the Coffee Maker Water Inlet Filter				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Task Does not apply to aircraft due to different coffee maker not being equipped. Aircraft is equipped with Expresso Maker PN# 925-0018-01 SN# 16-10-04945 Model 1804 . No Filter for water inlet		25-30
	Perform Discard of the Coffee Maker Water Inlet Filter (Coffee Maker PN 900-0019-XX)			

FINDINGS DETAILS

Finding #	Long Description	Status	Reported By / Date	Defect Source / Disposition	Defect Type	Priority	Follow-up WO #
82147	Coffee Maker requires additional time to access Inlet filter	CLOSED	B0599115 - Mark Fierro Feb 26, 2026 7:04 AM	MAINTENANCE 300-QA002	OTHER	3	4842709-INPRG

Bombardier

Sequence #	0007-2	Aircraft SN #	6111	MWPWO #	2498069
WO #	2525094	Aircraft Reg #	XA-SOL	Parent WO #	2498530

0007-2	WO #	2525094	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		No Log Entry	
STLMC - Detailed inspection of the life vests				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			25-00
	Perform Detailed inspection of the life vests			

Bombardier

Sequence #	0007-3	Aircraft SN #	6111	MWPWO #	2498069
WO #	2525096	Aircraft Reg #	XA-SOL	Parent WO #	2498530

0007-3	WO #	2525096	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		No Log Entry	
STLMC - Restoration of the life vests (17 each)				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			25-00
	Perform Restoration of the life vests			

Sequence #	0007-4	Aircraft SN #	6111	MWPWO #	2498069
WO #	2525099	Aircraft Reg #	XA-SOL	Parent WO #	2498530

0007-4	WO #	2525099	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		STLMC - Functional Test of the Portable Fire Extinguisher (Weight Test)	
STLMC - Functional test of the portable fire extinguisher (weight test)				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with Task 26-25-65-601. Performed Functional test (weight test) of the AFT Cabin portable fire extinguisher, in reference to CL-650 SMM 26-23-00-720-801. Weight is 12.2 lbs, no defects noted.	B0638589 - Sean Dodder Feb 03, 2026 04:29 AM	25-00
	Perform Functional test of the portable fire extinguisher (weight test)		B0161691 - Thomas Mitchell Feb 03, 2026 04:51 AM	
	200	Re-Installed AFT Cabin Portable Fire extinguisher, in reference to CL-650 26-23-00-720-801.	B0638589 - Sean Dodder Feb 03, 2026 04:29 AM	
	Removed AFT Cabin Portable Fire extinguisher, in reference to CL-650 26-23-00-720-801.		B0161691 - Thomas Mitchell Feb 03, 2026 04:51 AM	
	300	Removed all tools, equipment, and unwanted materials from the work area.	B0638589 - Sean Dodder Feb 03, 2026 04:29 AM	
	Remove all tools, equipment, and unwanted materials from the work area.		B0161691 - Thomas Mitchell Feb 03, 2026 04:51 AM	

FINDINGS DETAILS

Finding #	Long Description	Status	Reported By / Date	Defect Source / Disposition	Defect Type	Priority	Follow-up WO #
78641	Right side, bottom Divian storage door, does not latch properly upon closing door. This was found during retrieval of the Aft Portable Fire Extinguisher for the weight test.	CLOSED	B0638589 - Sean Dodder Feb 2, 2026 8:49 PM	MAINTENANCE 300-QA002	OTHER	3	4715740-APPR

Sequence #	0007-4	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	2525099	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498530

TOOL INFORMATION

Tool ID	Tool Description	Calibration Due Date
TUSS2392	Digital Scale	Jan 30, 2027 5:00 PM

Sequence #	0007-5	Aircraft SN #	6111	MWPWO #	2498069
WO #	2525101	Aircraft Reg #	XA-SOL	Parent WO #	2498530

0007-5	WO #	2525101	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		STLMC - Functional Test of the Portable Fire Extinguisher (Weight Test)	
STLMC - Functional test of the portable fire extinguisher (weight test)				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with Task 26-25-65-601. Performed Functional test (weight test) of the FWD Cabin portable fire extinguisher, in reference to CL-650 SMM 26-23-00-720-801. Weight is 5.38 lbs, no defects noted.	B0638589 - Sean Dodder Feb 03, 2026 03:29 AM	25-00
	Perform Functional test of the portable fire extinguisher (weight test)		B0161691 - Thomas Mitchell Feb 03, 2026 03:40 AM	
	200	Re-Installed FWD Cabin Portable Fire extinguisher, in reference to CL-650 26-23-00-720-801.	B0638589 - Sean Dodder Feb 03, 2026 03:29 AM	
	Removed FWD Cabin Portable Fire extinguisher, in reference to CL-650 26-23-00-720-801.		B0161691 - Thomas Mitchell Feb 03, 2026 03:40 AM	
	300	Removed all tools, equipment, and unwanted materials from the work area.	B0638589 - Sean Dodder Feb 03, 2026 03:29 AM	
	Remove all tools, equipment, and unwanted materials from the work area.		B0161691 - Thomas Mitchell Feb 03, 2026 03:40 AM	

TOOL INFORMATION

Tool ID	Tool Description	Calibration Due Date
TUSS2392	Digital Scale	Jan 30, 2027 5:00 PM

Bombardier

Sequence #	0007-6	Aircraft SN #	6111	MWPWO #	2498069
WO #	2525104	Aircraft Reg #	XA-SOL	Parent WO #	2498530

0007-6	WO #	2525104	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		STLMC - Operational Test of the Ordinance Signs	
STLMC - Operational test of the ordinance signs				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with Task 33-24-65-601. Performed Operational test of the ordinance signs, in reference to CL-650 SMM 33-24-00-710-801. No defects were noted.	B0638589 - Sean Dodder Feb 03, 2026 02:03 AM	33-00
	Perform Operational test of the ordinance signs		B0161691 - Thomas Mitchell Feb 03, 2026 02:21 AM	
	200	Removed all tools, equipment, and unwanted materials from the work area.	B0638589 - Sean Dodder Feb 03, 2026 02:03 AM	
	Remove all tools, equipment, and unwanted materials from the work area.		B0161691 - Thomas Mitchell Feb 03, 2026 02:21 AM	

Sequence #	0007-7	Aircraft SN #	6111	MWPWO #	2498069
WO #	2525106	Aircraft Reg #	XA-SOL	Parent WO #	2498530

0007-7	WO #	2525106	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		STLMC - Operational test of the interior emergency lights	
STLMC - Operational test of the interior emergency lights				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with STLMC Task 33-52-65-601, Operational test of the interior emergency lights. REF CL-650 SMM (TR 33-20080701) 33-51-00-710-801. Op Test Good.	B0143855 - Marlon Zurita Feb 04, 2026 04:16 PM	33-00
	Perform Operational test of the interior emergency lights		B0143196 - Robert Bohner Feb 04, 2026 04:54 PM	
	200	Complied with removal of all tools, equipment, and unwanted materials from the work area	B0641378 - Calvin Ambrose Feb 04, 2026 02:05 PM	
	Comply with removal of all tools, equipment, and unwanted materials from the work area		B0143196 - Robert Bohner Feb 04, 2026 04:54 PM	

Sequence #	0007-8	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	2525108	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498530

0007-8	**WO #**	**2525108**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		No Log Entry	
STLMC - General visual inspection of the portable O2 cylinder, regulator, mask				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 35-23-65-605. Perform detailed inspection of the Portable Oxygen Equipment. REF CL650 SMM 35-30-00-220-801. No defects noted.		35-00
	Perform General visual inspection of the portable O2 cylinder, regulator, mask			

Sequence #	0007-9	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	2525110	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498530

			LOG BOOK VERBIAGE	Deferrals
0007-9	**WO #**	**2525110**		
	SAP SVO #		STLMC - General Visual Inspection of the Water Tank and Distribution Lines (24M)	
STLMC - General Visual Inspection of the Water Tank and Distribution Lines				
Task / IRN # : 38-10-65-611				

Sequence #	0007-9	Aircraft SN #	6111	MWPWO #	2498069
WO #	2525110	Aircraft Reg #	XA-SOL	Parent WO #	2498530

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied With STLMC Task No. 38-10-65-611 - General Visual Inspection of the Water Tank and Distribution Lines- Ref: CL-650 SMM TASK 38-10-00-210-801. See Finding #78763 for discrepancies noted.	B1017798 - Hunter Van Der Heide Feb 04, 2026 04:08 AM B1019231 - Ivan Bojorquez Feb 04, 2026 02:17 AM	38-10
	C/W General Visual Inspection of the Water Tank and Distribution Lines		B0161691 - Thomas Mitchell Feb 04, 2026 04:39 AM	
	200	Removed 2EA lower galley drawers Ref: CL-650 SMM TASK 25-30-01-000-803	B1019231 - Ivan Bojorquez Feb 04, 2026 02:13 AM	
	Remove 2EA lower galley drawers Ref: CL-650 SMM TASK 25-30-01-000-803		Not Required	
	300	Installed 2EA lower galley drawers Ref: CL-650 SMM TASK 25-30-01-400-803	B0141448 - Graciela Pino Feb 04, 2026 04:56 AM	
	Install 2EA lower galley drawers Ref: CL-650 SMM TASK 25-30-01-400-803		B0161691 - Thomas Mitchell Feb 04, 2026 05:39 AM	
	400	Removed 2EA closeout panels at lower galley trash drawer compartment Ref: CL-650 SMM TASK 25-30-01-000-803	B1019231 - Ivan Bojorquez Feb 04, 2026 02:13 AM	
	Remove 2EA closeout panels at lower galley trash drawer compartment Ref: CL-650 SMM TASK 25-30-01-000-803		Not Required	
	500	Installed 2EA closeout panels at lower galley trash drawer compartment Ref: CL-650 SMM TASK 25-30-01-400-803	B0141448 - Graciela Pino Feb 04, 2026 04:45 AM	
	Install 2EA closeout panels at lower galley trash drawer compartment Ref: CL-650 SMM TASK 25-30-01-400-803		B0161691 - Thomas Mitchell Feb 04, 2026 04:50 AM	
	600	Removed RH1 Dado Panel Ref: CL-650 SMM TASK 25-26-09-000-801	B1019231 - Ivan Bojorquez Feb 04, 2026 02:13 AM	
	Remove RH1 Dado Panel Ref: CL-650 SMM TASK 25-26-09-000-801		Not Required	

Sequence #	0007-9	Aircraft SN #	6111	MWPWO #	2498069
WO #	2525110	Aircraft Reg #	XA-SOL	Parent WO #	2498530

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	700	Installed RH1 Dado Panel Ref: CL-650 SMM TASK 25-26-09-400-801	B0141448 - Graciela Pino Feb 04, 2026 05:05 AM	
	Install RH1 Dado Panel Ref: CL-650 SMM TASK 25-26-09-400-801		B0161691 - Thomas Mitchell Feb 04, 2026 05:39 AM	
	800	Removed Shelf at toilet enclosure Ref: CL-650 SMM TASK 25-40-03-000-801	B1019231 - Ivan Bojorquez Feb 04, 2026 02:13 AM	
	Remove Shelf at toilet enclosure Ref: CL-650 SMM TASK 25-40-03-000-801		Not Required	
	900	Installed Shelf at toilet enclosure Ref: CL-650 SMM TASK 25-40-03-400-801	B0141448 - Graciela Pino Feb 04, 2026 05:11 AM	
	Install Shelf at toilet enclosure Ref: CL-650 SMM TASK 25-40-03-400-801		B0161691 - Thomas Mitchell Feb 04, 2026 05:39 AM	
	1000	Removed Filter access panel at toilet enclosure Ref: CL-650 SMM TASK 25-40-03-000-801	B1019231 - Ivan Bojorquez Feb 04, 2026 02:13 AM	
	Remove Filter access panel at toilet enclosure Ref: CL-650 SMM TASK 25-40-03-000-801		Not Required	
	1100	Installed Filter access panel at toilet enclosure Ref: CL-650 SMM TASK 25-40-03-400-801	B0141448 - Graciela Pino Feb 04, 2026 05:11 AM	
	Install Filter access panel at toilet enclosure Ref: CL-650 SMM TASK 25-40-03-400-801		B0161691 - Thomas Mitchell Feb 04, 2026 05:39 AM	
	1200	Removed baggage upper shelf Ref: CL-650 SMM TASK 25-53-07-000-801	B1019231 - Ivan Bojorquez Feb 04, 2026 02:13 AM	
	Remove baggage upper shelf Ref: CL-650 SMM TASK 25-53-07-000-801		Not Required	
	1300	Installed baggage upper shelf Ref: CL-650 SMM TASK 25-53-07-400-801	B1019231 - Ivan Bojorquez Feb 04, 2026 05:36 AM	
	Install baggage upper shelf Ref: CL-650 SMM TASK 25-53-07-400-801		B0161691 - Thomas Mitchell Feb 04, 2026 05:39 AM	

Sequence #	0007-9	Aircraft SN #	6111	MWPWO #	2498069
WO #	2525110	Aircraft Reg #	XA-SOL	Parent WO #	2498530

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	1400	Removed Upper Drawer at lav vanity Ref: CL-650 SMM TASK 25-40-01-000-801	B1019231 - Ivan Bojorquez Feb 04, 2026 02:13 AM	
	Remove Upper Drawer at lav vanity Ref: CL-650 SMM TASK 25-40-01-000-801		Not Required	
	1500	Installed Upper Drawer at lav vanity Ref: CL-650 SMM TASK 25-40-01-400-801	B0141448 - Graciela Pino Feb 04, 2026 05:34 AM	
	Install Upper Drawer at lav vanity Ref: CL-650 SMM TASK 25-40-01-400-801		B0161691 - Thomas Mitchell Feb 04, 2026 05:39 AM	
	1600	Removed all tools, equipment and unwanted materials from the work area.	B1019231 - Ivan Bojorquez Feb 04, 2026 05:37 AM	
	Remove all tools, equipment and unwanted materials from the work area.		B0161691 - Thomas Mitchell Feb 04, 2026 05:39 AM	

FINDINGS DETAILS

Finding #	Long Description	Status	Reported By / Date	Defect Source / Disposition	Defect Type	Priority	Follow-up WO #
78763	Corrosion Noted at galley heater and line fittings/ trace of previous leak noted at galley trash drawer compartment.	CLOSED	B1019231 - Ivan Bojorquez Feb 3, 2026 6:33 PM	MAINTENANCE 300-QA002	OTHER	3	4715668-APPR

TOOL INFORMATION

Tool ID	Tool Description	Calibration Due Date
TUSS5127	Torque Wrench	Aug 30, 2026 5:00 PM

Sequence #	0007-10	Aircraft SN #	6111	MWPWO #	2498069
WO #	2525113	Aircraft Reg #	XA-SOL	Parent WO #	2498530

0007-10	WO #	2525113	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Complied with Task Card 38-30-65-601 - General Visual Inspection of the Waste Disposal System. Ref. CL650 SMM 38-30-00-210-801. No Discrepancies Noted.	
STLMC - GVI waste disposal system				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with Task Card 38-30-65-601. General Visual Inspection of the waste disposal system. Ref. CL650 SMM 38-30-00-210-801. No discrepancies noted at this time.	K1018275 - Emmanuel Cocoa Feb 27, 2026 07:11 PM	38-00
	Perform GVI waste disposal system		B1013522 - Brandon Jennings Feb 27, 2026 07:31 PM	
	200	Removed all tools equipment and unwanted materials.	K1018275 - Emmanuel Cocoa Feb 27, 2026 07:33 PM	
	Remove all tools equipment and unwanted materials.		B1013522 - Brandon Jennings Feb 27, 2026 07:39 PM	

Sequence #	0007-11	Aircraft SN #	6111	MWPWO #	2498069
WO #	4309943	Aircraft Reg #	XA-SOL	Parent WO #	2498530

0007-11	WO #	4309943	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Complied with STLMC Task - 25-63-65-602 - Detailed Inspection of the Cabin Emergency Equipment Ref CL-605 SMM 25-60-00-220-802.	
*25-63-65-602 DETAILED INSPECTION OF THE CABIN EMERGENCY EQUIPMENT				
Task / IRN # : 25-63-65-602				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 25-63-65-602 DETAILED INSPECTION OF THE CABIN EMERGENCY EQUIPMENT Ref CL-605 SMM 25-60-00-220-802	B0141448 - Graciela Pino Feb 04, 2026 01:50 AM B0161867 - Jeremy Kucera Feb 04, 2026 01:56 AM	25-00
	*25-63-65-602 DETAILED INSPECTION OF THE CABIN EMERGENCY EQUIPMENT		B0161691 - Thomas Mitchell Feb 04, 2026 03:26 AM	
	200	Removed all tools, equipment and unwanted materials from the work area.	B0141448 - Graciela Pino Feb 04, 2026 04:50 AM	
	Remove all tools, equipment and unwanted materials from the work area.		B0161691 - Thomas Mitchell Feb 04, 2026 05:05 AM	

Sequence #	0007-12	Aircraft SN #	6111	MWPWO #	2498069
WO #	4310171	Aircraft Reg #	XA-SOL	Parent WO #	2498530

0007-12	WO #	4310171	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		No Log Entry	
*38-40-65-601 RESTORATION (OVERHAUL) OF THE BLEED AIR FILTER/REGULATOR				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with STLMC TASK 38-40-65-601 Restoration (overhaul) of the bleed air filter/ regulator REF: A/C 6111 SMM Task 38-40-00-840-801 Step 1.A. to Step 1.E.(2) continue with step 1.E.(3) to 1.F.(2)	B0599115 - Mark Fierro Feb 25, 2026 09:04 PM B1018553 - Joshua Jackson Feb 25, 2026 08:26 PM	38-00
	*38-40-65-601 RESTORATION (OVERHAUL) OF THE BLEED AIR FILTER/REGULATOR		B1013522 - Brandon Jennings Feb 25, 2026 09:17 PM	
	101			
	*38-40-65-601 RESTORATION (OVERHAUL) OF THE BLEED AIR FILTER/REGULATOR continue with step 1.E.(3) to 1.F.(2)			

REMOVE AND RE-INSTALL DETAILS

	Removed Part # / Removed Serial #	Removed By	Removed - Part Description	Reference	Installed Part # / Installed Serial #	Installed By
	Removed Status	Removed Date-Time	Position	Installed Part Status	Installed Part Description	Installed Date-Time
	14E05B16FC	B1018553 - Joshua Jackson	REGULATOR, PLASTIC BOWL	SMM 38-40-00-840-801	14E05B16FC	B1018553 - Joshua Jackson
	UNSERVICEABLE	Feb 25, 2026 1:20 PM	AFT FUSELAGE	NEW	REGULATOR, PLASTIC BOWL	Feb 25, 2026 1:20 PM

Sequence #	0007-12	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4310171	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498530

FINDINGS DETAILS

Finding #	Long Description	Status	Reported By / Date	Defect Source / Disposition	Defect Type	Priority	Follow-up WO #
82036	During restoration of the bleed air filter regulator and filter it was noticed that one of the mounting brackets for one of the air lines is disbonded	CLOSED	B1018553 - Joshua Jackson Feb 25, 2026 12:55 PM	MAINTENANCE 300-QA002	OTHER	3	4842723-RDYPM

TOOL INFORMATION

Tool ID	Tool Description	Calibration Due Date
TUSS2038	Torque wrench	Jul 30, 2026 5:00 PM

Sequence #	0008	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	2503653	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

0008	**WO #**	**2503653**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #	13276324	48 month inspection	
48 month inspection				
Task / IRN # : C3500047				

Sequence #	0008	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503653	Aircraft Reg #	XA-SOL	Parent WO #	2498069

CHILD WORK ORDER DETAILS

	WO #	Description	Corrective Action	AMENDED
0008-1	2503705	Lubrication of the elevator servo	Complied with task 22-11-00-202 Lubrication of the elevator servo IAW CL-650 AMM 12-20-04-640-835. No defects noted. See elevator servo install working copy dated 2/12/26.	
0008-2	2503707	Detailed Inspection of the Fire-Extinguishing- System Lines	Complied with task 26-21-16-201, Perform Detailed Inspection of the Fire-Extinguishing- System Lines. REF CL650 AMM 26-20-00-220-802. No defects noted.	
0008-3	2503709	Detailed Inspection of the Rudder and Elevator Control Cables in the Fuselage/Stabilizer Section	Complied with task 27-00-00-208, Detailed Inspection of the Rudder and Elevator Control Cables in the Fuselage/ Stabilizer Section, in accordance with CL650 AMM 27-00-00-220-808. No defects noted.	
0008-4	2503712	Detailed Inspection of the Aileron Control Cables in the Control Column	Complied with task 27-00-00-212 Detailed Inspection of the Aileron Control Cables in the Control Column ref. CL-650 AMM 27-11-00-220-814. No defects noted.	
0008-5	2503714	Detailed Inspection of the Horizontal-Stabilizer Trim-Actuator Assembly	Complied with Task 27-40-00-202. Performed Detailed Inspection of the Horizontal-Stabilizer Trim-Actuator Assembly, in reference to CL-650 AMM 27-42-01-220-801. No defects were noted at this time.	
0008-6	2503715	Lubrication of the Horizontal Stabilizer Pitch-Trim-Actuator	Complied with task 27-40-00-204 Lubrication of the Horizontal Stabilizer Pitch-Trim-Actuator IAW CL-650 AMM 12-20-04-640-817.	
0008-7	2503718	Detailed Inspection of the Landing-Gear Emergency-Extension Cable in the Forward Avionics Compartment	Performed Detailed Inspection of the Landing-Gear Emergency-Extension Cable in the Forward Avionics Compartment in accordance with CL-650 AMM 32-34-28-220-803. No defects noted.	
0008-8	2503720	Detailed Inspection of the Landing-Gear Emergency-Extension Cable in the Main Avionics Compartment	Performed Detailed Inspection of the Landing-Gear Emergency-Extension Cable in the Main Avionics Compartment in accordance with CL-650 AMM 32-34-28-220-804. No defects noted.	
0008-9	2503722	General Visual Inspection of the Nose-Landing-Gear Door - LH	C/W Task 32-ZL-00-204, Performed General Visual Inspection of the Nose-Landing-Gear Door - LH IAW CL650 AMM 32-22-00-210-801. No Defects Noted.	

Sequence #	0008	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503653	Aircraft Reg #	XA-SOL	Parent WO #	2498069

CHILD WORK ORDER DETAILS

	WO #	Description	Corrective Action	AMENDED
0008-10	2503724	General Visual Inspection of the Nose Landing Gear Door - RH	Complied with TLMC 32-ZL-00-205. Performed a General Visual Inspection of the Nose-Landing-Gear Door - RH Ref. CL-650 AMM 32-22-00-210-801. No Defects Noted	
0008-11	2503726	General Visual Inspection of the Main-Landing-Gear Door - LH	C/W Task 32-ZL-00-207 Performed General Visual Inspection of the Main-Landing-Gear Door - LH IAW CL650 AMM 32-12-00-210-801. See findings for defects	
0008-12	2503728	General Visual Inspection of the Main-Landing-Gear Door - RH	C/W Task 32-ZL-00-208 Performed General Visual Inspection of the Main-Landing-Gear Door - RH IAW CL650 AMM 32-12-00-210-801. Ref WO 2503726 78816 for Defects	
0008-13	2503730	Functional Test of the Integrated Standby Instrument		
0008-14	2503732	Detailed Inspection of the Fittings and Attachments of the Passenger Door	Complied with TLMC task 52-11-00-202 Performed detailed inspection of the fittings and attachments of the passenger door REF CL-650 AMM 52-11-01-220-802. No defects noted.	
0008-15	2503734	General Visual Inspection of the Passenger Door - External	Complied with TLMC task 52-ZL-00-206 Performed general visual inspection of the passenger door (External) REF CL-650 AMM 52-11-01-210-802. No defects noted.	
0008-16	2503736	General Visual Inspection of the Passenger Door - Internal	Performed General Visual Inspection of the Passenger door - Internal IAW CL-650 AMM 52-11-01-210-803. COMPLIED with task 52-ZL-00-207. No Discrepancies Noted.	
0008-17	2503738	General Visual Inspection of the Overwing Emergency Exit Door - Internal	Complied with task 52-ZL-00-209 General Visual Inspection of the Overwing Emergency-Exit Door - Internal REF CL650 AMM 52-21-01-210-803. No defects noted at this time	
0008-18	2503740	General Visual Inspection of the Cargo Compartment Door - External	C/W Task 52-ZL-00-210 Performed General Visual Inspection of the Cargo Compartment Door - External IAW CL650 AMM 52-31-01-210-801 See Findings For Defects	
0008-19	2503742	General Visual Inspection of the Cargo Compartment Door - Internal	Complied with TLMC task 52-ZL-00-211 Performed general visual inspection of the cargo compartment door (Internal) REF CL-650 AMM 52-31-01-210-802. No defects noted.	
0008-20	2503743	Detailed Inspection of the NLG Wheel Well Structure	Complied with TLMC 53-10-00-212. Performed a Detailed Inspection of the NLG Wheel Well Structure Ref. CL-650 AMM 53-10-01-220-811. No defects noted.	

Sequence #	0008	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503653	Aircraft Reg #	XA-SOL	Parent WO #	2498069

CHILD WORK ORDER DETAILS

	WO #	Description	Corrective Action	AMENDED
0008-21	2503746	Detailed Inspection of the NLG Internal Box Structure - FS169 to FS235	Complied with task 53-10-00-213, Perform Detailed Inspection of the NLG Internal Box Structure - FS169 to FS235, in accordance with CL650 AMM 53-10-01-220-812. No defects noted.	
0008-22	2503748	Detailed Inspection of the Fittings and the Hinge on the Fuselage for the Passenger Door	Complied with TLMC 53-20-00-202. Performed the Detailed Inspection of the Fittings and the Hinge on the Fuselage for the Passenger Door Ref. CL-650 AMM 53-20-01-220-802. No defects noted.	
0008-23	2503749	Detailed Inspection of the Aft Keel Beam - FS513 to FS559	Complied with TLMC task 53-20-00-212 Performed Detailed inspection of the Aft Keel Beam (FS513 to FS559 REF CL-650 AMM 53-20-01-220-810. No defects noted.	
0008-24	2503752	Detailed Inspection of the Profile Plates of the Floor Support Structure - FS621	Complied with TLMC task 53-30-00-207 Performed detailed inspection of the profile plates of the floor structure (FS621) REF CL-650 AMM 53-30-01-220-821. No defects noted	
0008-25	2503754	Detailed Inspection of the Internal Skin and Fuselage Structure - FS621 to FS755	Complied with task 53-30-00-215 REF CL650 AMM 53-30-01-220-814. No defects noted at this time.	
0008-26	2503755	Detailed Inspection of the External Skin around the APU Exhaust Cutout	Performed Detailed Inspection of the External Skin around the APU Exhaust cutout IAW CL-605 AMM 53-30-01-220-817 . Complied with task 53-30-00-217 . NO DISCREPANCIES FOUND .	
0008-27	2503758	General Visual Inspection of the Nose Radome - External	complied with task 53-ZL-00-201. Performed a General Visual Inspection of the Nose Radome - External IAW CL 650 AMM 53-10-01-210-801. no defects noted.	
0008-28	2503760	General Visual Inspection of the Nose Radome - Internal	Complied with Task 53-ZL-00-202. Performed General Visual Inspection of the Nose Radome - Internal, in reference to CL-650 AMM 53-10-01-210-802. See finding 79097 for details.	
0008-29	2503761	General Visual Inspection of the Nose Compartment - Lower Internal RH	Complied with task 53-ZL-00-205, Perform General Visual Inspection of the Nose Compartment - Lower Internal RH. REF CL650 AMM 53-10-01-210-805. No defects noted.	
0008-30	2503764	General Visual Inspection of the NLG Wheel Well	C/W Task 53-ZL-00-206, Performed General Visual Inspection of the NLG Wheel Well IAW CL650 AMM 53-10-01-210-806. No Defects Noted.	

Sequence #	0008	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503653	Aircraft Reg #	XA-SOL	Parent WO #	2498069

CHILD WORK ORDER DETAILS

	WO #	Description	Corrective Action	AMENDED
0008-31	2503766	General Visual Inspection of the Forward Avionics and Flight Controls Compartment - Internal LH	Complied with Task 53-ZL-00-208. Performed General Visual Inspection of the Forward Avionics and Flight Controls Compartment - Internal, in reference to CL-650 AMM 53-10-01-210-808. No defects were noted at this time.	
0008-32	2503768	General Visual Inspection of the Forward Avionics and Flight Controls Compartment - Internal RH	Complied with Task 53-ZL-00-209. Performed General Visual Inspection of the Forward Avionics and Flight Controls Compartment - Internal, in reference to CL-650 AMM 53-10-01-210-808. No defects were noted at this time.	
0008-33	2503770	General Visual Inspection of the Main Avionics Compartment - External	Complied with Task 53-ZL-00-210. Performed General Visual Inspection of the Main Avionics Compartment - External, in reference to CL-650 AMM 53-20-01-210-801. No defects were noted at this time.	
0008-34	2503772	General Visual Inspection of the Main Avionics Compartment - Internal	Complied with Task 53-ZL-00-211. Performed General Visual Inspection of the Main Avionics Compartment - Internal, in reference to CL-650 AMM 53-20-01-210-802. No defects were noted at this time.	
0008-35	2503774	General Visual Inspection of the Mid-Fuselage - Lower External	Complied with TLMC task 53-ZL-00-212 Performed general visual inspection of the Mid-Fuselage (lower external) REF CL-650 AMM 53-20-01-210-803. No defects noted.	
0008-36	2503776	General Visual Inspection of the Forward Equipment Compartment - Internal	Complied with task 53-ZL-00-219, Perform General Visual Inspection of the Forward Equipment Compartment - Internal, in accordance with 650 MM 53-10-01-210-810.	
0008-37	2503778	General Visual Inspection of the Flight Compartment - Internal without removal of the headliner and the glareshield	Complied with task 53-ZL-00-221, Perform General Visual Inspection of the Flight Compartment - Internal without Removal of the Headliner and the Glareshield, No defects noted at this time REF 650 AMM 53-10-01-210-812.	
0008-38	2503780	General Visual Inspection of the Aft Equipment Compartment - External	C/W Task 53-ZL-00-227, Performed General Visual Inspection of the Aft Equipment Compartment - External IAW CL650 AMM 53-30-01-210-805. No Defects Noted.	
0008-39	2503781	General Visual Inspection of the Fuselage/Stabilizer Section - Internal	Complied with task 53-ZL-00-230, Perform General Visual Inspection of the Fuselage/Stabilizer Section - Internal, in accordance with CL650 AMM 53-43-01-210-802. No defects noted.	

Sequence #	0008	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503653	Aircraft Reg #	XA-SOL	Parent WO #	2498069

CHILD WORK ORDER DETAILS

	WO #	Description	Corrective Action	AMENDED
0008-40	2503784	General Visual Inspection of the Tail Cone - External	complied with task 53-ZL-00-231. Performed a General Visual Inspection of the Tail Cone - External IAW CL 350 AMM 53-66-01-210-801. no defects noted.	
0008-41	2503787	General Visual Inspection of the Tail Cone - Internal	Complied with TLMC task 53-ZL-00-232 Performed general visual inspection of the tail cone (Internal) REF BD-650 AMM 53-66-01-210-802. No defects noted.	
0008-42	2503788	General Visual Inspection of the Pylon - External LH	complied with task 54-ZL-00-201. Performed a General Visual Inspection of the L/H Pylon - External IAW CL 350 AMM 54-50-01-210-801. no defects noted	
0008-43	2503791	General Visual Inspection of the Pylon - External RH	complied with task 54-ZL-00-202. Performed a General Visual Inspection of the R/H Pylon - External IAW CL 350 AMM 54-50-01-210-801. no defects noted	
0008-44	2503793	General Visual Inspection of the Pylon Leading Edge - Internal LH	complied with task 54-ZL-00-203. Performed a General Visual Inspection of the L/H Pylon Leading Edge - Internal IAW CL 650 AMM 54-61-04-210-801. no defects noted.	
0008-45	2503794	General Visual Inspection of the Pylon Leading Edge - Internal RH	complied with task 54-ZL-00-204. Performed a General Visual Inspection of the R/H Pylon Leading Edge - Internal IAW CL 650 AMM 54-61-04-210-801. no defects noted.	
0008-46	2503797	General Visual Inspection of the Pylon Mid-Section - Internal LH	Complied with task 54-ZL-00-205, Perform General Visual Inspection of the Pylon Mid-Section - Internal LH, REF: Challenger 650 AMM 54-51-05-210-801. No defects noted.	
0008-47	2503799	General Visual Inspection of the Pylon Mid-Section - Internal RH	Complied with task 54-ZL-00-206, Perform General Visual Inspection of the Pylon Mid-Section - Internal RH, REF: Challenger 650 AMM 54-51-05-210-801. No defects noted.	
0008-48	2503800	Detailed Inspection of the Inner Pivot Pin of the Horizontal Stabilizer	Complied with TLMC task 55-10-00-207 Performed detailed inspection of the inner pivot pin of the horizontal stabilizer REF CL-650 AMM 55-10-01-220-815. No defects noted.	
0008-49	2503804	General Visual Inspection of the Vertical Stabilizer Assembly - External	Complied with Task 55-ZL-00-201. Performed General Visual Inspection of the Vertical Stabilizer Assembly - External, in reference to CL-650 AMM 55-30-01-210-806. No defects were noted.	

Sequence #	0008	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503653	Aircraft Reg #	XA-SOL	Parent WO #	2498069

CHILD WORK ORDER DETAILS

	WO #	Description	Corrective Action	AMENDED
0008-50	2503806	General Visual Inspection of the Wing Center Section - External LH	Complied with TLMC task 57-ZL-00-201 Performed general visual inspection of the LH wing center section (External) REF CL-650 AMM 57-10-00-210-801. No defects noted.	
0008-51	2503807	General Visual Inspection of the Wing Center Section - External RH	Complied with TLMC task 57-ZL-00-202 Performed general visual inspection of the RH wing center section (External) REF CL-650 AMM 57-10-00-210-801. No defects noted.	
0008-52	2503810	General Visual Inspection of the Inboard Leading Edge of the Wing - External LH	C/W Task 57-ZL-00-206, Performed General Visual Inspection of the Inboard Leading Edge of the Wing - External LH IAW CL650 AMM 57-40-00-210-801. Ref WO 4540931 for Defects	
0008-53	2503812	General Visual Inspection of the Inboard Leading Edge of the Wing - External RH	C/W Task 57-ZL-00-207, Performed General Visual Inspection of the Inboard Leading Edge of the Wing - External RH IAW CL650 AMM 57-40-00-210-801. Ref WO 4540931 for Defects	
0008-54	2503813	General Visual Inspection of the Outboard Leading Edge of the Wing - External LH	complied with task 57-ZL-00-210. performed a General Visual Inspection of the Outboard Leading Edge of the L/H Wing - External IAW CL 650 AMM 57-40-00-210-803. see W/O: 4540931 for corrective action to defects noted.	
0008-55	2503815	General Visual Inspection of the Outboard Leading Edge of the Wing - External RH	complied with task 57-ZL-00-211. performed a General Visual Inspection of the Outboard Leading Edge of the R/H Wing - External IAW CL 650 AMM 57-40-00-210-803. no defects noted	
0008-56	2503818	General Visual Inspection of the Wing from WS47 to WS148 - External LH	Complied with TLMC task 57-ZL-00-214 Performed general visual inspection of the LH wing from WS47 to WS148 (External) REF CL-650 AMM 57-10-00-210-803. No defects noted.	
0008-57	2503819	General Visual Inspection of the Wing from WS47 to WS148 - External RH	Complied with TLMC task 57-ZL-00-215 Performed general visual inspection of the RH wing from WS47 to WS148 (External) REF CL-650 AMM 57-10-00-210-803. No defects noted.	
0008-58	2503820	General Visual Inspection of the Wing from WS148 to WS353 - External LH	Complied with TLMC task 57-ZL-00-218 Performed general visual inspection of the LH wing from WS148 to WS353 (External) REF CL-650 AMM 57-10-00-210-805. No defects noted.	

Sequence #	0008	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503653	Aircraft Reg #	XA-SOL	Parent WO #	2498069

CHILD WORK ORDER DETAILS

	WO #	Description	Corrective Action	AMENDED
0008-59	2503824	General Visual Inspection of the Wing from WS148 to WS353 - External RH	Complied with TLMC task 57-ZL-00-219 Performed general visual inspection of the RH wing from WS148 to WS353 (External) REF CL-650 AMM 57-10-00-210-805. No defects noted.	
0008-60	2503825	General Visual Inspection of the Winglet - External LH	Complied with TLMC task 57-ZL-00-222 Performed general visual inspection of the LH winglet (External) REF CL-650 AMM 57-30-00-210-801.	
0008-61	2503826	General Visual Inspection of the Winglet - External RH	Complied with TLMC task 57-ZL-00-223 Performed general visual inspection of the RH winglet (External) REF CL-650 AMM 57-30-00-210-801.	
0008-62	2503830	General Visual Inspection of the Inboard Trailing Edge of the Wing - External LH	C/W Task 57-ZL-00-226 Performed General Visual Inspection of the Inboard Trailing Edge of the Wing - External LH IAW CL650 AMM 57-50-01-210-801 No Defects Noted.	
0008-63	2503831	General Visual Inspection of the Inboard Trailing Edge of the Wing - External RH	C/W Task 57-ZL-00-227, Performed General Visual Inspection of the Inboard Trailing Edge of the Wing - External RH IAW CL650 AMM 57-50-01-210-801. No Defects Noted	
0008-64	2503832	General Visual Inspection of the Outboard Trailing Edge of the Wing - External LH	complied with task 57-ZL-00-203. Performed a General Visual Inspection of the Outboard Trailing Edge of the L/H Wing - External IAW CL 650 AMM 57-50-01-210-803. see findings for defects noted.	
0008-65	2503836	General Visual Inspection of the Outboard Trailing Edge of the Wing - External RH	complied with task 57-ZL-00-231. Performed a General Visual Inspection of the Outboard Trailing Edge of the R/H Wing - External IAW CL 650 AMM 57-50-01-210-803. see findings 78871 for defects noted.	
0008-66	2503837	General Visual Inspection of the Nacelle - External LH	C/W Task 71-ZL-00-201, Performed General Visual Inspection of the Nacelle - External LH IAW Cl650 AMM 71-10-00-210-801. No Defects Noted	
0008-67	2503838	General Visual Inspection of the Nacelle - External RH	C/W Task 71-ZL-00-202, Performed General Visual Inspection of the Nacelle - External RH IAW CL650 AMM 71-10-00-210-801. No Defects Noted	

Sequence #	0008	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503653	Aircraft Reg #	XA-SOL	Parent WO #	2498069

CHILD WORK ORDER DETAILS

	WO #	Description	Corrective Action	AMENDED
0008-68	2503842	General Visual Inspection of the Translating Cowl - Internal LH	Complied with task 71-ZL-00-205, Performed General Visual Inspection of the Translating Cowl - Internal LH, in accordance with CL 650 AMM 71-11-01-210-801. No defects noted	
0008-69	2503843	General Visual Inspection of the Translating Cowl - Internal RH	Complied with task 71-ZL-00-206, Performed General Visual Inspection of the Translating Cowl - Internal RH, in accordance with CL 650 AMM 71-11-01-210-801.No defects noted	
0008-70	2503844	General Visual Inspection of the Torque Box of the Thrust Reverser - Internal LH	Complied with task 78-ZL-00-201, Perform General Visual Inspection of the Torque Box of the Thrust Reverser - Internal LH, in accordance with CL-650 AMM 78-30-00-210-802. defects noted. See finding 79069	
0008-71	2503848	General Visual Inspection of the Torque Box of the Thrust Reverser - Internal RH	Complied with task 78-ZL-00-202, Perform General Visual Inspection of the Torque Box of the Thrust Reverser - Internal RH, in accordance with CL-650 AMM 78-30-00-210-802. Defects noted. Finding 79068	
0008-72	2503849	General Visual Inspection of the Exhaust Nozzle Fairing-Assembly LH	Complied with Task 78-ZL-00-203. Performed General Visual Inspection of the Exhaust Nozzle Fairing-Assembly LH, in reference to CL-650 AMM 78-10-01-210-801. See finding 78917 and 78920 for details.	
0008-73	2503850	General Visual Inspection of the Exhaust Nozzle Fairing-Assembly RH	Complied with Task 78-ZL-00-204. Performed General Visual Inspection of the Exhaust Nozzle Fairing-Assembly RH, in reference to CL-650 AMM 78-10-01-210-801. See findings 78922 and 78923 for details.	
0008-74	2503854	Detailed Inspection of the Lightning/High Intensity Radiated Field (L/HIRF) protection in the Fuselage/Stabilizer - Internal	Complied with TLMC Task 22-12-00-202 Detailed Inspection of the Lightning/High Intensity Radiated Field (L/HIRF) protection in the Fuselage/Stabilizer - Internal IAW CL650 AMM Task 22-12-22-220-802. No defects noted. Removed all tools, equipment, and unwanted materials from the work area.	

Sequence #	0008	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503653	Aircraft Reg #	XA-SOL	Parent WO #	2498069

CHILD WORK ORDER DETAILS

	WO #	Description	Corrective Action	AMENDED
0008-75	2503855	Detailed Inspection of the Lightning/High Intensity Radiated Field (L/HIRF) Protection in the Aft Equipment Compartment	Complied with TLMC Task 22-12-00-204 Detailed Inspection of the Lightning/High Intensity Radiated Field (L/HIRF) Protection in the Aft Equipment Compartment IAW CL650 AMM Task 22-12-22-220-804. Finding for MINI QAR created REF finding # 80010.	
0008-76	2503857	Detailed Inspection of the Lightning/High Intensity Radiated Field (L/HIRF) Protection in the Avionics Compartments	Complied with task 22-12-00-208 detailed inspection of the lightning/ high intensity radiated field (L/HIRF) protection in the avionics compartments IAW CL-650 AMM 22-12-22-220-808 No defects noted	
0008-77	2503860	Detailed Inspection of the Lightning/High Intensity Radiated Field (L/HIRF) Protection in the Main Wheel Wells	Complied with task 22-12-00-212 detailed inspection of lightning/ high intensity radiated field 9L/HIRF) protection in the main wheel wells IAW CL-650 AMM 22-12-22-220-812 No defects noted	
0008-78	2503861	Detailed Inspection of the Lightning/High Intensity Radiated Field (L/HIRF) Protection in the Nose Wheel Well and Landing Gear Assembly	Complied with TLMC Task 22-12-00-213, Perform Detailed Inspection of the Lightning/High Intensity Radiated Field (L/HIRF) Protection in the Nose Wheel Well and Landing Gear Assembly. REF CL-650 AMM 22-12-22-220-813. No Defects Noted.	
0008-79	2503863	Functional Test (Bonding Check) of the Static Discharger Base	Complied with task 23-60-00-202, Functional Test (Bonding Check) of the Static Discharger Base, in accordance with CL-650 AMM 23-61-04-720-801 BOND TEST GOOD.	
0008-80	2503866	Detailed Inspection of the Aileron, Rudder, Elevator and Spoiler Control Cables in the Lower Forward Fuselage	Complied with task 27-00-00-201 Detailed Inspection of the Aileron, Rudder, Elevator and Spoiler Control Cables in the Lower Forward Fuselage IAW CL-650 AMM 27-00-00-220-801. No defects noted.	
0008-81	2503867	Detailed Inspection of the Aileron, Rudder, Elevator and Spoiler Control Cables in the Main Avionics Compartment	Complied with task 27-00-00-202, Perform Detailed Inspection of the Aileron, Rudder, Elevator and Spoiler Control Cables in the Main Avionics Compartment., in accordance with CL650 AMM 27-00-00-220-802. No defects noted.	
0008-82	2503869	Detailed Inspection of the Aileron Control Cables in the Outboard Wing Box	Complied with task 27-00-00-209, Perform LH and RH Detailed Inspection of the Aileron Control Cables in the Outboard Wing Box, REF CL650 AMM 27-11-00-220-811. No defects noted.	

Sequence #	0008	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503653	Aircraft Reg #	XA-SOL	Parent WO #	2498069

CHILD WORK ORDER DETAILS

	WO #	Description	Corrective Action	AMENDED
0008-83	2503873	Detailed Inspection of the Landing-Gear Emergency-Extension Cable in the NLG Wheel Well	Complied with TLMC 32-00-01-208. Performed a Detailed Inspection of the Landing-Gear Emergency-Extension Cable in the NLG Wheel Well Ref. CL-650 AMM 32-34-28-220-802. No defects noted.	
0008-84	2503874	General Visual Inspection of the Aft Nose-Landing-Gear Door	C/W Task 32-ZL-00-206, Performed General Visual Inspection of the Aft Nose-Landing-Gear Door IAW CL650 AMM 32-22-00-210-801. No Defects Noted	
0008-85	2503877	Detailed Inspection of the Door Frame Machined Fittings, Stops and Hooks of the Overwing Emergency-Exit Door	Complied with TLMC task 52-21-00-204 Performed detailed inspection of the door frame machined fittings, stops and hooks of the overwing emergency-exit door. REF CL-650 AMM 52-21-01-220-802. No defects noted.	
0008-86	2503879	General Visual Inspection of the Main Landing Gear Wheel Well	Complied with TLMC 53-ZL-00-214. Performed a General Visual Inspection of the LH & RH Main Landing Gear Wheel Well Ref. CL-650 AMM 53-20-01-210-805. See Findings 79009, 79011, and 79020 for defects found.	
0008-87	2503881	Detailed Inspection of the Aft Face of the Rear Spar of the Wing - WS48 to WS353	Complied with TLMC task 57-10-00-211 Performed Detailed inspection of the Aft face of the LH/RH rear spar of the wing from WS48 to WS353 REF CL-650 AMM 57-10-00-220-811. No defects noted.	
0008-88	2503885	Detailed Inspection of the Internal Wing (Auxiliary Spar, Planks, Skins, Structure and the MLG Trunnion Fitting) - WS48.00 to WS139.90	Complied with TLMC task 57-10-00-217 Performed detailed inspection of the LH/RH internal wing (Auxiliary spar, skins, structure and the MLG trunnion fitting) WS48.00 to WS139.90 REF CL-650 AMM 57-10-00-220-868. No defects noted.	
0008-89	2503888	Detailed Inspection of the Inboard Flap and Inboard Flap Vane (External Surfaces)	Complied with task 57-50-00-201 Detailed Inspection of the Inboard Flap and Inboard Flap Vane (External Surfaces) IAW CL-650 AMM 57-50-01-220-816. See finding 79664.	
0008-90	2503891	Detailed Inspection of the Outboard Flap (External Surfaces) and the Outboard Flap Vane (External Surfaces and Support Fittings)	Complied with task 57-50-00-206 Detailed Inspection of the Outboard Flap (External Surfaces) and the Outboard Flap Vane (External Surfaces and Support Fittings) IAW CL-650 AMM 57-50-01-220-817. No defects noted.	

Sequence #	0008	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503653	Aircraft Reg #	XA-SOL	Parent WO #	2498069

CHILD WORK ORDER DETAILS

	WO #	Description	Corrective Action	AMENDED
0008-91	2503892	Detailed Inspection of the External Surfaces and Forward Face of the Front Spar of the Ground Spoiler	Complied with task 57-70-00-201, Perform Detailed Inspection of LH and RH External Surfaces and Forward Face of the Front Spar of the Ground Spoiler, REF CL650 AMM 57-70-01-220-801. No defects noted.	
0008-92	2503897	Special Detailed Inspection of the Bonded Skins of the Ground Spoiler	Complied with Task No. 57-70-00-202. Performed a Special Detailed Inspection of the Bonded Skins of both the LH and RH Ground Spoiler. See Finding No. 79852 Ref: CL650 AMM 57-70-01-280-801	
0008-93	2503900	Detailed Inspection of the External Surfaces and Forward Face of the Front Spar of the Flight Spoiler	Complied with task 57-70-00-203, Perform Detailed Inspection of LH & RH External Surfaces and Forward Face of the Front Spar of the Flight Spoiler, REF CL650 AMM 57-70-01-220-802. No defects noted.	
0008-94	2503902	Special Detailed Inspection of the Bonded Skins of the Flight Spoiler	Complied with Task No. 57-70-00-204. Performed a Special Detailed Inspection of the Bonded Skins of both the LH and RH Flight Spoiler. No defects noted. Ref: CL650 AMM 57-70-01-280-802	
0008-95	2503906	Functional Test (Bonding Check) of the Nose-Radome Lightning Strips		
0008-96	2503908	Detailed Inspection of the Aileron and Spoiler Control Cables in the Main Landing Gear (MLG) Wheel Well	Complied with task 27-00-00-203 Detailed Inspection of the Aileron and Spoiler Control Cables in the Main Landing Gear (MLG) Wheel Well IAW CL-650 AMM 27-00-00-220-803. No defects noted.	
0008-97	2503911	Detailed Inspection of the Landing Gear Emergency Extension Cable in the MLG Wheel Well	Complied with Task Card 32-00-01-212. Perform LH and RH Detailed Inspection of the Landing Gear Emergency Extension Cable in the MLG Wheel Well. Ref. CL650 AMM 32-34-28-220-806. No discrepancies noted at this time.	
0008-98	2503913	Special Detailed Inspection of the Main Landing-Gear Side Brace Fitting Shaft, Part Number 601R10237-1 only	Deferral Code: Do Not Work Reason: Customer Request Details: Not on customer due list, per CAMP N/A	
0008-99	2503917	Lubrication of the Wing-to-Fuselage Attachment Links-FS513.00	Complied with TLMC task 53-20-00-233 Performed lubrication of the LH/RH wing to fuselage attachment links (FS513.00) REF CL-650 AMM 12-20-04-640-819.	

Sequence #	0008-1	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503705	Aircraft Reg #	XA-SOL	Parent WO #	2503653

0008-1	WO #	2503705	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Lubrication of the Elevator Servo	
Lubrication of the elevator servo				
CRITICAL MAINTENANCE TASK				
Task / IRN # : 22-11-00-202				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 22-11-00-202 Lubrication of the elevator servo IAW CL-650 AMM 12-20-04-640-835. No defects noted. See elevator servo install working copy dated 2/12/26.	B0650736 - Jesus Gonzalez Atondo Feb 12, 2026 03:53 PM	12-20
	Perform Lubrication of the elevator servo		B1013522 - Brandon Jennings Feb 12, 2026 04:06 PM	
	200	Removed the elevator servo IAW CL-650 AMM 22-11-13-000-801.	B0650736 - Jesus Gonzalez Atondo Feb 12, 2026 02:22 PM	
	Remove the elevator servo ref. CL-650 AMM 22-11-13-000-801.		Not Required	
CMT	300	Installed the elevator servo ref. CL-650 AMM 22-11-13-400-801. See working copy dated 2/12/26. Bond test good. (1miliohm)	B0650736 - Jesus Gonzalez Atondo Feb 12, 2026 03:53 PM	
	Install the elevator servo ref. CL-650 AMM 22-11-13-400-801.		B1013522 - Brandon Jennings Feb 12, 2026 04:06 PM	
	400	Performed the operational test of the elevator servo ref. CL-650 AMM 22-11-13-710-801. Operational test is good.	B0641903 - Felipe Mendoza Cervantes Mar 05, 2026 02:26 AM	
	Perform the operational test of the elevator servo ref. CL-650 AMM 22-11-13-710-801.		B0161691 - Thomas Mitchell Mar 05, 2026 03:51 AM	
	500	Removed all tools, equipment, and unwanted materials from the work area.	B0650736 - Jesus Gonzalez Atondo Feb 12, 2026 04:03 PM	
	Remove all tools, equipment, and unwanted materials from the work area.		B1013522 - Brandon Jennings Feb 12, 2026 04:06 PM	

Sequence #	0008-1	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503705	Aircraft Reg #	XA-SOL	Parent WO #	2503653

REMOVE AND RE-INSTALL DETAILS

	Removed Part # Removed Serial #	Removed By	Removed - Part Description	Reference	Installed Part # Installed Serial #	Installed By
	Removed Status	**Removed Date-Time**	**Position**	**Installed Part Status**	**Installed Part Description**	**Installed Date-Time**
	622-5027-101 102497	B0650736 - Jesus Gonzalez Atondo	ACTUATOR, SERVO ELEVATOR	Lubrication	622-5027-101 102497	B0650736 - Jesus Gonzalez Atondo
	SERVICEABLE	Feb 12, 2026 7:19 AM	UPPER	SERVICEABLE	ACTUATOR, SERVO ELEVATOR	Feb 12, 2026 8:49 AM

TOOL INFORMATION

Tool ID	Tool Description	Calibration Due Date
TUSS2036	torque wrench	May 30, 2026 5:00 PM
TUSS0607	bond checker	Jan 30, 2027 5:00 PM

Sequence #	0008-2	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	2503707	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2503653

0008-2	**WO #**	**2503707**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		Detailed Inspection of the Fire-Extinguishing- System Lines	
Detailed Inspection of the Fire-Extinguishing- System Lines				
Task / IRN # : 26-21-16-201				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 26-21-16-201, Perform Detailed Inspection of the Fire-Extinguishing- System Lines. REF CL650 AMM 26-20-00-220-802. No defects noted.	B1016542 - Carlos Ochoa Feb 12, 2026 03:46 AM	26-20
	Perform Detailed Inspection of the Fire-Extinguishing- System Lines		B0623124 - Michael Stacy Feb 12, 2026 04:48 AM	
	200	Removed all tools, equipment, and unwanted materials.	B1016542 - Carlos Ochoa Feb 12, 2026 03:46 AM	
	Remove all tools, equipment, and unwanted materials.		B0623124 - Michael Stacy Feb 12, 2026 04:48 AM	

Sequence #	0008-3	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503709	Aircraft Reg #	XA-SOL	Parent WO #	2503653

0008-3	WO #	2503709	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Rudder and Elevator Control Cables in the Fuselage/Stabilizer Section	
Detailed Inspection of the Rudder and Elevator Control Cables in the Fuselage/Stabilizer Section				
Task / IRN # : 27-00-00-208				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 27-00-00-208, Detailed Inspection of the Rudder and Elevator Control Cables in the Fuselage/Stabilizer Section, in accordance with CL650 AMM 27-00-00-220-808. No defects noted.	B0641903 - Felipe Mendoza Cervantes Feb 16, 2026 10:15 PM	27-00
	Detailed Inspection of the Rudder and Elevator Control Cables in the Fuselage/Stabilizer Section		B0623124 - Michael Stacy Feb 16, 2026 10:28 PM	
	200	Removed all tools equipment and unwanted materials from the work area.	B0641903 - Felipe Mendoza Cervantes Feb 16, 2026 10:15 PM	
	Remove all tools equipment and unwanted materials from the work area.		B0623124 - Michael Stacy Feb 16, 2026 10:28 PM	

Bombardier

Sequence #	0008-4	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503712	Aircraft Reg #	XA-SOL	Parent WO #	2503653

0008-4	WO #	2503712	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Aileron Control Cables in the Control Column	
Detailed Inspection of the Aileron Control Cables in the Control Column				
Task / IRN # : 27-00-00-212				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 27-00-00-212 Detailed Inspection of the Aileron Control Cables in the Control Column ref. CL-650 AMM 27-11-00-220-814. No defects noted.	B0650736 - Jesus Gonzalez Atondo Feb 11, 2026 08:14 PM	27-10
	Perform Detailed Inspection of the Aileron Control Cables in the Control Column		B1013522 - Brandon Jennings Feb 11, 2026 08:51 PM	
	200	Removed all tools, equipment, and unwanted materials from the work area.	B0650736 - Jesus Gonzalez Atondo Feb 11, 2026 08:14 PM	
	Remove all tools, equipment, and unwanted materials from the work area.		B1013522 - Brandon Jennings Feb 11, 2026 08:51 PM	

Sequence #	0008-5	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	2503714	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2503653

0008-5	**WO #**	**2503714**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		Detailed Inspection of the Horizontal-Stabilizer Trim-Actuator Assembly	
Detailed Inspection of the Horizontal-Stabilizer Trim-Actuator Assembly				
Task / IRN # : 27-40-00-202				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with Task 27-40-00-202. Performed Detailed Inspection of the Horizontal-Stabilizer Trim-Actuator Assembly, in reference to CL-650 AMM 27-42-01-220-801. No defects were noted at this time.	B0638589 - Sean Dodder Feb 10, 2026 10:12 PM	27-40
	Perform Detailed Inspection of the Horizontal-Stabilizer Trim-Actuator Assembly		B0623124 - Michael Stacy Feb 10, 2026 11:38 PM	
	200	Removed all tools, equipment, and unwanted materials from the work area.	B0638589 - Sean Dodder Feb 10, 2026 10:12 PM	
	Remove all tools, equipment, and unwanted materials from the work area.		B0623124 - Michael Stacy Feb 10, 2026 11:38 PM	

Sequence #	0008-6	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503715	Aircraft Reg #	XA-SOL	Parent WO #	2503653

0008-6	WO #	2503715	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Lubrication of the Horizontal Stabilizer Pitch-Trim-Actuator	
Lubrication of the Horizontal Stabilizer Pitch-Trim-Actuator				
Task / IRN # : 27-40-00-204				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 27-40-00-204 Lubrication of the Horizontal Stabilizer Pitch-Trim-Actuator IAW CL-650 AMM 12-20-04-640-817.	B0650736 - Jesus Gonzalez Atondo Feb 13, 2026 01:59 PM	12-20
	Perform Lubrication of the Horizontal Stabilizer Pitch-Trim-Actuator		B0142244 - Todd Bridges Feb 13, 2026 02:10 PM	
	200	Performed Ch.5 task 27-41-00-101. Operational test (BITE) of the horizontal stabilizer trim control system ref. CL-650 AMM 27-41-00-740-801. Operational check is good.	B0641903 - Felipe Mendoza Cervantes Mar 05, 2026 02:31 AM	
	Perform the ops test (BITE) of the horizontal stabilizer trim control system ref. CL-650 AMM 27-41-00-740-801.		B0161691 - Thomas Mitchell Mar 05, 2026 04:15 AM	
	300	Removed all tools, equipment, and unwanted materials from the work area.	B0650736 - Jesus Gonzalez Atondo Feb 13, 2026 01:59 PM	
	Remove all tools, equipment, and unwanted materials from the work area.		B0142244 - Todd Bridges Feb 13, 2026 02:10 PM	
	400	Removed all tools equipment and unwanted materials from the work area.	B0641903 - Felipe Mendoza Cervantes Mar 05, 2026 04:10 AM	
	Remove all tools equipment and unwanted materials from the work area.		B0161691 - Thomas Mitchell Mar 05, 2026 04:15 AM	

Sequence #	0008-7	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503718	Aircraft Reg #	XA-SOL	Parent WO #	2503653

0008-7	WO #	2503718	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Landing-Gear Emergency-Extension Cable in the Forward Avionics Compartment	
Detailed Inspection of the Landing-Gear Emergency-Extension Cable in the Forward Avionics Compartment				
Task / IRN # : 32-00-01-209				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Performed Detailed Inspection of the Landing-Gear Emergency-Extension Cable in the Forward Avionics Compartment in accordance with CL-650 AMM 32-34-28-220-803. No defects noted.	B1020176 - Matthew Doyle Feb 17, 2026 01:54 PM	32-30
	Perform Detailed Inspection of the Landing-Gear Emergency-Extension Cable in the Forward Avionics Compartment		B1013522 - Brandon Jennings Feb 17, 2026 02:03 PM	
	101	Complied with task number 32-00-01-209, Performed Detailed Inspection of the Landing-Gear Emergency-Extension Cable in the Forward Avionics Compartment in accordance with CL-650 AMM 32-34-28-220-803. No defects noted.	B1020176 - Matthew Doyle Feb 17, 2026 02:07 PM	
	Perform Detailed Inspection of the Landing-Gear Emergency-Extension Cable in the Forward Avionics Compartment		B1013522 - Brandon Jennings Feb 17, 2026 02:11 PM	09
	200	Removed all tools, equipment and unwanted materials from the work area	B1020176 - Matthew Doyle Feb 17, 2026 01:54 PM	
	Remove all tools, equipment and unwanted materials from the work area		B1013522 - Brandon Jennings Feb 17, 2026 02:03 PM	

Sequence #	0008-8	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503720	Aircraft Reg #	XA-SOL	Parent WO #	2503653

0008-8	WO #	2503720	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Landing-Gear Emergency-Extension Cable in the Main Avionics Compartment	
Detailed Inspection of the Landing-Gear Emergency-Extension Cable in the Main Avionics Compartment				
Task / IRN # : 32-00-01-210				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Performed Detailed Inspection of the Landing-Gear Emergency-Extension Cable in the Main Avionics Compartment in accordance with CL-650 AMM 32-34-28-220-804. No defects noted.	B1020176 - Matthew Doyle Feb 17, 2026 01:52 PM	32-30
	Perform Detailed Inspection of the Landing-Gear Emergency-Extension Cable in the Main Avionics Compartment		B1013522 - Brandon Jennings Feb 17, 2026 02:01 PM	
	101	Complied with task 32-00-01-210, Performed Detailed Inspection of the Landing-Gear Emergency-Extension Cable in the Main Avionics Compartment in accordance with CL-650 AMM 32-34-28-220-804. No defects noted.	B1020176 - Matthew Doyle Feb 17, 2026 02:09 PM	
	Perform Detailed Inspection of the Landing-Gear Emergency-Extension Cable in the Main Avionics Compartment		B1013522 - Brandon Jennings Feb 17, 2026 02:12 PM	09
	200	Removed all tools, equipment and unwanted materials from the work area.	B1020176 - Matthew Doyle Feb 17, 2026 01:52 PM	
	Remove all tools, equipment and unwanted materials from the work area.		B1013522 - Brandon Jennings Feb 17, 2026 02:01 PM	

Sequence #	0008-9	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503722	Aircraft Reg #	XA-SOL	Parent WO #	2503653

0008-9	WO #	2503722	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Nose-Landing-Gear Door - LH	
General Visual Inspection of the Nose-Landing-Gear Door - LH				
Task / IRN # : 32-ZL-00-204				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	C/W Task 32-ZL-00-204, Performed General Visual Inspection of the Nose-Landing-Gear Door - LH IAW CL650 AMM 32-22-00-210-801. No Defects Noted.	B0642374 - Joren Ayer Feb 04, 2026 05:45 PM	32-20
	Perform General Visual Inspection of the Nose-Landing-Gear Door - LH		B0143196 - Robert Bohner Feb 04, 2026 07:22 PM	
	200	Removed all tools, equipment, and unwanted materials from the work area.	B0642374 - Joren Ayer Feb 04, 2026 05:45 PM	
	Remove all tools, equipment, and unwanted materials from the work area.		B0143196 - Robert Bohner Feb 04, 2026 07:22 PM	

Sequence #	0008-10	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503724	Aircraft Reg #	XA-SOL	Parent WO #	2503653

0008-10	WO #	2503724	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Nose Landing Gear Door - RH	
General Visual Inspection of the Nose Landing Gear Door - RH				
Task / IRN # : 32-ZL-00-205				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	C/W Task 32-ZL-00-205, Performed General Visual Inspection of the Nose-Landing-Gear Door - RH IAW CL650 AMM 32-ZL-00-205. No Defects Noted	B0642374 - Joren Ayer Feb 04, 2026 05:47 PM	32-20
	Perform General Visual Inspection of the Nose-Landing-Gear Door - RH		B1013522 - Brandon Jennings Feb 04, 2026 07:00 PM	
	101	Complied with TLMC 32-ZL-00-205. Performed a General Visual Inspection of the Nose-Landing-Gear Door - RH Ref. CL-650 AMM 32-22-00-210-801. No Defects Noted	B0613291 - Eric Strong Feb 05, 2026 07:21 PM	
	Perform General Visual Inspection of the Nose-Landing-Gear Door - RH		B1013522 - Brandon Jennings Feb 05, 2026 07:33 PM	09
	200	Removed all tools, equipment, and unwanted materials from the work area.	B0642374 - Joren Ayer Feb 04, 2026 05:47 PM	
	Remove all tools, equipment, and unwanted materials from the work area.		B1013522 - Brandon Jennings Feb 04, 2026 07:00 PM	

Bombardier

Sequence #	0008-11	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503726	Aircraft Reg #	XA-SOL	Parent WO #	2503653

0008-11	WO #	2503726	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Main-Landing-Gear Door - LH	
General Visual Inspection of the Main-Landing-Gear Door - LH				
Task / IRN # : 32-ZL-00-207				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	C/W Task 32-ZL-00-207 Performed General Visual Inspection of the Main-Landing-Gear Door - LH IAW CL650 AMM 32-12-00-210-801. See findings for defects	B0642374 - Joren Ayer Feb 04, 2026 01:53 PM	32-10
	Perform General Visual Inspection of the Main-Landing-Gear Door - LH		B1013522 - Brandon Jennings Feb 04, 2026 04:04 PM	
	200	Removed all tools, equipment, and unwanted materials from the work area.	B0642374 - Joren Ayer Feb 04, 2026 01:53 PM	
	Remove all tools, equipment, and unwanted materials from the work area.		B1013522 - Brandon Jennings Feb 04, 2026 04:04 PM	

FINDINGS DETAILS

Finding #	Long Description	Status	Reported By / Date	Defect Source / Disposition	Defect Type	Priority	Follow-up WO #
78816	Found Gouges on INBD Side of LH/RH MLG Doors (Flagged)	CLOSED	B0642374 - Joren Ayer Feb 4, 2026 6:41 AM	MAINTENANCE 300-QA002	OTHER	3	4715648-PSAP
78818	Found Frayed RH MLG Door Bonding jumper	CLOSED	B0642374 - Joren Ayer Feb 4, 2026 6:47 AM	MAINTENANCE 300-QA002	OTHER	3	4715626-PSAP

Sequence #	0008-12	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	2503728	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2503653

0008-12	**WO #**	**2503728**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		General Visual Inspection of the Main-Landing-Gear Door - RH	
General Visual Inspection of the Main-Landing-Gear Door - RH				
Task / IRN # : 32-ZL-00-208				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	C/W Task 32-ZL-00-208 Performed General Visual Inspection of the Main-Landing-Gear Door - RH IAW CL650 AMM 32-12-00-210-801. Ref WO 2503726 78816 for Defects	B0642374 - Joren Ayer Feb 04, 2026 02:00 PM	32-10
	Perform General Visual Inspection of the Main-Landing-Gear Door - RH		B1013522 - Brandon Jennings Feb 04, 2026 04:09 PM	
	200	Removed all tools, equipment, and unwanted materials from the work area.	B0642374 - Joren Ayer Feb 04, 2026 02:00 PM	
	Remove all tools, equipment, and unwanted materials from the work area.		B1013522 - Brandon Jennings Feb 04, 2026 04:09 PM	

Sequence #	0008-13	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	2503730	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2503653

0008-13	**WO #**	**2503730**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		Functional Test of the Integrated Standby Instrument	
Functional Test of the Integrated Standby Instrument				
Task / IRN # : 34-12-00-203				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			34-10
	Perform Functional Test of the Integrated Standby Instrument			

Bombardier

Sequence #	0008-14	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503732	Aircraft Reg #	XA-SOL	Parent WO #	2503653

0008-14	WO #	2503732	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Fittings and Attachments of the Passenger Door	
Detailed Inspection of the Fittings and Attachments of the Passenger Door				
Task / IRN # : 52-11-00-202				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with TLMC task 52-11-00-202 Performed detailed inspection of the fittings and attachments of the passenger door REF CL-650 AMM 52-11-01-220-802. No defects noted.	B1002512 - Brandon Warne Feb 13, 2026 07:15 PM	52-10
	Perform Detailed Inspection of the Fittings and Attachments of the Passenger Door		B1019908 - Joseph Barnes Feb 13, 2026 07:38 PM	
	200	Removed all tools, equipment and materials from the work area.	B1002512 - Brandon Warne Feb 13, 2026 07:15 PM	
	Remove all tools, equipment and materials from the work area.		B1019908 - Joseph Barnes Feb 13, 2026 07:38 PM	

Sequence #	0008-15	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	2503734	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2503653

0008-15	**WO #**	**2503734**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		General Visual Inspection of the Passenger Door - External	
General Visual Inspection of the Passenger Door - External				
Task / IRN # : 52-ZL-00-206				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with TLMC task 52-ZL-00-206 Performed general visual inspection of the passenger door (External) REF CL-650 AMM 52-11-01-210-802. No defects noted.	B1002512 - Brandon Warne Feb 04, 2026 08:31 PM	52-10
	Perform General Visual Inspection of the Passenger Door - External		B1013522 - Brandon Jennings Feb 04, 2026 08:43 PM	
	200	Removed all tools, equipment and materials from the work area.	B1002512 - Brandon Warne Feb 04, 2026 08:31 PM	
	Remove all tools, equipment and materials from the work area.		B1013522 - Brandon Jennings Feb 04, 2026 08:43 PM	

Sequence #	0008-16	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503736	Aircraft Reg #	XA-SOL	Parent WO #	2503653

0008-16	WO #	2503736	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Passenger Door - Internal	
General Visual Inspection of the Passenger Door - Internal				
Task / IRN # : 52-ZL-00-207				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Performed General Visual Inspection of the Passenger door - Internal IAW CL-650 AMM 52-11-01-210-803. COMPLIED with task 52-ZL-00-207. No Discrepancies Noted.	B1018546 - Andres Velazquez Feb 08, 2026 11:53 PM	52-10
	Perform General Visual Inspection of the Passenger Door - Internal		B0142244 - Todd Bridges Feb 09, 2026 12:28 AM	
	200	Remove all tools, equipment , and unwanted materials from work area. IAW CL-650 AMM 52-11-01-210-803	B1018546 - Andres Velazquez Feb 08, 2026 11:53 PM	
	Remove all tools, equipment , and unwanted materials from work area.		B0142244 - Todd Bridges Feb 09, 2026 12:28 AM	

Sequence #	0008-17	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	2503738	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2503653

0008-17	**WO #**	**2503738**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		General Visual Inspection of the Overwing Emergency Exit Door - Internal	
General Visual Inspection of the Overwing Emergency Exit Door - Internal				
Task / IRN # : 52-ZL-00-209				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 52-ZL-00-209 General Visual Inspection of the Overwing Emergency-Exit Door - Internal REF CL650 AMM 52-21-01-210-803. No defects noted at this time	B0648431 - Caleb Sexton Feb 16, 2026 07:59 PM	52-20
	Perform General Visual Inspection of the Overwing Emergency-Exit Door - Internal		B1019908 - Joseph Barnes Feb 16, 2026 08:30 PM	
	200	Removed all tools, equipment and unwanted materials from the work area	B0648431 - Caleb Sexton Feb 16, 2026 07:59 PM	
	Remove all tools, equipment and unwanted materials from the work area		B1019908 - Joseph Barnes Feb 16, 2026 08:30 PM	

Bombardier

Sequence #	0008-18	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503740	Aircraft Reg #	XA-SOL	Parent WO #	2503653

0008-18	WO #	2503740	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Cargo Compartment Door - External	
General Visual Inspection of the Cargo Compartment Door - External				
Task / IRN # : 52-ZL-00-210				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	C/W Task 52-ZL-00-210 Performed General Visual Inspection of the Cargo Compartment Door - External IAW CL650 AMM 52-31-01-210-801 See Findings For Defects	B0642374 - Joren Ayer Feb 04, 2026 02:35 PM	52-30
	Perform General Visual Inspection of the Cargo Compartment Door - External		B0143196 - Robert Bohner Feb 04, 2026 04:57 PM	
	200	Removed all tools, equipment, and unwanted materials from the work area.	B0642374 - Joren Ayer Feb 04, 2026 02:36 PM	
	Remove all tools, equipment, and unwanted materials from the work area.		B0143196 - Robert Bohner Feb 04, 2026 04:57 PM	

FINDINGS DETAILS

Finding #	Long Description	Status	Reported By / Date	Defect Source / Disposition	Defect Type	Priority	Follow-up WO #
78825	Missing Decorative cover on Upper FWD baggage door stop bracket	CLOSED	B0642374 - Joren Ayer Feb 4, 2026 7:31 AM	MAINTENANCE 300-QA002	OTHER	3	4715587-APPR

Sequence #	0008-19	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	2503742	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2503653

0008-19	**WO #**	**2503742**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		General Visual Inspection of the Cargo Compartment Door - Internal	
General Visual Inspection of the Cargo Compartment Door - Internal				
Task / IRN # : 52-ZL-00-211				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with TLMC task 52-ZL-00-211 Performed general visual inspection of the cargo compartment door (Internal) REF CL-650 AMM 52-31-01-210-802. No defects noted.	B1002512 - Brandon Warne Feb 10, 2026 07:11 PM	52-30
	Perform General Visual Inspection of the Cargo Compartment Door - Internal		B1013522 - Brandon Jennings Feb 10, 2026 07:22 PM	
	200	Removed all tools, equipment and materials from the work area.	B1002512 - Brandon Warne Feb 10, 2026 07:11 PM	
	Remove all tools, equipment and materials from the work area.		B1013522 - Brandon Jennings Feb 10, 2026 07:22 PM	

Sequence #	0008-20	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503743	Aircraft Reg #	XA-SOL	Parent WO #	2503653

0008-20	WO #	2503743	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the NLG Wheel Well Structure	
Detailed Inspection of the NLG Wheel Well Structure				
Task / IRN # : 53-10-00-212				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with TLMC 53-10-00-212. Performed a Detailed Inspection of the NLG Wheel Well Structure Ref. CL-650 AMM 53-10-01-220-811. No defects noted.	B0613291 - Eric Strong Feb 05, 2026 08:27 PM	53-10
	Perform Detailed Inspection of the NLG Wheel Well Structure		B0143196 - Robert Bohner Feb 05, 2026 08:31 PM	
	200	Removed all tools, equipment, and unwanted materials from the work area.	B0613291 - Eric Strong Feb 05, 2026 08:27 PM	
	Remove all tools, equipment, and unwanted materials from the work area.		B0143196 - Robert Bohner Feb 05, 2026 08:31 PM	

Bombardier

Sequence #	0008-21	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503746	Aircraft Reg #	XA-SOL	Parent WO #	2503653

0008-21	WO #	2503746	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the NLG Internal Box Structure - FS169 to FS235	
Detailed Inspection of the NLG Internal Box Structure - FS169 to FS235				
Task / IRN # : 53-10-00-213				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 53-10-00-213, Perform Detailed Inspection of the NLG Internal Box Structure - FS169 to FS235, in accordance with CL650 AMM 53-10-01-220-812. No defects noted.	B1019545 - Tharathorn Locham Feb 12, 2026 05:46 PM	53-10
	Perform Detailed Inspection of the NLG Internal Box Structure - FS169 to FS235		B1013522 - Brandon Jennings Feb 12, 2026 06:54 PM	
	200	Removed all tools, equipment, and unwanted materials from the work area	B1019545 - Tharathorn Locham Feb 12, 2026 05:46 PM	
	Remove all tools, equipment, and unwanted materials from the work area		B1013522 - Brandon Jennings Feb 12, 2026 06:54 PM	

Sequence #	0008-22	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503748	Aircraft Reg #	XA-SOL	Parent WO #	2503653

0008-22	WO #	2503748	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Fittings and the Hinge on the Fuselage for the Passenger Door	
Detailed Inspection of the Fittings and the Hinge on the Fuselage for the Passenger Door				
Task / IRN # : 53-20-00-202				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with TLMC 53-20-00-202. Performed the Detailed Inspection of the Fittings and the Hinge on the Fuselage for the Passenger Door Ref. CL-650 AMM 53-20-01-220-802. No defects noted.	B0613291 - Eric Strong Feb 14, 2026 08:13 PM	53-20
	Perform Detailed Inspection of the Fittings and the Hinge on the Fuselage for the Passenger Door		B0142244 - Todd Bridges Feb 14, 2026 08:51 PM	
	200	Removed all tools, equipment, and unwanted materials from the work area.	B0613291 - Eric Strong Feb 14, 2026 08:13 PM	
	Remove all tools, equipment, and unwanted materials from the work area.		B0142244 - Todd Bridges Feb 14, 2026 08:51 PM	

Sequence #	0008-23	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	2503749	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2503653

0008-23	**WO #**	**2503749**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		Detailed Inspection of the Aft Keel Beam - FS513 to FS559	
Detailed Inspection of the Aft Keel Beam - FS513 to FS559				
Task / IRN # : 53-20-00-212				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with TLMC task 53-20-00-212 Performed Detailed inspection of the Aft Keel Beam (FS513 to FS559 REF CL-650 AMM 53-20-01-220-810. No defects noted.	B1002512 - Brandon Warne Feb 16, 2026 05:51 PM	53-20
	Perform Detailed Inspection of the Aft Keel Beam - FS513 to FS559		B1019908 - Joseph Barnes Feb 16, 2026 07:02 PM	
	200	Removed all tools, equipment and materials from the work area.	B1002512 - Brandon Warne Feb 16, 2026 05:51 PM	
	Remove all tools, equipment and materials from the work area.		B1019908 - Joseph Barnes Feb 16, 2026 07:02 PM	

Bombardier

Sequence #	0008-24	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503752	Aircraft Reg #	XA-SOL	Parent WO #	2503653

0008-24	WO #	2503752	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Profile Plates of the Floor Support Structure - FS621	
Detailed Inspection of the Profile Plates of the Floor Support Structure - FS621				
Task / IRN # : 53-30-00-207				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with TLMC task 53-30-00-207 Performed detailed inspection of the profile plates of the floor structure (FS621) REF CL-650 AMM 53-30-01-220-821. No defects noted	B1002512 - Brandon Warne Feb 13, 2026 08:03 PM	53-30
	Perform Detailed Inspection of the Profile Plates of the Floor Support Structure - FS621		Not Required	
	101	Complied with TLMC task 53-30-00-207 Performed detailed inspection of the profile plates of the floor structure (FS621) REF CL-650 AMM 53-30-01-220-821. No defects noted	B1002512 - Brandon Warne Feb 16, 2026 01:57 PM	
	Perform Detailed Inspection of the Profile Plates of the Floor Support Structure - FS621		Not Required	09
	102	Complied with TLMC task 53-30-00-207 Performed detailed inspection of the profile plates of the floor structure (FS621) REF CL-650 AMM 53-30-01-220-821. No defects noted	B1002512 - Brandon Warne Feb 16, 2026 02:02 PM	
	Perform Detailed Inspection of the Profile Plates of the Floor Support Structure - FS621		B1019908 - Joseph Barnes Feb 16, 2026 02:14 PM	09
	200	Removed all tools, equipment and materials from the work area.	B1002512 - Brandon Warne Feb 13, 2026 08:03 PM	
	Remove all tools, equipment and materials from the work area.		B1019908 - Joseph Barnes Feb 16, 2026 02:14 PM	

Bombardier

Sequence #	0008-25	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503754	Aircraft Reg #	XA-SOL	Parent WO #	2503653

0008-25	WO #	2503754	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Internal Skin and Fuselage Structure - FS621 to FS755	
Detailed Inspection of the Internal Skin and Fuselage Structure - FS621 to FS755				
Task / IRN # : 53-30-00-215				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 53-30-00-215 Detailed Inspection of the Internal Skin and Fuselage Structure - FS621 to FS755 REF CL650 AMM 53-30-01-220-814. No defects noted at this time.	B0648431 - Caleb Sexton Feb 10, 2026 08:43 PM	53-30
	Perform Detailed Inspection of the Internal Skin and Fuselage Structure - FS621 to FS755		B1013522 - Brandon Jennings Feb 10, 2026 08:54 PM	
	200	Removed all tools, equipment, and unwanted materials from the work area	B0648431 - Caleb Sexton Feb 10, 2026 08:43 PM	
	Remove all tools, equipment, and unwanted materials from the work area		B1013522 - Brandon Jennings Feb 10, 2026 08:54 PM	

Bombardier

Sequence #	0008-26	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503755	Aircraft Reg #	XA-SOL	Parent WO #	2503653

0008-26	WO #	2503755	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the External Skin around the APU Exhaust Cutout	
Detailed Inspection of the External Skin around the APU Exhaust Cutout				
Task / IRN # : 53-30-00-217				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Performed Detailed Inspection of the External Skin around the APU Exhaust cutout IAW CL-605 AMM 53-30-01-220-817 . Complied with task 53-30-00-217 . NO DISCREPANCIES FOUND .	B1018546 - Andres Velazquez Feb 08, 2026 05:00 PM	53-30
	Perform Detailed Inspection of the External Skin around the APU Exhaust Cutout		B0142244 - Todd Bridges Feb 08, 2026 05:19 PM	
	101	Performed Detailed Inspection of the External Skin around the APU Exhaust cutout IAW CL-650 AMM 53-30-01-220-817 . Complied with task 53-30-00-217 . NO DISCREPANCIES FOUND .	B1018546 - Andres Velazquez Feb 08, 2026 05:21 PM	
	Perform Detailed Inspection of the External Skin around the APU Exhaust Cutout		B0142244 - Todd Bridges Feb 08, 2026 05:23 PM	09
	200	Remove all tools , equipment, and unwanted materials form the work area. IAW CL-650 AMM 53-30-01-220-817	B1018546 - Andres Velazquez Feb 08, 2026 05:00 PM	
	Remove all tools , equipment, and unwanted materials form the work area.		B0142244 - Todd Bridges Feb 08, 2026 05:19 PM	

Sequence #	0008-27	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503758	Aircraft Reg #	XA-SOL	Parent WO #	2503653

0008-27	WO #	2503758	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Nose Radome - External	
General Visual Inspection of the Nose Radome - External				
Task / IRN # : 53-ZL-00-201				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	complied with task 53-ZL-00-201. Performed a General Visual Inspection of the Nose Radome - External IAW CL 605 AMM 53-10-01-210-801. no defects noted.	B0642326 - Austin McQuilkin Feb 04, 2026 02:29 PM	53-10
	Perform General Visual Inspection of the Nose Radome - External		B1013522 - Brandon Jennings Feb 04, 2026 02:41 PM	
	101	complied with task 53-ZL-00-201. Performed a General Visual Inspection of the Nose Radome - External IAW CL 650 AMM 53-10-01-210-801. no defects noted.	B0642326 - Austin McQuilkin Feb 04, 2026 08:08 PM	
	Perform General Visual Inspection of the Nose Radome - External		B1013522 - Brandon Jennings Feb 04, 2026 08:16 PM	09
	200	Removed all tools, equipment, and unwanted materials from the work area.	B0642326 - Austin McQuilkin Feb 04, 2026 02:29 PM	
	Remove all tools, equipment, and unwanted materials from the work area.		B1013522 - Brandon Jennings Feb 04, 2026 02:41 PM	

Bombardier

Sequence #	0008-28	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503760	Aircraft Reg #	XA-SOL	Parent WO #	2503653

0008-28	WO #	2503760	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Nose Radome - Internal	
General Visual Inspection of the Nose Radome - Internal				
Task / IRN # : 53-ZL-00-202				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with Task 53-ZL-00-202. Performed General Visual Inspection of the Nose Radome - Internal, in reference to CL-650 AMM 53-10-01-210-802. See finding 79097 for details.	B0638589 - Sean Dodder Feb 06, 2026 04:32 AM	53-10
	Perform General Visual Inspection of the Nose Radome - Internal		B0623124 - Michael Stacy Feb 06, 2026 04:43 AM	
	200	Removed all tools, equipment, and unwanted materials from the work area.	B0638589 - Sean Dodder Feb 06, 2026 04:32 AM	
	Remove all tools, equipment, and unwanted materials from the work area.		B0623124 - Michael Stacy Feb 06, 2026 04:43 AM	

FINDINGS DETAILS

Finding #	Long Description	Status	Reported By / Date	Defect Source / Disposition	Defect Type	Priority	Follow-up WO #
79097	Circumference erosion tape lifting and cracking at the 12 o clock position on the forward side of FS 169, under the Nose Radome. Photo included. Location has streamer.	CLOSED	B0638589 - Sean Dodder Feb 5, 2026 9:26 PM	MAINTENANCE 300-QA002	OTHER	3	4775764-APPR

Sequence #	0008-29	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503761	Aircraft Reg #	XA-SOL	Parent WO #	2503653

0008-29	WO #	2503761	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Nose Compartment - Lower Internal RH	
General Visual Inspection of the Nose Compartment - Lower Internal RH				
Task / IRN # : 53-ZL-00-205				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 53-ZL-00-205, Perform General Visual Inspection of the Nose Compartment - Lower Internal RH. REF CL650 AMM 53-10-01-210-805. No defects noted.	B1016542 - Carlos Ochoa Feb 12, 2026 10:22 PM	53-10
	Perform General Visual Inspection of the Nose Compartment - Lower Internal RH		B0623124 - Michael Stacy Feb 12, 2026 11:31 PM	
	200	See W/O: 3154422 operation 600 for retraction of the ADG.	B1016542 - Carlos Ochoa Feb 12, 2026 10:22 PM	
	Perform retraction of the dry ADG. REF CL650 AMM 24-23-01-840-806.		B0623124 - Michael Stacy Feb 12, 2026 11:31 PM	
	300	Removed all tools, equipment, and unwanted materials.	B1016542 - Carlos Ochoa Feb 12, 2026 10:22 PM	
	Remove all tools, equipment, and unwanted materials.		B0623124 - Michael Stacy Feb 12, 2026 11:31 PM	

Sequence #	0008-30	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	2503764	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2503653

0008-30	**WO #**	**2503764**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		General Visual Inspection of the NLG Wheel Well	
General Visual Inspection of the NLG Wheel Well				
Task / IRN # : 53-ZL-00-206				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	C/W Task 53-ZL-00-206, Performed General Visual Inspection of the NLG Wheel Well IAW CL650 AMM 53-10-01-210-806. No Defects Noted.	B0642374 - Joren Ayer Feb 04, 2026 05:56 PM	53-10
	Perform General Visual Inspection of the NLG Wheel Well		B1013522 - Brandon Jennings Feb 04, 2026 07:04 PM	
	200	Removed all tools, equipment, and unwanted materials from the work area.	B0642374 - Joren Ayer Feb 04, 2026 05:56 PM	
	Remove all tools, equipment, and unwanted materials from the work area.		B1013522 - Brandon Jennings Feb 04, 2026 07:04 PM	

Sequence #	0008-31	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503766	Aircraft Reg #	XA-SOL	Parent WO #	2503653

0008-31	WO #	2503766	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Forward Avionics and Flight Controls Compartment - Internal LH	
General Visual Inspection of the Forward Avionics and Flight Controls Compartment - Internal LH				
Task / IRN # : 53-ZL-00-208				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with Task 53-ZL-00-208. Performed General Visual Inspection of the Forward Avionics and Flight Controls Compartment - Internal, in reference to CL-650 AMM 53-10-01-210-808. No defects were noted at this time.	B0638589 - Sean Dodder Feb 12, 2026 11:44 PM	53-10
	Perform General Visual Inspection of the Forward Avionics and Flight Controls Compartment - Internal		B0623124 - Michael Stacy Feb 12, 2026 11:47 PM	
	200	Removed all tools, equipment, and unwanted materials from the work area.	B0638589 - Sean Dodder Feb 12, 2026 11:44 PM	
	Remove all tools, equipment, and unwanted materials from the work area.		B0623124 - Michael Stacy Feb 12, 2026 11:47 PM	

Sequence #	0008-32	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503768	Aircraft Reg #	XA-SOL	Parent WO #	2503653

0008-32	WO #	2503768	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Forward Avionics and Flight Controls Compartment - Internal RH	
General Visual Inspection of the Forward Avionics and Flight Controls Compartment - Internal RH				
Task / IRN # : 53-ZL-00-209				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with Task 53-ZL-00-209. Performed General Visual Inspection of the Forward Avionics and Flight Controls Compartment - Internal, in reference to CL-650 AMM 53-10-01-210-808. No defects were noted at this time.	B0638589 - Sean Dodder Feb 12, 2026 11:45 PM	53-10
	Perform General Visual Inspection of the Forward Avionics and Flight Controls Compartment - Internal		B0623124 - Michael Stacy Feb 12, 2026 11:48 PM	
	200	Removed all tools, equipment, and unwanted materials from the work area.	B0638589 - Sean Dodder Feb 12, 2026 11:45 PM	
	Remove all tools, equipment, and unwanted materials from the work area.		B0623124 - Michael Stacy Feb 12, 2026 11:48 PM	

Bombardier

Sequence #	0008-33	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503770	Aircraft Reg #	XA-SOL	Parent WO #	2503653

0008-33	WO #	2503770	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Main Avionics Compartment - External	
General Visual Inspection of the Main Avionics Compartment - External				
Task / IRN # : 53-ZL-00-210				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with Task 53-ZL-00-210. Performed General Visual Inspection of the Main Avionics Compartment - External, in reference to CL-650 AMM 53-20-01-210-801. No defects were noted at this time.	B0638589 - Sean Dodder Feb 13, 2026 01:17 AM	53-20
	Perform General Visual Inspection of the Main Avionics Compartment - External		B0623124 - Michael Stacy Feb 13, 2026 01:24 AM	
	200	Removed all tools, equipment, and unwanted materials from the work area.	B0638589 - Sean Dodder Feb 13, 2026 01:17 AM	
	Remove all tools, equipment, and unwanted materials from the work area.		B0623124 - Michael Stacy Feb 13, 2026 01:24 AM	

Sequence #	0008-34	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503772	Aircraft Reg #	XA-SOL	Parent WO #	2503653

0008-34	WO #	2503772	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Main Avionics Compartment - Internal	
General Visual Inspection of the Main Avionics Compartment - Internal				
Task / IRN # : 53-ZL-00-211				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with Task 53-ZL-00-211. Performed General Visual Inspection of the Main Avionics Compartment - Internal, in reference to CL-650 AMM 53-20-01-210-802. No defects were noted at this time.	B0638589 - Sean Dodder Feb 13, 2026 04:24 AM	53-20
	Perform General Visual Inspection of the Main Avionics Compartment - Internal		B0623124 - Michael Stacy Feb 13, 2026 04:26 AM	
	200	Removed all tools, equipment, and unwanted materials from the work area.	B0638589 - Sean Dodder Feb 13, 2026 04:24 AM	
	Remove all tools, equipment, and unwanted materials from the work area.		B0623124 - Michael Stacy Feb 13, 2026 04:26 AM	

Sequence #	0008-35	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	2503774	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2503653

0008-35	**WO #**	**2503774**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		General Visual Inspection of the Mid-Fuselage - Lower External	
General Visual Inspection of the Mid-Fuselage - Lower External				
Task / IRN # : 53-ZL-00-212				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with TLMC task 53-ZL-00-212 Performed general visual inspection of the Mid-Fuselage (lower external) REF CL-650 AMM 53-20-01-210-803. No defects noted.	B1002512 - Brandon Warne Feb 05, 2026 03:35 PM	53-20
	Perform General Visual Inspection of the Mid-Fuselage - Lower External		B1013522 - Brandon Jennings Feb 05, 2026 03:46 PM	
	200	Removed all tools, equipment and materials from the work area.	B1002512 - Brandon Warne Feb 05, 2026 03:35 PM	
	Remove all tools, equipment and materials from the work area.		B1013522 - Brandon Jennings Feb 05, 2026 03:46 PM	

Sequence #	0008-36	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503776	Aircraft Reg #	XA-SOL	Parent WO #	2503653

0008-36	WO #	2503776	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Forward Equipment Compartment - Internal	
General Visual Inspection of the Forward Equipment Compartment - Internal				
Task / IRN # : 53-ZL-00-219				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 53-ZL-00-219, Perform General Visual Inspection of the Forward Equipment Compartment - Internal, Ref 650 MM 53-10-01-210-810. No defects noted at this time.	B0646267 - Nicholas Wilkins Feb 12, 2026 05:34 PM	53-10
	Perform General Visual Inspection of the Forward Equipment Compartment - Internal		B1013522 - Brandon Jennings Feb 12, 2026 06:51 PM	
	200	Removed all tools, equipment and unwanted material from work area.	B0646267 - Nicholas Wilkins Feb 12, 2026 05:34 PM	
	Remove all tools, equipment and unwanted material from work area.		B1013522 - Brandon Jennings Feb 12, 2026 06:51 PM	

Sequence #	0008-37	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503778	Aircraft Reg #	XA-SOL	Parent WO #	2503653

0008-37	WO #	2503778	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Flight Compartment - Internal without removal of the headliner and the glareshield	
General Visual Inspection of the Flight Compartment - Internal without removal of the headliner and the glareshield				
Task / IRN # : 53-ZL-00-221				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 53-ZL-00-221, Perform General Visual Inspection of the Flight Compartment - Internal without Removal of the Headliner and the Glareshield, in accordance with 650 MM 53-10-01-210-812.	B0646267 - Nicholas Wilkins Feb 12, 2026 05:12 PM	53-10
	Perform General Visual Inspection of the Flight Compartment - Internal without Removal of the Headliner and the Glareshield		B1013522 - Brandon Jennings Feb 12, 2026 06:49 PM	
	101	Complied with task 53-ZL-00-221, Perform General Visual Inspection of the Flight Compartment - Internal without Removal of the Headliner and the Glareshield, in accordance with CL650 AMM 53-10-01-210-812. No Defects Noted at this time	B0646267 - Nicholas Wilkins Mar 04, 2026 01:43 PM	
	Perform General Visual Inspection of the Flight Compartment - Internal without Removal of the Headliner and the Glareshield			09
	200	Removed all tools, equipment and unwanted material from work area.	B0646267 - Nicholas Wilkins Feb 12, 2026 05:12 PM	
	Remove all tools, equipment and unwanted material from work area.		B1013522 - Brandon Jennings Feb 12, 2026 06:49 PM	

Bombardier

Sequence #	0008-38	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503780	Aircraft Reg #	XA-SOL	Parent WO #	2503653

0008-38	WO #	2503780	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Aft Equipment Compartment - External	
General Visual Inspection of the Aft Equipment Compartment - External				
Task / IRN # : 53-ZL-00-227				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	C/W Task 53-ZL-00-227, Performed General Visual Inspection of the Aft Equipment Compartment - External IAW CL650 AMM 53-30-01-210-805. No Defects Noted.	B0642374 - Joren Ayer Feb 04, 2026 06:39 PM	53-30
	Perform General Visual Inspection of the Aft Equipment Compartment - External		B1013522 - Brandon Jennings Feb 04, 2026 07:13 PM	
	200	Removed all tools, equipment, and unwanted materials from the work area.	B0642374 - Joren Ayer Feb 04, 2026 06:39 PM	
	Remove all tools, equipment, and unwanted materials from the work area.		B1013522 - Brandon Jennings Feb 04, 2026 07:13 PM	

Sequence #	0008-39	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503781	Aircraft Reg #	XA-SOL	Parent WO #	2503653

0008-39	WO #	2503781	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Fuselage/Stabilizer Section - Internal	
General Visual Inspection of the Fuselage/Stabilizer Section - Internal				
Task / IRN # : 53-ZL-00-230				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	C/W Task 53-ZL-00-230, Performed General Visual Inspection of the Fuselage/Stabilizer Section - Internal IAW CL650 AMM 53-43-01-210-801. No Defects Noted	B0642374 - Joren Ayer Feb 04, 2026 06:52 PM	53-40
	Perform General Visual Inspection of the Fuselage/ Stabilizer Section - Internal		B1013522 - Brandon Jennings Feb 04, 2026 07:15 PM	
	101	Complied with task 53-ZL-00-230, Perform General Visual Inspection of the Fuselage/Stabilizer Section - Internal, in accordance with CL650 AMM 53-43-01-210-802. No defects noted.	B1019545 - Tharathorn Locham Feb 12, 2026 03:20 PM	
	Perform General Visual Inspection of the Fuselage/ Stabilizer Section - Internal		B1013522 - Brandon Jennings Feb 12, 2026 03:48 PM	09
	200	Removed all tools, equipment, and unwanted materials from the work area.	B0642374 - Joren Ayer Feb 04, 2026 06:52 PM	
	Remove all tools, equipment, and unwanted materials from the work area.		B1013522 - Brandon Jennings Feb 04, 2026 07:15 PM	

Sequence #	0008-40	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503784	Aircraft Reg #	XA-SOL	Parent WO #	2503653

0008-40	WO #	2503784	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Tail Cone - External	
General Visual Inspection of the Tail Cone - External				
Task / IRN # : 53-ZL-00-231				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	complied with task 53-ZL-00-231. Performed a General Visual Inspection of the Tail Cone - External IAW CL 350 AMM 53-66-01-210-801. no defects noted.	B0642326 - Austin McQuilkin Feb 04, 2026 06:26 PM	53-60
	Perform General Visual Inspection of the Tail Cone - External		B1013522 - Brandon Jennings Feb 04, 2026 07:05 PM	
	101	complied with task 53-ZL-00-231. Performed a General Visual Inspection of the Tail Cone - External IAW CL 650 AMM 53-66-01-210-801. no defects noted.	B0642326 - Austin McQuilkin Feb 04, 2026 08:10 PM	
	Perform General Visual Inspection of the Tail Cone - External		B1013522 - Brandon Jennings Feb 04, 2026 08:18 PM	09
	200	Removed all tools, equipment, and unwanted materials from the work area.	B0642326 - Austin McQuilkin Feb 04, 2026 06:26 PM	
	Remove all tools, equipment, and unwanted materials from the work area.		B1013522 - Brandon Jennings Feb 04, 2026 07:05 PM	
	300	reference op 101 for correctoin	B0642326 - Austin McQuilkin Feb 04, 2026 08:10 PM	
	Rejection for op 100. A/C is a Challenger 650 not 350 admin correction to corrective action required.		B1013522 - Brandon Jennings Feb 04, 2026 08:18 PM	

Sequence #	0008-41	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503787	Aircraft Reg #	XA-SOL	Parent WO #	2503653

0008-41	WO #	2503787	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Tail Cone - Internal	
General Visual Inspection of the Tail Cone - Internal				
Task / IRN # : 53-ZL-00-232				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with TLMC task 53-ZL-00-232 Performed general visual inspection of the tail cone (Internal) REF BD-650 AMM 53-66-01-210-802. No defects noted.	B1002512 - Brandon Warne Feb 10, 2026 05:09 PM	53-60
	General Visual Inspection of the Tail Cone - Internal		B1013522 - Brandon Jennings Feb 10, 2026 05:14 PM	
	200	Removed all tools, equipment and materials from the work area.	B1002512 - Brandon Warne Feb 10, 2026 05:09 PM	
	Remove all tools equipment and material from the work area.		B1013522 - Brandon Jennings Feb 10, 2026 05:14 PM	

Bombardier

Sequence #	0008-42	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503788	Aircraft Reg #	XA-SOL	Parent WO #	2503653

0008-42	WO #	2503788	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Pylon - External LH	
General Visual Inspection of the Pylon - External LH				
Task / IRN # : 54-ZL-00-201				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	complied with task 54-ZL-00-201. Performed a General Visual Inspection of the L/H Pylon - External IAW CL 350 AMM 54-50-01-210-801. no defects noted	B0642326 - Austin McQuilkin Feb 04, 2026 05:16 PM	54-50
	Perform General Visual Inspection of the Pylon - External LH		B1013522 - Brandon Jennings Feb 04, 2026 05:38 PM	
	200	Removed all tools, equipment, and unwanted materials from the work area.	B0642326 - Austin McQuilkin Feb 04, 2026 05:16 PM	
	Remove all tools, equipment, and unwanted materials from the work area.		B1013522 - Brandon Jennings Feb 04, 2026 05:38 PM	

Bombardier

Sequence #	0008-43	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503791	Aircraft Reg #	XA-SOL	Parent WO #	2503653

0008-43	WO #	2503791	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Pylon - External RH	
General Visual Inspection of the Pylon - External RH				
Task / IRN # : 54-ZL-00-202				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	complied with task 54-ZL-00-202. Performed a General Visual Inspection of the R/H Pylon - External IAW CL 350 AMM 54-50-01-210-801. no defects noted	B0642326 - Austin McQuilkin Feb 04, 2026 05:19 PM	54-50
	Perform General Visual Inspection of the Pylon - External RH		B1013522 - Brandon Jennings Feb 04, 2026 05:37 PM	
	200	Removed all tools, equipment, and unwanted materials from the work area.	B0642326 - Austin McQuilkin Feb 04, 2026 05:19 PM	
	Remove all tools, equipment, and unwanted materials from the work area.		B1013522 - Brandon Jennings Feb 04, 2026 05:37 PM	

Sequence #	0008-44	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	2503793	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2503653

0008-44	**WO #**	**2503793**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		General Visual Inspection of the Pylon Leading Edge - Internal LH	
General Visual Inspection of the Pylon Leading Edge - Internal LH				
Task / IRN # : 54-ZL-00-203				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	complied with task 54-ZL-00-203. Performed a General Visual Inspection of the L/H Pylon Leading Edge - Internal IAW CL 650 AMM 54-61-04-210-801. no defects noted.	B0642326 - Austin McQuilkin Feb 04, 2026 10:39 PM	54-60
	Perform General Visual Inspection of the Pylon Leading Edge - Internal LH		B0161691 - Thomas Mitchell Feb 04, 2026 11:27 PM	
	200	Removed all tools, equipment, and unwanted materials from the work area.	B0642326 - Austin McQuilkin Feb 04, 2026 10:39 PM	
	Remove all tools, equipment, and unwanted materials from the work area.		B0161691 - Thomas Mitchell Feb 04, 2026 11:27 PM	

Bombardier

Sequence #	0008-45	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503794	Aircraft Reg #	XA-SOL	Parent WO #	2503653

0008-45	WO #	2503794	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Pylon Leading Edge - Internal RH	
General Visual Inspection of the Pylon Leading Edge - Internal RH				
Task / IRN # : 54-ZL-00-204				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	complied with task 54-ZL-00-204. Performed a General Visual Inspection of the R/H Pylon Leading Edge - Internal IAW CL 650 AMM 54-61-04-210-801. no defects noted.	B0642326 - Austin McQuilkin Feb 04, 2026 10:41 PM	54-60
	Perform General Visual Inspection of the Pylon Leading Edge - Internal RH		B0161691 - Thomas Mitchell Feb 04, 2026 11:24 PM	
	200	Removed all tools, equipment, and unwanted materials from the work area.	B0642326 - Austin McQuilkin Feb 04, 2026 10:41 PM	
	Remove all tools, equipment, and unwanted materials from the work area.		B0161691 - Thomas Mitchell Feb 04, 2026 11:24 PM	

Bombardier

Sequence #	0008-46	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503797	Aircraft Reg #	XA-SOL	Parent WO #	2503653

0008-46	WO #	2503797	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Pylon Mid-Section - Internal LH	
General Visual Inspection of the Pylon Mid-Section - Internal LH				
Task / IRN # : 54-ZL-00-205				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 54-ZL-00-205, Perform General Visual Inspection of the Pylon Mid-Section - Internal LH, REF: Challenger 650 AMM 54-51-05-210-801. No defects noted.	B0646464 - Jonathan Nelson Feb 05, 2026 04:31 AM	54-50
	Perform General Visual Inspection of the Pylon Mid-Section - Internal LH		B0623124 - Michael Stacy Feb 05, 2026 04:34 AM	
	200	Removed all tools, equipment, and unwanted materials to prevent foreign object damage (FOD) to the aircraft.	B0646464 - Jonathan Nelson Feb 05, 2026 04:31 AM	
	Remove all tools, equipment, and unwanted materials to prevent foreign object damage (FOD) to the aircraft.		B0623124 - Michael Stacy Feb 05, 2026 04:34 AM	

Sequence #	0008-47	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503799	Aircraft Reg #	XA-SOL	Parent WO #	2503653

0008-47	WO #	2503799	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Pylon Mid-Section - Internal RH	
General Visual Inspection of the Pylon Mid-Section - Internal RH				
Task / IRN # : 54-ZL-00-206				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 54-ZL-00-206, Perform General Visual Inspection of the Pylon Mid-Section - Internal RH, REF: Challenger 650 AMM 54-51-05-210-801. No defects noted.	B0646464 - Jonathan Nelson Feb 05, 2026 04:45 AM	54-50
	Perform General Visual Inspection of the Pylon Mid-Section - Internal RH		B0623124 - Michael Stacy Feb 05, 2026 04:49 AM	
	200	Removed all tools, equipment, and unwanted materials to prevent foreign object damage (FOD) to the aircraft.	B0646464 - Jonathan Nelson Feb 05, 2026 04:45 AM	
	Remove all tools, equipment, and unwanted materials to prevent foreign object damage (FOD) to the aircraft.		B0623124 - Michael Stacy Feb 05, 2026 04:49 AM	

Sequence #	0008-48	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503800	Aircraft Reg #	XA-SOL	Parent WO #	2503653

0008-48	WO #	2503800	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Inner Pivot Pin of the Horizontal Stabilizer	
Detailed Inspection of the Inner Pivot Pin of the Horizontal Stabilizer				
Task / IRN # : 55-10-00-207				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with TLMC task 55-10-00-207 Performed detailed inspection of the inner pivot pin of the horizontal stabilizer REF CL-650 AMM 55-10-01-220-815. No defects noted.	B1002512 - Brandon Warne Feb 17, 2026 08:40 PM	55-10
	Perform Detailed Inspection of the Inner Pivot Pin of the Horizontal Stabilizer		B1013522 - Brandon Jennings Feb 17, 2026 08:56 PM	
	200	Removed all tools, equipment and materials from the work area.	B1002512 - Brandon Warne Feb 17, 2026 08:40 PM	
	Remove all tools, equipment and materials from the work area.		B1013522 - Brandon Jennings Feb 17, 2026 08:56 PM	

TOOL INFORMATION

Tool ID	Tool Description	Calibration Due Date
TUSS5185	Torque Wrench	Oct 30, 2026 5:00 PM

Bombardier

Sequence #	0008-49	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503804	Aircraft Reg #	XA-SOL	Parent WO #	2503653

0008-49	WO #	2503804	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Vertical Stabilizer Assembly - External	
General Visual Inspection of the Vertical Stabilizer Assembly - External				
Task / IRN # : 55-ZL-00-201				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with Task 55-ZL-00-201. Performed General Visual Inspection of the Vertical Stabilizer Assembly - External, in reference to CL-650 AMM 55-30-01-210-806. No defects were noted.	B0638589 - Sean Dodder Feb 06, 2026 03:45 AM	55-30
	Perform General Visual Inspection of the Vertical Stabilizer Assembly - External		B0623124 - Michael Stacy Feb 06, 2026 04:13 AM	
	200	Removed all tools, equipment, and unwanted materials from the work area.	B0638589 - Sean Dodder Feb 06, 2026 03:45 AM	
	Remove all tools, equipment, and unwanted materials from the work area.		B0623124 - Michael Stacy Feb 06, 2026 04:13 AM	

Bombardier

Sequence #	0008-50	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503806	Aircraft Reg #	XA-SOL	Parent WO #	2503653

0008-50	WO #	2503806	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Wing Center Section - External LH	
General Visual Inspection of the Wing Center Section - External LH				
Task / IRN # : 57-ZL-00-201				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with TLMC task 57-ZL-00-201 Performed general visual inspection of the LH wing center section (External) REF CL-650 AMM 57-10-00-210-801. No defects noted.	B1002512 - Brandon Warne Feb 09, 2026 02:30 PM	57-10
	Perform General Visual Inspection of the Wing Center Section - External LH		B1013522 - Brandon Jennings Feb 09, 2026 02:50 PM	
	200	Removed all tools, equipment and materials from the work area.	B1002512 - Brandon Warne Feb 09, 2026 02:30 PM	
	Remove all tools, equipment and materials from the work area.		B1013522 - Brandon Jennings Feb 09, 2026 02:50 PM	

Sequence #	0008-51	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503807	Aircraft Reg #	XA-SOL	Parent WO #	2503653

0008-51	WO #	2503807	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Wing Center Section - External RH	
General Visual Inspection of the Wing Center Section - External RH				
Task / IRN # : 57-ZL-00-202				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with TLMC task 57-ZL-00-202 Performed general visual inspection of the RH wing center section (External) REF CL-650 AMM 57-10-00-210-801. No defects noted.	B1002512 - Brandon Warne Feb 09, 2026 02:44 PM	57-10
	Perform General Visual Inspection of the Wing Center Section - External RH		B1013522 - Brandon Jennings Feb 09, 2026 02:51 PM	
	200	Removed all tools, equipment and materials from the work area.	B1002512 - Brandon Warne Feb 09, 2026 02:44 PM	
	Remove all tools, equipment and materials from the work area.		B1013522 - Brandon Jennings Feb 09, 2026 02:51 PM	

Sequence #	0008-52	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503810	Aircraft Reg #	XA-SOL	Parent WO #	2503653

0008-52	WO #	2503810	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Inboard Leading Edge of the Wing - External LH	
General Visual Inspection of the Inboard Leading Edge of the Wing - External LH				
Task / IRN # : 57-ZL-00-206				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	C/W Task 57-ZL-00-206, Performed General Visual Inspection of the Inboard Leading Edge of the Wing - External LH IAW CL650 AMM 57-40-00-210-801. Ref WO 4540931 for Defects	B0642374 - Joren Ayer Feb 04, 2026 04:17 PM	57-40
	Perform General Visual Inspection of the Inboard Leading Edge of the Wing - External LH		B0143196 - Robert Bohner Feb 04, 2026 04:58 PM	
	200	Removed all tools, equipment, and unwanted materials from the work area.	B0642374 - Joren Ayer Feb 04, 2026 04:18 PM	
	Remove all tools, equipment, and unwanted materials from the work area.		B0143196 - Robert Bohner Feb 04, 2026 04:58 PM	

Sequence #	0008-53	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503812	Aircraft Reg #	XA-SOL	Parent WO #	2503653

0008-53	WO #	2503812	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Inboard Leading Edge of the Wing - External RH	
General Visual Inspection of the Inboard Leading Edge of the Wing - External RH				
Task / IRN # : 57-ZL-00-207				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	C/W Task 57-ZL-00-207, Performed General Visual Inspection of the Inboard Leading Edge of the Wing - External RH IAW CL650 AMM 57-40-00-210-801. Ref WO 4540931 for Defects	B0642374 - Joren Ayer Feb 04, 2026 04:21 PM	57-40
	Perform General Visual Inspection of the Inboard Leading Edge of the Wing - External RH		B0143196 - Robert Bohner Feb 04, 2026 05:00 PM	
	200	Removed all tools, equipment, and unwanted materials from the work area.	B0642374 - Joren Ayer Feb 04, 2026 04:22 PM	
	Remove all tools, equipment, and unwanted materials from the work area.		B0143196 - Robert Bohner Feb 04, 2026 05:00 PM	

Bombardier

Sequence #	0008-54	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503813	Aircraft Reg #	XA-SOL	Parent WO #	2503653

0008-54	WO #	2503813	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Outboard Leading Edge of the Wing - External LH	
General Visual Inspection of the Outboard Leading Edge of the Wing - External LH				
Task / IRN # : 57-ZL-00-210				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	complied with task 57-ZL-00-210. performed a General Visual Inspection of the Outboard Leading Edge of the L/H Wing - External IAW CL 650 AMM 57-40-00-210-803. see W/O: 4540931 for corrective action to defects noted.	B0642326 - Austin McQuilkin Feb 04, 2026 05:56 PM	57-40
	Perform General Visual Inspection of the Outboard Leading Edge of the Wing - External LH		B0143196 - Robert Bohner Feb 04, 2026 07:23 PM	
	200	Removed all tools, equipment, and unwanted materials from the work area.	B0642326 - Austin McQuilkin Feb 04, 2026 05:56 PM	
	Remove all tools, equipment, and unwanted materials from the work area.		B0143196 - Robert Bohner Feb 04, 2026 07:23 PM	

Bombardier

Sequence #	0008-55	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503815	Aircraft Reg #	XA-SOL	Parent WO #	2503653

0008-55	WO #	2503815	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Outboard Leading Edge of the Wing - External RH	
General Visual Inspection of the Outboard Leading Edge of the Wing - External RH				
Task / IRN # : 57-ZL-00-211				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	complied with task 57-ZL-00-211. performed a General Visual Inspection of the Outboard Leading Edge of the R/H Wing - External IAW CL 650 AMM 57-40-00-210-803. no defects noted	B0642326 - Austin McQuilkin Feb 04, 2026 05:59 PM	57-40
	Perform General Visual Inspection of the Outboard Leading Edge of the Wing - External RH		B1013522 - Brandon Jennings Feb 04, 2026 06:59 PM	
	200	Removed all tools, equipment, and unwanted materials from the work area.	B0642326 - Austin McQuilkin Feb 04, 2026 05:59 PM	
	Remove all tools, equipment, and unwanted materials from the work area.		B1013522 - Brandon Jennings Feb 04, 2026 06:59 PM	

Sequence #	0008-56	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503818	Aircraft Reg #	XA-SOL	Parent WO #	2503653

0008-56	WO #	2503818	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Wing from WS47 to WS148 - External LH	
General Visual Inspection of the Wing from WS47 to WS148 - External LH				
Task / IRN # : 57-ZL-00-214				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with TLMC task 57-ZL-00-214 Performed general visual inspection of the LH wing from WS47 to WS148 (External) REF CL-650 AMM 57-10-00-210-803. No defects noted.	B1002512 - Brandon Warne Feb 09, 2026 03:38 PM	57-10
	Perform General Visual Inspection of the Wing from WS47 to WS148 - External LH		B1013522 - Brandon Jennings Feb 09, 2026 04:24 PM	
	200	Removed all tools, equipment and materials from the work area.	B1002512 - Brandon Warne Feb 09, 2026 03:38 PM	
	Remove all tools, equipment and materials from the work area.		B1013522 - Brandon Jennings Feb 09, 2026 04:24 PM	

Bombardier

Sequence #	0008-57	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503819	Aircraft Reg #	XA-SOL	Parent WO #	2503653

0008-57	WO #	2503819	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Wing from WS47 to WS148 - External RH	
General Visual Inspection of the Wing from WS47 to WS148 - External RH				
Task / IRN # : 57-ZL-00-215				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with TLMC task 57-ZL-00-215 Performed general visual inspection of the RH wing from WS47 to WS148 (External) REF CL-650 AMM 57-10-00-210-803. No defects noted.	B1002512 - Brandon Warne Feb 09, 2026 03:56 PM	57-10
	Perform General Visual Inspection of the Wing from WS47 to WS148 - External RH		B1013522 - Brandon Jennings Feb 09, 2026 04:25 PM	
	200	Removed all tools, equipment and materials from the work area.	B1002512 - Brandon Warne Feb 09, 2026 03:56 PM	
	Remove all tools, equipment and materials from the work area.		B1013522 - Brandon Jennings Feb 09, 2026 04:25 PM	

Bombardier

Sequence #	0008-58	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503820	Aircraft Reg #	XA-SOL	Parent WO #	2503653

0008-58	WO #	2503820	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Wing from WS148 to WS353 - External LH	
General Visual Inspection of the Wing from WS148 to WS353 - External LH				
Task / IRN # : 57-ZL-00-218				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with TLMC task 57-ZL-00-218 Performed general visual inspection of the LH wing from WS148 to WS353 (External) REF CL-650 AMM 57-10-00-210-805. No defects noted.	B1002512 - Brandon Warne Feb 09, 2026 01:34 PM	57-10
	Perform General Visual Inspection of the Wing from WS148 to WS353 - External LH		B1013522 - Brandon Jennings Feb 09, 2026 01:53 PM	
	200	Removed all tools, equipment and materials from the work area.	B1002512 - Brandon Warne Feb 09, 2026 01:34 PM	
	Remove all tools, equipment and materials from the work area.		B1013522 - Brandon Jennings Feb 09, 2026 01:53 PM	

Bombardier

Sequence #	0008-59	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503824	Aircraft Reg #	XA-SOL	Parent WO #	2503653

0008-59	WO #	2503824	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Wing from WS148 to WS353 - External RH	
General Visual Inspection of the Wing from WS148 to WS353 - External RH				
Task / IRN # : 57-ZL-00-219				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with TLMC task 57-ZL-00-219 Performed general visual inspection of the RH wing from WS148 to WS353 (External) REF CL-650 AMM 57-10-00-210-805. No defects noted.	B1002512 - Brandon Warne Feb 09, 2026 01:49 PM	57-10
	Perform General Visual Inspection of the Wing from WS148 to WS353 - External RH		B1013522 - Brandon Jennings Feb 09, 2026 01:57 PM	
	200	Removed all tools, equipment and materials from the work area.	B1002512 - Brandon Warne Feb 09, 2026 01:49 PM	
	Remove all tools, equipment and materials from the work area.		B1013522 - Brandon Jennings Feb 09, 2026 01:57 PM	

Sequence #	0008-60	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503825	Aircraft Reg #	XA-SOL	Parent WO #	2503653

0008-60	WO #	2503825	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Winglet - External LH	
General Visual Inspection of the Winglet - External LH				
Task / IRN # : 57-ZL-00-222				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with TLMC task 57-ZL-00-222 Performed general visual inspection of the LH winglet (External) REF CL-650 AMM 57-30-00-210-801.	B1002512 - Brandon Warne Feb 05, 2026 02:44 PM	57-30
	Perform General Visual Inspection of the Winglet - External LH		B1013522 - Brandon Jennings Feb 05, 2026 02:49 PM	
	101	Complied with TLMC task 57-ZL-00-222 Performed general visual inspection of the LH winglet (External) REF CL-650 AMM 57-30-00-210-801. No defects noted.	B1002512 - Brandon Warne Feb 05, 2026 02:53 PM	
	Perform General Visual Inspection of the Winglet - External LH		B1013522 - Brandon Jennings Feb 05, 2026 03:24 PM	09
	200	Removed all tools, equipment and materials from the work area.	B1002512 - Brandon Warne Feb 05, 2026 02:44 PM	
	Remove all tools, equipment and materials from the work area.		B1013522 - Brandon Jennings Feb 05, 2026 02:49 PM	

Sequence #	0008-61	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503826	Aircraft Reg #	XA-SOL	Parent WO #	2503653

0008-61	WO #	2503826	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Winglet - External RH	
General Visual Inspection of the Winglet - External RH				
Task / IRN # : 57-ZL-00-223				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with TLMC task 57-ZL-00-223 Performed general visual inspection of the RH winglet (External) REF CL-650 AMM 57-30-00-210-801.	B1002512 - Brandon Warne Feb 05, 2026 02:38 PM	57-30
	Perform General Visual Inspection of the Winglet - External RH		B1013522 - Brandon Jennings Feb 05, 2026 02:47 PM	
	101	Complied with TLMC task 57-ZL-00-223 Performed general visual inspection of the RH winglet (External) REF CL-650 AMM 57-30-00-210-801. No defects noted.	B1002512 - Brandon Warne Feb 05, 2026 02:53 PM	
	Perform General Visual Inspection of the Winglet - External RH		B1013522 - Brandon Jennings Feb 05, 2026 03:25 PM	09
	200	Removed all tools, equipment and materials from the work area.	B1002512 - Brandon Warne Feb 05, 2026 02:38 PM	
	Remove all tools, equipment and materials from the work area.		B1013522 - Brandon Jennings Feb 05, 2026 02:47 PM	

Bombardier

Sequence #	0008-62	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503830	Aircraft Reg #	XA-SOL	Parent WO #	2503653

0008-62	WO #	2503830	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Inboard Trailing Edge of the Wing - External LH	
General Visual Inspection of the Inboard Trailing Edge of the Wing - External LH				
Task / IRN # : 57-ZL-00-226				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	C/W Task 57-ZL-00-226 Performed General Visual Inspection of the Inboard Trailing Edge of the Wing - External LH IAW CL650 AMM 57-50-01-210-801 No Defects Noted.	B0642374 - Joren Ayer Feb 04, 2026 03:25 PM	57-50
	Perform General Visual Inspection of the Inboard Trailing Edge of the Wing - External LH		B1013522 - Brandon Jennings Feb 04, 2026 04:15 PM	
	200	Removed all tools, equipment, and unwanted materials from the work area.	B0642374 - Joren Ayer Feb 04, 2026 03:26 PM	
	Remove all tools, equipment, and unwanted materials from the work area.		B1013522 - Brandon Jennings Feb 04, 2026 04:15 PM	

Sequence #	0008-63	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503831	Aircraft Reg #	XA-SOL	Parent WO #	2503653

0008-63	WO #	2503831	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Inboard Trailing Edge of the Wing - External RH	
General Visual Inspection of the Inboard Trailing Edge of the Wing - External RH				
Task / IRN # : 57-ZL-00-227				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	C/W Task 57-ZL-00-227, Performed General Visual Inspection of the Inboard Trailing Edge of the Wing - External RH IAW CL650 AMM 57-50-01-210-801. No Defects Noted	B0642374 - Joren Ayer Feb 04, 2026 03:30 PM	57-50
	Perform General Visual Inspection of the Inboard Trailing Edge of the Wing - External RH		B1013522 - Brandon Jennings Feb 04, 2026 04:19 PM	
	200	Removed all tools, equipment, and unwanted materials from the work area.	B0642374 - Joren Ayer Feb 04, 2026 03:30 PM	
	Remove all tools, equipment, and unwanted materials from the work area.		B1013522 - Brandon Jennings Feb 04, 2026 04:19 PM	

Bombardier

Sequence #	0008-64	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503832	Aircraft Reg #	XA-SOL	Parent WO #	2503653

0008-64	WO #	2503832	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Outboard Trailing Edge of the Wing - External LH	
General Visual Inspection of the Outboard Trailing Edge of the Wing - External LH				
Task / IRN # : 57-ZL-00-230				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	complied with task 57-ZL-00-203. Performed a General Visual Inspection of the Outboard Trailing Edge of the L/H Wing - External IAW CL 650 AMM 57-50-01-210-803. see findings for defects noted.	B0642326 - Austin McQuilkin Feb 04, 2026 07:51 PM	57-50
	Perform General Visual Inspection of the Outboard Trailing Edge of the Wing - External LH		B1013522 - Brandon Jennings Feb 04, 2026 08:22 PM	
	200	Removed all tools, equipment, and unwanted materials from the work area.	B0642326 - Austin McQuilkin Feb 04, 2026 07:51 PM	
	Remove all tools, equipment, and unwanted materials from the work area.		B1013522 - Brandon Jennings Feb 04, 2026 08:22 PM	

FINDINGS DETAILS

Finding #	Long Description	Status	Reported By / Date	Defect Source / Disposition	Defect Type	Priority	Follow-up WO #
78871	L/H MFS IBD teflon pad found to be missing and the R/H MFS IBD teflon pad found to be disbonded.	CLOSED	B0642326 - Austin McQuilkin Feb 4, 2026 12:54 PM	MAINTENANCE 300-QA002	OTHER	3	4715576-PSAP

Bombardier

Sequence #	0008-65	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503836	Aircraft Reg #	XA-SOL	Parent WO #	2503653

0008-65	WO #	2503836	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Outboard Trailing Edge of the Wing - External RH	
General Visual Inspection of the Outboard Trailing Edge of the Wing - External RH				
Task / IRN # : 57-ZL-00-231				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	complied with task 57-ZL-00-231. Performed a General Visual Inspection of the Outboard Trailing Edge of the R/H Wing - External IAW CL 650 AMM 57-50-01-210-803. see findings 78871 for defects noted.	B0642326 - Austin McQuilkin Feb 04, 2026 07:57 PM	57-50
	Perform General Visual Inspection of the Outboard Trailing Edge of the Wing - External RH		B1013522 - Brandon Jennings Feb 04, 2026 08:21 PM	
	200	Removed all tools, equipment, and unwanted materials from the work area.	B0642326 - Austin McQuilkin Feb 04, 2026 07:57 PM	
	Remove all tools, equipment, and unwanted materials from the work area.		B1013522 - Brandon Jennings Feb 04, 2026 08:21 PM	

Bombardier

Sequence #	0008-66	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503837	Aircraft Reg #	XA-SOL	Parent WO #	2503653

0008-66	WO #	2503837	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Nacelle - External LH	
General Visual Inspection of the Nacelle - External LH				
Task / IRN # : 71-ZL-00-201				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	C/W Task 71-ZL-00-201, Performed General Visual Inspection of the Nacelle - External LH IAW Cl650 AMM 71-10-00-210-801. No Defects Noted	B0642374 - Joren Ayer Feb 04, 2026 03:54 PM	71-10
	Perform General Visual Inspection of the Nacelle - External LH		B1013522 - Brandon Jennings Feb 04, 2026 04:55 PM	
	200	Removed all tools, equipment, and unwanted materials from the work area.	B0642374 - Joren Ayer Feb 04, 2026 03:54 PM	
	Remove all tools, equipment, and unwanted materials from the work area.		B1013522 - Brandon Jennings Feb 04, 2026 04:55 PM	

Sequence #	0008-67	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503838	Aircraft Reg #	XA-SOL	Parent WO #	2503653

0008-67	WO #	2503838	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Nacelle - External RH	
General Visual Inspection of the Nacelle - External RH				
Task / IRN # : 71-ZL-00-202				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	C/W Task 71-ZL-00-202, Performed General Visual Inspection of the Nacelle - External RH IAW CL650 AMM 71-10-00-210-801. No Defects Noted	B0642374 - Joren Ayer Feb 04, 2026 03:57 PM	71-10
	Perform General Visual Inspection of the Nacelle - External RH		B1013522 - Brandon Jennings Feb 04, 2026 04:57 PM	
	200	Removed all tools, equipment, and unwanted materials from the work area.	B0642374 - Joren Ayer Feb 04, 2026 03:57 PM	
	Remove all tools, equipment, and unwanted materials from the work area.		B1013522 - Brandon Jennings Feb 04, 2026 04:57 PM	

Sequence #	0008-68	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503842	Aircraft Reg #	XA-SOL	Parent WO #	2503653

0008-68	WO #	2503842	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Translating Cowl - Internal LH	
General Visual Inspection of the Translating Cowl - Internal LH				
Task / IRN # : 71-ZL-00-205				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 71-ZL-00-205, Perform General Visual Inspection of the Translating Cowl - Internal LH, in accordance with 650 MM 71-11-01-210-801. No defects noted	B0603116 - Juan Ahumada Feb 05, 2026 01:35 AM	71-10
	Perform General Visual Inspection of the Translating Cowl - Internal LH		B0623124 - Michael Stacy Feb 05, 2026 03:23 AM	
	200	Complied with FOD check of area worked (no FOD noted)	B0603116 - Juan Ahumada Feb 05, 2026 02:14 AM	
	Comply with FOD check of area worked		B0623124 - Michael Stacy Feb 05, 2026 03:23 AM	
	300	Removed all tools, equipment and unwanted materials from the work area	B0603116 - Juan Ahumada Feb 05, 2026 02:22 AM	
	Remove all tools, equipment and unwanted materials from the work area		B0623124 - Michael Stacy Feb 05, 2026 03:23 AM	

Sequence #	0008-69	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503843	Aircraft Reg #	XA-SOL	Parent WO #	2503653

0008-69	WO #	2503843	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Translating Cowl - Internal RH	
General Visual Inspection of the Translating Cowl - Internal RH				
Task / IRN # : 71-ZL-00-206				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 71-ZL-00-206, Perform General Visual Inspection of the Translating Cowl - Internal RH, in accordance with 650 AMM 71-11-01-210-801.No defects noted	B0603116 - Juan Ahumada Feb 05, 2026 02:10 AM	71-10
	Perform General Visual Inspection of the Translating Cowl - Internal RH		B0623124 - Michael Stacy Feb 05, 2026 03:25 AM	
	200	Complied with FOD check of area worked (no FOD noted)	B0603116 - Juan Ahumada Feb 05, 2026 02:10 AM	
	Comply with FOD check of area worked		B0623124 - Michael Stacy Feb 05, 2026 03:25 AM	
	300	Removed all tools, equipment and unwanted materials from the work area	B0603116 - Juan Ahumada Feb 05, 2026 02:23 AM	
	Remove all tools, equipment and unwanted materials from the work area		B0623124 - Michael Stacy Feb 05, 2026 03:25 AM	

Bombardier

Sequence #	0008-70	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503844	Aircraft Reg #	XA-SOL	Parent WO #	2503653

0008-70	WO #	2503844	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Torque Box of the Thrust Reverser - Internal LH	
General Visual Inspection of the Torque Box of the Thrust Reverser - Internal LH				
Task / IRN # : 78-ZL-00-201				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 78-ZL-00-201, Perform General Visual Inspection of the Torque Box of the Thrust Reverser - Internal LH, in accordance with CL-650 AMM 78-30-00-210-802. defects noted.	B0642051 - Terry Walters Feb 05, 2026 08:44 PM	78-30
	Perform General Visual Inspection of the Torque Box of the Thrust Reverser - Internal LH		B0143196 - Robert Bohner Feb 05, 2026 08:58 PM	
	200	Removed all Tools, Equipment, and unwanted Materials from the work area.	B0642051 - Terry Walters Feb 05, 2026 08:44 PM	
	Remove all Tools, Equipment, and unwanted Materials from the work area.		B0143196 - Robert Bohner Feb 05, 2026 08:58 PM	

FINDINGS DETAILS

Finding #	Long Description	Status	Reported By / Date	Defect Source / Disposition	Defect Type	Priority	Follow-up WO #
79069	LH T/R blocker doors down to bare material.	CLOSED	B0642051 - Terry Walters Feb 5, 2026 1:42 PM	MAINTENANCE 300-QA002	OTHER	3	4784975-PSAP

Bombardier

Sequence #	0008-71	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503848	Aircraft Reg #	XA-SOL	Parent WO #	2503653

0008-71	WO #	2503848	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Torque Box of the Thrust Reverser - Internal RH	
General Visual Inspection of the Torque Box of the Thrust Reverser - Internal RH				
Task / IRN # : 78-ZL-00-202				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 78-ZL-00-202, Perform General Visual Inspection of the Torque Box of the Thrust Reverser - Internal RH, in accordance with CL-650 AMM 78-30-00-210-802. Defects noted.	B0642051 - Terry Walters Feb 05, 2026 08:38 PM	78-30
	Perform General Visual Inspection of the Torque Box of the Thrust Reverser - Internal RH		B0143196 - Robert Bohner Feb 05, 2026 08:54 PM	
	200	Removed all tools, equipment, and unwanted materials from the work area.	B0642051 - Terry Walters Feb 05, 2026 08:38 PM	
	Remove all tools, equipment, and unwanted materials from the work area.		B0143196 - Robert Bohner Feb 05, 2026 08:54 PM	

FINDINGS DETAILS

Finding #	Long Description	Status	Reported By / Date	Defect Source / Disposition	Defect Type	Priority	Follow-up WO #
79068	T/R panels on RH T/R down to bare material	CLOSED	B0642051 - Terry Walters Feb 5, 2026 1:34 PM	MAINTENANCE 300-QA002	OTHER	3	4784967-PSAP

Bombardier

Sequence #	0008-72	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503849	Aircraft Reg #	XA-SOL	Parent WO #	2503653

0008-72	WO #	2503849	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Exhaust Nozzle Fairing-Assembly LH	
General Visual Inspection of the Exhaust Nozzle Fairing-Assembly LH				
Task / IRN # : 78-ZL-00-203				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with Task 78-ZL-00-203. Performed General Visual Inspection of the Exhaust Nozzle Fairing-Assembly LH, in reference to CL-650 AMM 78-10-01-210-801. See finding 78917 and 78920 for details.	B0638589 - Sean Dodder Feb 05, 2026 04:36 AM	78-10
	Perform General Visual Inspection of the Exhaust Nozzle Fairing-Assembly LH		B0623124 - Michael Stacy Feb 05, 2026 04:37 AM	
	200	Removed all tools, equipment, and unwanted materials from the work area.	B0638589 - Sean Dodder Feb 05, 2026 04:36 AM	
	Remove all tools, equipment, and unwanted materials from the work area.		B0623124 - Michael Stacy Feb 05, 2026 04:37 AM	

FINDINGS DETAILS

Finding #	Long Description	Status	Reported By / Date	Defect Source / Disposition	Defect Type	Priority	Follow-up WO #
78917	Sealant beginning to fail and crack around multiple interior ribs of LH Exhaust Nozzle Fairing-Assembly Interior. Photos included.	CLOSED	B0638589 - Sean Dodder Feb 4, 2026 9:26 PM	MAINTENANCE 300-QA002	OTHER	3	4715442-PSAP
78920	Section of metal on interior of LH Exhaust Nozzle Fairing-Assembly, beginning to lift and oil can in appearance and touch. Photo included.	CLOSED	B0638589 - Sean Dodder Feb 4, 2026 9:31 PM	MAINTENANCE 300-QA002	OTHER	3	4715439-PSAP

Bombardier

Sequence #	0008-73	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503850	Aircraft Reg #	XA-SOL	Parent WO #	2503653

0008-73	WO #	2503850	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Exhaust Nozzle Fairing-Assembly RH	
General Visual Inspection of the Exhaust Nozzle Fairing-Assembly RH				
Task / IRN # : 78-ZL-00-204				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with Task 78-ZL-00-204. Performed General Visual Inspection of the Exhaust Nozzle Fairing-Assembly RH, in reference to CL-650 AMM 78-10-01-210-801. See findings 78922 and 78923 for details.	B0638589 - Sean Dodder Feb 05, 2026 04:50 AM	78-10
	Perform General Visual Inspection of the Exhaust Nozzle Fairing-Assembly RH		B0623124 - Michael Stacy Feb 05, 2026 04:53 AM	
	200	Removed all tools, equipment, and unwanted materials from the work area.	B0638589 - Sean Dodder Feb 05, 2026 04:50 AM	
	Remove all tools, equipment, and unwanted materials from the work area.		B0623124 - Michael Stacy Feb 05, 2026 04:53 AM	

FINDINGS DETAILS

Finding #	Long Description	Status	Reported By / Date	Defect Source / Disposition	Defect Type	Priority	Follow-up WO #
78922	Sealant beginning to fail and crack around multiple interior ribs of RH Exhaust Nozzle Fairing-Assembly Interior. Photos included.	CLOSED	B0638589 - Sean Dodder Feb 4, 2026 9:42 PM	MAINTENANCE 300-QA002	OTHER	3	4715433-PSAP
78923	Multiple locations of bare/lifting paint on the interior of the RH Exhaust Nozzle Fairing-Assembly. Photos included.	CLOSED	B0638589 - Sean Dodder Feb 4, 2026 9:42 PM	MAINTENANCE 300-QA002	OTHER	3	4715414-PSAP

Sequence #	0008-74	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503854	Aircraft Reg #	XA-SOL	Parent WO #	2503653

0008-74	WO #	2503854	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Lightning/High Intensity Radiated Field (L/HIRF) protection in the Fuselage/Stabilizer - Internal	
Detailed Inspection of the Lightning/High Intensity Radiated Field (L/HIRF) protection in the Fuselage/Stabilizer - Internal				
Task / IRN # : 22-12-00-202				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with TLMC Task 22-12-00-202 Detailed Inspection of the Lightning/High Intensity Radiated Field (L/HIRF) protection in the Fuselage/Stabilizer - Internal IAW CL650 AMM Task 22-12-22-220-802. No defects noted.	B0141003 - Francisco Ayon Feb 12, 2026 08:01 PM	22-10
	Perform Detailed Inspection of the Lightning/High Intensity Radiated Field (L/HIRF) protection in the Fuselage/Stabilizer - Internal		B1013522 - Brandon Jennings Feb 12, 2026 08:07 PM	
	200	Removed all tools, equipment, and unwanted materials from the work area.	B0141003 - Francisco Ayon Feb 12, 2026 08:01 PM	
	Remove all tools, equipment, and unwanted materials from the work area.		B1013522 - Brandon Jennings Feb 12, 2026 08:07 PM	

Bombardier

Sequence #	0008-75	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503855	Aircraft Reg #	XA-SOL	Parent WO #	2503653

0008-75	WO #	2503855	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Lightning/High Intensity Radiated Field (L/HIRF) Protection in the Aft Equipment Compartment	
Detailed Inspection of the Lightning/High Intensity Radiated Field (L/HIRF) Protection in the Aft Equipment Compartment				
Task / IRN # : 22-12-00-204				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with TLMC Task 22-12-00-204 Detailed Inspection of the Lightning/High Intensity Radiated Field (L/HIRF) Protection in the Aft Equipment Compartment IAW CL650 AMM Task 22-12-22-220-804. Finding for MINI QAR created REF finding # 80010.	B0141003 - Francisco Ayon Feb 12, 2026 08:54 PM	22-10
	Perform Detailed Inspection of the Lightning/High Intensity Radiated Field (L/HIRF) Protection in the Aft Equipment Compartment		B1019908 - Joseph Barnes Feb 12, 2026 09:06 PM	
	200	Removed all tools, equipment, and unwanted materials from the work area.	B0141003 - Francisco Ayon Feb 12, 2026 08:54 PM	
	Remove all tools, equipment, and unwanted materials from the work area.		B1019908 - Joseph Barnes Feb 12, 2026 09:06 PM	

FINDINGS DETAILS

Finding #	Long Description	Status	Reported By / Date	Defect Source / Disposition	Defect Type	Priority	Follow-up WO #
80010	AFT Equipment Bay Mini QAR has a broken antenna.	CLOSED	B0141003 - Francisco Ayon Feb 12, 2026 1:44 PM	MAINTENANCE 300-QA002	OTHER	3	4804983-PROPOSAL

Sequence #	0008-76	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503857	Aircraft Reg #	XA-SOL	Parent WO #	2503653

0008-76	WO #	2503857	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Lightning/High Intensity Radiated Field (L/HIRF) Protection in the Avionics Compartments	
Detailed Inspection of the Lightning/High Intensity Radiated Field (L/HIRF) Protection in the Avionics Compartments				
Task / IRN # : 22-12-00-208				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 22-12-00-208 detailed inspection of the lightning/ high intensity radiated field (L/HIRF) protection in the avionics compartments IAW CL-650 AMM 22-12-22-220-808 No defects noted	B0619443 - Tyler Herrera Feb 13, 2026 03:44 PM	22-10
	Perform Detailed Inspection of the Lightning/High Intensity Radiated Field (L/HIRF) Protection in the Avionics Compartments		B1019908 - Joseph Barnes Feb 13, 2026 03:55 PM	
	200	Removed tools and equipment from aircraft	B0619443 - Tyler Herrera Feb 13, 2026 03:44 PM	
	Remove tools and equipment		B1019908 - Joseph Barnes Feb 13, 2026 03:55 PM	

Sequence #	0008-77	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503860	Aircraft Reg #	XA-SOL	Parent WO #	2503653

0008-77	WO #	2503860	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Lightning/High Intensity Radiated Field (L/HIRF) Protection in the Main Wheel Wells	
Detailed Inspection of the Lightning/High Intensity Radiated Field (L/HIRF) Protection in the Main Wheel Wells				
Task / IRN # : 22-12-00-212				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 22-12-00-212 detailed inspection of lightning/ high intensity radiated field 9L/HIRF) protection in the main wheel wells IAW CL-650 AMM 22-12-22-220-812 No defects noted	B0619443 - Tyler Herrera Feb 13, 2026 07:20 PM	22-10
	Perform Detailed Inspection of the Lightning/High Intensity Radiated Field (L/HIRF) Protection in the Main Wheel Wells		B1019908 - Joseph Barnes Feb 13, 2026 07:35 PM	
	200	Removed tools and equipment from aircraft	B0619443 - Tyler Herrera Feb 13, 2026 07:20 PM	
	Remove tools and equipment		B1019908 - Joseph Barnes Feb 13, 2026 07:35 PM	

Sequence #	0008-78	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503861	Aircraft Reg #	XA-SOL	Parent WO #	2503653

0008-78	WO #	2503861	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Lightning/High Intensity Radiated Field (L/HIRF) Protection in the Nose Wheel Well and Landing Gear Assembly	
Detailed Inspection of the Lightning/High Intensity Radiated Field (L/HIRF) Protection in the Nose Wheel Well and Landing Gear Assembly				
Task / IRN # : 22-12-00-213				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with TLMC Task 22-12-00-213, Perform Detailed Inspection of the Lightning/High Intensity Radiated Field (L/HIRF) Protection in the Nose Wheel Well and Landing Gear Assembly. REF CL-650 AMM 22-12-22-220-813. No Defects Noted.	B0143855 - Marlon Zurita Mar 05, 2026 08:48 PM	22-10
	Perform Detailed Inspection of the Lightning/High Intensity Radiated Field (L/HIRF) Protection in the Nose Wheel Well and Landing Gear Assembly		B0141354 - Karl Tuxhorn Mar 05, 2026 08:53 PM	
	200	Complied with removal of all tools, equipment, and unwanted materials from the work area	B0641378 - Calvin Ambrose Mar 05, 2026 08:44 PM	
	Comply with removal of all tools, equipment, and unwanted materials from the work area		B0141354 - Karl Tuxhorn Mar 05, 2026 08:53 PM	

Sequence #	0008-79	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503863	Aircraft Reg #	XA-SOL	Parent WO #	2503653

0008-79	WO #	2503863	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Functional Test (Bonding Check) of the Static Discharger Base	
Functional Test (Bonding Check) of the Static Discharger Base				
Task / IRN # : 23-60-00-202				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 23-60-00-202, Functional Test (Bonding Check) of the Static Discharger Base, in accordance with CL-650 AMM 23-61-04-720-801 step D 6. SPM 51-80-00-760-801. BOND TEST GOOD.	B0143864 - Aaric Cerna Feb 09, 2026 04:53 PM	23-60
	Functional Test (Bonding Check) of the Static Discharger Base		B1013522 - Brandon Jennings Feb 09, 2026 04:59 PM	
	101	Complied with task 23-60-00-202, Functional Test (Bonding Check) of the Static Discharger Base, in accordance with CL-650 AMM 23-61-04-720-801 BOND TEST GOOD.	B0143864 - Aaric Cerna Feb 09, 2026 05:47 PM	
	Functional Test (Bonding Check) of the Static Discharger Base		B1013522 - Brandon Jennings Feb 09, 2026 05:50 PM	09
	200	Removed tools, equipment and all unwanted materials from work area	B0143864 - Aaric Cerna Feb 09, 2026 04:53 PM	
	Remove tools, equipment and all unwanted materials from work area		B1013522 - Brandon Jennings Feb 09, 2026 04:59 PM	

TOOL INFORMATION

Tool ID	Tool Description	Calibration Due Date
TUSJ1779	MEGAOHM	Apr 29, 2026 5:00 PM

Sequence #	0008-80	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503866	Aircraft Reg #	XA-SOL	Parent WO #	2503653

0008-80	WO #	2503866	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Aileron, Rudder, Elevator and Spoiler Control Cables in the Lower Forward Fuselage	
Detailed Inspection of the Aileron, Rudder, Elevator and Spoiler Control Cables in the Lower Forward Fuselage				
Task / IRN # : 27-00-00-201				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 27-00-00-201 Detailed Inspection of the Aileron, Rudder, Elevator and Spoiler Control Cables in the Lower Forward Fuselage IAW CL-650 AMM 27-00-00-220-801. No defects noted.	B0650736 - Jesus Gonzalez Atondo Feb 13, 2026 08:48 PM	27-00
	Detailed Inspection of the Aileron, Rudder, Elevator and Spoiler Control Cables in the Lower Forward		B0142244 - Todd Bridges Feb 13, 2026 09:32 PM	
	200	Removed all tools, equipment, and unwanted materials from the work area.	B0650736 - Jesus Gonzalez Atondo Feb 13, 2026 08:48 PM	
	Remove all tools, equipment, and unwanted materials from the work area.		B0142244 - Todd Bridges Feb 13, 2026 09:32 PM	

Sequence #	0008-81	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503867	Aircraft Reg #	XA-SOL	Parent WO #	2503653

0008-81	WO #	2503867	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Aileron, Rudder, Elevator and Spoiler Control Cables in the Main Avionics Compartment	
Detailed Inspection of the Aileron, Rudder, Elevator and Spoiler Control Cables in the Main Avionics Compartment				
Task / IRN # : 27-00-00-202				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 27-00-00-202, Perform Detailed Inspection of the Aileron, Rudder, Elevator and Spoiler Control Cables in the Main Avionics Compartment., in accordance with CL650 AMM 27-00-00-220-802. No defects noted.	B0641903 - Felipe Mendoza Cervantes Feb 17, 2026 12:42 AM	27-00
	Perform Detailed Inspection of the Aileron, Rudder, Elevator and Spoiler Control Cables in the Main Avionics Compartment.		B0623124 - Michael Stacy Feb 17, 2026 12:55 AM	
	200	Removed all tools equipment and unwanted materials from the work area.	B0641903 - Felipe Mendoza Cervantes Feb 17, 2026 12:42 AM	
	Remove all tools equipment and unwanted materials from the work area.		B0623124 - Michael Stacy Feb 17, 2026 12:55 AM	

Sequence #	0008-82	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503869	Aircraft Reg #	XA-SOL	Parent WO #	2503653

0008-82	WO #	2503869	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Aileron Control Cables in the Outboard Wing Box	
Detailed Inspection of the Aileron Control Cables in the Outboard Wing Box				
Task / IRN # : 27-00-00-209				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 27-00-00-209, Perform LH Detailed Inspection of the Aileron Control Cables in the Outboard Wing Box, REF CL650 AMM 27-11-00-220-811. No defects noted.	B1016542 - Carlos Ochoa Feb 10, 2026 04:51 AM	27-10
	Perform LH Detailed Inspection of the Aileron Control Cables in the Outboard Wing Box		B0161691 - Thomas Mitchell Feb 10, 2026 05:12 AM	
	200	Complied with task 27-00-00-209, Perform RH Detailed Inspection of the Aileron Control Cables in the Outboard Wing Box, REF CL650 AMM 27-11-00-220-811. No defects noted.	B1016542 - Carlos Ochoa Feb 10, 2026 04:51 AM	27-10
	Perform RH Detailed Inspection of the Aileron Control Cables in the Outboard Wing Box		B0161691 - Thomas Mitchell Feb 10, 2026 05:12 AM	
	300	Removed all tools, equipment, and unwanted materials.	B1016542 - Carlos Ochoa Feb 10, 2026 04:51 AM	
	Remove all tools, equipment, and unwanted materials.		B0161691 - Thomas Mitchell Feb 10, 2026 05:12 AM	

Sequence #	0008-83	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503873	Aircraft Reg #	XA-SOL	Parent WO #	2503653

0008-83	WO #	2503873	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Landing-Gear Emergency-Extension Cable in the NLG Wheel Well	
Detailed Inspection of the Landing-Gear Emergency-Extension Cable in the NLG Wheel Well				
Task / IRN # : 32-00-01-208				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with TLMC 32-00-01-208. Performed a Detailed Inspection of the Landing-Gear Emergency-Extension Cable in the NLG Wheel Well Ref. CL-650 AMM 32-34-28-220-802. No defects noted.	B0613291 - Eric Strong Feb 05, 2026 07:14 PM	32-30
	Perform Detailed Inspection of the Landing-Gear Emergency-Extension Cable in the NLG Wheel Well		B0143196 - Robert Bohner Feb 05, 2026 07:19 PM	
	200	Removed all tools, equipment, and unwanted materials from the work area.	B0613291 - Eric Strong Feb 05, 2026 07:14 PM	
	Remove all tools, equipment, and unwanted materials from the work area.		B0143196 - Robert Bohner Feb 05, 2026 07:19 PM	

Sequence #	0008-84	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	2503874	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2503653

0008-84	**WO #**	**2503874**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		General Visual Inspection of the Aft Nose-Landing-Gear Door	
General Visual Inspection of the Aft Nose-Landing-Gear Door				
Task / IRN # : 32-ZL-00-206				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	C/W Task 32-ZL-00-206, Performed General Visual Inspection of the Aft Nose-Landing-Gear Door IAW CL650 AMM 32-22-00-210-801. No Defects Noted	B0642374 - Joren Ayer Feb 04, 2026 05:50 PM	32-20
	Perform General Visual Inspection of the Aft Nose-Landing-Gear Door		B1013522 - Brandon Jennings Feb 04, 2026 07:02 PM	
	200	Removed all tools, equipment, and unwanted materials from the work area.	B0642374 - Joren Ayer Feb 04, 2026 05:50 PM	
	Remove all tools, equipment, and unwanted materials from the work area.		B1013522 - Brandon Jennings Feb 04, 2026 07:02 PM	

Sequence #	0008-85	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503877	Aircraft Reg #	XA-SOL	Parent WO #	2503653

0008-85	WO #	2503877	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Door Frame Machined Fittings, Stops and Hooks of the Overwing Emergency-Exit Door	
Detailed Inspection of the Door Frame Machined Fittings, Stops and Hooks of the Overwing Emergency-Exit Door				
Task / IRN # : 52-21-00-204				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with TLMC task 52-21-00-204 Performed detailed inspection of the door frame machined fittings, stops and hooks of the overwing emergency-exit door. REF CL-650 AMM 52-21-01-220-802. No defects noted.	B1002512 - Brandon Warne Feb 13, 2026 09:00 PM	52-20
	Perform Detailed Inspection of the Door Frame Machined Fittings, Stops and Hooks of the Overwing Emergency-Exit Door		B1019908 - Joseph Barnes Feb 13, 2026 09:11 PM	
	200	Removed all tools, equipment and materials from the work area.	B1002512 - Brandon Warne Feb 13, 2026 09:00 PM	
	Remove all tools, equipment and materials from the work area.		B1019908 - Joseph Barnes Feb 13, 2026 09:11 PM	

Sequence #	0008-86	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503879	Aircraft Reg #	XA-SOL	Parent WO #	2503653

0008-86	WO #	2503879	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Main Landing Gear Wheel Well	
General Visual Inspection of the Main Landing Gear Wheel Well				
Task / IRN # : 53-ZL-00-214				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with TLMC 53-ZL-00-214. Performed a General Visual Inspection of the LH Main Landing Gear Wheel Well Ref. CL-650 AMM 53-20-01-210-805. See Finding 79011 for defects found.	B0613291 - Eric Strong Feb 05, 2026 04:37 PM	53-20
	Perform LH General Visual Inspection of the Main Landing Gear Wheel Well LH		B1013522 - Brandon Jennings Feb 05, 2026 05:10 PM	
	200	Complied with TLMC 53-ZL-00-214. Performed a General Visual Inspection of the RH Main Landing Gear Wheel Well Ref. CL-650 AMM 53-20-01-210-805. See Finding 79009 for defects found.	B0613291 - Eric Strong Feb 05, 2026 04:37 PM	53-20
	Perform RH General Visual Inspection of the Main Landing Gear Wheel Well		B1013522 - Brandon Jennings Feb 05, 2026 05:10 PM	
	300	Removed all tools, equipment, and unwanted materials from the work area.	B0613291 - Eric Strong Feb 05, 2026 04:37 PM	
	Remove all tools, equipment, and unwanted materials from the work area.		B1013522 - Brandon Jennings Feb 05, 2026 05:10 PM	

Sequence #	0008-86	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503879	Aircraft Reg #	XA-SOL	Parent WO #	2503653

FINDINGS DETAILS

Finding #	Long Description	Status	Reported By / Date	Defect Source / Disposition	Defect Type	Priority	Follow-up WO #
79009	Fuel tube in RH MLG Wheel Well has missing/flaking primer in multiple areas (flagged)	CLOSED	B0613291 - Eric Strong Feb 5, 2026 9:28 AM	MAINTENANCE 300-QA002	OTHER	3	4755774-PSAP
79011	Hydraulic Pressure Relief Valve on AFT face of LH Wheel Well is suspected to be leaking (flagged)	CLOSED	B0613291 - Eric Strong Feb 5, 2026 9:32 AM	MAINTENANCE 300-QA002	OTHER	3	4749015-PSAP
79020	#3 Hydraulic Reservoir in Main Landing Gear Wheel Well has evidence of leakage around multiple fastener heads (flagged)	CLOSED	B0613291 - Eric Strong Feb 5, 2026 9:49 AM	MAINTENANCE 300-QA002	OTHER	3	4749029-PSAP

Sequence #	0008-87	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503881	Aircraft Reg #	XA-SOL	Parent WO #	2503653

0008-87	WO #	2503881	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Aft Face of the Rear Spar of the Wing - WS48 to WS353	
Detailed Inspection of the Aft Face of the Rear Spar of the Wing - WS48 to WS353				
Task / IRN # : 57-10-00-211				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with TLMC task 57-10-00-211 Performed Detailed inspection of the Aft face of the LH rear spar of the wing from WS48 to WS353 REF CL-650 AMM 57-10-00-220-811. No defects noted.	B1002512 - Brandon Warne Feb 12, 2026 05:31 PM	57-10
	Perform Detailed Inspection of the Aft Face of LH Rear Spar of the Wing - WS48 to WS353		B1013522 - Brandon Jennings Feb 12, 2026 06:47 PM	
	200	Complied with TLMC task 57-10-00-211 Performed Detailed inspection of the Aft face of the RH rear spar of the wing from WS48 to WS353 REF CL-650 AMM 57-10-00-220-811. No defects noted.	B1002512 - Brandon Warne Feb 12, 2026 05:31 PM	57-10
	Perform Detailed Inspection of the Aft Face of RH Rear Spar of the Wing - WS48 to WS353		B1013522 - Brandon Jennings Feb 12, 2026 06:47 PM	
	300	Removed all tools, equipment and materials from the work area.	B1002512 - Brandon Warne Feb 12, 2026 05:31 PM	
	Remove all tools, equipment and materials from the work area.		B1013522 - Brandon Jennings Feb 12, 2026 06:47 PM	

Sequence #	0008-88	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503885	Aircraft Reg #	XA-SOL	Parent WO #	2503653

0008-88	WO #	2503885	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Internal Wing (Auxiliary Spar, Planks, Skins, Structure and the MLG Trunnion Fitting) - WS48.00 to WS139.90	
Detailed Inspection of the Internal Wing (Auxiliary Spar, Planks, Skins, Structure and the MLG Trunnion Fitting) - WS48.00 to WS139.90				
Task / IRN # : 57-10-00-217				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with TLMC task 57-10-00-217 Performed detailed inspection of the LH internal wing (Auxiliary spar, skins, structure and the MLG trunnion fitting) WS48.00 to WS139.90 REF CL-650 AMM 57-10-00-220-868. No defects noted.	B1002512 - Brandon Warne Feb 10, 2026 07:25 PM	57-10
	Perform Detailed Inspection of LH Internal Wing (Auxiliary Spar, Planks, Skins, Structure and the MLG Trunnion Fitting) - WS48.00 to WS139.90		B1013522 - Brandon Jennings Feb 10, 2026 07:29 PM	
	200	Complied with TLMC task 57-10-00-217 Performed detailed inspection of the RH internal wing (Auxiliary spar, skins, structure and the MLG trunnion fitting) WS48.00 to WS139.90 REF CL-650 AMM 57-10-00-220-868. No defects noted.	B1002512 - Brandon Warne Feb 10, 2026 07:25 PM	57-10
	Perform Detailed Inspection of RH Internal Wing (Auxiliary Spar, Planks, Skins, Structure and the MLG Trunnion Fitting) - WS48.00 to WS139.90		B1013522 - Brandon Jennings Feb 10, 2026 07:29 PM	
	300	Removed all tools, equipment and materials from the work area.	B1002512 - Brandon Warne Feb 10, 2026 07:25 PM	
	Remove all tools, equipment and materials from the work area.		B1013522 - Brandon Jennings Feb 10, 2026 07:29 PM	

Bombardier

Sequence #	0008-89	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503888	Aircraft Reg #	XA-SOL	Parent WO #	2503653

0008-89	WO #	2503888	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Inboard Flap and Inboard Flap Vane (External Surfaces)	
Detailed Inspection of the Inboard Flap and Inboard Flap Vane (External Surfaces)				
Task / IRN # : 57-50-00-201				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 57-50-00-201 Detailed Inspection of the LH Inboard Flap and Inboard Flap Vane (External Surfaces) IAW CL-650 AMM 57-50-01-220-816. See finding 79664.	B0650736 - Jesus Gonzalez Atondo Feb 10, 2026 02:07 PM	57-50
	Perform Detailed Inspection of LH Inboard Flap and Inboard Flap Vane (External Surfaces)		B1013522 - Brandon Jennings Feb 10, 2026 02:16 PM	
	200	Complied with task 57-50-00-201 Detailed Inspection of the RH Inboard Flap and Inboard Flap Vane (External Surfaces) IAW CL-650 AMM 57-50-01-220-816. See finding 79664.	B0650736 - Jesus Gonzalez Atondo Feb 10, 2026 02:07 PM	57-50
	Perform Detailed Inspection of RH Inboard Flap and Inboard Flap Vane (External Surfaces)		B1013522 - Brandon Jennings Feb 10, 2026 02:16 PM	
	300	Removed all tools, equipment, and unwanted materials from the work area.	B0650736 - Jesus Gonzalez Atondo Feb 10, 2026 02:07 PM	
	Remove all tools, equipment, and unwanted materials from the work area.		B1013522 - Brandon Jennings Feb 10, 2026 02:16 PM	

FINDINGS DETAILS

Finding #	Long Description	Status	Reported By / Date	Defect Source / Disposition	Defect Type	Priority	Follow-up WO #
79664	Deep scratches found on the LH/RH IB flap vane.	CLOSED	B0650736 - Jesus Gonzalez Atondo Feb 10, 2026 7:00 AM	MAINTENANCE 300-QA002	OTHER	3	4755838-PSAP

Sequence #	0008-90	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503891	Aircraft Reg #	XA-SOL	Parent WO #	2503653

0008-90	WO #	2503891	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Outboard Flap (External Surfaces) and the Outboard Flap Vane (External Surfaces and Support Fittings)	
Detailed Inspection of the Outboard Flap (External Surfaces) and the Outboard Flap Vane (External Surfaces and Support Fittings)				
Task / IRN # : 57-50-00-206				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 57-50-00-206 Detailed Inspection of the LH Outboard Flap (External Surfaces) and the Outboard Flap Vane (External Surfaces and Support Fittings) IAW CL-650 AMM 57-50-01-220-817. No defects noted.	B0650736 - Jesus Gonzalez Atondo Feb 10, 2026 02:27 PM	57-50
	Perform Detailed Inspection of LH Outboard Flap (External Surfaces) and the Outboard Flap Vane (External Surfaces and Support Fittings)		B1013522 - Brandon Jennings Feb 10, 2026 02:59 PM	
	200	Complied with task 57-50-00-206 Detailed Inspection of the RH Outboard Flap (External Surfaces) and the Outboard Flap Vane (External Surfaces and Support Fittings) IAW CL-650 AMM 57-50-01-220-817. No defects noted.	B0650736 - Jesus Gonzalez Atondo Feb 10, 2026 02:27 PM	57-50
	Perform Detailed Inspection of RH Outboard Flap (External Surfaces) and the Outboard Flap Vane (External Surfaces and Support Fittings)		B1013522 - Brandon Jennings Feb 10, 2026 02:59 PM	
	300	Removed all tools, equipment, and unwanted materials from the work area	B0650736 - Jesus Gonzalez Atondo Feb 10, 2026 02:27 PM	
	Remove all tools, equipment, and unwanted materials from the work area.		B1013522 - Brandon Jennings Feb 10, 2026 02:59 PM	

Sequence #	0008-91	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503892	Aircraft Reg #	XA-SOL	Parent WO #	2503653

0008-91	WO #	2503892	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the External Surfaces and Forward Face of the Front Spar of the Ground Spoiler	
Detailed Inspection of the External Surfaces and Forward Face of the Front Spar of the Ground Spoiler				
Task / IRN # : 57-70-00-201				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 57-70-00-201, Perform Detailed Inspection of LH External Surfaces and Forward Face of the Front Spar of the Ground Spoiler, REF CL650 AMM 57-70-01-220-801. No defects noted.	B1016542 - Carlos Ochoa Feb 10, 2026 04:29 AM	57-70
	Perform Detailed Inspection of LH External Surfaces and Forward Face of the Front Spar of the Ground Spoiler		B0161691 - Thomas Mitchell Feb 10, 2026 04:49 AM	
	200	Complied with task 57-70-00-201, Perform Detailed Inspection of RH External Surfaces and Forward Face of the Front Spar of the Ground Spoiler, REF CL650 AMM 57-70-01-220-801. No defects noted.	B1016542 - Carlos Ochoa Feb 10, 2026 04:29 AM	57-70
	Perform Detailed Inspection of RH External Surfaces and Forward Face of the Front Spar of the Ground Spoiler		B0161691 - Thomas Mitchell Feb 10, 2026 04:49 AM	
	300	Removed all tools, equipment, and unwanted materials.	B1016542 - Carlos Ochoa Feb 10, 2026 04:29 AM	
	Remove all tools, equipment, and unwanted materials.		B0161691 - Thomas Mitchell Feb 10, 2026 04:49 AM	

Sequence #	0008-92	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503897	Aircraft Reg #	XA-SOL	Parent WO #	2503653

0008-92	WO #	2503897	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Special Detailed Inspection of the Bonded Skins of the Ground Spoiler	
Special Detailed Inspection of the Bonded Skins of the Ground Spoiler				
Task / IRN # : 57-70-00-202				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with Task No. 57-70-00-202. Performed a Special Detailed Inspection of the Bonded Skins of the LH Ground Spoiler. No defects noted. Ref: CL650 AMM 57-70-01-280-801	B0646266 - Sergio Rodriguez Figueroa Feb 11, 2026 02:33 PM	57-70
	Perform Special Detailed Inspection of LH Bonded Skins of the Ground Spoiler		B1013522 - Brandon Jennings Feb 11, 2026 04:53 PM	
	200	Complied with Task No. 57-70-00-202. Performed a Special Detailed Inspection of the Bonded Skins of the RH Ground Spoiler. No defects noted. Ref: CL650 AMM 57-70-01-280-801	B0646266 - Sergio Rodriguez Figueroa Feb 11, 2026 02:33 PM	57-70
	Perform Special Detailed Inspection of RH Bonded Skins of the Ground Spoiler		B1013522 - Brandon Jennings Feb 11, 2026 04:53 PM	
	300	Complied with Task No. 57-70-00-202. Performed a Special Detailed Inspection of the Bonded Skins of the LH Ground Spoiler. See Finding No. 79852. Ref: CL650 AMM 57-70-01-280-801	B0646266 - Sergio Rodriguez Figueroa Feb 11, 2026 04:45 PM	
	Administrative Correction for Op: 100. Wording.		B1013522 - Brandon Jennings Feb 11, 2026 04:53 PM	
	400	Complied with Task No. 57-70-00-202. Performed a Special Detailed Inspection of the Bonded Skins of the RH Ground Spoiler. See Finding No. 79852. Ref: CL650 AMM 57-70-01-280-801	B0646266 - Sergio Rodriguez Figueroa Feb 11, 2026 04:45 PM	
	Administrative Correction for Op: 200. Wording.		B1013522 - Brandon Jennings Feb 11, 2026 04:53 PM	
	500	Removed all tools, equipment, and unwanted materials from the work area as required.	B0646266 - Sergio Rodriguez Figueroa Feb 11, 2026 04:45 PM	
	Remove all tools, equipment, and unwanted material from the work area.		B1013522 - Brandon Jennings Feb 11, 2026 04:53 PM	

Sequence #	0008-92	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	2503897	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2503653

FINDINGS DETAILS

Finding #	Long Description	Status	Reported By / Date	Defect Source / Disposition	Defect Type	Priority	Follow-up WO #
79852	Found torn/missing placard on both the LH and RH Ground Spoilers.	CLOSED	B0646266 - Sergio Rodriguez Figueroa Feb 11, 2026 7:46 AM	MAINTENANCE 300-QA002	OTHER	3	4795496-PSAP

Sequence #	0008-93	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503900	Aircraft Reg #	XA-SOL	Parent WO #	2503653

0008-93	WO #	2503900	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the External Surfaces and Forward Face of the Front Spar of the Flight Spoiler	
Detailed Inspection of the External Surfaces and Forward Face of the Front Spar of the Flight Spoiler				
Task / IRN # : 57-70-00-203				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 57-70-00-203, Perform Detailed Inspection of LH External Surfaces and Forward Face of the Front Spar of the Flight Spoiler, REF CL650 AMM 57-70-01-220-802. No defects noted.	B1016542 - Carlos Ochoa Feb 10, 2026 10:48 PM	57-70
	Perform Detailed Inspection of LH External Surfaces and Forward Face of the Front Spar of the Flight Spoiler		B0623124 - Michael Stacy Feb 10, 2026 11:26 PM	
	200	Complied with task 57-70-00-203, Perform Detailed Inspection of RH External Surfaces and Forward Face of the Front Spar of the Flight Spoiler, REF CL650 AMM 57-70-01-220-802. No defects noted.	B1016542 - Carlos Ochoa Feb 10, 2026 10:48 PM	57-70
	Perform Detailed Inspection of RH External Surfaces and Forward Face of the Front Spar of the Flight Spoiler		B0623124 - Michael Stacy Feb 10, 2026 11:26 PM	
	300	Removed all tools, equipment, and unwanted materials.	B1016542 - Carlos Ochoa Feb 10, 2026 10:48 PM	
	Remove all tools, equipment, and unwanted materials.		B0623124 - Michael Stacy Feb 10, 2026 11:26 PM	

Sequence #	0008-94	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503902	Aircraft Reg #	XA-SOL	Parent WO #	2503653

0008-94	WO #	2503902	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Special Detailed Inspection of the Bonded Skins of the Flight Spoiler	
Special Detailed Inspection of the Bonded Skins of the Flight Spoiler				
Task / IRN # : 57-70-00-204				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with Task No. 57-70-00-204. Performed a Special Detailed Inspection of the Bonded Skins of the LH Flight Spoiler. No defects noted. Ref: CL650 AMM 57-70-01-280-802	B0646266 - Sergio Rodriguez Figueroa Feb 11, 2026 02:45 PM	57-70
	Perform Special Detailed Inspection of LH Bonded Skins of the Flight Spoiler		B1013522 - Brandon Jennings Feb 11, 2026 04:08 PM	
	200	Complied with Task No. 57-70-00-204. Performed a Special Detailed Inspection of the Bonded Skins of the RH Flight Spoiler. No defects noted. Ref: CL650 AMM 57-70-01-280-802	B0646266 - Sergio Rodriguez Figueroa Feb 11, 2026 02:45 PM	57-70
	Perform Special Detailed Inspection of RH Bonded Skins of the Flight Spoiler		B1013522 - Brandon Jennings Feb 11, 2026 04:08 PM	
	300	Removed all tools, equipment, and unwanted materials from the work area as required.	B0646266 - Sergio Rodriguez Figueroa Feb 11, 2026 02:45 PM	
	Remove all tools, equipment, and unwanted material from the work area.		B1013522 - Brandon Jennings Feb 11, 2026 04:08 PM	

Bombardier

Sequence #	0008-95	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503906	Aircraft Reg #	XA-SOL	Parent WO #	2503653

0008-95	WO #	2503906	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Functional Test (Bonding Check) of the Nose-Radome Lightning Strips	
Functional Test (Bonding Check) of the Nose-Radome Lightning Strips				
Task / IRN # : 23-60-00-203				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			53-60
	Functional Test (Bonding Check) of the Nose-Radome Lightning Strips			

Sequence #	0008-96	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503908	Aircraft Reg #	XA-SOL	Parent WO #	2503653

0008-96	WO #	2503908	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Aileron and Spoiler Control Cables in the Main Landing Gear (MLG) Wheel Well	
Detailed Inspection of the Aileron and Spoiler Control Cables in the Main Landing Gear (MLG) Wheel Well				
Task / IRN # : 27-00-00-203				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 27-00-00-203 Detailed Inspection of the LH Aileron and Spoiler Control Cables in the Main Landing Gear (MLG) Wheel Well IAW CL-650 AMM 27-00-00-220-803. No defects noted.	B0650736 - Jesus Gonzalez Atondo Feb 13, 2026 03:37 PM	27-00
	Perform LH Detailed Inspection of the Aileron and Spoiler Control Cables in the Main Landing Gear (MLG) Wheel Well		B0142244 - Todd Bridges Feb 13, 2026 03:58 PM	
	200	Complied with task 27-00-00-203 Detailed Inspection of the RH Aileron and Spoiler Control Cables in the Main Landing Gear (MLG) Wheel Well IAW CL-650 AMM 27-00-00-220-803. No defects noted.	B0650736 - Jesus Gonzalez Atondo Feb 13, 2026 03:37 PM	27-00
	Perform RH Detailed Inspection of the Aileron and Spoiler Control Cables in the Main Landing Gear (MLG) Wheel Well		B0142244 - Todd Bridges Feb 13, 2026 03:58 PM	
	300	Removed all tools, equipment, and unwanted materials from the work area.	B0650736 - Jesus Gonzalez Atondo Feb 13, 2026 03:37 PM	
	Remove all tools, equipment, and unwanted materials from the work area.		B0142244 - Todd Bridges Feb 13, 2026 03:58 PM	

Sequence #	0008-97	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503911	Aircraft Reg #	XA-SOL	Parent WO #	2503653

0008-97	WO #	2503911	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Landing Gear Emergency Extension Cable in the MLG Wheel Well	
Detailed Inspection of the Landing Gear Emergency Extension Cable in the MLG Wheel Well				
Task / IRN # : 32-00-01-212				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with Task Card 32-00-01-212. Perform LH Detailed Inspection of the Landing Gear Emergency Extension Cable in the MLG Wheel Well. Ref. CL650 AMM 32-34-28-220-806. No discrepancies noted at this time.	K1018275 - Emmanuel Cocoa Feb 06, 2026 03:45 PM	32-30
	Perform LH Detailed Inspection of the Landing Gear Emergency Extension Cable in the MLG Wheel Well		B1013522 - Brandon Jennings Feb 06, 2026 04:18 PM	
	200	Complied with Task Card 32-00-01-212. Perform RH Detailed Inspection of the Landing Gear Emergency Extension Cable in the MLG Wheel Well. Ref. CL650 AMM 32-34-28-220-806. No discrepancies noted at this time.	K1018275 - Emmanuel Cocoa Feb 06, 2026 03:45 PM	32-30
	Perform RH Detailed Inspection of the Landing Gear Emergency Extension Cable in the MLG Wheel Well		B1013522 - Brandon Jennings Feb 06, 2026 04:18 PM	
	300	Remove all tools equipment and un wanted materials.	K1018275 - Emmanuel Cocoa Feb 06, 2026 03:52 PM	
	Remove all tools equipment and un wanted materials.		B1013522 - Brandon Jennings Feb 06, 2026 04:18 PM	

Bombardier

Sequence #	0008-99	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503917	Aircraft Reg #	XA-SOL	Parent WO #	2503653

0008-99	WO #	2503917	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Lubrication of the Wing-to-Fuselage Attachment Links-FS513.00	
Lubrication of the Wing-to-Fuselage Attachment Links-FS513.00				
Task / IRN # : 53-20-00-233				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with TLMC task 53-20-00-233 Performed lubrication of the LH wing to fuselage attachment links (FS513.00) REF CL-650 AMM 12-20-04-640-819.	B1002512 - Brandon Warne Feb 13, 2026 02:45 PM	12-20
	Perform Lubrication of the LH Wing-to-Fuselage Attachment Links-FS513.00		B0142244 - Todd Bridges Feb 13, 2026 03:01 PM	
	200	Complied with TLMC task 53-20-00-233 Performed lubrication of the RH wing to fuselage attachment links (FS513.00) REF CL-650 AMM 12-20-04-640-819.	B1002512 - Brandon Warne Feb 13, 2026 02:45 PM	12-20
	Perform Lubrication of the RH Wing-to-Fuselage Attachment Links-FS513.00		B0142244 - Todd Bridges Feb 13, 2026 03:01 PM	
	300	Removed all tools, equipment and materials from the work area.	B1002512 - Brandon Warne Feb 13, 2026 02:45 PM	
	Remove all tools, equipment and materials from the work area.		B0142244 - Todd Bridges Feb 13, 2026 03:01 PM	

Bombardier

Sequence #	0009	Aircraft SN #	6111	MWPWO #	2498069
WO #	2498733	Aircraft Reg #	XA-SOL	Parent WO #	2498069

0009	WO #	2498733	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13276317	48 Month inspection STLMC tasks (605/650)	
48 Month inspection STLMC tasks (605/650)				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with 48 Month inspection STLMC tasks (605/650). See children work orders for work accomplished.	B0599115 - Mark Fierro Feb 08, 2026 02:34 PM	
	48 Month inspection STLMC tasks (605/650)		B0142942 - Frank Wilson Feb 08, 2026 03:51 PM	

CHILD WORK ORDER DETAILS

	WO #	Description	Corrective Action	AMENDED
0009-1	2525125	STLMC - Detailed Inspection of the Interior Cabinets, Doors and Drawers	Complied with STLMC task 25-29-65-601 detailed inspection of the Interior Cabinets, Doors, and Drawers Ref CL-650 SMM 25-24-00-220-801 No defects noted	
0009-2	2525128	STLMC - Detailed inspection of the emergency exit life line	Complied with STLMC task 25-63-65-601 detailed inspection of the emergency exit lifeline Ref CL-650 SMM 25-60-00-220-801. No defects noted.	

Sequence #	0009-1	Aircraft SN #	6111	MWPWO #	2498069
WO #	2525125	Aircraft Reg #	XA-SOL	Parent WO #	2498733

0009-1	WO #	2525125	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Complied with STLMC Task 25-29-65-601 - Detailed Inspection of the Interior Cabinets, Doors and Drawers Ref CL-650 SMM 25-24-00-220-801 No Defects Noted.	
STLMC - Detailed Inspection of the Interior Cabinets, Doors and Drawers				
Task / IRN # : 25-29-65-601				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with STLMC task 25-29-65-601 detailed inspection of the Interior Cabinets, Doors, and Drawers Ref CL-650 SMM 25-24-00-220-801 No defects noted	B0141448 - Graciela Pino Feb 03, 2026 10:44 PM B0161867 - Jeremy Kucera Feb 04, 2026 02:00 AM	25-20
	Perform a Detailed Inspection of the Interior Cabinets, Doors, and Drawers		B0161691 - Thomas Mitchell Feb 04, 2026 03:27 AM	
	200	Removed all tools, equipment and unwanted materials from the work area.	B1019231 - Ivan Bojorquez Feb 04, 2026 04:27 AM	
	Remove all tools, equipment and unwanted materials from the work area.		B0161691 - Thomas Mitchell Feb 04, 2026 04:44 AM	

FINDINGS DETAILS

Finding #	Long Description	Status	Reported By / Date	Defect Source / Disposition	Defect Type	Priority	Follow-up WO #
78745	STLMC - Detailed Inspection of the Interior Cabinets, Doors and Drawers. Galley drawer #3 latch sticks out (not flushed). Galley drawer #6 latch gets stuck. Galley drawer #8 latch sticks out (not flushed).	CLOSED	B0141448 - Graciela Pino Feb 3, 2026 4:10 PM	MAINTENANCE 300-QA002	OTHER	3	4715747-APPR

Sequence #	0009-2	Aircraft SN #	6111	MWPWO #	2498069
WO #	2525128	Aircraft Reg #	XA-SOL	Parent WO #	2498733

0009-2	WO #	2525128	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		STLMC - Detailed inspection of the emergency exit life line	
STLMC - Detailed inspection of the emergency exit life line				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with STLMC task 25-63-65-601 detailed inspection of the emergency exit lifeline Ref CL-650 SMM 25-60-00-220-801. No defects noted	B0141448 - Graciela Pino Feb 03, 2026 09:40 PM B0161867 - Jeremy Kucera Feb 04, 2026 02:12 AM	25-00
	Perform Detailed inspection of the emergency exit life line		B0161691 - Thomas Mitchell Feb 04, 2026 03:32 AM	
	200	Removed all tools, equipment and unwanted materials from the work area.	B1019231 - Ivan Bojorquez Feb 04, 2026 04:25 AM	
	Remove all tools, equipment and unwanted materials from the work area.		B0161691 - Thomas Mitchell Feb 04, 2026 04:46 AM	

Sequence #	0010	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	2503652	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

0010	**WO #**	**2503652**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #	13276330	96 month inspection	
96 month inspection				
Task / IRN # : C3500075				

Sequence #	0010	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503652	Aircraft Reg #	XA-SOL	Parent WO #	2498069

CHILD WORK ORDER DETAILS

	WO #	Description	Corrective Action	AMENDED
0010-1	2503993	Functional test of the Static Dischargers	Complied with task 23-60-00-201, Perform Functional test of the Static Dischargers, in accordance with CL-650 AMM 23-61-01-720-801. Functional test failed. See finding 79442 for details. Bond test of Static dischargers Good.	
0010-2	2503995	Detailed Inspection of the Rudder and Elevator Control Cables in the Lower Mid-Fuselage Compartment	Complied with task 27-00-00-205, Perform Detailed Inspection of the Rudder and Elevator Control Cables in the Lower Mid-Fuselage Compartment, in accordance with 650 MM 27-00-00-220-805. No defects noted at this time.	
0010-3	2503999	Detailed Inspection of the Elevator Control Cables in the Vertical Stabilizer	Complied with task 27-00-00-207, Perform Detailed Inspection of the Elevator Control Cables in the Vertical Stabilizer, in accordance with CL650 AMM 27-00-00-220-807. No defects noted.	
0010-4	2504000	Functional test of the Forward and Aft Auxiliary Tanks - Interspace and Fuel Transfer Line Shrouds	Complied with TLMC task 28-10-00-210 Performed functional test of the forward and aft aux tanks (Interspace and fuel transfer line shrouds) REF CL-650 AMM 28-12-20-720-802. Functional test good.	
0010-5	2504002	Operational Test of the Collector-Tank Check Valve		
0010-6	2504006	Functional Test of the Flight Data Recorder (FDR) Dedicated Sensors (Challenger 604 - A/C 5463 and Subs, Post SB 604-31-010) (Challenger 605 – Post SB 605-31-001) (Challenger 650 – Post SB 650-31-001)	Complied with task 31-31-00-203, Perform Functional Test of the Flight Data Recorder (FDR) Dedicated Sensors (Post SB 650-31-001), in accordance with 650 MM 31-31-01-720-801. ALL PARAMETERS WITHIN LIMITS. TEST GOOD	
0010-7	2504007	Functional Test of the Flight Data Recorder (FDR) Force Sensors	Complied with task 31-31-00-204, Perform Functional Test of the Flight Data Recorder (FDR) Force Sensors (Post SB 650-31-001), in accordance with CL-650 AMM 31-31-01-720-804. Flight deck temp. = 23 degrees. Pilot/ Copilot pitch control force = 24.0 FWD 19.0 AFT pilot/Copilot Roll control force = 7.5 CCW, 7.8 CW. Rudder pedal force LIB/LOB = 26 Rudder pedal force RIB/ROB = 26. Downloaded details and provided to CPM.	
0010-8	2504010	Detailed Inspection of the Landing-Gear Emergency-Extension Cable in the Mid-Lower Fuselage Compartment	Complied with TLMC 32-00-01-211. Performed the Detailed Inspection of the Landing-Gear Emergency-Extension Cable in the Mid-Lower Fuselage Compartment Ref. CL-650 AMM 32-34-28-220-805. No defects noted.	

Sequence #	0010	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503652	Aircraft Reg #	XA-SOL	Parent WO #	2498069

CHILD WORK ORDER DETAILS

	WO #	Description	Corrective Action	AMENDED
0010-9	2504012	Discard of the Nosewheel-Steering Control Potentiometer Coupling Setscrews, Part No. B0201102-2-220 (A/C 6194 and Subs or Post SB 650-32-007). NOTE: All 4 setscrews must be replaced. NOTE: For aircraft Post SB 650-32-007, the 96 Months task interval starts at the incorporation date of the Service Bulletin.	Deferral Code: Do Not Work Reason: Customer Request Details: Not on customer due list, per CAMP N/A	
0010-10	2504013	Detailed Inspection of the Internal Structure of the Passenger Door	Complied with task 52-11-00-203, Perform Detailed Inspection of the Internal Structure of the Passenger Door, in accordance with 650 MM 52-11-01-220-803. No defects noted at this time.	
0010-11	2504016	Detailed Inspection of the Internal Structure of the Overwing Emergency-Exit Door	Complied with task 52-21-00-203, Perform Detailed Inspection of the Internal Structure of the Overwing Emergency-Exit Door, in accordance with CL650 AMM 52-21-01-220-803. No defects noted.	
0010-12	2504018	Detailed Inspection of the Stop Fittings of the Cargo Compartment Door	Complied with TLMC 52-31-00-202, Perform Detailed Inspection of the Stop Fittings of the Cargo Compartment Door. In REF: CL-650 AMM 52-31-01-220-802. No defects noted at this time.	
0010-13	2504019	Detailed Inspection of the Internal Structure of the Cargo Compartment Door	Complied with TLMC 52-31-00-203, Perform Detailed Inspection of the Internal Structure of the Cargo Compartment Door. In REF: CL-650 AMM 52-31-01-220-803. No defects noted at this time.	
0010-14	2504021	General Visual Inspection of the Overwing Emergency-Exit Door - External	Complied with Task: 52-ZL-00-208; Perform General Visual Inspection of the Overwing Emergency-Exit Door - External. Ref: CL-650 AMM 52-21-01-210-801. See Finding #80261 For discrepancy.	
0010-15	2504024	Detailed Inspection of the Internal Fuselage, Frames and Forward Bulkhead - FS169.00 to FS202.75	Complied with task 53-10-00-201 Detailed Inspection of the Internal Fuselage, Frames and Forward Bulkhead - FS169.00 to FS202.75 REF CL650 AMM 53-10-01-220-801. No defects noted at this time.	

Sequence #	0010	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503652	Aircraft Reg #	XA-SOL	Parent WO #	2498069

CHILD WORK ORDER DETAILS

	WO #	Description	Corrective Action	AMENDED
0010-16	2504025	Detailed Inspection of the Beams, Crossmembers and Panels of the Floor Structure - FS169 to FS280	Complied with task 53-10-00-208, Perform Detailed Inspection of the Beams, Crossmembers and Panels of the Floor Structure - FS169 to FS280, in accordance with CL-650 AMM 53-10-01-220-807. No Defects Noted.	
0010-17	2504027	Detailed Inspection of the Forward Jacking Point - FS278	Complied with task 53-10-00-210, Performed Detailed Inspection of the Forward Jacking Point - FS278, in accordance with CL 650 AMM 53-10-01-220-809. No defects noted.	
0010-18	2504030	Detailed inspection of the Floor Support Structure - FS280 to FS409, as visible with floor panels installed	Complied with task 53-20-00-203 Detailed inspection of the Floor Support Structure - FS280 to FS409, as visible with floor panels installed REF CL650 AMM 53-20-01-220-803. No defects noted at this time.	
0010-19	2504031	Detailed Inspection of the Aft Face of the Frame below the Floor - FS409	Complied with task 53-20-00-216, Perform Detailed Inspection of the Aft Face of the Frame below the Floor - FS409, in accordance with CL-650 AMM 53-20-01-220-814. No Defects Noted.	
0010-20	2504033	Detailed Inspection of the Fittings of the Emergency-Exit Door	Complied with task 53-20-00-218 Detailed Inspection of the Fittings of the Emergency-Exit Door REF CL650 AMM 53-20-01-220-816. No defects noted at this time	
0010-21	2504036	Detailed Inspection of the Floor Sill Area Over the Wing Box - FS409 to FS559	Complied with task 53-20-00-220, Perform Detailed Inspection of the Floor Sill Area Over the Wing Box - FS409 to FS559, in accordance with CL-650 AMM 53-20-01-220-818. No defects noted	
0010-22	2504038	Detailed Inspection of the Wing-to-Fuselage Attachment Lug - FS424	Complied with TLMC task 53-20-00-221 Performed detailed inspection of the wing to fuselage attachment lug at FS424 REF CL-650 53-20-01-220-819. No defects noted.	
0010-23	2504039	Detailed Inspection of the Underfloor Longeron Assembly - FS409 to FS559	Complied with task 53-20-00-229, Perform Detailed Inspection of the Underfloor Longeron Assembly - FS409 to FS559, in accordance with CL-650 AMM 53-20-01-220-827. No Defects Noted	
0010-24	2504042	Detailed Inspection of the MLG Uplock Structure - FS513 to FS559 below WL73 (LH and RH)	Complied with TLMC 53-20-00-230. Performed a Detailed Inspection of the MLG Uplock Structure - FS513 to FS559 below WL73 (LH and RH) Ref. CL-650 AMM 53-20-01-220-828. No defects noted.	

Sequence #	0010	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503652	Aircraft Reg #	XA-SOL	Parent WO #	2498069

CHILD WORK ORDER DETAILS

	WO #	Description	Corrective Action	AMENDED
0010-25	2504043	Detailed Inspection of the Internal Surfaces of the Forward Auxiliary Tank	Complied with task 53-20-00-232, Perform Detailed Inspection of the Internal Surfaces of the Forward Auxiliary Tank, in accordance with CL-650 AMM 53-20-01-220-863. No Defects Noted.	
0010-26	2504045	Detailed Inspection of the Aft Face of the Pressure Bulkhead below the Floor - FS559	Complied with task 53-30-00-201, Perform Detailed Inspection of the Aft Face of the Pressure Bulkhead below the Floor - FS559, in accordance with CL-650 AMM 53-30-01-220-801. No Defects noted.	
0010-27	2504048	Detailed Inspection of the Forward Face of the Pressure Bulkhead below the Floor - FS559	Complied with task 53-30-00-202, Perform Detailed Inspection of the Forward Face of the Pressure Bulkhead below the Floor - FS559, in accordance with 650 MM 53-30-01-220-802. No defects noted at this time.	
0010-28	2504050	Detailed Inspection of the Aft Face of the Rear Pressure Bulkhead - FS621	Complied with task 53-30-00-203, Perform Detailed Inspection of the Aft Face of the Rear Pressure Bulkhead - FS621, in accordance with CL-650 AMM 53-30-01-220-803. No Defects noted.	
0010-29	2504051	Detailed Inspection of the Stabilizer Drag Angles - FS700 to FS820, and Stringer 2L and 2R	Complied with TLMC task 53-30-00-204 Performed detailed inspection of the stabilizer drag angles (FS700 to FS820 and stringer 2L and 2R REF CL-650 53-30-01-220-804. No defects noted.	
0010-30	2504054	Detailed Inspection of the Profile Plates of the Floor Support Structure - FS559 to FS621	Complied with task 53-30-00-206, Perform Detailed Inspection of the Profile Plates of the Floor Support Structure - FS559 to FS621. REF CL650 AMM 53-30-01-220-806. No defects noted.	
0010-31	2504056	Detailed Inspection of the Engine Support Beam Structure	Complied with Task Card 53-30-00-208. Peformed Detailed Inspection of the Engine Support Beam Structure. Ref. CL650 AMM 53-30-01-220-807. No discrepancies noted at this time.	
0010-32	2504057	Detailed Inspection of the Internal Aft Fuselage (Skin and Structure, FS621.00 Bulkhead Forward Face and the External Surfaces of the Aft-Auxiliary Fuel Tank)-FS559.00 to FS621.00 Below the Floor	Complied with task 53-30-00-209, Perform Detailed Inspection of the Internal Aft Fuselage (Skin and Structure, FS621.00 Bulkhead Forward Face and the External Surfaces of the Aft-Auxiliary Fuel Tank)-FS559.00 to FS621.00 Below the Floor, in accordance with CL650 AMM 53-30-01-220-852. No defects noted.	

Sequence #	0010	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503652	Aircraft Reg #	XA-SOL	Parent WO #	2498069

CHILD WORK ORDER DETAILS

	WO #	Description	Corrective Action	AMENDED
0010-33	2504060	Detailed Inspection of the Track Supports near, and the Sills and Frames around, the Cargo Compartment Door Cutout	Complied with task 53-30-00-211, Perform Detailed Inspection of the Track Supports near, and the Sills and Frames around, the Cargo Compartment Door Cutout, REF CL650 AMM 53-30-01-220-810. See finding 80544.	
0010-34	2504061	Detailed Inspection of the Fittings of the Cargo Compartment Door	Complied with TLMC 53-30-00-213, Detailed Inspection of the Fittings of the Cargo Compartment Door. In REF: CL-650 AMM 53-30-01-220-812. No defects noted at this time.	
0010-35	2504064	Detailed Inspection of the Forward Face of the Frame - FS755	Complied with task 53-30-00-216 Detailed Inspection of the Forward Face of the Frame - FS755 REF CL650 AMM 53-30-01-220-816. No defects noted at this time	
0010-36	2504066	Detailed Inspection of the External Side Skin Panels of the Fuselage - FS559 to FS755 and Stringer 6L to 20L and 6R to 20R Covered by Pylon	Complied with TLMC 53-30-00-219, Perform Detailed Inspection of the External Side Skin Panels of the Fuselage - FS559 to FS755 and Stringer 6L to 20L and 6R to 20R Covered by Pylon. In REF: CL-650 AMM 53-30-01-220-819. No defects noted at this time.	
0010-37	2504068	Detailed Inspection of the Internal Skin and Structure of the Aft Auxiliary Tank	Complied with task 53-30-00-222, Perform Detailed Inspection of the Internal Skin and Structure of the Aft Auxiliary Tank. REF CL650 AMM 53-30-01-220-850. No defects noted.	
0010-38	2504069	Special Detailed Inspection of the Skin and Fuselage Structure - FS718.00 to FS755.00	Complied with task 53-30-00-223 Performed special detailed inspection of the fuselage skin panels from FS718.00 to FS755.00, between STR7 and STR18. IAW CL650 NDT manual part 6, ET-53-30-012. No defects noted.	
0010-39	2504072	Detailed Inspection of the Aft Face of the Frame - VS67.5%	Complied with task 53-43-00-202 Detailed Inspection of the Aft Face of the Frame - VS67.50%, REF CL650 AMM 53-43-02-220-801. No defects noted at this time	
0010-40	2504073	Detailed Inspection of the Internal Skin and Fuselage Structure - FS755 to VS67.5%	Complied with task 53-43-00-203 Detailed Inspection of the Internal Skin and Fuselage Structure - FS755 to VS67.50% REF CL650 AMM 53-43-02-220-802. No defects noted at this time.	
0010-41	2504076	Detailed Inspection of the Internal Skin and Structure of the Tail Tank	Complied with task 53-50-00-201, Perform Detailed Inspection of the Internal Skin and Structure of the Tail Tank, in accordance with CL-650 AMM 53-66-01-220-801. No defects noted.	

Sequence #	0010	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503652	Aircraft Reg #	XA-SOL	Parent WO #	2498069

CHILD WORK ORDER DETAILS

	WO #	Description	Corrective Action	AMENDED
0010-42	2504078	Detailed Inspection of the Floor Structure of the Tail Tank	Complied with task 53-50-00-202, Perform Detailed Inspection of the Floor Structure of the Tail Tank, in accordance with CL-650 AMM 53-66-01-220-802. No Defects Noted.	
0010-43	2504079	Detailed Inspection of the Forward Face of the Fuel Tail Tank Forward Bulkhead	Complied with TLMC task 53-50-00-203 Performed detailed inspection of the forward face of the fuel tail tank forward bulkhead REF CL-650 AMM 53-66-01-220-803. No defecst noted.	
0010-44	2504080	Detailed Inspection of the Aft Face of the Tail Tank Aft Bulkhead	Complied with task 53-50-00-204, Perform Detailed Inspection of the Aft Face of the Tail Tank Aft Bulkhead, in accordance with CL-650 AMM 53-66-01-220-804. No Defects noted.	
0010-45	2504084	General Visual Inspection of the Nose Compartment - Lower External	Complied with task 53-ZL-00-203 General Visual Inspection of the Nose Compartment - Lower External REF CL650 AMM 53-10-01-210-803. No defects noted	
0010-46	2504085	General Visual Inspection of the Nose Compartment - Lower Internal LH	Complied with task 53-ZL-00-204 General Visual Inspection of the Nose Compartment - Lower Internal LH REF CL650 AMM 53-10-01-210-804. Defects noted on finding #80009	
0010-47	2504087	General Visual Inspection of the Forward Avionics and Flight Controls Compartment - External	Complied with task 53-ZL-00-207 General Visual Inspection of the Forward Avionics and Flight Controls Compartment - External REF CL650 AMM 53-10-01-210-807. No defects noted at this time.	
0010-48	2504091	General Visual Inspection of the Lower Surface of the Pressure-Floor from FS409 to FS559	Complied with task 53-ZL-00-213, General Visual Inspection of the lower surface of the pressure-floor from FS409 to FS559. REF:CL-650AMM 53-20-01-210-804, no defects noted	
0010-49	2504092	General Visual Inspection of the Mid-Fuselage between the Pressure Floor and the Cabin Floor - Lower Internal	Complied with task 53-ZL-00-215, Perform General Visual Inspection of the Mid-Fuselage between the Pressure Floor and the Cabin Floor - Lower Internal. REF CL650 AMM 53-20-01-210-806. No defects noted.	
0010-50	2504093	General Visual Inspection of the Aft Compartment and Aft Wing-to-Fuselage Fairing - External	Complied with task 53-ZL-00-216 General Visual Inspection of the Aft Compartment and Aft Wing-to-Fuselage Fairing - External REF CL650 AMM 53-30-01-210-801. No defects noted at this time	

Sequence #	0010	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503652	Aircraft Reg #	XA-SOL	Parent WO #	2498069

CHILD WORK ORDER DETAILS

	WO #	Description	Corrective Action	AMENDED
0010-51	2504097	General Visual Inspection of the Forward Equipment Compartment - External	Complied with task 53-ZL-00-218 General Visual Inspection of the Forward Equipment Compartment - External REF CL650 AMM 53-10-01-210-809. No defects noted at this time	
0010-52	2504098	General Visual Inspection of the Passenger Compartment - External	Complied with task 53-ZL-00-222 General Visual Inspection of the Passenger Compartment - External REF CL650 AMM 53-20-01-210-807. No defects noted at this time.	
0010-53	2504101	General Visual Inspection of the Cargo Compartment - External	Complied with task 53-ZL-00-224, Perform General Visual Inspection of the Cargo Compartment - External, in accordance with CL-650 AMM 53-30-01-210-803. No defects noted.	
0010-54	2504103	General Visual Inspection of the Cargo Compartment - Internal without Removal of the Headliner	Complied with task 53-ZL-00-225 General Visual Inspection of the Cargo Compartment - Internal without Removal of the Headliner REF CL650 AMM 53-30-01-210-807. No defects noted at this time.	
0010-55	2504104	General Visual Inspection of the Fuselage/Stabilizer Section - External	Complied with task 53-ZL-00-229, Perform General Visual Inspection of the Fuselage/Stabilizer Section - External, in accordance with CL650 AMM 53-43-01-210-801. No defects noted.	
0010-56	2504107	General Visual Inspection of the Mid-Fuselage Compartment - Lower Internal (FS559.0 to FS621.0)	Complied with task 53-ZL-00-233 General Visual Inspection of the Mid-Fuselage Compartment - Lower Internal (FS559.0 to FS621.0) REF CL650 AMM 53-20-01-210-809. No defects noted at this time.	
0010-57	2504109	General Visual Inspection of the Pylon Trailing Edge - Internal LH	Complied with task 54-ZL-00-207, Perform General Visual Inspection of the Pylon Trailing Edge - Internal LH, REF: 650 AMM 54-62-04-210-801. No defects noted.	
0010-58	2504110	General Visual Inspection of the Pylon Trailing Edge - Internal RH	Complied with task 54-ZL-00-208, Perform General Visual Inspection of the Pylon Trailing Edge - Internal RH, REF: Challenger 650 AMM 54-62-04-210-801. No defects noted.	
0010-59	2504113	Detailed Inspection of the Upper Face of the Top Canted Rib and the Rib Fittings of the Vertical Stabilizer and the Attachment Fittings and Skin Splices of the Horizontal Stabilizer	Complied with TLMC task 55-10-00-201 Performed Detailed Inspection of the Upper Face of the Top Canted Rib and the Rib Fittings of the Vertical Stabilizer and the Attachment Fittings and Skin Splices of the Horizontal Stabilizer REF CL-650 AMM 55-00-00-220-803. No defects noted.	

Sequence #	0010	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503652	Aircraft Reg #	XA-SOL	Parent WO #	2498069

CHILD WORK ORDER DETAILS

	WO #	Description	Corrective Action	AMENDED
0010-60	2504115	Detailed Inspection of the Front Spar of the Horizontal Stabilizer	Complied with task 55-10-00-202, detailed inspection of the front spar of the horizontal stabilizer. Ref:CL-650 AMM 55-10-01-220-802, no defects noted	
0010-61	2504117	Detailed Inspection of the Horizontal Stabilizer (internal skins, structure, rear spar and hinge fittings) and the Elevator (forward face of the front spar, hinge fittings and bolts)	Complied with TLMC task 55-10-00-203 Performed Detailed Inspection of the Horizontal Stabilizer (internal skins, structure, rear spar and hinge fittings) and the Elevator (forward face of the front spar, hinge fittings and bolts) REF CL-650 AMM 55-00-00-220-801. No defects noted.	
0010-62	2504119	Detailed Inspection of the External Surfaces of the Elevator	Complied with Task 55-20-00-202. Performed Detailed Inspection of the External Surfaces of the Elevator, in reference to CL-650 AMM 55-20-01-220-802. See findings 80234 and 80235 for details.	
0010-63	2504120	Detailed Inspection of the Vertical-Stabilizer (Forward Side of the Front Spar, Attachment Fittings and the Splice Strap)	Complied with task 55-30-00-201, Perform Detailed Inspection of the Vertical-Stabilizer (Forward Side of the Front Spar, Attachment Fittings and the Splice Strap), in accordance with CL650 AMM 55-30-01-220-812. No defects noted.	
0010-64	2504123	Detailed Inspection of the Internal Structure of the Vertical Stabilizer	Complied with TLMC task 55-30-00-206 Performed detailed inspection of the internal structure of the vertical stabilizer REF CL-650 AMM 55-30-01-220-806. No defects noted.	
0010-65	2504125	Detailed Inspection of the External Surfaces of the Rudder	Complied with Task 55-40-00-201. Performed Detailed Inspection of the External Surfaces of the Rudder, in reference to CL-650 AMM 55-40-01-220-801. See finding 79762 for details.	
0010-66	2504126	Detailed Inspection of the Rudder (Forward Face of the Front Spar and Hinge Bolts) and the Vertical Stabilizer (Aft Face of the Rear Spar and Rudder Hinge Fittings)	Complied with TLMC task 55-40-00-202 Performed Detailed Inspection of the Rudder (Forward Face of the Front Spar and Hinge Bolts) and the Vertical Stabilizer (Aft Face of the Rear Spar and Rudder Hinge Fittings) REF CL-650 AMM 55-00-00-220-802. No defects noted.	
0010-67	2504129	General Visual Inspection of the Ram Air Intake and Dorsal Fairing - Internal	Complied with Task No. 55-ZL-00-202. Performed a GVI of the Ram Air Intake and Dorsal Fairing (INTERNAL). No defects noted. Ref: CL650 AMM 55-30-01-210-802	

Sequence #	0010	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503652	Aircraft Reg #	XA-SOL	Parent WO #	2498069

CHILD WORK ORDER DETAILS

	WO #	Description	Corrective Action	AMENDED
0010-68	2504130	General Visual Inspection of the Leading Edge of the Vertical Stabilizer - Internal	Complied with task 55-ZL-00-203, Perform General Visual Inspection of the Leading Edge of the Vertical Stabilizer - Internal, in accordance with CL650 AMM 55-30-01-210-803. No defects noted.	
0010-69	2504132	General Visual Inspection of the Vertical Stabilizer - Internal	Complied with task 55-ZL-00-204 General Visual Inspection of the Vertical Stabilizer - Internal REF CL650 AMM 55-30-01-210-804. No defects noted at this time	
0010-70	2504135	General Visual Inspection of the Tip of the Vertical Stabilizer - Internal	Complied with task 55-ZL-00-205 General Visual Inspection of the Tip of the Vertical Stabilizer - Internal REF CL650 AMM 55-30-01-210-805. No defects noted at this time.	
0010-71	2504136	General Visual Inspection of the Horizontal Stabilizer - External LH	Complied with Task No. 55-ZL-00-206. Performed a GVI of the Horizontal Stabilizer (LH, EXTERNAL). No defects noted. Ref: CL650 AMM 55-10-01-210-801	
0010-72	2504139	General Visual Inspection of the Horizontal Stabilizer - External RH	Complied with Task No. 55-ZL-00-207. Performed a GVI of the Horizontal Stabilizer (RH, EXTERNAL). No defects noted. Ref: CL650 AMM 55-10-01-210-801	
0010-73	2504141	General Visual Inspection of the Leading Edge of the Horizontal Stabilizer - Internal LH	Complied with Task 55-ZL-00-208. Performed General Visual Inspection of the Leading Edge of the Horizontal Stabilizer - Internal LH, in reference to CL-650 AMM 55-10-01-210-803. No defects were noted at this time.	
0010-74	2504142	General Visual Inspection of the Leading Edge of the Horizontal Stabilizer - Internal RH	Complied with Task 55-ZL-00-209. Performed General Visual Inspection of the Leading Edge of the Horizontal Stabilizer - Internal RH, in reference to CL-650 AMM 55-10-01-210-803. No defects were noted at this time.	
0010-75	2504144	General Visual Inspection of the Horizontal Stabilizer - Internal LH	Complied with Task No. 55-ZL-00-210. Performed a GVI of the Horizontal Stabilizer (LH, INTERNAL). No defects noted. Ref: CL650 AMM 55-10-01-210-802	
0010-76	2504147	General Visual Inspection of the Horizontal Stabilizer - Internal RH	Complied with Task No. 55-ZL-00-211. Performed a GVI of the Horizontal Stabilizer (RH, INTERNAL). No defects noted. Ref: CL650 AMM 55-10-01-210-802	

Sequence #	0010	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503652	Aircraft Reg #	XA-SOL	Parent WO #	2498069

CHILD WORK ORDER DETAILS

	WO #	Description	Corrective Action	AMENDED
0010-77	2504148	Detailed Inspection of the External Center Wing (Front Spar and the Bayonet Fitting) - LWS50.00 to RWS50.00	Complied with TLMC task 57-10-00-201 Performed detailed inspection of the external center wing (Front spar and the bayonet fitting) from LWS50.00 to RWS50.00 REF CL-650 AMM 57-10-00-220-866. No defects noted.	
0010-78	2504150	General Visual Inspection of the Front Spar of the Wing Center Section - External	Complied with task 57-ZL-00-203 General Visual Inspection of the Front Spar of the Wing Center Section - External REF CL650 AMM 57-10-00-210-807. No defects noted at this time	
0010-79	2504153	General Visual Inspection of the Wing Center Section - Internal LH	Complied with TLMC task 57-ZL-00-204 Performed general visual inspection of the LH center section (Internal). REF CL-650 AMM 57-10-00-210-802. No defects noted.	
0010-80	2504154	General Visual Inspection of the Wing Center Section - Internal RH	Complied with TLMC task 57-ZL-00-205 Performed general visual inspection of the RH wing center section (Internal) REF CL-650 AMM 57-10-00-210-802. No defects noted.	
0010-81	2504155	General Visual Inspection of the Inboard Leading Edge of the Wing - Internal LH	Complied with task 57-ZL-00-208, Perform General Visual Inspection of the Inboard Leading Edge of the Wing - Internal LH, in accordance with 650 MM 57-40-00-210-802. No defects noted at this time.	
0010-82	2504159	General Visual Inspection of the Inboard Leading Edge of the Wing - Internal RH	Complied with task 57-ZL-00-209, Perform General Visual Inspection of the Inboard Leading Edge of the Wing - Internal RH, in accordance with 650 MM 57-40-00-210-802. No defects noted at this time.	
0010-83	2504160	General Visual Inspection of the Outboard Leading Edge of the Wing - Internal LH	Complied with task 57-ZL-00-212, Perform General Visual Inspection of the Outboard Leading Edge of the Wing - Internal LH, in accordance with 650 MM 57-40-00-210-804. No defects noted at this time.	
0010-84	2504161	General Visual Inspection of the Outboard Leading Edge of the Wing - Internal RH	Complied with task 57-ZL-00-213, Perform General Visual Inspection of the Outboard Leading Edge of the Wing - Internal RH, in accordance with 650 MM 57-40-00-210-804. No defects noted at this time. Removed all tools, equipment and unwanted materials from the work area.	
0010-85	2504165	General Visual Inspection of the Wing from WS45 to WS148 - Internal LH	Complied with TLMC task 57-ZL-00-216 Performed general visual inspection of the LH wing from WS45 to WS148 (Internal) REF CL-650 AMM 57-10-00-210-804. No defects noted.	

Sequence #	0010	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503652	Aircraft Reg #	XA-SOL	Parent WO #	2498069

CHILD WORK ORDER DETAILS

	WO #	Description	Corrective Action	AMENDED
0010-86	2504166	General Visual Inspection of the Wing from WS45 to WS148 - Internal RH	Complied with TLMC task 57-ZL-00-217 Performed general visual inspection of the RH wing from WS45 to WS148 (Internal) REF CL-650 AMM 57-10-00-210-804. No defects noted.	
0010-87	2504167	General Visual Inspection of the Wing from WS148 to WS353 - Internal LH	Complied with TLMC task 57-ZL-00-220 Performed general visual inspection of the LH wing from WS148 to WS353 (Internal) REF CL-650 AMM 57-10-00-210-806. No defects noted.	
0010-88	2504171	General Visual Inspection of the Wing from WS148 to WS353 - Internal RH	Complied with TLMC task 57-ZL-00-221 Performed general visual inspection of the RH wing from WS148 to WS 353 (Internal) REF CL-650 AMM 57-10-00-210-806. No defects noted.	
0010-89	2504172	General Visual Inspection of the Aileron Shroud - Internal LH	Complied with task 57-ZL-00-234, Perform General Visual Inspection of the Aileron Shroud - Internal LH, in accordance with CL-650 AMM 57-60-01-210-802. No Defects Noted.	
0010-90	2504173	General Visual Inspection of the Aileron Shroud - Internal RH	Complied with task 57-ZL-00-235, Perform General Visual Inspection of the Aileron Shroud - Internal RH, in accordance with CL-650 AMM 57-60-01-210-802. No Defects Noted.	
0010-91	2504177	Install Main Landing Gear (MLG) for Maintenance		
0010-92	2504178	Install Nose Landing Gear (NLG) for Maintenance		
0010-93	2504179	Remove Main Landing Gear (MLG) for Maintenance	See Child WO: 4799084 & 4799096 for Side Brace Fitting Inspections.	
0010-94	2504185	Remove Nose Landing Gear (NLG) for Maintenance	Removed the Nose Landing Gear/Strut Assembly as required. (PN: 604-85002-41 / SN: S0000W9HC). See WO: 2504178 for Installation. Ref: CL650 AMM 32-21-00-000-801	
0010-95	2504186	Detailed Inspection of the Lightning/High Intensity Radiated Field L/ HIRF Protection in the Flight Compartment	Complied with task 22-12-00-201, Perform Detailed Inspection of the Lightning/High Intensity Radiated Field L/ HIRF Protection in the Flight Compartment, in accordance with CL 650 AMM 22-12-22-220-801. No defects noted.	

Sequence #	0010	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503652	Aircraft Reg #	XA-SOL	Parent WO #	2498069

CHILD WORK ORDER DETAILS

	WO #	Description	Corrective Action	AMENDED
0010-96	2504189	Detailed Inspection of the Lightning/High Intensity Radiated Field L/HIRF Protection of the Vertical Stabilizer - Internal	Complied with TLMC Task 22-12-00-203, Detailed Inspection of the Lightning/High Intensity Radiated Field L/HIRF Protection of the Vertical Stabilizer - Internal. REF CL-650 AMM 22-12-22-220-803. No Defects Noted. See Open Access Work Order 3154420 and Close Access Work Order 3154422 for vertical stab panels removal and installation.	
0010-97	2504191	Detailed Inspection of the Lightning/High Intensity Radiated Field L/HIRF Protection in the Fuselage between FS409.00 and FS621.00, below WL73.5 - Internal	Complied with TLMC Task 22-12-00-205, Detailed Inspection of the Lightning/High Intensity Radiated Field L/HIRF Protection in the Fuselage between FS409.00 and FS621.00, below WL73.5 - Internal. REF CL-650 AMM 22-12-22-220-805. No Defects Noted. See Open Access Work Order 3154420 and Close Access Work Order 3154422 for floor panel removal and installation.	
0010-98	2504193	Detailed Inspection of the Lightning/High Intensity Radiated Field (L/HIRF) Protection on the Avionics Racks	Complied with TLMC Task 22-12-00-206, Detail Inspection of the Lightning/High Intensity Radiated Field (L/HIRF) Protection on the Avionics Racks. REF CL-650 AMM 22-12-22-220-806. No Defects Noted.	
0010-99	2504194	Special Detailed Inspection (Borescope) of the Lightning/High Intensity Radiated Field (L/HIRF) Protection on the #2 VHF Antenna	Complied with task 22-12-00-207 special detailed inspection (Borescope) of the lightning/ high intensity radiated field (L/HIRF) protection on the VHF #2 antenna IAW CL-650 AMM 22-12-22-280-801 No defects noted	
0010-100	2504197	Detailed Inspection of the Lightning/High Intensity Radiated Field L/HIRF Protection on the Upper FS621 Bulkhead	Complied with TLMC Task 22-12-00-209 Detailed Inspection of the Lightning/High Intensity Radiated Field L/HIRF Protection on the Upper FS621 Bulkhead IAW CL650 AMM Task 22-12-22-220-809. No defects noted. Removed all tools, equipment, and unwanted materials from the work area.	
0010-101	2504199	Detailed Inspection of the Lightning/High Intensity Radiated Field L/HIRF Protection on the Wing Disconnects - External	Complied with TLMC Task 22-12-00-210 Detailed Inspection of the Lightning/High Intensity Radiated Field L/HIRF Protection on the Wing Disconnects - External IAW CL650 AMM Task 22-12-22-220-810. Finding created for Broken back shell at connector P8CG finding # 79996.	
0010-102	2504200	Detailed Inspection of the Portable Fire−Extinguisher Container	Deferral Code: Do Not Work Reason: Customer Request Details: Not on customer due list, per CAMP due 1/11/2031	

Sequence #	0010	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503652	Aircraft Reg #	XA-SOL	Parent WO #	2498069

CHILD WORK ORDER DETAILS

	WO #	Description	Corrective Action	AMENDED
0010-103	2504203	Detailed Inspection of the Aileron, Rudder, Elevator and Spoiler Control Cables in the Mid-Lower Fuselage	Complied with task 27-00-00-204, Perform Detailed Inspection of the Aileron, Rudder, Elevator and Spoiler Control Cables in the Mid-Lower Fuselage, in accordance with CL650 AMM 27-00-00-220-804. No defects noted.	
0010-104	2504205	Functional Test of the Vent Line Shrouds	Complied with TLMC task 28-10-00-207 Performed functional test of the vent line shrouds REF 28-14-22-720-801. Functional test good.	
0010-105	2504206	Functional Test of the Motive-Flow Line Shrouds	Complied with TLMC task 28-10-00-208 Performed LH/RH functional test of the motive-flow line shrouds REF CL-650 AMM 28-22-10-720-801. Functional test good.	
0010-106	2504210	Functional Test of the Fuel-Feed Line Shrouds	Complied with TLMC task 28-10-00-209 Performed LH/RH functional test of the fuel-feed line shrouds REF CL-650 28-21-16-720-801. Functional test good.	
0010-107	2504213	Detailed Inspection of the Main Landing Gear (MLG) Assembly		
0010-108	2504215	Detailed Inspection of the Hinge and Fasteners of the Main Landing-Gear Door	Complied with TLMC 32-12-00-201. Performed the Detailed Inspection of the Hinge and Fasteners of the LH & RH Main Landing-Gear Door Ref. CL-650 AMM 32-12-01-220-801. No defects noted.	
0010-109	2504218	Detailed Inspection of the Internal Fuselage (Skins and Structure) - FS202.75 to FS280.00 Below the Floor	Complied with task 53-10-00-203, Perform Detailed Inspection of the Internal Fuselage (Skins and Structure) - FS202.75 to FS280.00 Below the Floor, in accordance with CL-650 AMM 53-10-01-220-803. No Defects Noted.	
0010-110	2504220	Detailed Inspection of the Sills, Frames and External Skin around the Passenger Door Cutout	Complied with TLMC task 53-20-00-201 Performed detailed inspection of the sills, frames and external skin around the passenger door cutout REF CL-650 AMM 53-20-01-220-801. No defects noted.	
0010-111	2504222	Detailed Inspection of the Internal Mid-Fuselage (Skin and Structure, FS409.00 Bulkhead Forward Face and the External Surfaces of the Forward-Auxiliary Fuel Tank) - FS280.00 to FS409.00 below the floor	Complied with task 53-20-00-207, Perform Detailed Inspection of the Internal Mid-Fuselage (Skin and Structure, FS409.00 Bulkhead Forward Face and the External Surfaces of the Forward-Auxiliary Fuel Tank) - FS280.00 to FS409.00 below the floor, in accordance with CL-650 AMM 53-20-01-220-861. No defects noted	

Sequence #	0010	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503652	Aircraft Reg #	XA-SOL	Parent WO #	2498069

CHILD WORK ORDER DETAILS

	WO #	Description	Corrective Action	AMENDED
0010-112	2504224	Detailed Inspection of Wing-to-Fuselage Attachment Link - FS513	Complied with TLMC task 53-10-00-224 Performed LH/RH detailed inspection of the wing to fuselage attachment link (FS513) REF CL-650 AMM 53-20-01-220-822. No defects noted.	
0010-113	2504226	Detailed Inspection of the Wing-to-Floor Tie Beam - FS460	Complied with TLMC task 53-20-00-225 Performed LH/RH detailed inspection of the wing to floor tie beam (FS460) REF CL-650 53-20-01-220-823. No defects noted.	
0010-114	2504230	Detailed Inspection of the Upper Surface of the Pressure Floor Skin Panel - FS409 to FS559 and BL36L to BL36R	Complied with task 53-20-00-226, Perform Detailed Inspection of the Upper Surface of the Pressure Floor Skin Panel - FS409 to FS559 and BL36L to BL36R, in accordance with CL-650 AMM 53-20-01-220-824. With Defects Noted see findings for details.	
0010-115	2504232	Detailed Inspection of the Lower Surface of the Pressure Floor Skin Panel - FS409 to FS559 and BL36L to BL36R	Complied with task 53-20-00-227, Perform Detailed Inspection of the Lower Surface of the Pressure Floor Skin Panel - FS409 to FS559 and BL36L to BL36R, in accordance with CL-650 AMM 53-20-01-220-825. No Defects Noted.	
0010-116	2504233	Detailed Inspection of the Pressure Floor Support Beams - FS409 to FS559, BL0.0, BL9, BL18.6, BL27 and BL35.4	Complied with task 53-20-00-228,Detailed Inspection of the Pressure Floor Support Beams - FS409 to FS559, BL0.0, BL9, BL18.6, BL27 and BL35.4. Ref: CL-650 AMM 53-20-01-220-826. One defect noted, see finding: 80368	
0010-117	2504236	Detailed Inspection of the Forward Engine-Mount Spar Assembly	Complied with Task Card 54-50-00-201. Perform Detailed Inspection of LH and RH Forward Engine-Mount Spar Assembly. Ref. CL650 AMM 54-50-01-220-801.	
0010-118	2504238	Detailed Inspection of the Internal Structure of the Pylon	Complied with TLMC 54-50-00-203. Performed a Detailed Inspection of Internal Structure of the Pylon Ref. CL-650 AMM 54-50-01-220-803. No defects noted.	
0010-119	2504240	Detailed Inspection of the Aft Engine-Mount Support Structure	Complied with Task Card 54-50-00-204. Perform Detailed Inspection of LH and RH Aft Engine-Mount Support Structure. Ref. CL650 AMM 54-50-01-220-804. No discrepancies noted at this time.	
0010-120	2504246	Detailed Inspection of the Internal Center Wing (Spars, Rib and Wing Plank Surfaces) - LWS45.00 to RWS45.00	Complied with task 57-10-00-202, Perform LH & RH Detailed Inspection of the Internal Center Wing (Spars, Rib and Wing Plank Surfaces) - LWS4500 to RWS4500, in accordance with CL-650 AMM 57-10-00-220-864. No Defects Noted.	

Sequence #	0010	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503652	Aircraft Reg #	XA-SOL	Parent WO #	2498069

CHILD WORK ORDER DETAILS

	WO #	Description	Corrective Action	AMENDED
0010-121	2504247	Detailed Inspection of the External Center Wing (Rear Spar and Upper Wing Plank, MLG Side Brace Fitting and Rear Spar Bayonet-Fitting) - LWS48.00 to RWS48.00	Complied with task 57-10-00-204, Perform LH & RH Detailed Inspection of the External Center Wing (Rear Spar and Upper Wing Plank, MLG Side Brace Fitting and Rear Spar Bayonet-Fitting) - LWS48.00 to RWS48.00, in accordance with CL-650 AMM 57-10-00-220-865. No Defects Noted.	
0010-122	2504251	Detailed Inspection of the Forward Face of the Front Spar of the Wing - WS50 to WS353	Complied with task 57-10-00-208, Performed LH & RH Detailed Inspection of the Forward Face of the Front Spar of the wing - WS50 to WS353 In accordance with CL-650 AMM 57-10-00-220-808 No Defects Noted	
0010-123	2504255	Detailed Inspection of the Internal Wing (Front Spar, Rear Spar, Wing Planks, Structure and the MLG Mounting Fittings) - WS45.00 to Canted WS314.50	Complied with task 57-10-00-209 LH & RH Detailed Inspection of the Internal Wing (Front Spar, Rear Spar, Wing Planks, Structure and the MLG Mounting Fittings) - WS4500 to Canted WS31450 REF CL650 AMM 57-10-00-220-867. No defects noted at this time.	
0010-124	2504256	Detailed Inspection of the Internal Skin and the Wing Structure - Canted WS314.5 to WS353	Complied with task 57-10-00-213, Perform LH & RH Detailed Inspection of the Internal Skin and the Wing Structure - Canted WS3145 to WS353, in accordance with CL-650 AMM 57-10-00-220-813. No Defects Noted.	
0010-125	2504261	Detailed Inspection of the Wing-to-Fuselage Attachment Fittings and Bolts - FS424.00, FS473.15 and FS513.00	Complied with TLMC 57-10-00-224 Performed LH/RH detailed inspection of the wing to fuselage attachment fittings and bolts (FS424.00, FS473.15 and FS513.00 REF CL-650 AMM 57-10-00-220-869. No defects noted.	
0010-126	2504264	Detailed Inspection of the Attachment Fittings of the Flap Hinge Box of the Inboard Flap - WS76.5 and WS127.25	Complied with task 57-10-00-227 Detailed Inspection of the Attachment Fittings of the Flap Hinge Box of the Inboard Flap - WS76.5 and WS127.25 IAW CL-650 AMM 57-10-00-220-827. No defects noted.	
0010-127	2504267	Detailed Inspection of the Attachment Fittings of the Flap Hinge Box of the Outboard Flap - WS178, WS220 and WS264	Complied with task 57-10-00-228, detailed inspection of the attachment fittings of the flap hinge box of the outboard flap - WS178, WS220 and WS 264 IAW CL-650 AMM 57-10-00-220-828. No defects found.	
0010-128	2504270	Detailed Inspection of the Aileron (External Surfaces, Wing-to-Aileron Hinge Fittings, Hinge Bolts and Anti-Float Torsion Bar)	Complied with task 57-10-00-229 Detailed Inspection of the Aileron (External Surfaces, Wing-to-Aileron Hinge Fittings, Hinge Bolts and Anti-Float Torsion Bar) IAW CL-650 AMM 57-60-01-220-808. No defects noted.	

Sequence #	0010	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503652	Aircraft Reg #	XA-SOL	Parent WO #	2498069

CHILD WORK ORDER DETAILS

	WO #	Description	Corrective Action	AMENDED
0010-129	2504273	Detailed Inspection of the Hinge Fittings for the Ground Spoiler	Complied with Task No. 57-10-00-230. Performed a Detailed Inspection of the Hinge Fittings for both the LH and RH Ground Spoilers. See Finding No. 79862 Ref: CL650 AMM 57-10-00-220-830	
0010-130	2504276	Detailed Inspection of the Hinge Fittings for the Flight Spoiler	Complied with Task No. 57-10-00-231. Performed a Detailed Inspection of the Hinge Fittings for both the LH and RH Flight Spoilers. No defects noted. Ref: CL650 AMM 57-10-00-220-831.	
0010-131	2504279	Detailed Inspection of the Skin, Spars, Attachment Fittings, and Internal Structure of the Winglet	Complied with task 57-30-00-201, Perform LH and RH Detailed Inspection of the Skin, Spars, Attachment Fittings, and Internal Structure of the Winglet, in accordance with CL650 AMM 57-30-00-220-801. No defects noted	
0010-132	2504282	Detailed Inspection of the Inboard Flap (External Skins, Attachment Lugs and Hinge Arms)	Complied with task 57-50-00-202 Detailed Inspection of the Inboard Flap (External Skins, Attachment Lugs and Hinge Arms) IAW CL-650 AMM 57-50-01-220-818. No defects noted.	
0010-133	2504283	Detailed Inspection of the Outboard Flap (External Skins, Attachment Lugs and Hinge Arms)	Complied with task 57-50-00-207 Detailed Inspection of the Outboard Flap (External Skins, Attachment Lugs and Hinge Arms) IAW CL-650 AMM 57-50-01-220-819. No defects noted.	
0010-134	2504288	Detailed Inspection of the Flap Hinge Boxes of the Inboard Flap	Complied with task 57-50-00-210, Perform LH & RH Detailed Inspection of the Flap Hinge Boxes of the Inboard Flap, REF CL650 AMM 57-50-01-220-810. No defects noted.	
0010-135	2504291	Detailed Inspection of the Flap Hinge Boxes of the Outboard Flap	Complied with task 57-50-00-211, Performed LH and RH Detailed Inspection of the Flap Hinge Boxes of the Outboard Flap, in accordance with CL 650 AMM 57-50-01-220-811. See findings 79605 and 79606 for defects.	
0010-136	2504292	Detailed Inspection of the Hinge Bolts of the Ground Spoiler	Complied with Task No. 57-70-00-205. Performed Detailed Inspection of the Hinge Bolts of the Ground Spoiler Ref CL-650 AMM 57-70-01-220-805. No defects noted.	

Sequence #	0010	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503652	Aircraft Reg #	XA-SOL	Parent WO #	2498069

CHILD WORK ORDER DETAILS

	WO #	Description	Corrective Action	AMENDED
0010-137	2504297	Detailed Inspection of the Hinge Bolts of the Flight Spoiler	Complied with Task No.57-70-00-206. Performed a Detailed Inspection of the LH Flight Spoiler Bolts (IB, OB, MID-IB). Installed NEW hardware as required. No defects noted. Continue with the Detailed Inspection of the MID-OB Flight Spoiler bolt. Ref: CL650 AMM 57-70-01-220-804 Steps 4.A through G.7(c).	
0010-138	2504300	Detailed Inspection of the Hinge Fittings of the Core Cowl Door	Complied with Task No. 71-12-00-205. Performed a Detailed Inspection of the Hinge Fittings of both the LH and RH Core Cowl Doors. No defects noted. Ref: CL650 AMM 71-12-01-220-801.	
0010-139	2504301	Detailed Inspection of the Service Pylon Casting and Support Rails	Complied with TLMC task 71-13-00-202 Performed Detailed inspection of the LH/RH service pylon casting and support rails REF CL-650 AMM 71-10-00-220-801. No defects noted.	
0010-140	2504306	Detailed Inspection of the Forward Engine Mount Yoke and Link Assembly	Complied with Task Card 71-20-00-202. Perform LH and RH Detailed Inspection of the Forward Engine Mount Yoke and Link Assembly. Ref. CL650 AMM 71-21-01-220-803. No discrepancies noted at this time.	
0010-141	2504309	Detailed Inspection of the Aft Engine Mount Assembly	Complied with task card 71-20-00-203. Perform LH and RH Detailed Inspection of the Aft Engine Mount Assembly. Ref. CL650 AMM 71-22-01-220-801. No discrepancies noted at this time.	
0010-142	2504310	Detailed Inspection of the Main Pylon Tracks of the Thrust-Reverser	Complied with task 78-30-00-206 LH & RH REF CL650 AMM 78-34-07-220-802. No defects noted at this time	
0010-143	2504315	Detailed Inspection of the Thrust-Reverser Main Tracks	Complied with task 78-30-00-207 LH & RH Detailed Inspection of the Thrust-Reverser Main Tracks REF CL650 AMM 78-34-04-220-801. No defects noted at this time.	
0010-144	2504318	Detailed Inspection of the Attachment Fittings for the Thrust-Reverser Main Tracks	Complied with task 78-30-00-208 LH & RH Detailed Inspection of the Attachment Fittings for the Thrust-Reverser Main Tracks REF CL650 AMM 78-34-04-220-802. No defects noted at this time	
0010-145	2504319	Detailed Inspection of the Support Fittings of the Thrust-Reverser Ballscrew Actuators	Complied with task 78-30-00-209 LH & RH Detailed Inspection of the Support Fittings of the Thrust-Reverser Ballscrew Actuators REF CL650 AMM 78-32-04-220-801. No defects noted at this time.	

Sequence #	0010	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503652	Aircraft Reg #	XA-SOL	Parent WO #	2498069

CHILD WORK ORDER DETAILS

	WO #	Description	Corrective Action	AMENDED
0010-146	2504324	Defuel Aircraft for Maintenance	Complied with gravity defueling of aircraft. REF: Challenger 650 AMM 12-11-28-650-804	
0010-147	2504326	Fuel Aircraft for Maintenance		
0010-148	2504327	Install Ailerons for Maintenance	Installed LH/RH Aileron IAW CL-650 AMM 27-15-01-400-801. See CMT working copy dated 2/18/26.	
0010-149	2504328	Install Elevators for Maintenance		
0010-150	2504334	Install Rudder for Maintenance	This WO is referenced by WO# 4761617 - if this is a duplicate that WO must be addressed	
0010-151	2504336	Remove Ailerons for Maintenance	Removed LH/RH Aileron IAW CL-650 AMM 27-15-01-000-801. See WO:2504327 for installation.	
0010-152	2504337	Remove Elevators for Maintenance	Removed LH and RH Elevators in reference to CL-650 AMM 27-34-01-000-801.	
0010-153	2504342	Remove Rudder for Maintenance	Removed the rudder IAW CL-650 AMM 27-24-01-000-801. See Finding 79866 See WO:2504334 for installation.	
0010-154	2504344	Detailed Inspection of the Nose Landing Gear (NLG) Assembly		
0010-155	2504345	Detailed Inspection of the Lower Internal Skin and Fuselage Structure - FS280 to FS409, as visible with the floor panels installed	Complied with task 53-20-00-206, Perform Detailed Inspection of the Lower Internal Skin and Fuselage Structure - FS280 to FS409, as visible with the floor panels installed, in accordance with CL-650 AMM 53-20-01-220-805. No Defects Noted.	
0010-156	2504348	Aircraft Jacking for Maintenance	Performed Jacking of the Aircraft for Maintenance REF CL 650 AMM 07-10-01-581-801. Down-Jacking of Aircraft to Be Performed on WO: 2504351.	
0010-157	2504351	Down-Jack Aircraft		
0010-158	2504352	Detailed Inspection of the Lightning/High Intensity Radiated Field L/HIRF Protection on the Wing Disconnects - Internal	Complied with TLMC Task 22-12-00-211 Detailed Inspection of the Lightning/High Intensity Radiated Field L/HIRF Protection on the Wing Disconnects - Internal IAW CL650 AMM Task 22-12-22-220-811. No defects noted.	

Sequence #	0010	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503652	Aircraft Reg #	XA-SOL	Parent WO #	2498069

CHILD WORK ORDER DETAILS

	WO #	Description	Corrective Action	AMENDED
0010-159	2504354	Detailed inspection of the Floor Support Structure - FS280 to FS409	Complied with task 53-20-00-204, Perform Detailed inspection of the Floor Support Structure - FS280 to FS409, in accordance with CL-650 AMM 53-20-01-220-830. No Defects Noted.	
0010-160	2504357	Detailed Inspection of the Internal Forward Keel Beam - FS364 to FS394	Complied with task 53-20-00-210 Detailed Inspection of the Internal Forward Keel Beam - FS364 to FS394 REF CL650 AMM 53-20-01-220-808. No defects noted at this time	
0010-161	2504358	Detailed Inspection of the Sills, Frames and External Skin around the Emergency-Exit Door Cutout	Complied with task 53-20-00-217, Performed Detailed Inspection of the Sills, Frames and External Skin around the Emergency-Exit Door Cutout, in accordance with Cl 650 AMM 53-20-01-220-815. No defects noted	
0010-162	2504361	Detailed Inspection of the Frame below the Floor - FS513	Complied with task 53-20-00-223, Perform Detailed Inspection of the Frame below the Floor - FS513, in accordance with CL-650 AMM 53-20-01-220-821. No Defects Noted.	
0010-163	2504363	Detailed Inspection of the Forward Keel Beam Pressure Box and Keel Beam Lugs and Links - FS394 to FS409	Complied with task 53-20-00-211, Perform Detailed Inspection of the Forward Keel Beam Pressure Box and Keel Beam Lugs and Links - FS394 to FS409, in accordance with CL-650 AMM 53-20-01-220-809. No Defects Noted	
0010-164	2504364	Detailed Inspection of the Wing-to-Fuselage Attachment Lug - FS473.15	Complied with TLMC task 53-20-00-222 Performed LH/RH detailed inspection of the wing to body fuselage attachment lug (FS473.15) REF CL-650 AMM 53-20-01-220-820. No defects noted.	

Bombardier

Sequence #	0010-1	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503993	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-1	WO #	2503993	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Functional test of the Static Dischargers	
Functional test of the Static Dischargers				
Task / IRN # : 23-60-00-201				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 23-60-00-201, Perform Functional test of the Static Dischargers, in accordance with CL-650 AMM 23-61-01-720-801. Functional test failed. See finding 79442 for details. Bond test of Static dischargers Good.	B0143864 - Aaric Cerna Feb 09, 2026 03:37 PM	23-60
	Perform Functional test of the Static Dischargers		B1013522 - Brandon Jennings Feb 09, 2026 04:54 PM	
	200	Removed tools, equipment and all unwanted materials from work area	B0143864 - Aaric Cerna Feb 09, 2026 03:37 PM	
	Remove tools, equipment and all unwanted materials from work area		B1013522 - Brandon Jennings Feb 09, 2026 04:54 PM	

FINDINGS DETAILS

Finding #	Long Description	Status	Reported By / Date	Defect Source / Disposition	Defect Type	Priority	Follow-up WO #
79442	Found 13 BAD static wicks. 1 at end cap of the right side horizontal stab PN 2-18SC1 1 at tail cone PN 2-17SC1 1 at LH MID winglet PN 2-11SC1 1 at LH wing OB PN 2-17SC1 3 at LH aileron PN 2-17SC1 3 at RH aileron PN 2-17SC1 1 at RH wing OB PN 2-17SC1 2 AT RH winglet MID and BOTTOM PN SC111SC1. All others within limits	CLOSED	B0143864 - Aaric Cerna Feb 9, 2026 7:29 AM	MAINTENANCE 300-QA002	OTHER	3	4800910-APPR

Sequence #	0010-1	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	2503993	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2503652

TOOL INFORMATION

Tool ID	Tool Description	Calibration Due Date
TUSJ1779	Megohm	Apr 29, 2026 5:00 PM

Sequence #	0010-2	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503995	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-2	WO #	2503995	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Rudder and Elevator Control Cables in the Lower Mid-Fuselage Compartment	
Detailed Inspection of the Rudder and Elevator Control Cables in the Lower Mid-Fuselage Compartment				
Task / IRN # : 27-00-00-205				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 27-00-00-205, Perform Detailed Inspection of the Rudder and Elevator Control Cables in the Lower Mid-Fuselage Compartment, in accordance with 650 MM 27-00-00-220-805. No defects noted at this time.	B0142041 - Timothy Winfree Feb 15, 2026 07:01 PM	27-00
	Perform Detailed Inspection of the Rudder and Elevator Control Cables in the Lower Mid-Fuselage Compartment		B0142244 - Todd Bridges Feb 15, 2026 08:02 PM	
	200	Removed all tools, equipment, and unwanted materials from the work area.	B0142041 - Timothy Winfree Feb 15, 2026 07:03 PM	
	Remove all tools, equipment, and unwanted materials from the work area.		B0142244 - Todd Bridges Feb 15, 2026 08:02 PM	

Sequence #	0010-3	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503999	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-3	WO #	2503999	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Elevator Control Cables in the Vertical Stabilizer	
Detailed Inspection of the Elevator Control Cables in the Vertical Stabilizer				
Task / IRN # : 27-00-00-207				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 27-00-00-207, Perform Detailed Inspection of the Elevator Control Cables in the Vertical Stabilizer, in accordance with CL650 AMM 27-00-00-220-807. No defects noted.	B0641903 - Felipe Mendoza Cervantes Feb 16, 2026 11:42 PM	27-00
	Perform Detailed Inspection of the Elevator Control Cables in the Vertical Stabilizer		B0623124 - Michael Stacy Feb 17, 2026 12:57 AM	
	200	Removed all tools equipment and unwanted materials from the work area.	B0641903 - Felipe Mendoza Cervantes Feb 16, 2026 11:42 PM	
	Remove all tools equipment and unwanted materials from the work area.		B0623124 - Michael Stacy Feb 17, 2026 12:57 AM	

Sequence #	0010-4	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504000	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-4	WO #	2504000	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Functional Test of the Forward and Aft Auxiliary Tanks - Interspace and Fuel Transfer Line Shrouds	
Functional test of the Forward and Aft Auxiliary Tanks - Interspace and Fuel Transfer Line Shrouds				
Task / IRN # : 28-10-00-210				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with TLMC task 28-10-00-210 Performed functional test of the forward and aft aux tanks (Interspace and fuel transfer line shrouds) REF CL-650 AMM 28-12-20-720-802. Functional test good.	B1002512 - Brandon Warne Feb 23, 2026 02:20 PM	28-10
	Perform Functional test of the Forward and Aft Auxiliary Tanks - Interspace and Fuel Transfer Line Shrouds		B1013522 - Brandon Jennings Feb 23, 2026 09:01 PM	
	101	Complied with TLMC task 28-10-00-210 Performed functional test of the forward and aft aux tanks (Interspace and fuel transfer line shrouds) REF CL-650 AMM 28-12-10-720-802. Functional test good.	B1002512 - Brandon Warne Feb 24, 2026 12:53 PM	
	Perform Functional test of the Forward and Aft Auxiliary Tanks - Interspace and Fuel Transfer Line Shrouds		B1013522 - Brandon Jennings Feb 24, 2026 01:39 PM	09
	200	Removed all tools, equipment and materials from the work area.	B1002512 - Brandon Warne Feb 23, 2026 02:20 PM	
	Remove all tools, equipment and materials from the work area.		B1013522 - Brandon Jennings Feb 23, 2026 09:01 PM	

TOOL INFORMATION

Tool ID	Tool Description	Calibration Due Date
TUSS2451	Air test stand	Feb 27, 2027 5:00 PM

Bombardier

Sequence #	0010-5	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504002	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-5	WO #	2504002	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Operational Test of the Collector-Tank Check Valve	
Operational Test of the Collector-Tank Check Valve				
Task / IRN # : 28-20-00-202				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			28-10
	Perform LH Operational Test of the Collector-Tank Check Valve			
	200			28-10
	Perform RH Operational Test of the Collector-Tank Check Valve			

Sequence #	0010-6	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504006	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-6	WO #	2504006	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Functional Test of the Flight Data Recorder (FDR) Dedicated Sensors (Challenger 604 - A/C 5463 and Subs, Post SB 604-31-010) (Challenger 605 – Post SB 605-31-001) (Challenger 650 – Post SB 650-31-001)	
Functional Test of the Flight Data Recorder (FDR) Dedicated Sensors (Challenger 604 - A/C 5463 and Subs, Post SB 604-31-010) (Challenger 605 – Post SB 605-31-001) (Challenger 650 – Post SB 650-31-001)				
Task / IRN # : 31-31-00-203				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 31-31-00-203, Perform Functional Test of the Flight Data Recorder (FDR) Dedicated Sensors (Post SB 650-31-001), in accordance with 650 MM 31-31-01-720-801. ALL PARAMETERS WITHIN LIMITS. TEST GOOD	B0143864 - Aaric Cerna Feb 06, 2026 04:37 PM	31-30
	Perform Functional Test of the Flight Data Recorder (FDR) Dedicated Sensors (Post SB 650-31-001)		B1013522 - Brandon Jennings Feb 06, 2026 05:10 PM	
	200	Removed tools, equipment and all unwanted materials from work area	B0143864 - Aaric Cerna Feb 06, 2026 04:37 PM	
	Remove tools, equipment and all unwanted materials from work area		B1013522 - Brandon Jennings Feb 06, 2026 05:10 PM	

TOOL INFORMATION

Tool ID	Tool Description	Calibration Due Date
TUDSS4478	INCLINOMETER	Mar 30, 2026 5:00 PM

Sequence #	0010-7	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504007	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-7	WO #	2504007	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Functional Test of the Flight Data Recorder (FDR) Force Sensors	
Functional Test of the Flight Data Recorder (FDR) Force Sensors				
Task / IRN # : 31-31-00-204				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 31-31-00-204, Perform Functional Test of the Flight Data Recorder (FDR) Force Sensors (Post SB 650-31-001), in accordance with CL-650 AMM 31-31-01-720-804. Flight deck temp. = 23 degrees. Pilot/Copilot pitch control force = 24.0 FWD 19.0 AFT pilot/Copilot Roll control force = 7.5 CCW, 7.8 CW. Rudder pedal force LIB/LOB = 26 Rudder pedal force RIB/ ROB = 26. Downloaded details and provided to CPM.	B0143864 - Aaric Cerna Feb 05, 2026 08:44 PM	31-30
	Perform Functional Test of the Flight Data Recorder (FDR) Force Sensors (Post SB 650-31-001)		B0143196 - Robert Bohner Feb 05, 2026 08:56 PM	
	200	Removed all tools, equipment and all unwanted materials from work area.	B0143864 - Aaric Cerna Feb 05, 2026 08:44 PM	
	Remove all tools, equipment and all unwanted materials from work area.		B0143196 - Robert Bohner Feb 05, 2026 08:56 PM	

TOOL INFORMATION

Tool ID	Tool Description	Calibration Due Date
TUSS2040	TORQUE	Dec 30, 2026 5:00 PM
TUSS4478	INCLINOMETER	Mar 30, 2026 5:00 PM
TUSS4798	FORCE GAUGE	Nov 29, 2026 5:00 PM
TUSS0118	BRAKE PEDAL PRESSURE TEST	Feb 27, 2026 5:00 PM

Bombardier

Sequence #	0010-8	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504010	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-8	WO #	2504010	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Landing-Gear Emergency-Extension Cable in the Mid-Lower Fuselage Compartment	
Detailed Inspection of the Landing-Gear Emergency-Extension Cable in the Mid-Lower Fuselage Compartment				
Task / IRN # : 32-00-01-211				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with TLMC 32-00-01-211. Performed a Detailed Inspection of the Landing-Gear Emergency-Extension Cable in the MLG Wheel Well Ref. CL-650 AMM 32-34-28-220-805. No defects noted.	B0613291 - Eric Strong Feb 05, 2026 05:05 PM	32-30
	Perform Detailed Inspection of the Landing-Gear Emergency-Extension Cable in the Mid-Lower Fuselage		B0143196 - Robert Bohner Feb 05, 2026 05:25 PM	
	101	Complied with TLMC 32-00-01-211. Continued with the Detailed Inspection of the Landing-Gear Emergency-Extension Cable in the Mid-Lower Fuselage underneath cabin floor panels Ref. CL-650 AMM 32-34-28-220-805. No defects noted.	B0613291 - Eric Strong Feb 14, 2026 08:09 PM	
	Continue with the Detailed Inspection of the Landing-Gear Emergency-Extension Cable in the Mid-Lower Fuselage underneath cabin floor panels Ref. CL-650 AMM 32-34-28-220-805		B0142244 - Todd Bridges Feb 14, 2026 08:49 PM	
	200	Removed all tools, equipment, and unwanted materials from the work area.	B0613291 - Eric Strong Feb 14, 2026 08:09 PM	
	Remove all tools, equipment, and unwanted materials from the work area.		B0142244 - Todd Bridges Feb 14, 2026 08:49 PM	

Bombardier

Sequence #	0010-10	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504013	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-10	WO #	2504013	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Internal Structure of the Passenger Door	
Detailed Inspection of the Internal Structure of the Passenger Door				
Task / IRN # : 52-11-00-203				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 52-11-00-203, Perform Detailed Inspection of the Internal Structure of the Passenger Door, in accordance with 650 MM 52-11-01-220-803. No defects noted at this time.	B0142041 - Timothy Winfree Feb 14, 2026 11:52 PM	52-10
	Perform Detailed Inspection of the Internal Structure of the Passenger Door		B0142244 - Todd Bridges Feb 15, 2026 12:17 AM	
	200	Removed all tools, equipment, and unwanted materials from the work area.	B0142041 - Timothy Winfree Feb 15, 2026 12:20 AM	
	Remove all tools, equipment, and unwanted materials from the work area.		B0142244 - Todd Bridges Feb 15, 2026 12:23 AM	

Sequence #	0010-11	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504016	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-11	WO #	2504016	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Internal Structure of the Overwing Emergency-Exit Door	
Detailed Inspection of the Internal Structure of the Overwing Emergency-Exit Door				
Task / IRN # : 52-21-00-203				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 52-21-00-203, Perform Detailed Inspection of the Internal Structure of the Overwing Emergency-Exit Door, in accordance with CL650 AMM 52-21-01-220-803. No defects noted.	B0641903 - Felipe Mendoza Cervantes Feb 17, 2026 01:57 AM	52-20
	Perform Detailed Inspection of the Internal Structure of the Overwing Emergency-Exit Door		B0623124 - Michael Stacy Feb 17, 2026 04:03 AM	
	200	removed all tools equipment and unwanted materials from the work area.	B0641903 - Felipe Mendoza Cervantes Feb 17, 2026 01:57 AM	
	remove all tools equipment and unwanted materials from the work area.		B0623124 - Michael Stacy Feb 17, 2026 04:03 AM	

Bombardier

Sequence #	0010-12	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504018	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-12	WO #	2504018	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Stop Fittings of the Cargo Compartment Door	
Detailed Inspection of the Stop Fittings of the Cargo Compartment Door				
Task / IRN # : 52-31-00-202				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with TLMC 52-31-00-202, Perform Detailed Inspection of the Stop Fittings of the Cargo Compartment Door. In REF: CL-650 AMM 52-31-01-220-802. No defects noted at this time.	B1018339 - Dwain Wolf Feb 13, 2026 08:27 PM	52-30
	Perform Detailed Inspection of the Stop Fittings of the Cargo Compartment Door		B0142244 - Todd Bridges Feb 13, 2026 09:12 PM	
	200	Removed all tools, equipment, and unwanted materials from the work area.	B1018339 - Dwain Wolf Feb 13, 2026 08:27 PM	
	Remove all tools, equipment, and unwanted materials from the work area.		B0142244 - Todd Bridges Feb 13, 2026 09:12 PM	

Bombardier

Sequence #	0010-13	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504019	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-13	WO #	2504019	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Internal Structure of the Cargo Compartment Door	
Detailed Inspection of the Internal Structure of the Cargo Compartment Door				
Task / IRN # : 52-31-00-203				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with TLMC 52-31-00-203, Perform Detailed Inspection of the Internal Structure of the Cargo Compartment Door. In REF: CL-650 AMM 52-31-01-220-803. No defects noted at this time.	B1018339 - Dwain Wolf Feb 13, 2026 08:09 PM	52-30
	Perform Detailed Inspection of the Internal Structure of the Cargo Compartment Door		B0142244 - Todd Bridges Feb 13, 2026 09:10 PM	
	200	Removed all tools, equipment, and unwanted materials from the work area.	B1018339 - Dwain Wolf Feb 13, 2026 08:09 PM	
	Remove all tools, equipment, and unwanted materials from the work area.		B0142244 - Todd Bridges Feb 13, 2026 09:10 PM	

Bombardier

Sequence #	0010-14	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504021	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-14	WO #	2504021	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Overwing Emergency-Exit Door - External	
General Visual Inspection of the Overwing Emergency-Exit Door - External				
Task / IRN # : 52-ZL-00-208				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with Task: 52-ZL-00-208; Perform General Visual Inspection of the Overwing Emergency-Exit Door - External. Ref: CL-650 AMM 52-21-01-210-801. See Finding #80261 For discrepancy.	B1017798 - Hunter Van Der Heide Feb 14, 2026 04:39 AM	52-20
	Perform General Visual Inspection of the Overwing Emergency-Exit Door - External		B0161691 - Thomas Mitchell Feb 14, 2026 05:00 AM	
	200	Removed all tools, equipment, and unwanted materials from the area.	B1017798 - Hunter Van Der Heide Feb 14, 2026 04:39 AM	
	Remove all tools, equipment, and unwanted materials from the area.		B0161691 - Thomas Mitchell Feb 14, 2026 05:00 AM	

FINDINGS DETAILS

Finding #	Long Description	Status	Reported By / Date	Defect Source / Disposition	Defect Type	Priority	Follow-up WO #
80262	Lock cable for hardware of the fwd.-upper door stop missing.	CLOSED	B0645936 - Carlos Zerino Feb 13, 2026 9:26 PM	MAINTENANCE 300-QA002	OTHER	3	4803011-PSAP

Sequence #	0010-15	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504024	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-15	WO #	2504024	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Internal Fuselage, Frames and Forward Bulkhead - FS169.00 to FS202.75	
Detailed Inspection of the Internal Fuselage, Frames and Forward Bulkhead - FS169.00 to FS202.75				
Task / IRN # : 53-10-00-201				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 53-10-00-201 Detailed Inspection of the Internal Fuselage, Frames and Forward Bulkhead - FS169.00 to FS202.75 REF CL650 AMM 53-10-01-220-801. No defects noted at this time.	B0648431 - Caleb Sexton Feb 16, 2026 08:10 PM	53-10
	Perform Detailed Inspection of the Internal Fuselage, Frames and Forward Bulkhead - FS169.00 to FS202.75		B1019908 - Joseph Barnes Feb 16, 2026 08:34 PM	
	200	Removed all tools, equipment and unwanted materials from the work area	B0648431 - Caleb Sexton Feb 16, 2026 08:10 PM	
	Remove all tools, equipment and unwanted materials from the work area		B1019908 - Joseph Barnes Feb 16, 2026 08:34 PM	

Sequence #	0010-16	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	2504025	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2503652

0010-16	**WO #**	**2504025**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		Detailed Inspection of the Beams, Crossmembers and Panels of the Floor Structure - FS169 to FS280	
Detailed Inspection of the Beams, Crossmembers and Panels of the Floor Structure - FS169 to FS280				
Task / IRN # : 53-10-00-208				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 53-10-00-208, Perform Detailed Inspection of the Beams, Crossmembers and Panels of the Floor Structure - FS169 to FS280, in accordance with CL-650 AMM 53-10-01-220-807. No Defects Noted.	B0642051 - Terry Walters Feb 16, 2026 03:24 PM	53-10
	Perform Detailed Inspection of the Beams, Crossmembers and Panels of the Floor Structure - FS169 to FS280		B1019908 - Joseph Barnes Feb 16, 2026 03:35 PM	
	200	Removed all Tools, equipment, and unwanted materials from the work area.	B0642051 - Terry Walters Feb 16, 2026 03:24 PM	
	Remove all Tools, equipment, and unwanted materials from the work area.		B1019908 - Joseph Barnes Feb 16, 2026 03:35 PM	

Sequence #	0010-17	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504027	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-17	WO #	2504027	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Forward Jacking Point - FS278	
Detailed Inspection of the Forward Jacking Point - FS278				
Task / IRN # : 53-10-00-210				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 53-10-00-210, Performed Detailed Inspection of the Forward Jacking Point - FS278, in accordance with CL 650 AMM 53-10-01-220-809. No defects noted.	B1017798 - Hunter Van Der Heide Feb 14, 2026 04:43 AM	53-10
	Perform Detailed Inspection of the Forward Jacking Point - FS278		B0161691 - Thomas Mitchell Feb 14, 2026 05:02 AM	
	200	Removed all tools, equipment, and unwanted materials from the area.	B1017798 - Hunter Van Der Heide Feb 14, 2026 04:43 AM	
	Remove all tools, equipment, and unwanted materials from the area.		B0161691 - Thomas Mitchell Feb 14, 2026 05:02 AM	

Sequence #	0010-18	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504030	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-18	WO #	2504030	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed inspection of the Floor Support Structure - FS280 to FS409, as visible with floor panels installed	
Detailed inspection of the Floor Support Structure - FS280 to FS409, as visible with floor panels installed				
Task / IRN # : 53-20-00-203				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 53-20-00-203 Detailed inspection of the Floor Support Structure - FS280 to FS409, as visible with floor panels installed REF CL650 AMM 53-20-01-220-803. No defects noted at this time.	B0648431 - Caleb Sexton Feb 16, 2026 03:30 PM	53-20
	Performed Detailed inspection of the Floor Support Structure - FS280 to FS409, as visible with floor panels installed		B1019908 - Joseph Barnes Feb 16, 2026 03:57 PM	
	200	Removed all tools, equipment, and unwanted materials from the work area	B0648431 - Caleb Sexton Feb 16, 2026 03:30 PM	
	Remove all tools, equipment, and unwanted materials from the work area		B1019908 - Joseph Barnes Feb 16, 2026 03:57 PM	

Bombardier

Sequence #	0010-19	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504031	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-19	WO #	2504031	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Aft Face of the Frame below the Floor -FS409	
Detailed Inspection of the Aft Face of the Frame below the Floor -FS409				
Task / IRN # : 53-20-00-216				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 53-20-00-216, Perform Detailed Inspection of the Aft Face of the Frame below the Floor -FS409, in accordance with CL-650 AMM 53-20-01-220-814. No Defects Noted.	B0642051 - Terry Walters Feb 16, 2026 02:25 PM	53-20
	Perform Detailed Inspection of the Aft Face of the Frame below the Floor -FS409		B1019908 - Joseph Barnes Feb 16, 2026 02:27 PM	
	200	Remove all Tools, equipment, and unwanted materials from the work area.	B0642051 - Terry Walters Feb 16, 2026 02:25 PM	
	Remove all Tools, equipment, and unwanted materials from the work area.		B1019908 - Joseph Barnes Feb 16, 2026 02:27 PM	
	201	Removed all Tools, equipment, and unwanted materials from the work area.	B0642051 - Terry Walters Feb 16, 2026 02:47 PM	
	Remove all Tools, equipment, and unwanted materials from the work area.		B1019908 - Joseph Barnes Feb 16, 2026 03:29 PM	09

Bombardier

Sequence #	0010-20	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504033	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-20	WO #	2504033	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Fittings of the Emergency-Exit Door	
Detailed Inspection of the Fittings of the Emergency-Exit Door				
Task / IRN # : 53-20-00-218				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 53-20-00-218 Detailed Inspection of the Fittings of the Emergency-Exit Door REF CL650 AMM 53-20-01-220-816. No defects noted at this time	B0648431 - Caleb Sexton Feb 16, 2026 09:16 PM	53-20
	Perform Detailed Inspection of the Fittings of the Emergency-Exit Door		B1013522 - Brandon Jennings Feb 17, 2026 02:51 PM	
	200	Removed all tools, equipment and unwanted materials from the work area	B0648431 - Caleb Sexton Feb 16, 2026 09:16 PM	
	Remove all tools, equipment and unwanted materials from the work area		B1013522 - Brandon Jennings Feb 17, 2026 02:51 PM	

Bombardier

Sequence #	0010-21	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504036	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-21	WO #	2504036	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Floor Sill Area Over the Wing Box - FS409 to FS559	
Detailed Inspection of the Floor Sill Area Over the Wing Box - FS409 to FS559				
Task / IRN # : 53-20-00-220				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 53-20-00-220, Perform Detailed Inspection of the Floor Sill Area Over the Wing Box - FS409 to FS559, in accordance with CL-650 AMM 53-20-01-220-818. No defects noted	B0642051 - Terry Walters Feb 16, 2026 04:38 PM	53-20
	Perform Detailed Inspection of the Floor Sill Area Over the Wing Box - FS409 to FS559		B1019908 - Joseph Barnes Feb 16, 2026 05:09 PM	
	200	Removed all Tools, Equipment, and unwanted materials from the work area.	B0642051 - Terry Walters Feb 16, 2026 04:38 PM	
	Remove all Tools, Equipment, and unwanted materials from the work area.		B1019908 - Joseph Barnes Feb 16, 2026 05:09 PM	

Bombardier

Sequence #	0010-22	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504038	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-22	WO #	2504038	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Wing-to-Fuselage Attachment Lug - FS424	
Detailed Inspection of the Wing-to-Fuselage Attachment Lug - FS424				
Task / IRN # : 53-20-00-221				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with TLMC task 53-20-00-221 Performed detailed inspection of the wing to fuselage attachment lug at FS424 REF CL-650 53-20-01-220-819. No defects noted.	B1002512 - Brandon Warne Feb 12, 2026 07:03 PM	53-20
	Perform Detailed Inspection of the Wing-to-Fuselage Attachment Lug - FS424		B1013522 - Brandon Jennings Feb 12, 2026 07:47 PM	
	200	Removed all tools, equipment and materials from the work area.	B1002512 - Brandon Warne Feb 12, 2026 07:03 PM	
	Remove all tools, equipment and materials from the work area.		B1013522 - Brandon Jennings Feb 12, 2026 07:47 PM	

Bombardier

Sequence #	0010-23	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504039	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-23	WO #	2504039	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Underfloor Longeron Assembly - FS409 to FS559	
Detailed Inspection of the Underfloor Longeron Assembly - FS409 to FS559				
Task / IRN # : 53-20-00-229				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 53-20-00-229, Perform Detailed Inspection of the Underfloor Longeron Assembly - FS409 to FS559, in accordance with CL-650 AMM 53-20-01-220-827. No Defects Noted	B0642051 - Terry Walters Feb 16, 2026 02:10 PM	53-20
	Perform Detailed Inspection of the Underfloor Longeron Assembly - FS409 to FS559		B1019908 - Joseph Barnes Feb 16, 2026 02:24 PM	
	200	Removed all Tools, equipment, and unwanted materials from the work area.	B0642051 - Terry Walters Feb 16, 2026 02:10 PM	
	Remove all Tools, equipment, and unwanted materials from the work area.		B1019908 - Joseph Barnes Feb 16, 2026 02:24 PM	

Sequence #	0010-24	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504042	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-24	WO #	2504042	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the MLG Uplock Structure - FS513 to FS559 below WL73 (LH and RH)	
Detailed Inspection of the MLG Uplock Structure - FS513 to FS559 below WL73 (LH and RH)				
Task / IRN # : 53-20-00-230				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with TLMC 53-20-00-230. Performed a Detailed Inspection of the MLG Uplock Structure - FS513 to FS559 below WL73 (LH and RH) Ref. CL-650 AMM 53-20-01-220-828. No defects noted.	B0613291 - Eric Strong Feb 05, 2026 09:00 PM	53-20
	Perform Detailed Inspection of the MLG Uplock Structure - FS513 to FS559 below WL73 (LH and RH)		B1019908 - Joseph Barnes Feb 05, 2026 09:07 PM	
	200	Removed all tools, equipment, and unwanted materials from the work area.	B0613291 - Eric Strong Feb 05, 2026 09:00 PM	
	Remove all tools, equipment, and unwanted materials from the work area.		B1019908 - Joseph Barnes Feb 05, 2026 09:07 PM	

Sequence #	0010-25	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504043	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-25	WO #	2504043	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Internal Surfaces of the Forward Auxiliary Tank	
Detailed Inspection of the Internal Surfaces of the Forward Auxiliary Tank				
Task / IRN # : 53-20-00-232				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 53-20-00-232, Perform Detailed Inspection of the Internal Surfaces of the Forward Auxiliary Tank, in accordance with CL-650 AMM 53-20-01-220-863. No Defects Noted.	B0642051 - Terry Walters Feb 17, 2026 08:22 PM	53-20
	Perform Detailed Inspection of the Internal Surfaces of the Forward Auxiliary Tank		B1013522 - Brandon Jennings Feb 17, 2026 09:01 PM	
	200	Removed all tools, equipment, and unwanted materials from the work area.	B0642051 - Terry Walters Feb 17, 2026 08:22 PM	
	Remove all tools, equipment, and unwanted materials from the work area.		B1013522 - Brandon Jennings Feb 17, 2026 09:01 PM	

Sequence #	0010-26	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504045	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-26	WO #	2504045	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Aft Face of the Pressure Bulkhead below the Floor - FS559	
Detailed Inspection of the Aft Face of the Pressure Bulkhead below the Floor - FS559				
Task / IRN # : 53-30-00-201				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 53-30-00-201, Perform Detailed Inspection of the Aft Face of the Pressure Bulkhead below the Floor - FS559, in accordance with CL-650 AMM 53-30-01-220-801. No Defects noted.	B1022275 - Kaitlynn Maxon Feb 17, 2026 02:30 PM	53-30
	Perform Detailed Inspection of the Aft Face of the Pressure Bulkhead below the Floor - FS559		B1013522 - Brandon Jennings Feb 17, 2026 02:58 PM	
	200	Removed all tools, equipment, and unwanted materials from the work area.	B1022275 - Kaitlynn Maxon Feb 17, 2026 02:32 PM	
	Remove all tools, equipment, and unwanted materials from the work area.		B1013522 - Brandon Jennings Feb 17, 2026 02:58 PM	

Bombardier

Sequence #	0010-27	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504048	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-27	WO #	2504048	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Forward Face of the Pressure Bulkhead below the Floor - FS559	
Detailed Inspection of the Forward Face of the Pressure Bulkhead below the Floor - FS559				
Task / IRN # : 53-30-00-202				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 53-30-00-202, Perform Detailed Inspection of the Forward Face of the Pressure Bulkhead below the Floor - FS559, in accordance with 650 MM 53-30-01-220-802. No defects noted at this time.	B0142041 - Timothy Winfree Feb 15, 2026 02:55 PM	53-30
	Perform Detailed Inspection of the Forward Face of the Pressure Bulkhead below the Floor - FS559		B0142244 - Todd Bridges Feb 15, 2026 08:07 PM	
	200	entered in error	B0142041 - Timothy Winfree Feb 15, 2026 04:50 PM	
			B0142244 - Todd Bridges Feb 15, 2026 08:07 PM	
	300	Removed all tools, equipment, and unwanted materials from the work area	B0142041 - Timothy Winfree Feb 15, 2026 04:51 PM	
	Remove all tools, equipment, and unwanted materials from the work area		B0142244 - Todd Bridges Feb 15, 2026 08:07 PM	

Sequence #	0010-28	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504050	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-28	WO #	2504050	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Aft Face of the Rear Pressure Bulkhead - FS621	
Detailed Inspection of the Aft Face of the Rear Pressure Bulkhead - FS621				
Task / IRN # : 53-30-00-203				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 53-30-00-203, Perform Detailed Inspection of the Aft Face of the Rear Pressure Bulkhead - FS621, in accordance with CL-650 AMM 53-30-01-220-803. No Defects noted.	B0642051 - Terry Walters Feb 17, 2026 08:22 PM	53-30
	Perform Detailed Inspection of the Aft Face of the Rear Pressure Bulkhead - FS621		B1013522 - Brandon Jennings Feb 17, 2026 08:59 PM	
	200	Removed all tools, equipment, and unwanted materials from the work area.	B0642051 - Terry Walters Feb 17, 2026 08:22 PM	
	Remove all tools, equipment, and unwanted materials from the work area.		B1013522 - Brandon Jennings Feb 17, 2026 08:59 PM	

Bombardier

Sequence #	0010-29	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504051	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-29	WO #	2504051	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Stabilizer Drag Angles - FS700 to FS820, and Stringer 2L and 2R	
Detailed Inspection of the Stabilizer Drag Angles - FS700 to FS820, and Stringer 2L and 2R				
Task / IRN # : 53-30-00-204				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with TLMC task 53-30-00-204 Performed detailed inspection of the stabilizer drag angles (FS700 to FS820 and stringer 2L and 2R REF CL-650 53-30-01-220-804. No defects noted.	B1002512 - Brandon Warne Feb 18, 2026 07:25 PM	53-30
	Perform Detailed Inspection of the Stabilizer Drag Angles - FS700 to FS820, and Stringer 2L and 2R		B1013522 - Brandon Jennings Feb 18, 2026 08:24 PM	
	200	Removed all tools, equipment and materials from the work area.	B1002512 - Brandon Warne Feb 18, 2026 07:25 PM	
	Remove all tools, equipment and materials from the work area.		B1013522 - Brandon Jennings Feb 18, 2026 08:24 PM	

Bombardier

Sequence #	0010-30	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504054	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-30	WO #	2504054	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Profile Plates of the Floor Support Structure - FS559 to FS621	
Detailed Inspection of the Profile Plates of the Floor Support Structure - FS559 to FS621				
Task / IRN # : 53-30-00-206				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 53-30-00-206, Perform Detailed Inspection of the Profile Plates of the Floor Support Structure - FS559 to FS621. REF CL650 AMM 53-30-01-220-806. No defects noted.	B1016542 - Carlos Ochoa Feb 16, 2026 10:45 PM	53-30
	Perform Detailed Inspection of the Profile Plates of the Floor Support Structure - FS559 to FS621		B0623124 - Michael Stacy Feb 17, 2026 01:33 AM	
	200	Removed all tools, equipment, and unwanted materials.	B1016542 - Carlos Ochoa Feb 16, 2026 10:45 PM	
	Remove all tools, equipment, and unwanted materials.		B0623124 - Michael Stacy Feb 17, 2026 01:33 AM	

Bombardier

Sequence #	0010-31	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504056	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-31	WO #	2504056	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Engine Support Beam Structure	
Detailed Inspection of the Engine Support Beam Structure				
Task / IRN # : 53-30-00-208				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with Task Card 53-30-00-208. Peformed Detailed Inspection of the Engine Support Beam Structure. Ref. CL650 AMM 53-30-01-220-807. No discrepancies noted at this time.	K1018275 - Emmanuel Cocoa Feb 07, 2026 03:51 PM	53-30
	Peformed Detailed Inspection of the Engine Support Beam Structure		B0142244 - Todd Bridges Feb 07, 2026 04:46 PM	
	200	Removed all tools equipment and unwanted materials.	K1018275 - Emmanuel Cocoa Feb 07, 2026 03:51 PM	
	Remove all tools equipment and unwanted materials.		B0142244 - Todd Bridges Feb 07, 2026 04:46 PM	

Sequence #	0010-32	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504057	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-32	WO #	2504057	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Internal Aft Fuselage (Skin and Structure, FS621.00 Bulkhead Forward Face and the External Surfaces of the Aft-Auxiliary Fuel Tank)-FS559.00 to FS621.00 Below the Floor	
Detailed Inspection of the Internal Aft Fuselage (Skin and Structure, FS621.00 Bulkhead Forward Face and the External Surfaces of the Aft-Auxiliary Fuel Tank)-FS559.00 to FS621.00 Below the Floor				
Task / IRN # : 53-30-00-209				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 53-30-00-209, Perform Detailed Inspection of the Internal Aft Fuselage (Skin and Structure, FS621.00 Bulkhead Forward Face and the External Surfaces of the Aft-Auxiliary Fuel Tank)-FS559.00 to FS621.00 Below the Floor, in accordance with CL650 AMM 53-30-01-220-852. No defects noted.	B0641903 - Felipe Mendoza Cervantes Feb 17, 2026 04:01 AM	53-30
	Perform Detailed Inspection of the Internal Aft Fuselage (Skin and Structure, FS621.00 Bulkhead Forward Face and the External Surfaces of the Aft-Auxiliary Fuel Tank)-FS559.00 to FS621.00 Below the Floor		B0623124 - Michael Stacy Feb 17, 2026 04:04 AM	
	200	Removed all tools equipment and unwanted materials from the work area.	B0641903 - Felipe Mendoza Cervantes Feb 17, 2026 04:01 AM	
	Remove all tools equipment and unwanted materials from the work area.		B0623124 - Michael Stacy Feb 17, 2026 04:04 AM	

Bombardier

Sequence #	0010-33	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504060	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-33	WO #	2504060	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Track Supports near, and the Sills and Frames around, the Cargo Compartment Door Cutout	
Detailed Inspection of the Track Supports near, and the Sills and Frames around, the Cargo Compartment Door Cutout				
Task / IRN # : 53-30-00-211				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 53-30-00-211, Perform Detailed Inspection of the Track Supports near, and the Sills and Frames around, the Cargo Compartment Door Cutout, REF CL650 AMM 53-30-01-220-810. See finding 80544.	B1016542 - Carlos Ochoa Feb 16, 2026 11:25 PM	53-30
	Perform Detailed Inspection of the Track Supports near, and the Sills and Frames around, the Cargo Compartment Door Cutout		B0623124 - Michael Stacy Feb 16, 2026 11:37 PM	
	200	Removed all tools, equipment, and unwanted materials.	B1016542 - Carlos Ochoa Feb 16, 2026 11:25 PM	
	Remove all tools, equipment, and unwanted materials.		B0623124 - Michael Stacy Feb 16, 2026 11:37 PM	

FINDINGS DETAILS

Finding #	Long Description	Status	Reported By / Date	Defect Source / Disposition	Defect Type	Priority	Follow-up WO #
80544	Found paint damage on baggage door cutout at FWD bottom corner. See attached photo.	CLOSED	B1016542 - Carlos Ochoa Feb 16, 2026 4:17 PM	MAINTENANCE 300-QA002	OTHER	3	4790143-RDYLT

Sequence #	0010-34	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504061	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-34	WO #	2504061	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Fittings of the Cargo Compartment Door	
Detailed Inspection of the Fittings of the Cargo Compartment Door				
Task / IRN # : 53-30-00-213				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with TLMC 53-30-00-213, Detailed Inspection of the Fittings of the Cargo Compartment Door. In REF: CL-650 AMM 53-30-01-220-812. No defects noted at this time.	B1018339 - Dwain Wolf Feb 13, 2026 03:24 PM	53-30
	Perform Detailed Inspection of the Fittings of the Cargo Compartment Door		B1019908 - Joseph Barnes Feb 13, 2026 03:50 PM	
	200	Removed all tools, equipment, and unwanted materials, from the work area.	B1018339 - Dwain Wolf Feb 13, 2026 03:24 PM	
	Remove all tools, equipment, and unwanted materials, from the work area.		B1019908 - Joseph Barnes Feb 13, 2026 03:50 PM	

Sequence #	0010-35	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	2504064	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2503652

0010-35	**WO #**	**2504064**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		Detailed Inspection of the Forward Face of the Frame - FS755	
Detailed Inspection of the Forward Face of the Frame - FS755				
Task / IRN # : 53-30-00-216				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 53-30-00-216 Detailed Inspection of the Forward Face of the Frame - FS755 REF CL650 AMM 53-30-01-220-816. No defects noted at this time	B0648431 - Caleb Sexton Feb 10, 2026 03:42 PM	53-30
	Perform Detailed Inspection of the Forward Face of the Frame - FS755		B1013522 - Brandon Jennings Feb 10, 2026 03:55 PM	
	200	Removed all tools equipment and unwanted material from the work area	B0648431 - Caleb Sexton Feb 10, 2026 04:06 PM	
	Remove all tools equipment and unwanted material from the work area		B1013522 - Brandon Jennings Feb 10, 2026 08:12 PM	

Sequence #	0010-36	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504066	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-36	WO #	2504066	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the External Side Skin Panels of the Fuselage - FS559 to FS755 and Stringer 6L to 20L and 6R to 20R Covered by Pylon	
Detailed Inspection of the External Side Skin Panels of the Fuselage - FS559 to FS755 and Stringer 6L to 20L and 6R to 20R Covered by Pylon				
Task / IRN # : 53-30-00-219				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with TLMC 53-30-00-219, Perform Detailed Inspection of the External Side Skin Panels of the Fuselage - FS559 to FS755 and Stringer 6L to 20L and 6R to 20R Covered by Pylon. In REF: CL-650 AMM 53-30-01-220-819. No defects noted at this time.	B1018339 - Dwain Wolf Feb 13, 2026 08:57 PM	53-30
	Perform Detailed Inspection of the External Side Skin Panels of the Fuselage - FS559 to FS755 and Stringer 6L to 20L and 6R to 20R Covered by Pylon		B0142244 - Todd Bridges Feb 13, 2026 09:50 PM	
	200	Removed all tools, equipment, and unwanted materials from the work area.	B1018339 - Dwain Wolf Feb 13, 2026 08:57 PM	
	Remove all tools, equipment, and unwanted materials from the work area.		B0142244 - Todd Bridges Feb 13, 2026 09:50 PM	

Sequence #	0010-37	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504068	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-37	WO #	2504068	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Internal Skin and Structure of the Aft Auxiliary Tank	
Detailed Inspection of the Internal Skin and Structure of the Aft Auxiliary Tank				
Task / IRN # : 53-30-00-222				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 53-30-00-222, Perform Detailed Inspection of the Internal Skin and Structure of the Aft Auxiliary Tank. REF CL650 AMM 53-30-01-220-850. No defects noted.	B1016542 - Carlos Ochoa Feb 17, 2026 04:28 AM	53-30
	Perform Detailed Inspection of the Internal Skin and Structure of the Aft Auxiliary Tank		B0623124 - Michael Stacy Feb 17, 2026 04:34 AM	
	200	Removed all tools, equipment, and unwanted materials.	B1016542 - Carlos Ochoa Feb 17, 2026 04:28 AM	
	Remove all tools, equipment, and unwanted materials.		B0623124 - Michael Stacy Feb 17, 2026 04:34 AM	

Sequence #	0010-38	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504069	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-38	WO #	2504069	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Special Detailed Inspection of the Skin and Fuselage Structure - FS718.00 to FS755.00	
Special Detailed Inspection of the Skin and Fuselage Structure - FS718.00 to FS755.00				
Task / IRN # : 53-30-00-223				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 53-30-00-223 Performed special detailed inspection of the fuselage skin panels from FS718.00 to FS755.00, between STR7 and STR18. IAW CL650 NDT manual part 6, ET-53-30-012. No defects noted.	B0642788 - Gary Mendoza Feb 26, 2026 07:29 PM	53-30
	Perform Special Detailed Inspection of the Skin and Fuselage Structure - FS718.00 to FS755.00		B1019685 - Wallace Warren Feb 27, 2026 05:36 PM	

TOOL INFORMATION

Tool ID	Tool Description	Calibration Due Date
TUSJ2276	ET Flaw Detector	Oct 30, 2026 5:00 PM

Sequence #	0010-39	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504072	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-39	WO #	2504072	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Aft Face of the Frame - VS67.5%	
Detailed Inspection of the Aft Face of the Frame - VS67.5%				
Task / IRN # : 53-43-00-202				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 53-43-00-202 Detailed Inspection of the Aft Face of the Frame - VS67.50%, REF CL650 AMM 53-43-02-220-801. No defects noted at this time	B0648431 - Caleb Sexton Feb 10, 2026 04:30 PM	53-40
	Perform Detailed Inspection of the Aft Face of the Frame - VS67.5%		B1013522 - Brandon Jennings Feb 10, 2026 04:44 PM	
	200	Removed all tools equipment and unwanted material from the work area	B0648431 - Caleb Sexton Feb 10, 2026 04:30 PM	
	Remove all tools equipment and unwanted material from the work area		B1013522 - Brandon Jennings Feb 10, 2026 04:44 PM	

Sequence #	0010-40	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504073	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-40	WO #	2504073	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Internal Skin and Fuselage Structure - FS755 to VS67.5%	
Detailed Inspection of the Internal Skin and Fuselage Structure - FS755 to VS67.5%				
Task / IRN # : 53-43-00-203				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 53-43-00-203 Detailed Inspection of the Internal Skin and Fuselage Structure - FS755 to VS67.50% REF CL650 AMM 53-43-02-220-802. No defects noted at this time.	B0648431 - Caleb Sexton Feb 10, 2026 06:49 PM	53-40
	Perform Detailed Inspection of the Internal Skin and Fuselage Structure - FS755 to VS67.5%		B1013522 - Brandon Jennings Feb 10, 2026 07:21 PM	
	200	Removed all tools equipment and unwanted material from the work area	B0648431 - Caleb Sexton Feb 10, 2026 06:49 PM	
	Remove all tools equipment and unwanted material from the work area		B1013522 - Brandon Jennings Feb 10, 2026 07:21 PM	

Sequence #	0010-41	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504076	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-41	WO #	2504076	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Internal Skin and Structure of the Tail Tank	
Detailed Inspection of the Internal Skin and Structure of the Tail Tank				
Task / IRN # : 53-50-00-201				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 53-50-00-201, Perform Detailed Inspection of the Internal Skin and Structure of the Tail Tank, in accordance with CL-650 AMM 53-66-01-220-801. No defects noted.	B1022275 - Kaitlynn Maxon Feb 17, 2026 02:38 PM	53-60
	Perform Detailed Inspection of the Internal Skin and Structure of the Tail Tank		B1013522 - Brandon Jennings Feb 17, 2026 02:56 PM	
	200	Removed all tools, materials, and unwanted equipment from the work area.	B1022275 - Kaitlynn Maxon Feb 17, 2026 02:38 PM	
	Remove all tools, equipment, and unwanted materials from the work area.		B1013522 - Brandon Jennings Feb 17, 2026 02:56 PM	

Bombardier

Sequence #	0010-42	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504078	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-42	WO #	2504078	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Floor Structure of the Tail Tank	
Detailed Inspection of the Floor Structure of the Tail Tank				
Task / IRN # : 53-50-00-202				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 53-50-00-202, Perform Detailed Inspection of the Floor Structure of the Tail Tank, in accordance with CL-650 AMM 53-66-01-220-802. No Defects Noted.	B0642051 - Terry Walters Feb 17, 2026 03:27 PM	53-60
	Perform Detailed Inspection of the Floor Structure of the Tail Tank		B1013522 - Brandon Jennings Feb 17, 2026 04:46 PM	
	200	Removed all tools, equipment, and unwanted materials from the work area.	B0642051 - Terry Walters Feb 17, 2026 03:27 PM	
	remove all tools, equipment, and unwanted materials from the work area.		B1013522 - Brandon Jennings Feb 17, 2026 04:46 PM	

Bombardier

Sequence #	0010-43	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504079	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-43	WO #	2504079	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Forward Face of the Fuel Tail Tank Forward Bulkhead	
Detailed Inspection of the Forward Face of the Fuel Tail Tank Forward Bulkhead				
Task / IRN # : 53-50-00-203				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with TLMC task 53-50-00-203 Performed detailed inspection of the forward face of the fuel tail tank forward bulkhead REF CL-650 AMM 53-66-01-220-803. No defecst noted.	B1002512 - Brandon Warne Feb 17, 2026 01:38 PM	53-60
	Perform Detailed Inspection of the Forward Face of the Fuel Tail Tank Forward Bulkhead		B1013522 - Brandon Jennings Feb 17, 2026 01:45 PM	
	200	Removed all tools, equipment and materials from the work area.	B1002512 - Brandon Warne Feb 17, 2026 01:38 PM	
	Remove all tools, equipment and materials from the work area.		B1013522 - Brandon Jennings Feb 17, 2026 01:45 PM	

TOOL INFORMATION

Tool ID	Tool Description	Calibration Due Date
TUSS3348	Borescope	Feb 27, 2027 5:00 PM

Sequence #	0010-44	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	2504080	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2503652

0010-44	**WO #**	**2504080**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		Detailed Inspection of the Aft Face of the Tail Tank Aft Bulkhead	
Detailed Inspection of the Aft Face of the Tail Tank Aft Bulkhead				
Task / IRN # : 53-50-00-204				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 53-50-00-204, Perform Detailed Inspection of the Aft Face of the Tail Tank Aft Bulkhead, in accordance with CL-650 AMM 53-66-01-220-804. No Defects noted.	B0642051 - Terry Walters Feb 17, 2026 03:54 PM	53-60
	Perform Detailed Inspection of the Aft Face of the Tail Tank Aft Bulkhead		B1013522 - Brandon Jennings Feb 17, 2026 04:47 PM	
	200	Removed all tools, equipment, and unwanted materials from the work area.	B0642051 - Terry Walters Feb 17, 2026 03:54 PM	
	Remove all tools, equipment, and unwanted materials from the work area.		B1013522 - Brandon Jennings Feb 17, 2026 04:47 PM	

Sequence #	0010-45	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504084	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-45	WO #	2504084	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Nose Compartment - Lower External	
General Visual Inspection of the Nose Compartment - Lower External				
Task / IRN # : 53-ZL-00-203				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 53-ZL-00-203 General Visual Inspection of the Nose Compartment - Lower External REF CL650 AMM 53-10-01-210-803. No defects noted	B0648431 - Caleb Sexton Feb 12, 2026 07:28 PM	53-10
	Perform General Visual Inspection of the Nose Compartment - Lower External		B1013522 - Brandon Jennings Feb 12, 2026 08:38 PM	
	200	Removed all tools, equipment, and unwanted materials from the work area	B0648431 - Caleb Sexton Feb 12, 2026 07:28 PM	
	Remove all tools, equipment, and unwanted materials from the work area		B1013522 - Brandon Jennings Feb 12, 2026 08:38 PM	

Bombardier

Sequence #	0010-46	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504085	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-46	WO #	2504085	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Nose Compartment - Lower Internal LH	
General Visual Inspection of the Nose Compartment - Lower Internal LH				
Task / IRN # : 53-ZL-00-204				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 53-ZL-00-204 General Visual Inspection of the Nose Compartment - Lower Internal LH REF CL650 AMM 53-10-01-210-804. Defects noted on finding #80009	B0648431 - Caleb Sexton Feb 12, 2026 08:56 PM	53-10
	Perform General Visual Inspection of the Nose Compartment - Lower Internal LH		B1013522 - Brandon Jennings Feb 12, 2026 09:04 PM	
	200	Removed all tools, equipment, and unwanted materials from the work area	B0648431 - Caleb Sexton Feb 12, 2026 08:56 PM	
	Remove all tools, equipment, and unwanted materials from the work area		B1013522 - Brandon Jennings Feb 12, 2026 09:04 PM	

FINDINGS DETAILS

Finding #	Long Description	Status	Reported By / Date	Defect Source / Disposition	Defect Type	Priority	Follow-up WO #
80009	Selector valve in access panel nose compartment access panel 121AL Evidence of hydraulic leak and missing paint on assembly.	CLOSED	B0648431 - Caleb Sexton Feb 12, 2026 1:41 PM	MAINTENANCE 300-QA002	OTHER	3	4765811-RDYLT

Sequence #	0010-47	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504087	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-47	WO #	2504087	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Forward Avionics and Flight Controls Compartment - External	
General Visual Inspection of the Forward Avionics and Flight Controls Compartment - External				
Task / IRN # : 53-ZL-00-207				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 53-ZL-00-207 General Visual Inspection of the Forward Avionics and Flight Controls Compartment - External REF CL650 AMM 53-10-01-210-807. No defects noted at this time.	B0648431 - Caleb Sexton Feb 13, 2026 02:17 PM	53-10
	Perform General Visual Inspection of the Forward Avionics and Flight Controls Compartment - External		B0142244 - Todd Bridges Feb 13, 2026 03:03 PM	
	200	Removed all tools, equipment, and unwanted materials from the work area	B0648431 - Caleb Sexton Feb 13, 2026 02:17 PM	
	Remove all tools, equipment, and unwanted materials from the work area		B0142244 - Todd Bridges Feb 13, 2026 03:03 PM	

Sequence #	0010-48	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504091	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-48	WO #	2504091	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Lower Surface of the Pressure-Floor from FS409 to FS559	
General Visual Inspection of the Lower Surface of the Pressure-Floor from FS409 to FS559				
Task / IRN # : 53-ZL-00-213				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 53-ZL-00-213, General Visual Inspection of the lower surface of the pressure-floor from FS409 to FS559. REF:CL-650AMM 53-20-01-210-804, no defects noted	B1018409 - Areida Cruz Feb 08, 2026 05:10 PM	53-20
	Perform General Visual Inspection of the Lower Surface of the Pressure-Floor from FS409 to FS559		B0142244 - Todd Bridges Feb 08, 2026 05:36 PM	
	200	Removed all tools, equipment, and unwanted materials from the work area	B1018409 - Areida Cruz Feb 08, 2026 05:10 PM	
	Remove all tools, equipment, and unwanted materials from the work area		B0142244 - Todd Bridges Feb 08, 2026 05:36 PM	

Sequence #	0010-49	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504092	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-49	WO #	2504092	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Mid-Fuselage between the Pressure Floor and the Cabin Floor - Lower Internal	
General Visual Inspection of the Mid-Fuselage between the Pressure Floor and the Cabin Floor - Lower Internal				
Task / IRN # : 53-ZL-00-215				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 53-ZL-00-215, Perform General Visual Inspection of the Mid-Fuselage between the Pressure Floor and the Cabin Floor - Lower Internal. REF CL650 AMM 53-20-01-210-806. No defects noted.	B1016542 - Carlos Ochoa Feb 14, 2026 04:48 AM	53-20
	Perform General Visual Inspection of the Mid-Fuselage between the Pressure Floor and the Cabin Floor - Lower Internal		B0161691 - Thomas Mitchell Feb 14, 2026 04:57 AM	
	200	Removed all tools, equipment, and unwanted materials.	B1016542 - Carlos Ochoa Feb 14, 2026 04:48 AM	
	Remove all tools, equipment, and unwanted materials.		B0161691 - Thomas Mitchell Feb 14, 2026 04:57 AM	

Sequence #	0010-50	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504093	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-50	WO #	2504093	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Aft Compartment and Aft Wing-to-Fuselage Fairing - External	
General Visual Inspection of the Aft Compartment and Aft Wing-to-Fuselage Fairing - External				
Task / IRN # : 53-ZL-00-216				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 53-ZL-00-216 General Visual Inspection of the Aft Compartment and Aft Wing-to-Fuselage Fairing - External REF CL650 AMM 53-30-01-210-801. No defects noted at this time	B0648431 - Caleb Sexton Feb 13, 2026 03:34 PM	53-30
	Perform General Visual Inspection of the Aft Compartment and Aft Wing-to-Fuselage Fairing - External		B1019908 - Joseph Barnes Feb 13, 2026 03:48 PM	
	200	Removed all tools, equipment and unwanted materials from the work area	B0648431 - Caleb Sexton Feb 13, 2026 03:34 PM	
	Remove all tools, equipment and unwanted materials from the work area		B1019908 - Joseph Barnes Feb 13, 2026 03:48 PM	

Bombardier

Sequence #	0010-51	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504097	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-51	WO #	2504097	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Forward Equipment Compartment - External	
General Visual Inspection of the Forward Equipment Compartment - External				
Task / IRN # : 53-ZL-00-218				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 53-ZL-00-218 General Visual Inspection of the Forward Equipment Compartment - External REF CL650 AMM 53-10-01-210-809. No defects noted at this time	B0648431 - Caleb Sexton Feb 16, 2026 01:42 PM	53-10
	Perform General Visual Inspection of the Forward Equipment Compartment - External		B1019908 - Joseph Barnes Feb 16, 2026 02:08 PM	
	200	Removed all tools, equipment, and unwanted materials from the work area	B0648431 - Caleb Sexton Feb 16, 2026 01:42 PM	
	Remove all tools, equipment, and unwanted materials from the work area		B1019908 - Joseph Barnes Feb 16, 2026 02:08 PM	

Sequence #	0010-52	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504098	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-52	WO #	2504098	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Passenger Compartment - External	
General Visual Inspection of the Passenger Compartment - External				
Task / IRN # : 53-ZL-00-222				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 53-ZL-00-222 General Visual Inspection of the Passenger Compartment - External REF CL650 AMM 53-20-01-210-807. No defects noted at this time.	B0648431 - Caleb Sexton Feb 16, 2026 06:58 PM	53-20
	Perform General Visual Inspection of the Passenger Compartment - External		B1017318 - Steve Pritchett Feb 16, 2026 07:46 PM	
	200	Removed all tools, equipment, and unwanted materials from the work area	B0648431 - Caleb Sexton Feb 16, 2026 06:58 PM	
	Remove all tools, equipment, and unwanted materials from the work area		B1013522 - Brandon Jennings Feb 17, 2026 05:38 PM	

Bombardier

Sequence #	0010-53	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504101	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-53	WO #	2504101	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Cargo Compartment - External	
General Visual Inspection of the Cargo Compartment - External				
Task / IRN # : 53-ZL-00-224				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 53-ZL-00-224, Perform General Visual Inspection of the Cargo Compartment - External, in accordance with CL-650 AMM 53-30-01-210-803. No defects noted.	B0642051 - Terry Walters Feb 04, 2026 08:51 PM	53-30
	Perform General Visual Inspection of the Cargo Compartment - External		B1013522 - Brandon Jennings Feb 04, 2026 08:59 PM	
	200	Removed all tools, equipment, and unwanted materials from the work area.	B0642051 - Terry Walters Feb 04, 2026 08:51 PM	
	Remove all tools, equipment, and unwanted materials from the work area.		B1013522 - Brandon Jennings Feb 04, 2026 08:59 PM	

Sequence #	0010-54	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504103	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-54	WO #	2504103	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Cargo Compartment - Internal without Removal of the Headliner	
General Visual Inspection of the Cargo Compartment - Internal without Removal of the Headliner				
Task / IRN # : 53-ZL-00-225				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 53-ZL-00-225 General Visual Inspection of the Cargo Compartment - Internal without Removal of the Headliner REF CL650 AMM 53-30-01-210-807. No defects noted at this time.	B0648431 - Caleb Sexton Feb 16, 2026 04:07 PM	53-30
	Perform General Visual Inspection of the Cargo Compartment - Internal without Removal of the Headliner		B1019908 - Joseph Barnes Feb 16, 2026 04:18 PM	
	200	Removed all tools, equipment, and unwanted materials from the work area	B0648431 - Caleb Sexton Feb 16, 2026 04:07 PM	
	Remove all tools, equipment, and unwanted materials from the work area		B1019908 - Joseph Barnes Feb 16, 2026 04:18 PM	

Bombardier

Sequence #	0010-55	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504104	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-55	WO #	2504104	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Fuselage/Stabilizer Section - External	
General Visual Inspection of the Fuselage/Stabilizer Section - External				
Task / IRN # : 53-ZL-00-229				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 53-ZL-00-229, Perform General Visual Inspection of the Fuselage/Stabilizer Section - External, in accordance with CL650 AMM 53-43-01-210-801. No defects noted.	B1019545 - Tharathorn Locham Feb 12, 2026 03:26 PM	53-40
	Perform General Visual Inspection of the Fuselage/ Stabilizer Section - External		B1013522 - Brandon Jennings Feb 12, 2026 03:50 PM	
	200	Removed all tools equipment and unwanted material from work area	B1019545 - Tharathorn Locham Feb 12, 2026 03:26 PM	
	Remove all tools equipment and unwanted material from work area		B1013522 - Brandon Jennings Feb 12, 2026 03:50 PM	

Bombardier

Sequence #	0010-56	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504107	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-56	WO #	2504107	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Mid-Fuselage Compartment - Lower Internal (FS559.0 to FS621.0)	
General Visual Inspection of the Mid-Fuselage Compartment - Lower Internal (FS559.0 to FS621.0)				
Task / IRN # : 53-ZL-00-233				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 53-ZL-00-233 General Visual Inspection of the Mid-Fuselage Compartment - Lower Internal (FS559.0 to FS621.0) REF CL650 AMM 53-20-01-210-809. No defects noted at this time.	B0648431 - Caleb Sexton Feb 16, 2026 04:55 PM	53-20
	Perform General Visual Inspection of the Mid-Fuselage Compartment - Lower Internal (FS559.0 to FS621.0)		B1019908 - Joseph Barnes Feb 16, 2026 05:28 PM	
	200	Removed all tools, equipment, and unwanted materials from the work area	B0648431 - Caleb Sexton Feb 16, 2026 04:55 PM	
	Remove all tools, equipment, and unwanted materials from the work area		B1019908 - Joseph Barnes Feb 16, 2026 05:28 PM	

Sequence #	0010-57	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	2504109	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2503652

0010-57	**WO #**	**2504109**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		General Visual Inspection of the Pylon Trailing Edge - Internal LH	
General Visual Inspection of the Pylon Trailing Edge - Internal LH				
Task / IRN # : 54-ZL-00-207				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 54-ZL-00-207, Perform General Visual Inspection of the Pylon Trailing Edge - Internal LH, REF: 650 AMM 54-62-04-210-801. No defects noted.	B0646464 - Jonathan Nelson Feb 05, 2026 05:08 AM	54-60
	Perform General Visual Inspection of the Pylon Trailing Edge - Internal LH		B0623124 - Michael Stacy Feb 05, 2026 05:14 AM	
	200	Removed all tools, equipment, and unwanted materials to prevent foreign object damage (FOD) to the aircraft.	B0646464 - Jonathan Nelson Feb 05, 2026 05:08 AM	
	Remove all tools, equipment, and unwanted materials to prevent foreign object damage (FOD) to the aircraft.		B0623124 - Michael Stacy Feb 05, 2026 05:14 AM	

Bombardier

Sequence #	0010-58	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504110	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-58	WO #	2504110	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Pylon Trailing Edge - Internal RH	
General Visual Inspection of the Pylon Trailing Edge - Internal RH				
Task / IRN # : 54-ZL-00-208				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 54-ZL-00-208, Perform General Visual Inspection of the Pylon Trailing Edge - Internal RH, REF: Challenger 650 AMM 54-62-04-210-801. No defects noted.	B0646464 - Jonathan Nelson Feb 05, 2026 05:12 AM	54-60
	Perform General Visual Inspection of the Pylon Trailing Edge - Internal RH		B0623124 - Michael Stacy Feb 05, 2026 05:16 AM	
	200	Removed all tools, equipment, and unwanted materials to prevent foreign object damage (FOD) to the aircraft.	B0646464 - Jonathan Nelson Feb 05, 2026 05:12 AM	
	Remove all tools, equipment, and unwanted materials to prevent foreign object damage (FOD) to the aircraft.		B0623124 - Michael Stacy Feb 05, 2026 05:16 AM	

Sequence #	0010-59	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504113	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-59	WO #	2504113	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Upper Face of the Top Canted Rib and the Rib Fittings of the Vertical Stabilizer and the Attachment Fittings and Skin Splices of the Horizontal Stabilizer	
Detailed Inspection of the Upper Face of the Top Canted Rib and the Rib Fittings of the Vertical Stabilizer and the Attachment Fittings and Skin Splices of the Horizontal Stabilizer				
Task / IRN # : 55-10-00-201				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with TLMC task 55-10-00-201 Performed Detailed Inspection of the Upper Face of the Top Canted Rib and the Rib Fittings of the Vertical Stabilizer and the Attachment Fittings and Skin Splices of the Horizontal Stabilizer REF CL-650 AMM 55-00-00-220-803. No defects noted.	B1002512 - Brandon Warne Feb 17, 2026 09:01 PM	55-10
	Perform Detailed Inspection of the Upper Face of the Top Canted Rib and the Rib Fittings of the Vertical Stabilizer and the Attachment Fittings and Skin Splices of the Horizontal Stabilizer		B1013522 - Brandon Jennings Feb 17, 2026 09:16 PM	
	200	Removed all tools, equipment and materials from the work area.	B1002512 - Brandon Warne Feb 17, 2026 09:01 PM	
	Remove all tools, equipment and materials from the work area.		B1013522 - Brandon Jennings Feb 17, 2026 09:16 PM	

Bombardier

Sequence #	0010-60	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504115	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-60	WO #	2504115	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Front Spar of the Horizontal Stabilizer	
Detailed Inspection of the Front Spar of the Horizontal Stabilizer				
Task / IRN # : 55-10-00-202				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 55-10-00-202, detailed inspection of the front spar of the horizontal stabilizer. Ref:CL-650 AMM 55-10-01-220-802, no defects noted	B1018409 - Areida Cruz Feb 09, 2026 12:04 AM	55-10
	Perform Detailed Inspection of the Front Spar of the Horizontal Stabilizer		B0142244 - Todd Bridges Feb 09, 2026 12:33 AM	
	200	Removed all tools, equipment, and unwanted materials from the work area	B1018409 - Areida Cruz Feb 09, 2026 12:04 AM	
	Remove all tools, equipment, and unwanted materials from the work area		B0142244 - Todd Bridges Feb 09, 2026 12:33 AM	

Sequence #	0010-61	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504117	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-61	WO #	2504117	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Horizontal Stabilizer (internal skins, structure, rear spar and hinge fittings) and the Elevator (forward face of the front spar, hinge fittings and bolts)	
Detailed Inspection of the Horizontal Stabilizer (internal skins, structure, rear spar and hinge fittings) and the Elevator (forward face of the front spar, hinge fittings and bolts)				
Task / IRN # : 55-10-00-203				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with TLMC task 55-10-00-203 Performed Detailed Inspection of the Horizontal Stabilizer (internal skins, structure, rear spar and hinge fittings) and the Elevator (forward face of the front spar, hinge fittings and bolts) REF CL-650 AMM 55-00-00-220-801. No defects noted.	B1002512 - Brandon Warne Feb 17, 2026 06:49 PM	55-00
	Perform Detailed Inspection of the Horizontal Stabilizer (internal skins, structure, rear spar and hinge fittings) and the Elevator (forward face of the front spar, hinge fittings and bolts)		B1013522 - Brandon Jennings Feb 17, 2026 07:15 PM	
	200	Removed all tools, equipment and materials from the work area.	B1002512 - Brandon Warne Feb 17, 2026 06:49 PM	
	Remove all tools, equipment and materials from the work area.		B1013522 - Brandon Jennings Feb 17, 2026 07:15 PM	

Bombardier

Sequence #	0010-62	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504119	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-62	WO #	2504119	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the External Surfaces of the Elevator	
Detailed Inspection of the External Surfaces of the Elevator				
Task / IRN # : 55-20-00-202				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with Task 55-20-00-202. Performed Detailed Inspection of the External Surfaces of the Elevator, in reference to CL-650 AMM 55-20-01-220-802. See findings 80234 and 80235 for details.	B0638589 - Sean Dodder Feb 13, 2026 11:05 PM	55-20
	Perform Detailed Inspection of the External Surfaces of the Elevator		B0161691 - Thomas Mitchell Feb 14, 2026 03:28 AM	
	200	Removed all tools, equipment, and unwanted materials from the work area.	B0638589 - Sean Dodder Feb 13, 2026 11:05 PM	
	Remove all tools, equipment, and unwanted materials from the work area.		B0161691 - Thomas Mitchell Feb 14, 2026 03:28 AM	

FINDINGS DETAILS

Finding #	Long Description	Status	Reported By / Date	Defect Source / Disposition	Defect Type	Priority	Follow-up WO #
80234	On RH Elevator, multiple spots within the middle and inboard hinge locations need touch up primer and paint. Has exposed metal. Photos included.	CLOSED	B0638589 - Sean Dodder Feb 13, 2026 3:28 PM	MAINTENANCE 300-QA002	OTHER	3	4796018-PSAP
80235	On LH Elevator, multiple spots within the middle and outboard hinge locations need touch up primer and paint. Has exposed metal. Photos included.	CLOSED	B0638589 - Sean Dodder Feb 13, 2026 3:46 PM	MAINTENANCE 300-QA002	OTHER	3	4796020-PSAP

Sequence #	0010-63	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504120	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-63	WO #	2504120	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Vertical-Stabilizer (Forward Side of the Front Spar, Attachment Fittings and the Splice Strap)	
Detailed Inspection of the Vertical-Stabilizer (Forward Side of the Front Spar, Attachment Fittings and the Splice Strap)				
Task / IRN # : 55-30-00-201				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 55-30-00-201, Perform Detailed Inspection of the Vertical-Stabilizer (Forward Side of the Front Spar, Attachment Fittings and the Splice Strap), in accordance with CL650 AMM 55-30-01-220-812. No defects noted.	B1019545 - Tharathorn Locham Feb 12, 2026 05:45 PM	55-30
	Perform Detailed Inspection of the Vertical-Stabilizer (Forward Side of the Front Spar, Attachment Fittings and the Splice Strap)		B1013522 - Brandon Jennings Feb 12, 2026 06:55 PM	
	200	Removed all tools, equipment, and unwanted materials from the work area	B1019545 - Tharathorn Locham Feb 12, 2026 05:45 PM	
	Remove all tools, equipment, and unwanted materials from the work area		B1013522 - Brandon Jennings Feb 12, 2026 06:55 PM	

Bombardier

Sequence #	0010-64	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504123	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-64	WO #	2504123	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Internal Structure of the Vertical Stabilizer	
Detailed Inspection of the Internal Structure of the Vertical Stabilizer				
Task / IRN # : 55-30-00-206				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with TLMC task 55-30-00-206 Performed detailed inspection of the internal structure of the vertical stabilizer REF CL-650 AMM 55-30-01-220-806. No defects noted.	B1002512 - Brandon Warne Feb 17, 2026 04:30 PM	55-30
	Perform Detailed Inspection of the Internal Structure of the Vertical Stabilizer		B1013522 - Brandon Jennings Feb 17, 2026 04:41 PM	
	200	Removed all tools, equipment and materials from the work area.	B1002512 - Brandon Warne Feb 17, 2026 04:30 PM	
	Remove all tools, equipment and materials from the work area.		B1013522 - Brandon Jennings Feb 17, 2026 04:41 PM	

Bombardier

Sequence #	0010-65	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504125	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-65	WO #	2504125	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the External Surfaces of the Rudder	
Detailed Inspection of the External Surfaces of the Rudder				
Task / IRN # : 55-40-00-201				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with Task 55-40-00-201. Performed Detailed Inspection of the External Surfaces of the Rudder, in reference to CL-650 AMM 55-40-01-220-801. See finding 79762 for details.	B0638589 - Sean Dodder Feb 10, 2026 11:32 PM	55-40
	Perform Detailed Inspection of the External Surfaces of the Rudder		B0623124 - Michael Stacy Feb 10, 2026 11:36 PM	
	200	Removed all tools, equipment, and unwanted materials from the work area.	B0638589 - Sean Dodder Feb 10, 2026 11:32 PM	
	Remove all tools, equipment, and unwanted materials from the work area.		B0623124 - Michael Stacy Feb 10, 2026 11:36 PM	

FINDINGS DETAILS

Finding #	Long Description	Status	Reported By / Date	Defect Source / Disposition	Defect Type	Priority	Follow-up WO #
79762	The structure below the rudder, has protective tape covering that is torn on the bottom and is lifting on top left hand corner. Found during Detailed Inspection of the External Surfaces of the Rudder. Photos are included.	CLOSED	B0638589 - Sean Dodder Feb 10, 2026 3:49 PM	MAINTENANCE 300-QA002	OTHER	3	4755876-PSAP

Sequence #	0010-66	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504126	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-66	WO #	2504126	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Rudder (Forward Face of the Front Spar and Hinge Bolts) and the Vertical Stabilizer (Aft Face of the Rear Spar and Rudder Hinge Fittings)	
Detailed Inspection of the Rudder (Forward Face of the Front Spar and Hinge Bolts) and the Vertical Stabilizer (Aft Face of the Rear Spar and Rudder Hinge Fittings)				
Task / IRN # : 55-40-00-202				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with TLMC task 55-40-00-202 Performed Detailed Inspection of the Rudder (Forward Face of the Front Spar and Hinge Bolts) and the Vertical Stabilizer (Aft Face of the Rear Spar and Rudder Hinge Fittings) REF CL-650 AMM 55-00-00-220-802. No defects noted.	B1002512 - Brandon Warne Feb 17, 2026 03:23 PM	55-00
	Perform Detailed Inspection of the Rudder (Forward Face of the Front Spar and Hinge Bolts) and the Vertical Stabilizer (Aft Face of the Rear Spar and Rudder Hinge Fittings)		B1013522 - Brandon Jennings Feb 17, 2026 03:48 PM	
	200	Removed all tools, equipment and materials from the work area.	B1002512 - Brandon Warne Feb 17, 2026 03:23 PM	
	Remove all tools, equipment and materials from the work area.		B1013522 - Brandon Jennings Feb 17, 2026 03:48 PM	

Sequence #	0010-67	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504129	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-67	WO #	2504129	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Ram Air Intake and Dorsal Fairing - Internal	
General Visual Inspection of the Ram Air Intake and Dorsal Fairing - Internal				
Task / IRN # : 55-ZL-00-202				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with Task No. 55-ZL-00-202. Performed a GVI of the Ram Air Intake and Dorsal Fairing (INTERNAL). No defects noted. Ref: CL650 AMM 55-30-01-210-802	B0646266 - Sergio Rodriguez Figueroa Feb 09, 2026 08:53 PM	55-30
	Perform General Visual Inspection of the Ram Air Intake and Dorsal Fairing - Internal		B1013522 - Brandon Jennings Feb 09, 2026 09:09 PM	
	200	Removed all tools, equipment, and unwanted materials from the work area as required.	B0646266 - Sergio Rodriguez Figueroa Feb 09, 2026 08:53 PM	
	Remove all tools, equipment, and unwanted material from the work area.		B1013522 - Brandon Jennings Feb 09, 2026 09:09 PM	

Sequence #	0010-68	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504130	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-68	WO #	2504130	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Leading Edge of the Vertical Stabilizer - Internal	
General Visual Inspection of the Leading Edge of the Vertical Stabilizer - Internal				
Task / IRN # : 55-ZL-00-203				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 55-ZL-00-203, Perform General Visual Inspection of the Leading Edge of the Vertical Stabilizer - Internal, in accordance with CL650 AMM 55-30-01-210-803. No defects noted.	B1019545 - Tharathorn Locham Feb 12, 2026 04:12 PM	55-30
	Perform General Visual Inspection of the Leading Edge of the Vertical Stabilizer - Internal		B1013522 - Brandon Jennings Feb 12, 2026 06:56 PM	
	200	Removed all tools equipment and unwanted material from work area	B1019545 - Tharathorn Locham Feb 12, 2026 04:12 PM	
	Remove all tools equipment and unwanted material from work area		B1013522 - Brandon Jennings Feb 12, 2026 06:56 PM	

Bombardier

Sequence #	0010-69	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504132	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-69	WO #	2504132	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Vertical Stabilizer - Internal	
General Visual Inspection of the Vertical Stabilizer - Internal				
Task / IRN # : 55-ZL-00-204				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 55-ZL-00-204 General Visual Inspection of the Vertical Stabilizer - Internal REF CL650 AMM 55-30-01-210-804. No defects noted at this time	B0648431 - Caleb Sexton Feb 10, 2026 08:31 PM	55-30
	Perform General Visual Inspection of the Vertical Stabilizer - Internal		B1013522 - Brandon Jennings Feb 10, 2026 08:49 PM	
	200	Removed all tools equipment and unwanted material from the work area	B0648431 - Caleb Sexton Feb 10, 2026 08:31 PM	
	Remove all tools equipment and unwanted material from the work area		B1013522 - Brandon Jennings Feb 10, 2026 08:49 PM	

Sequence #	0010-70	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504135	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-70	WO #	2504135	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Tip of the Vertical Stabilizer - Internal	
General Visual Inspection of the Tip of the Vertical Stabilizer - Internal				
Task / IRN # : 55-ZL-00-205				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 55-ZL-00-205 General Visual Inspection of the Tip of the Vertical Stabilizer - Internal REF CL650 AMM 55-30-01-210-805. No defects noted at this time.	B0648431 - Caleb Sexton Feb 10, 2026 08:41 PM	55-30
	Perform General Visual Inspection of the Tip of the Vertical Stabilizer - Internal		B1013522 - Brandon Jennings Feb 10, 2026 08:50 PM	
	200	Removed all tools equipment and unwanted material from the work area	B0648431 - Caleb Sexton Feb 10, 2026 08:41 PM	
	Remove all tools equipment and unwanted material from the work area		B1013522 - Brandon Jennings Feb 10, 2026 08:50 PM	

Sequence #	0010-71	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504136	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-71	WO #	2504136	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Horizontal Stabilizer - External LH	
General Visual Inspection of the Horizontal Stabilizer - External LH				
Task / IRN # : 55-ZL-00-206				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with Task No. 55-ZL-00-206. Performed a GVI of the Horizontal Stabilizer (LH, EXTERNAL). No defects noted. Ref: CL650 AMM 55-10-01-210-801	B0646266 - Sergio Rodriguez Figueroa Feb 09, 2026 02:42 PM	55-10
	Perform General Visual Inspection of the Horizontal Stabilizer - External LH		B1013522 - Brandon Jennings Feb 09, 2026 03:30 PM	
	200	Removed all tools, equipment, and unwanted materials from the work area as required.	B0646266 - Sergio Rodriguez Figueroa Feb 09, 2026 02:45 PM	
	Remove all tools, equipment, and unwanted material from the work area.		B1013522 - Brandon Jennings Feb 09, 2026 03:30 PM	

Sequence #	0010-72	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504139	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-72	WO #	2504139	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Horizontal Stabilizer - External RH	
General Visual Inspection of the Horizontal Stabilizer - External RH				
Task / IRN # : 55-ZL-00-207				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with Task No. 55-ZL-00-207. Performed a GVI of the Horizontal Stabilizer (RH, EXTERNAL). No defects noted. Ref: CL650 AMM 55-10-01-210-801	B0646266 - Sergio Rodriguez Figueroa Feb 09, 2026 02:49 PM	55-10
	Perform General Visual Inspection of the Horizontal Stabilizer - External RH		B1013522 - Brandon Jennings Feb 09, 2026 03:31 PM	
	200	Removed all tools, equipment, and unwanted materials from the work area as required.	B0646266 - Sergio Rodriguez Figueroa Feb 09, 2026 02:49 PM	
	Remove all tools, equipment, and unwanted material from the work area.		B1013522 - Brandon Jennings Feb 09, 2026 03:31 PM	

Sequence #	0010-73	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504141	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-73	WO #	2504141	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Leading Edge of the Horizontal Stabilizer - Internal LH	
General Visual Inspection of the Leading Edge of the Horizontal Stabilizer - Internal LH				
Task / IRN # : 55-ZL-00-208				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with Task 55-ZL-00-208. Performed General Visual Inspection of the Leading Edge of the Horizontal Stabilizer - Internal LH, in reference to CL-650 AMM 55-10-01-210-803. No defects were noted at this time.	B0638589 - Sean Dodder Feb 11, 2026 04:42 AM	55-10
	Perform General Visual Inspection of the Leading Edge of the Horizontal Stabilizer - Internal LH		B0623124 - Michael Stacy Feb 11, 2026 04:48 AM	
	200	Removed all tools, equipment, and unwanted materials from the work area.	B0638589 - Sean Dodder Feb 11, 2026 04:42 AM	
	Remove all tools, equipment, and unwanted materials from the work area.		B0623124 - Michael Stacy Feb 11, 2026 04:48 AM	

Sequence #	0010-74	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504142	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-74	WO #	2504142	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Leading Edge of the Horizontal Stabilizer - Internal RH	
General Visual Inspection of the Leading Edge of the Horizontal Stabilizer - Internal RH				
Task / IRN # : 55-ZL-00-209				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with Task 55-ZL-00-209. Performed General Visual Inspection of the Leading Edge of the Horizontal Stabilizer - Internal RH, in reference to CL-650 AMM 55-10-01-210-803. No defects were noted at this time.	B0638589 - Sean Dodder Feb 11, 2026 12:58 AM	55-10
	Perform General Visual Inspection of the Leading Edge of the Horizontal Stabilizer - Internal RH		B0623124 - Michael Stacy Feb 11, 2026 04:49 AM	
	200	Removed all tools, equipment, and unwanted materials from the work area.	B0638589 - Sean Dodder Feb 11, 2026 12:58 AM	
	Remove all tools, equipment, and unwanted materials from the work area.		B0623124 - Michael Stacy Feb 11, 2026 04:49 AM	

Bombardier

Sequence #	0010-75	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504144	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-75	WO #	2504144	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Horizontal Stabilizer - Internal LH	
General Visual Inspection of the Horizontal Stabilizer - Internal LH				
Task / IRN # : 55-ZL-00-210				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with Task No. 55-ZL-00-210. Performed a GVI of the Horizontal Stabilizer (LH, INTERNAL). No defects noted. Ref: CL650 AMM 55-10-01-210-802	B0646266 - Sergio Rodriguez Figueroa Feb 09, 2026 04:08 PM	55-10
	Perform General Visual Inspection of the Horizontal Stabilizer - Internal LH		B1013522 - Brandon Jennings Feb 09, 2026 04:27 PM	
	200	Removed all tools, equipment, and unwanted materials from the work area as required.	B0646266 - Sergio Rodriguez Figueroa Feb 09, 2026 04:14 PM	
	Remove all tools, equipment, and unwanted material from the work area.		B1013522 - Brandon Jennings Feb 09, 2026 04:27 PM	

Bombardier

Sequence #	0010-76	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504147	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-76	WO #	2504147	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Horizontal Stabilizer - Internal RH	
General Visual Inspection of the Horizontal Stabilizer - Internal RH				
Task / IRN # : 55-ZL-00-211				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with Task No. 55-ZL-00-211. Performed a GVI of the Horizontal Stabilizer (RH, INTERNAL). No defects noted. Ref: CL650 AMM 55-10-01-210-802	B0646266 - Sergio Rodriguez Figueroa Feb 09, 2026 04:33 PM	55-10
	Perform General Visual Inspection of the Horizontal Stabilizer - Internal RH		B1013522 - Brandon Jennings Feb 09, 2026 04:52 PM	
	200	Removed all tools, equipment, and unwanted materials from the work area as required.	B0646266 - Sergio Rodriguez Figueroa Feb 09, 2026 04:33 PM	
	Remove all tools, equipment, and unwanted material from the work area.		B1013522 - Brandon Jennings Feb 09, 2026 04:52 PM	

Sequence #	0010-77	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504148	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-77	WO #	2504148	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the External Center Wing (Front Spar and the Bayonet Fitting) - LWS50.00 to RWS50.00	
Detailed Inspection of the External Center Wing (Front Spar and the Bayonet Fitting) - LWS50.00 to RWS50.00				
Task / IRN # : 57-10-00-201				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with TLMC task 57-10-00-201 Performed detailed inspection of the external center wing (Front spar and the bayonet fitting) from LWS50.00 to RWS50.00 REF CL-650 AMM 57-10-00-220-866. No defects noted.	B1002512 - Brandon Warne Feb 10, 2026 09:00 PM	57-10
	Perform Detailed Inspection of the External Center Wing (Front Spar and the Bayonet Fitting) - LWS50.00 to RWS50.00		B1013522 - Brandon Jennings Feb 10, 2026 09:05 PM	
	200	Removed all tools equipment and materials from the work area.	B1002512 - Brandon Warne Feb 10, 2026 09:00 PM	
	Remove all tools equipment and materials from the work area.		B1013522 - Brandon Jennings Feb 10, 2026 09:05 PM	

Bombardier

Sequence #	0010-78	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504150	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-78	WO #	2504150	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Front Spar of the Wing Center Section - External	
General Visual Inspection of the Front Spar of the Wing Center Section - External				
Task / IRN # : 57-ZL-00-203				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 57-ZL-00-203 General Visual Inspection of the Front Spar of the Wing Center Section - External REF CL650 AMM 57-10-00-210-807. No defects noted at this time	B0648431 - Caleb Sexton Feb 12, 2026 06:58 PM	57-10
	Perform General Visual Inspection of the Front Spar of the Wing Center Section - External		B1019908 - Joseph Barnes Feb 12, 2026 07:37 PM	
	200	Removed all tools, equipment, and unwanted materials from the work area	B0648431 - Caleb Sexton Feb 12, 2026 06:58 PM	
	Remove all tools, equipment, and unwanted materials from the work area		B1019908 - Joseph Barnes Feb 12, 2026 07:37 PM	

Sequence #	0010-79	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	2504153	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2503652

0010-79	**WO #**	**2504153**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		General Visual Inspection of the Wing Center Section - Internal LH	
General Visual Inspection of the Wing Center Section - Internal LH				
Task / IRN # : 57-ZL-00-204				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with TLMC task 57-ZL-00-204 Performed general visual inspection of the LH center section (Internal). REF CL-650 AMM 57-10-00-210-802. No defects noted.	B1002512 - Brandon Warne Feb 09, 2026 04:49 PM	57-10
	Perform General Visual Inspection of the Wing Center Section - Internal LH		B1013522 - Brandon Jennings Feb 09, 2026 04:57 PM	
	200	Removed all tools, equipment and materials from the work area.	B1002512 - Brandon Warne Feb 09, 2026 04:49 PM	
	Remove all tools, equipment and materials from the work area.		B1013522 - Brandon Jennings Feb 09, 2026 04:57 PM	

Bombardier

Sequence #	0010-80	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504154	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-80	WO #	2504154	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Wing Center Section - Internal RH	
General Visual Inspection of the Wing Center Section - Internal RH				
Task / IRN # : 57-ZL-00-205				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with TLMC task 57-ZL-00-205 Performed general visual inspection of the RH wing center section (Internal) REF CL-650 AMM 57-10-00-210-802. No defects noted.	B1002512 - Brandon Warne Feb 09, 2026 07:58 PM	57-10
	Perform General Visual Inspection of the Wing Center Section - Internal RH		B1013522 - Brandon Jennings Feb 09, 2026 08:31 PM	
	200	Removed all tools, equipment and materials from the work area.	B1002512 - Brandon Warne Feb 09, 2026 07:58 PM	
	Remove all tools, equipment and materials from the work area.		B1013522 - Brandon Jennings Feb 09, 2026 08:31 PM	

Sequence #	0010-81	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504155	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-81	WO #	2504155	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Inboard Leading Edge of the Wing - Internal LH	
General Visual Inspection of the Inboard Leading Edge of the Wing - Internal LH				
Task / IRN # : 57-ZL-00-208				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 57-ZL-00-208, Perform General Visual Inspection of the Inboard Leading Edge of the Wing - Internal LH, in accordance with 650 MM 57-40-00-210-802. No defects noted at this time.	B0142041 - Timothy Winfree Feb 06, 2026 03:22 PM	57-40
	Perform General Visual Inspection of the Inboard Leading Edge of the Wing - Internal LH		B0142244 - Todd Bridges Feb 06, 2026 10:44 PM	
	200	Removed all tools, equipment and unwanted materials from the work area.	B0142041 - Timothy Winfree Feb 06, 2026 11:47 PM	
	FOD statement -		B0142244 - Todd Bridges Feb 07, 2026 03:55 PM	

Sequence #	0010-82	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504159	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-82	WO #	2504159	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Inboard Leading Edge of the Wing - Internal RH	
General Visual Inspection of the Inboard Leading Edge of the Wing - Internal RH				
Task / IRN # : 57-ZL-00-209				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 57-ZL-00-209, Perform General Visual Inspection of the Inboard Leading Edge of the Wing - Internal RH, in accordance with 650 MM 57-40-00-210-802. No defects noted at this time.	B0142041 - Timothy Winfree Feb 06, 2026 04:34 PM	57-40
	Perform General Visual Inspection of the Inboard Leading Edge of the Wing - Internal RH		B0142244 - Todd Bridges Feb 06, 2026 10:46 PM	
	200	Removed all tools, equipment and unwanted materials from the work area.	B0142041 - Timothy Winfree Feb 06, 2026 11:49 PM	
	FOD statement -		B0142244 - Todd Bridges Feb 07, 2026 03:54 PM	

Bombardier

Sequence #	0010-83	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504160	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-83	WO #	2504160	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Outboard Leading Edge of the Wing - Internal LH	
General Visual Inspection of the Outboard Leading Edge of the Wing - Internal LH				
Task / IRN # : 57-ZL-00-212				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 57-ZL-00-212, Perform General Visual Inspection of the Outboard Leading Edge of the Wing - Internal LH, in accordance with 650 MM 57-40-00-210-804. No defects noted at this time.	B0142041 - Timothy Winfree Feb 06, 2026 11:22 PM	57-40
	Perform General Visual Inspection of the Outboard Leading Edge of the Wing - Internal LH		B0142244 - Todd Bridges Feb 07, 2026 12:27 AM	
	200	Removed all tools, equipment and unwanted materials from the work area.	B0142041 - Timothy Winfree Feb 06, 2026 11:52 PM	
	FOD statement		B0142244 - Todd Bridges Feb 07, 2026 12:27 AM	

Bombardier

Sequence #	0010-84	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504161	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-84	WO #	2504161	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Outboard Leading Edge of the Wing - Internal RH	
General Visual Inspection of the Outboard Leading Edge of the Wing - Internal RH				
Task / IRN # : 57-ZL-00-213				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 57-ZL-00-213, Perform General Visual Inspection of the Outboard Leading Edge of the Wing - Internal RH, in accordance with 650 MM 57-40-00-210-804. No defects noted at this time. Removed all tools, equipment and unwanted materials from the work area.	B0142041 - Timothy Winfree Feb 07, 2026 12:24 AM	57-40
	Perform General Visual Inspection of the Outboard Leading Edge of the Wing - Internal RH		B0142244 - Todd Bridges Feb 07, 2026 12:29 AM	

Sequence #	0010-85	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	2504165	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2503652

0010-85	**WO #**	**2504165**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		General Visual Inspection of the Wing from WS45 to WS148 - Internal LH	
General Visual Inspection of the Wing from WS45 to WS148 - Internal LH				
Task / IRN # : 57-ZL-00-216				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with TLMC task 57-ZL-00-216 Performed general visual inspection of the LH wing from WS45 to WS148 (Internal) REF CL-650 AMM 57-10-00-210-804. No defects noted.	B1002512 - Brandon Warne Feb 09, 2026 06:50 PM	57-10
	Perform General Visual Inspection of the Wing from WS45 to WS148 - Internal LH		B1013522 - Brandon Jennings Feb 09, 2026 07:08 PM	
	200	Removed all tools, equipment and materials from the work area.	B1002512 - Brandon Warne Feb 09, 2026 06:50 PM	
	Remove all tools, equipment and materials from the work area.		B1013522 - Brandon Jennings Feb 09, 2026 07:08 PM	

Bombardier

Sequence #	0010-86	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504166	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-86	WO #	2504166	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Wing from WS45 to WS148 - Internal RH	
General Visual Inspection of the Wing from WS45 to WS148 - Internal RH				
Task / IRN # : 57-ZL-00-217				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with TLMC task 57-ZL-00-217 Performed general visual inspection of the RH wing from WS45 to WS148 (Internal) REF CL-650 AMM 57-10-00-210-804. No defects noted.	B1002512 - Brandon Warne Feb 09, 2026 08:54 PM	57-10
	Perform General Visual Inspection of the Wing from WS45 to WS148 - Internal RH		B1013522 - Brandon Jennings Feb 09, 2026 09:08 PM	
	200	Removed all tools, equipment and materials from the work area.	B1002512 - Brandon Warne Feb 09, 2026 08:54 PM	
	Remove all tools, equipment and materials from the work area.		B1013522 - Brandon Jennings Feb 09, 2026 09:08 PM	

Bombardier

Sequence #	0010-87	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504167	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-87	WO #	2504167	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Wing from WS148 to WS353 - Internal LH	
General Visual Inspection of the Wing from WS148 to WS353 - Internal LH				
Task / IRN # : 57-ZL-00-220				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with TLMC task 57-ZL-00-220 Performed general visual inspection of the LH wing from WS148 to WS353 (Internal) REF CL-650 AMM 57-10-00-210-806. No defects noted.	B1002512 - Brandon Warne Feb 10, 2026 08:40 PM	57-10
	Perform General Visual Inspection of the Wing from WS148 to WS353 - Internal LH		B1013522 - Brandon Jennings Feb 10, 2026 08:45 PM	
	200	Removed all tools, equipment and materials from the work area.	B1002512 - Brandon Warne Feb 10, 2026 08:40 PM	
	Remove all tools, equipment and materials from the work area.		B1013522 - Brandon Jennings Feb 10, 2026 08:45 PM	

Bombardier

Sequence #	0010-88	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504171	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-88	WO #	2504171	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Wing from WS148 to WS353 - Internal RH	
General Visual Inspection of the Wing from WS148 to WS353 - Internal RH				
Task / IRN # : 57-ZL-00-221				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with TLMC task 57-ZL-00-221 Performed general visual inspection of the RH wing from WS148 to WS353 (Internal) REF CL-650 AMM 57-10-00-210-806. No defects noted.	B1002512 - Brandon Warne Feb 10, 2026 04:12 PM	57-10
	Perform General Visual Inspection of the Wing from WS148 to WS353 - Internal RH		B1013522 - Brandon Jennings Feb 10, 2026 04:37 PM	
	200	Removed all tools, equipment and materials from the work area.	B1002512 - Brandon Warne Feb 10, 2026 04:12 PM	
	Remove all tools, equipment and materials from the work area.		B1013522 - Brandon Jennings Feb 10, 2026 04:37 PM	

Bombardier

Sequence #	0010-89	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504172	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-89	WO #	2504172	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Aileron Shroud - Internal LH	
General Visual Inspection of the Aileron Shroud - Internal LH				
Task / IRN # : 57-ZL-00-234				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 57-ZL-00-234, Perform General Visual Inspection of the Aileron Shroud - Internal LH, in accordance with CL-650 AMM 57-60-01-210-802. No Defects Noted.	B0642051 - Terry Walters Feb 05, 2026 03:59 PM	57-60
	Perform General Visual Inspection of the Aileron Shroud - Internal LH		B0143196 - Robert Bohner Feb 05, 2026 04:28 PM	
	200	Removed all Tools, equipment, and unwanted materials from the work area.	B0642051 - Terry Walters Feb 05, 2026 03:59 PM	
	Remove all Tools, equipment, and unwanted materials from the work area.		B0143196 - Robert Bohner Feb 05, 2026 04:28 PM	

Sequence #	0010-90	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504173	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-90	WO #	2504173	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Aileron Shroud - Internal RH	
General Visual Inspection of the Aileron Shroud - Internal RH				
Task / IRN # : 57-ZL-00-235				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 57-ZL-00-235, Perform General Visual Inspection of the Aileron Shroud - Internal RH, in accordance with CL-650 AMM 57-60-01-210-802. No Defects Noted.	B0642051 - Terry Walters Feb 05, 2026 04:00 PM	57-60
	Perform General Visual Inspection of the Aileron Shroud - Internal RH		B0143196 - Robert Bohner Feb 05, 2026 04:31 PM	
	200	Removed all tools, equipment, and unwanted materials from the work area.	B0642051 - Terry Walters Feb 05, 2026 04:00 PM	
	Remove all tools, equipment, and unwanted materials from the work area.		B0143196 - Robert Bohner Feb 05, 2026 04:31 PM	

Bombardier

Sequence #	0010-91	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504177	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-91	WO #	2504177	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Install Main Landing Gear (MLG) for Maintenance	
Install Main Landing Gear (MLG) for Maintenance				
Task / IRN # : INSTALL MLG				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			32-10
	Install LH Main Landing Gear (MLG) for Maintenance			
	200			32-10
	Install RH Main Landing Gear (MLG) for Maintenance			

Sequence #	0010-92	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504178	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-92	WO #	2504178	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Install Nose Landing Gear (NLG) for Maintenance	
Install Nose Landing Gear (NLG) for Maintenance				
Task / IRN # : INSTALL NLG				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			32-20
	Install Nose Landing Gear (NLG) for Maintenance			
	200			
	Install NLG Drag Brace (PN: 604-85002-51 / SN: S0000W82T). See WO: 2504185 Op: 200 for Removal. Ref: CL650 AMM 32-21-07-400-801			
	300			
	Install NLG Retraction Actuator (PN: 600-85002-37 / SN: 16CCC1652). See WO: 2504185 Op: 300 for Removal. Ref: CL650 32-33-01-400-801			

Sequence #	0010-93	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504179	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-93	WO #	2504179	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Remove Main Landing Gear (MLG) for Maintenance	
Remove Main Landing Gear (MLG) for Maintenance				
Task / IRN # : REMOVE MLG				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			32-10
	Remove LH Main Landing Gear (MLG) for Maintenance			
	200			32-10
	Remove RH Main Landing Gear (MLG) for Maintenance			

CHILD WORK ORDER DETAILS

	WO #	Description	Corrective Action	AMENDED
0010-93-1	4727678	Remove & Install LH Main Landing Gear (MLG)		
0010-93-2	4727698	Remove & Install RH Main Landing Gear (MLG)		
0010-93-3	4799084	Remove and Reinstall the LH MLG SIde Brace Fitting Shaft		
0010-93-4	4799096	Remove and Reinstall the RH MLG Side Brace Fitting Shaft	Perform Inspection of Shaft on WO: 2504213	

Sequence #	0010-93-1	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4727678	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2504179

0010-93-1	**WO #**	**4727678**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		No Log Entry	
Remove & Install LH Main Landing Gear (MLG)				
CRITICAL MAINTENANCE TASK				

Sequence #	0010-93-1	Aircraft SN #	6111	MWPWO #	2498069
WO #	4727678	Aircraft Reg #	XA-SOL	Parent WO #	2504179

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Removed LH Main Landing Gear (MLG) IAW CL-650 AMM 32-11-00-000-801.	B0650736 - Jesus Gonzalez Atondo Feb 06, 2026 09:29 PM	
	Remove LH Main Landing Gear (MLG) IAW CL-650 AMM 32-11-00-000-801.		Not Required	
	200			
	Install LH Main Landing Gear (MLG)			
	300	Removed #1 drive cap IAW CL-650 AMM 32-44-10-000-801.	B0650736 - Jesus Gonzalez Atondo Feb 06, 2026 05:40 PM	
	Remove #1 drive cap IAW CL-650 AMM 32-44-10-000-801.		Not Required	
	400	Reinstalled the #1 drive cap IAW CL-650 AMM 32-44-10-400-801.	B0650736 - Jesus Gonzalez Atondo Mar 03, 2026 05:57 PM	
	Install #1 drive cap IAW CL-650 AMM 32-44-10-400-801.		B1013522 - Brandon Jennings Mar 04, 2026 02:10 PM	
	500	Removed #2 drive cap IAW CL-650 AMM 32-44-10-000-801.	B0650736 - Jesus Gonzalez Atondo Feb 06, 2026 05:40 PM	
	Remove #2 drive cap IAW CL-650 AMM 32-44-10-000-801.		Not Required	
	600	Reinstalled the #2 drive cap IAW CL-650 AMM 32-44-10-400-801.	B0650736 - Jesus Gonzalez Atondo Mar 03, 2026 05:57 PM	
	Install #2 drive cap IAW CL-650 AMM 32-44-10-400-801.		B1013522 - Brandon Jennings Mar 04, 2026 02:10 PM	
	700	Removed the #1 wheel speed transducer IAW CL-650 AMM 32-44-01-000-801.	B0650736 - Jesus Gonzalez Atondo Feb 06, 2026 05:40 PM	
	Remove the #1 wheel speed transducer IAW CL-650 AMM 32-44-01-000-801.		Not Required	

Sequence #	0010-93-1	Aircraft SN #	6111	MWPWO #	2498069
WO #	4727678	Aircraft Reg #	XA-SOL	Parent WO #	2504179

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
CMT	800	Reinstalled the #1 wheel speed transducer IAW CL-650 AMM 32-44-01-400-801. See CMT working copy dated 3/3/26. See OP:3100 for the ops test of the antiskid system	B0650736 - Jesus Gonzalez Atondo Mar 03, 2026 07:15 PM	
	Install the #1 wheel speed transducer IAW CL-650 AMM 32-44-01-400-801.		B1013522 - Brandon Jennings Mar 04, 2026 02:10 PM	
	900	Removed the #2 wheel speed transducer IAW CL-650 AMM 32-44-01-000-801.	B0650736 - Jesus Gonzalez Atondo Feb 06, 2026 05:40 PM	
	Remove the #2 wheel speed transducer IAW CL-650 AMM 32-44-01-000-801.		Not Required	
CMT	1000	Reinstalled the #2 wheel speed transducer IAW CL-650 AMM 32-44-01-400-801. See CMT working copy dated 3/3/26. See OP:3100 for the ops test of the antiskid system	B0650736 - Jesus Gonzalez Atondo Mar 03, 2026 07:15 PM	
	Install the #2 wheel speed transducer IAW CL-650 AMM 32-44-01-400-801.		B1013522 - Brandon Jennings Mar 04, 2026 02:10 PM	
	1100	Removed the #1 wheel and tire assy. IAW CL-650 AMM 32-41-01-000-801.	B0650736 - Jesus Gonzalez Atondo Feb 06, 2026 05:52 PM	
	Remove the #1 wheel and tire assy. IAW CL-650 AMM 32-41-01-000-801.		Not Required	
CMT	1200	Reinstalled the #1 wheel and tire assy. IAW CL-650 AMM 32-41-01-400-801. Rotation check good. Serviced to 185PSI. See CMT working copy dated 3/3/26.	B0650736 - Jesus Gonzalez Atondo Mar 03, 2026 08:17 PM	
	Install the #1 wheel and tire assy. IAW CL-650 AMM 32-41-01-400-801.		B1013522 - Brandon Jennings Mar 04, 2026 02:10 PM	
	1300	Removed the #2 wheel and tire assy. IAW CL-650 AMM 32-41-01-000-801.	B0650736 - Jesus Gonzalez Atondo Feb 06, 2026 05:52 PM	
	Remove the #2 wheel and tire assy. IAW CL-650 AMM 32-41-01-000-801.		Not Required	
CMT	1400	Reinstalled the #2 wheel and tire assy. IAW CL-650 AMM 32-41-01-400-801. Rotation check good. Serviced to 185PSI. See CMT working copy dated 3/3/26.	B0650736 - Jesus Gonzalez Atondo Mar 03, 2026 08:17 PM	
	Install the #2 wheel and tire assy. IAW CL-650 AMM 32-41-01-400-801.		B1013522 - Brandon Jennings Mar 04, 2026 02:10 PM	

Sequence #	0010-93-1	Aircraft SN #	6111	MWPWO #	2498069
WO #	4727678	Aircraft Reg #	XA-SOL	Parent WO #	2504179

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	1500	Removed #1 brake unit IAW CL-650 AMM 32-43-19-000-801.	B0650736 - Jesus Gonzalez Atondo Feb 06, 2026 09:12 PM	
	Remove #1 brake unit IAW CL-650 AMM 32-43-19-000-801.		Not Required	
CMT	1600	Reinstalled the #1 brake unit IAW CL-650 AMM 32-43-19-400-801. Leak check good. See CMT working copy dated 3/2/2026.	B0650736 - Jesus Gonzalez Atondo Mar 03, 2026 08:25 PM	
	Install #1 brake unit IAW CL-650 AMM 32-43-19-400-801.		B1013522 - Brandon Jennings Mar 04, 2026 02:10 PM	
	1700	Removed #2 brake unit IAW CL-650 AMM 32-43-19-000-801.	B0650736 - Jesus Gonzalez Atondo Feb 06, 2026 09:12 PM	
	Remove #2 brake unit IAW CL-650 AMM 32-43-19-000-801.		Not Required	
CMT	1800	Reinstalled the #2 brake unit IAW CL-650 AMM 32-43-19-400-801. Leak check good. See CMT working copy dated 3/2/2026.	B0650736 - Jesus Gonzalez Atondo Mar 03, 2026 08:25 PM	
	Install #2 brake unit IAW CL-650 AMM 32-43-19-400-801.		B1013522 - Brandon Jennings Mar 04, 2026 02:10 PM	
	1900	Removed the left MLG pintle pin swivel coupling IAW CL-650 AMM 32-11-16-000-801.	B0650736 - Jesus Gonzalez Atondo Feb 06, 2026 09:19 PM	
	Remove the left MLG pintle pin swivel coupling IAW CL-650 AMM 32-11-16-000-801.		Not Required	
CMT	2000	Reinstalled the left MLG pintle pin swivel coupling IAW CL-650 AMM 32-11-16-400-801. Leak check good. See CMT working copy dated 3/2/26 See OP: 2900 for ops test of the brake system.	B0650736 - Jesus Gonzalez Atondo Mar 03, 2026 07:44 PM	
	Install the left MLG pintle pin swivel coupling IAW CL-650 AMM 32-11-16-400-801.		B1013522 - Brandon Jennings Mar 04, 2026 02:10 PM	
	2100	Removed the left MLG extension and retraction actuator IAW CL-650 AMM 32-32-01-000-801.	B0650736 - Jesus Gonzalez Atondo Feb 06, 2026 09:29 PM	
	Remove the left MLG extension and retraction actuator IAW CL-650 AMM 32-32-01-000-801.		Not Required	

Sequence #	0010-93-1	Aircraft SN #	6111	MWPWO #	2498069
WO #	4727678	Aircraft Reg #	XA-SOL	Parent WO #	2504179

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
CMT	2200			
	Install the left MLG extension and retraction actuator IAW CL-650 AMM 32-32-01-400-801.			
	2300			
	Bleed the No.2 hyd system ref. CL-650 AMM 29-10-00-870-801.			
	2400			
	Bleed the No.3 hyd system ref. CL-650 AMM 29-10-00-870-802.			
	2500			
	Service the MLG shock strut with nitrogen and oil ref. CL-650 AMM 12-12-32-614-802.			
	2600			
	Bleed the IB and OB brakes ref. CL-650 AMM 32-43-00-870-801.			
	2700			
	Perform the functional test of the landing gear extension/ retraction system ref. CL-650 AMM 32-30-00-720-801.			
	2800			
	Perform the operational test of the MLG emergency extension system ref. CL-650 AMM 32-34-00-710-801.			
	2900			
	Perform the operational test of the brake system ref. CL-650 AMM 32-43-00-710-801.			

Sequence #	0010-93-1	Aircraft SN #	6111	MWPWO #	2498069
WO #	4727678	Aircraft Reg #	XA-SOL	Parent WO #	2504179

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	3000			
	Perform the operational test of the PSS system ref. CL-650 AMM 32-61-00-710-801.			
	3100			
	Perform the operational test of the antiskid system ref. CL-650 AMM 32-44-00-710-801.			
	3200			
	Lower the aircraft to the ground and remove the jacks ref. CL-650 AMM 07-10-01-586-801.			

Sequence #	0010-93-1	Aircraft SN #	6111	MWPWO #	2498069
WO #	4727678	Aircraft Reg #	XA-SOL	Parent WO #	2504179

REMOVE AND RE-INSTALL DETAILS

	Removed Part # Removed Serial #	Removed By	Removed - Part Description	Reference	Installed Part # Installed Serial #	Installed By
	Removed Status	**Removed Date-Time**	**Position**	**Installed Part Status**	**Installed Part Description**	**Installed Date-Time**
	604-87000-7	B0650736 - Jesus Gonzalez Atondo	CAP DRIVE, ANTI-SKID	MLG Removal	604-87000-7	B0650736 - Jesus Gonzalez Atondo
	SERVICEABLE	Feb 6, 2026 10:30 AM	1	SERVICEABLE	CAP DRIVE, ANTI-SKID	Mar 3, 2026 1:54 PM
	604-87000-7	B0650736 - Jesus Gonzalez Atondo	CAP DRIVE, ANTI-SKID	MLG Removal	604-87000-7	B0650736 - Jesus Gonzalez Atondo
	SERVICEABLE	Feb 6, 2026 10:31 AM	2	SERVICEABLE	CAP DRIVE, ANTI-SKID	Mar 3, 2026 1:56 PM
	604-87000-1 3012	B0650736 - Jesus Gonzalez Atondo	TRANSDUCER, WHEEL SPEED	MLG Removal	604-87000-1 3012	B0650736 - Jesus Gonzalez Atondo
	SERVICEABLE	Feb 6, 2026 10:41 AM	1	SERVICEABLE	TRANSDUCER, WHEEL SPEED	Mar 3, 2026 2:03 PM
	604-87000-1 3013	B0650736 - Jesus Gonzalez Atondo	TRANSDUCER, WHEEL SPEED	MLG Removal	604-87000-1 3013	B0650736 - Jesus Gonzalez Atondo
	SERVICEABLE	Feb 6, 2026 10:42 AM	2	SERVICEABLE	TRANSDUCER, WHEEL SPEED	Mar 3, 2026 2:03 PM
	604-85123-1 AUG17-4595	B0650736 - Jesus Gonzalez Atondo	WHEEL ASSY, MLG	MLG Removal	604-85123-1 AUG17-4595	B0650736 - Jesus Gonzalez Atondo
	SERVICEABLE	Feb 6, 2026 10:53 AM	1	SERVICEABLE	WHEEL ASSY, MLG	Mar 3, 2026 2:03 PM
	604-85123-1 AUG17-4594	B0650736 - Jesus Gonzalez Atondo	WHEEL ASSY, MLG	MLG Removal	604-85123-1 AUG17-4594	B0650736 - Jesus Gonzalez Atondo
	SERVICEABLE	Feb 6, 2026 10:55 AM	2	SERVICEABLE	WHEEL ASSY, MLG	Mar 3, 2026 2:03 PM
	604-85123-101 MAY17-3062	B0650736 - Jesus Gonzalez Atondo	BRAKE ASSY	MLG Removal	604-85123-101 MAY17-3062	B0650736 - Jesus Gonzalez Atondo
	SERVICEABLE	Feb 6, 2026 2:13 PM	1	SERVICEABLE	BRAKE ASSY	Mar 3, 2026 2:03 PM
	604-85123-101 MAY17-3066	B0650736 - Jesus Gonzalez Atondo	BRAKE ASSY	MLG Removal	604-85123-101 MAY17-3066	B0650736 - Jesus Gonzalez Atondo
	SERVICEABLE	Feb 6, 2026 2:15 PM	2	SERVICEABLE	BRAKE ASSY	Mar 3, 2026 2:03 PM

Sequence #	0010-93-1	Aircraft SN #	6111	MWPWO #	2498069
WO #	4727678	Aircraft Reg #	XA-SOL	Parent WO #	2504179

REMOVE AND RE-INSTALL DETAILS

	Removed Part # Removed Serial #	Removed By	Removed - Part Description	Reference	Installed Part # Installed Serial #	Installed By
	Removed Status	**Removed Date-Time**	**Position**	**Installed Part Status**	**Installed Part Description**	**Installed Date-Time**
	6600-5	B0650736 - Jesus Gonzalez Atondo	COUPLING, SWIVEL (LH)	MLG Removal	6600-5	B0650736 - Jesus Gonzalez Atondo
	SERVICEABLE	Feb 6, 2026 2:24 PM	LEFT	SERVICEABLE	COUPLING, SWIVEL (LH)	Mar 3, 2026 2:03 PM
	604-85001-9 01489	B0650736 - Jesus Gonzalez Atondo	MLG SIDE BRACE ACTUATOR	MLG Removal	604-85001-9 01489	B0650736 - Jesus Gonzalez Atondo
	SERVICEABLE	Feb 6, 2026 2:25 PM	LEFT	SERVICEABLE	MLG SIDE BRACE ACTUATOR	Mar 3, 2026 1:56 PM
	604-85001-27 SOOOOWCVN	B0650736 - Jesus Gonzalez Atondo	MLG ASSY, DRESSED (LH)	MLG Removal	604-85001-27 SOOOOWCVN	B0650736 - Jesus Gonzalez Atondo
	SERVICEABLE	Feb 6, 2026 2:26 PM	LEFT	REPAIRED	MLG ASSY, DRESSED (LH)	Mar 3, 2026 2:04 PM

FINDINGS DETAILS

Finding #	Long Description	Status	Reported By	Defect Source	Defect Type	Priority	Follow-up WO #
			Date	**Disposition**			
83417	Found that L/H actuator upper zerk fitting is requires replacement upon receiving actuator from overhaul.	CLOSED	B1022255 - Carson Chang	MAINTENANCE	OTHER	3	4894804-INPRG
			Mar 6, 2026 9:41 AM	300-QA002			

TOOL INFORMATION

Tool ID	Tool Description	Calibration Due Date
TUSS2036	torque wrench	May 30, 2026 5:00 PM
TUSS3756	torque wrench	Oct 30, 2026 5:00 PM
TUSS149C	torque wrench	Feb 27, 2027 5:00 PM
TUSS5185	torque wrench	Oct 30, 2026 5:00 PM
TUSS5271	tire gauge	Dec 30, 2026 5:00 PM
TUSS4590	tire gauge	Oct 30, 2026 5:00 PM

Sequence #	0010-93-2	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4727698	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2504179

0010-93-2	**WO #**	**4727698**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		Remove & Install RH Main Landing Gear (MLG)	
Remove & Install RH Main Landing Gear (MLG)				
CRITICAL MAINTENANCE TASK				

Sequence #	0010-93-2	Aircraft SN #	6111	MWPWO #	2498069
WO #	4727698	Aircraft Reg #	XA-SOL	Parent WO #	2504179

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Removed RH MLG assembly REF CL-650 AMM 32-11-00-000-801.	B1002512 - Brandon Warne Feb 09, 2026 01:06 PM	
	Remove RH Main Landing Gear (MLG)		Not Required	
	200			
	Install RH Main Landing Gear (MLG)			
	300	Removed RH MLG side stay actuator REF CL-650 AMM 32-32-01-000-801.	B1002512 - Brandon Warne Feb 09, 2026 01:06 PM	
	Remove RH MLG side stay actuator.		Not Required	
	400			
	Install RH MLG side stay actuator REF CL-650 AMM 32-32-01-400-801.			
	500	Removed #3 RH MLG wheel assembly REF CL-650 AMM 32-41-01-000-801.	B1018546 - Andres Velazquez Feb 06, 2026 10:13 PM	
	Remove #3 MLG wheel assembly.		Not Required	
	600	Installed #3 MLG wheel assembly REF CL-650 AMM 32-41-01-400-801.	B1002512 - Brandon Warne Mar 04, 2026 05:45 PM	
	Install #3 MLG wheel assembly REF CL-650 AMM 32-41-01-400-801.		B1013522 - Brandon Jennings Mar 04, 2026 08:12 PM	
CMT	601	Installed #3 MLG wheel assembly REF CL-650 AMM 32-41-01-400-801. See CMT copy dated 3/3/26 for work performed.	B1002512 - Brandon Warne Mar 04, 2026 07:31 PM	
	Install #3 MLG wheel assembly REF CL-650 AMM 32-41-01-400-801.		B1013522 - Brandon Jennings Mar 04, 2026 08:12 PM	
	700	Removed # 4 RH MLG Wheel assembly IAW CL-650 AMM 32-41-01-000-801	B1018546 - Andres Velazquez Feb 06, 2026 10:13 PM	
	Remove #4 RH MLG wheel assembly.		Not Required	

Sequence #	0010-93-2	Aircraft SN #	6111	MWPWO #	2498069
WO #	4727698	Aircraft Reg #	XA-SOL	Parent WO #	2504179

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	800	Installed #4 RH MLG wheel assembly REF CL-650 AMM 32-41-01-400-801.	B1002512 - Brandon Warne Mar 04, 2026 05:45 PM	
	Install #4 RH MLG wheel assembly REF CL-650 AMM 32-41-01-400-801.		B1013522 - Brandon Jennings Mar 04, 2026 08:12 PM	
CMT	801	Installed #4 RH MLG wheel assembly REF CL-650 AMM 32-41-01-400-801. See CMT copy dated 3/3/26 for work performed.	B1002512 - Brandon Warne Mar 04, 2026 07:31 PM	
	Install #4 RH MLG wheel assembly REF CL-650 AMM 32-41-01-400-801.		B1013522 - Brandon Jennings Mar 04, 2026 08:27 PM	
	900	Removed #3 RH MLG Wheel Speed Transducer IAW CL-650 AMM 32-44-01-00-801	B1018546 - Andres Velazquez Feb 06, 2026 10:13 PM	
	Remove #3 RH MLG Wheel Speed Transducer		Not Required	
	1000	Installed #3 RH MLG Wheel Speed Transducer REF CL-650 AMM 32-44-01-400-801.	B1002512 - Brandon Warne Mar 04, 2026 05:45 PM	
	Install #3 RH MLG Wheel Speed Transducer IAW CL-650 AMM 32-44-01-400-801.		B1013522 - Brandon Jennings Mar 04, 2026 08:12 PM	
CMT	1001	Installed #3 RH MLG Wheel Speed Transducer REF CL-650 AMM 32-44-01-400-801. See CMT copy dated 3/3/26 for work performed.	B1002512 - Brandon Warne Mar 04, 2026 07:31 PM	
	Install #3 RH MLG Wheel Speed Transducer IAW CL-650 AMM 32-44-01-400-801.		B1013522 - Brandon Jennings Mar 04, 2026 08:27 PM	
	1100	Removed #4 RH MLG Wheel Speed Transducer IAW CL-650 AMM 32-44-01-00-801	B1018546 - Andres Velazquez Feb 06, 2026 10:13 PM	
	Remove #4 RH MLG Wheel Speed Transducer		Not Required	
	1200	Installed #4 RH MLG Wheel Speed Transducer REF CL-650 AMM 32-44-01-400-801.	B1002512 - Brandon Warne Mar 04, 2026 05:45 PM	
	Install #4 RH MLG Wheel Speed Transducer IAW CL-650 AMM 32-44-01-400-801.		B1013522 - Brandon Jennings Mar 04, 2026 08:12 PM	

Sequence #	0010-93-2	Aircraft SN #	6111	MWPWO #	2498069
WO #	4727698	Aircraft Reg #	XA-SOL	Parent WO #	2504179

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
CMT	1201	Installed #4 RH MLG Wheel Speed Transducer REF CL-650 AMM 32-44-01-400-801. See CMT copy dated 3/3/26 for work performed.	B1002512 - Brandon Warne Mar 04, 2026 07:31 PM	
	Install #4 RH MLG Wheel Speed Transducer IAW CL-650 AMM 32-44-01-400-801.		B1013522 - Brandon Jennings Mar 04, 2026 08:27 PM	
	1300	Removed #3 RH MLG Brake Unit IAW CL-650 AMM 32-43-19-000-801.	B1018546 - Andres Velazquez Feb 06, 2026 10:13 PM	
	Remove #3 RH MLG Brake Unit.		Not Required	
	1400	Installed NEW #3 RH MLG Brake Unit REF CL-650 AMM 32-43-19-400-801.	B1002512 - Brandon Warne Mar 04, 2026 05:45 PM	
	Install #3 RH MLG Brake Unit IAW CL-650 AMM 32-43-19-400-801.		B1013522 - Brandon Jennings Mar 04, 2026 08:12 PM	
CMT	1401	Installed OVERHAULED #3 RH MLG Brake Unit REF CL-650 AMM 32-43-19-400-801. See CMT copy dated 3/3/26 for work performed.	B1002512 - Brandon Warne Mar 04, 2026 07:31 PM	
	Install #3 RH MLG Brake Unit IAW CL-650 AMM 32-43-19-400-801.		B1013522 - Brandon Jennings Mar 04, 2026 08:27 PM	
	1500	Removed #4 RH MLG Brake Unit IAW CL-650 AMM 32-43-19-000-801.	B1018546 - Andres Velazquez Feb 06, 2026 10:13 PM	
	Remove #4 RH MLG Brake Unit.		Not Required	
	1600	Installed NEW #4 RH MLG Brake Unit REF CL-650 AMM 32-43-19-400-801.	B1002512 - Brandon Warne Mar 04, 2026 05:45 PM	
	Install #4 RH MLG Brake Unit IAW CL-650 AMM 32-43-19-400-801.		B1013522 - Brandon Jennings Mar 04, 2026 08:12 PM	
CMT	1601	Installed OVERHAULED #4 RH MLG Brake Unit REF CL-650 AMM 32-43-19-400-801. See CMT copy dated 3/3/26 for work performed.	B1002512 - Brandon Warne Mar 04, 2026 07:31 PM	
	Install #4 RH MLG Brake Unit IAW CL-650 AMM 32-43-19-400-801.		B1013522 - Brandon Jennings Mar 04, 2026 08:27 PM	
	1700	Removed RH MLG Pintle Pin Swivel-Coupling IAW CL-650 AMM 32-11-16-000-801.	B1018546 - Andres Velazquez Feb 06, 2026 11:07 PM	
	Remove RH MLG Pintle Pin Swivel-Coupling.		Not Required	

Sequence #	0010-93-2	Aircraft SN #	6111	MWPWO #	2498069
WO #	4727698	Aircraft Reg #	XA-SOL	Parent WO #	2504179

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	1800	Installed RH MLG Pintle Pin Swivel-Coupling REF CL-650 AMM 32-11-16-400-801.	B1002512 - Brandon Warne Mar 04, 2026 05:45 PM	
	Install RH MLG Pintle Pin Swivel-Coupling IAW CL-650 AMM 32-11-16-400-801.		B1013522 - Brandon Jennings Mar 04, 2026 08:12 PM	
CMT	1801	Installed RH MLG Pintle Pin Swivel-Coupling REF CL-650 AMM 32-11-16-400-801. See CMT copy dated 3/3/26 for work performed.	B1002512 - Brandon Warne Mar 04, 2026 07:31 PM	
	Install RH MLG Pintle Pin Swivel-Coupling IAW CL-650 AMM 32-11-16-400-801.		B1013522 - Brandon Jennings Mar 04, 2026 08:27 PM	
	1900	Removed #3 RH MLG Drive cap IAW CL-650 AMM 32-44-10-000-801.	B1018546 - Andres Velazquez Feb 06, 2026 10:13 PM	
	Remove #3 RH MLG Drive cap.		Not Required	
	2000	Installed #3 RH MLG Drive cap REF CL-650 AMM 32-44-10-400-801	B1002512 - Brandon Warne Mar 04, 2026 05:45 PM	
	Install #3 RH MLG Drive cap IAW CL-650 AMM 32-44-10-400-801		B1013522 - Brandon Jennings Mar 04, 2026 08:12 PM	
	2001	Installed #3 RH MLG Drive cap REF CL-650 AMM 32-44-10-400-801. See CMT copy dated 3/3/26 for work performed.	B1002512 - Brandon Warne Mar 04, 2026 07:31 PM	
	Install #3 RH MLG Drive cap IAW CL-650 AMM 32-44-10-400-801		B1013522 - Brandon Jennings Mar 04, 2026 08:27 PM	
	2100	Removed #4 RH MLG Drive cap IAW CL-650 AMM 32-44-10-000-801.	B1018546 - Andres Velazquez Feb 06, 2026 10:13 PM	
	Remove #4 RH MLG Drive cap.		Not Required	
	2200	Installed #4 RH MLG Drive cap REF CL-650 AMM 32-44-10-400-801	B1002512 - Brandon Warne Mar 04, 2026 05:45 PM	
	Install #4 RH MLG Drive cap IAW CL-650 AMM 32-44-10-400-801		B1013522 - Brandon Jennings Mar 04, 2026 08:12 PM	

Sequence #	0010-93-2	Aircraft SN #	6111	MWPWO #	2498069
WO #	4727698	Aircraft Reg #	XA-SOL	Parent WO #	2504179

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
CMT	2201	Installed #4 RH MLG Drive cap REF CL-650 AMM 32-44-10-400-801. See CMT copy dated 3/3/26 for work performed.	B1002512 - Brandon Warne Mar 04, 2026 07:31 PM	
	Install #4 RH MLG Drive cap IAW CL-650 AMM 32-44-10-400-801		B1013522 - Brandon Jennings Mar 04, 2026 08:27 PM	
	2300			
	Bleed the No.2 hyd system REF CL-650 AMM 29-10-00-870-801.			
	2400			
	Bleed the No.3 hyd system REF CL-650 AMM 29-10-00-870-802.			
	2500			
	Service the MLG shock strut with nitrogen and oil REF CL-650 AMM 12-12-32-614-802.			
	2600			
	Bleed the IB and OB brakes REF CL-650 AMM 32-43-00-870-801.			
	2700			
	Perform the functional test of the landing gear extension/ retraction system REF CL-650 AMM 32-30-00-720-801.			
	2800			
	Perform the operational test of the MLG emergency extension system REF CL-650 AMM 32-34-00-710-801.			
	2900			
	Perform the operational test of the brake system REF CL-650 AMM 32-43-00-710-801.			

Sequence #	0010-93-2	Aircraft SN #	6111	MWPWO #	2498069
WO #	4727698	Aircraft Reg #	XA-SOL	Parent WO #	2504179

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	3000			
	Perform the operational test of the PSS system REF CL-650 AMM 32-61-00-710-801.			
	3100			
	Perform the operational test of the antiskid system REF CL-650 AMM 32-44-00-710-801.			
	3200			
	Lower the aircraft to the ground and remove the jacks ref. CL-650 AMM 07-10-01-586-801.			

Sequence #	0010-93-2	Aircraft SN #	6111	MWPWO #	2498069
WO #	4727698	Aircraft Reg #	XA-SOL	Parent WO #	2504179

REMOVE AND RE-INSTALL DETAILS

	Removed Part # Removed Serial #	Removed By	Removed - Part Description	Reference	Installed Part # Installed Serial #	Installed By
	Removed Status	**Removed Date-Time**	**Position**	**Installed Part Status**	**Installed Part Description**	**Installed Date-Time**
	604-87000-7 NSN	B1018546 - Andres Velazquez	CAP DRIVE, ANTI-SKID	Gear removal	604-87000-7 NSN	B1002512 - Brandon Warne
	SERVICEABLE	Feb 6, 2026 3:15 PM	INBOARD	SERVICEABLE	CAP DRIVE, ANTI-SKID	Mar 4, 2026 12:34 PM
	604-87000-7 NSN	B1018546 - Andres Velazquez	CAP DRIVE, ANTI-SKID	Gear removal	604-87000-7 NSN	B1002512 - Brandon Warne
	SERVICEABLE	Feb 6, 2026 3:18 PM	OUTBOARD	SERVICEABLE	CAP DRIVE, ANTI-SKID	Mar 4, 2026 12:35 PM
	604-87000-1 3006	B1018546 - Andres Velazquez	TRANSDUCER, WHEEL SPEED	Gear removal	604-87000-1 3006	B1002512 - Brandon Warne
	SERVICEABLE	Feb 6, 2026 3:19 PM	INBOARD	SERVICEABLE	TRANSDUCER, WHEEL SPEED	Mar 4, 2026 12:36 PM
	604-87000-1 3007	B1018546 - Andres Velazquez	TRANSDUCER, WHEEL SPEED	Gear removal	604-87000-1 3007	B1002512 - Brandon Warne
	SERVICEABLE	Feb 6, 2026 3:21 PM	OUTBOARD	SERVICEABLE	TRANSDUCER, WHEEL SPEED	Mar 4, 2026 12:37 PM
	604-85123-1 DEC16-4478	B1002512 - Brandon Warne	WHEEL ASSY, MLG	Gear removal	604-85123-1 DEC16-4478	B1002512 - Brandon Warne
	SERVICEABLE	Feb 6, 2026 3:22 PM	INBOARD	SERVICEABLE	WHEEL ASSY, MLG	Mar 4, 2026 12:37 PM
	604-85123-1 DEC16-4477	B1002512 - Brandon Warne	WHEEL ASSY, MLG	Gear removal	604-85123-1 DEC16-4477	B1002512 - Brandon Warne
	SERVICEABLE	Feb 6, 2026 3:24 PM	OUTBOARD	SERVICEABLE	WHEEL ASSY, MLG	Mar 4, 2026 12:38 PM
	604-85001-9 01490	B1002512 - Brandon Warne	MLG SIDE BRACE ACTUATOR	Gear removal		
	SERVICEABLE	Feb 6, 2026 3:26 PM	RIGHT			
	604-85001-5 16SPP20162	B1002512 - Brandon Warne	SHOCK ABSORBER	Gear removal	604-85001-5 16SPP20162	B1002512 - Brandon Warne
	SERVICEABLE	Feb 6, 2026 3:27 PM	RIGHT	SERVICEABLE	SHOCK ABSORBER	Mar 3, 2026 12:39 PM

Sequence #	0010-93-2	Aircraft SN #	6111	MWPWO #	2498069
WO #	4727698	Aircraft Reg #	XA-SOL	Parent WO #	2504179

REMOVE AND RE-INSTALL DETAILS

	Removed Part # Removed Serial #	Removed By	Removed - Part Description	Reference	Installed Part # Installed Serial #	Installed By
	Removed Status	**Removed Date-Time**	**Position**	**Installed Part Status**	**Installed Part Description**	**Installed Date-Time**
	604-85123-101 MAY17-3065	B1018546 - Andres Velazquez	BRAKE ASSY	Gear removal	604-85123-101 MAR96-0090	B1002512 - Brandon Warne
	UNSERVICEABLE	Feb 6, 2026 3:29 PM	INBOARD	OVERHAULED	BRAKE ASSY	Mar 4, 2026 12:42 PM
	604-85123-101 MAY17-3061	B1018546 - Andres Velazquez	BRAKE ASSY	Gear removal	604-85123-101 NOV17-3109	B1002512 - Brandon Warne
		Feb 6, 2026 3:31 PM	OUTBOARD	OVERHAULED	BRAKE ASSY	Mar 4, 2026 12:43 PM
	6603-5 346-1	B1002512 - Brandon Warne	COUPLING, SWIVEL (RH)	Gear removal	6603-5 346-1	B1002512 - Brandon Warne
		Feb 6, 2026 3:38 PM	RIGHT	SERVICEABLE	COUPLING, SWIVEL (RH)	Mar 4, 2026 12:40 PM
	19090-110 S0000WCVQ	B1002512 - Brandon Warne	MLG ASSY, DRESSED (RH)	Scheduled	19090-110 S0000WCVQ	B1002512 - Brandon Warne
	REPAIR & RETURN	Feb 9, 2026 1:08 PM	RIGHT	SERVICEABLE	MLG ASSY, DRESSED (RH)	Mar 3, 2026 12:40 PM

TOOL INFORMATION

Tool ID	Tool Description	Calibration Due Date
TUSS149C	Torque Wrench	Feb 27, 2027 5:00 PM
TUSS3756	Torque Wrench	Oct 30, 2026 5:00 PM
TUSS2036	Torque Wrench	May 30, 2026 5:00 PM
TUSS5185	Torque Wrench	Oct 30, 2026 5:00 PM
TUSS4590	Tire Gauge	Oct 30, 2026 5:00 PM
TUSS5271	Tire Gauge	Dec 20, 2026 5:00 PM

Sequence #	0010-93-3	Aircraft SN #	6111	MWPWO #	2498069
WO #	4799084	Aircraft Reg #	XA-SOL	Parent WO #	2504179

0010-93-3	WO #	4799084	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		No Log Entry	
Remove and Reinstall the LH MLG SIde Brace Fitting Shaft				
CRITICAL MAINTENANCE TASK				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Removed the LH MLG Side Brace Fitting Shaft IAW CL-650 AMM 32-32-02-000-801. No defects noted.	B0650736 - Jesus Gonzalez Atondo Feb 19, 2026 07:34 PM	
	Remove the LH MLG Side Brace Fitting Shaft		Not Required	
CMT	200			
	Install the LH MLG Side Brace Fitting Shaft ref. CL-650 AMM 32-32-02-400-801.			
	300	Performed the detailed inspection of the LH MLG side brace fitting shaft ref. CL-650 AMM 32-11-00-220-801 step 2.F(9). See finding 81234.	B0650736 - Jesus Gonzalez Atondo Feb 19, 2026 08:26 PM	
	Perform the detailed inspection of the LH MLG side brace fitting shaft ref. CL-650 AMM 32-11-00-220-801 step 2.F(9).		B1013522 - Brandon Jennings Feb 19, 2026 08:57 PM	

REMOVE AND RE-INSTALL DETAILS

	Removed Part # / Removed Serial #	Removed By	Removed - Part Description	Reference	Installed Part # / Installed Serial #	Installed By
	Removed Status	Removed Date-Time	Position	Installed Part Status	Installed Part Description	Installed Date-Time
	601R10237-3 0107	B0650736 - Jesus Gonzalez Atondo	SHAFT, MLG SIDE BRACE FITTING	Inspection		
	SERVICEABLE	Feb 19, 2026 12:30 PM	LEFT			

Sequence #	0010-93-3	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4799084	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2504179

FINDINGS DETAILS

Finding #	Long Description	Status	Reported By / Date	Defect Source / Disposition	Defect Type	Priority	Follow-up WO #
81234	LH MLG side brace fitting shaft worn, and finish is damaged.	CLOSED	B0650736 - Jesus Gonzalez Atondo Feb 19, 2026 1:11 PM	MAINTENANCE 300-QA002	OTHER	3	4804818-INPRG

Sequence #	0010-93-4	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4799096	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2504179

0010-93-4	**WO #**	**4799096**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		No Log Entry	
Remove and Reinstall the RH MLG Side Brace Fitting Shaft				
CRITICAL MAINTENANCE TASK				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Removed the RH MLG Side Brace Fitting Shaft IAW CL-650 AMM 32-32-02-000-801.	B1022275 - Kaitlynn Maxon Feb 19, 2026 08:30 PM	
	Remove the RH MLG Side Brace Fitting Shaft		Not Required	
CMT	200			
	Install the RH MLG Side Brace Fitting Shaft ref. CL-650 AMM 32-32-02-400-801.			
	300	PERFORMED INSPECTION OF RH MLG SIDE BRACE FITTING-SHAFT IAW CL-650 AMM 32-11-00-220-801 STEP F(9).	B1022275 - Kaitlynn Maxon Feb 19, 2026 08:31 PM	
	Perform inspection of RH MLG Side brace fitting-shaft.		B1013522 - Brandon Jennings Feb 19, 2026 08:56 PM	
	301	PERFORMED INSPECTION OF RH MLG SIDE BRACE FITTING-SHAFT IAW CL-650 AMM 32-11-00-220-801 STEP F(9). See findings for details.	B1022275 - Kaitlynn Maxon Feb 19, 2026 09:10 PM	
	Perform inspection of RH MLG Side brace fitting-shaft.		B1013522 - Brandon Jennings Feb 19, 2026 09:11 PM	09

Sequence #	0010-93-4	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4799096	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2504179

REMOVE AND RE-INSTALL DETAILS

	Removed Part # Removed Serial #	Removed By	Removed - Part Description	Reference	Installed Part # Installed Serial #	Installed By
	Removed Status	**Removed Date-Time**	**Position**	**Installed Part Status**	**Installed Part Description**	**Installed Date-Time**
	601R10237-3 0127	B0650736 - Jesus Gonzalez Atondo	SHAFT, MLG SIDE BRACE FITTING	Inspection	601R10237-3 0467	
	SERVICEABLE	Feb 19, 2026 12:45 PM	RIGHT	NEW	SHAFT, MLG SIDE BRACE FITTING	

FINDINGS DETAILS

Finding #	Long Description	Status	Reported By	Defect Source	Defect Type	Priority	Follow-up WO #
			Date	**Disposition**			
81242	DAMAGE FOUND ON AFT FACE OF RH MLG SIDE BRACE FITTING-SHAFT.	CLOSED	B1022275 - Kaitlynn Maxon	MAINTENANCE	OTHER	3	4804823-INPRG
			Feb 19, 2026 1:23 PM	300-QA002			

Sequence #	0010-94	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504185	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-94	WO #	2504185	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Remove Nose Landing Gear (NLG) for Maintenance	
Remove Nose Landing Gear (NLG) for Maintenance				
Task / IRN # : REMOVE NLG				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Removed the Nose Landing Gear/Strut Assembly as required. (PN: 604-85002-41 / SN: S0000W9HC). See WO: 2504178 for Installation. Ref: CL650 AMM 32-21-00-000-801	B0646266 - Sergio Rodriguez Figueroa Feb 06, 2026 05:31 PM	32-20
	Remove Nose Landing Gear (NLG) for Maintenance (604/605/650)			
	200	Removed NLG Drag Brace to FOM as required (PN: 604-85002-51 / SN: S0000W82T). See WO: 2504178 for Installation. Ref: CL650 AMM 32-21-07-000-801	B0646266 - Sergio Rodriguez Figueroa Feb 06, 2026 05:31 PM	
	Remove NLG Drag Brace to FOM. Ref: CL650 AMM 32-21-07-000-801			
	300	Removed NLG Retraction Actuator to FOM as required (PN: 600-85002-37 / SN: 16CCC1652). See WO: 2504178 for Installation. Ref: CL650 32-33-01-000-801	B0646266 - Sergio Rodriguez Figueroa Feb 06, 2026 05:31 PM	
	Remove NLG Retraction Actuator to FOM. Ref: CL650 32-33-01-000-801			

Sequence #	0010-94	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504185	Aircraft Reg #	XA-SOL	Parent WO #	2503652

REMOVE AND RE-INSTALL DETAILS

	Removed Part # Removed Serial #	Removed By	Removed - Part Description	Reference	Installed Part # Installed Serial #	Installed By
	Removed Status	**Removed Date-Time**	**Position**	**Installed Part Status**	**Installed Part Description**	**Installed Date-Time**
	604-85002-41 S0000W9HC	B0646266 - Sergio Rodriguez Figueroa	GEAR ASSY, NOSE LANDING	Shipping out for Inspection.		
	SERVICEABLE	Feb 6, 2026 10:31 AM	FORWARD			
	604-85002-51 S0000W82T	B0646266 - Sergio Rodriguez Figueroa	BRACE ASSY, DRAG	Shipping out for Inspection.		
	SERVICEABLE	Feb 6, 2026 10:34 AM	FORWARD			
	600-85002-37 16CCC1652	B0646266 - Sergio Rodriguez Figueroa	ACTUATOR ASSY, NLG EXTENT/RETRACT	Shipping out for Inspection		
	SERVICEABLE	Feb 6, 2026 10:37 AM	FORWARD			

Bombardier

Sequence #	0010-95	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504186	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-95	WO #	2504186	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Lightning/High Intensity Radiated Field L/HIRF Protection in the Flight Compartment	
Detailed Inspection of the Lightning/High Intensity Radiated Field L/HIRF Protection in the Flight Compartment				
Task / IRN # : 22-12-00-201				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 22-12-00-201, Perform Detailed Inspection of the Lightning/High Intensity Radiated Field L/HIRF Protection in the Flight Compartment, in accordance with CL 650 AMM 22-12-22-220-801. No defects noted.	B0143864 - Aaric Cerna Feb 10, 2026 07:18 PM	22-10
	Perform Detailed Inspection of the Lightning/High Intensity Radiated Field L/HIRF Protection in the Flight Compartment		B1013522 - Brandon Jennings Feb 10, 2026 07:24 PM	
	200	Removed all tools equipment and unwanted material from work area	B0143864 - Aaric Cerna Feb 10, 2026 07:35 PM	
	Remove all tools equipment and unwanted material from work area		B1013522 - Brandon Jennings Feb 10, 2026 07:57 PM	

Sequence #	0010-96	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504189	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-96	WO #	2504189	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Lightning/High Intensity Radiated Field L/HIRF Protection of the Vertical Stabilizer - Internal	
Detailed Inspection of the Lightning/High Intensity Radiated Field L/HIRF Protection of the Vertical Stabilizer - Internal				
Task / IRN # : 22-12-00-203				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with TLMC Task 22-12-00-203, Detailed Inspection of the Lightning/High Intensity Radiated Field L/HIRF Protection of the Vertical Stabilizer - Internal. REF CL-650 AMM 22-12-22-220-803. No Defects Noted. See Open Access Work Order 3154420 and Close Access Work Order 3154422 for vertical stab panels removal and installation.	B1014141 - Christopher Drawdy Feb 12, 2026 01:30 PM	22-10
	Perform Detailed Inspection of the Lightning/High Intensity Radiated Field L/HIRF Protection of the Vertical Stabilizer - Internal		B1013522 - Brandon Jennings Feb 12, 2026 02:09 PM	
	200	Complied with removal of all tools, equipment, and unwanted materials from the work area	B0641378 - Calvin Ambrose Feb 11, 2026 08:10 PM	
	Comply with removal of all tools, equipment, and unwanted materials from the work area		B1013522 - Brandon Jennings Feb 12, 2026 02:09 PM	

Sequence #	0010-97	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504191	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-97	WO #	2504191	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Lightning/High Intensity Radiated Field L/HIRF Protection in the Fuselage between FS409.00 and FS621.00, below WL73.5 - Internal	
Detailed Inspection of the Lightning/High Intensity Radiated Field L/HIRF Protection in the Fuselage between FS409.00 and FS621.00, below WL73.5 - Internal				
Task / IRN # : 22-12-00-205				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with TLMC Task 22-12-00-205, Detailed Inspection of the Lightning/High Intensity Radiated Field L/HIRF Protection in the Fuselage between FS409.00 and FS621.00, below WL73.5 - Internal. REF CL-650 AMM 22-12-22-220-805. No Defects Noted. See Open Access Work Order 3154420 and Close Access Work Order 3154422 for floor panel removal and installation.	B1014141 - Christopher Drawdy Feb 12, 2026 01:32 PM	22-10
	Perform Detailed Inspection of the Lightning/High Intensity Radiated Field L/HIRF Protection in the Fuselage between FS409.00 and FS621.00, below WL73.5 - Internal		B1013522 - Brandon Jennings Feb 12, 2026 01:40 PM	
	200	Complied with removal of all tools, equipment, and unwanted materials from the work area	B0641378 - Calvin Ambrose Feb 11, 2026 07:29 PM	
	Comply with removal of all tools, equipment, and unwanted materials from the work area		B1013522 - Brandon Jennings Feb 12, 2026 01:40 PM	

Sequence #	0010-98	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504193	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-98	WO #	2504193	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Lightning/High Intensity Radiated Field (L/HIRF) Protection on the Avionics Racks	
Detailed Inspection of the Lightning/High Intensity Radiated Field (L/HIRF) Protection on the Avionics Racks				
Task / IRN # : 22-12-00-206				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with TLMC Task 22-12-00-206, Detail Inspection of the Lightning/High Intensity Radiated Field (L/HIRF) Protection on the Avionics Racks. REF CL-650 AMM 22-12-22-220-806. No Defects Noted.	B0143855 - Marlon Zurita Feb 20, 2026 05:10 PM	22-10
	Perform Detailed Inspection of the Lightning/High Intensity Radiated Field (L/HIRF) Protection on the Avionics Racks		B0141354 - Karl Tuxhorn Feb 20, 2026 07:43 PM	
	200	Complied with removal of all tools, equipment, and unwanted materials from the work area	B0641378 - Calvin Ambrose Feb 20, 2026 04:54 PM	
	Comply with removal of all tools, equipment, and unwanted materials from the work area		B0141354 - Karl Tuxhorn Feb 20, 2026 07:43 PM	

TOOL INFORMATION

Tool ID	Tool Description	Calibration Due Date
TUSS3348	BORESCOPE	Feb 19, 2027 5:00 PM

Sequence #	0010-99	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504194	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-99	WO #	2504194	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Special Detailed Inspection (Borescope) of the Lightning/High Intensity Radiated Field (L/HIRF) Protection on the #2 VHF Antenna	
Special Detailed Inspection (Borescope) of the Lightning/High Intensity Radiated Field (L/HIRF) Protection on the #2 VHF Antenna				
Task / IRN # : 22-12-00-207				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 22-12-00-207 special detailed inspection (Borescope) of the lightning/ high intensity radiated field (L/HIRF) protection on the VHF #2 antenna IAW CL-650 AMM 22-12-22-280-801 No defects noted	B0619443 - Tyler Herrera Feb 06, 2026 05:03 PM	22-10
	Perform Special Detailed Inspection (Borescope) of the Lightning/High Intensity Radiated Field (L/HIRF) Protection on the #2 VHF Antenna		B1013522 - Brandon Jennings Feb 06, 2026 05:15 PM	
	200	Removed tools and equipment from aircraft	B0619443 - Tyler Herrera Feb 06, 2026 05:03 PM	
	Remove tools and equipment		B1013522 - Brandon Jennings Feb 06, 2026 05:15 PM	

TOOL INFORMATION

Tool ID	Tool Description	Calibration Due Date
TUSS3348	Boroscope	

Sequence #	0010-100	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504197	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-100	WO #	2504197	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Lightning/High Intensity Radiated Field L/HIRF Protection on the Upper FS621 Bulkhead	
Detailed Inspection of the Lightning/High Intensity Radiated Field L/HIRF Protection on the Upper FS621 Bulkhead				
Task / IRN # : 22-12-00-209				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with TLMC Task 22-12-00-209 Detailed Inspection of the Lightning/High Intensity Radiated Field L/HIRF Protection on the Upper FS621 Bulkhead IAW CL650 AMM Task 22-12-22-220-809. No defects noted.	B0141003 - Francisco Ayon Feb 12, 2026 05:26 PM	22-10
	Perform Detailed Inspection of the Lightning/High Intensity Radiated Field L/HIRF Protection on the Upper FS621 Bulkhead		B1013522 - Brandon Jennings Feb 12, 2026 05:54 PM	
	200	Removed all tools, equipment, and unwanted materials from the work area.	B0141003 - Francisco Ayon Feb 12, 2026 05:26 PM	
	Remove all tools, equipment, and unwanted materials from the work area.		B1013522 - Brandon Jennings Feb 12, 2026 05:54 PM	

Sequence #	0010-101	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504199	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-101	WO #	2504199	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Lightning/High Intensity Radiated Field L/HIRF Protection on the Wing Disconnects - External	
Detailed Inspection of the Lightning/High Intensity Radiated Field L/HIRF Protection on the Wing Disconnects - External				
Task / IRN # : 22-12-00-210				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with TLMC Task 22-12-00-210 Detailed Inspection of the Lightning/High Intensity Radiated Field L/HIRF Protection on the Wing Disconnects - External IAW CL650 AMM Task 22-12-22-220-810. Finding created for Broken back shell at connector P8CG finding # 79996.	B0141003 - Francisco Ayon Feb 12, 2026 06:46 PM	22-10
	Perform Detailed Inspection of the Lightning/High Intensity Radiated Field L/HIRF Protection on the Wing Disconnects - External		B1013522 - Brandon Jennings Feb 12, 2026 07:04 PM	
	200	Removed all tools, equipment, and unwanted materials from the work area.	B0141003 - Francisco Ayon Feb 12, 2026 06:46 PM	
	Remove all tools, equipment, and unwanted materials from the work area.		B1013522 - Brandon Jennings Feb 12, 2026 07:04 PM	

FINDINGS DETAILS

Finding #	Long Description	Status	Reported By / Date	Defect Source / Disposition	Defect Type	Priority	Follow-up WO #
79996	RH Flap Position Transmitter connector P8CG back shell ground tab is broken. PN: 450FS005NF12	CLOSED	B0141003 - Francisco Ayon Feb 12, 2026 10:55 AM	MAINTENANCE 300-QA002	OTHER	3	4767693-RDYPM

Sequence #	0010-103	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504203	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-103	WO #	2504203	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Aileron, Rudder, Elevator and Spoiler Control Cables in the Mid-Lower Fuselage	
Detailed Inspection of the Aileron, Rudder, Elevator and Spoiler Control Cables in the Mid-Lower Fuselage				
Task / IRN # : 27-00-00-204				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 27-00-00-204, Perform Detailed Inspection of the Aileron, Rudder, Elevator and Spoiler Control Cables in the Mid-Lower Fuselage, in accordance with CL650 AMM 27-00-00-220-804. No defects noted.	B0641903 - Felipe Mendoza Cervantes Feb 17, 2026 12:44 AM	27-00
	Perform Detailed Inspection of the Aileron, Rudder, Elevator and Spoiler Control Cables in the Mid-Lower Fuselage		B0623124 - Michael Stacy Feb 17, 2026 12:56 AM	
	200	Removed all tools equipment and unwanted materials from the work area.	B0641903 - Felipe Mendoza Cervantes Feb 17, 2026 12:44 AM	
	Remove all tools equipment and unwanted materials from the work area.		B0623124 - Michael Stacy Feb 17, 2026 12:56 AM	

Bombardier

Sequence #	0010-104	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504205	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-104	WO #	2504205	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Functional Test of the Vent Line Shrouds	
Functional Test of the Vent Line Shrouds				
Task / IRN # : 28-10-00-207				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with TLMC task 28-10-00-207 Performed functional test of the vent line shrouds REF 28-14-22-720-801. Functional test good.	B1002512 - Brandon Warne Feb 11, 2026 02:53 PM	28-10
	Perform Functional Test of the Vent Line Shrouds		B1013522 - Brandon Jennings Feb 11, 2026 04:06 PM	
	200	Removed all tools, equipment and materials from the work area.	B1002512 - Brandon Warne Feb 11, 2026 02:53 PM	
	Remove all tools, equipment and materials from the work area.		B1013522 - Brandon Jennings Feb 11, 2026 04:06 PM	

Sequence #	0010-105	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	2504206	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2503652

0010-105	**WO #**	**2504206**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		Functional Test of the Motive-Flow Line Shrouds	
Functional Test of the Motive-Flow Line Shrouds				
Task / IRN # : 28-10-00-208				

Sequence #	0010-105	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504206	Aircraft Reg #	XA-SOL	Parent WO #	2503652

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Performed LH functional test of the motive-flow line shrouds REF CL-650 AMM 28-22-10-720-801. Functional test good.	B1002512 - Brandon Warne Feb 11, 2026 07:16 PM	28-20
	Perform LH Functional Test of the Motive-Flow Line Shrouds		B1013522 - Brandon Jennings Feb 11, 2026 08:06 PM	
	101	Complied with TLMC task 28-10-00-208 Performed LH functional test of the motive-flow line shrouds REF CL-650 AMM 28-22-10-720-801. Functional test good.	B1002512 - Brandon Warne Feb 11, 2026 08:10 PM	
	Perform LH Functional Test of the Motive-Flow Line Shrouds		B1013522 - Brandon Jennings Feb 11, 2026 08:15 PM	09
	200	Performed RH functional test of the motive-flow line shrouds REF CL-650 AMM 28-22-10-720-801.	B1002512 - Brandon Warne Feb 11, 2026 07:16 PM	28-20
	Perform RH Functional Test of the Motive-Flow Line Shrouds		B1013522 - Brandon Jennings Feb 11, 2026 08:06 PM	
	201	Complied with TLMC task 28-10-00-208 Performed RH functional test of the motive-flow line shrouds REF CL-650 AMM 28-22-10-720-801. Functional test good.	B1002512 - Brandon Warne Feb 11, 2026 08:10 PM	
	Perform RH Functional Test of the Motive-Flow Line Shrouds		B1013522 - Brandon Jennings Feb 11, 2026 08:15 PM	09
	300	Connected LH and RH Motive flow hoses on pylon firewall fitting REF CL-650 AMM 71-00-00-400-801	B1002512 - Brandon Warne Feb 11, 2026 07:16 PM	
	Disconnected LH and RH Motive flow hoses from pylon firewall fitting.		B1013522 - Brandon Jennings Feb 11, 2026 08:06 PM	
	400	Connected LH and RH motive flow line inside the fuel tank REF CL-650 AMM 28-22-10-720-801 and CL-650 SPM 20-22-00-910-801.	B1002512 - Brandon Warne Feb 11, 2026 07:16 PM	
	Disconnected LH and RH motive flow line from inside the fuel tank.		B1013522 - Brandon Jennings Feb 11, 2026 08:06 PM	

TOOL INFORMATION

Tool ID	Tool Description	Calibration Due Date
TUSS4231	Torque Wrench	Jul 30, 2026 5:00 PM
TUSS2451	Air pressure gauge	Feb 27, 2027 5:00 PM

Bombardier

Sequence #	0010-106	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504210	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-106	WO #	2504210	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Functional Test of the Fuel-Feed Line Shrouds	
Functional Test of the Fuel-Feed Line Shrouds				
Task / IRN # : 28-10-00-209				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with TLMC task 28-10-00-209 Performed LH functional test of the fuel-feed line shrouds REF CL-650 28-21-16-720-801. Functional test good.	B1002512 - Brandon Warne Feb 12, 2026 03:58 PM	28-20
	Perform LH Functional Test of the Fuel-Feed Line Shrouds		B1013522 - Brandon Jennings Feb 12, 2026 04:54 PM	
	200	Complied with TLMC task 28-10-00-209 Performed RH functional test of the fuel-feed line shrouds REF CL-650 28-21-16-720-801. Functional test good.	B1002512 - Brandon Warne Feb 12, 2026 03:58 PM	28-20
	Perform RH Functional Test of the Fuel-Feed Line Shrouds		B1013522 - Brandon Jennings Feb 12, 2026 04:54 PM	
	300	Removed all tools, equipment and materials from the work area.	B1002512 - Brandon Warne Feb 12, 2026 03:58 PM	
	Remove all tools, equipment and materials from the work area.		B1013522 - Brandon Jennings Feb 12, 2026 04:54 PM	

TOOL INFORMATION

Tool ID	Tool Description	Calibration Due Date
TUSS2451	Air pressure gauge	Feb 27, 2027 5:00 PM

Sequence #	0010-107	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	2504213	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2503652

0010-107	**WO #**	**2504213**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		Detailed Inspection of the Main Landing Gear (MLG) Assembly	
Detailed Inspection of the Main Landing Gear (MLG) Assembly				
Task / IRN # : 32-00-01-215				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			32-10
	Detailed Inspection of the Main Landing Gear (MLG) Assembly			

Bombardier

Sequence #	0010-108	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504215	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-108	WO #	2504215	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Hinge and Fasteners of the Main Landing-Gear Door	
Detailed Inspection of the Hinge and Fasteners of the Main Landing-Gear Door				
Task / IRN # : 32-12-00-201				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with TLMC 32-12-00-201. Performed the Detailed Inspection of the Hinge and Fasteners of the LH Main Landing-Gear Door Ref. CL-650 AMM 32-12-01-220-801. No defects noted.	B0613291 - Eric Strong Feb 15, 2026 03:23 PM	32-10
	Perform LH Detailed Inspection of the Hinge and Fasteners of the Main Landing-Gear Door		B1019908 - Joseph Barnes Feb 16, 2026 03:36 PM	
	200	Complied with TLMC 32-12-00-201. Performed the Detailed Inspection of the Hinge and Fasteners of the RH Main Landing-Gear Door Ref. CL-650 AMM 32-12-01-220-801. No defects noted.	B0613291 - Eric Strong Feb 15, 2026 03:23 PM	32-10
	Perform RH Detailed Inspection of the Hinge and Fasteners of the Main Landing-Gear Door		B1019908 - Joseph Barnes Feb 16, 2026 03:36 PM	
	300	Removed all tools equipment, and unwanted materials from the work area.	B0613291 - Eric Strong Feb 15, 2026 03:23 PM	
	Remove all tools equipment, and unwanted materials from the work area.		B1019908 - Joseph Barnes Feb 16, 2026 03:36 PM	

Sequence #	0010-109	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504218	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-109	WO #	2504218	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Internal Fuselage (Skins and Structure) - FS202.75 to FS280.00 Below the Floor	
Detailed Inspection of the Internal Fuselage (Skins and Structure) - FS202.75 to FS280.00 Below the Floor				
Task / IRN # : 53-10-00-203				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 53-10-00-203, Perform Detailed Inspection of the Internal Fuselage (Skins and Structure) - FS202.75 to FS280.00 Below the Floor, in accordance with CL-650 AMM 53-10-01-220-803. No Defects Noted.	B0642051 - Terry Walters Feb 16, 2026 04:22 PM	53-10
	Perform Detailed Inspection of the Internal Fuselage (Skins and Structure) - FS202.75 to FS280.00 Below the Floor		B1019908 - Joseph Barnes Feb 16, 2026 04:37 PM	
	200	Removed all Tools, Equipment, and unwanted materials from the work area.	B0642051 - Terry Walters Feb 16, 2026 04:22 PM	
	Remove all Tools, Equipment, and unwanted materials from the work area.		B1019908 - Joseph Barnes Feb 16, 2026 04:37 PM	

Sequence #	0010-110	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504220	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-110	WO #	2504220	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Sills, Frames and External Skin around the Passenger Door Cutout	
Detailed Inspection of the Sills, Frames and External Skin around the Passenger Door Cutout				
Task / IRN # : 53-20-00-201				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with TLMC task 53-20-00-201 Performed detailed inspection of the sills, frames and external skin around the passenger door cutout REF CL-650 AMM 53-20-01-220-801. No defects noted.	B1002512 - Brandon Warne Feb 16, 2026 08:51 PM	53-20
	Perform Detailed Inspection of the Sills, Frames and External Skin around the Passenger Door Cutout		B1019908 - Joseph Barnes Feb 16, 2026 09:14 PM	
	200	Removed all tools, equipment and materials from the work area.	B1002512 - Brandon Warne Feb 16, 2026 08:51 PM	
	Remove all tools, equipment and materials from the work area.		B1019908 - Joseph Barnes Feb 16, 2026 09:14 PM	

Sequence #	0010-111	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504222	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-111	WO #	2504222	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Internal Mid-Fuselage (Skin and Structure, FS409.00 Bulkhead Forward Face and the External Surfaces of the Forward-Auxiliary Fuel Tank) - FS280.00 to FS409.00 below the floor	
Detailed Inspection of the Internal Mid-Fuselage (Skin and Structure, FS409.00 Bulkhead Forward Face and the External Surfaces of the Forward-Auxiliary Fuel Tank) - FS280.00 to FS409.00 below the floor				
Task / IRN # : 53-20-00-207				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 53-20-00-207, Perform Detailed Inspection of the Internal Mid-Fuselage (Skin and Structure, FS409.00 Bulkhead Forward Face and the External Surfaces of the Forward-Auxiliary Fuel Tank) - FS280.00 to FS409.00 below the floor, in accordance with CL-650 AMM 53-20-01-220-861. No defects noted	B0642051 - Terry Walters Feb 16, 2026 04:51 PM	53-20
	Perform Detailed Inspection of the Internal Mid-Fuselage (Skin and Structure, FS409.00 Bulkhead Forward Face and the External Surfaces of the Forward-Auxiliary Fuel Tank) - FS280.00 to FS409.00 below the floor		B1019908 - Joseph Barnes Feb 16, 2026 05:10 PM	
	200	Removed all Tools, Equipment, and unwanted materials from the work area.	B0642051 - Terry Walters Feb 16, 2026 04:51 PM	
	Remove all Tools, Equipment, and unwanted materials from the work area.		B1019908 - Joseph Barnes Feb 16, 2026 05:10 PM	

Bombardier

Sequence #	0010-112	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504224	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-112	WO #	2504224	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of Wing-to-Fuselage Attachment Link - FS513	
Detailed Inspection of Wing-to-Fuselage Attachment Link - FS513				
Task / IRN # : 53-20-00-224				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with TLMC task 53-10-00-224 Performed LH detailed inspection of the wing to fuselage attachment link (FS513) REF CL-650 AMM 53-20-01-220-822. No defects noted.	B1002512 - Brandon Warne Feb 12, 2026 08:57 PM	53-20
	Perform LH Detailed Inspection of Wing-to-Fuselage Attachment Link - FS513		B1013522 - Brandon Jennings Feb 12, 2026 09:08 PM	
	101	Complied with TLMC task 53-20-00-224 Performed LH detailed inspection of the wing to fuselage attachment link (FS513) REF CL-650 AMM 53-20-01-220-822. No defects noted.	B1002512 - Brandon Warne Feb 12, 2026 09:16 PM	
	Perform LH Detailed Inspection of Wing-to-Fuselage Attachment Link - FS513		B0142244 - Todd Bridges Feb 13, 2026 02:54 PM	09
	200	Complied with TLMC task 53-10-00-224 Performed RH detailed inspection of the wing to fuselage attachment link (FS513) REF CL-650 AMM 53-20-01-220-822. No defects noted.	B1002512 - Brandon Warne Feb 12, 2026 08:57 PM	53-20
	Perform RH Detailed Inspection of Wing-to-Fuselage Attachment Link - FS513		B1013522 - Brandon Jennings Feb 12, 2026 09:08 PM	
	201	Complied with TLMC task 53-20-00-224 Performed RH detailed inspection of the wing to fuselage attachment link (FS513) REF CL-650 AMM 53-20-01-220-822. No defects noted.	B1002512 - Brandon Warne Feb 12, 2026 09:16 PM	
	Perform RH Detailed Inspection of Wing-to-Fuselage Attachment Link - FS513		B0142244 - Todd Bridges Feb 13, 2026 02:54 PM	09
	300	Removed all tools, equipment and materials from the work.	B1002512 - Brandon Warne Feb 12, 2026 08:57 PM	
	Remove all tools, equipment and materials from the work.		B1013522 - Brandon Jennings Feb 12, 2026 09:08 PM	

Sequence #	0010-113	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	2504226	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2503652

0010-113	**WO #**	**2504226**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		Detailed Inspection of the Wing-to-Floor Tie Beam - FS460	
Detailed Inspection of the Wing-to-Floor Tie Beam - FS460				
Task / IRN # : 53-20-00-225				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with TLMC task 53-20-00-225 Performed LH detailed inspection of the wing to floor tie beam (FS460) REF CL-650 53-20-01-220-823. No defects noted.	B1002512 - Brandon Warne Feb 13, 2026 02:22 PM	53-20
	Perform LH Detailed Inspection of the Wing-to-Floor Tie Beam - FS460		B0142244 - Todd Bridges Feb 13, 2026 02:58 PM	
	200	Complied with TLMC task 53-20-00-225 Performed RH detailed inspection of the wing to floor tie beam (FS460) REF CL-650 53-20-01-220-823. No defects noted.	B1002512 - Brandon Warne Feb 13, 2026 02:22 PM	53-20
	Perform RH Detailed Inspection of the Wing-to-Floor Tie Beam - FS460		B0142244 - Todd Bridges Feb 13, 2026 02:58 PM	
	300	Removed all tools, equipment and materials from the work area.	B1002512 - Brandon Warne Feb 13, 2026 02:22 PM	
	Remove all tools, equipment and materials from the work area.		B0142244 - Todd Bridges Feb 13, 2026 02:58 PM	

Sequence #	0010-114	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504230	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-114	WO #	2504230	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Upper Surface of the Pressure Floor Skin Panel - FS409 to FS559 and BL36L to BL36R	
Detailed Inspection of the Upper Surface of the Pressure Floor Skin Panel - FS409 to FS559 and BL36L to BL36R				
Task / IRN # : 53-20-00-226				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 53-20-00-226, Perform Detailed Inspection of the Upper Surface of the Pressure Floor Skin Panel - FS409 to FS559 and BL36L to BL36R, in accordance with CL-650 AMM 53-20-01-220-824. With Defects Noted see findings for details.	B0642051 - Terry Walters Feb 16, 2026 05:05 PM	53-20
	Perform Detailed Inspection of the Upper Surface of the Pressure Floor Skin Panel - FS409 to FS559 and BL36L to BL36R		B1019908 - Joseph Barnes Feb 16, 2026 05:35 PM	
	200	Removed all tools, equipment, and unwanted materials from the work area.	B0642051 - Terry Walters Feb 16, 2026 05:05 PM	
	Remove all tools, equipment, and unwanted materials from the work area.		B1019908 - Joseph Barnes Feb 16, 2026 05:35 PM	

FINDINGS DETAILS

Finding #	Long Description	Status	Reported By / Date	Defect Source / Disposition	Defect Type	Priority	Follow-up WO #
80462	Exposed graphite on floor Panel 232WRF, tape protection is torn and coming up on the panel.	CLOSED	B0642051 - Terry Walters Feb 16, 2026 10:01 AM	MAINTENANCE 300-QA002	OTHER	3	4790148-PSAP

Sequence #	0010-115	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504232	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-115	WO #	2504232	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Lower Surface of the Pressure Floor Skin Panel - FS409 to FS559 and BL36L to BL36R	
Detailed Inspection of the Lower Surface of the Pressure Floor Skin Panel - FS409 to FS559 and BL36L to BL36R				
Task / IRN # : 53-20-00-227				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 53-20-00-227, Perform Detailed Inspection of the Lower Surface of the Pressure Floor Skin Panel - FS409 to FS559 and BL36L to BL36R, in accordance with CL-650 AMM 53-20-01-220-825. No Defects Noted.	B0642051 - Terry Walters Feb 13, 2026 03:42 PM	53-20
	Perform Detailed Inspection of the Lower Surface of the Pressure Floor Skin Panel - FS409 to FS559 and BL36L to BL36R		B0142244 - Todd Bridges Feb 13, 2026 09:44 PM	
	200	Removed all Tools, Equipment, and unwanted materials from the work area.	B0642051 - Terry Walters Feb 13, 2026 03:42 PM	
	Remove all Tools, Equipment, and unwanted materials from the work area.		B0142244 - Todd Bridges Feb 13, 2026 09:44 PM	

Bombardier

Sequence #	0010-116	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504233	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-116	WO #	2504233	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Pressure Floor Support Beams - FS409 to FS559, BL0.0, BL9, BL18.6, BL27 and BL35.4	
Detailed Inspection of the Pressure Floor Support Beams - FS409 to FS559, BL0.0, BL9, BL18.6, BL27 and BL35.4				
Task / IRN # : 53-20-00-228				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 53-20-00-228,Detailed Inspection of the Pressure Floor Support Beams - FS409 to FS559, BL0.0, BL9, BL18.6, BL27 and BL35.4. Ref: CL-650 AMM 53-20-01-220-826. One defect noted, see finding : 80368	B1018409 - Areida Cruz Feb 15, 2026 03:27 PM	53-20
	Perform Detailed Inspection of the Pressure Floor Support Beams - FS409 to FS559, BL0.0, BL9, BL18.6, BL27 and BL35.4		B0142244 - Todd Bridges Feb 15, 2026 04:30 PM	
	200	Removed all tools, equipment, and unwanted materials from the work area	B1018409 - Areida Cruz Feb 15, 2026 03:27 PM	
	Remove all tools, equipment, and unwanted materials from the work area		B0142244 - Todd Bridges Feb 15, 2026 04:30 PM	

FINDINGS DETAILS

Finding #	Long Description	Status	Reported By / Date	Defect Source / Disposition	Defect Type	Priority	Follow-up WO #
80368	Under floor panel 232 MRF found a wire insulation to be torn and core wire is exposed	CLOSED	B1018409 - Areida Cruz Feb 15, 2026 7:46 AM	MAINTENANCE 300-QA002	OTHER	3	4795513-PSAP

Sequence #	0010-117	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504236	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-117	WO #	2504236	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Forward Engine-Mount Spar Assembly	
Detailed Inspection of the Forward Engine-Mount Spar Assembly				
Task / IRN # : 54-50-00-201				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with Task Card 54-50-00-201. Perform Detailed Inspection of LH Forward Engine-Mount Spar Assembly. Ref. CL650 AMM 54-50-01-220-801. No discrepancies noted at this time.	K1018275 - Emmanuel Cocoa Feb 06, 2026 05:03 PM	54-50
	Perform Detailed Inspection of LH Forward Engine-Mount Spar Assembly		B1013522 - Brandon Jennings Feb 06, 2026 05:32 PM	
	200	Complied with Task Card 54-50-00-201. Perform Detailed Inspection of RH Forward Engine-Mount Spar Assembly. Ref. CL650 AMM 54-50-01-220-801. No discrepancies noted at this time.	K1018275 - Emmanuel Cocoa Feb 06, 2026 05:29 PM	54-50
	Perform Detailed Inspection of RH Forward Engine-Mount Spar Assembly		B1013522 - Brandon Jennings Feb 06, 2026 05:32 PM	
	300	Removed all tools equipment and unwanted materials	K1018275 - Emmanuel Cocoa Feb 06, 2026 05:29 PM	
	Remove all tools equipment and unwanted materials		B1013522 - Brandon Jennings Feb 06, 2026 05:32 PM	

Bombardier

Sequence #	0010-118	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504238	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-118	WO #	2504238	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Internal Structure of the Pylon	
Detailed Inspection of the Internal Structure of the Pylon				
Task / IRN # : 54-50-00-203				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with TLMC 54-50-00-203. Performed a Detailed Inspection of LH Internal Structure of the Pylon Ref. CL-650 AMM 54-50-01-220-803. No defects noted.	B0613291 - Eric Strong Feb 08, 2026 11:35 PM	54-50
	Perform Detailed Inspection of LH Internal Structure of the Pylon		B0142244 - Todd Bridges Feb 09, 2026 12:31 AM	
	200	Performed detailed inspection of RH Internal Structure of the Pylon IAW CL-650 AMM 54-50-01-220-803. Complied with Task 54-50-00-203 No discrepancies noted.	B1018546 - Andres Velazquez Feb 07, 2026 12:44 AM	54-50
	Perform Detailed Inspection of RH Internal Structure of the Pylon		B0142244 - Todd Bridges Feb 09, 2026 12:31 AM	
	300	Removed all tools, equipment, and unwanted materials from the work area.	B0613291 - Eric Strong Feb 08, 2026 11:35 PM	
	Remove all tools, equipment, and unwanted materials from the work area.		B0142244 - Todd Bridges Feb 09, 2026 12:31 AM	

Sequence #	0010-119	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504240	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-119	WO #	2504240	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Aft Engine-Mount Support Structure	
Detailed Inspection of the Aft Engine-Mount Support Structure				
Task / IRN # : 54-50-00-204				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with Task Card 54-50-00-204. Perform Detailed Inspection of LH Aft Engine-Mount Support Structure. Ref. CL650 AMM 54-50-01-220-804. No discrepancies noted at this time.	K1018275 - Emmanuel Cocoa Feb 07, 2026 03:41 PM	54-50
	Perform Detailed Inspection of LH Aft Engine-Mount Support Structure		B0142244 - Todd Bridges Feb 07, 2026 04:49 PM	
	200	Complied with Task Card 54-50-00-204. Perform Detailed Inspection of RH Aft Engine-Mount Support Structure. REF. CL650 AMM 54-50-01-220-804. No discrepancies noted at this time.	K1018275 - Emmanuel Cocoa Feb 06, 2026 05:51 PM	54-50
	Perform Detailed Inspection of RH Aft Engine-Mount Support Structure		B0142244 - Todd Bridges Feb 07, 2026 04:49 PM	
	300	Removed all tools equipment and unwanted materials.	K1018275 - Emmanuel Cocoa Feb 07, 2026 03:41 PM	
	Remove all tools equipment and unwanted materials.		B0142244 - Todd Bridges Feb 07, 2026 04:49 PM	

Bombardier

Sequence #	0010-120	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504246	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-120	WO #	2504246	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Internal Center Wing (Spars, Rib and Wing Plank Surfaces) - LWS45.00 to RWS45.00	
Detailed Inspection of the Internal Center Wing (Spars, Rib and Wing Plank Surfaces) - LWS45.00 to RWS45.00				
Task / IRN # : 57-10-00-202				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 57-10-00-202, Perform LH Detailed Inspection of the Internal Center Wing (Spars, Rib and Wing Plank Surfaces) - LWS4500 to RWS4500, in accordance with CL-650 AMM 57-10-00-220-864. No Defects Noted.	B0642051 - Terry Walters Feb 16, 2026 07:14 PM	57-10
	Perform LH Detailed Inspection of the Internal Center Wing (Spars, Rib and Wing Plank Surfaces) - LWS4500 to RWS4500		B1019908 - Joseph Barnes Feb 16, 2026 07:42 PM	
	200	Complied with task 57-10-00-202, Perform RH Detailed Inspection of the Internal Center Wing (Spars, Rib and Wing Plank Surfaces) - LWS4500 to RWS4500, in accordance with CL-650 AMM 57-10-00-220-864. No Defects Noted	B0642051 - Terry Walters Feb 16, 2026 07:14 PM	57-10
	Perform RH Detailed Inspection of the Internal Center Wing (Spars, Rib and Wing Plank Surfaces) - LWS4500 to RWS4500		B1019908 - Joseph Barnes Feb 16, 2026 07:42 PM	
	300	Removed all tools, equipment, and unwanted materials from the work area.	B0642051 - Terry Walters Feb 16, 2026 07:14 PM	
	Remove all tools, equipment, and unwanted materials from the work area.		B1019908 - Joseph Barnes Feb 16, 2026 07:42 PM	

Sequence #	0010-121	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504247	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-121	WO #	2504247	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the External Center Wing (Rear Spar and Upper Wing Plank, MLG Side Brace Fitting and Rear Spar Bayonet-Fitting) - LWS48.00 to RWS48.00	
Detailed Inspection of the External Center Wing (Rear Spar and Upper Wing Plank, MLG Side Brace Fitting and Rear Spar Bayonet-Fitting) - LWS48.00 to RWS48.00				
Task / IRN # : 57-10-00-204				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 57-10-00-204, Perform LH Detailed Inspection of the External Center Wing (Rear Spar and Upper Wing Plank, MLG Side Brace Fitting and Rear Spar Bayonet-Fitting) - LWS48.00 to RWS48.00, in accordance with CL-650 AMM 57-10-00-220-865. No Defects Noted.	B0642051 - Terry Walters Feb 16, 2026 07:19 PM	57-10
	Perform LH Detailed Inspection of the External Center Wing (Rear Spar and Upper Wing Plank, MLG Side Brace Fitting and Rear Spar Bayonet-Fitting) - LWS48.00 to RWS48.00		B1019908 - Joseph Barnes Feb 16, 2026 07:43 PM	
	200	Complied with task 57-10-00-204, Perform RH Detailed Inspection of the External Center Wing (Rear Spar and Upper Wing Plank, MLG Side Brace Fitting and Rear Spar Bayonet-Fitting) - LWS48.00 to RWS48.00, in accordance with CL-650 AMM 57-10-00-220-865. No Defects Noted.	B0642051 - Terry Walters Feb 16, 2026 07:19 PM	57-10
	Perform RH Detailed Inspection of the External Center Wing (Rear Spar and Upper Wing Plank, MLG Side Brace Fitting and Rear Spar Bayonet-Fitting) - LWS48.00 to RWS48.00		B1019908 - Joseph Barnes Feb 16, 2026 07:43 PM	
	300	Removed all tools, equipment, and unwanted materials from the work area.	B0642051 - Terry Walters Feb 16, 2026 07:19 PM	
	Remove all tools, equipment, and unwanted materials from the work area.		B1019908 - Joseph Barnes Feb 16, 2026 07:43 PM	

Bombardier

Sequence #	0010-122	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504251	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-122	WO #	2504251	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Forward Face of the Front Spar of the Wing - WS50 to WS353	
Detailed Inspection of the Forward Face of the Front Spar of the Wing - WS50 to WS353				
Task / IRN # : 57-10-00-208				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 57-10-00-208, Performed LH Detailed Inspection of the Forward Face of the Front Spar of the wing - WS50 to WS353 In accordance with CL-650 AMM 57-10-00-220-808 No Defects Noted	B0642051 - Terry Walters Feb 16, 2026 07:37 PM	57-10
	Perform LH Detailed Inspection of the Forward Face of the Front Spar of the Wing - WS50 to WS353		B1019908 - Joseph Barnes Feb 16, 2026 08:04 PM	
	200	Complied with task 57-10-00-208, Performed RH Detailed Inspection of the Forward Face of the Front Spar of the wing - WS50 to WS353 In accordance with CL-650 AMM 57-10-00-220-808 No Defects Noted	B0642051 - Terry Walters Feb 16, 2026 07:37 PM	57-10
	Perform RH Detailed Inspection of the Forward Face of the Front Spar of the Wing - WS50 to WS353		B1019908 - Joseph Barnes Feb 16, 2026 08:04 PM	
	300	Removed all tools, equipment, and unwanted materials from the work area.	B0642051 - Terry Walters Feb 16, 2026 07:37 PM	
	Remove all tools, equipment, and unwanted materials from the work area.		B1019908 - Joseph Barnes Feb 16, 2026 08:04 PM	

Sequence #	0010-123	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	2504255	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2503652

			LOG BOOK VERBIAGE	Deferrals
0010-123	**WO #**	**2504255**		
	SAP SVO #		Detailed Inspection of the Internal Wing (Front Spar, Rear Spar, Wing Planks, Structure and the MLG Mounting Fittings) - WS45.00 to Canted WS314.50	
Detailed Inspection of the Internal Wing (Front Spar, Rear Spar, Wing Planks, Structure and the MLG Mounting Fittings) - WS45.00 to Canted WS314.50				
Task / IRN # : 57-10-00-209				

Sequence #	0010-123	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504255	Aircraft Reg #	XA-SOL	Parent WO #	2503652

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task number 57-10-00-209. Performed LH Detailed Inspection of the Internal Wing (Front Spar, Rear Spar, Wing Planks, Structure and the MLG Mounting Fittings) - WS4500 to Canted WS31450 IAW CL650 AMM 57-10-00-209. No defects noted.	B1022255 - Carson Chang Feb 17, 2026 07:55 PM	57-10
	Perform LH Detailed Inspection of the Internal Wing (Front Spar, Rear Spar, Wing Planks, Structure and the MLG Mounting Fittings) - WS4500 to Canted WS31450		B1013522 - Brandon Jennings Feb 17, 2026 08:13 PM	
	101	Complied with task number 57-10-00-209. Performed LH Detailed Inspection of the Internal Wing (Front Spar, Rear Spar, Wing Planks, Structure and the MLG Mounting Fittings) - WS45.00 to Canted WS314.50 IAW CL650 AMM 57-10-00-220-867. No defects noted.	B1022255 - Carson Chang Feb 17, 2026 08:48 PM	
	Perform LH Detailed Inspection of the Internal Wing (Front Spar, Rear Spar, Wing Planks, Structure and the MLG Mounting Fittings) - WS4500 to Canted WS31450		B1013522 - Brandon Jennings Feb 17, 2026 08:58 PM	09
	200	Complied with task 57-10-00-209 RH Detailed Inspection of the Internal Wing (Front Spar, Rear Spar, Wing Planks, Structure and the MLG Mounting Fittings) - WS4500 to Canted WS31450 REF CL650 AMM 57-10-00-220-867. No defects noted at this time.	B0648431 - Caleb Sexton Feb 17, 2026 07:58 PM	57-10
	Perform RH Detailed Inspection of the Internal Wing (Front Spar, Rear Spar, Wing Planks, Structure and the MLG Mounting Fittings) - WS4500 to Canted WS31450		B1013522 - Brandon Jennings Feb 17, 2026 08:13 PM	
	300	Removed all tools, equipment, and unwanted materials from the work area	B0648431 - Caleb Sexton Feb 17, 2026 07:58 PM	
	Remove all tools, equipment, and unwanted materials from the work area		B1013522 - Brandon Jennings Feb 17, 2026 08:13 PM	

Bombardier

Sequence #	0010-124	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504256	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-124	WO #	2504256	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Internal Skin and the Wing Structure - Canted WS314.5 to WS353	
Detailed Inspection of the Internal Skin and the Wing Structure - Canted WS314.5 to WS353				
Task / IRN # : 57-10-00-213				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 57-10-00-213, Perform LH Detailed Inspection of the Internal Skin and the Wing Structure - Canted WS3145 to WS353, in accordance with CL-650 AMM 57-10-00-220-813. No Defects Noted.	B0642051 - Terry Walters Feb 16, 2026 07:35 PM	57-10
	Perform LH Detailed Inspection of the Internal Skin and the Wing Structure - Canted WS3145 to WS353		B1019908 - Joseph Barnes Feb 16, 2026 08:04 PM	
	200	Complied with task 57-10-00-213, Perform RH Detailed Inspection of the Internal Skin and the Wing Structure - Canted WS3145 to WS353, in accordance with CL-650 AMM 57-10-00-220-813. No Defects Noted.	B0642051 - Terry Walters Feb 16, 2026 07:35 PM	57-10
	Perform RH Detailed Inspection of the Internal Skin and the Wing Structure - Canted WS3145 to WS353		B1019908 - Joseph Barnes Feb 16, 2026 08:04 PM	
	300	Removed all tools, equipment, and unwanted materials from the work area.	B0642051 - Terry Walters Feb 16, 2026 07:35 PM	
	Remove all tools, equipment, and unwanted materials from the work area.		B1019908 - Joseph Barnes Feb 16, 2026 08:04 PM	

Sequence #	0010-125	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504261	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-125	WO #	2504261	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Wing-to-Fuselage Attachment Fittings and Bolts - FS424.00, FS473.15 and FS513.00	
Detailed Inspection of the Wing-to-Fuselage Attachment Fittings and Bolts - FS424.00, FS473.15 and FS513.00				
Task / IRN # : 57-10-00-224				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with TLMC 57-10-00-224 Performed LH detailed inspection of the wing to fuselage attachment fittings and bolts (FS424.00, FS473.15 and FS513.00 REF CL-650 AMM 57-10-00-220-869. No defects noted.	B1002512 - Brandon Warne Feb 12, 2026 08:50 PM	57-10
	Perform LH Detailed Inspection of the Wing-to-Fuselage Attachment Fittings and Bolts - FS424.00, FS473.15 and FS513.00		B1013522 - Brandon Jennings Feb 12, 2026 09:02 PM	
	200	Complied with TLMC 57-10-00-224 Performed RH detailed inspection of the wing to fuselage attachment fittings and bolts (FS424.00, FS473.15 and FS513.00 REF CL-650 AMM 57-10-00-220-869. No defects noted.	B1002512 - Brandon Warne Feb 12, 2026 08:50 PM	57-10
	Perform RH Detailed Inspection of the Wing-to-Fuselage Attachment Fittings and Bolts - FS424.00, FS473.15 and FS513.00		B1013522 - Brandon Jennings Feb 12, 2026 09:02 PM	
	300	Removed all tools, equipment and materials from the work area.	B1002512 - Brandon Warne Feb 12, 2026 08:50 PM	
	Remove all tools, equipment and materials from the work area.		B1013522 - Brandon Jennings Feb 12, 2026 09:02 PM	

Bombardier

Sequence #	0010-126	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504264	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-126	WO #	2504264	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Attachment Fittings of the Flap Hinge Box of the Inboard Flap - WS76.5 and WS127.25	
Detailed Inspection of the Attachment Fittings of the Flap Hinge Box of the Inboard Flap - WS76.5 and WS127.25				
Task / IRN # : 57-10-00-227				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 57-10-00-227 Detailed Inspection of the LH Attachment Fittings of the Flap Hinge Box of the Inboard Flap - WS76.5 and WS127.25 IAW CL-650 AMM 57-10-00-220-827. No defects noted.	B0650736 - Jesus Gonzalez Atondo Feb 10, 2026 03:42 PM	57-10
	Perform LH Detailed Inspection of the Attachment Fittings of the Flap Hinge Box of the Inboard Flap - WS76.5 and WS127.25		B1013522 - Brandon Jennings Feb 10, 2026 03:52 PM	
	200	Complied with task 57-10-00-227 Detailed Inspection of the RH Attachment Fittings of the Flap Hinge Box of the Inboard Flap - WS76.5 and WS127.25 IAW CL-650 AMM 57-10-00-220-827. No defects noted.	B0650736 - Jesus Gonzalez Atondo Feb 10, 2026 03:42 PM	57-10
	Perform RH Detailed Inspection of the Attachment Fittings of the Flap Hinge Box of the Inboard Flap - WS76.5 and WS127.25		B1013522 - Brandon Jennings Feb 10, 2026 03:52 PM	
	300	Removed all tools, equipment, and unwanted materials from the work area.	B0650736 - Jesus Gonzalez Atondo Feb 10, 2026 03:42 PM	
	Remove all tools, equipment, and unwanted materials from the work area.		B1013522 - Brandon Jennings Feb 10, 2026 03:52 PM	

Sequence #	0010-127	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504267	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-127	WO #	2504267	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Attachment Fittings of the Flap Hinge Box of the Outboard Flap - WS178, WS220 and WS264	
Detailed Inspection of the Attachment Fittings of the Flap Hinge Box of the Outboard Flap - WS178, WS220 and WS264				
Task / IRN # : 57-10-00-228				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 57-10-00-228, detailed inspection of the attachment fittings of the LH flap hinge box of the outboard flap - WS178, WS220 and WS 264 IAW CL-650 AMM 57-10-00-220-828. No defects found.	B1021822 - Joseph Cuoco Feb 10, 2026 05:40 PM	57-10
	Perform LH Detailed Inspection of the Attachment Fittings of the Flap Hinge Box of the Outboard Flap - WS178, WS220 and WS264		B1013522 - Brandon Jennings Feb 10, 2026 06:58 PM	
	200	Complied with task 57-10-00-228, detailed inspection of the attachment fittings of the RH flap hinge box of the outboard flap - WS178, WS220 and WS 264 IAW CL-650 AMM 57-10-00-220-828. No defects found.	B1021822 - Joseph Cuoco Feb 10, 2026 05:40 PM	57-10
	Perform RH Detailed Inspection of the Attachment Fittings of the Flap Hinge Box of the Outboard Flap - WS178, WS220 and WS264		B1013522 - Brandon Jennings Feb 10, 2026 06:58 PM	
	300	Removed all tools, equipment and unwanted materials from the work area.	B1021822 - Joseph Cuoco Feb 10, 2026 05:40 PM	
	Remove all tools, equipment and unwanted materials from the work area.		B1013522 - Brandon Jennings Feb 10, 2026 06:58 PM	

Sequence #	0010-128	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504270	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-128	WO #	2504270	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Aileron (External Surfaces, Wing-to-Aileron Hinge Fittings, Hinge Bolts and Anti-Float Torsion Bar)	
Detailed Inspection of the Aileron (External Surfaces, Wing-to-Aileron Hinge Fittings, Hinge Bolts and Anti-Float Torsion Bar)				
Task / IRN # : 57-10-00-229				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 57-10-00-229 Detailed Inspection of the LH Aileron (External Surfaces, Wing-to-Aileron Hinge Fittings, Hinge Bolts and Anti-Float Torsion Bar) IAW CL-650 AMM 57-60-01-220-808. No defects noted.	B0650736 - Jesus Gonzalez Atondo Feb 12, 2026 01:39 PM	57-60
	Perform LH Detailed Inspection of the Aileron (External Surfaces, Wing-to-Aileron Hinge Fittings, Hinge Bolts and Anti-Float Torsion Bar)		B1013522 - Brandon Jennings Feb 12, 2026 01:47 PM	
	200	Complied with task 57-10-00-229 Detailed Inspection of the RH Aileron (External Surfaces, Wing-to-Aileron Hinge Fittings, Hinge Bolts and Anti-Float Torsion Bar) IAW CL-650 AMM 57-60-01-220-808. No defects noted.	B0650736 - Jesus Gonzalez Atondo Feb 12, 2026 01:39 PM	
	Perform RH Detailed Inspection of the Aileron (External Surfaces, Wing-to-Aileron Hinge Fittings, Hinge Bolts and Anti-Float Torsion Bar)		B1013522 - Brandon Jennings Feb 12, 2026 01:47 PM	
	300	Removed all tools, equipment, and unwanted materials from the work area.	B0650736 - Jesus Gonzalez Atondo Feb 12, 2026 01:39 PM	
	Remove all tools, equipment, and unwanted materials from the work area.		B1013522 - Brandon Jennings Feb 12, 2026 01:47 PM	
	400	See WO:2504336 for removal. See WO:2504327 for install.	B0650736 - Jesus Gonzalez Atondo Feb 12, 2026 01:52 PM	
	Operation to capture location of aileron removal/ install work performed		B1013522 - Brandon Jennings Feb 12, 2026 01:57 PM	

Bombardier

Sequence #	0010-129	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504273	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-129	WO #	2504273	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Hinge Fittings for the Ground Spoiler	
Detailed Inspection of the Hinge Fittings for the Ground Spoiler				
Task / IRN # : 57-10-00-230				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with Task No. 57-10-00-230. Performed a Detailed Inspection of the Hinge Fittings for the LH Ground Spoilers. See Finding No. 79862 Ref: CL650 AMM 57-10-00-220-830	B0646266 - Sergio Rodriguez Figueroa Feb 11, 2026 04:26 PM	57-10
	Perform LH Detailed Inspection of the Hinge Fittings for the Ground Spoiler		B1013522 - Brandon Jennings Feb 11, 2026 04:37 PM	
	200	Complied with Task No. 57-10-00-230. Performed a Detailed Inspection of the Hinge Fittings for the RH Ground Spoilers. No defects noted. Ref: CL650 AMM 57-10-00-220-830	B0646266 - Sergio Rodriguez Figueroa Feb 11, 2026 04:26 PM	57-10
	Perform RH Detailed Inspection of the Hinge Fittings for the Ground Spoiler		B1013522 - Brandon Jennings Feb 11, 2026 04:37 PM	
	300	Removed all tools, equipment, and unwanted materials from the work area as required.	B0646266 - Sergio Rodriguez Figueroa Feb 11, 2026 04:26 PM	
	Remove all tools, equipment, and unwanted material from the work area.		B1013522 - Brandon Jennings Feb 11, 2026 04:37 PM	

FINDINGS DETAILS

Finding #	Long Description	Status	Reported By / Date	Defect Source / Disposition	Defect Type	Priority	Follow-up WO #
79862	Found torn Bonding/Jumper Cable (PN: MS25083-5BB6) on LH Ground Spoiler.	CLOSED	B0646266 - Sergio Rodriguez Figueroa Feb 11, 2026 9:10 AM	MAINTENANCE 300-QA002	OTHER	3	4755973-PSAP

Bombardier

Sequence #	0010-130	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504276	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-130	WO #	2504276	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Hinge Fittings for the Flight Spoiler	
Detailed Inspection of the Hinge Fittings for the Flight Spoiler				
Task / IRN # : 57-10-00-231				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with Task No. 57-10-00-231. Performed a Detailed Inspection of the Hinge Fittings for the LH Flight Spoiler. No defects noted. Ref: CL650 AMM 57-10-00-220-831.	B0646266 - Sergio Rodriguez Figueroa Feb 11, 2026 05:37 PM	57-10
	Perform LH Detailed Inspection of the Hinge Fittings for the Flight Spoiler		B1013522 - Brandon Jennings Feb 11, 2026 05:46 PM	
	200	Complied with Task No. 57-10-00-231. Performed a Detailed Inspection of the Hinge Fittings for the RH Flight Spoiler. No defects noted. Ref: CL650 AMM 57-10-00-220-831.	B0646266 - Sergio Rodriguez Figueroa Feb 11, 2026 05:37 PM	57-10
	Perform RH Detailed Inspection of the Hinge Fittings for the Flight Spoiler		B1013522 - Brandon Jennings Feb 11, 2026 05:46 PM	
	300	Removed all tools, equipment, and unwanted materials from the work area as required.	B0646266 - Sergio Rodriguez Figueroa Feb 11, 2026 05:37 PM	
	Remove all tools, equipment, and unwanted material from the work area.		B1013522 - Brandon Jennings Feb 11, 2026 05:46 PM	

Sequence #	0010-131	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504279	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-131	WO #	2504279	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Skin, Spars, Attachment Fittings, and Internal Structure of the Winglet	
Detailed Inspection of the Skin, Spars, Attachment Fittings, and Internal Structure of the Winglet				
Task / IRN # : 57-30-00-201				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 57-30-00-201, Perform LH Detailed Inspection of the Skin, Spars, Attachment Fittings, and Internal Structure of the Winglet, in accordance with CL650 AMM 57-30-00-220-801. No defects noted.	B0641903 - Felipe Mendoza Cervantes Feb 19, 2026 01:24 AM	57-30
	Perform LH Detailed Inspection of the Skin, Spars, Attachment Fittings, and Internal Structure of the Winglet		B0623124 - Michael Stacy Feb 19, 2026 01:40 AM	
	200	Complied with task 57-30-00-201, Perform RH Detailed Inspection of the Skin, Spars, Attachment Fittings, and Internal Structure of the Winglet, in accordance with CL-650 AMM 57-30-00-220-801. No Defects Noted.	B0642051 - Terry Walters Feb 16, 2026 08:26 PM	57-30
	Perform RH Detailed Inspection of the Skin, Spars, Attachment Fittings, and Internal Structure of the Winglet		B1019908 - Joseph Barnes Feb 16, 2026 08:51 PM	
	300	Removed all tools, equipment, and unwanted materials from the work area.	B0641903 - Felipe Mendoza Cervantes Feb 19, 2026 01:24 AM	
	Remove all tools, equipment, and unwanted materials from the work area.		B0623124 - Michael Stacy Feb 19, 2026 01:40 AM	

FINDINGS DETAILS

Finding #	Long Description	Status	Reported By / Date	Defect Source / Disposition	Defect Type	Priority	Follow-up WO #
80732	LH Winglet has Excessive Filler Material that requires removed to access the screws	CLOSED	B0162034 - Tyler Poggi Feb 17, 2026 12:53 PM	MAINTENANCE 300-QA002	OTHER	3	4787778-PSAP

Sequence #	0010-132	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504282	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-132	WO #	2504282	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Inboard Flap (External Skins, Attachment Lugs and Hinge Arms)	
Detailed Inspection of the Inboard Flap (External Skins, Attachment Lugs and Hinge Arms)				
Task / IRN # : 57-50-00-202				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 57-50-00-202 Detailed Inspection of the LH Inboard Flap (External Skins, Attachment Lugs and Hinge Arms) IAW CL-650 AMM 57-50-01-220-818. No defects noted.	B0650736 - Jesus Gonzalez Atondo Feb 10, 2026 04:14 PM	57-50
	Perform LH Detailed Inspection of the Inboard Flap (External Skins, Attachment Lugs and Hinge Arms)		B1013522 - Brandon Jennings Feb 10, 2026 04:38 PM	
	200	Complied with task 57-50-00-202 Detailed Inspection of the RH Inboard Flap (External Skins, Attachment Lugs and Hinge Arms) IAW CL-650 AMM 57-50-01-220-818. No defects noted.	B0650736 - Jesus Gonzalez Atondo Feb 10, 2026 04:14 PM	57-50
	Perform RH Detailed Inspection of the Inboard Flap (External Skins, Attachment Lugs and Hinge Arms)		B1013522 - Brandon Jennings Feb 10, 2026 04:38 PM	
	300	Removed all tools, equipment, and unwanted materials from the work area.	B0650736 - Jesus Gonzalez Atondo Feb 10, 2026 04:14 PM	
	Remove all tools, equipment, and unwanted materials from the work area.		B1013522 - Brandon Jennings Feb 10, 2026 04:38 PM	

Sequence #	0010-133	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504283	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-133	WO #	2504283	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Outboard Flap (External Skins, Attachment Lugs and Hinge Arms)	
Detailed Inspection of the Outboard Flap (External Skins, Attachment Lugs and Hinge Arms)				
Task / IRN # : 57-50-00-207				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 57-50-00-207 Detailed Inspection of the LH Outboard Flap (External Skins, Attachment Lugs and Hinge Arms) IAW CL-650 AMM 57-50-01-220-819. No defects noted.	B0650736 - Jesus Gonzalez Atondo Feb 10, 2026 05:39 PM	57-50
	Perform LH Detailed Inspection of the Outboard Flap (External Skins, Attachment Lugs and Hinge Arms)		B1013522 - Brandon Jennings Feb 10, 2026 06:56 PM	
	200	Complied with task 57-50-00-207 Detailed Inspection of the RH Outboard Flap (External Skins, Attachment Lugs and Hinge Arms) IAW CL-650 AMM 57-50-01-220-819. No defects noted.	B0650736 - Jesus Gonzalez Atondo Feb 10, 2026 05:39 PM	57-50
	Perform RH Detailed Inspection of the Outboard Flap (External Skins, Attachment Lugs and Hinge Arms)		B1013522 - Brandon Jennings Feb 10, 2026 06:56 PM	
	300	Removed all tools, equipment, and unwanted materials from the work area.	B0650736 - Jesus Gonzalez Atondo Feb 10, 2026 05:39 PM	
	Remove all tools, equipment, and unwanted materials from the work area.		B1013522 - Brandon Jennings Feb 10, 2026 06:56 PM	

Bombardier

Sequence #	0010-134	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504288	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-134	WO #	2504288	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Flap Hinge Boxes of the Inboard Flap	
Detailed Inspection of the Flap Hinge Boxes of the Inboard Flap				
Task / IRN # : 57-50-00-210				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 57-50-00-210, Perform LH Detailed Inspection of the Flap Hinge Boxes of the Inboard Flap, REF CL650 AMM 57-50-01-220-810. No defects noted.	B1016542 - Carlos Ochoa Feb 10, 2026 10:01 PM	57-50
	Perform LH Detailed Inspection of the Flap Hinge Boxes of the Inboard Flap		B0623124 - Michael Stacy Feb 11, 2026 04:46 AM	
	200	Complied with task 57-50-00-210, Perform RH Detailed Inspection of the Flap Hinge Boxes of the Inboard Flap, REF CL650 AMM 57-50-01-220-810. No defects noted.	B1016542 - Carlos Ochoa Feb 10, 2026 10:01 PM	57-50
	Perform RH Detailed Inspection of the Flap Hinge Boxes of the Inboard Flap		B0623124 - Michael Stacy Feb 11, 2026 04:46 AM	
	300	Removed all tools, equipment, and unwanted materials.	B1016542 - Carlos Ochoa Feb 10, 2026 10:01 PM	
	Remove all tools, equipment, and unwanted materials.		B0623124 - Michael Stacy Feb 11, 2026 04:46 AM	

Sequence #	0010-135	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504291	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-135	WO #	2504291	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Flap Hinge Boxes of the Outboard Flap	
Detailed Inspection of the Flap Hinge Boxes of the Outboard Flap				
Task / IRN # : 57-50-00-211				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 57-50-00-211, Performed LH Detailed Inspection of the Flap Hinge Boxes of the Outboard Flap, in accordance with CL 650 AMM 57-50-01-220-811. See findings 79605 and 79606 for defects.	B1017798 - Hunter Van Der Heide Feb 10, 2026 04:13 AM	57-50
	Perform LH Detailed Inspection of the Flap Hinge Boxes of the Outboard Flap		B0161691 - Thomas Mitchell Feb 10, 2026 04:26 AM	
	200	Complied with task 57-50-00-211, Performed RH Detailed Inspection of the Flap Hinge Boxes of the Outboard Flap, in accordance with Cl 650 AMM 57-50-01-220-811. No defects noted.	B1017798 - Hunter Van Der Heide Feb 10, 2026 04:13 AM	57-50
	Perform RH Detailed Inspection of the Flap Hinge Boxes of the Outboard Flap		B0161691 - Thomas Mitchell Feb 10, 2026 04:26 AM	
	300	Removed all tools, equipment, and unwanted materials from the area.	B1017798 - Hunter Van Der Heide Feb 10, 2026 04:13 AM	
	Remove all tools, equipment, and unwanted materials from the are.		B0161691 - Thomas Mitchell Feb 10, 2026 04:26 AM	

Sequence #	0010-135	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504291	Aircraft Reg #	XA-SOL	Parent WO #	2503652

FINDINGS DETAILS

Finding #	Long Description	Status	Reported By / Date	Defect Source / Disposition	Defect Type	Priority	Follow-up WO #
79605	Evaluate and Advise: Corroded spring on the LH outboard flap hinge box (marked with streamer)	CLOSED	B1017798 - Hunter Van Der Heide Feb 9, 2026 7:02 PM	MAINTENANCE 300-QA002	OTHER	3	4750264-PSAP
79606	Corroded nut on the LH outboard flap hinge box (middle) marked with streamer	CLOSED	B1017798 - Hunter Van Der Heide Feb 9, 2026 7:05 PM	MAINTENANCE 300-QA002	OTHER	3	4756106-PSAP

Sequence #	0010-136	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	2504292	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2503652

0010-136	**WO #**	**2504292**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		Detailed Inspection of the Hinge Bolts of the Ground Spoiler	
Detailed Inspection of the Hinge Bolts of the Ground Spoiler				
Task / IRN # : 57-70-00-205				

Sequence #	0010-136	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504292	Aircraft Reg #	XA-SOL	Parent WO #	2503652

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with Task No. 57-70-00-205. Performed a Detailed Inspection of the Hinge Bolts of the LH Ground Spoiler. Removed and replaced the LH MIDDLE Hinge hardware with NEW hardware as required. Continue with Installation. See CMT Working Copy dated 02/13/26 for work performed. Ref: CL650 AMM 57-70-01-220-805 Steps 5.A through G.2(F)	B0646266 - Sergio Rodriguez Figueroa Feb 13, 2026 08:57 PM	57-70
	Perform LH Detailed Inspection of the Hinge Bolts of the Ground Spoiler		B0142244 - Todd Bridges Feb 13, 2026 09:53 PM	
	101	Complied with Task No. 57-70-00-205. Continued with the Detailed Inspection of the Hinge Bolts of the LH Ground Spoiler. Removed and replaced the LH (IB, MID, OB) Hinge hardware with NEW hardware as required. Ref: CL650 AMM 57-70-01-220-805 Steps G.(3) through Close Out.	B0646266 - Sergio Rodriguez Figueroa Feb 16, 2026 08:25 PM	
	Continue with the Detailed Inspection of the Hinge Bolts of the LH Ground Spoiler. Ref: CL650 AMM 57-70-01-220-805 Steps G.(3) through Close out.		B1019908 - Joseph Barnes Feb 16, 2026 08:58 PM	
	200	Complied with Task No. 57-70-00-205. Performed a Detailed Inspection of the Hinge Bolts of the Ground Spoiler. Removed and replaced with NEW hardware as required. Continue with Installation. Ref: CL650 AMM 57-70-01-220-805 Steps 5.A through G(3)	B0646266 - Sergio Rodriguez Figueroa Feb 12, 2026 08:48 PM	57-70
	Perform RH Detailed Inspection of the Hinge Bolts of the Ground Spoiler		B1013522 - Brandon Jennings Feb 12, 2026 09:00 PM	
	201	Complied with Task No. 57-70-00-205. Continued with the Detailed Inspection of the Hinge Bolts of the RH Ground Spoiler. Removed and replaced the RH (IB, MID, OB) Hinge hardware with NEW hardware as required. Ref: CL650 AMM 57-70-01-220-805 Steps G.(3) through Close Out.	B0646266 - Sergio Rodriguez Figueroa Feb 16, 2026 08:25 PM	
	Continue with the Detailed Inspection of the Hinge Bolts of the RH Ground Spoiler. Ref: CL650 AMM 57-70-01-220-805 Steps G(3) through Close out.		B1019908 - Joseph Barnes Feb 16, 2026 08:58 PM	
	300	Performed operational check of the ground spoilers. Operational check is good. REF: 27-61-00-710-802.	B0641903 - Felipe Mendoza Cervantes Mar 05, 2026 05:07 AM	
	Perform an Operational Test of the Ground Spoiler. Ref: CL650 AMM 27-61-00-710-802		B0609145 - Miguel Pacheco Mar 06, 2026 01:13 AM	

Sequence #	0010-136	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	2504292	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2503652

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	400	Removed all tools equipment and unwanted materials from the work area.	B0641903 - Felipe Mendoza Cervantes Mar 05, 2026 05:08 AM	
	Remove all tools equipment and unwanted materials from the work area.		B0609145 - Miguel Pacheco Mar 06, 2026 01:13 AM	

TOOL INFORMATION

Tool ID	Tool Description	Calibration Due Date
TUSS159G	Torque Wrench	Oct 30, 2026 5:00 PM
TUSS159G	Torque Wrench	Oct 30, 2026 5:00 PM

Sequence #	0010-137	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	2504297	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2503652

0010-137	**WO #**	**2504297**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		Detailed Inspection of the Hinge Bolts of the Flight Spoiler	
Detailed Inspection of the Hinge Bolts of the Flight Spoiler				
Task / IRN # : 57-70-00-206				

Sequence #	0010-137	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504297	Aircraft Reg #	XA-SOL	Parent WO #	2503652

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with Task No.57-70-00-206. Performed a Detailed Inspection of the LH Flight Spoiler Bolts (IB, OB, MID-IB). Installed NEW hardware as required. No defects noted. Continue with the Detailed Inspection of the MID-OB Flight Spoiler bolt. Ref: CL650 AMM 57-70-01-220-804 Steps 4.A through G.7(c).	B0646266 - Sergio Rodriguez Figueroa Feb 17, 2026 08:55 PM	57-70
	PERFORM LH - Detailed Inspection of the Hinge Bolts of the Flight Spoiler		B1013522 - Brandon Jennings Feb 17, 2026 09:18 PM	
	101	Continued with the Detailed Inspection of the LH MID-OB Hinge Bolt of the Flight Spoiler. Installed NEW hardware as required, no defects noted. Continue with the detailed inspection of the Hinge bolted of the flight spoiler. Ref: CL650 AMM 57-70-01-220-804 Steps 4.A through close out.	B0646266 - Sergio Rodriguez Figueroa Mar 05, 2026 05:09 PM	
	Continue with the Detailed Inspection of the LH MID-OB Hinge Bolt of the Flight Spoiler. Ref: CL650 AMM 57-70-01-220-804		B1013522 - Brandon Jennings Mar 05, 2026 07:17 PM	
	200	Complied with Task No.57-70-00-206. Performed a Detailed Inspection of the RH Flight Spoiler Bolts (IB, OB, MID-IB). Installed NEW hardware as required. No defects noted. Continue with the Detailed Inspection of the MID-OB Flight Spoiler bolt. Ref: CL650 AMM 57-70-01-220-804 Steps 4.A through G.7(c).	B0646266 - Sergio Rodriguez Figueroa Feb 17, 2026 08:55 PM	57-70
	PERFORM RH - Detailed Inspection of the Hinge Bolts of the Flight Spoiler		B1013522 - Brandon Jennings Feb 17, 2026 09:18 PM	
	201	Continued with the Detailed Inspection of the RH MID-OB Hinge Bolt of the Flight Spoiler. Installed NEW hardware as required, no defects noted. Continue with the detailed inspection of the Hinge bolted of the flight spoiler. Ref: CL650 AMM 57-70-01-220-804 Steps 4.A through G.8	B0646266 - Sergio Rodriguez Figueroa Feb 25, 2026 08:40 PM	
	Continue with the Detailed Inspection of the RH MID-OB Hinge Bolt of the Flight Spoiler. Ref: CL650 AMM 57-70-01-220-804		B1013522 - Brandon Jennings Feb 25, 2026 09:20 PM	
	202	Continued with the detailed inspection of the Hinge bolts of the flight spoiler. No defects noted. Ref: CL650 AMM 57-70-01-220-804 Steps G.9 through Close out.	B0646266 - Sergio Rodriguez Figueroa Mar 05, 2026 05:09 PM	
	Continue with the detailed inspection of the Hinge bolts of the flight spoiler. Ref: CL650 AMM 57-70-01-220-804 Steps G.9 through Close out.		B1013522 - Brandon Jennings Mar 05, 2026 07:17 PM	

Sequence #	0010-137	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504297	Aircraft Reg #	XA-SOL	Parent WO #	2503652

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	203	Continued with the Detailed Inspection of the RH MID-OB Hinge Bolt of the Flight Spoiler. Installed NEW hardware as required, no defects noted. Continue with the detailed inspection of the Hinge bolted of the flight spoiler. Ref: CL650 AMM 57-70-01-220-804 Steps 4.A through G.8	B0646266 - Sergio Rodriguez Figueroa Mar 05, 2026 03:41 PM	
	Continue with the Detailed Inspection of the RH MID-OB Hinge Bolt of the Flight Spoiler. Ref: CL650 AMM 57-70-01-220-804		B1013522 - Brandon Jennings Mar 05, 2026 04:24 PM	09
	300	Performed an Operational Test of the Flight Spoilers. Ops test good, no defects noted. Ref: CL650 AMM 27-61-00-710-801	B0646266 - Sergio Rodriguez Figueroa Mar 05, 2026 05:09 PM	
	Perform an Operational Test of the Flight Spoilers. Ref: CL650 AMM 27-61-00-710-801		B0142491 - George Ambrose Mar 05, 2026 05:55 PM	

FINDINGS DETAILS

Finding #	Long Description	Status	Reported By / Date	Defect Source / Disposition	Defect Type	Priority	Follow-up WO #
80619	Seized hardware during removal of the hinge bolts on both the LH and RH Flight Spoilers.	CLOSED	B0646266 - Sergio Rodriguez Figueroa Feb 17, 2026 6:11 AM	MAINTENANCE 300-QA002	OTHER	3	4784215-PSAP

TOOL INFORMATION

Tool ID	Tool Description	Calibration Due Date
TUSS2036	Torque Wrench	May 30, 2026 5:00 PM
TUSS2036	Torque Wrench 40-200 in	May 30, 2026 5:00 PM

Bombardier

Sequence #	0010-138	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504300	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-138	WO #	2504300	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Hinge Fittings of the Core Cowl Door	
Detailed Inspection of the Hinge Fittings of the Core Cowl Door				
Task / IRN # : 71-12-00-205				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with Task No. 71-12-00-205. Performed a Detailed Inspection of the Hinge Fittings of the LH Core Cowl Doors (UPPER, LOWER). No defects noted. Ref: CL650 AMM 71-12-01-220-801.	B0646266 - Sergio Rodriguez Figueroa Feb 10, 2026 08:54 PM	71-10
	Perform LH Detailed Inspection of the Hinge Fittings of the Core Cowl Door		B1013522 - Brandon Jennings Feb 10, 2026 09:00 PM	
	200	Complied with Task No. 71-12-00-205. Performed a Detailed Inspection of the Hinge Fittings of the RH Core Cowl Doors (UPPER, LOWER). No defects noted. Ref: CL650 AMM 71-12-01-220-801.	B0646266 - Sergio Rodriguez Figueroa Feb 10, 2026 08:54 PM	71-10
	Perform RH Detailed Inspection of the Hinge Fittings of the Core Cowl Door		B1013522 - Brandon Jennings Feb 10, 2026 09:00 PM	
	300	Removed all tools, equipment, and unwanted materials from the work area as required.	B0646266 - Sergio Rodriguez Figueroa Feb 10, 2026 08:54 PM	
	Remove all tools, equipment, and unwanted material from the work area.		B1013522 - Brandon Jennings Feb 10, 2026 09:00 PM	

Bombardier

Sequence #	0010-139	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504301	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-139	WO #	2504301	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Service Pylon Casting and Support Rails	
Detailed Inspection of the Service Pylon Casting and Support Rails				
Task / IRN # : 71-13-00-202				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with TLMC task 71-13-00-202 Performed Detailed inspection of the LH service pylon casting and support rails REF CL-650 AMM 71-10-00-220-801. No defects noted.	B1014141 - Christopher Drawdy Feb 11, 2026 08:52 PM	71-10
	Perform LH Detailed Inspection of the Service Pylon Casting and Support Rails		B1013522 - Brandon Jennings Feb 12, 2026 01:24 PM	
	200	Complied with TLMC task 71-13-00-202 Performed Detailed inspection of the RH service pylon casting and support rails REF CL-650 AMM 71-10-00-220-801. No defects noted.	B1014141 - Christopher Drawdy Feb 11, 2026 08:52 PM	71-10
	Perform RH Detailed Inspection of the Service Pylon Casting and Support Rails		B1013522 - Brandon Jennings Feb 12, 2026 01:24 PM	
	300	Removed all tools, equipment and materials from the work area.	B1002512 - Brandon Warne Feb 11, 2026 09:04 PM	
	Remove all tools, equipment and materials from the work area.		B1013522 - Brandon Jennings Feb 12, 2026 01:24 PM	

Sequence #	0010-140	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504306	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-140	WO #	2504306	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Forward Engine Mount Yoke and Link Assembly	
Detailed Inspection of the Forward Engine Mount Yoke and Link Assembly				
Task / IRN # : 71-20-00-202				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with Task Card 71-20-00-202. Perform LH Detailed Inspection of the Forward Engine Mount Yoke and Link Assembly. Ref. CL650 AMM 71-21-01-220-803. No discrepancies noted at this time.	K1018275 - Emmanuel Cocoa Feb 07, 2026 03:28 PM	71-20
	Perform LH Detailed Inspection of the Forward Engine Mount Yoke and Link Assembly		B0142244 - Todd Bridges Feb 07, 2026 04:51 PM	
	200	Complied with Task Card 71-20-00-202. Perform RH Detailed Inspection of the Forward Engine Mount Yoke and Link Assembly. Ref. CL650 AMM 71-21-01-220-803. No discrepancies noted at this time.	K1018275 - Emmanuel Cocoa Feb 07, 2026 03:28 PM	71-20
	Perform RH Detailed Inspection of the Forward Engine Mount Yoke and Link Assembly		B0142244 - Todd Bridges Feb 07, 2026 04:51 PM	
	300	Removed all tools equipment and unwanted materials.	K1018275 - Emmanuel Cocoa Feb 07, 2026 03:28 PM	
	Remove all tools equipment and unwanted materials.		B0142244 - Todd Bridges Feb 07, 2026 04:51 PM	

Bombardier

Sequence #	0010-141	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504309	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-141	WO #	2504309	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Aft Engine Mount Assembly	
Detailed Inspection of the Aft Engine Mount Assembly				
Task / IRN # : 71-20-00-203				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task card 71-20-00-203. Perform LH Detailed Inspection of the Aft Engine Mount Assembly. Ref. CL650 AMM 71-22-01-220-801. No discrepancies noted at this time.	K1018275 - Emmanuel Cocoa Feb 07, 2026 03:34 PM	71-20
	Perform LH Detailed Inspection of the Aft Engine Mount Assembly		B0142244 - Todd Bridges Feb 07, 2026 04:54 PM	
	200	Complied with task card 71-20-00-203. Perform RH Detailed Inspection of the Aft Engine Mount Assembly. Ref. CL650 AMM 71-22-01-220-801. No discrepancies noted at this time.	K1018275 - Emmanuel Cocoa Feb 07, 2026 03:34 PM	71-20
	Perform RH Detailed Inspection of the Aft Engine Mount Assembly		B0142244 - Todd Bridges Feb 07, 2026 04:54 PM	
	300	Removed all tools equipment and unwanted materials.	K1018275 - Emmanuel Cocoa Feb 07, 2026 03:34 PM	
	Remove all tools equipment and unwanted materials.		B0142244 - Todd Bridges Feb 07, 2026 04:54 PM	

Bombardier

Sequence #	0010-142	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504310	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-142	WO #	2504310	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Main Pylon Tracks of the Thrust-Reverser	
Detailed Inspection of the Main Pylon Tracks of the Thrust-Reverser				
Task / IRN # : 78-30-00-206				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 78-30-00-206 LH Detailed Inspection of the Main Pylon Tracks of the Thrust-Reverser REF CL650 AMM 78-34-07-220-802. No defects noted at this time	B0648431 - Caleb Sexton Feb 17, 2026 02:07 PM	78-30
	Perform LH Detailed Inspection of the Main Pylon Tracks of the Thrust-Reverser		B1013522 - Brandon Jennings Feb 17, 2026 02:53 PM	
	200	Complied with task 78-30-00-206 RH Detailed Inspection of the Main Pylon Tracks of the Thrust-Reverser REF CL650 AMM 78-34-07-220-802. No defects noted at this time	B0648431 - Caleb Sexton Feb 17, 2026 02:07 PM	78-30
	Perform RH Detailed Inspection of the Main Pylon Tracks of the Thrust-Reverser		B1013522 - Brandon Jennings Feb 17, 2026 02:53 PM	
	300	Removed all tools, equipment, and unwanted materials from the work area	B0648431 - Caleb Sexton Feb 17, 2026 02:07 PM	
	Remove all tools, equipment, and unwanted materials from the work area		B1013522 - Brandon Jennings Feb 17, 2026 02:53 PM	
	400	Complied with Lubrication of the Thrust Reverser Pylon−Tracks REF CL650 AMM 12−20−04−640−815	B0648431 - Caleb Sexton Feb 17, 2026 05:24 PM	
	C/W Lubrication of the Thrust Reverser Pylon−Tracks REF CL650 AMM 12−20−04−640−815		B1013522 - Brandon Jennings Feb 17, 2026 05:37 PM	

Sequence #	0010-143	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504315	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-143	WO #	2504315	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Thrust-Reverser Main Tracks	
Detailed Inspection of the Thrust-Reverser Main Tracks				
Task / IRN # : 78-30-00-207				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 78-30-00-207 LH Detailed Inspection of the Thrust-Reverser Main Tracks REF CL650 AMM 78-34-04-220-801. No defects noted at this time.	B0648431 - Caleb Sexton Feb 17, 2026 02:37 PM	78-30
	Perform LH Detailed Inspection of the Thrust-Reverser Main Tracks		B1013522 - Brandon Jennings Feb 17, 2026 05:36 PM	
	200	Complied with task 78-30-00-207 RH Detailed Inspection of the Thrust-Reverser Main Tracks REF CL650 AMM 78-34-04-220-801. No defects noted at this time.	B0648431 - Caleb Sexton Feb 17, 2026 02:37 PM	78-30
	Perform RH Detailed Inspection of the Thrust-Reverser Main Tracks		B1013522 - Brandon Jennings Feb 17, 2026 05:36 PM	
	300	Removed all tools, equipment, and unwanted materials from the work area	B0648431 - Caleb Sexton Feb 17, 2026 02:37 PM	
	Remove all tools, equipment, and unwanted materials from the work area		B1013522 - Brandon Jennings Feb 17, 2026 05:36 PM	
	400	Complied with Lubrication of the Thrust Reverser Main−Tracks REF CL650 AMM 12−20−04−640−816	B0648431 - Caleb Sexton Feb 17, 2026 05:18 PM	
	C/W Lubrication of the Thrust Reverser Main−Tracks REF CL650 AMM 12−20−04−640−816		B1013522 - Brandon Jennings Feb 17, 2026 05:36 PM	

Sequence #	0010-144	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504318	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-144	WO #	2504318	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Attachment Fittings for the Thrust-Reverser Main Tracks	
Detailed Inspection of the Attachment Fittings for the Thrust-Reverser Main Tracks				
Task / IRN # : 78-30-00-208				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 78-30-00-208 LH Detailed Inspection of the Attachment Fittings for the Thrust-Reverser Main Tracks REF CL650 AMM 78-34-04-220-802. No defects noted at this time	B0648431 - Caleb Sexton Feb 17, 2026 03:56 PM	78-30
	Perform LH Detailed Inspection of the Attachment Fittings for the Thrust-Reverser Main Tracks		B1013522 - Brandon Jennings Feb 17, 2026 04:16 PM	
	200	Complied with task 78-30-00-208 RH Detailed Inspection of the Attachment Fittings for the Thrust-Reverser Main Tracks REF CL650 AMM 78-34-04-220-802. No defects noted at this time	B0648431 - Caleb Sexton Feb 17, 2026 03:56 PM	78-30
	Perform RH Detailed Inspection of the Attachment Fittings for the Thrust-Reverser Main Tracks		B1013522 - Brandon Jennings Feb 17, 2026 04:16 PM	
	300	Removed all tools, equipment, and unwanted materials from the work area	B0648431 - Caleb Sexton Feb 17, 2026 03:56 PM	
	Remove all tools, equipment, and unwanted materials from the work area		B1013522 - Brandon Jennings Feb 17, 2026 04:16 PM	

Sequence #	0010-145	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504319	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-145	WO #	2504319	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Support Fittings of the Thrust-Reverser Ballscrew Actuators	
Detailed Inspection of the Support Fittings of the Thrust-Reverser Ballscrew Actuators				
Task / IRN # : 78-30-00-209				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 78-30-00-209 LH Detailed Inspection of the Support Fittings of the Thrust-Reverser Ballscrew Actuators REF CL650 AMM 78-32-04-220-801. No defects noted at this time.	B0648431 - Caleb Sexton Feb 17, 2026 05:13 PM	78-30
	Perform LH Detailed Inspection of the Support Fittings of the Thrust-Reverser Ballscrew Actuators		B1013522 - Brandon Jennings Feb 17, 2026 05:49 PM	
	200	Complied with task 78-30-00-209 RH Detailed Inspection of the Support Fittings of the Thrust-Reverser Ballscrew Actuators REF CL650 AMM 78-32-04-220-801. No defects noted at this time.	B0648431 - Caleb Sexton Feb 17, 2026 05:13 PM	78-30
	Perform RH Detailed Inspection of the Support Fittings of the Thrust-Reverser Ballscrew Actuators		B1013522 - Brandon Jennings Feb 17, 2026 05:49 PM	
	300	Removed all tools, equipment, and unwanted materials from the work area	B0648431 - Caleb Sexton Feb 17, 2026 05:13 PM	
	Remove all tools, equipment, and unwanted materials from the work area		B1013522 - Brandon Jennings Feb 17, 2026 05:49 PM	

Sequence #	0010-146	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	2504324	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2503652

0010-146	**WO #**	**2504324**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		No Log Entry	
Defuel Aircraft for Maintenance				
Task / IRN # : DEFUEL AIRCRAFT				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with gravity defueling of aircraft. REF: Challenger 650 AMM 12-11-28-650-804	B0646464 - Jonathan Nelson Feb 05, 2026 02:24 AM	12-10
	Defuel Aircraft for Maintenance		B0161691 - Thomas Mitchell Feb 05, 2026 03:26 AM	
	200	Removed all tools, equipment, and unwanted materials to prevent foreign object damage (FOD) to the aircraft.	B0646464 - Jonathan Nelson Feb 05, 2026 02:24 AM	
	Remove all tools, equipment, and unwanted materials to prevent foreign object damage (FOD) to the aircraft.		B0161691 - Thomas Mitchell Feb 05, 2026 03:26 AM	

Bombardier

Sequence #	0010-147	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	2504326	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2503652

0010-147	**WO #**	**2504326**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		No Log Entry	
Fuel Aircraft for Maintenance				
Task / IRN # : FUEL AIRCRAFT				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			12-10
	Fuel Aircraft for Maintenance			

Sequence #	0010-148	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	2504327	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2503652

			LOG BOOK VERBIAGE	Deferrals
0010-148	**WO #**	**2504327**		
	SAP SVO #		No Log Entry	
Install Ailerons for Maintenance				
CRITICAL MAINTENANCE TASK				
Task / IRN # : INSTALL AILERONS				

Sequence #	0010-148	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504327	Aircraft Reg #	XA-SOL	Parent WO #	2503652

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
CMT	100	Installed the LH Aileron IAW CL-650 AMM 27-15-01-400-801 steps 2.A through 2.F(15). Steps 2.F(2)(3) Not Applicable, items not removed. Steps 2.F(11)(12) only applicable to the right aileron. See CMT working copy dated 2/18/26	B0650736 - Jesus Gonzalez Atondo Feb 19, 2026 01:18 PM	27-10
	Install LH Aileron		B1013522 - Brandon Jennings Feb 19, 2026 01:50 PM	
CMT	101	Continued with the install of the LH Aileron ref. CL-650 AMM 27-15-01-400-801 steps 2.F(16) to Closeout. See CMT working copy dated 2/18/26.	B0650736 - Jesus Gonzalez Atondo Mar 05, 2026 04:01 PM	
	Continue with the install of the LH Aileron ref. CL-650 AMM 27-15-01-400-801 steps 2.F(16) to Closeout. See CMT working copy dated 2/18/26.		B0141354 - Karl Tuxhorn Mar 05, 2026 05:19 PM	
CMT	200	Installed the RH Aileron IAW CL-650 AMM 27-15-01-400-801 steps 2.A through 2.F(15). Steps 2.F(2)(3) Not Applicable, items not removed. See CMT working copy dated 2/18/26	B0650736 - Jesus Gonzalez Atondo Feb 19, 2026 01:18 PM	27-10
	Install RH Aileron		B1013522 - Brandon Jennings Feb 19, 2026 01:50 PM	
CMT	201	Continued with the install of the RH Aileron ref. CL-650 AMM 27-15-01-400-801 steps 2.F(16) to Closeout. See CMT working copy dated 2/18/26.	B0650736 - Jesus Gonzalez Atondo Mar 05, 2026 04:01 PM	
	Continue with the install of the RH Aileron ref. CL-650 AMM 27-15-01-400-801 steps 2.F(16) to Closeout. See CMT working copy dated 2/18/26.		B0141354 - Karl Tuxhorn Mar 05, 2026 05:19 PM	
	300	Completed functional test of the aileron backlash IAW CL650 AMM TASK 27-11-720-802. Functional test good.	B1022255 - Carson Chang Mar 04, 2026 05:57 PM	
	Complete functional test of the aileron backlash test IAW CL-650 AMM TASK 27-11-00-720-802		B1013522 - Brandon Jennings Mar 04, 2026 07:26 PM	
	301	Completed functional test of the aileron backlash IAW CL650 AMM TASK 27-11-00-720-802. Functional test good.	B1022255 - Carson Chang Mar 04, 2026 07:36 PM	
	Complete functional test of the aileron backlash test IAW CL-650 AMM TASK 27-11-00-720-802		B1013522 - Brandon Jennings Mar 04, 2026 08:02 PM	09
CMT	400	Performed the rigging of the PCU and aileron IAW CL-650 AMM 27-11-00-820-802. See CMT working copy dated 3/5/26. Rig check good.	B1022255 - Carson Chang Mar 05, 2026 03:18 PM	
	Perform the rigging of the PCU and aileron ref. CL-650 AMM 27-11-00-820-802.		B1013522 - Brandon Jennings Mar 05, 2026 03:26 PM	

Sequence #	0010-148	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504327	Aircraft Reg #	XA-SOL	Parent WO #	2503652

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
CMT	500	Performed ops test of the aileron position transmitter IAW CL-650 AMM 27-15-10-710-801. Ops check good See Aileron install CMT working copy dated 2/18/26	B1022255 - Carson Chang Mar 05, 2026 03:54 PM	
	Perform ops test of the aileron position transmitter ref. CL-650 AMM 27-15-10-710-801.		B0141354 - Karl Tuxhorn Mar 05, 2026 05:19 PM	
CMT	600	Performed adjustment of the aileron dual-synchro transmitter IAW CL-650 AMM TASK 22-11-11-820-801. Ops check good, no adjustment required. LH: -0.10 degrees & RH: -.011 degrees See Aileron instal CMT working copy dated 2/18/26	B1022255 - Carson Chang Mar 05, 2026 03:54 PM	
	Perform adjustment of the aileron dual-syncro transmitter ref. CL-650 AMM 22-11-11-820-801.		B0141354 - Karl Tuxhorn Mar 05, 2026 05:19 PM	
	700	Removed all tools, equipment and unwanted materials from the work area.	B1022255 - Carson Chang Mar 05, 2026 03:54 PM	
	Remove all tools, equipment and unwanted materials from the work area.		B0141354 - Karl Tuxhorn Mar 05, 2026 05:19 PM	

REMOVE AND RE-INSTALL DETAILS

	Removed Part # / Removed Serial #	Removed By	Removed - Part Description	Reference	Installed Part # / Installed Serial #	Installed By
	Removed Status	Removed Date-Time	Position	Installed Part Status	Installed Part Description	Installed Date-Time
	600-13000-1006 06111	B0650736 - Jesus Gonzalez Atondo	AILERON ASSY	Inspection	600-13000-1006 06111	B0650736 - Jesus Gonzalez Atondo
	SERVICEABLE	Feb 10, 2026 1:39 PM	RIGHT	SERVICEABLE	AILERON ASSY	Feb 19, 2026 6:19 AM
	600-13000-1005 06111	B0650736 - Jesus Gonzalez Atondo	AILERON ASSY	Inspection	600-13000-1005 06111	B0650736 - Jesus Gonzalez Atondo
	SERVICEABLE	Feb 10, 2026 1:36 PM	LEFT	SERVICEABLE	AILERON ASSY	Feb 19, 2026 6:19 AM

Sequence #	0010-148	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	2504327	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2503652

TOOL INFORMATION

Tool ID	Tool Description	Calibration Due Date
TUSS3756	torque wrench	Oct 30, 2026 5:00 PM
TUSS149C	torque wrench	Feb 27, 2027 5:00 PM
TUSS2036	torque wrench	May 30, 2026 5:00 PM
TUSS2702T	torque meter	Aug 30, 2026 5:00 PM
TUSS4022	safety cable tool	Jan 30, 2027 5:00 PM
TUSS4798	Digital Force Gauge	Nov 29, 2026 5:00 PM
TUSS2330K	Dial indicator	Aug 30, 2026 5:00 PM
TUSS4281	inclinometer	Apr 29, 2026 5:00 PM
TUSS3068	inclinometer	Aug 30, 2026 5:00 PM

Sequence #	0010-149	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	2504328	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2503652

0010-149	**WO #**	**2504328**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		Install Elevators for Maintenance	
Install Elevators for Maintenance				
CRITICAL MAINTENANCE TASK				
Task / IRN # : INSTALL ELEVATORS				

Sequence #	0010-149	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504328	Aircraft Reg #	XA-SOL	Parent WO #	2503652

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
CMT	100 Install LH Elevator for Maintenance	Installed LH elevator steps (E).1 through (F).7.(C). See working copy dated 2/24/26 REF: CL-650 AMM 27-34-01-400-801	B1018547 - Matthew Rossier Feb 25, 2026 04:56 AM B0161691 - Thomas Mitchell Feb 26, 2026 01:51 AM	27-30
CMT	101 Continue install of LH elevator steps (F).8. - close out. See working copy dated 2/24/26 REF: CL-650 AMM 27-34-01-400-801	Continued install of LH elevator Steps (F).8 - through close out, See working copy dated 2/24/26. REF: Cl-650 AMM 27-34-01-400-801	B1018547 - Matthew Rossier Feb 26, 2026 03:29 AM B0161691 - Thomas Mitchell Feb 26, 2026 04:34 AM	
CMT	200 Install RH Elevator for Maintenance	Installed RH elevator REF: CL650 AMM 27-34-01-400-801. See CMT working copy dated 2 March 2026 for work performed.	B0641903 - Felipe Mendoza Cervantes Mar 04, 2026 05:27 AM B0161691 - Thomas Mitchell Mar 04, 2026 11:27 PM	27-30
	300 Perform operational test of the elevator control system REF: CL-650 AMM 27-31-00-710-801	Performed operational test of the elevator control system. Operational test is good. REF: CL-650 AMM 27-31-00-710-801	B0641903 - Felipe Mendoza Cervantes Mar 05, 2026 12:24 AM B0161691 - Thomas Mitchell Mar 05, 2026 01:00 AM	
	400 Perform install of RH elevator outboard retainer hinge on hinge inboard side. Retainer was temporarily installed. REF: CL650 AMM 27-34-01-400-801.			
	500 Perform bond check of RH elevator.			

Sequence #	0010-149	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504328	Aircraft Reg #	XA-SOL	Parent WO #	2503652

REMOVE AND RE-INSTALL DETAILS

	Removed Part # Removed Serial #	Removed By	Removed - Part Description	Reference	Installed Part # Installed Serial #	Installed By
	Removed Status	**Removed Date-Time**	**Position**	**Installed Part Status**	**Installed Part Description**	**Installed Date-Time**
	600-24025-1013 1498	B0638589 - Sean Dodder	ELEVATOR ASSY, (LH)	CL-650 AMM 27−34−01−000−801	600-24025-1013 1498	B1018547 - Matthew Rossier
	SERVICEABLE	Feb 11, 2026 9:58 PM	LEFT	SERVICEABLE	ELEVATOR ASSY, (LH)	Feb 24, 2026 10:03 PM
	600-24025-1014 1498	B0638589 - Sean Dodder	ELEVATOR ASSY, (RH)	CL-650 AMM 27−34−01−000−801		
	SERVICEABLE	Feb 11, 2026 10:00 PM	RIGHT			

FINDINGS DETAILS

Finding #	Long Description	Status	Reported By	Defect Source	Defect Type	Priority	Follow-up WO #
			Date	**Disposition**			
82973	During install found RH elevator outboard grounding stud on the airframe side loose see attachment for location.	CLOSED	B0641903 - Felipe Mendoza Cervantes	MAINTENANCE	OTHER	3	4882286-INPRG
			Mar 3, 2026 8:57 PM	300-QA002			

TOOL INFORMATION

Tool ID	Tool Description	Calibration Due Date
TUSS2036	TORQUE WRENCH	May 30, 2026 5:00 PM
TUSS0607	BOND METER	Jan 30, 2027 5:00 PM
TUSS3536	SAFETY CABLE GUN	Sep 29, 2026 5:00 PM
TUSJ2176	Torque Wrench	Sep 29, 2026 5:00 PM
TUSS159G	Torque Wrench	Oct 30, 2026 5:00 PM

Bombardier

Sequence #	0010-150	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504334	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-150	WO #	2504334	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		No Log Entry	
Install Rudder for Maintenance				
CRITICAL MAINTENANCE TASK				
Task / IRN # : INSTALL RUDDER				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
CMT	100	Performed installation of the rudder REF: CL650 AMM 27-24-01-400-801 Bond check is good. See CMT working copy dated FEB 19 2026.	B0641903 - Felipe Mendoza Cervantes Feb 21, 2026 04:00 AM	27-20
	Install Rudder for Maintenance		B0623124 - Michael Stacy Feb 21, 2026 04:04 AM	
	200	Performed operational test of the rudder control system. REF: CL650 AMM 27-21-00-710-801. Ops test good at this time. Mo discrepancies noted at this time.	K1018275 - Emmanuel Cocoa Mar 04, 2026 08:05 PM	
	Perform operational test of the rudder control system. REF: CL650 AMM 27-21-00-710-801.		B1013522 - Brandon Jennings Mar 04, 2026 08:42 PM	
	300	Removed all tools equipment and unwanted materials.	K1018275 - Emmanuel Cocoa Mar 04, 2026 08:05 PM	
	Remove all tools equipment and unwanted materials.		B1013522 - Brandon Jennings Mar 04, 2026 08:42 PM	

REMOVE AND RE-INSTALL DETAILS

	Removed Part # / Removed Serial #	Removed By	Removed - Part Description	Reference	Installed Part # / Installed Serial #	Installed By
	Removed Status	Removed Date-Time	Position	Installed Part Status	Installed Part Description	Installed Date-Time
	604-22001-1 6111	B0650736 - Jesus Gonzalez Atondo	RUDDER ASSY, COMPLETE	Inspection	604-22001-1 6111	B0641903 - Felipe Mendoza Cervantes
	SERVICEABLE	Feb 11, 2026 9:47 AM	AFTER	SERVICEABLE	RUDDER ASSY, COMPLETE	Feb 19, 2026 8:47 PM

Sequence #	0010-150	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	2504334	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2503652

TOOL INFORMATION

Tool ID	Tool Description	Calibration Due Date
TUSJ2176	Torque Wrench	Sep 29, 2026 5:00 PM
TUSS159G	Torque Wrench	Oct 30, 2026 5:00 PM
TUSS149C	Torque Wrench	Feb 27, 2027 5:00 PM
TUSS0607	Bond Tester	Jan 30, 2027 5:00 PM

Sequence #	0010-151	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	2504336	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2503652

0010-151	**WO #**	**2504336**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		No Log Entry	
Remove Ailerons for Maintenance				
Task / IRN # : REMOVE AILERONS				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Removed LH Aileron IAW CL-650 AMM 27-15-01-000-801. See WO:2504327 for installation.	B0650736 - Jesus Gonzalez Atondo Feb 10, 2026 08:35 PM	27-10
	Remove LH Ailerons for Maintenance		Not Required	
	200	Removed RH Aileron IAW CL-650 AMM 27-15-01-000-801. See WO:2504327 for installation.	B0650736 - Jesus Gonzalez Atondo Feb 10, 2026 08:35 PM	27-10
	Remove RH Ailerons for Maintenance		Not Required	

Bombardier

Sequence #	0010-152	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504337	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-152	WO #	2504337	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		No Log Entry	
Remove Elevators for Maintenance				
Task / IRN # : REMOVE ELEVATORS				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Removed LH Elevator in reference to CL-650 AMM 27-34-01-000-801.	B0638589 - Sean Dodder Feb 12, 2026 04:54 AM	27-30
	Remove LH Elevators for Maintenance		Not Required	
	200	Began removal of RH Elevator in reference to CL-650 AMM 27-34-01-000-801, steps 1. D. (1) through (10).	B0638589 - Sean Dodder Feb 11, 2026 06:05 AM	27-30
	Remove RH Elevators for Maintenance		Not Required	
	201	Completed removal of RH Elevator in reference to CL-650 AMM 27-34-01-000-801.	B0638589 - Sean Dodder Feb 12, 2026 04:53 AM	
	Complete removal of RH Elevator for Maintenance.		Not Required	
	300	See work order 2504328 for Elevator install.	B0638589 - Sean Dodder Feb 12, 2026 04:53 AM	
	Install Elevators for maintenance.		B0623124 - Michael Stacy Feb 12, 2026 04:54 AM	
	400	Removed all tools, equipment and unwanted materials from the work area.	B0638589 - Sean Dodder Feb 12, 2026 04:53 AM	
	Remove all tools, equipment and unwanted materials from the work area.		B0623124 - Michael Stacy Feb 12, 2026 04:54 AM	

Sequence #	0010-152	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	2504337	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2503652

FINDINGS DETAILS

Finding #	Long Description	Status	Reported By / Date	Defect Source / Disposition	Defect Type	Priority	Follow-up WO #
79952	During Removal of RH Elevator, inboard bolt #1, was seized within bearing, and was extremely difficult to remove. Evaluate Elevator side of inboard hinge, and aircraft side of inboard hinge.	CLOSED	B0638589 - Sean Dodder Feb 11, 2026 9:25 PM	MAINTENANCE 300-QA002	OTHER	3	4761360-RDYLT

Bombardier

Sequence #	0010-153	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504342	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-153	WO #	2504342	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		No Log Entry	
Remove Rudder for Maintenance				
Task / IRN # : REMOVE RUDDER				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Removed the rudder IAW CL-650 AMM 27-24-01-000-801. See Finding 79866 See WO: 2504334 for installation.	B0650736 - Jesus Gonzalez Atondo Feb 11, 2026 04:46 PM	27-20
	Remove Rudder for Maintenance		Not Required	

FINDINGS DETAILS

Finding #	Long Description	Status	Reported By / Date	Defect Source / Disposition	Defect Type	Priority	Follow-up WO #
79866	Rudder middle hinges attachment hardware requires replacement, and all new rudder attachment self locking nuts.	CLOSED	B0650736 - Jesus Gonzalez Atondo Feb 11, 2026 9:26 AM	MAINTENANCE 300-QA002	OTHER	3	4761617-PSAP

Bombardier

Sequence #	0010-154	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504344	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-154	WO #	2504344	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Nose Landing Gear (NLG) Assembly	
Detailed Inspection of the Nose Landing Gear (NLG) Assembly				
Task / IRN # : 32-00-01-216				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			32-20
	Detailed Inspection of the Nose Landing Gear (NLG) Assembly			

Sequence #	0010-154	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504344	Aircraft Reg #	XA-SOL	Parent WO #	2503652

REMOVE AND RE-INSTALL DETAILS

	Removed Part # Removed Serial #	Removed By	Removed - Part Description	Reference	Installed Part # Installed Serial #	Installed By
	Removed Status	**Removed Date-Time**	**Position**	**Installed Part Status**	**Installed Part Description**	**Installed Date-Time**
	200812305 16CAM1604		BODY		200812305 23CAM4565	
	UNSERVICEABLE	Mar 4, 2026 12:35 PM	FORWARD	NEW	BODY	Mar 4, 2026 12:52 PM
	200812303 MER4435		COVER, STEERING ACTUATOR		200812201 MER8066	
	UNSERVICEABLE	Mar 4, 2026 12:50 PM	FORWARD	NEW	COVER	Mar 4, 2026 12:52 PM
	200811660 MY1550700		SPACER		200811660 MY3338060	
	UNSERVICEABLE	Mar 4, 2026 12:54 PM	FORWARD	NEW	SPACER	Mar 4, 2026 12:56 PM
	200811669 CPS1320453		SPACER		200811669 MER8419	
	UNSERVICEABLE	Mar 4, 2026 12:56 PM	FORWARD	NEW	SPACER	Mar 4, 2026 1:01 PM
	200812605 MER4422		SUPPORT, RACK		200812605 MER8419	
	UNSERVICEABLE	Mar 4, 2026 1:02 PM	FORWARD	NEW	SUPPORT, RACK	Mar 4, 2026 1:03 PM
	200811621		SLEEVE		200811621	
	UNSERVICEABLE	Mar 4, 2026 1:05 PM	FORWARD		SLEEVE	
	604-85002-41 S0000W9HC		GEAR ASSY, NOSE LANDING		604-85002-41 S0000W9HC	
	UNSERVICEABLE	Mar 4, 2026 1:43 PM	FORWARD	REPAIRED	GEAR ASSY, NOSE LANDING	Mar 4, 2026 1:46 PM

Sequence #	0010-155	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504345	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-155	WO #	2504345	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Lower Internal Skin and Fuselage Structure - FS280 to FS409	
Detailed Inspection of the Lower Internal Skin and Fuselage Structure - FS280 to FS409, as visible with the floor panels installed				
Task / IRN # : 53-20-00-206				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 53-20-00-206, Perform Detailed Inspection of the Lower Internal Skin and Fuselage Structure - FS280 to FS409, as visible with the floor panels installed, in accordance with CL-650 AMM 53-20-01-220-805. No Defects Noted.	B0642051 - Terry Walters Feb 13, 2026 03:18 PM	53-20
	Perform Detailed Inspection of the Lower Internal Skin and Fuselage Structure - FS280 to FS409, as visible with the floor panels installed		B1019908 - Joseph Barnes Feb 13, 2026 03:49 PM	
	200	Removed all Tools, Equipment, and unwanted materials from the work area.	B0642051 - Terry Walters Feb 13, 2026 03:18 PM	
	Remove all Tools, Equipment, and unwanted materials from the work area.		B1019908 - Joseph Barnes Feb 13, 2026 03:49 PM	

Bombardier

Sequence #	0010-156	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504348	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-156	WO #	2504348	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		No Log Entry	
Aircraft Jacking for Maintenance				
Task / IRN # : AIRCRAFT JACKING				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Performed Jacking of the Aircraft for Maintenance REF CL 650 AMM 07-10-01-581-801. Down-Jacking of Aircraft to Be Performed on WO: 2504351.	B1014141 - Christopher Drawdy Feb 18, 2026 05:22 PM	07-10
	Aircraft Jacking for Maintenance		B1013522 - Brandon Jennings Feb 20, 2026 05:10 PM	

Bombardier

Sequence #	0010-157	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504351	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-157	WO #	2504351	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		No Log Entry	
Down-Jack Aircraft				
Task / IRN # : DOWN-JACKING				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			07-10
	Down-Jack Aircraft			

Sequence #	0010-158	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504352	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-158	WO #	2504352	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Lightning/High Intensity Radiated Field L/HIRF Protection on the Wing Disconnects - Internal	
Detailed Inspection of the Lightning/High Intensity Radiated Field L/HIRF Protection on the Wing Disconnects - Internal				
Task / IRN # : 22-12-00-211				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with TLMC Task 22-12-00-211 Detailed Inspection of the Lightning/High Intensity Radiated Field L/HIRF Protection on the Wing Disconnects - Internal IAW CL650 AMM Task 22-12-22-220-811. No defects noted.	B0141003 - Francisco Ayon Feb 12, 2026 07:20 PM	22-10
	Perform Detailed Inspection of the Lightning/High Intensity Radiated Field L/HIRF Protection on the Wing Disconnects - Internal		B1019908 - Joseph Barnes Feb 12, 2026 07:39 PM	
	200	Removed all tools, equipment, and unwanted materials from the work area.	B0141003 - Francisco Ayon Feb 12, 2026 07:20 PM	
	Remove all tools, equipment, and unwanted materials from the work area.		B1019908 - Joseph Barnes Feb 12, 2026 07:39 PM	

Sequence #	0010-159	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	2504354	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2503652

0010-159	**WO #**	**2504354**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		Detailed inspection of the Floor Support Structure - FS280 to FS409	
Detailed inspection of the Floor Support Structure - FS280 to FS409				
Task / IRN # : 53-20-00-204				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 53-20-00-204, Perform Detailed inspection of the Floor Support Structure - FS280 to FS409, in accordance with CL-650 AMM 53-20-01-220-830. No Defects Noted.	B0642051 - Terry Walters Feb 16, 2026 08:27 PM	53-20
	Perform Detailed inspection of the Floor Support Structure - FS280 to FS409		B1019908 - Joseph Barnes Feb 16, 2026 08:54 PM	
	200	Removed all tools, equipment, and unwanted materials from the work area.	B0642051 - Terry Walters Feb 16, 2026 08:27 PM	
	Remove all tools, equipment, and unwanted materials from the work area.		B1019908 - Joseph Barnes Feb 16, 2026 08:54 PM	

Bombardier

Sequence #	0010-160	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504357	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-160	WO #	2504357	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Internal Forward Keel Beam - FS364 to FS394	
Detailed Inspection of the Internal Forward Keel Beam - FS364 to FS394				
Task / IRN # : 53-20-00-210				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 53-20-00-210 Detailed Inspection of the Internal Forward Keel Beam - FS364 to FS394 REF CL650 AMM 53-20-01-220-808. No defects noted at this time	B0648431 - Caleb Sexton Feb 16, 2026 02:27 PM	53-20
	Perform Detailed Inspection of the Internal Forward Keel Beam - FS364 to FS394		B1019908 - Joseph Barnes Feb 16, 2026 02:51 PM	
	200	Removed all tools, equipment, and unwanted materials from the work area	B0648431 - Caleb Sexton Feb 16, 2026 02:27 PM	
	Remove all tools, equipment, and unwanted materials from the work area		B1019908 - Joseph Barnes Feb 16, 2026 02:51 PM	

Sequence #	0010-161	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504358	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-161	WO #	2504358	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Sills, Frames and External Skin around the Emergency-Exit Door Cutout	
Detailed Inspection of the Sills, Frames and External Skin around the Emergency-Exit Door Cutout				
Task / IRN # : 53-20-00-217				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 53-20-00-217, Performed Detailed Inspection of the Sills, Frames and External Skin around the Emergency-Exit Door Cutout, in accordance with Cl 650 AMM 53-20-01-220-815. No defects noted	B1017798 - Hunter Van Der Heide Feb 14, 2026 04:37 AM	53-20
	Perform Detailed Inspection of the Sills, Frames and External Skin around the Emergency-Exit Door Cutout		B0161691 - Thomas Mitchell Feb 14, 2026 04:59 AM	
	200	Removed all tools, equipment, and unwanted materials from the area.	B1017798 - Hunter Van Der Heide Feb 14, 2026 04:37 AM	
	Remove all tools, equipment, and unwanted materials from the area.		B0161691 - Thomas Mitchell Feb 14, 2026 04:59 AM	

Sequence #	0010-162	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504361	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-162	WO #	2504361	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Frame below the Floor - FS513	
Detailed Inspection of the Frame below the Floor - FS513				
Task / IRN # : 53-20-00-223				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 53-20-00-223, Perform Detailed Inspection of the Frame below the Floor - FS513, in accordance with CL-650 AMM 53-20-01-220-821. No Defects Noted.	B0642051 - Terry Walters Feb 13, 2026 01:46 PM	53-20
	Perform Detailed Inspection of the Frame below the Floor - FS513		B0142244 - Todd Bridges Feb 13, 2026 02:15 PM	
	101	Complied with task 53-20-00-223, Perform Detailed Inspection of the Frame below the Floor - FS513, in accordance with CL-650 AMM 53-20-01-220-821. No Defects Noted.	B0642051 - Terry Walters Feb 13, 2026 02:23 PM	
	Perform Detailed Inspection of the Frame below the Floor - FS513		B0142244 - Todd Bridges Feb 13, 2026 03:07 PM	09
	200	Remove all Tools, equipment, and unwanted materials from the work area.	B0642051 - Terry Walters Feb 13, 2026 02:23 PM	
	Remove all Tools, equipment, and unwanted materials from the work area.		B0142244 - Todd Bridges Feb 13, 2026 03:07 PM	

Bombardier

Sequence #	0010-163	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504363	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-163	WO #	2504363	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Forward Keel Beam Pressure Box and Keel Beam Lugs and Links - FS394 to FS409	
Detailed Inspection of the Forward Keel Beam Pressure Box and Keel Beam Lugs and Links - FS394 to FS409				
Task / IRN # : 53-20-00-211				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 53-20-00-211, Perform Detailed Inspection of the Forward Keel Beam Pressure Box and Keel Beam Lugs and Links - FS394 to FS409, in accordance with 650 MM 53-20-01-220-809.	B0142041 - Timothy Winfree Feb 15, 2026 01:17 PM	53-20
	Perform Detailed Inspection of the Forward Keel Beam Pressure Box and Keel Beam Lugs and Links - FS394 to FS409		B1013522 - Brandon Jennings Feb 17, 2026 04:49 PM	
	101	Complied with task 53-20-00-211, Perform Detailed Inspection of the Forward Keel Beam Pressure Box and Keel Beam Lugs and Links - FS394 to FS409, in accordance with CL-650 AMM 53-20-01-220-809. No Defects Noted	B0642051 - Terry Walters Feb 17, 2026 04:38 PM	
	Corrected inspection results		B1013522 - Brandon Jennings Feb 17, 2026 04:49 PM	
	200	Removed all tools, equipment, and unwanted materials from the work area	B0142041 - Timothy Winfree Feb 15, 2026 04:47 PM	
	Remove all tools, equipment, and unwanted materials from the work area.		B1013522 - Brandon Jennings Feb 17, 2026 04:49 PM	

Bombardier

Sequence #	0010-164	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504364	Aircraft Reg #	XA-SOL	Parent WO #	2503652

0010-164	WO #	2504364	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Wing-to-Fuselage Attachment Lug - FS473.15	
Detailed Inspection of the Wing-to-Fuselage Attachment Lug - FS473.15				
Task / IRN # : 53-20-00-222				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with TLMC task 53-20-00-222 Performed LH detailed inspection of the wing to body fuselage attachment lug (FS473.15) REF CL-650 AMM 53-20-01-220-820. No defects noted.	B1002512 - Brandon Warne Feb 12, 2026 08:02 PM	53-20
	Perform LH Detailed Inspection of the Wing-to-Fuselage Attachment Lug - FS47315		B1013522 - Brandon Jennings Feb 12, 2026 08:12 PM	
	200	Complied with TLMC task 53-20-00-222 Performed RH detailed inspection of the wing to body fuselage attachment lug (FS473.15) REF CL-650 AMM 53-20-01-220-820. No defects noted.	B1002512 - Brandon Warne Feb 12, 2026 08:02 PM	53-20
	Perform RH Detailed Inspection of the Wing-to-Fuselage Attachment Lug - FS47315		B1013522 - Brandon Jennings Feb 12, 2026 08:12 PM	
	300	Removed all tools, equipment and materials from the work area.	B1002512 - Brandon Warne Feb 12, 2026 08:02 PM	
	Remove all tools, equipment and materials from the work area.		B1013522 - Brandon Jennings Feb 12, 2026 08:12 PM	

Sequence #	0011	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	2498788	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

0011	**WO #**	**2498788**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #	13276311	Landing gear - 96 Month inspection (ICT) (604/605/650) (North America)	
Landing gear - 96 Month inspection (ICT) (604/605/650) (North America)				
Task / IRN # : 32-00-01-215 , 32-00-01-216				

Sequence #	0012	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	2503651	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

0012	**WO #**	**2503651**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #	13276310	600 Hr airframe inspection	
600 Hr airframe inspection				
Task / IRN # : C3500058				

Sequence #	0012	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503651	Aircraft Reg #	XA-SOL	Parent WO #	2498069

CHILD WORK ORDER DETAILS

	WO #	Description	Corrective Action	AMENDED
0012-1	2503938	Operational test of the Pressurization Control System (Manual mode)	C/W Task 21-30-00-230, Performed Operational test of the Pressurization Control System (Manual mode) IAW CL650 AMM 21-31-00-710-802 No Defects Noted.	
0012-2	2503942	Operational test of the Transformer Rectifier Unit (TRU) fan	Complied with TLMC Task 24-30-00-201, Operational test of the Transformer Rectifier Unit (TRU) fan. REF CL-650 AMM 24-31-01-710-802. Op Test Good.	
0012-3	2503943	General Visual Inspection of the Saddle Tank Drain	Complied with Task No. 28-10-00-205. Performed a GVI of the Saddle Tank Drain. No leaks, no defects noted. Ref: CL650 AMM 28-13-10-210-801	
0012-4	2503945	Visual check of the Vent and Distribution Shroud Drains for Blockage and Leakage	Complied with Task 28-10-00-213. Performed Visual check of the Vent and Distribution Shroud Drains for Blockage and Leakage, in reference to CL-650 AMM 28-00-00-210-801. No defects were noted at this time.	
0012-5	2503948	Visual check of the Filter Differential-Pressure Indicator	Complied with Task 29-10-00-201. Performed Visual check of the Filter Differential-Pressure Indicators, on all 3 hydraulic systems, in reference to CL-650 AMM 29-10-00-210-801. No defects were noted at this time.	
0012-6	2503949	Operational test of the Cowl Anti-Ice Failure Indication	Complied with Task 30-22-00-101. Performed Operational test of the Cowl Anti-Ice Failure Indication, in reference to CL-650 AMM 30-22-00-710-801. No defects were noted at this time.	
0012-7	2503952	Functional Test of the Windshield Rain Repellent Layer. NOTE: This task applies to Sully Glass Faceply Windshields, Part No. 270-462-00-XX and Sierracin Glass Faceply Windshields, Part No. 158700-57 and Subs.	Complied with TLMC task 30-40-00-201 Performed functional test of the windshield rain repellent layer REF CL-650 AMM 30-40-00-720-801. Functional test good.	
0012-8	2503955	Operational Test of the Audio Warning Control Panel	Complied with TLMC Task 31-41-00-202, Operational Test of the Audio Warning Control Panel. REF CL-650 AMM 31-51-01-710-801. Op Test Good.	
0012-9	2503956	General Visual Inspection of the Nose Landing Gear (NLG) Assembly	Complied with TLMC 32-00-01-214. Performed a General Visual Inspection of the Nose Landing Gear (NLG) Assembly Ref. CL-650 AMM 32-21-01-210-801. See Finding # 78883 for defects found.	

Sequence #	0012	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503651	Aircraft Reg #	XA-SOL	Parent WO #	2498069

CHILD WORK ORDER DETAILS

	WO #	Description	Corrective Action	AMENDED
0012-10	2503959	General Visual Inspection of the Fuel Access Panels	Complied with Task No. 28-10-00-201. Performed a GVI of both the LH and RH Wing Fuel Access Panels. No leaks, no defects noted. Ref: CL650 AMM 28-11-01-210-801	
0012-11	2503962	General Visual Inspection of the Water Drain Valves	Complied with Task No. 28-10-00-203. Performed a GVI of both the LH and RH Water Drain Valves. No leaks, no defects noted. Ref: CL650 AMM 28-11-04-210-801.	
0012-12	2503963	General Visual Inspection of the Fuel Drain Valves	Complied with Task No.28-10-00-202. Performed a GVI of both the LH and RH Wing Fuel Drain Lines. No leaks, no defects noted. Ref: CL650 AMM 28-11-07-210-801	
0012-13	2503968	General Visual Inspection of the Fuel Tank Exterior	Complied with Task No. 28-10-00-204. Performed a GVI of both the LH and RH Fuel Tank Exterior. No leaks, no defects noted. Ref: CL650 AMM 28-10-00-210.	
0012-14	2503971	General Visual Inspection of the Gravity Filler Cap	Complied with TLMC 28-10-00-206. Performed LH & RH General Visual Inspection of the Gravity Filler Cap Ref. CL-650 AMM 28-10-00-210-802. No defects noted.	
0012-15	2503972	General Visual Inspection of the Main Landing Gear (MLG) Assembly	Complied with TLMC 32-00-01-213. Performed a General Visual Inspection of the LH & RH Main Landing Gear (MLG) Assembly Ref. CL-650 AMM 32-11-00-210-801. See Findings 78993 & 78994 for defects found.	
0012-16	2503977	Detailed Inspection of the Brake Wear Pins	Complied with TLMC 32-40-00-205. Performed a Detailed Inspection of the LH & RH MLG Brake Wear Pins Ref. CL-650 AMM 32-43-19-220-801. No defects noted. LH OTBD Brake Pin Measurement: 0.276 (33% brake remaining) LH INBD Brake Pin Measurement: 0.2375 (28% brake remaining) RH OTBD Brake Pin Measurement: 0.2485 (29% brake remaining) RH INBD Brake Pin Measurement: 0.3245 (39% brake remaining)	
0012-17	2503980	General Visual Inspection of the Drains Mast and Channels	Complied with Task 71-12-00-203. Performed General Visual Inspection of the LH and RH Drains Mast and Channels, in reference to CL-650 AMM 71-12-01-210-804. No defects were noted at this time.	

Sequence #	0012	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503651	Aircraft Reg #	XA-SOL	Parent WO #	2498069

CHILD WORK ORDER DETAILS

	WO #	Description	Corrective Action	AMENDED
0012-18	2503981	Operational Test of the Drains Mast and Channels	Complied with Task 71-12-00-204. Performed Operational Test of the LH and RH Drains Mast and Channels, in reference to CL-650 AMM 71-12-01-710-801. No defects were noted at this time.	
0012-19	2503984	Detailed Inspection of the Drain-Plug Magnetic Chip-Detector	Complied with Task Card 80-11-00-202. Perform LH and RH Detailed Inspection of the Drain-Plug Magnetic Chip-Detector. REF. CL650 AMM 80-11-01-220-801. No discrepancies noted at this time.	
0012-20	2503986	Discard of the Air Turbine Starter (ATS) oil		
0012-21	2503988	Operational Test of the Hydraulic Firewall Shutoff-Valve. Part Numbers B97-19-452/-453/-454/-454A Part Number B97-19-455 and Subs	Deferral Code: Do Not Work Reason: Customer Request Details: Not on customer due list, per CAMP 1600 H	
0012-22	2503992	Operational Test of the Engine-Firewall Fuel Shutoff-Valve	Complied with TLMC task 28-21-13-201 Performed operational test of the Engine-Firewall Fuel Shutoff-Valve REF CL-650 AMM 28-21-13-710-801. Operational test good.	

Sequence #	0012-1	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503938	Aircraft Reg #	XA-SOL	Parent WO #	2503651

0012-1	WO #	2503938	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Operational test of the Pressurization Control System (Manual mode)	
Operational test of the Pressurization Control System (Manual mode)				
Task / IRN # : 21-30-00-203				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	C/W Task 21-30-00-230, Performed Operational test of the Pressurization Control System (Manual mode) IAW CL650 AMM 21-31-00-710-802 No Defects Noted.	B0642374 - Joren Ayer Feb 03, 2026 03:52 PM	21-30
	Perform Operational test of the Pressurization Control System (Manual mode)		B1013522 - Brandon Jennings Feb 03, 2026 04:02 PM	
	101	C/W Task 21-31-00-201, Performed Operational test of the Pressurization Control System (Manual mode) IAW CL650 AMM 21-31-00-710-802 No Defects Noted.	B0642374 - Joren Ayer Feb 03, 2026 04:09 PM	
	Perform Operational test of the Pressurization Control System (Manual mode)		B1013522 - Brandon Jennings Feb 03, 2026 04:10 PM	09
	200	Removed all tools, equipment, and unwanted materials from the work area.	B0642374 - Joren Ayer Feb 03, 2026 03:53 PM	
	Remove all tools, equipment, and unwanted materials from the work area.		B1013522 - Brandon Jennings Feb 03, 2026 04:02 PM	

Sequence #	0012-2	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503942	Aircraft Reg #	XA-SOL	Parent WO #	2503651

0012-2	WO #	2503942	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Operational test of the Transformer Rectifier Unit (TRU) fan	
Operational test of the Transformer Rectifier Unit (TRU) fan				
Task / IRN # : 24-30-00-201				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with TLMC Task 24-30-00-201, Operational test of the Transformer Rectifier Unit (TRU) fan. REF CL-650 AMM 24-31-01-710-802. Op Test Good.	B0143855 - Marlon Zurita Feb 04, 2026 04:17 PM	24-30
	Perform Operational test of the Transformer Rectifier Unit (TRU) fan		B0143196 - Robert Bohner Feb 04, 2026 04:49 PM	
	200	Complied with removal of all tools, equipment, and unwanted materials from the work area	B0641378 - Calvin Ambrose Feb 04, 2026 03:34 PM	
	Comply with removal of all tools, equipment, and unwanted materials from the work area		B0143196 - Robert Bohner Feb 04, 2026 04:49 PM	

Sequence #	0012-3	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503943	Aircraft Reg #	XA-SOL	Parent WO #	2503651

0012-3	WO #	2503943	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Saddle Tank Drain	
General Visual Inspection of the Saddle Tank Drain				
Task / IRN # : 28-10-00-205				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with Task No. 28-10-00-205. Performed a GVI of the Saddle Tank Drain. No leaks, no defects noted. Ref: CL650 AMM 28-13-10-210-801	B0646266 - Sergio Rodriguez Figueroa Feb 05, 2026 05:17 PM	28-10
	Perform General Visual Inspection of the Saddle Tank Drain		B0143196 - Robert Bohner Feb 05, 2026 05:23 PM	
	200	Removed all tools, equipment, and unwanted materials from the work area as required.	B0646266 - Sergio Rodriguez Figueroa Feb 05, 2026 05:17 PM	
	Remove all tools, equipment, and unwanted material from the work area.		B0143196 - Robert Bohner Feb 05, 2026 05:23 PM	

Bombardier

Sequence #	0012-4	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503945	Aircraft Reg #	XA-SOL	Parent WO #	2503651

0012-4	WO #	2503945	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Visual check of the Vent and Distribution Shroud Drains for Blockage and Leakage	
Visual check of the Vent and Distribution Shroud Drains for Blockage and Leakage				
Task / IRN # : 28-10-00-213				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with Task 28-10-00-213. Performed Visual check of the Vent and Distribution Shroud Drains for Blockage and Leakage, in reference to CL-650 AMM 28-00-00-210-801. No defects were noted at this time.	B0638589 - Sean Dodder Feb 07, 2026 01:55 AM	28-00
	Perform Visual check of the Vent and Distribution Shroud Drains for Blockage and Leakage		B0623124 - Michael Stacy Feb 07, 2026 01:58 AM	
	200	Removed all tools, equipment, and unwanted materials from the work area.	B0638589 - Sean Dodder Feb 07, 2026 01:55 AM	
	Remove all tools, equipment, and unwanted materials from the work area.		B0623124 - Michael Stacy Feb 07, 2026 01:58 AM	

Sequence #	0012-5	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	2503948	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2503651

0012-5	**WO #**	**2503948**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		Visual check of the Filter Differential-Pressure Indicator	
Visual check of the Filter Differential-Pressure Indicator				
Task / IRN # : 29-10-00-201				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with Task 29-10-00-201. Performed Visual check of the Filter Differential-Pressure Indicators, on all 3 hydraulic systems, in reference to CL-650 AMM 29-10-00-210-801. No defects were noted at this time.	B0638589 - Sean Dodder Feb 06, 2026 11:19 PM	29-10
	Perform Visual check of the Filter Differential-Pressure Indicator		B0142244 - Todd Bridges Feb 06, 2026 11:38 PM	
	200	Removed all tools, equipment, and unwanted materials from the work area.	B0638589 - Sean Dodder Feb 06, 2026 11:19 PM	
	Remove all tools, equipment, and unwanted materials from the work area.		B0142244 - Todd Bridges Feb 06, 2026 11:38 PM	

Bombardier

Sequence #	0012-6	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503949	Aircraft Reg #	XA-SOL	Parent WO #	2503651

0012-6	WO #	2503949	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Operational test of the Cowl Anti-Ice Failure Indication	
Operational test of the Cowl Anti-Ice Failure Indication				
Task / IRN # : 30-22-00-101				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with Task 30-22-00-101. Performed Operational test of the Cowl Anti-Ice Failure Indication, in reference to CL-650 AMM 30-22-00-710-801. No defects were noted at this time.	B0638589 - Sean Dodder Feb 06, 2026 04:33 AM	30-20
	Perform Operational test of the Cowl Anti-Ice Failure Indication		B0623124 - Michael Stacy Feb 06, 2026 04:42 AM	
	200	Removed all tools, equipment, and unwanted materials from the work area.	B0638589 - Sean Dodder Feb 06, 2026 04:33 AM	
	Remove all tools, equipment, and unwanted materials from the work area.		B0623124 - Michael Stacy Feb 06, 2026 04:42 AM	

Sequence #	0012-7	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503952	Aircraft Reg #	XA-SOL	Parent WO #	2503651

0012-7	WO #	2503952	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Functional Test of the Windshield Rain Repellent Layer. NOTE: This task applies to Sully Glass Faceply Windshields, Part No. 270-462-00-XX and Sierracin Glass Faceply Windshields, Part No. 158700-57 and Subs.	
Functional Test of the Windshield Rain Repellent Layer. NOTE: This task applies to Sully Glass Faceply Windshields, Part No. 270-462-00-XX and Sierracin Glass Faceply Windshields, Part No. 158700-57 and Subs.				
Task / IRN # : 30-40-00-201				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with TLMC task 30-40-00-201 Performed functional test of the windshield rain repellent layer REF CL-650 AMM 30-40-00-720-801. Functional test good.	B1002512 - Brandon Warne Feb 04, 2026 07:25 PM	34-40
	Perform Functional Test of the Windshield Rain Repellent Layer		B0143196 - Robert Bohner Feb 04, 2026 07:37 PM	
	200	Removed all tools, equipment and materials from the work area.	B1002512 - Brandon Warne Feb 04, 2026 07:25 PM	
	Remove all tools, equipment and materials from the work area.		B0143196 - Robert Bohner Feb 04, 2026 07:37 PM	

Sequence #	0012-8	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503955	Aircraft Reg #	XA-SOL	Parent WO #	2503651

0012-8	WO #	2503955	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Operational Test of the Audio Warning Control Panel	
Operational Test of the Audio Warning Control Panel				
Task / IRN # : 31-41-00-202				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with TLMC Task 31-41-00-202, Operational Test of the Audio Warning Control Panel. REF CL-650 AMM 31-51-01-710-801. Op Test Good.	B0143855 - Marlon Zurita Feb 04, 2026 04:26 PM	31-50
	Perform Operational Test of the Audio Warning Control Panel		B0143196 - Robert Bohner Feb 04, 2026 04:56 PM	
	200	Complied with removal of all tools, equipment, and unwanted materials from the work area	B0641378 - Calvin Ambrose Feb 04, 2026 04:05 PM	
	Comply with removal of all tools, equipment, and unwanted materials from the work area		B0143196 - Robert Bohner Feb 04, 2026 04:56 PM	

Sequence #	0012-9	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503956	Aircraft Reg #	XA-SOL	Parent WO #	2503651

0012-9	WO #	2503956	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Nose Landing Gear (NLG) Assembly	
General Visual Inspection of the Nose Landing Gear (NLG) Assembly				
Task / IRN # : 32-00-01-214				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with TLMC 32-00-01-214. Performed a General Visual Inspection of the Nose Landing Gear (NLG) Assembly Ref. CL-650 AMM 32-21-01-210-801. See Finding # 78883 for defects found.	B0613291 - Eric Strong Feb 04, 2026 08:57 PM	32-20
	Perform General Visual Inspection of the Nose Landing Gear (NLG) Assembly		B1013522 - Brandon Jennings Feb 04, 2026 09:09 PM	
	200	Removed all tools, equipment, and unwanted materials from the work area.	B0613291 - Eric Strong Feb 04, 2026 08:57 PM	
	Remove all tools, equipment, and unwanted materials from the work area.		B1013522 - Brandon Jennings Feb 04, 2026 09:09 PM	

FINDINGS DETAILS

Finding #	Long Description	Status	Reported By / Date	Defect Source / Disposition	Defect Type	Priority	Follow-up WO #
78883	NLG shock strut has multiple areas of chipped paint on the axle assembly and the torque links	CLOSED	B0613291 - Eric Strong Feb 4, 2026 1:51 PM	MAINTENANCE 300-QA002	OTHER	3	4715572-APPR

Sequence #	0012-10	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503959	Aircraft Reg #	XA-SOL	Parent WO #	2503651

0012-10	WO #	2503959	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Fuel Access Panels	
General Visual Inspection of the Fuel Access Panels				
Task / IRN # : 28-10-00-201				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with Task No. 28-10-00-201. Performed a GVI of the LH Wing Fuel Access Panels. No leaks, no defects noted. Ref: CL650 AMM 28-11-01-210-801	B0646266 - Sergio Rodriguez Figueroa Feb 03, 2026 03:38 PM	28-10
	Perform LH General Visual Inspection of the Fuel Access Panels		B1013522 - Brandon Jennings Feb 03, 2026 04:26 PM	
	200	Complied with Task No. 28-10-00-201. Performed a GVI of the RH Wing Fuel Access Panels. No leaks, no defects noted. Ref: CL650 AMM 28-11-01-210-801	B0646266 - Sergio Rodriguez Figueroa Feb 03, 2026 03:38 PM	28-10
	Perform RH General Visual Inspection of the Fuel Access Panels		B1013522 - Brandon Jennings Feb 03, 2026 04:26 PM	
	300	Removed all tools, equipment, and unwanted materials from work area as required.	B0646266 - Sergio Rodriguez Figueroa Feb 03, 2026 04:29 PM	
	Remove all tools equipment and unwanted material from work area		B1013522 - Brandon Jennings Feb 03, 2026 04:31 PM	

Sequence #	0012-11	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503962	Aircraft Reg #	XA-SOL	Parent WO #	2503651

0012-11	WO #	2503962	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Water Drain Valves	
General Visual Inspection of the Water Drain Valves				
Task / IRN # : 28-10-00-203				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with Task No. 28-10-00-203. Performed a GVI of the LH Water Drain Valves. No leaks, no defects noted. Ref: CL650 AMM 28-11-04-210-801.	B0646266 - Sergio Rodriguez Figueroa Feb 03, 2026 05:49 PM	28-10
	Perform LH General Visual Inspection of the Water Drain Valves		B1013522 - Brandon Jennings Feb 03, 2026 07:07 PM	
	200	Complied with Task No. 28-10-00-203. Performed a GVI of the RH Water Drain Valves. No leaks, no defects noted. Ref: CL650 AMM 28-11-04-210-801.	B0646266 - Sergio Rodriguez Figueroa Feb 03, 2026 05:49 PM	28-10
	Perform RH General Visual Inspection of the Water Drain Valves		B1013522 - Brandon Jennings Feb 03, 2026 07:07 PM	
	300	Removed all tools, equipment, and unwanted materials from the work area as required.	B0646266 - Sergio Rodriguez Figueroa Feb 03, 2026 05:53 PM	
	Remove all tools, equipment, and unwanted material from the work area.		B1013522 - Brandon Jennings Feb 03, 2026 07:07 PM	

Sequence #	0012-12	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503963	Aircraft Reg #	XA-SOL	Parent WO #	2503651

0012-12	WO #	2503963	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Fuel Drain Valves	
General Visual Inspection of the Fuel Drain Valves				
Task / IRN # : 28-10-00-202				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with Task No.28-10-00-202. Performed a GVI of the LH Wing Fuel Drain Lines. No leaks, no defects noted. Ref: CL650 AMM 28-11-07-210-801	B0646266 - Sergio Rodriguez Figueroa Feb 03, 2026 09:07 PM	28-10
	Perform LH General Visual Inspection of the Fuel Drain Valves		B1013522 - Brandon Jennings Feb 03, 2026 09:13 PM	
	200	Complied with Task No.28-10-00-202. Performed a GVI of the LH Wing Fuel Drain Lines. No leaks, no defects noted. Ref: CL650 AMM 28-11-07-210-801	B0646266 - Sergio Rodriguez Figueroa Feb 03, 2026 09:07 PM	28-10
	Perform RH General Visual Inspection of the Fuel Drain Valves		B1013522 - Brandon Jennings Feb 03, 2026 09:13 PM	
	201	Complied with Task No.28-10-00-202. Performed a GVI of the RH Wing Fuel Drain Lines. No leaks, no defects noted. Ref: CL650 AMM 28-11-07-210-801	B0646266 - Sergio Rodriguez Figueroa Feb 03, 2026 09:22 PM	
	Perform RH General Visual Inspection of the Fuel Drain Valves		B1013522 - Brandon Jennings Feb 04, 2026 07:58 PM	09
	300	Removed all tools, equipment, and unwanted materials from the work area as required.	B0646266 - Sergio Rodriguez Figueroa Feb 03, 2026 09:07 PM	
	Remove all tools, equipment, and unwanted material from the work area.		B1013522 - Brandon Jennings Feb 03, 2026 09:13 PM	

Sequence #	0012-13	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503968	Aircraft Reg #	XA-SOL	Parent WO #	2503651

0012-13	WO #	2503968	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Fuel Tank Exterior	
General Visual Inspection of the Fuel Tank Exterior				
Task / IRN # : 28-10-00-204				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with Task No. 28-10-00-204. Performed a GVI of the LH Fuel Tank Exterior. No leaks, no defects noted. Ref: CL650 AMM 28-10-00-210.	B0646266 - Sergio Rodriguez Figueroa Feb 05, 2026 04:17 PM	28-10
	Perform LH General Visual Inspection of the Fuel Tank Exterior		B0143196 - Robert Bohner Feb 05, 2026 04:25 PM	
	101	Complied with Task No. 28-10-00-204. Performed a GVI of the LH Fuel Tank Exterior. No leaks, no defects noted. Ref: CL650 AMM 28-10-00-210-801	B0646266 - Sergio Rodriguez Figueroa Feb 05, 2026 04:53 PM	
	Perform LH General Visual Inspection of the Fuel Tank Exterior		B1013522 - Brandon Jennings Feb 05, 2026 05:18 PM	09
	200	Complied with Task No. 28-10-00-204. Performed a GVI of the RH Fuel Tank Exterior. No leaks, no defects noted. Ref: CL650 AMM 28-10-00-210.	B0646266 - Sergio Rodriguez Figueroa Feb 05, 2026 04:17 PM	28-10
	Perform RH General Visual Inspection of the Fuel Tank Exterior		B0143196 - Robert Bohner Feb 05, 2026 04:25 PM	
	201	Complied with Task No. 28-10-00-204. Performed a GVI of the RH Fuel Tank Exterior. No leaks, no defects noted. Ref: CL650 AMM 28-10-00-210-801	B0646266 - Sergio Rodriguez Figueroa Feb 05, 2026 04:53 PM	
	Perform RH General Visual Inspection of the Fuel Tank Exterior		B1013522 - Brandon Jennings Feb 05, 2026 05:18 PM	09
	300	Removed all tools, equipment, and unwanted materials from the work area as required.	B0646266 - Sergio Rodriguez Figueroa Feb 05, 2026 04:17 PM	
	Remove all tools, equipment, and unwanted material from the work area.		B0143196 - Robert Bohner Feb 05, 2026 04:25 PM	

Sequence #	0012-14	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503971	Aircraft Reg #	XA-SOL	Parent WO #	2503651

0012-14	WO #	2503971	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Gravity Filler Cap	
General Visual Inspection of the Gravity Filler Cap				
Task / IRN # : 28-10-00-206				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with TLMC 28-10-00-206. Performed LH General Visual Inspection of the Gravity Filler Cap Ref. CL-650 AMM 28-10-00-210-802. No defects noted.	B0613291 - Eric Strong Feb 04, 2026 08:13 PM	28-10
	Perform LH General Visual Inspection of the Gravity Filler Cap		B1013522 - Brandon Jennings Feb 04, 2026 08:27 PM	
	200	Complied with TLMC 28-10-00-206. Performed RH General Visual Inspection of the Gravity Filler Cap Ref. CL-650 AMM 28-10-00-210-802. No defects noted.	B0613291 - Eric Strong Feb 04, 2026 08:13 PM	28-10
	Perform RH General Visual Inspection of the Gravity Filler Cap		B1013522 - Brandon Jennings Feb 04, 2026 08:27 PM	
	300	Opened access cover 640AT Ref. CL-650 AMM 28-10-00-210-802	B0613291 - Eric Strong Feb 04, 2026 08:13 PM	
	Open the access cover 640AT to access the center-tank gravity filler cap Ref. CL-650 AMM 28-10-00-210-802		B1013522 - Brandon Jennings Feb 04, 2026 08:27 PM	
	400	Closed the access cover 640AT Ref. CL-650 AMM 28-10-00-210-802	B0613291 - Eric Strong Feb 04, 2026 08:13 PM	
	Close the access cover 640AT Ref. CL-650 AMM 28-10-00-210-802		B1013522 - Brandon Jennings Feb 04, 2026 08:27 PM	
	500	Removed all tools, equipment, and unwanted materials from the work area.	B0613291 - Eric Strong Feb 04, 2026 08:13 PM	
	Remove all tools, equipment, and unwanted materials from the work area.		B1013522 - Brandon Jennings Feb 04, 2026 08:27 PM	

Bombardier

Sequence #	0012-15	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503972	Aircraft Reg #	XA-SOL	Parent WO #	2503651

0012-15	WO #	2503972	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Main Landing Gear (MLG) Assembly	
General Visual Inspection of the Main Landing Gear (MLG) Assembly				
Task / IRN # : 32-00-01-213				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with TLMC 32-00-01-213. Performed a General Visual Inspection of the LH Main Landing Gear (MLG) Assembly Ref. CL-650 AMM 32-11-00-210-801. See Finding 78994 for defects found.	B0613291 - Eric Strong Feb 05, 2026 03:38 PM	32-10
	Perform LH General Visual Inspection of the Main Landing Gear (MLG) Assembly		B1013522 - Brandon Jennings Feb 05, 2026 03:57 PM	
	200	Complied with TLMC 32-00-01-213. Performed a General Visual Inspection of the RH Main Landing Gear (MLG) Assembly Ref. CL-650 AMM 32-11-00-210-801. See Finding 78993 for defects found.	B0613291 - Eric Strong Feb 05, 2026 03:38 PM	32-10
	Perform RH General Visual Inspection of the Main Landing Gear (MLG) Assembly		B1013522 - Brandon Jennings Feb 05, 2026 03:57 PM	
	300	Removed all tools, equipment, and unwanted materials from the work area.	B0613291 - Eric Strong Feb 05, 2026 03:38 PM	
	Remove all tools, equipment, and unwanted materials from the work area.		B1013522 - Brandon Jennings Feb 05, 2026 03:57 PM	

FINDINGS DETAILS

Finding #	Long Description	Status	Reported By / Date	Defect Source / Disposition	Defect Type	Priority	Follow-up WO #
78993	RH MLG strut assembly has 2 EA electrical harnesses that are kinked near both brake assemblies (flagged)	CLOSED	B0613291 - Eric Strong Feb 5, 2026 8:24 AM	MAINTENANCE 300-QA002	OTHER	3	4761494-APPR
78994	Hydraulic line routed above LH MLG strut assembly suspected to be leaking (flagged)	CLOSED	B0613291 - Eric Strong Feb 5, 2026 8:28 AM	MAINTENANCE 300-QA002	OTHER	3	4749000-PSAP

Bombardier

Sequence #	0012-16	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503977	Aircraft Reg #	XA-SOL	Parent WO #	2503651

0012-16	WO #	2503977	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Brake Wear Pins	
Detailed Inspection of the Brake Wear Pins				
Task / IRN # : 32-40-00-205				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with TLMC 32-40-00-205. Performed a Detailed Inspection of the LH MLG Brake Wear Pins Ref. CL-650 AMM 32-43-19-220-801. No defects noted. LH OTBD Brake Pin Measurement: 0.276 (33% brake remaining) LH INBD Brake Pin Measurement: 0.2375 (28% brake remaining)	B0613291 - Eric Strong Feb 05, 2026 05:39 PM	32-40
	Perform LH Detailed Inspection of the Brake Wear Pins		B0143196 - Robert Bohner Feb 05, 2026 07:18 PM	
	200	Complied with TLMC 32-40-00-205. Performed a Detailed Inspection of the RH MLG Brake Wear Pins Ref. CL-650 AMM 32-43-19-220-801. No defects noted. RH OTBD Brake Pin Measurement: 0.2485 (29% brake remaining) RH INBD Brake Pin Measurement: 0.3245 (39% brake remaining)	B0613291 - Eric Strong Feb 05, 2026 05:39 PM	32-40
	Perform RH Detailed Inspection of the Brake Wear Pins		B0143196 - Robert Bohner Feb 05, 2026 07:18 PM	
	300	Removed all tools, equipment, and unwanted materials from the work area.	B0613291 - Eric Strong Feb 05, 2026 05:39 PM	
	Remove all tools, equipment, and unwanted materials from the work area.		B0143196 - Robert Bohner Feb 05, 2026 07:18 PM	

Sequence #	0012-17	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503980	Aircraft Reg #	XA-SOL	Parent WO #	2503651

0012-17	WO #	2503980	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Drains Mast and Channels	
General Visual Inspection of the Drains Mast and Channels				
Task / IRN # : 71-12-00-203				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with Task 71-12-00-203. Performed General Visual Inspection of the LH and RH Drains Mast and Channels, in reference to CL-650 AMM 71-12-01-210-804. No defects were noted at this time.	B0638589 - Sean Dodder Feb 06, 2026 11:44 PM	71-10
	Perform General Visual Inspection of the Drains Mast and Channels		B0623124 - Michael Stacy Feb 06, 2026 11:57 PM	
	200	Removed all tools, equipment, and unwanted materials from the work area.	B0638589 - Sean Dodder Feb 06, 2026 11:44 PM	
	Remove all tools, equipment, and unwanted materials from the work area.		B0623124 - Michael Stacy Feb 06, 2026 11:57 PM	

Sequence #	0012-18	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	2503981	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2503651

0012-18	**WO #**	**2503981**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		Operational Test of the Drains Mast and Channels	
Operational Test of the Drains Mast and Channels				
Task / IRN # : 71-12-00-204				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with Task 71-12-00-204. Performed Operational Test of the LH and RH Drains Mast and Channels, in reference to CL-650 AMM 71-12-01-710-801. No defects were noted at this time.	B0638589 - Sean Dodder Feb 06, 2026 10:24 PM	71-10
	Perform Operational Test of the Drains Mast and Channels		B0623124 - Michael Stacy Feb 06, 2026 10:26 PM	
	200	Removed all tools, equipment, and unwanted materials from the work area.	B0638589 - Sean Dodder Feb 06, 2026 10:24 PM	
	Remove all tools, equipment, and unwanted materials from the work area.		B0623124 - Michael Stacy Feb 06, 2026 10:26 PM	

Sequence #	0012-19	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503984	Aircraft Reg #	XA-SOL	Parent WO #	2503651

0012-19	WO #	2503984	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Detailed Inspection of the Drain-Plug Magnetic Chip-Detector	
Detailed Inspection of the Drain-Plug Magnetic Chip-Detector				
Task / IRN # : 80-11-00-202				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with Task Card 80-11-00-202. Perform LH Detailed Inspection of the Drain-Plug Magnetic Chip-Detector. REF. CL650 AMM 80-11-01-220-801. No discrepancies noted at this time.	B1022255 - Carson Chang Feb 16, 2026 05:34 PM	80-10
	Perform LH Detailed Inspection of the Drain-Plug Magnetic Chip-Detector		B1019908 - Joseph Barnes Feb 16, 2026 05:54 PM	
	200	Complied with Task Card 80-11-00-202. Perform RH Detailed Inspection of the Drain-Plug Magnetic Chip-Detector. REF. CL650 AMM 80-11-01-220-801. No discrepancies noted at this time.	K1018275 - Emmanuel Cocoa Feb 16, 2026 05:13 PM	80-10
	Perform RH Detailed Inspection of the Drain-Plug Magnetic Chip-Detector		B1019908 - Joseph Barnes Feb 16, 2026 05:54 PM	
	300	Removed all tools equipment and unwanted materials.	K1018275 - Emmanuel Cocoa Feb 16, 2026 05:13 PM	
	Remove all tools equipment and unwanted materials.		B1019908 - Joseph Barnes Feb 16, 2026 05:54 PM	
	400			
	Continue Detailed Inspection of the Drain-Plug Magnetic Chip-Detector ref CL650 AMM12-13-80-612-801 step 2.F.(10). Through close out. Dry Motor for 30 second and examine oil level.			

Sequence #	0012-19	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	2503984	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2503651

TOOL INFORMATION

Tool ID	Tool Description	Calibration Due Date
TUSJ2176	Torque wrench	Sep 29, 2026 5:00 PM
TUSS3698	Safety cable gun	Dec 29, 2026 5:00 PM

Bombardier

Sequence #	0012-20	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503986	Aircraft Reg #	XA-SOL	Parent WO #	2503651

0012-20	WO #	2503986	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Discard of the Air Turbine Starter (ATS) oil	
Discard of the Air Turbine Starter (ATS) oil				
Task / IRN # : 80-11-00-203				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with TLMC 80-11-00-203. Performed the LH Discard of the Air Turbine Starter (ATS) oil Ref. CL-650 AMM 80-11-01-680-801.	B0613291 - Eric Strong Feb 04, 2026 05:21 PM	80-10
	Perform LH Discard of the Air Turbine Starter (ATS) oil		B1013522 - Brandon Jennings Feb 04, 2026 05:41 PM	
	200	Complied with TLMC 80-11-00-203. Performed the RH Discard of the Air Turbine Starter (ATS) oil Ref. CL-650 AMM 80-11-01-680-801.	B0613291 - Eric Strong Feb 04, 2026 05:21 PM	80-10
	Perform RH Discard of the Air Turbine Starter (ATS) oil		B1013522 - Brandon Jennings Feb 04, 2026 05:41 PM	
	300	Serviced LH and RH Air Turbine Starter Oil Ref. CL-650 AMM 12-13-80-612-801 Steps 2.A. through 2.F.(9)	B0613291 - Eric Strong Feb 04, 2026 05:18 PM	
	Service LH and RH Air Turbine Starter Oil Ref. CL-650 AMM 12-13-80-612-801		B1013522 - Brandon Jennings Feb 04, 2026 05:41 PM	
	301			
	Continue the Servicing of LH and RH Air Turbine Starter Oil Ref. CL-650 AMM 12-13-80-612-801 Steps 2.F.(10) through Closeout (Dry Motor runs and checking oil quantity)			
	400			
	Remove all tools, equipment and unwanted materials from the work area.			

Sequence #	0012-20	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	2503986	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2503651

TOOL INFORMATION

Tool ID	Tool Description	Calibration Due Date
TUSS3500	Torque Wrench	Jan 30, 2027 5:00 PM

Sequence #	0012-22	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	2503992	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2503651

0012-22	**WO #**	**2503992**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		Operational Test of the Engine-Firewall Fuel Shutoff-Valve	
Operational Test of the Engine-Firewall Fuel Shutoff-Valve				
Task / IRN # : 28-21-13-201				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with TLMC task 28-21-13-201 Performed operational test of the Engine-Firewall Fuel Shutoff-Valve REF CL-650 AMM 28-21-13-710-801. Operational test good.	B1002512 - Brandon Warne Feb 04, 2026 05:54 PM	28-20
	Perform Operational Test of the Engine-Firewall Fuel Shutoff-Valve		B1013522 - Brandon Jennings Feb 04, 2026 07:11 PM	
	200	Removed all tools, equipment and materials from the work area.	B1002512 - Brandon Warne Feb 04, 2026 05:54 PM	
	Remove all tools, equipment and materials from the work area.		B1013522 - Brandon Jennings Feb 04, 2026 07:11 PM	

Sequence #	0013	Aircraft SN #	6111	MWPWO #	2498069
WO #	2498675	Aircraft Reg #	XA-SOL	Parent WO #	2498069

0013	WO #	2498675	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13276285	Complied with Task 29-11-00-301 - Performed Functional Test (Acidity Inspection) of the Hydraulic Fluid System No. 1 and No. 2 Ref CL-650 AMM 29-11-00-281-801. Functional Test Good.	
Functional Test (Acidity Inspection) of the Hydraulic Fluid (System No. 1 and No. 2)				
Task / IRN # : 29-11-00-301				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with TASK number 29-11-00-301 Performed Functional test (Acidity Inspection) of the hydraulic fluid system No. 1 and No. 2 REF CL-650 AMM 29-11-00-281-801. Functional test good.	B1002512 - Brandon Warne Feb 04, 2026 03:43 PM	29-10
	Perform Functional Test (Acidity Inspection) of the Hydraulic Fluid (System No. 1 and No. 2)		B1013522 - Brandon Jennings Feb 04, 2026 04:25 PM	
	200	Removed all tools, equipment and materials from the work area.	B1002512 - Brandon Warne Feb 04, 2026 03:43 PM	
	Remove all tools, equipment and materials from the work area.		B1013522 - Brandon Jennings Feb 04, 2026 04:25 PM	

Sequence #	0014	Aircraft SN #	6111	MWPWO #	2498069
WO #	2498677	Aircraft Reg #	XA-SOL	Parent WO #	2498069

0014	WO #	2498677	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13276287	Complied with Task 29-12-00-301 - Performed Functional Test (Acidity Inspection) of the Hydraulic Fluid (System No. 3) Ref CL-650 AMM 29-12-00-281-801. Functional Test Good.	
Functional Test (Acidity Inspection) of the Hydraulic Fluid (System No. 3)				
Task / IRN # : 29-12-00-301				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task number 29-12-00-301 Performed Functional test (acidity inspection) of the hydraulic fluid (system No.3) REF CL-650 AMM 29-12-00-281-801. Functional test good.	B1002512 - Brandon Warne Feb 04, 2026 05:01 PM	29-10
	Perform Functional Test (Acidity Inspection) of the Hydraulic Fluid (System No. 3)		B1013522 - Brandon Jennings Feb 04, 2026 05:09 PM	
	200	Removed all tools, equipment and materials from the work area.	B1002512 - Brandon Warne Feb 04, 2026 05:01 PM	
	Remove all tools, equipment and materials from the work area.		B1013522 - Brandon Jennings Feb 04, 2026 05:09 PM	

Sequence #	0015	Aircraft SN #	6111	MWPWO #	2498069
WO #	2498484	Aircraft Reg #	XA-SOL	Parent WO #	2498069

0015	WO #	2498484	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13276312	Complied with Task 30-40-00-401 - Perform Detailed Inspection of the LH & RH Windshields/Side Windows Aerodynamic Seals. REF CL650 AMM 56-10-01-220-804.	
Detailed Inspection of the Windshield/Side Window Aerodynamic Seal				
Task / IRN # : 30-40-00-301				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 30-40-00-401. Perform Detailed Inspection of the LH & RH Windshields/Side Windows Aerodynamic Seals. REF CL650 AMM 56-10-01-220-804. See finding 80831.	B1016542 - Carlos Ochoa Feb 18, 2026 04:58 AM	56-10
	Perform Detailed Inspection of the Windshield/Side Window Aerodynamic Seal		B0623124 - Michael Stacy Feb 19, 2026 12:35 AM	
	101	Complied with task 30-40-00-301. Perform Detailed Inspection of the LH & RH Windshields/Side Windows Aerodynamic Seals. REF CL650 AMM 56-10-01-220-804. See finding 80831.	B1016542 - Carlos Ochoa Feb 19, 2026 12:30 AM	
	Admin correction for operation 100: incorrect task number. Perform Detailed Inspection of the Windshield/Side Window Aerodynamic Seal		B0623124 - Michael Stacy Feb 19, 2026 12:35 AM	
	200	Removed all tools, equipment, and unwanted tools.	B1016542 - Carlos Ochoa Feb 18, 2026 04:58 AM	
	Remove all tools, equipment, and unwanted tools.		B0623124 - Michael Stacy Feb 19, 2026 12:35 AM	

Sequence #	0015	Aircraft SN #	6111	MWPWO #	2498069
WO #	2498484	Aircraft Reg #	XA-SOL	Parent WO #	2498069

FINDINGS DETAILS

Finding #	Long Description	Status	Reported By / Date	Defect Source / Disposition	Defect Type	Priority	Follow-up WO #
80831	Found seal separation on Pilots windshield at zones 15 and 10 approximately 0.5 inches long, copilots windshield at zone 1 measuring 0.3 inches, and on copilots side window at zone 30 measuring 0.5 inches. Flagged with streamer.	CLOSED	B1016542 - Carlos Ochoa Feb 17, 2026 9:49 PM	MAINTENANCE 300-QA002	OTHER	3	4791276-PSAP

Sequence #	0016	Aircraft SN #	6111	MWPWO #	2498069
WO #	2498452	Aircraft Reg #	XA-SOL	Parent WO #	2498069

0016	WO #	2498452	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13276306	Complied with Task 52-45-00-301 - Lubrication of the Service Door Locks Previously Complied with on 17-Dec-2025	
Lubrication of the Service Door Locks				
Task / IRN # : 52-45-00-301				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Do Not Work Per Customer Request.	B1014141 - Christopher Drawdy Feb 12, 2026 05:22 PM	12-20
	Perform Lubrication of the Service Door Locks		B1013522 - Brandon Jennings Feb 12, 2026 05:53 PM	
	200	Lubrication of the Service Door Locks Previously Complied with on 17-Dec-2025	B1014141 - Christopher Drawdy Feb 13, 2026 03:53 PM	
	Perform Lubrication of the Service Door Locks		B1017318 - Steve Pritchett Feb 13, 2026 04:00 PM	

Bombardier

Sequence #	0017	Aircraft SN #	6111	MWPWO #	2498069
WO #	2498492	Aircraft Reg #	XA-SOL	Parent WO #	2498069

0017	WO #	2498492	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13276316	Standby compass swing (CL)	
Standby compass swing (CL)				
Task / IRN # : COMPASS SWING				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			34-00
	Perform Standby Compass Swing			

Sequence #	0018	Aircraft SN #	6111	MWPWO #	2498069
WO #	4292870	Aircraft Reg #	XA-SOL	Parent WO #	2498069

0018	WO #	4292870	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13429469	Operational Test of the Air Driven Generator (ADG) Performed on Incoming Flight see Airframe Logbook Entry Dated January 20th, 2026.	
Operational test of the Air Driven Generator (ADG)				
REQUIRED INSPECTION ITEM				
Task / IRN # : 24-23-00-101				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Operational Test of the Air Driven Generator (ADG) performed on Incoming flight see Airframe Logbook Entry Dated January 20th, 2026.	B1014141 - Christopher Drawdy Feb 20, 2026 03:29 PM	24-20
	Operational test of the Air Driven Generator (ADG)		B1013522 - Brandon Jennings Feb 20, 2026 05:15 PM	
RII	200			24-20
	Perform Manual Extension of the Dry Air-Driven-Generator (Dry ADG) and Open door 122AR per AMM 24-23-01-840-805 Note: this is a CMR/RII task			
RII	300			24-20
	Perform Retraction of the Dry Air-Driven-Generator (Dry ADG) After Manual Extension and Close door 122AR per AMM 24-23-01-840-806 Note: this is a CMR/RII task			

Bombardier

Sequence #	0019	Aircraft SN #	6111	MWPWO #	2498069
WO #	4292915	Aircraft Reg #	XA-SOL	Parent WO #	2498069

0019	WO #	4292915	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13429470	*38-10-65-609 RESTORATION (REPLACE FILTER CARTRIDGE AND GASKET) OF THE WATER FILTER ASSEMBLY	
*38-10-65-609 RESTORATION (REPLACE FILTER CARTRIDGE AND GASKET) OF THE WATER FILTER ASSEMBLY				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Performed *38-10-65-609 RESTORATION (REPLACED FILTER CARTRIDGE AND GASKET) OF THE WATER FILTER ASSEMBLY REF: A/C 6111 SMM TASK 38-10-00-840-802 STEP 1.A. to 1.E.(9) continue With Step 1.E.(10) to1.F.(4) and Perform SMM task 38-10-00-710-801 Operational test of the potable water system	B0599115 - Mark Fierro Feb 25, 2026 09:27 PM B1021707 - Miguel Dicochea Feb 25, 2026 08:53 PM	38-00
	*38-10-65-609 RESTORATION (REPLACE FILTER CARTRIDGE AND GASKET) OF THE WATER FILTER ASSEMBLY		B1013522 - Brandon Jennings Feb 26, 2026 01:50 PM	
	101			
	*38-10-65-609 RESTORATION (REPLACE FILTER CARTRIDGE AND GASKET) OF THE WATER FILTER ASSEMBLY. Continue With Step 1.E.(10) to1.F.(4) and Perform SMM task 38-10-00-710-801 Operational test of the potable water system			

REMOVE AND RE-INSTALL DETAILS

	Removed Part # / Removed Serial #	Removed By	Removed - Part Description	Reference	Installed Part # / Installed Serial #	Installed By
	Removed Status	Removed Date-Time	Position	Installed Part Status	Installed Part Description	Installed Date-Time
	770006	B1021707 - Miguel Dicochea	WATER FILTER CARTRIDGE , TOA2	SMM TASK 38-10-00-840-802	770006	B1021707 - Miguel Dicochea
	UNSERVICEABLE	Feb 25, 2026 2:09 PM		NEW	WATER FILTER CARTRIDGE , TOA2	Feb 25, 2026 2:10 PM

Sequence #	0020	Aircraft SN #	6111	MWPWO #	2498069
WO #	4292932	Aircraft Reg #	XA-SOL	Parent WO #	2498069

0020	WO #	4292932	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13429471	Complied with Task 24-20-00-207 - Functional Test of the ADG Heater. Ref CL-650 AMM 24-23-01-720-801. Load Current Measured (1.146 A). Functional Test Good. (24M)	
*24-20-00-207 FUNCTIONAL TEST OF THE AIR DRIVEN GENERATOR (ADG) HEATER.				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with TLMC Task 24-20-00-207, Functional Test of the ADG Heater. REF CL-650 AMM 24-23-01-720-801. Load current measured (1.146 A). Functional Test Good. See Work Order 4292870, Operation 300 for Retraction of the dry ADG	B0143855 - Marlon Zurita Feb 11, 2026 06:53 PM	24-00
	*24-20-00-207 FUNCTIONAL TEST OF THE AIR DRIVEN GENERATOR (ADG) HEATER.		B1013522 - Brandon Jennings Feb 11, 2026 08:56 PM	
	200	Opened Circuit Breaker panel No.2 to FOM. REF CL-650 AMM 24-23-01-720-801, by releasing the studs that hold the circuit breaker panel to the FS. 280 bulkhead.	B0641378 - Calvin Ambrose Feb 11, 2026 01:45 PM	
	Open Circuit Breaker panel No.2 to FOM. REF CL-650 AMM 24-23-01-720-801		Not Required	
	300	Closed Circuit Break Panel No. 2. REF CL-650 AMM 24-23-00-207, by pushing Circuit Breaker panel No.2 to FS.280 bulkhead and tightening the studs that hold the Circuit Breaker panel to the bulkhead.	B0641378 - Calvin Ambrose Feb 11, 2026 02:17 PM	
	Close Circuit Breaker Panel No.2. REF CL-650 AMM 24-23-01-720-801		B1013522 - Brandon Jennings Feb 11, 2026 02:24 PM	
	301	Closed Circuit Break Panel No. 2. REF CL-650 AMM 24-23-01-720-801, by pushing Circuit Breaker panel No.2 to FS.280 bulkhead and tightening the studs that hold the Circuit Breaker panel to the bulkhead.	B0641378 - Calvin Ambrose Feb 11, 2026 02:32 PM	
	Close Circuit Breaker Panel No.2. REF CL-650 AMM 24-23-01-720-801		B1013522 - Brandon Jennings Feb 11, 2026 02:36 PM	09
	400	Complied with removal of all tools, equipment, and unwanted materials from the work area	B0641378 - Calvin Ambrose Feb 11, 2026 03:39 PM	
	Comply with removal of all tools, equipment, and unwanted materials from the work area		B1013522 - Brandon Jennings Feb 11, 2026 08:56 PM	

Sequence #	0020	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4292932	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

OPERATIONAL DETAILS

	Operation #	Corrective Action Long Description	Tech Sign Off	ATA Code
	Operation Description		Insp Sign Off	Reason for Work

TOOL INFORMATION

Tool ID	Tool Description	Calibration Due Date
TUSS1026	Multimeter	Apr 29, 2026 5:00 PM

Bombardier

Sequence #	0021	Aircraft SN #	6111	MWPWO #	2498069
WO #	4292944	Aircraft Reg #	XA-SOL	Parent WO #	2498069

0021	WO #	4292944	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13429472	Complied with Task 27-50-00-104 - Performed Functional Test of the Flap Extension and Retraction (Flap Half-Speed Test) Ref CL-650 AMM 27-50-00-720-801. Functional Test Good.	
27-50-00-104 FUNCTIONAL TEST OF THE FLAP EXTENSION AND RETRACTION (FLAP HALF-SPEED TEST). (CMR)				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with TLMC task 27-50-00-104 Performed Functional Test of the Flap Extension and Retraction (Flap Half-Speed Test) REF CL-650 AMM 27-50-00-720-801. Functional test good.	B1002512 - Brandon Warne Feb 04, 2026 08:59 PM	27-00
	27-50-00-104 FUNCTIONAL TEST OF THE FLAP EXTENSION AND RETRACTION (FLAP HALF-SPEED TEST). (CMR)		B1013522 - Brandon Jennings Feb 04, 2026 09:07 PM	
	200	Removed all tools, equipment and materials from the work area.	B1002512 - Brandon Warne Feb 04, 2026 08:59 PM	
	Remove all tools, equipment and materials from the work area.		B1013522 - Brandon Jennings Feb 04, 2026 09:07 PM	

Bombardier

Sequence #	0022	Aircraft SN #	6111	MWPWO #	2498069
WO #	4292960	Aircraft Reg #	XA-SOL	Parent WO #	2498069

0022	WO #	4292960	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13429430	Complied with Task 56-10-00-102 - Detailed Inspection of the Side Window - 4 Bushing Holes. Ref CL650 AMM 56-10-01-220-802, no Defects Noted (AWL*)	
56-10-00-102 DETAILED INSPECTION OF THE SIDE WINDOW - 4 BUSHING HOLES. (AWL)				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 56-10-00-102 DETAILED INSPECTION OF THE SIDE WINDOW - 4 BUSHING HOLES. Ref CL650 AMM 56-10-01-220-802, no defects noted	B0580384 - Patrick Arceneaux Feb 06, 2026 11:22 PM	56-00
	56-10-00-102 DETAILED INSPECTION OF THE SIDE WINDOW - 4 BUSHING HOLES. (AWL*)		B0623124 - Michael Stacy Feb 06, 2026 11:26 PM	
	200	Removed all tools, equipment and unwanted material from the work area	B0580384 - Patrick Arceneaux Feb 06, 2026 11:22 PM	
	Remove all tools, equipment and unwanted material from the work area		B0623124 - Michael Stacy Feb 06, 2026 11:26 PM	

Sequence #	0023	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4540931	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

0023	**WO #**	**4540931**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #	13485372	No Log Entry	
*EVALUATE LH AND RH WING L/E DAMAGE				

Sequence #	0023	Aircraft SN #	6111	MWPWO #	2498069
WO #	4540931	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100 EVALUATE LH AND RH WING L/E DAMAGE	Evaluated all 18 dents on wing L/H side Leading edges dent#1 D .009" L .750" W .900" dent#2 D .002" L .740" W .550" dent#3 D .002" L .600" W .450" dent#4 D .003" L .490" W .370" dent#5 D .002" L .600" W .350" dent#6 D .018" L 1.000" W 1.100" dent#7 D .006" L .950" W .880" dent#8 D .010" L .850" W .540" dent#9 D .002" L .450" W .710" dent#10 D .003" L .700" W .650" dent#11 D .003" L .910" W .900" dent#12 D .009" L .500" W .450" dent#13 D .004" L .600" W .730" dent#14 D .002" L .350" W .300" dent#15 D .005" L .450" W .300" dent#16 D .004" L .800" W .920" dent#17 D .003" L .850" W .700" dent#18 D .011" L 1.000" W .900" Evaluated all 17 dents on wing R/H side Leading edges dent#1 D .010" L .700" W .700" dent#2 D .003" L .650" W .550" dent#3 D .003" L .450" W .450" dent#4 D .004" L .520" W .350" dent#5 D .002" L .400" W .300" dent#6 D .010" L .875" W 0.610" dent#7 D .005" L .750" W .600" dent#8 D .002" L .700" W .480" dent#9 D .007" L .750" W .350" dent#10 D .005" L .750" W .350" dent#11 D .003" L .710" W .520" dent#12 D .002" L .480" W .250" dent#13 D .004" L .650" W .600" dent#14 D .002" L .510" W .450" dent#15 D .003" L .450" W .350" dent#16 D .005" L 1.100" W .950" dent#17 D .003" L .750" W .420" All dents within limits I.A.W CL650 SRM 57-75-01-01 table 101 page 105	B1021894 - Frederic Charlier Feb 13, 2026 08:50 PM B0142244 - Todd Bridges Feb 13, 2026 10:10 PM	57-00
	200 Perform Eddy Current inspection of wing leading edges for cracks in areas marked by maintenance personnel. Left wing LE 15 marked areas Right wing LE 18 marked areas	Performed Eddy Current inspection of LH and RH wing leading edges for cracks in areas marked by maintenance personnel. Left wing LE 15 marked areas Right wing LE 18 marked areas IAW BD100 NDT Manual Part 1, Section 6D NO Defects Noted.	B0642788 - Gary Mendoza Feb 13, 2026 05:56 PM B1019685 - Wallace Warren Feb 13, 2026 06:50 PM	

Sequence #	0023	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4540931	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	300	Performed Eddy Current inspection of LH and RH wing leading edges for cracks in areas marked by maintenance personnel. Left wing LE 18 marked areas Right wing LE 17 marked areas IAW BD100 NDT Manual Part 1, Section 6D NO Defects Noted.	B1019685 - Wallace Warren Feb 16, 2026 09:10 PM	
	Added to correct the number of areas inspected in Op 200		B1019685 - Wallace Warren Feb 16, 2026 09:11 PM	

TOOL INFORMATION

Tool ID	Tool Description	Calibration Due Date
TUSJ2147	Eddy Current Instrument	Oct 30, 2026 5:00 PM
TUSS111C	depth gauge	Dec 30, 2026 5:00 PM

Sequence #	0024	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4650880	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

0024	**WO #**	**4650880**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #	13485390	36 month life raft restoration at vendor (2 each) (CL)	
36 month life raft restoration at vendor (2 each) (CL)				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	See WO:4707941 OP:1100/1300 for the removal of the life rafts.	B0650736 - Jesus Gonzalez Atondo Feb 09, 2026 03:57 PM	25-60
	Remove Life Rafts for service		Not Required	
	200			25-60
	Re-install Life Rafts			
	300	Routed life rafts to vendor for restoration	B1014141 - Christopher Drawdy Feb 18, 2026 05:33 PM	
	Send life rafts to vendor for restoration		B1013522 - Brandon Jennings Feb 20, 2026 05:12 PM	

Sequence #	0024	Aircraft SN #	6111	MWPWO #	2498069
WO #	4650880	Aircraft Reg #	XA-SOL	Parent WO #	2498069

REMOVE AND RE-INSTALL DETAILS

	Removed Part # Removed Serial #	Removed By	Removed - Part Description	Reference	Installed Part # Installed Serial #	Installed By
	Removed Status	**Removed Date-Time**	**Position**	**Installed Part Status**	**Installed Part Description**	**Installed Date-Time**
	1015FASA-6K4-1-150 10UL-02627	B1018553 - Joshua Jackson	LIFE RAFT	SMM 25-21-05-000-801		
	REPAIR & RETURN	Feb 9, 2026 12:25 PM	NO.2			
	1015FASA-6K4-1-150 10UL-02628	B1018553 - Joshua Jackson	LIFE RAFT	SMM 25-21-05-000-801		
	REPAIR & RETURN	Feb 9, 2026 12:29 PM	NO.1			

Bombardier

Sequence #	0025	Aircraft SN #	6111	MWPWO #	2498069
WO #	4651286	Aircraft Reg #	XA-SOL	Parent WO #	2498069

0025	WO #	4651286	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13485374	No Log Entry	
*REPLACE LH AILERON FLUTTER DAMPER PER SRPSA 831366				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Removed and Replaced the LH Aileron Flutter as Per SRPSA Instructions, See Operations 200 thru 500 for Details	B0650736 - Jesus Gonzalez Atondo Mar 04, 2026 08:03 PM	27-00
	*REPLACE LH AILERON FLUTTER DAMPER PER SRPSA 831366		B1013522 - Brandon Jennings Mar 04, 2026 08:34 PM	
	200	Removed LH aileron flutter damper IAW Cl-650 AMM 27-15-07-000-801	B1021822 - Joseph Cuoco Feb 09, 2026 02:52 PM	
	Remove LH aileron flutter damper ref. CL-650 AMM 27-15-07-000-801.		Not Required	
	300	Installed overhauled LH aileron flutter damper IAW Cl-650 AMM 27-15-07-400-801.	B1021822 - Joseph Cuoco Feb 09, 2026 03:20 PM	
	Install LH aileron flutter damper ref. CL-650 AMM 27-15-07-400-801.		B1013522 - Brandon Jennings Feb 09, 2026 03:28 PM	
	400	Performed the operational test of the aileron control system IAW CL-650 AMM 27-11-00-710-801. Ops test good.	B0650736 - Jesus Gonzalez Atondo Mar 04, 2026 08:03 PM	
	Perform the operational test of the aileron control system ref. CL-650 AMM 27-11-00-710-801.		B1013522 - Brandon Jennings Mar 04, 2026 08:34 PM	
	500	Removed all tools, equipment and unwanted material from work area.	B1021822 - Joseph Cuoco Feb 09, 2026 03:36 PM	
	Remove all tools equipment and unwanted material from work area		B0161691 - Thomas Mitchell Feb 14, 2026 04:31 AM	

Sequence #	0025	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4651286	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

REMOVE AND RE-INSTALL DETAILS

	Removed Part # Removed Serial #	Removed By	Removed - Part Description	Reference	Installed Part # Installed Serial #	Installed By
	Removed Status	**Removed Date-Time**	**Position**	**Installed Part Status**	**Installed Part Description**	**Installed Date-Time**
	600-75142-9 HAI7829	B0650736 - Jesus Gonzalez Atondo	DAMPER, FLUTTER	Replace per SRPSA 831366	600-75142-9 HAI4046	B0650736 - Jesus Gonzalez Atondo
	EXCHANGE	Feb 9, 2026 6:53 AM	LEFT	OVERHAULED	DAMPER, FLUTTER	Feb 9, 2026 7:20 AM

TOOL INFORMATION

Tool ID	Tool Description	Calibration Due Date
TUSS3756	Torque Wrench	Oct 30, 2026 5:00 PM

Bombardier

Sequence #	0026	Aircraft SN #	6111	MWPWO #	2498069
WO #	4651310	Aircraft Reg #	XA-SOL	Parent WO #	2498069

0026	WO #	4651310	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13485391	No Log Entry	
Remove and replace Main Landing Gear (MLG) tire (4 each) (604/605/650)				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Evaluated All MLG Tires Found Tires to be worn beyond allowable limits due to Weather Cracks Ref. CL 650 AMM 12-15-00-210-801	B1020176 - Matthew Doyle Feb 17, 2026 02:40 PM	32-10
	Evaluate MLG Wheel and Tire Assemblies for Wear condition		B1013522 - Brandon Jennings Feb 17, 2026 02:49 PM	
	200			32-10
	Note: R & R wheel assy, Note A : 9 HR tire change : 24 HR			
	300	Performed Removal of MLG Wheel and Tire Assemblies Ref Challenger 650 SMM 32-42-28 Meggit Aircraft Braking Systems PN: 5012373 0B9R9	B0642051 - Terry Walters Feb 17, 2026 07:57 PM	32-10
	Perform removal of MLG Wheel and Tire Assemblies		B1013522 - Brandon Jennings Feb 24, 2026 03:44 PM	
	400			
	Perform installation of MLG Wheel and Tire Assemblies			
	500	See WO's 4818595, 4818617, 4818674, and 4818676 for the replacement of the MLG Tires.	B0646266 - Sergio Rodriguez Figueroa Mar 03, 2026 06:10 PM	
	Perform replacement of the MLG Tires (4ea.)		B1013522 - Brandon Jennings Mar 03, 2026 09:20 PM	

Sequence #	0026	Aircraft SN #	6111	MWPWO #	2498069
WO #	4651310	Aircraft Reg #	XA-SOL	Parent WO #	2498069

REMOVE AND RE-INSTALL DETAILS

	Removed Part # Removed Serial #	Removed By	Removed - Part Description	Reference	Installed Part # Installed Serial #	Installed By
	Removed Status	Removed Date-Time	Position	Installed Part Status	Installed Part Description	Installed Date-Time
	5012373 AUG17-4595	B0642051 - Terry Walters	WHEEL ASSY, MLG	32-42-28		
	REPAIR & RETURN	Feb 18, 2026 8:38 AM	1			
	5012373 AUG17-4594	B0642051 - Terry Walters	WHEEL ASSY, MLG	32-42-28		
	REPAIR & RETURN	Feb 18, 2026 8:40 AM	2			
	5012373 DEC16-4478	B0642051 - Terry Walters	WHEEL ASSY, MLG	32-42-28		
	REPAIR & RETURN	Feb 18, 2026 8:41 AM	3			
	5012373 DEC16-4477	B0642051 - Terry Walters	WHEEL ASSY, MLG	32-42-28		
	REPAIR & RETURN	Feb 18, 2026 8:42 AM	4			

FINDINGS DETAILS

Finding #	Long Description	Status	Reported By	Defect Source	Defect Type	Priority	Follow-up WO #
			Date	Disposition			
79184	R/H #3 Brake Assy surface corrosion /new cotter keys	CLOSED	B1018546 - Andres Velazquez	MAINTENANCE	OTHER	3	4786778-RDYLT
			Feb 6, 2026 10:46 AM	300-QA002			
79185	R/H #4 Brake Assy surface corrosion /new cotter	CLOSED	B1018546 - Andres Velazquez	MAINTENANCE	OTHER	3	4786878-RDYLT
			Feb 6, 2026 10:50 AM	300-QA002			

Sequence #	0027	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4651322	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

0027	**WO #**	**4651322**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #	13485395	No Log Entry	
Remove and replace Nose Landing Gear (NLG) tire (both) (604/605/650)				

Sequence #	0027	Aircraft SN #	6111	MWPWO #	2498069
WO #	4651322	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Evaluated The NLG Tires Found Tires to be worn beyond allowable limits due to Cuts and Weather Cracks Ref. CL 650 AMM 12-15-00-210-801	B1020176 - Matthew Doyle Feb 17, 2026 02:39 PM	32-40
	Evaluate the NLG Tires		B1013522 - Brandon Jennings Feb 17, 2026 03:46 PM	
	200	See WO's: 4819305 and 4819314 for the replacements of both the LH and RH NLG Tires.	B0646266 - Sergio Rodriguez Figueroa Mar 03, 2026 02:26 PM	32-40
	Perform replacement of the NLG Tires (both)		B1013522 - Brandon Jennings Mar 03, 2026 06:57 PM	
	300			32-40
	Perform installation of NLG Wheel and Tire Assemblies (both)			
	400	Removed NLG Wheel/Tire Assembly No.1 (PN: 5010600-1 / SN: MAR17-8606) to FOM as required. Ref: CL650 AMM 32-42-01-000-801	B0646266 - Sergio Rodriguez Figueroa Feb 06, 2026 06:07 PM	
	Remove NLG Wheel/Tire Assembly No.1 to FOM. Ref: CL650 AMM 32-42-01-000-801		Not Required	
	500			
	Install NLG Wheel/Tire Assembly No.1 (PN: 5010600-1 / SN: MAR17-8606). Ref: CL650 AMM 32-42-01-400-801			
	600	Removed NLG Wheel/Tire Assembly No.2 (PN: 5010600-1 / SN: AUG17-8658) to FOM as required. Ref: CL650 AMM 32-42-01-000-801	B0646266 - Sergio Rodriguez Figueroa Feb 06, 2026 06:07 PM	
	Remove NLG Wheel/Tire Assembly No.2 (PN: 5010600-1 / SN: AUG17-8658) to FOM. Ref: CL650 AMM 32-42-01-000-801		Not Required	
	700			
	Install NLG Wheel/Tire Assembly No.2 (PN: 5010600-1 / SN: AUG17-8658). Ref: CL650 AMM 32-42-01-400-801			

Sequence #	0027	Aircraft SN #	6111	MWPWO #	2498069
WO #	4651322	Aircraft Reg #	XA-SOL	Parent WO #	2498069

REMOVE AND RE-INSTALL DETAILS

	Removed Part # Removed Serial #	Removed By	Removed - Part Description	Reference	Installed Part # Installed Serial #	Installed By
	Removed Status	**Removed Date-Time**	**Position**	**Installed Part Status**	**Installed Part Description**	**Installed Date-Time**
	5010600-1 MAR17-8606	B0646266 - Sergio Rodriguez Figueroa	WHEEL SUB-ASSY, OUTBOARD	New Tires getting Installed		
	EXCHANGE	Feb 6, 2026 10:54 AM	1			
	5010600-1 AUG17-8658	B0646266 - Sergio Rodriguez Figueroa	WHEEL SUB-ASSY, OUTBOARD	New Tires will be installed.		
	EXCHANGE	Feb 6, 2026 10:58 AM	2			

Bombardier

Sequence #	0028	Aircraft SN #	6111	MWPWO #	2498069
WO #	4651359	Aircraft Reg #	XA-SOL	Parent WO #	2498069

0028	WO #	4651359	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13485389	No Log Entry	
*CUSTOMER REQUESTING NEW LANDING GEAR LOCKING PINS				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			32-00
	*CUSTOMER REQUESTING NEW LANDING GEAR LOCKING PINS			

Bombardier

Sequence #	0029	Aircraft SN #	6111	MWPWO #	2498069
WO #	4715433	Aircraft Reg #	XA-SOL	Parent WO #	2498069

0029	WO #	4715433	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13493706	No Log Entry	
Sealant beginning to fail and crack around multiple interior ribs of RH Exhaust Nozzle Fairing-Assembly Interior. Photos included.				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Performed removal of deteriorated sealant and applied new sealant. In REF: Bombardier Supplementary Maint. Data 78-11-00 and Bombardier SPM 51-23-00-100-801. See op 200 for cure check.	B1018339 - Dwain Wolf Feb 23, 2026 06:46 PM	
	Sealant beginning to fail and crack around multiple interior ribs of RH Exhaust Nozzle Fairing-Assembly Interior. Photos included.		B1013522 - Brandon Jennings Feb 23, 2026 08:18 PM	
	200	Performed 24-Hour cure check of PR1750 B-1/2 on RH tailcone exhaust nozzle ribs. In REF: Bombardier SPM 51-23-00-390-801. Cure check good.	B1018339 - Dwain Wolf Feb 24, 2026 05:26 PM	
	Perform 24-Hour cure check of PR1750 B-1/2 on RH tailcone exhaust nozzle ribs. In REF: Bombardier SPM 51-23-00-390-801. Cure started at 10am (02/23/2026). Cure end 10am (02/24/2026).		B1013522 - Brandon Jennings Feb 24, 2026 07:32 PM	
	300	Removed all tools, equipment, and unwanted materials from the work area.	B1018339 - Dwain Wolf Feb 23, 2026 06:46 PM	
	Remove all tools, equipment, and unwanted materials from the work area.		B1013522 - Brandon Jennings Feb 23, 2026 08:18 PM	

Bombardier

Sequence #	0030	Aircraft SN #	6111	MWPWO #	2498069
WO #	4715442	Aircraft Reg #	XA-SOL	Parent WO #	2498069

0030	WO #	4715442	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13493708	No Log Entry	
Sealant beginning to fail and crack around multiple interior ribs of LH Exhaust Nozzle Fairing-Assembly Interior. Photos included.				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	REMOVED OLD CRACKED SEALANT ON LH EXHAUST FAIRING AND APPLIED NEW HI-TEMP SEALANT , IAW REF CL 650 SPM 51-23-00-390-824	B0646498 - Abel Gaxiola Feb 22, 2026 11:38 PM	
	Sealant beginning to fail and crack around multiple interior ribs of LH Exhaust Nozzle Fairing-Assembly Interior. Photos included.		B0142244 - Todd Bridges Feb 23, 2026 12:17 AM	
	200	REMOVED ALL TOOL / EQUIPMENT AND UNWANTED MATERIALS FROM WORK AREA	B0646498 - Abel Gaxiola Feb 22, 2026 11:38 PM	
	REMOVE ALL TOOL / EQUIPMENT AND UNWANTED MATERIALS FROM WORK AREA		B0142244 - Todd Bridges Feb 23, 2026 12:17 AM	
	300	Perform 24-Hour cure check of PR1750 B-1/2 on LH tailcone exhaust nozzle ribs. In REF: Bombardier SPM 51-23-00-390-801. Cure check good.	B1018339 - Dwain Wolf Feb 23, 2026 06:00 PM	
	PERFORM CURE CHECK		B1013522 - Brandon Jennings Feb 23, 2026 07:08 PM	

Sequence #	0031	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4715572	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

0031	**WO #**	**4715572**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #	13493687	No Log Entry	
NLG shock strut has multiple areas of chipped paint on the axle assembly and the torque links				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			
	NLG shock strut has multiple areas of chipped paint on the axle assembly and the torque links			

Sequence #	0032	Aircraft SN #	6111	MWPWO #	2498069
WO #	4715576	Aircraft Reg #	XA-SOL	Parent WO #	2498069

0032	WO #	4715576	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13493689	No Log Entry	
L/H Multi Function spoiler IBD teflon pad found to be missing and the R/H Multi Function spoiler IBD teflon pad found to be disbonded.				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Replaced L/H MFS IBD teflon pad with new one. The R/H MFS IBD teflon pad replaced with new one. Ref. CL650 SPM 51-21-25-340-801.	K1018275 - Emmanuel Cocoa Feb 17, 2026 08:47 PM	
	L/H MFS IBD teflon pad found to be missing and the R/H MFS IBD teflon pad found to be disbonded.		B1013522 - Brandon Jennings Feb 17, 2026 09:11 PM	
	200	Removed all tools equipment and unwanted materials.	K1018275 - Emmanuel Cocoa Feb 17, 2026 08:49 PM	
	Remove all tools equipment and unwanted materials.		B1013522 - Brandon Jennings Feb 17, 2026 09:11 PM	
	300	Cure Check good Ref Cl650 SRM 51−21−25−340−801.	K1018275 - Emmanuel Cocoa Feb 23, 2026 04:10 PM	
	Cure Check 24hr sealant applied at 1340 on FEB 17 2026		B1013522 - Brandon Jennings Feb 23, 2026 05:42 PM	

Sequence #	0033	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4715599	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

0033	**WO #**	**4715599**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #	13493690	No Log Entry	
multiple dents found on the L/H and R/H side of the nose fuselage zone requireing further evaluation to determine servicability.				

Bombardier

Sequence #	0033	Aircraft SN #	6111	MWPWO #	2498069
WO #	4715599	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Measured 7 dents on R/H and L/H side of FWD fuselage. I.A.W CL650 SRM 53-10-01-01 Dents found to be within RVSM area	B1021894 - Frederic Charlier Feb 10, 2026 04:25 PM	
	multiple dents found on the L/H and R/H side of the nose fuselage zone requireing further evaluation to determine servicability.		B0161691 - Thomas Mitchell Feb 14, 2026 04:34 AM	
	200	Performed Eddy Current inspection for cracks on the L/H and R/H side of the nose fuselage zone at dents 7(ea) as marked. IAW CL650 NDT manual part 1, section 6D. No defects noted.	B0642788 - Gary Mendoza Feb 11, 2026 03:36 PM	
	Request NDT inspection for crack check at each 7 dents locations		B1019685 - Wallace Warren Feb 11, 2026 03:53 PM	
	300	See operations 100 and 200 for work performed. No further action required	B0629148 - Robert Greaves Mar 05, 2026 01:27 AM	
	Continue evaluation from operation 100.		B0161691 - Thomas Mitchell Mar 05, 2026 05:45 AM	
	400	Removed PFD 1 ref: CL-650 AMM Task 31−61−01−000−801	B1001648 - Steve Cardenas Feb 20, 2026 01:06 AM	
	Remove PFD 1 ref: CL-650 AMM Task 31−61−01−000−801		Not Required	
	500	Installed PFD 1 ref: CL-650 AMM Task 31−61−01−400−801, Bond check good at . 01mOhms	B1001648 - Steve Cardenas Mar 05, 2026 01:10 AM	
	Install PFD 1 ref: CL-650 AMM Task 31−61−01−400−801		B0161691 - Thomas Mitchell Mar 05, 2026 05:45 AM	
	600	Removed MFD 1 ref: CL-650 AMM Task 31−61−01−000−801	B1001648 - Steve Cardenas Feb 20, 2026 01:06 AM	
	Remove MFD 1 ref: CL-650 AMM Task 31−61−01−000−801		Not Required	
	700	Installed MFD 1 ref: CL-650 AMM Task 31−61−01−400−801, bond check good at .01mOhm	B1001648 - Steve Cardenas Mar 04, 2026 11:22 PM	
	Install MFD 1 ref: CL-650 AMM Task 31−61−01−400−801		B0161691 - Thomas Mitchell Mar 05, 2026 01:07 AM	

Sequence #	0033	Aircraft SN #	6111	MWPWO #	2498069
WO #	4715599	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	800	Removed PFD 1 Tray ref: Cl-650 AMM Task 31−61−04−000−801	B1001648 - Steve Cardenas Feb 20, 2026 01:06 AM	
	Remove PFD 1 Tray ref: Cl-650 AMM Task 31−61−04−000−801		Not Required	
	900	Installed PFD 1 Tray ref: Cl-650 AMM Task 31−61−04−400−801, bond check good at 0.0mOhms	B1001648 - Steve Cardenas Mar 05, 2026 01:10 AM	
	Install PFD 1 Tray ref: Cl-650 AMM Task 31−61−04−400−801		B0161691 - Thomas Mitchell Mar 05, 2026 05:45 AM	
	1000	Removed MFD 1 Tray ref: Cl-650 AMM Task 31−61−04−000−801	B1001648 - Steve Cardenas Feb 20, 2026 01:06 AM	
	Remove MFD 1 Tray ref: Cl-650 AMM Task 31−61−04−000−801		Not Required	
	1100	Installed MFD 1 Tray ref: Cl-650 AMM Task 31−61−04−400−801, Bond check good .01mOhm	B1001648 - Steve Cardenas Mar 04, 2026 10:12 PM	
	Install MFD 1 Tray ref: Cl-650 AMM Task 31−61−04−400−801		B0161691 - Thomas Mitchell Mar 04, 2026 10:51 PM	
	1200	Performed Operational Test of the Adaptive Flight−Display Unit ref: CL-650 AMM task 31−61−00−710−801, system op checks good.	B1001648 - Steve Cardenas Mar 05, 2026 04:41 AM	
	Perform Operational Test of the Adaptive Flight−Display Unit ref: CL-650 AMM task 31−61−00−710−801		B0161691 - Thomas Mitchell Mar 05, 2026 05:45 AM	

Sequence #	0033	Aircraft SN #	6111	MWPWO #	2498069
WO #	4715599	Aircraft Reg #	XA-SOL	Parent WO #	2498069

REMOVE AND RE-INSTALL DETAILS

	Removed Part # Removed Serial #	Removed By	Removed - Part Description	Reference	Installed Part # Installed Serial #	Installed By
	Removed Status	**Removed Date-Time**	**Position**	**Installed Part Status**	**Installed Part Description**	**Installed Date-Time**
	822-1917-228 48LN3D	B1001648 - Steve Cardenas	AFD-5220E, ADAPTIVE FLIGHT DISPLAY	CL-650 AMM Task 31−61−01−000−801	822-1917-228 48LN3D	B1001648 - Steve Cardenas
	SERVICEABLE	Feb 19, 2026 6:06 PM	1	SERVICEABLE	AFD-5220E, ADAPTIVE FLIGHT DISPLAY	Mar 4, 2026 6:15 PM
	822-1576-001 49HV41	B1001648 - Steve Cardenas	MOUNT, ADAPTIVE FLIGHT, IMT-5220	CL-650 AMM Task 31−61−04−000−801	822-1576-001 49HV41	B1001648 - Steve Cardenas
	SERVICEABLE	Feb 19, 2026 6:10 PM	1	SERVICEABLE	MOUNT, ADAPTIVE FLIGHT, IMT-5220	Mar 4, 2026 2:46 PM
	822-1917-228 4861GC	B1001648 - Steve Cardenas	AFD-5220E, ADAPTIVE FLIGHT DISPLAY	CL-650 AMM Task 31−61−01−000−801	822-1917-228 4861GC	B1001648 - Steve Cardenas
	SERVICEABLE	Feb 19, 2026 6:11 PM	2	SERVICEABLE	AFD-5220E, ADAPTIVE FLIGHT DISPLAY	Mar 4, 2026 4:18 PM
	822-1576-001 49G0FF	B1001648 - Steve Cardenas	MOUNT, ADAPTIVE FLIGHT, IMT-5220	Cl-650 AMM Task 31−61−04−000−801	822-1576-001 49G0FF	B1001648 - Steve Cardenas
	SERVICEABLE	Feb 19, 2026 6:14 PM	2	SERVICEABLE	MOUNT, ADAPTIVE FLIGHT, IMT-5220	Mar 4, 2026 2:44 PM

TOOL INFORMATION

Tool ID	Tool Description	Calibration Due Date
TUSJ2276	ET Flaw Detector	Oct 30, 2026 5:00 PM
TUSS4982	torquescrewdriver	Jul 30, 2026 5:00 PM
TUSS0607	bond meter	Jan 30, 2027 5:00 PM

Bombardier

Sequence #	0034	Aircraft SN #	6111	MWPWO #	2498069
WO #	4715626	Aircraft Reg #	XA-SOL	Parent WO #	2498069

0034	WO #	4715626	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13493673	No Log Entry	
Found Frayed RH MLG Door Bonding jumper				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Removed and Installed New Bonding Jumper on R/H MLG Door. Ref: CL-650 SPM 51-80-00-000-801 and 51-80-00-400-801.	B0646275 - Hector Amaya Jr Feb 18, 2026 12:26 AM	
	Found Frayed RH MLG Door Bonding jumper		B0623124 - Michael Stacy Feb 18, 2026 01:49 AM	
	200	Removed all tools, equipment, and unwanted materials from the work area.	B0646275 - Hector Amaya Jr Feb 18, 2026 12:26 AM	
	Remove all tools, equipment, and unwanted materials from the work area.		B0623124 - Michael Stacy Feb 18, 2026 01:49 AM	

TOOL INFORMATION

Tool ID	Tool Description	Calibration Due Date
TUSS2176	Torque Wrench	Sep 29, 2026 5:00 PM

Bombardier

Sequence #	0035	Aircraft SN #	6111	MWPWO #	2498069
WO #	4715668	Aircraft Reg #	XA-SOL	Parent WO #	2498069

0035	WO #	4715668	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13493676	No Log Entry	
Evaluate and Advise: Corrosion Noted at galley heater and line fittings/ trace of previous leak noted at galley trash drawer compartment.				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			
	Corrosion Noted at galley heater and line fittings/ trace of previous leak noted at galley trash drawer compartment.			

Sequence #	0036	Aircraft SN #	6111	MWPWO #	2498069
WO #	4739575	Aircraft Reg #	XA-SOL	Parent WO #	2498069

0036	WO #	4739575	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13497192	No Log Entry	
Multiple Panels on Zone 300 have improperly installed face seal, Seal Bonded to panel and Aircraft. Will Require new Faying Sealant				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Applied Faying Surface sealant on multiple Areas on Zone 300 as Required in Ref CL-650 SPM 51−23−00−390−803.	B0143806 - Alejandro Cabanillas Feb 17, 2026 08:51 PM	
	Multiple Panels on Zone 300 have improperly installed face seal, Seal Bonded to panel and Aircraft		B1013522 - Brandon Jennings Feb 17, 2026 09:13 PM	
	200	Removed all tools ,equipment and unwanted materials from working Area.	B0143806 - Alejandro Cabanillas Feb 17, 2026 08:55 PM	
	Remove all tools ,equipment and unwanted materials from working Area.		B1013522 - Brandon Jennings Feb 17, 2026 09:13 PM	
	300	Performed cure check in Ref CL-650 SPM 51-23-00-390-801. Cure check good	B0143806 - Alejandro Cabanillas Feb 19, 2026 02:57 PM	
	Perform cure check		B1013522 - Brandon Jennings Feb 19, 2026 03:50 PM	

Sequence #	0037	Aircraft SN #	6111	MWPWO #	2498069
WO #	4748584	Aircraft Reg #	XA-SOL	Parent WO #	2498069

0037	WO #	4748584	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13498352	No Log Entry	
LH and RH Horizontal Stabilizer Cuff seals are worn out.				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Removed worn out LH / RH Horizontal Stabilizer cuff seals and replaced with new. Ref: CL-650 SPM 51-21-13-100-801	B0645936 - Carlos Zerino Feb 14, 2026 03:45 AM	
	LH and RH Horizontal Stabilizer Cuff seals Are worn out.		B0161691 - Thomas Mitchell Feb 14, 2026 03:53 AM	
	200	Complied with cure check of the sealant sample for operation 100. Ref CL-650 SPM 51-23-00-390-801. Cure check good.	B0161867 - Jeremy Kucera Feb 18, 2026 03:50 AM	
	Comply with cure check of sealant sample for operation 100; ref: CL-650 SPM 51-23-00-390-801, due 2/14/26 at 20:44		B0623124 - Michael Stacy Feb 18, 2026 05:23 AM	
	300	Remove all tools, equipment, and unwanted materials from the work area.	B0161867 - Jeremy Kucera Feb 18, 2026 03:51 AM	
	Remove all tools, equipment, and unwanted materials from the work area.		B0623124 - Michael Stacy Feb 18, 2026 05:23 AM	

Sequence #	0038	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4748980	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

0038	**WO #**	**4748980**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #	13498242	No Log Entry	
Torn Orcon Tape on both LH and RH IB Flaps, underneath Flap Fairings (572DB, 572GB, 672DB, 672GB).				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Replaced torn Orcon tape with New Orcon tape on LH and RH IB flaps underneath Flap Fairings 572DB, 572GB, 672DB and 672GB REF CL-650 SPM 51-90-00-930-802.	B1002512 - Brandon Warne Feb 16, 2026 07:08 PM	
	Torn Orcon Tape on both LH and RH IB Flaps, underneath Flap Fairings (572DB, 572GB, 672DB, 672GB).		B1017318 - Steve Pritchett Feb 16, 2026 07:39 PM	
	200	Removed all tools, equipment and materials from the work area.	B1002512 - Brandon Warne Feb 16, 2026 07:08 PM	
	Remove all tools, equipment and materials from the work area.		B1017318 - Steve Pritchett Feb 16, 2026 07:39 PM	

Bombardier

Sequence #	0039	Aircraft SN #	6111	MWPWO #	2498069
WO #	4749000	Aircraft Reg #	XA-SOL	Parent WO #	2498069

0039	WO #	4749000	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13498243	No Log Entry	
Hydraulic line routed above LH MLG strut assembly suspected to be leaking (flagged) Evaluate and advise				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Retorqued Hydraulic Line Routed Above L/H MLG Strut Assy. Ref: CL-650 SPM 20-22-00-910-801.	B0646275 - Hector Amaya Jr Feb 18, 2026 01:02 AM	
	Hydraulic line routed above LH MLG strut assembly suspected to be leaking (flagged)		B0623124 - Michael Stacy Feb 18, 2026 01:53 AM	
	200	Performed Leak Check of Line. Ref: CL-650 SPM 20-70-00-210-801. Leak Check Good.	B0646275 - Hector Amaya Jr Feb 18, 2026 11:29 PM	
	Perform Leak Check of Line.		B0623124 - Michael Stacy Feb 19, 2026 12:37 AM	
	300	Removed all tools, equipment, and unwanted materials from the work area.	B0646275 - Hector Amaya Jr Feb 19, 2026 12:58 AM	
	Remove all tools, equipment, and unwanted materials from the work area.		B0623124 - Michael Stacy Feb 19, 2026 01:09 AM	

TOOL INFORMATION

Tool ID	Tool Description	Calibration Due Date
TUSS159G	Torque Wrench	Oct 30, 2026 5:00 PM

Bombardier

Sequence #	0040	Aircraft SN #	6111	MWPWO #	2498069
WO #	4749015	Aircraft Reg #	XA-SOL	Parent WO #	2498069

0040	WO #	4749015	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13498244	No Log Entry	
Hydraulic Pressure Relief Valve on AFT face of LH Wheel Well is suspected to be leaking (flagged) evaluate and advise.				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Retorqued Hydraulic Line on MLG Priority Valve Connected to Expander. Ref: CL-650 AMM 32-32-10-400-801	B0646275 - Hector Amaya Jr Feb 18, 2026 01:48 AM	
	Hydraulic Pressure Relief Valve on AFT face of LH Wheel Well is suspected to be leaking (flagged)		B0623124 - Michael Stacy Feb 18, 2026 01:54 AM	
	200	Performed Leak Check of Priority Valve Hydraulic Line. Ref: CL-650 AMM 32-32-10-400-801 Step F. (17) and (19). Leak Check Good.	B0646275 - Hector Amaya Jr Feb 18, 2026 11:40 PM	
	Perform Leak Check of Priority Valve Hydraulic Line.		B0623124 - Michael Stacy Feb 19, 2026 12:38 AM	
	300	Removed all tools, equipment, and unwanted materials from the work area.	B0646275 - Hector Amaya Jr Feb 19, 2026 12:59 AM	
	Remove all tools, equipment, and unwanted materials from the work area.		B0623124 - Michael Stacy Feb 19, 2026 01:09 AM	

TOOL INFORMATION

Tool ID	Tool Description	Calibration Due Date
TUSS4231	Torque Wrench	Jul 30, 2026 5:00 PM

Bombardier

Sequence #	0041	Aircraft SN #	6111	MWPWO #	2498069
WO #	4749029	Aircraft Reg #	XA-SOL	Parent WO #	2498069

0041	WO #	4749029	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13498331	No Log Entry	
#3 Hydraulic Reservoir in Main Landing Gear Wheel Well has evidence of leakage around multiple fastener heads (flagged) evaluate and advise.				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Cleaned #3 Hydraulic Reservoir and Surrounding areas. Ref: CL-605 SPM 51-25-00-110-801.	B0646275 - Hector Amaya Jr Feb 18, 2026 03:52 AM	
	#3 Hydraulic Reservoir in Main Landing Gear Wheel Well has evidence of leakage around multiple fastener heads (flagged)		B0623124 - Michael Stacy Feb 18, 2026 05:31 AM	
	101	Cleaned #3 Hydraulic Reservoir and Surrounding areas. Ref: CL-650 SPM 51-25-00-110-801.	B0646275 - Hector Amaya Jr Feb 18, 2026 05:31 AM	
	Admin Correction for Operation 100. Incorrect A/C on ref.		B0623124 - Michael Stacy Feb 18, 2026 05:31 AM	
	200	Performed Leak Check of the #3 Hydraulic Reservoir. Ref: CL-650 SPM 20-70-00-210-801. Leak Check Good.	B0646275 - Hector Amaya Jr Feb 18, 2026 11:45 PM	
	Perform Leak Check of the #3 Hydraulic Reservoir.		B0623124 - Michael Stacy Feb 19, 2026 12:38 AM	
	300	Removed all tools, equipment, and unwanted materials from the work area.	B0646275 - Hector Amaya Jr Feb 19, 2026 01:03 AM	
	Remove all tools, equipment, and unwanted materials from the work area.		B0623124 - Michael Stacy Feb 19, 2026 01:10 AM	

Sequence #	0041	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4749029	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

FINDINGS DETAILS

Finding #	Long Description	Status	Reported By / Date	Defect Source / Disposition	Defect Type	Priority	Follow-up WO #
81024	Hydraulic Return Line Below Hyd. Res. #3 missing Paint from Previous Hydraulic Fluid Spill. See Attachment for Details.	CLOSED	B0646275 - Hector Amaya Jr Feb 18, 2026 4:46 PM	MAINTENANCE 300-QA002	OTHER	3	4796803-RDYLT

Bombardier

Sequence #	0042	Aircraft SN #	6111	MWPWO #	2498069
WO #	4750047	Aircraft Reg #	XA-SOL	Parent WO #	2498069

0042	WO #	4750047	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13498377	No Log Entry	
Disbonding phenolic ring fuel panel 540AB				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	REBONDED PHENOLIC ON FUEL PANEL 540AB IAW REF CL 650 SPM 51-21-26-340-801	B0646498 - Abel Gaxiola Feb 15, 2026 11:31 PM	
	Disbonding phenolic fuel panel 540AB		B0142244 - Todd Bridges Feb 16, 2026 12:02 AM	
	200	PERFORMED ACCELERATED CURE OF 2 HR AT A TEMP OF 160 DEG F. CURE CHECK GOOD WITH NO DEFECTS NOTED IAW REF CL 650 SPM 51-21-26-340-801 PAGE 210 SECTION 2 (F)	B0646498 - Abel Gaxiola Feb 15, 2026 11:31 PM	
	PERFORM CURE CECK		B0142244 - Todd Bridges Feb 16, 2026 12:02 AM	

Sequence #	0043	Aircraft SN #	6111	MWPWO #	2498069
WO #	4750145	Aircraft Reg #	XA-SOL	Parent WO #	2498069

0043	WO #	4750145	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13498428	No Log Entry	
The Top Duct of the APU Inlet Assembly, has large sections of insulation torn off/broken, on both the front and aft side of the duct. Photos are included, location has streamer.				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with applying new sections of insulation on top duct of the APU Inlet Assembly on both the front and aft side of the duct. REF CL650 SPM 51-28-01-390-803.	B0648431 - Caleb Sexton Feb 23, 2026 06:47 PM	
	The Top Duct of the APU Inlet Assembly, has large sections of insulation torn off/broken, on both the front and aft side of the duct. Photos are included, location has streamer.		B1013522 - Brandon Jennings Feb 23, 2026 08:04 PM	
	101	Complied with applying new sections of insulation on top duct of the APU Inlet Assembly on both the front and aft side of the duct. REF CL650 AMM 49-14-01-400-801 Step E(2)(a).	B0648431 - Caleb Sexton Feb 23, 2026 07:31 PM	
	The Top Duct of the APU Inlet Assembly, has large sections of insulation torn off/broken, on both the front and aft side of the duct. Photos are included, location has streamer.		B1013522 - Brandon Jennings Feb 23, 2026 08:04 PM	
	200	Complied with Remove all tools, equipment, and unwanted materials from the work	B0648431 - Caleb Sexton Feb 23, 2026 06:47 PM	
	C/W Remove all tools, equipment, and unwanted materials from the work		B1013522 - Brandon Jennings Feb 23, 2026 08:04 PM	

Sequence #	0044	Aircraft SN #	6111	MWPWO #	2498069
WO #	4750169	Aircraft Reg #	XA-SOL	Parent WO #	2498069

0044	WO #	4750169	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13498379	No Log Entry	
Panel 832DR seal disbanding.				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Prepped panel 832DR and re-bonded the seal to the panel Ref CL-650 SPM 51-21-33-100-801 and 51−21−33−340−801 Step F. (2) (a) trough F. (2) (f).	B0161867 - Jeremy Kucera Feb 19, 2026 10:54 PM	
	Panel 832DR seal disbanding.		B0623124 - Michael Stacy Feb 19, 2026 11:40 PM	
	200	Performed 48hr cure check of the panel and seal Ref CL650 SPM 51-21-33-340-801 Step F. (5) (a) due 2/21/26 at 4pm. Cure check good.	B1020176 - Matthew Doyle Feb 23, 2026 06:47 PM	
	Perform 48hr cure check of the panel and seal Ref CL650 SPM 51−21−33−340−801 Step F. (5) (a) due 2/21/26 at 4pm		B1013522 - Brandon Jennings Feb 23, 2026 07:06 PM	
	300	Removed all tools equipment and unwanted material from work area	B1020176 - Matthew Doyle Feb 24, 2026 01:26 PM	
	Remove all tools equipment and unwanted material from work area		B1013522 - Brandon Jennings Feb 24, 2026 01:30 PM	

Sequence #	0045	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4750251	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

0045	**WO #**	**4750251**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #	13498414	No Log Entry	
Fuel Panel 640AB phenolic strip is disbonded in multiple areas				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	REBONDED PHENOLIC ON FUEL PANEL 640 AB IAW REF CL 650 SPM 51-21-26-340-801	B0646498 - Abel Gaxiola Feb 15, 2026 11:33 PM	
	Fuel Panel 640AB phenolic strip is disbonded in multiple areas		B0142244 - Todd Bridges Feb 16, 2026 12:04 AM	
	200	PERFORMED ACCELERATED CURE OF 2 HR AT A TEMP OF 160 DEG F. CURE CHECK GOOD WITH NO DEFECTS NOTED IAW REF CL 650 SPM 51-21-26-340-801 PAGE 210 SECTION 2 (F)	B0646498 - Abel Gaxiola Feb 15, 2026 11:33 PM	
	PERFORM CURE CHECK		B0142244 - Todd Bridges Feb 16, 2026 12:04 AM	

Sequence #	0046	Aircraft SN #	6111	MWPWO #	2498069
WO #	4750264	Aircraft Reg #	XA-SOL	Parent WO #	2498069

0046	WO #	4750264	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13498322	No Log Entry	
Evaluate and Advise: Corroded spring on the LH outboard flap hinge box (marked with streamer)				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Removed and replaced corroded spring on O/B Bute door actuator assembly with NEW part. REF CL650 SPM 20-21-00-910-801 and 20-50-00-400-802.	B1016542 - Carlos Ochoa Feb 18, 2026 01:27 AM	
	Evaluate and Advise: Corroded spring on the LH outboard flap hinge box (marked with streamer)		B0623124 - Michael Stacy Feb 18, 2026 01:55 AM	
	200	Removed O/B Bute Door Actuator. REF CL650 AMM 27-54-16-000-801.	B1016542 - Carlos Ochoa Feb 18, 2026 01:27 AM	
	Remove O/B Bute Door Actuator. REF CL650 AMM 27-54-16-000-801.		Not Required	
	300	Reinstalled O/B Bute Door Actuator. REF 27-54-16-400-801. See work order: 3154422 for installation of flap hinge fairings.	B1016542 - Carlos Ochoa Feb 18, 2026 01:27 AM	
	Reinstall O/B Bute Door Actuator. REF CL650 AMM 27-54-16-400-801.		B0623124 - Michael Stacy Feb 18, 2026 01:55 AM	
	301	Reinstalled O/B Bute Door Actuator. REF CL-650 AMM 27-54-16-400-801. See work order: 3154422 for installation of flap hinge fairings.	B1016542 - Carlos Ochoa Feb 18, 2026 01:58 AM	
	Reinstall O/B Bute Door Actuator. REF CL650 AMM 27-54-16-400-801.		B0623124 - Michael Stacy Feb 18, 2026 01:59 AM	09
	400	Removed all tools, equipment, and unwanted materials.	B1016542 - Carlos Ochoa Feb 18, 2026 01:27 AM	
	Remove all tools, equipment, and unwanted materials.		B0623124 - Michael Stacy Feb 18, 2026 01:55 AM	

Sequence #	0046	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4750264	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

REMOVE AND RE-INSTALL DETAILS

	Removed Part # Removed Serial #	Removed By	Removed - Part Description	Reference	Installed Part # Installed Serial #	Installed By
	Removed Status	**Removed Date-Time**	**Position**	**Installed Part Status**	**Installed Part Description**	**Installed Date-Time**
	LHC187R06M	B1016542 - Carlos Ochoa	SPRING, COMPRESSION	Corrosion found on spring	LHC187R06M	B1016542 - Carlos Ochoa
	UNSERVICEABLE	Feb 17, 2026 4:30 PM		NEW	SPRING, COMPRESSION	Feb 17, 2026 6:00 PM

TOOL INFORMATION

Tool ID	Tool Description	Calibration Due Date
TUSS3756	Torque Wrench	Oct 30, 2026 5:00 PM

Sequence #	0047	Aircraft SN #	6111	MWPWO #	2498069
WO #	4755774	Aircraft Reg #	XA-SOL	Parent WO #	2498069

0047	WO #	4755774	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13499416	No Log Entry	
Fuel tube in RH MLG Wheel Well has missing/flaking primer in multiple areas (flagged)				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Painted Fuel tube in RH MLG Wheel Well in areas with flaking/missing primer IAW CL650 SRM 51-01-26-00.	B1022255 - Carson Chang Feb 16, 2026 05:49 PM	
	Fuel tube in RH MLG Wheel Well has missing/flaking primer in multiple areas (flagged)		B1019908 - Joseph Barnes Feb 16, 2026 07:13 PM	
	200	Remove all tools equipment and unwanted materials.	B1022255 - Carson Chang Feb 16, 2026 06:49 PM	
	Remove all tools equipment and unwanted materials.		B1019908 - Joseph Barnes Feb 16, 2026 07:13 PM	
	201	Removed all tools equipment and unwanted materials.	B1022255 - Carson Chang Feb 16, 2026 07:18 PM	
	Remove all tools equipment and unwanted materials.		B1019908 - Joseph Barnes Feb 16, 2026 07:45 PM	09

TOOL INFORMATION

Tool ID	Tool Description	Calibration Due Date
TUSSJ2176	Torque wrench	Sep 29, 2026 5:00 PM
TUSS3698	Safety Cable Gun	Dec 30, 2026 5:00 PM

Sequence #	0048	Aircraft SN #	6111	MWPWO #	2498069
WO #	4755876	Aircraft Reg #	XA-SOL	Parent WO #	2498069

0048	WO #	4755876	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13499374	No Log Entry	
The structure below the rudder, has protective tape covering that is torn on the bottom and is lifting on top left hand corner.				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Removed old protective tape and installed new protective tape on the bottom structure below the rudder REF CL-650 SPM 51-90-00-930-802.	B1002512 - Brandon Warne Feb 16, 2026 04:09 PM	
	The structure below the rudder, has protective tape covering that is torn on the bottom and is lifting on top left hand corner.		B1019908 - Joseph Barnes Feb 16, 2026 04:17 PM	
	200	Removed all tools, equipment and materials from the work area.	B1002512 - Brandon Warne Feb 16, 2026 04:09 PM	
	Remove all tools, equipment and materials from the work area.		B1019908 - Joseph Barnes Feb 16, 2026 04:17 PM	

Sequence #	0049	Aircraft SN #	6111	MWPWO #	2498069
WO #	4755973	Aircraft Reg #	XA-SOL	Parent WO #	2498069

0049	WO #	4755973	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13499384	No Log Entry	
Found torn Bonding/Jumper Cable (PN: MS25083-5BB6) on LH Ground Spoiler.				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Removed torn OB Bonding/Jumper Cable from the LH Ground Spoiler and Replaced with a NEW Bonding/Jumper Cable as required. Ref: CL650 SPM 20-21-00-910-801	B0646266 - Sergio Rodriguez Figueroa Feb 18, 2026 07:25 PM	
	Found torn Bonding/Jumper Cable (PN: MS25083-5BB6) on LH Ground Spoiler.		B1013522 - Brandon Jennings Feb 18, 2026 08:26 PM	
	101	Removed torn OB Bonding/Jumper Cable from the LH Ground Spoiler and Replaced with a NEW Bonding/Jumper Cable as required. Ref: CL650 SPM 51-80-00-400-801	B0646266 - Sergio Rodriguez Figueroa Feb 18, 2026 08:33 PM	
	Found torn Bonding/Jumper Cable (PN: MS25083-5BB6) on LH Ground Spoiler.		B1013522 - Brandon Jennings Feb 19, 2026 02:27 PM	09
	200	Removed all tools, equipment, and unwanted materials from the work area as required.	B0646266 - Sergio Rodriguez Figueroa Feb 18, 2026 07:25 PM	
	Remove all tools, equipment, and unwanted material from the work area.		B1013522 - Brandon Jennings Feb 18, 2026 08:26 PM	

TOOL INFORMATION

Tool ID	Tool Description	Calibration Due Date
TUSS3756	Torque Wrench	Oct 30, 2026 5:00 PM

Sequence #	0050	Aircraft SN #	6111	MWPWO #	2498069
WO #	4756106	Aircraft Reg #	XA-SOL	Parent WO #	2498069

0050	WO #	4756106	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13499361	No Log Entry	
Corroded nut on the LH outboard flap hinge box (middle) marked with streamer				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Replaced corroded nut on LH outboard flap middle hinge box with new nut REF CL-650 AMM 27-54-16-400-801.	B1002512 - Brandon Warne Feb 18, 2026 08:24 PM	
	Corroded nut on the LH outboard flap hinge box (middle) marked with streamer		B1013522 - Brandon Jennings Feb 18, 2026 09:08 PM	
	200	Removed all tools, equipment and materials from the work area.	B1002512 - Brandon Warne Feb 18, 2026 08:24 PM	
	Remove all tools, equipment and materials from the work area.		B1013522 - Brandon Jennings Feb 18, 2026 09:08 PM	

TOOL INFORMATION

Tool ID	Tool Description	Calibration Due Date
TUSS3756	Torque Wrench	Oct 30, 2026 5:00 PM

Sequence #	0051	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4761360	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

0051	**WO #**	**4761360**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #	13500768	No Log Entry	
During Removal of RH Elevator, inboard bolt #1, was seized within bearing, and was extremely difficult to remove. Evaluate Elevator side of inboard hinge, and aircraft side of inboard hinge.				

Sequence #	0051	Aircraft SN #	6111	MWPWO #	2498069
WO #	4761360	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Evaluated the Elevator side inboard hinge, which is good no defects noted. Evaluated the Horizontal inboard hinge for the elevator. Inboard press fit flange bushing is scored and need to be replaced.	B0161867 - Jeremy Kucera Feb 14, 2026 03:57 AM	
	During Removal of RH Elevator, inboard bolt #1, was seized within bearing, and was extremely difficult to remove. Evaluate Elevator side of inboard hinge, and aircraft side of inboard hinge.		B0161691 - Thomas Mitchell Feb 14, 2026 04:08 AM	
	200	Evaluated the RH Elevator side inboard hinge, which is good no defects noted. Evaluated the RH Horizontal inboard hinge for the elevator. Inboard press fit flange bushing is scored and needs to be replaced.	B0161867 - Jeremy Kucera Feb 14, 2026 03:59 AM	
	Admin correction for operation 100		B0161691 - Thomas Mitchell Feb 14, 2026 04:08 AM	
	300	Evaluated RH horizontal inboard elevator hinge plate noted hinge plate in need of alodine, primer, and paint. No other defects noted. See operation 500 for work performed.	B0641903 - Felipe Mendoza Cervantes Mar 02, 2026 10:45 PM	
	Evaluate RH Horizontal inboard elevator hinge plate.		B0161691 - Thomas Mitchell Mar 02, 2026 11:45 PM	
	400	Removed RH inboard elevator hinge inboard bushing, and installed new bushing PN: 600-10300-21. REF: CL650 SRM 51-79-03-00.	B0641903 - Felipe Mendoza Cervantes Feb 28, 2026 04:32 AM	
	Replace the RH Horizontal inboard elevator hinge inboard press fit flange bushing.		B0161691 - Thomas Mitchell Mar 02, 2026 11:45 PM	
	500	Applied Alodine, touch-up primer and paint to RH elevator inboard attaching hinge on the aircraft side. REF: CL-650 SRM 51-01-06-00 and CL-650 SRM 51-01-08-00.	B0641903 - Felipe Mendoza Cervantes Mar 02, 2026 10:45 PM	
	Apply Alodine, primer and topcoat to the RH Horizontal inboard hinge for the elevator.		B0161691 - Thomas Mitchell Mar 02, 2026 11:45 PM	
	600	Performed 3 day cure check of topcoat applied on 2 MARCH 2026 at 1530 hours on RH elevator inboard most hinge. Cure check is good, cure check done on 5 March 2026 at 1530 hours REF: CL-650 SRM 51-01-08-00	B0641903 - Felipe Mendoza Cervantes Mar 05, 2026 11:38 PM	
	Perform 3 day cure check of topcoat applied on 2 MARCH 2026 at 1530 hours on RH elevator inboard most hinge. REF: CL-650 SRM 51-01-08-00		B0609145 - Miguel Pacheco Mar 06, 2026 01:16 AM	

Sequence #	0051	Aircraft SN #	6111	MWPWO #	2498069
WO #	4761360	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	700	Removed all tools, equipment and unwanted materials from the work area.	B0641903 - Felipe Mendoza Cervantes Mar 05, 2026 11:38 PM	
	Remove all tools,equipment and unwanted martials.		B0609145 - Miguel Pacheco Mar 06, 2026 01:16 AM	

Sequence #	0052	Aircraft SN #	6111	MWPWO #	2498069
WO #	4761617	Aircraft Reg #	XA-SOL	Parent WO #	2498069

0052	WO #	4761617	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13500898	No Log Entry	
Rudder middle hinges attachment hardware requires replacement, and all new rudder attachment self locking nuts.				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Ordered and received new attachment hardware for Rudder middle hinges. See work order 2504334 for install.	B1016542 - Carlos Ochoa Feb 20, 2026 01:53 AM	
	Rudder middle hinges attachment hardware requires replacement, and all new rudder attachment self locking nuts.		B0623124 - Michael Stacy Feb 20, 2026 01:58 AM	

Bombardier

Sequence #	0053	Aircraft SN #	6111	MWPWO #	2498069
WO #	4761494	Aircraft Reg #	XA-SOL	Parent WO #	2498069

0053	WO #	4761494	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13501535	No Log Entry	
RH MLG strut assembly has 2 EA electrical harnesses that are kinked near both brake assemblies (flagged)				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			
	RH MLG strut assembly has 2 EA electrical harnesses that are kinked near both brake assemblies (flagged)			

Bombardier

Sequence #	0054	Aircraft SN #	6111	MWPWO #	2498069
WO #	4765811	Aircraft Reg #	XA-SOL	Parent WO #	2498069

0054	WO #	4765811	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13501496	No Log Entry	
Selector valve in access panel nose compartment access panel 121AL Evidence of hydraulic leak and missing paint on assembly.				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Torqued hydraulic line on the selector valve ref. CL-650 AMM 32-33-07-400-801 step 2.F(13). See OP:300 for leak check.	B0650736 - Jesus Gonzalez Atondo Feb 20, 2026 02:44 PM	
	Selector valve in access panel nose compartment access panel 121AL Evidence of hydraulic leak.		B1013522 - Brandon Jennings Feb 20, 2026 03:42 PM	05
	200	Cleaned and reapplied primer/paint to NLG selector valve IAW CL-650 SRM 51-01-06 and 51-01-08.	B1022275 - Kaitlynn Maxon Feb 20, 2026 04:23 PM	
	Selector valve missing paint on assembly.		B1013522 - Brandon Jennings Feb 20, 2026 04:32 PM	
	300	Pressurized No.3 hyd system and checked hydraulic lines on the selector valve for leaks ref. CL-650 AMM 12-00-04-862-803. Leak check good.	B0650736 - Jesus Gonzalez Atondo Mar 04, 2026 05:34 PM	
	Pressurize No.3 hyd system and check for leaks		B1013522 - Brandon Jennings Mar 04, 2026 05:49 PM	

TOOL INFORMATION

Tool ID	Tool Description	Calibration Due Date
TUSS159G	Torque wrench	Oct 30, 2026 5:00 PM

Bombardier

Sequence #	0055	Aircraft SN #	6111	MWPWO #	2498069
WO #	4766207	Aircraft Reg #	XA-SOL	Parent WO #	2498069

0055	WO #	4766207	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13501594	No Log Entry	
Work Order Entered in Error				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Work Order Entered in Error	B1014141 - Christopher Drawdy Feb 13, 2026 04:02 PM	
	Work Order Entered in Error		B1017318 - Steve Pritchett Feb 13, 2026 05:23 PM	

Sequence #	0056	Aircraft SN #	6111	MWPWO #	2498069
WO #	4784215	Aircraft Reg #	XA-SOL	Parent WO #	2498069

0056	WO #	4784215	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13504231	No Log Entry	
Seized hardware during removal of the hinge bolts on both the LH and RH Flight Spoilers.				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Removed seized hardware and replaced with new hardware IAW CL-650 AMM Ref: 57-70-01-220-804	B1021822 - Joseph Cuoco Feb 26, 2026 08:26 PM	
	Seized hardware during removal of the hinge bolts on both the LH and RH Flight Spoilers.		B1013522 - Brandon Jennings Feb 26, 2026 09:08 PM	
	200	Removed all tools, equipment, and unwanted materials from the work area.	B1021822 - Joseph Cuoco Feb 26, 2026 08:26 PM	
	Remove all tools, equipment, and unwanted materials from the work area.		B1013522 - Brandon Jennings Feb 26, 2026 09:08 PM	

Bombardier

Sequence #	0057	Aircraft SN #	6111	MWPWO #	2498069
WO #	4784967	Aircraft Reg #	XA-SOL	Parent WO #	2498069

0057	WO #	4784967	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13504405	No Log Entry	
T/R panels on RH T/R down to bare material, in multiple locations				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Applied Primer on T/R Blocker Doors as Required. Ref: CL-650 SRM 51-01-06.	B0646275 - Hector Amaya Jr Feb 20, 2026 01:32 AM	
	T/R panels on RH T/R down to bare material		B0623124 - Michael Stacy Feb 20, 2026 01:33 AM	
	200	Removed all tools, equipment, and unwanted materials from the work area.	B0646275 - Hector Amaya Jr Feb 20, 2026 01:32 AM	
	Remove all tools, equipment, and unwanted materials from the work area.		B0623124 - Michael Stacy Feb 20, 2026 01:33 AM	

Sequence #	0058	Aircraft SN #	6111	MWPWO #	2498069
WO #	4784975	Aircraft Reg #	XA-SOL	Parent WO #	2498069

0058	WO #	4784975	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13504387	No Log Entry	
LH T/R blocker doors down to bare material.				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Applied new primer coat on affected areas of the LH ENG TR blocker doors. REF CL650 SRM 51-01-06.	B1016542 - Carlos Ochoa Feb 20, 2026 12:59 AM	
	LH T/R blocker doors down to bare material.		B0623124 - Michael Stacy Feb 20, 2026 01:01 AM	
	200	Performed solvent cleaning of the affected areas on LH ENG TR blocker doors. REF CL650 SPM 51-25-00-110-801.	B1016542 - Carlos Ochoa Feb 20, 2026 12:59 AM	
	Perform solvent cleaning of the affected areas on LH ENG TR blocker doors. REF CL650 SPM 51-25-00-110-801.		B0623124 - Michael Stacy Feb 20, 2026 01:01 AM	
	300	Removed all tools, equipment, and unwanted materials.	B1016542 - Carlos Ochoa Feb 20, 2026 12:59 AM	
	Remove all tools, equipment, and unwanted materials.		B0623124 - Michael Stacy Feb 20, 2026 01:01 AM	

Sequence #	0059	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4784980	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

0059	**WO #**	**4784980**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #	13504410	No Log Entry	
Access panel 520AB LH wing landing/taxi light window has 4 stripped fasteners. (P/N: CA2023-5 and CA2035)				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			
	Access panel 520AB LH wing landing/taxi light window has 4 stripped fasteners. (P/N: CA2023-5 and CA2035)			

Bombardier

Sequence #	0060	Aircraft SN #	6111	MWPWO #	2498069
WO #	4786778	Aircraft Reg #	XA-SOL	Parent WO #	2498069

0060	WO #	4786778	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13504529	R/H #3 Brake Assy surface corrosion /new cotter keys	
R/H #3 Brake Assy has evidence of surface corrosion. Evaluate.				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Inspected R/H #3 Brake Assy surface corrosion ref. CL-650 CMM Brake Assy. 5012333 32-44-69 Check Section par. 7. Face backplate corrosion depth within limits, 0.0007in, 0.00065in, 0.0008in, 0.0045in. MAX corrosion depth must not be deeper than 0.020in.	B0650736 - Jesus Gonzalez Atondo Feb 19, 2026 04:02 PM	
	R/H #3 Brake Assy surface corrosion		B1013522 - Brandon Jennings Feb 19, 2026 04:26 PM	
	101	Brake Assembly Grit Blast Requires Brake Dissemble and is Beyond or Repair capabilities, Replace Brake Assy.	B0650736 - Jesus Gonzalez Atondo Feb 27, 2026 08:20 PM	
	Grit blast to remove corrosion ref. CL-650 CMM brake assy 5012333 32-44-69		B1013522 - Brandon Jennings Feb 27, 2026 08:36 PM	
	200	Received overhauled brake unit PN:5012333 SN:MAR96-0090, See WO:4727698 OP:1400 for the installation of the #3 brake unit.	B0650736 - Jesus Gonzalez Atondo Feb 27, 2026 08:20 PM	
	Order and Receive #3 Brake Assembly		B1013522 - Brandon Jennings Feb 27, 2026 08:36 PM	

TOOL INFORMATION

Tool ID	Tool Description	Calibration Due Date
TUSS5046	depth gauge	Apr 6, 2026 5:00 PM
TUSS2882	digital caliper	May 30, 2026 5:00 PM

Sequence #	0061	Aircraft SN #	6111	MWPWO #	2498069
WO #	4786878	Aircraft Reg #	XA-SOL	Parent WO #	2498069

0061	WO #	4786878	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13504550	No Log Entry	
R/H #4 Brake Assy has evidence of surface corrosion. Evaluate.				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Inspected R/H #4 Brake Assy surface corrosion ref. CL-650 CMM Brake Assy. 5012333 32-44-69 Check Section par. 7. Face backplate corrosion depth within limits, 0.0007in, 0.0006in, 0.0008in, 0.0010in, 0.0095in, 0.0009in. MAX corrosion depth must not be deeper than 0.020in. #4 brake assy requires more access, found corrosion between the torque tube and backplate.	B0650736 - Jesus Gonzalez Atondo Feb 19, 2026 04:04 PM	
	R/H #4 Brake Assy surface corrosion		B1013522 - Brandon Jennings Feb 19, 2026 04:25 PM	
	101	Brake Corrosion Repairs are Beyond the Repair Station Capability Replace Brake Assy.	B0650736 - Jesus Gonzalez Atondo Feb 27, 2026 08:18 PM	
	Grit blast to remove corrosion ref. CL-650 CMM brake assy 5012333 32-44-69		B1013522 - Brandon Jennings Feb 27, 2026 08:40 PM	
	200	Brake Corrosion Repairs are Beyond the Repair Station Capability Replace Brake Assy.	B0650736 - Jesus Gonzalez Atondo Feb 27, 2026 08:18 PM	
	Remove torque tube assy and check for corrosion.		B1013522 - Brandon Jennings Feb 27, 2026 08:40 PM	
	300	Received overhauled brake unit PN:5012333 SN:NOV17-3109, See WO:4727698 OP:1600 for the installation of the #4 brake unit.	B0650736 - Jesus Gonzalez Atondo Feb 27, 2026 08:18 PM	
	Order and Receive #4 Serviceable Brake Assy.		B1013522 - Brandon Jennings Feb 27, 2026 08:40 PM	

Sequence #	0061	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4786878	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

TOOL INFORMATION

Tool ID	Tool Description	Calibration Due Date
TUSS5046	depth gauge	Apr 6, 2026 5:00 PM
TUSS2882	digital caliper	May 30, 2026 5:00 PM

Bombardier

Sequence #	0062	Aircraft SN #	6111	MWPWO #	2498069
WO #	4787778	Aircraft Reg #	XA-SOL	Parent WO #	2498069

0062	WO #	4787778	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13505238	No Log Entry	
LH Winglet has Excessive Filler Material that requires removed to access the screws				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Removed excessive paint on attaching screw heads of LH wing lower surface fairing 560DB using metallic pick. See WO: 3154422 for opening of panel.	B0641903 - Felipe Mendoza Cervantes Feb 19, 2026 12:53 AM	
	LH Winglet has Excessive Filler Material that requires removed to access the screws		B0623124 - Michael Stacy Feb 19, 2026 12:56 AM	
	200	Removed all tools equipment and unwanted materials from the work area.	B0641903 - Felipe Mendoza Cervantes Feb 19, 2026 12:53 AM	
	Remove all tools equipment and unwanted materials from the work area.		B0623124 - Michael Stacy Feb 19, 2026 12:56 AM	

Bombardier

Sequence #	0063	Aircraft SN #	6111	MWPWO #	2498069
WO #	4791276	Aircraft Reg #	XA-SOL	Parent WO #	2498069

0063	WO #	4791276	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13505240	No Log Entry	
Found seal separation on Pilots windshield at zones 15 and 10 approximately 0.5 inches long, copilots windshield at zone 1 measuring 0.3 inches, and on copilots side window at zone 30 measuring 0.5 inches. Flagged with streamer.				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Performed preparation for repairs of affected areas of the windshields/side windows aerodynamic sealant. REF CL650 AMM 56-11-01-390-801 steps D.1. thru D.2. and F.1. thru F.3.(f.).	B1016542 - Carlos Ochoa Feb 19, 2026 01:08 AM	
	Found seal separation on Pilots windshield at zones 15 and 10 approximately 0.5 inches long, copilots windshield at zone 1 measuring 0.3 inches, and on copilots side window at zone 30 measuring 0.5 inches. Flagged with streamer.		B0623124 - Michael Stacy Feb 19, 2026 01:21 AM	
	200	Continued repairs of the windshields/side windows aerodynamic sealant. REF CL650 AMM 56-11-01-390-801 steps F.(4.) thru F.(4.)(o.). See operation 300 for cure check and closeout.	B1016542 - Carlos Ochoa Feb 21, 2026 02:28 AM	
	Continue repairs of the windshields/side windows sealant. REF CL650 AMM 56−11−01−390−801 steps F.4. thru Closeout.		B0623124 - Michael Stacy Feb 21, 2026 03:21 AM	
	300	Performed 24 hour cure check of the repaired sealant at 16:00 on 2/23/26. Cure check good. REF: CL-650 AMM 56-11-01-390-801 steps F(4)(P). Through close out.	B1018547 - Matthew Rossier Feb 24, 2026 04:53 AM	
	Perform 24 hour cure check of the repaired sealant at 19:15 on 02/21/26. REF CL650 AMM 56-11-01-390-801 steps F.(4.)(p.) thru closeout.		B0609145 - Miguel Pacheco Feb 24, 2026 04:54 AM	
	400	Removed all tools, equipment, and unwanted materials form work area.	B1018547 - Matthew Rossier Feb 24, 2026 04:53 AM	
	Remove all tools, equipment, and unwanted materials from work area.		B0609145 - Miguel Pacheco Feb 24, 2026 04:54 AM	

Sequence #	0064	Aircraft SN #	6111	MWPWO #	2498069
WO #	4796018	Aircraft Reg #	XA-SOL	Parent WO #	2498069

0064	WO #	4796018	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13505949	No Log Entry	
On RH Elevator, multiple spots within the middle and inboard hinge locations need touch up primer and paint. Has exposed metal. Photos included.				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Applied touch-up primer and paint on RH elevator middle and inboard hinge areas. REF: CL650 SRM 51-01-06-00 and CL650 SRM 51-01-08-00.	B0641903 - Felipe Mendoza Cervantes Feb 20, 2026 12:43 AM	
	On RH Elevator, multiple spots within the middle and inboard hinge locations need touch up primer and paint. Has exposed metal. Photos included.		B0623124 - Michael Stacy Feb 20, 2026 12:49 AM	
	200	Removed all tools equipment and unwanted materials from the work area.	B0641903 - Felipe Mendoza Cervantes Feb 20, 2026 12:43 AM	
	Remove all tools equipment and unwanted materials from the work area.		B0623124 - Michael Stacy Feb 20, 2026 12:49 AM	

Sequence #	0065	Aircraft SN #	6111	MWPWO #	2498069
WO #	4796020	Aircraft Reg #	XA-SOL	Parent WO #	2498069

0065	WO #	4796020	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13505950	No Log Entry	
LH Elevator, multiple spots within the middle and outboard hinge locations need touch up primer and paint. Has exposed metal. Photos included.				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Applied touch-up primer and paint on LH elevator middle and outboard hinge areas. REF: CL650 SRM 51-01-06-00 and CL650 SRM 51-01-08-00.	B0641903 - Felipe Mendoza Cervantes Feb 19, 2026 11:43 PM	
	On LH Elevator, multiple spots within the middle and outboard hinge locations need touch up primer and paint. Has exposed metal. Photos included.		B0623124 - Michael Stacy Feb 19, 2026 11:53 PM	
	200	Removed all tools equipment and unwanted materials from the work area.	B0641903 - Felipe Mendoza Cervantes Feb 19, 2026 11:43 PM	
	Remove all tools equipment and unwanted materials from the work area.		B0623124 - Michael Stacy Feb 19, 2026 11:53 PM	

Bombardier

Sequence #	0066	Aircraft SN #	6111	MWPWO #	2498069
WO #	4796803	Aircraft Reg #	XA-SOL	Parent WO #	2498069

0066	WO #	4796803	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13505952	No Log Entry	
Hydraulic Return Line Below Hyd. Res. #3 missing Paint from Previous Hydraulic Fluid Spill. See Attachment for Details.				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Applied touch-up primer and paint to hydraulic return line below hydraulic reservoir #3. REF: CL-650 SRM 51-01-06-00 and CL-650 SRM 51-01-08-00.	B0641903 - Felipe Mendoza Cervantes Feb 25, 2026 10:56 PM	
	Hydraulic Return Line Below Hyd. Res. #3 missing Paint from Previous Hydraulic Fluid Spill. See Attachment for Details.		B0161691 - Thomas Mitchell Feb 25, 2026 11:58 PM	
	200	Removed all tools equipment and unwanted materials from the work area	B0641903 - Felipe Mendoza Cervantes Feb 25, 2026 10:56 PM	
	Remove all tools equipment and unwanted materials from the work area.		B0161691 - Thomas Mitchell Feb 25, 2026 11:58 PM	
	300	Performed cure check on 4 March 2026 at 1555 hours on hydraulic line under reservoir #3 topcoat applied on 25 FEB 2026 at 1530 hours. Cure check is good. REF: CL650 SRM 51-01-08-00.	B0641903 - Felipe Mendoza Cervantes Mar 04, 2026 10:58 PM	
	Perform 3 day cure check of topcoat applied on 25 FEB 2026 at 1530 hours to hydraulic line under reservoir #3 see attachments. REF: CL-650 SRM 51-01-08-00		B0161691 - Thomas Mitchell Mar 05, 2026 01:03 AM	

Bombardier

Sequence #	0067	Aircraft SN #	6111	MWPWO #	2498069
WO #	4791438	Aircraft Reg #	XA-SOL	Parent WO #	2498069

0067	WO #	4791438	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13506136	No Log Entry	
Passenger door cable pulley wheel worn.				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Removed and Installed a NEW passenger door cable pulley (P/N: MS20220-2) Ref. CL-650 AMM 52-11-19-000-801 & 52-11-19-400-801 Steps 2.D.(1) and 2.E.(9)-(10)	B0613291 - Eric Strong Feb 20, 2026 11:38 PM	
	Passenger door cable pulley wheel worn .		B0142244 - Todd Bridges Feb 21, 2026 12:05 AM	
	200			
	Do an operational test of the passenger-door actuator motor Ref. CL-650 AMM 52-11-19-710-801			
	300			
	Remove all tools, equipment, and unwanted materials from the work area.			

REMOVE AND RE-INSTALL DETAILS

	Removed Part # / Removed Serial #	Removed By	Removed - Part Description	Reference	Installed Part # / Installed Serial #	Installed By
	Removed Status	Removed Date-Time	Position	Installed Part Status	Installed Part Description	Installed Date-Time
	MS20220-2	B0613291 - Eric Strong	PULLEY, PAX DOOR CABLE	worn	MS20220-2	B0613291 - Eric Strong
	UNSERVICEABLE	Feb 20, 2026 2:27 PM		SERVICEABLE	PULLEY, PAX DOOR CABLE	Feb 20, 2026 2:27 PM

Bombardier

Sequence #	0068	Aircraft SN #	6111	MWPWO #	2498069
WO #	4800751	Aircraft Reg #	XA-SOL	Parent WO #	2498069

0068	WO #	4800751	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13506617	No Log Entry	
Panel 325CL print seal damaged				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Applied gap sealant to panel 325CL by taping the perimeter with fiberglass tape followed by pressure sensitive tape, then applied a layer of dry lubricant release agent. The panel was them temp installed and gap sealed. REF: CL-650 SPM 51-23-00-390-808	B1018547 - Matthew Rossier Feb 20, 2026 12:45 AM	
	Panel 325CL print seal damaged		B0623124 - Michael Stacy Feb 20, 2026 12:48 AM	
	200	Performed 9 hour cure check of panel 325CL on 2/20/26 at 5:00 PM REF: CL-650 SPM 51-23-00-390-801 and removed panel as well as all tape. See panel log WO: 3154422 for close	B1018547 - Matthew Rossier Feb 21, 2026 12:33 AM	
	Perform 9 hour cure check of sealant on panel 325CL on 2/20/26 at 1:30 AM REF: CL-650 SPM 51-23-00-390-801 Remove panel 325CL and tape upon completion of cure check REF: CL-650 AMM 55-30-43-000-802		B0623124 - Michael Stacy Feb 21, 2026 12:37 AM	
	300	Performed 9 hour cure check of panel 325CL on 2/20/26 at 5:00 PM REF: CL-650 SPM 51-23-00-390-801 cure check good. Removed panel as well as all tape. See panel log WO: 3154422 for close	B1018547 - Matthew Rossier Feb 21, 2026 12:40 AM	
	Admin correction for operation 200 - incorrect sign off		B0623124 - Michael Stacy Feb 21, 2026 12:41 AM	
	400	Removed all tools, equipment, and unwanted materials from work area	B1018547 - Matthew Rossier Feb 21, 2026 12:43 AM	
	Remove all tools, equipment, and unwanted materials from work area		B0161691 - Thomas Mitchell Feb 27, 2026 10:19 PM	

Bombardier

Sequence #	0069	Aircraft SN #	6111	MWPWO #	2498069
WO #	4802722	Aircraft Reg #	XA-SOL	Parent WO #	2498069

0069	WO #	4802722	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13506703	No Log Entry	
Panel 191AL & 192AR (HDY SYS PNL) has desponded spacer next to key lock				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Performed Cementing of Teflon Lock Block on Panels 191AL and 192 AR (2ea). Ref: CL-650 SPM 51-21-25-340-801.	B0646275 - Hector Amaya Jr Feb 21, 2026 12:52 AM	
	Panel 191AL & 192AR (HDY SYS PNL) has desponded spacer next to key lock		B0623124 - Michael Stacy Feb 21, 2026 01:26 AM	
	200	Performed 24 hour cure check of lock blocks on panels 191AL and 192AR at 16:30 on 2/23/26. Cure check good. REF: CL-650 SPM 51-21-25-340-801	B1018547 - Matthew Rossier Feb 23, 2026 11:30 PM	
	Perform 24H Cure Check of Lock Blocks at 2/21/26 at 5:51PM. Ref: CL-650 SPM 51-21-25-340-801.		B0622205 - Cody Borgwald Feb 23, 2026 11:41 PM	
	300	Removed all tools, equipment, and unwanted materials from work area.	B1018547 - Matthew Rossier Feb 23, 2026 11:30 PM	
	Remove all tools, equipment, and unwanted materials from work area		B0622205 - Cody Borgwald Feb 23, 2026 11:41 PM	

Sequence #	0070	Aircraft SN #	6111	MWPWO #	2498069
WO #	4795496	Aircraft Reg #	XA-SOL	Parent WO #	2498069

0070	WO #	4795496	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13506917	No Log Entry	
Found torn/missing placard on both the LH and RH Ground Spoilers.				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Removed and replaced Caution placards on LH and RH Ground Spoilers with NEW parts. REF CL650 AMM 11-20-00-000-801 and 11-20-00-400-801.	B1016542 - Carlos Ochoa Feb 23, 2026 11:45 PM	
	Found torn/missing placard on both the LH and RH Ground Spoilers.		B0622205 - Cody Borgwald Feb 24, 2026 12:26 AM	
	101	Removed and replaced Caution placards on LH and RH Ground Spoilers with NEW parts. REF CL650 AMM 11-20-00-000-801 and 11-20-00-400-801. P/N: S6913-1	B1016542 - Carlos Ochoa Feb 23, 2026 11:57 PM	
	Admin correction for operation 100: Missing part number info. Found torn/missing placard on both the LH and RH Ground Spoilers.		B0622205 - Cody Borgwald Feb 24, 2026 12:26 AM	
	200	Removed all tools, equipment, and unwanted materials.	B1016542 - Carlos Ochoa Feb 23, 2026 11:45 PM	
	Remove all tools, equipment, and unwanted materials.		B0622205 - Cody Borgwald Feb 24, 2026 12:26 AM	

Bombardier

Sequence #	0071	Aircraft SN #	6111	MWPWO #	2498069
WO #	4803011	Aircraft Reg #	XA-SOL	Parent WO #	2498069

0071	WO #	4803011	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13507065	No Log Entry	
Overwing Emergency-Exit Door, safety Lock cable for hardware of the fwd.-upper door stop missing.				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Installed new safety cable on FWD upper stop fitting of the Emergency-Exit Door. REF CL650 SPM 20-50-00-400-807.	B1016542 - Carlos Ochoa Feb 20, 2026 11:53 PM	
	Overwing Emergency-Exit Door, Lock cable for hardware of the fwd.-upper door stop missing.		B0623124 - Michael Stacy Feb 21, 2026 12:31 AM	
	200	Removed all tools, equipment, and unwanted materials.	B1016542 - Carlos Ochoa Feb 20, 2026 11:53 PM	
	Remove all tools, equipment, and unwanted materials.		B0623124 - Michael Stacy Feb 21, 2026 12:31 AM	

TOOL INFORMATION

Tool ID	Tool Description	Calibration Due Date
TUSS3984	Safety Cable Gun	Apr 29, 2026 5:00 PM

Sequence #	0072	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4804823	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

0072	**WO #**	**4804823**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #	13506971	No Log Entry	
DAMAGE FOUND ON AFT FACE OF RH MLG SIDE BRACE FITTING-SHAFT.				
CRITICAL MAINTENANCE TASK				

Sequence #	0072	Aircraft SN #	6111	MWPWO #	2498069
WO #	4804823	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
CMT	100	Replaced RH MLG side brace fitting shaft with NEW Ref CL-650 AMM 32-32-02-400-801 Steps 2. E. (1)-(8),(13) see working copy dated 2-20-26	B0645936 - Carlos Zerino Feb 21, 2026 04:52 AM	
	DAMAGE FOUND ON AFT FACE OF RH MLG SIDE BRACE FITTING-SHAFT.		B0623124 - Michael Stacy Feb 21, 2026 05:06 AM	
CMT	200	Continued install of new RH MLG side brace fitting shaft; Ref CL-650 AMM 32-32-02-400-801; steps (9) through close-out	B0580384 - Patrick Arceneaux Feb 23, 2026 11:24 PM	
	Continue install of new RH MLG side brace fitting shaft; Ref CL-650 AMM 32-32-02-400-801; steps (9) through close-out		B0622205 - Cody Borgwald Feb 24, 2026 02:09 AM	
CMT	201	Continued install of new RH MLG side brace fitting shaft; Ref CL-650 AMM 32-32-02-400-801; steps (9) through close-out. See CMT working copy dated 2/20/26	B0580384 - Patrick Arceneaux Feb 23, 2026 11:31 PM	
	Admin correction for corrective action on op 200		B0622205 - Cody Borgwald Feb 24, 2026 02:09 AM	
	300	Removed all tools, equipment and unwanted materials from the work area.	B0161867 - Jeremy Kucera Mar 05, 2026 12:52 AM	
	Remove all tools, equipment and unwanted materials from the work area.		B0161691 - Thomas Mitchell Mar 05, 2026 03:30 AM	
	400	Performed 24 hour cure check sealant applied on RH side brace shaft. Cure check is good REF: CL-650 SPM 51-23-00-390-801.	B0641903 - Felipe Mendoza Cervantes Feb 25, 2026 11:15 PM	
	Perform 24hr cure check on sealant		B0161691 - Thomas Mitchell Feb 26, 2026 12:31 AM	
	401	Performed 24 hour cure check sealant applied on FEB 23 2026 at 1630 hours on RH side brace shaft. Cure check is good, cure check performed on FEB 25 2026 at 1600 hours. REF: CL-650 SPM 51-23-00-390-801.	B0641903 - Felipe Mendoza Cervantes Feb 25, 2026 11:25 PM	
	Admin correction for operation 400 missing sealant application and cure check date and time.		B0161691 - Thomas Mitchell Feb 26, 2026 12:31 AM	

Sequence #	0072	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4804823	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

REMOVE AND RE-INSTALL DETAILS

	Removed Part # Removed Serial #	Removed By	Removed - Part Description	Reference	Installed Part # Installed Serial #	Installed By
	Removed Status	**Removed Date-Time**	**Position**	**Installed Part Status**	**Installed Part Description**	**Installed Date-Time**
	601R10237-3 0127	B0645936 - Carlos Zerino	SHAFT, MLG SIDE BRACE FITTING	AMM 32-32-02-000-801	601R10237-3 0527	B0645936 - Carlos Zerino
	UNSERVICEABLE	Feb 20, 2026 9:55 PM	RIGHT	NEW	SHAFT, MLG SIDE BRACE FITTING	Feb 20, 2026 10:02 PM

TOOL INFORMATION

Tool ID	Tool Description	Calibration Due Date
TUSS4231	TORQUE WRENCH	Jul 30, 2026 5:00 PM

Sequence #	0073	Aircraft SN #	6111	MWPWO #	2498069
WO #	4804818	Aircraft Reg #	XA-SOL	Parent WO #	2498069

0073	WO #	4804818	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13507026	No Log Entry	
LH MLG side brace fitting shaft worn, and finish is damaged.				
CRITICAL MAINTENANCE TASK				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
CMT	100	Replaced LH MLG side brace fitting shaft with NEW Ref CL-650 AMM 32-32-02-400-801 Steps 2. E. (1)-(8),(13) see working copy dated 2-20-26	B0580384 - Patrick Arceneaux Feb 21, 2026 04:44 AM	
	LH MLG side brace fitting shaft worn, and finish is damaged.		B0623124 - Michael Stacy Feb 21, 2026 05:00 AM	
CMT	200	Continued install of new LH MLG side brace fitting shaft REF CL650 AMM 32-32-02-400-801 steps 9-close out. See CMT working copy dated 2/20/26	B0580384 - Patrick Arceneaux Feb 23, 2026 11:27 PM	
	Continue install of LH MLG side brace fitting shaft REF CL650 AMM 32-32-02-400-801 steps 9-close out		B0622205 - Cody Borgwald Feb 24, 2026 01:57 AM	
	300	Performed 24 hour cure check sealant applied on LH side brace shaft. Cure check is good REF: CL-650 SPM 51-23-00-390-801.	B0641903 - Felipe Mendoza Cervantes Feb 25, 2026 11:13 PM	
	Perform 24hr cure check on sealant		B0161691 - Thomas Mitchell Feb 26, 2026 12:27 AM	
	301	Performed 24 hour cure check sealant applied on FEB 23 2026 at 1630 hours on LH side brace shaft. Cure check is good, cure check performed on FEB 25 2026 at 1600 hours. REF: CL-650 SPM 51-23-00-390-801.	B0641903 - Felipe Mendoza Cervantes Feb 25, 2026 11:28 PM	
	Admin correction for operation 300 missing sealant application and cure check date and time.		B0161691 - Thomas Mitchell Feb 26, 2026 12:27 AM	
	400	Verified all tools, equipment and unwanted materials were removed from the work area.	B0161867 - Jeremy Kucera Mar 05, 2026 12:54 AM	
	Remove all tools, equipment and unwanted materials from the work area		B0161691 - Thomas Mitchell Mar 05, 2026 03:28 AM	

Sequence #	0073	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4804818	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

REMOVE AND RE-INSTALL DETAILS

	Removed Part # Removed Serial #	Removed By	Removed - Part Description	Reference	Installed Part # Installed Serial #	Installed By
	Removed Status	**Removed Date-Time**	**Position**	**Installed Part Status**	**Installed Part Description**	**Installed Date-Time**
	601R10237-3-01 0107	B0580384 - Patrick Arceneaux	SHAFT, MLG SIDE BRACE FITTING	CL-650 AMM 32-32-02-000-801	601R10237-3-01 0467	B0580384 - Patrick Arceneaux
	UNSERVICEABLE	Feb 20, 2026 9:48 PM	LEFT	NEW	SHAFT, MLG SIDE BRACE FITTING	Feb 20, 2026 9:48 PM

TOOL INFORMATION

Tool ID	Tool Description	Calibration Due Date
TUSS4231	Torque wrench	Jul 30, 2026 5:00 PM

Bombardier

Sequence #	0074	Aircraft SN #	6111	MWPWO #	2498069
WO #	4810267	Aircraft Reg #	XA-SOL	Parent WO #	2498069

0074	WO #	4810267	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13507634	No Log Entry	
Horizontal stabilizer flutter dampener Access panel (332BB) has damage print seal.				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Taped perimeter of panel 332BB with fiberglass tape followed by pressure sensitive tape. Then temp installed the panel and applied gap sealant REF: CL-650 SPM 51-23-00-390-808	B1018547 - Matthew Rossier Feb 26, 2026 10:19 PM	
	Horizontal stabilizer flutter dampener Access panel (332BB) has damage print seal.		B0161691 - Thomas Mitchell Feb 27, 2026 10:18 PM	
	101	Performed 9HR cure check of sealant on panel 332BB on 2/27/26 at 2:30PM, Cure check good. REF: CL-650 SPM 51-23-00-390-801. Then removed panel as well as all tape.	B1018547 - Matthew Rossier Feb 27, 2026 09:44 PM	
	Perform 9HR cure check of sealant on panel 332BB on 2/27/26 at 12:30AM REF: CL-650 SPM 51-23-00-390-801 Remove panel as well as all tape.		B0161691 - Thomas Mitchell Feb 27, 2026 10:18 PM	
	200	Removed all tools, equipment, and unwanted materials from work area	B1018547 - Matthew Rossier Mar 03, 2026 01:21 AM	
	Remove all tools, equipment, and unwanted materials from work area		B0161691 - Thomas Mitchell Mar 03, 2026 01:31 AM	

Bombardier

Sequence #	0075	Aircraft SN #	6111	MWPWO #	2498069
WO #	4866456	Aircraft Reg #	XA-SOL	Parent WO #	2498069

0075	WO #	4866456	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13515841	No Log Entry	
L/H MLG Door Jumper Cable (CL650 AIPC 32-12-01 Fig 1 item 55 P/N M83413-8A-004BB) requires replacement.				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Removed torn L/H MLG door jumper cable and installed new jumper cable PN:M83413-8A-004BB ref. CL-650 SPM 51-80-00-400-801. See WO: 4755078 OP:500 for the installation of the LH MLG door and attachment of the jumper cable.	B0650736 - Jesus Gonzalez Atondo Mar 04, 2026 07:39 PM	
	L/H MLG Door Jumper Cable (CL650 AIPC 32-12-01 Fig 1 item 55 P/N M83413-8A-004BB) requires replacement.		B1013522 - Brandon Jennings Mar 04, 2026 08:29 PM	
	200	Removed all tools, equipment, and unwanted materials from the work area.	B0650736 - Jesus Gonzalez Atondo Mar 04, 2026 07:41 PM	
	Remove all tools, equipment, and unwanted materials from the work area.		B1013522 - Brandon Jennings Mar 04, 2026 08:29 PM	

TOOL INFORMATION

Tool ID	Tool Description	Calibration Due Date
TUSS3756	TORQUE WRENCH	Oct 30, 2026 5:00 PM

Sequence #	0076	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4882286	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

0076	**WO #**	**4882286**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #	13517704	No Log Entry	
During install found RH elevator outboard grounding stud on the airframe side loose see attachment for location.				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			
	During install found RH elevator outboard grounding stud on the airframe side loose see attachment for location.			

Sequence #	0077	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4882329	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

0077	**WO #**	**4882329**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #	13517747	No Log Entry	
During operational test of the engine fire / overheat detection system, found that the EICAS shows no indication of Left Jetpipe OVHT.				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Duplicate write up see work order 4700051 for Jet pipe overheat	B0161867 - Jeremy Kucera Mar 04, 2026 11:57 PM	
	During operational test of the engine fire / overheat detection system, found that the EICAS shows no indication of Left Jetpipe OVHT.		B0161691 - Thomas Mitchell Mar 05, 2026 03:32 AM	

Sequence #	0078	Aircraft SN #	6111	MWPWO #	2498069
WO #	4894804	Aircraft Reg #	XA-SOL	Parent WO #	2498069

0078	WO #	4894804	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13519096	No Log Entry	
Found that L/H actuator upper zerk fitting is requires replacement upon receiving actuator from overhaul.				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Removed L/H actuator upper damaged zerk fitting and installed new zerk fitting PN:AS15001-1U ref. CL-650 SPM 20-21-00-910-801.	B0650736 - Jesus Gonzalez Atondo Mar 06, 2026 05:47 PM	
	Found that L/H actuator upper zerk fitting is damaged requires replacement upon receiving actuator from overhaul.			
	200	Removed all tools, equipment, and unwanted materials from the work area.	B0650736 - Jesus Gonzalez Atondo Mar 06, 2026 05:47 PM	
	Remove all tools, equipment, and unwanted materials from the work area.			

TOOL INFORMATION

Tool ID	Tool Description	Calibration Due Date
TUSS3756	torque wrench	Oct 30, 2026 5:00 PM

Sequence #	1001	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	3303456	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

1001	**WO #**	**3303456**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #	13276352	No Log Entry	
Disable ADS-B by Pulling / Locking Out Transponder and GPS Circuit Breakers (REF RIL# BA-0004 Rev 3)				
Task / IRN # : RIL BA-0004 REV 3				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with Disabling ADS-B by pulling / locking out GPS/Transponder breakers (REF RIL# BA-0004 Rev 3)	B0641378 - Calvin Ambrose Feb 04, 2026 01:17 PM	05-00
	Disable ADS-B by pulling / locking out GPS breakers (REF RIL# BA-0004 Rev 3)		Not Required	
	200			34-00
	Enable ADS-B by pushing/ locking in GPS breakers			

Bombardier

Sequence #	1002	Aircraft SN #	6111	MWPWO #	2498069
WO #	2498400	Aircraft Reg #	XA-SOL	Parent WO #	2498069

1002	WO #	2498400	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13276288	No Log Entry	
Comply with FAR 91.411 and 91.413 requirements (in conjunction with 24 month inspection) (604/605/650)				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Defer work order per customer request/ Proposal. See attachment.	B0143855 - Marlon Zurita Feb 05, 2026 05:49 PM	05-00
	Perform Compliance with FAR 91.411 and 91.413 requirements		B0161691 - Thomas Mitchell Feb 14, 2026 04:30 AM	
	200	FAR 91.411 and 91.413 previously complied with. REF CL-650 AMM 34-54-01-820-801 and CL-650 AMM 34-12-00-820-801. See Centro De Servicios De Aviacion Ejecutiva, S.A. DE C.V. Log Book Entry Dated January 20'th 2026 for work performed.	B0641378 - Calvin Ambrose Mar 02, 2026 05:10 PM	
	Comply with FAR 91.411 and 91.413 requirements (in conjunction with 24 month inspection) (604/605/650)		B1017318 - Steve Pritchett Mar 02, 2026 07:53 PM	

Sequence #	1003	Aircraft SN #	6111	MWPWO #	2498069
WO #	2498435	Aircraft Reg #	XA-SOL	Parent WO #	2498069

1003	WO #	2498435	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13276313	No Log Entry	
Functional Test of the Air Data Computer (ADC)(RVSM Qualified A/C)				
Task / IRN # : 34-13-00-102				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Defer work order per customer request/ Proposal. See attachment.	B0143855 - Marlon Zurita Feb 05, 2026 05:52 PM	34-10
	Functional Test of the Air Data Computer (ADC) (RVSM Qualified A/C)		B1017318 - Steve Pritchett Feb 10, 2026 08:54 PM	
	200	Previously Complied with TLMC Task 34-13-00-102, Functional Test of the Air Data Computer (ADC)(RVSM Qualified A/C). REF CL-650 AMM 34-13-00-720-809. See Centro De Servicios De Aviacion Ejecutiva, S.A. DE C.V. Log Book Entry Dated January 20'th 2026 for work performed.	B0641378 - Calvin Ambrose Mar 02, 2026 05:15 PM	
	Comply with Functional Test of the Air Data Computer (ADC)(RVSM Qualified A/C)		B1017318 - Steve Pritchett Mar 02, 2026 07:57 PM	

Sequence #	1004	Aircraft SN #	6111	MWPWO #	2498069
WO #	2498463	Aircraft Reg #	XA-SOL	Parent WO #	2498069

1004	WO #	2498463	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13276308	Complied with Task 24-00-00-301 - Ops Test (Cycling) of the the Thermal Circuit Breakers IAW CL-650 AMM 24-00-00-710-801 Test Good.	
Operational Test (Cycling) of the Thermal Circuit Breaker				
Task / IRN # : 24-00-00-301				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 24-00-00-301 ops test (Cycling) of the the thermal circuit breakers IAW CL-650 AMM 24-00-00-710-801 Test good	B0619443 - Tyler Herrera Feb 06, 2026 04:30 PM	24-00
	Perform Operational Test (Cycling) of the Thermal Circuit Breaker		B1013522 - Brandon Jennings Feb 06, 2026 04:47 PM	
	200	Removed tools and equipment from aircraft	B0619443 - Tyler Herrera Feb 06, 2026 04:30 PM	
	Remove tools and equipment		B1013522 - Brandon Jennings Feb 06, 2026 04:47 PM	

Sequence #	1005	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503620	Aircraft Reg #	XA-SOL	Parent WO #	2498069

1005	WO #	2503620	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13276309	Complied with Task 31-41-00-202 - Operational Test of the Audio Warning Control Panel Ref CL 650 AMM 31-51-01-710-801. Operational Test Good.	
Operational Test of the Audio Warning Control Panel				
Task / IRN # : 31-41-00-202				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 31-41-00-202 Operational Test of the Audio Warning Control Panel Ref CL 650 AMM 31-51-01-710-801. Operational Test Good	B0629148 - Robert Greaves Feb 06, 2026 03:51 AM	31-50
	Perform Operational Test of the Audio Warning Control Panel		B0623124 - Michael Stacy Feb 06, 2026 04:21 AM	
	200	Removed all tools, equipment and unwanted materials from the work area	B0629148 - Robert Greaves Feb 06, 2026 03:51 AM	
	Remove all tools, equipment and unwanted materials from the work area		B0623124 - Michael Stacy Feb 06, 2026 04:21 AM	

Bombardier

Sequence #	1006	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503644	Aircraft Reg #	XA-SOL	Parent WO #	2498069

1006	WO #	2503644	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13276318	No Log Entry	
34-CARS-625-14 - Test ATC Transponders 0 24 Month				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Defer work order per customer request/ Proposal. See attachment.	B0143855 - Marlon Zurita Feb 05, 2026 07:12 PM	
	Perform test and inspection of the ATC transponder system per 34-CARS-625-14.		B0142244 - Todd Bridges Feb 07, 2026 08:10 PM	
	200	Previously Complied with 34-CARS-625-14 - Test ATC Transponders 0 24 Month. See Centro De Servicios De Aviacion Ejecutiva, S.A. DE C.V. Log Book Entry Dated January 20'th 2026 for work performed.	B0641378 - Calvin Ambrose Mar 02, 2026 05:20 PM	
	Comply with 34-CARS-625-14 - Test ATC Transponders 0 24 Month		B1017318 - Steve Pritchett Mar 02, 2026 08:02 PM	

Bombardier

Sequence #	1007	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503646	Aircraft Reg #	XA-SOL	Parent WO #	2498069

1007	WO #	2503646	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13276307	No Log Entry	
34-CARS-625-13 - Check Altimeter Devices - 24 Month				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Defer work order per customer request/ Proposal. See attachment.	B0143855 - Marlon Zurita Feb 05, 2026 07:16 PM	
	Perform Functional check altimeter system test and inspection.		B0142244 - Todd Bridges Feb 07, 2026 08:04 PM	
	200	Previously Complied with 34-CARS-625-13 - Check Altimeter Devices - 24 Month. See Centro De Servicios De Aviacion Ejecutiva, S.A. DE C.V. Log Book Entry Dated January 20'th 2026 for work performed.	B0641378 - Calvin Ambrose Mar 02, 2026 05:18 PM	
	Comply with 34-CARS-625-13 - Check Altimeter Devices - 24 Month		B1017318 - Steve Pritchett Mar 02, 2026 08:00 PM	

Bombardier

Sequence #	1008	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4294225	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

1008	**WO #**	**4294225**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #	13429568	No Log Entry	
*Entertainment - Replace the existing aircraft paint scheme with a new custom paint scheme on the Ni				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			25-00
	Entertainment - Replace the existing aircraft paint scheme with a new custom paint scheme on the Niceview splash screens			

Bombardier

Sequence #	1009	Aircraft SN #	6111	MWPWO #	2498069
WO #	4294308	Aircraft Reg #	XA-SOL	Parent WO #	2498069

1009	WO #	4294308	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13429570	No Log Entry	
*Entertainment - Replace the existing Blue ray player with repaired unit				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			25-00
	Entertainment - Replace the existing Blue ray player with repaired unit			

Bombardier

Sequence #	1010	Aircraft SN #	6111	MWPWO #	2498069
WO #	4550328	Aircraft Reg #	XA-SOL	Parent WO #	2498069

1010	WO #	4550328	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13485375	No Log Entry	
*Troubleshoot CMS issue- LHT Niceview Database requires frequent reloading(both front and aft monito				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Confirmed with Field Service Representative that the issue to be performed and tracked under this work order is the troubleshooting of both front and aft monitors loosing signal at random times. Intermittent issue. The section regarding LHT Niceview Database requires frequent reloading was entered in error. See attached email. See next operation for troubleshooting.	B0143855 - Marlon Zurita Feb 05, 2026 04:28 PM	25-00
	Troubleshoot CMS issue- LHT Niceview Database requires frequent reloading(both front and aft monitors loose signal)		B0143196 - Robert Bohner Feb 05, 2026 05:34 PM	
	101	Swapped J15, into J13 on the EIU 1 for troubleshooting purposes, after 40min of monitoring both FWD and Aft monitor, Monitor did not flicker or shutoff. Continue troubleshooting.	B1001648 - Steve Cardenas Feb 06, 2026 01:57 AM	
	Troubleshoot CMS issue- both front and aft monitors loosing signal at random times. Intermittent issue.		B0623124 - Michael Stacy Feb 06, 2026 03:32 AM	
	102			
	Troubleshoot CMS issue- both front and aft monitors loosing signal at random times. Intermittent issue.			

Bombardier

Sequence #	1011	Aircraft SN #	6111	MWPWO #	2498069
WO #	4700026	Aircraft Reg #	XA-SOL	Parent WO #	2498069

1011	WO #	4700026	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13491747	No Log Entry	
Comply with incoming Avionics cabin sweep. Report observations to CPM.				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with incoming Avionics cabin sweep. Reported observations to CPM.	B1001648 - Steve Cardenas Feb 04, 2026 04:24 AM	
	Comply with incoming Avionics cabin sweep. Report observations to CPM.		B0161691 - Thomas Mitchell Feb 04, 2026 05:09 AM	
	200	Removed all tools, equipment, and unwanted materials from the work area.	B1001648 - Steve Cardenas Feb 04, 2026 04:24 AM	
	Remove all tools, equipment, and unwanted materials from the work area.		B0161691 - Thomas Mitchell Feb 04, 2026 05:09 AM	

Sequence #	1012	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4700051	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

1012	**WO #**	**4700051**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #	13491643	No Log Entry	
Red Jet Pipe Pylon/ LHS doesn't post during test. Troubleshoot and advise. Incoming customer reported discrepancy.				

Sequence #	1012	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4700051	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Performed Operational Test of the Engine Fire/ Overheat Detection-System, REF CL-650 AMM 26-11-00-710-801. Confirmed discrepancy while performing Procedure step (1)(a), when FIRE DET WARN/FAIL toggle switch was held on the WARN position, Red L JETPIPE OVHT message did not appear on the EICAS. Gained access to panels Aft CoPilot side panel (222CZ) and RH 280 Bulkhead panel (222DRW) for additional access. Disconnected connector (1P2WC) from LH JETPIPE FIRE DETECTION UNIT. Checked for voltage on connector (1P2WC) pin(A) and measured 26.6 VDC. Checked for voltage on connector (1P2WC) pin(C) and measured 0.09 VDC. Confirmed continuity on connector (1P2WC) pin(E) and pin(B), measuring 101.6 ohms on E and 1.0 ohms on B. Applying ground to connector (1P2WC) pin(F) displayed an AMBER JET PIPE OVHT FAIL. Gained Access to JB8 by removing Jepp box panel (221CLF). Disconnected JB8 connector P209 and tested continuity between LH JETPIPE FIRE DETECTION UNIT connector (1P2WC) pin(c) and JB8 connector (P209) pin(23), measured 1.4 Ohms. Ordered new LH JETPIPE FIRE DETECTION UNIT PN: 377-02836 Continue Troubleshooting by replacing LH JETPIPE FIRE DETECTION UNIT	B0641378 - Calvin Ambrose Feb 05, 2026 08:34 PM	
	Red Jet Pipe Pylon/ LHS doesn't post during test. Troubleshoot and advise. Incoming customer reported discrepancy.		B0143196 - Robert Bohner Feb 05, 2026 08:38 PM	

Sequence #	1012	Aircraft SN #	6111	MWPWO #	2498069
WO #	4700051	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	101	Continuing to troubleshoot LH Jet pipe overheat detection IAW CL650 AMM Task 26-11-00-710-801, Swapped Jet pipe detection unit connectors 1P2WC and 2P2WC. Performed OPS test Jet pipe overheat detection, problem remained on the LH side determined detection unit checked OK. Returned connectors for the Jet pipe overheat detection unit back to normal configuration. Continuing to troubleshoot, rang out wiring from LH Jet pipe detection connector 1P2WC pin D and H. found across Jet pipe/ Pylon detection sensor were only reading 8.8 Megohms. Removed connectors at Jet pipe detection sensor and rang out wiring from LH detection unit to Jet pipe. Found LH Jet pipe connector P41EZ was reading intermittently with meter. Was able to get a good reading when wire was pushed into the connector. Jet pipe detection connector P41EZ requires replacement.	B0141003 - Francisco Ayon Mar 02, 2026 05:29 PM	
	Continue Troubleshooting by replacing LH JETPIPE FIRE DETECTION UNIT		B1013522 - Brandon Jennings Mar 02, 2026 05:45 PM	
	200			
	Perform Operational Test of JB8. REF CL-650 AMM 24-01-08-710-801			
	300			
	Replace LH Jet pipe FENWAL Connector P41EZ IAW Bombardier SPM CH 20-20-70.			

TOOL INFORMATION

Tool ID	Tool Description	Calibration Due Date
TUSS1026	Multimeter	Apr 29, 2026 5:00 PM
TUSS4135	Multi-Meter	May 30, 2026 5:00 PM

Sequence #	1013	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4700061	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

1013	**WO #**	**4700061**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #	13491644	No Log Entry	
Unable to fuel aircraft up with cockpit panel only. Fuel Control panel located in cockpit must be turned off in order to be able to properly fuel aircraft with the outside panel. Troubleshoot and advise. Customer reported incoming discrepancy.				

Sequence #	1013	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4700061	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Performed electrical operational check of both Refuel/ Defuel panels IAW CL650 AMM Task 28-25-00-710-801 and wiring diagram 28-41-00. With meter, checked voltage outputs from Refuel/ Defuel panels with or without Refuel/ Defuel Shutoff valves selected. IAW wiring Diagram 28-41-00 monitored voltages at TB module TB446. Was able to verify power with either panel switch selection to each refuel valve, all voltages checked good. Verified transfer of power and commands to refuel/ defuel valves when selecting cockpit refuel/ defuel to the ON position. Verified overwing Refuel/ Defuel panel was inhibited. When cockpit Refuel/ Defuel panel was turned off, power to overwing Refuel/ Defuel panel was restored. Talking further with the customer, issue is only occurring when fueling process to the aircraft via the cockpit refuel/ defuel panel was interrupted. When trying to resume the fueling process, the fueling process could not be reestablished with the cockpit refuel/ defuel panel. The refueling process was then reestablished utilizing the overwing refuel/ defuel panel. Customer is requesting replacement of cockpit refuel/ defuel panel.	B0141003 - Francisco Ayon Feb 11, 2026 08:15 PM	
	Unable to fuel aircraft up with cockpit panel only. Fuel Control panel located in cockpit must be turned off in order to be able to properly fuel aircraft with the outside panel. Troubleshoot and advise. Customer reported incoming discrepancy.		B1017318 - Steve Pritchett Feb 11, 2026 09:25 PM	
	101			
	Continue to troubleshoot fueling issue by removing and replacing cockpit refuel/ defuel panel IAW CL650 SMM Task 28-41-01-000-801 and 28-41-01-400-801.			

TOOL INFORMATION

Tool ID	Tool Description	Calibration Due Date
TUSS4135	Multi-Meter	May 30, 2026 5:00 PM

Sequence #	1014	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4713578	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

1014	**WO #**	**4713578**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #	13493384	No Log Entry	
LH Seat 4 (inboard): Headphone audio is only heard in the left earcup. Troubleshoot and advise.				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			
	LH Seat 4 (inboard): Headphone audio is only heard in the left earcup. Troubleshoot and advise.			

Bombardier

Sequence #	1015	Aircraft SN #	6111	MWPWO #	2498069
WO #	4713581	Aircraft Reg #	XA-SOL	Parent WO #	2498069

1015	WO #	4713581	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13493505	No Log Entry	
Upwash lights: Lights did not turn off or dim when commanded. Troubleshoot and advise.				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with Up-wash lights OP check IAW CL650 SMM Task 33-20-00-710-801. With MISC LIGHTING CONTROL PANEL CABIN switch set to NORM, was able to select UPWASH Lights ON/ OFF and Bright and DIM from the galley or VIP touch screens. UPWASH Lights OP checked good.	B0141003 - Francisco Ayon Feb 09, 2026 08:24 PM	
	Upwash lights: Lights did not turn off or dim when commanded. Troubleshoot and advise.		B1019908 - Joseph Barnes Feb 09, 2026 08:30 PM	
	200	Removed all tools, equipment, and unwanted materials from the work area.	B0141003 - Francisco Ayon Feb 09, 2026 08:24 PM	
	Remove all tools, equipment, and unwanted materials from the work area.		B1019908 - Joseph Barnes Feb 09, 2026 08:30 PM	

Bombardier

Sequence #	1016	Aircraft SN #	6111	MWPWO #	2498069
WO #	4713634	Aircraft Reg #	XA-SOL	Parent WO #	2498069

1016	WO #	4713634	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13493404	No Log Entry	
LH Seat 2 CMS touchscreen: Intermittently power cycled after approximately 10 minutes. Required a reboot from the galley touchscreen. (Occurred twice, then remained stable.)				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Trouble shot LH# 2 seat CMS touch screen IAW CL650 SMM Task 44-10-00-710-801. With Cabin Management System powered up for more than 10 minutes, touch screen stayed on and did not reboot. Shook all associated harness to the touch screen and panel never rebooted. Monitored touch screen for 1 hour and CMS Touch Screen never rebooted.	B0141003 - Francisco Ayon Feb 10, 2026 08:27 PM	
	LH Seat 2 CMS touchscreen: Intermittently power cycled after approximately 10 minutes. Required a reboot from the galley touchscreen. (Occurred twice, then remained stable.)		B1013522 - Brandon Jennings Feb 10, 2026 08:35 PM	
	101			
	Continue Troubleshooting LH Seat 2 CMS touchscreen.			

Bombardier

Sequence #	1017	Aircraft SN #	6111	MWPWO #	2498069
WO #	4713795	Aircraft Reg #	XA-SOL	Parent WO #	2498069

1017	WO #	4713795	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13493477	No Log Entry	
Microwave intermittent heating. Seems the microwave is not functioning well. Customer reported discrepancy.				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			
	Microwave intermittent heating. Seems the microwave is not functioning well. Customer reported discrepancy.			

Bombardier

Sequence #	1018	Aircraft SN #	6111	MWPWO #	2498069
WO #	4715617	Aircraft Reg #	XA-SOL	Parent WO #	2498069

1018	WO #	4715617	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13493710	No Log Entry	
further evaluation required to determin servicability of both pitot static probes and the pitot static head due to dents in the inlet.				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Performed Detailed Inspection of the Pitot-Static Probes, REF CL-650 AMM 34-11-00-220-801. Evaluated LH and RH Pitot Static Probes and Standby Pitot Head. See Below for observations noted. On LH Pitot Static Probe opening, visually noted a dent on the 12 o'clock position, measured (0.2 mm) and does not exceed the (0.762 mm, See Procedure Step 1.(i) NOTE 1). LH Pitot Static Probe is serviceable On RH Pitot Static Probe opening visually noted 2 dents around the 1 o'clock and 3 o'clock positions. Dents measured (.0.21 mm) and (0.29 mm) and do not exceed the (0.762 mm), but appear to exceed 20% of the lip circumference (See Procedure Step 1.(i) NOTE 2. Recommend new RH Pitot Static Probe, See Finding 79876 for RH Pitot Static Probe discrepancy found. On Standby Pitot Head opening, visually noted 2 dents on the 12 o'clock position and on 5 o'clock position. Dents measured (0.538 mm) and (0.218 mm) and do not exceed the (1.524 mm) of the normal tip diameter, but the dents appear to exceed 20% of the lip circumference (See Procedure Step 2.(e) NOTE 2). Recommend new Standby Pitot Head, See Finding 79877 for Standby Pitot Head discrepancy found.	B0641378 - Calvin Ambrose Feb 11, 2026 05:29 PM	
	further evaluation required to determin servicability of both pitot static probes and the pitot static head due to dents in the inlet.		B1013522 - Brandon Jennings Feb 11, 2026 05:42 PM	
	200	Complied with removal of all tools, equipment, and unwanted materials from the work area	B0641378 - Calvin Ambrose Feb 11, 2026 05:29 PM	
	Comply with removal of all tools, equipment, and unwanted materials from the work area		B1013522 - Brandon Jennings Feb 11, 2026 05:42 PM	

Bombardier

Sequence #	1018	Aircraft SN #	6111	MWPWO #	2498069
WO #	4715617	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work

FINDINGS DETAILS

Finding #	Long Description	Status	Reported By / Date	Defect Source / Disposition	Defect Type	Priority	Follow-up WO #
79876	RH Pitot Static Probe dents exceed 20% of lip circumference. While Performing Detailed Inspection of the Pitot-Static Probes, REF CL-650 AMM 34-11-00-220-801. Evaluated LH and RH Pitot Static Probes and Standby Pitot Head. On RH Pitot Static Probe opening visually noted 2 dents around the 1 o'clock and 3 o'clock positions. Dents measured (.0.21 mm) and (0.29 mm) and do not exceed the (0.762 mm), but appear to exceed 20% of the lip circumference. (Step 1.(i) NOTE 2. RH PITOT STATIC PROBE Model 0856KV10 / SN: 303122	CLOSED	B0641378 - Calvin Ambrose Feb 11, 2026 10:08 AM	MAINTENANCE 300-QA002	OTHER	3	4757843-INPRG
79877	Standby Pitot Static Probe dent exceeds 20% of the lip circumference. While Performing Detailed Inspection of the Pitot-Static Probes, REF CL-650 AMM 34-11-00-220-801. Evaluated LH and RH Pitot Static Probes and Standby Pitot Head. On Standby Pitot Head opening, visually noted 2 dents on the 12 o'clock position and on 5 o'clock position. Dents measured (0.538 mm) and (0.218 mm) and do not exceed the (1.524 mm) of the normal tip diameter, but the dents appear to exceed 20% of the lip circumference (Step 2. (e) NOTE 2). STANDBY PITOT STATIC PROBE MODEL 0851HF / SN:362843	CLOSED	B0641378 - Calvin Ambrose Feb 11, 2026 10:14 AM	MAINTENANCE 300-QA002	OTHER	3	4757582-INPRG

TOOL INFORMATION

Tool ID	Tool Description	Calibration Due Date
TUSS2883	Digital Caliper	Feb 27, 2027 5:00 PM

Bombardier

Sequence #	1019	Aircraft SN #	6111	MWPWO #	2498069
WO #	4755476	Aircraft Reg #	XA-SOL	Parent WO #	2498069

1019	WO #	4755476	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13499325	No Log Entry	
Found shield terminal lug broken on ELT connector when removing ELT for battery inspection.				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Replaced Shield terminal lug on ELT connector and resecured to aircraft ground lug. Work done with ref to drawing 25-62-00 and CL-650 SPM 2-16-20-02	B0619443 - Tyler Herrera Feb 13, 2026 02:20 PM	
	Found shield terminal lug broken on ELT connector when removing ELT for battery inspection.		B1019908 - Joseph Barnes Feb 13, 2026 09:20 PM	
	101	Replaced Shield terminal lug on ELT connector and resecured to aircraft ground lug. Work done with ref to drawing 25-62-00 and CL-650 SPM 20-16-20-02	B0619443 - Tyler Herrera Feb 13, 2026 02:28 PM	
	Admin correction to correct SPM ref		B1019908 - Joseph Barnes Feb 13, 2026 09:20 PM	
	200	Removed tools and equipment from aircraft	B0619443 - Tyler Herrera Feb 13, 2026 02:20 PM	
	Remove tools and equipment from aircraft		B1019908 - Joseph Barnes Feb 13, 2026 09:20 PM	

TOOL INFORMATION

Tool ID	Tool Description	Calibration Due Date
TUSJ2123	Green lug crimper	Jul 30, 2026 5:00 PM

Sequence #	1020	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4757407	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

1020	**WO #**	**4757407**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #	13499638	No Log Entry	
Comply with update of Nav databases. (If applicable- Jepp, FMS, Emaps, Graphical, SVS).				

OPERATIONAL DETAILS

	Operation # / **Operation Description**	**Corrective Action Long Description**	**Tech Sign Off** / **Insp Sign Off**	**ATA Code** / **Reason for Work**
	100	Entered in Error. Customer to Update the aircraft's Nav Databases after Aircraft is RTS. No further action required.	B0143855 - Marlon Zurita Feb 11, 2026 09:09 PM	
	Comply with update of Nav databases. (If applicable- Jepp, FMS, Emaps, Graphical, SVS).		B0161691 - Thomas Mitchell Feb 14, 2026 04:37 AM	

Sequence #	1021	Aircraft SN #	6111	MWPWO #	2498069
WO #	4757582	Aircraft Reg #	XA-SOL	Parent WO #	2498069

1021	WO #	4757582	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13499671	No Log Entry	
Standby Pitot Static Probe dent exceeds 20% of the lip circumference. While Performing Detailed Inspection of the Pitot-Static Probes, REF CL-650 AMM 34-11-00-220-801. Evaluated LH and RH Pitot Static Probes and Standby Pitot Head. On Standby Pitot Head opening, visually noted 2 dents on the 12 o'clock position and on 5 o'clock position. Dents measured (0.538 mm) and (0.218 mm) and do not exceed the (1.524 mm) of the normal tip diameter, but the dents appear to exceed 20% of the lip circumference (Step 2.(e) NOTE 2). STANDBY PITOT STATIC PROBE MODEL 0851HF / SN:362843				
CRITICAL MAINTENANCE TASK				

Bombardier

Sequence #	1021	Aircraft SN #	6111	MWPWO #	2498069
WO #	4757582	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			
	Standby Pitot Static Probe dent exceeds 20% of the lip circumference. While Performing Detailed Inspection of the Pitot-Static Probes, REF CL-650 AMM 34-11-00-220-801. Evaluated LH and RH Pitot Static Probes and Standby Pitot Head. On Standby Pitot Head opening, visually noted 2 dents on the 12 o'clock position and on 5 o'clock position. Dents measured (0.538 mm) and (0.218 mm) and do not exceed the (1.524 mm) of the normal tip diameter, but the dents appear to exceed 20% of the lip circumference (Step 2.(e) NOTE 2). STANDBY PITOT STATIC PROBE MODEL 0851HF / SN:362843			
	200	Removed Standby Pitot Static Probe. REF CL-650 AMM 34-11-04-000-801	B0641378 - Calvin Ambrose Feb 16, 2026 02:28 PM	
	Remove Standby Pitot Static Probe. REF CL-650 AMM 34-11-04-000-801		Not Required	
	300	Installed NEW Standby Pitot Static Probe. REF CL-650 AMM 34-11-04-400-801. Bond Test Good (Measured 0.01 Ohms). See Operation 400 for Op Test of the Air Data Sensors Anti-Ice System, and Operation 500 for Leak Test of the P3 and S3 System.	B0641378 - Calvin Ambrose Feb 16, 2026 07:09 PM	
	Install NEW Standby Pitot Static Probe. REF CL-650 AMM 34-11-04-400-801		B1019908 - Joseph Barnes Feb 16, 2026 08:22 PM	
	400			
	Perform Operational Test of the Air Data Sensors Anti-Ice System, REF CL-650 AMM 30-31-00-710-801			
	500			
	Do a leak test of the P3 and S3 Systems. REF CL-650 AMM 34-11-00-790-803			

Sequence #	1021	Aircraft SN #	6111	MWPWO #	2498069
WO #	4757582	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	600	Removed NEW Standby Pitot Static Probe to FOM. REF CL-650 AMM 34-11-04-000-801 PN:0851HF SN:469787	B0641378 - Calvin Ambrose Feb 18, 2026 08:02 PM	
	Remove NEW Standby Pitot Static Probe to FOM. REF CL-650 AMM 34-11-04-000-801		Not Required	
CMT	700	Installed the previously removed NEW Standby Pitot Static Probe. REF CL-650 AMM 34-11-04-400-801 and CMT Working Copy Dated FEB-18-2026. Bond Test Good (Measured 0.01 Ohms). See Operation 400 and CMT Working Copy Dated FEB-23-2026 for Operational Test of Air Data Sensors Anti-Ice System. See Operation 500 and CMT Working Copy Dated FEB-23-2026 for Leak Test of the P3 and S3 Systems.	B0641378 - Calvin Ambrose Feb 23, 2026 08:21 PM	
	Install the previously removed NEW Standby Pitot Static Probe. REF CL-650 AMM 34-11-04-400-801		B1013522 - Brandon Jennings Feb 23, 2026 08:35 PM	
	800	Removed the clamp around the Standby Pitot Static Probe pressure line to FOM, by removing the screw from the clamp.	B0641378 - Calvin Ambrose Feb 23, 2026 08:50 PM	
	Remove the clamp around the Standby Pitot Static Probe pressure line to FOM.		Not Required	
	900			
	Install the clamp around the Standby Pitot Static Probe pressure line.			

Sequence #	1021	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4757582	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

REMOVE AND RE-INSTALL DETAILS

	Removed Part # Removed Serial #	Removed By	Removed - Part Description	Reference	Installed Part # Installed Serial #	Installed By
	Removed Status	**Removed Date-Time**	**Position**	**Installed Part Status**	**Installed Part Description**	**Installed Date-Time**
	0851HF 362843	B0641378 - Calvin Ambrose	PROBE, 3RD PITOT STATIC	REF CL-650 AMM 34-11-04-000-801	0851HF 469787	B0641378 - Calvin Ambrose
	UNSERVICEABLE	Feb 16, 2026 6:57 AM	STANDBY	NEW	PROBE, 3RD PITOT STATIC	Feb 16, 2026 11:07 AM
	0851HF 469787	B0641378 - Calvin Ambrose	PROBE, 3RD PITOT STATIC	REF CL-650 AMM 34-11-04-000-801	0851HF 469787	B0641378 - Calvin Ambrose
	SERVICEABLE	Feb 18, 2026 12:46 PM	STANDBY	NEW	PROBE, 3RD PITOT STATIC	Feb 23, 2026 1:00 PM

TOOL INFORMATION

Tool ID	Tool Description	Calibration Due Date
TUSS0607	Bond Tester	Jan 30, 2027 5:00 PM
TUSS2243	Torque Wrench	Dec 30, 2026 5:00 PM
TUSS2040	Torque Wrench	Dec 30, 2026 5:00 PM
TUSS0607	BOND TESTER	Jan 30, 2027 5:00 PM
TUSS4982	Torque Wrench	Jul 30, 2026 5:00 PM
TUSS159G	Torque Wrench	Oct 30, 2026 5:00 PM

Sequence #	1022	Aircraft SN #	6111	MWPWO #	2498069
WO #	4757843	Aircraft Reg #	XA-SOL	Parent WO #	2498069

	WO #	4757843	LOG BOOK VERBIAGE	Deferrals
1022	SAP SVO #	13499684	RH Pitot Static Probe dents exceed 20% of lip circumference. While Performing Detailed Inspection of the Pitot-Static Probes, REF CL-650 AMM 34-11-00-220-801. Evaluated LH and RH Pitot Static Probes and Standby Pitot Head. On RH Pitot Static Probe opening visually noted 2 dents around the 1 o'clock and 3 o'clock positions. Dents measured (.0.21 mm) and (0.29 mm) and do not exceed the (0.762 mm), but appear to exceed 20% of the lip circumference. (Step 1.(i) NOTE 2. RH PITOT STATIC PROBE Model 0856KV10 / SN: 303122	
RH Pitot Static Probe dents exceed 20% of lip circumference. While Performing Detailed Inspection of the Pitot-Static Probes, REF CL-650 AMM 34-11-00-220-801. Evaluated LH and RH Pitot Static Probes and Standby Pitot Head. On RH Pitot Static Probe opening visually noted 2 dents around the 1 o'clock and 3 o'clock positions. Dents measured (.0.21 mm) and (0.29 mm) and do not exceed the (0.762 mm), but appear to exceed 20% of the lip circumference. (Step 1.(i) NOTE 2. RH PITOT STATIC PROBE Model 0856KV10 / SN: 303122				
CRITICAL MAINTENANCE TASK				

Sequence #	1022	Aircraft SN #	6111	MWPWO #	2498069
WO #	4757843	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			
	RH Pitot Static Probe dents exceed 20% of lip circumference. While Performing Detailed Inspection of the Pitot-Static Probes, REF CL-650 AMM 34-11-00-220-801. Evaluated LH and RH Pitot Static Probes and Standby Pitot Head. On RH Pitot Static Probe opening visually noted 2 dents around the 1 o'clock and 3 o'clock positions. Dents measured (.0.21 mm) and (0.29 mm) and do not exceed the (0.762 mm), but appear to exceed 20% of the lip circumference. (Step 1.(i) NOTE 2. RH PITOT STATIC PROBE Model 0856KV10 / SN: 303122			
	200	Removed RH Pitot Static Probe. REF CL-650 AMM 34-11-01-000-801.	B0641378 - Calvin Ambrose Feb 17, 2026 04:49 PM	
	Remove RH Pitot Static Probe. REF CL-650 AMM 34-11-01-000-801.		Not Required	
CMT	300	Installed NEW RH Pitot Static Probe. REF CL-650 AMM 34-11-01-400-801 and CMT Working Copy Dated FEB-17-2026. Bond Check Good (Measured 0.1 Ohms). See Operation 400 and CMT Working Copy Dated FEB-17-2026 for Alignment Check of the Pitot Static Probes. See Operation 500 and CMT Working Copy Dated FEB-23-2026 for Op Test of the Air Date Sensors Anti-Ice System. See Operation 600 and CMT Working Copy Dated FEB-17-2026 for Leak Test of the P1 and Pilot's S1 and Co-Pilot's S2 Systems. See Operation 700 and CMT Working Copy Dated FEB-17-2026 for Leak Test of the P2 and Pilot's S2 and Co-Pilot's S1 Systems.	B0641378 - Calvin Ambrose Feb 27, 2026 06:54 PM	
	Install RH Pitot Static Probe. REF CL-650 AMM 34-11-01-400-801.		B1013522 - Brandon Jennings Feb 27, 2026 07:26 PM	

Sequence #	1022	Aircraft SN #	6111	MWPWO #	2498069
WO #	4757843	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
CMT	400	Performed Alignment Check of the RH Pitot Static Probe. REF CL-650 AMM 34-11-01-820-801 and CMT Working Copy Dated FEB-17-2026. Steps D.(1) through D.(3) are N/A, only the Co-pilot Pitot-Static Probe was replaced. Recorded Angle is (5.1 degrees down). Alignment Check Good.	B0641378 - Calvin Ambrose Feb 27, 2026 06:54 PM	
	Perform Alignment Check of the RH Pitot Static Probe. REF CL-650 AMM 34-11-01-820-801		B1013522 - Brandon Jennings Feb 27, 2026 07:26 PM	
	500			
	Perform Operational Test of the Air-Data-Sensors Anti-Ice System. REF CL-650 AMM 30-31-00-710-801			
	600			
	Perform Leak Test of the P1 and pilot's S1 and copilot's S2 Systems. REF CL-650 AMM 34-11-00-790-801			
	700			
	Perform Leak Test of the P2 and pilot's S2 and copilot's S1 Systems. REF CL-650 AMM 34-11-00-790-802			
	800	Loosened Wire Harnesses near the RH Pitot Static Probe pressure lines to FOM. REF Bombardier SPM 20-12-00	B0641378 - Calvin Ambrose Feb 17, 2026 07:57 PM	
	Loosen Wire Harnesses near the RH Pitot Static pressure lines to FOM. REF Bombardier SPM 20-12-00		Not Required	
	900	Complied with Securing the loosened Wire Harness near the RH Pitot Static Pressure lines. REF Bombardier SPM 20-12-00-02.	B0641378 - Calvin Ambrose Feb 27, 2026 02:52 PM	
	Secure Loosened Wire Harnesses near the RH Pitot Static pressure lines. REF Bombardier SPM 20-12-00		B1013522 - Brandon Jennings Feb 27, 2026 03:27 PM	

Sequence #	1022	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4757843	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

REMOVE AND RE-INSTALL DETAILS

	Removed Part # Removed Serial #	Removed By	Removed - Part Description	Reference	Installed Part # Installed Serial #	Installed By
	Removed Status	**Removed Date-Time**	**Position**	**Installed Part Status**	**Installed Part Description**	**Installed Date-Time**
	0856KV10 303122	B0641378 - Calvin Ambrose	PROBE, PITOT STATIC, RVSM, RH	CL-650 AMM 34-11-01-000-801	0856KV10 335781	B0641378 - Calvin Ambrose
	UNSERVICEABLE	Feb 17, 2026 8:59 AM	RIGHT	NEW	PROBE, PITOT STATIC, RVSM, RH	Feb 27, 2026 10:40 AM

TOOL INFORMATION

Tool ID	Tool Description	Calibration Due Date
TUSS4000	Torque Screwdriver	Oct 30, 2026 5:00 PM
TUSS2243	Torque Wrench	Dec 30, 2026 5:00 PM
TUSS4478	Inclinometer - Digital	Mar 30, 2026 5:00 PM
TUSS0607	Bond Tester	Jan 30, 2027 5:00 PM

Sequence #	1023	Aircraft SN #	6111	MWPWO #	2498069
WO #	4767693	Aircraft Reg #	XA-SOL	Parent WO #	2498069

1023	WO #	4767693	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13501916	No Log Entry	
RH Flap Position Transmitter connector P8CG back shell ground tab is broken. PN: 450FS005NF12				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Replaced broken P8CG backshell by disconnecting the P8CG connector from the RH Flap Position Transmitter and installing a NEW P8CG connector backshell (PN: 450FS005NF12), reconnected P8CG connector with NEW backshell to RH Flap Position Transmitter. REF CL-650 AMM 27-55-01-000-801 and Bombardier SPM 20-20-01. See Operation 200 for Op Testing of the Flap Position Transmitter.	B0641378 - Calvin Ambrose Feb 19, 2026 02:23 PM	
	RH Flap Position Transmitter connector P8CG back shell ground tab is broken. PN: 450FS005NF12		B1013522 - Brandon Jennings Feb 19, 2026 02:36 PM	
	101	Replaced broken P8CG backshell by disconnecting the P8CG connector from the RH Flap Position Transmitter and installing a NEW P8CG connector backshell (PN: 450FS005NF12), reconnected P8CG connector with NEW backshell to RH Flap Position Transmitter. REF CL-650 AMM 27-55-01-000-801 / CL-650 AMM 27-55-01-400-801 and Bombardier SPM 20-20-01. See Operation 200 for Op Testing of the Flap Position Transmitter.	B0641378 - Calvin Ambrose Feb 19, 2026 02:41 PM	
	RH Flap Position Transmitter connector P8CG back shell ground tab is broken. PN: 450FS005NF12		B1013522 - Brandon Jennings Feb 19, 2026 02:44 PM	09
	200	Performed Operational Test of the Flap Position Transmitter. REF CL-650 AMM 27-55-01-710-801, system op checks good.	B1001648 - Steve Cardenas Mar 05, 2026 04:28 AM	
	Perform Operational Test of the Flap Position Transmitter. REF CL-650 AMM 27-55-01-710-801		B0161691 - Thomas Mitchell Mar 05, 2026 05:34 AM	

Bombardier

Sequence #	1024	Aircraft SN #	6111	MWPWO #	2498069
WO #	4795513	Aircraft Reg #	XA-SOL	Parent WO #	2498069

1024	WO #	4795513	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13506603	No Log Entry	
Under floor panel 232 MRF found a wire insulation to be torn and core wire is exposed. Evaluate.				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Evaluated the damaged wire (2EC21B20) twisted shielded, noted the exterior insulation. Noted that the location of the damage appeared to line up with a nutplate above for panel 232MRF. Visually inspected the exposed metallic beneath the exterior insulation, noted no frayed strands or broken strands on the shield braid. No damage to the two core wires was noted. Repaired damage to the wire exterior insulation. REF Bombardier SPM 20-12-10-02.	B0641378 - Calvin Ambrose Feb 20, 2026 03:17 PM	
	Under floor panel 232 MRF found a wire insulation to be torn and core wire is exposed		B1013522 - Brandon Jennings Feb 20, 2026 04:33 PM	
	200	Complied with removal of all tools, equipment, and unwanted materials from the work area	B0641378 - Calvin Ambrose Feb 20, 2026 02:57 PM	
	Comply with removal of all tools, equipment, and unwanted materials from the work area		B1013522 - Brandon Jennings Feb 20, 2026 04:33 PM	

Sequence #	1025	Aircraft SN #	6111	MWPWO #	2498069
WO #	4800910	Aircraft Reg #	XA-SOL	Parent WO #	2498069

1025	WO #	4800910	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13506671	No Log Entry	

Found 13 BAD static wicks.
1 at end cap of the right side horizontal stab PN 2-18SC1
1 at tail cone PN 2-17SC1
1 at LH MID winglet PN 2-11SC1
1 at LH wing OB PN 2-17SC1
3 at LH aileron PN 2-17SC1
3 at RH aileron PN 2-17SC1
1 at RH wing OB PN 2-17SC1
2 AT RH winglet MID and BOTTOM PN 2-11SC1.
All others within limits

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			
	Found 13 BAD static wicks. 1 at end cap of the right side horizontal stab PN 2-18SC1 1 at tail cone PN 2-17SC1 1 at LH MID winglet PN 2-11SC1 1 at LH wing OB PN 2-17SC1 3 at LH aileron PN 2-17SC1 3 at RH aileron PN 2-17SC1 1 at RH wing OB PN 2-17SC1 2 AT RH winglet MID and BOTTOM PN SC111SC1. All others within limits			

Bombardier

Sequence #	1026	Aircraft SN #	6111	MWPWO #	2498069
WO #	4804983	Aircraft Reg #	XA-SOL	Parent WO #	2498069

1026	WO #	4804983	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13506964	No Log Entry	
AFT Equipment Bay Mini QAR has a broken antenna.				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			
	AFT Equipment Bay Mini QAR has a broken antenna.			

Bombardier

Sequence #	1027	Aircraft SN #	6111	MWPWO #	2498069
WO #	4808182	Aircraft Reg #	XA-SOL	Parent WO #	2498069

1027	WO #	4808182	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13507421	No Log Entry	
ELPS Serial number 26450 Failed Cap check. Test attempted 3 times with no success. Recommend Power pack replacement.				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Work order created to track material and labor, See Maximo CSO WO 4757932 for work performed	B0629148 - Robert Greaves Mar 04, 2026 08:55 PM	
	ELPS Serial number 26450 Failed Cap check. Test attempted 3 times with no success. Recommend Power pack replacement.		B0161691 - Thomas Mitchell Mar 04, 2026 10:28 PM	
	200	Removed all tools, equipment, and unwanted materials from the work area	B0629148 - Robert Greaves Mar 04, 2026 08:55 PM	
	Remove all tools, equipment, and unwanted materials from the work area		B0161691 - Thomas Mitchell Mar 04, 2026 10:28 PM	

Sequence #	1028	Aircraft SN #	6111	MWPWO #	2498069
WO #	4808201	Aircraft Reg #	XA-SOL	Parent WO #	2498069

1028	WO #	4808201	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13507422	No Log Entry	
ELPS Serial number 26447 Failed Cap check. Test attempted 3 times with no success. Recommend Power pack replacement.				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Work order created to track material and labor, See Maximo CSO WO 4757921 for work performed	B0629148 - Robert Greaves Mar 04, 2026 08:53 PM	
	ELPS Serial number 26447 Failed Cap check. Test attempted 3 times with no success. Recommend Power pack replacement.		B0161691 - Thomas Mitchell Mar 04, 2026 10:14 PM	
	200	Removed all tools, equipment, and unwanted materials from the work area	B0629148 - Robert Greaves Mar 04, 2026 08:53 PM	
	Remove all tools, equipment, and unwanted materials from the work area		B0161691 - Thomas Mitchell Mar 04, 2026 10:14 PM	

Sequence #	1029	Aircraft SN #	6111	MWPWO #	2498069
WO #	4808216	Aircraft Reg #	XA-SOL	Parent WO #	2498069

1029	WO #	4808216	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13507423	No Log Entry	
ELPS Serial number 26449 Failed Cap check. Test attempted 3 times with no success. Recommend Power pack replacement.				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Work order created to track material and labor, See Maximo CSO WO 4757940 for work performed	B0629148 - Robert Greaves Mar 04, 2026 08:52 PM	
	ELPS Serial number 26449 Failed Cap check. Test attempted 3 times with no success. Recommend Power pack replacement.		B0161691 - Thomas Mitchell Mar 04, 2026 10:32 PM	
	200	Removed all tools, equipment, and unwanted materials from the work area	B0629148 - Robert Greaves Mar 04, 2026 08:52 PM	
	Remove all tools, equipment, and unwanted materials from the work area		B0161691 - Thomas Mitchell Mar 04, 2026 10:32 PM	

Sequence #	2001	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503654	Aircraft Reg #	XA-SOL	Parent WO #	2498069

2001	WO #	2503654	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13276320	600 HOUR Engine Inspection LH	
600 HOUR Engine Inspection LH				
Task / IRN # : C3500057				

CHILD WORK ORDER DETAILS

	WO #	Description	Corrective Action	AMENDED
2001-1	2503928	General Visual Inspection of the Fan Blades (LH)	Complied with task 72-20-00-201L, Performed LH General Visual Inspection of the Fan Blades, in accordance with CL 650 AMM 72-20-00-210-801. No Defects noted	
2001-2	2503930	General Visual Inspection of the Fan Spinner	Complied with task 72-20-00-202L, Perform LH General Visual Inspection of the Fan Spinner, in accordance with CL650 AMM 72-20-00-210-802. No defects noted	
2001-3	2503931	General Visual Inspection of the Fan Shroud Core Material	Complied with Task 72-20-00-210. Performed LH General Visual Inspection of the Fan Shroud Core Material, in reference to CL-650 AMM 72-20-00-210-805. No defects were noted at this time.	
2001-4	2503932	General Visual Inspection of the Thermal Blanket	Complied with Task Card 72-40-00-205L. Perform LH General Visual Inspection of the Thermal Blanket. Ref. CL650 AMM 72-40-00-210-802. No discrepancies noted at this time.	
2001-5	2503936	Visual Check of the Oil-Filter Impending-Bypass Indicator	Complied with task 79-00-00-203L, Perform LH Visual Check of the Oil-Filter Impending-Bypass Indicator, in accordance with CL650 AMM 79-30-10-210-801. No defects noted	
2001-6	2503937	Visual Check of the C-Sump Drain Outlet (LH)	Complied with task 79-00-00-207L, Perform LH Visual Check of the C-Sump Drain Outlet, in accordance with CL650 AMM 71-71-04-210-801. No defects noted.	

Sequence #	2001-1	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503928	Aircraft Reg #	XA-SOL	Parent WO #	2503654

2001-1	WO #	2503928	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Fan Blades	
General Visual Inspection of the Fan Blades (LH)				
Task / IRN # : 72-20-00-201L				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 72-20-00-201L, Performed LH General Visual Inspection of the Fan Blades, in accordance with CL 650 AMM 72-20-00-210-801. No Defects noted	B1017798 - Hunter Van Der Heide Feb 05, 2026 01:01 AM	72-20
	Perform LH General Visual Inspection of the Fan Blades		B0623124 - Michael Stacy Feb 05, 2026 01:12 AM	
	200	Removed all tools, equipment, and unwanted materials from the area	B1017798 - Hunter Van Der Heide Feb 05, 2026 01:01 AM	
	Remove all tools, equipment, and unwanted materials from the area		B0623124 - Michael Stacy Feb 05, 2026 01:12 AM	

Sequence #	2001-2	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	2503930	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2503654

2001-2	**WO #**	**2503930**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		General Visual Inspection of the Fan Spinner	
General Visual Inspection of the Fan Spinner				
Task / IRN # : 72-20-00-202L				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 72-20-00-202L, Perform LH General Visual Inspection of the Fan Spinner, in accordance with CL650 AMM 72-20-00-210-802. No defects noted	B0580384 - Patrick Arceneaux Feb 05, 2026 12:26 AM	72-20
	Perform LH General Visual Inspection of the Fan Spinner		B0623124 - Michael Stacy Feb 05, 2026 01:06 AM	
	200	Removed all tools equipment and unwanted materials from the work area	B0580384 - Patrick Arceneaux Feb 05, 2026 12:26 AM	
	Remove all tools equipment and unwanted materials from the work area		B0623124 - Michael Stacy Feb 05, 2026 01:06 AM	

Bombardier

Sequence #	2001-3	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503931	Aircraft Reg #	XA-SOL	Parent WO #	2503654

2001-3	WO #	2503931	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Fan Shroud Core Material	
General Visual Inspection of the Fan Shroud Core Material				
Task / IRN # : 72-20-00-210L				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with Task 72-20-00-210. Performed LH General Visual Inspection of the Fan Shroud Core Material, in reference to CL-650 AMM 72-20-00-210-805. No defects were noted at this time.	B0638589 - Sean Dodder Feb 05, 2026 12:47 AM	72-20
	Perform LH General Visual Inspection of the Fan Shroud Core Material		B0623124 - Michael Stacy Feb 05, 2026 01:08 AM	
	200	Removed all tools, equipment and unwanted materials from the work area.	B0638589 - Sean Dodder Feb 05, 2026 12:47 AM	
	Remove all tools, equipment and unwanted materials from the work area.		B0623124 - Michael Stacy Feb 05, 2026 01:08 AM	

Sequence #	2001-4	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503932	Aircraft Reg #	XA-SOL	Parent WO #	2503654

2001-4	WO #	2503932	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Thermal Blanket	
General Visual Inspection of the Thermal Blanket				
Task / IRN # : 72-40-00-205L				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with Task Card 72-40-00-205L. Perform LH General Visual Inspection of the Thermal Blanket. Ref. CL650 AMM 72-40-00-210-802. No discrepancies noted at this time.	K1018275 - Emmanuel Cocoa Feb 07, 2026 04:08 PM	72-40
	Perform LH General Visual Inspection of the Thermal Blanket		B0142244 - Todd Bridges Feb 07, 2026 04:57 PM	
	200	Removed all tools equipment and unwanted materials.	K1018275 - Emmanuel Cocoa Feb 07, 2026 04:08 PM	
	Remove all tools equipment and unwanted materials.		B0142244 - Todd Bridges Feb 07, 2026 04:57 PM	

Sequence #	2001-5	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503936	Aircraft Reg #	XA-SOL	Parent WO #	2503654

2001-5	WO #	2503936	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Visual Check of the Oil-Filter Impending-Bypass Indicator	
Visual Check of the Oil-Filter Impending-Bypass Indicator				
Task / IRN # : 79-00-00-203L				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 79-00-00-203L, Perform LH Visual Check of the Oil-Filter Impending-Bypass Indicator, in accordance with CL650 AMM 79-30-10-210-801. No defects noted	B1019545 - Tharathorn Locham Feb 12, 2026 01:57 PM	79-30
	Perform LH Visual Check of the Oil-Filter Impending-Bypass Indicator		B1013522 - Brandon Jennings Feb 12, 2026 02:48 PM	
	200	Removed all tools equipment and unwanted material from work area	B1019545 - Tharathorn Locham Feb 12, 2026 03:21 PM	
	Remove all tools equipment and unwanted material from work area		B1013522 - Brandon Jennings Feb 12, 2026 03:44 PM	

Sequence #	2001-6	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503937	Aircraft Reg #	XA-SOL	Parent WO #	2503654

2001-6	WO #	2503937	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Visual Check of the C-Sump Drain Outlet	
Visual Check of the C-Sump Drain Outlet (LH)				
Task / IRN # : 79-00-00-207L				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 79-00-00-207L, Perform LH Visual Check of the C-Sump Drain Outlet, in accordance with CL650 AMM 71-71-04-210-801. No defects noted.	B1019545 - Tharathorn Locham Feb 12, 2026 02:13 PM	79-00
	Perform LH Visual Check of the C-Sump Drain Outlet		B1013522 - Brandon Jennings Feb 12, 2026 02:51 PM	
	200	Removed all tools equipment and unwanted material from work area	B1019545 - Tharathorn Locham Feb 12, 2026 03:22 PM	
	Remove all tools equipment and unwanted material from work area		B1013522 - Brandon Jennings Feb 12, 2026 03:51 PM	

Bombardier

Sequence #	2002	Aircraft SN #	6111	MWPWO #	2498069
WO #	4292599	Aircraft Reg #	XA-SOL	Parent WO #	2498069

2002	WO #	4292599	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13429467	200 HOUR Engine Inspection (LH)	
200 HOUR Engine Inspection (LH)				
Task / IRN # : C30831				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	See Child WO: 4292626 for Work Performed		72-00
	72-20-00-207 NO. 1 ENGINE - DETAILED INSPECTION ENGINE MASTER CHIP DETECTOR INDICATOR			

CHILD WORK ORDER DETAILS

	WO #	Description	Corrective Action	AMENDED
2002-1	4292626	72-20-00-207 NO. 1 ENGINE - DETAILED INSPECTION ENGINE MASTER CHIP DETECTOR INDICATOR	COMPLIED WITH TASK CARD 72-20-00-207. INSPECTED NO.1 ENGINE MASTER CHIP DETECTOR INDICATOR IAW CL650 AMM 79-21-13-220-801. No defect noted	

Sequence #	2002-1	Aircraft SN #	6111	MWPWO #	2498069
WO #	4292626	Aircraft Reg #	XA-SOL	Parent WO #	4292599

2002-1	WO #	4292626	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		72-20-00-207 NO. 1 Engine Detailed Inspection Engine Master Chip Detector Indicator	
72-20-00-207 NO. 1 ENGINE - DETAILED INSPECTION ENGINE MASTER CHIP DETECTOR INDICATOR				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	COMPLIED WITH TASK CARD 72-20-00-207. INSPECTED NO.1 ENGINE MASTER CHIP DETECTOR INDICATOR IAW CL650 AMM 79-21-13-220-801. No defect noted	B1022255 - Carson Chang Feb 16, 2026 08:02 PM	
	Task card 72-20-00-207 NO. 1 ENGINE - DETAILED INSPECTION ENGINE MASTER CHIP DETECTOR INDICATOR		B1019908 - Joseph Barnes Feb 16, 2026 08:33 PM	
	200	Removed all tools, equipment, and unwanted materials from the work area	B1022255 - Carson Chang Feb 16, 2026 08:05 PM	
	Remove all tools, equipment, and unwanted materials from the work area		B1019908 - Joseph Barnes Feb 16, 2026 08:33 PM	

Sequence #	2401	Aircraft SN #	6111	MWPWO #	2498069
WO #	2503655	Aircraft Reg #	XA-SOL	Parent WO #	2498069

2401	WO #	2503655	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13276124	600 HOUR Engine Inspection RH	
600 HOUR Engine Inspection RH				
Task / IRN # : C3500193				

CHILD WORK ORDER DETAILS

	WO #	Description	Corrective Action	AMENDED
2401-1	2504368	General Visual Inspection of the Fan Blades (RH)	Complied with task 72-20-00-201R, Performed RH General Visual Inspection of the Fan Blades, in accordance with CL 650 AMM 72-20-00-210-801. No defects noted	
2401-2	2504370	General Visual Inspection of the Fan Spinner	Complied with task 72-20-00-202, Perform RH General Visual Inspection of the Fan Spinner, in accordance with CL650 AMM 72-20-00-210-802. No defects noted	
2401-3	2504372	General Visual Inspection of the Fan Shroud Core Material	Complied with Task 72-20-00-210. Performed RH General Visual Inspection of the Fan Shroud Core Material, in reference to CL-650 AMM 72-20-00-210-805. No defects were noted at this time.	
2401-4	2504374	General Visual Inspection of the Thermal Blanket	Complied with Task Card 72-40-00-205R. Perform RH General Visual Inspection of the Thermal Blanket. Ref, CL 650 AMM 72-40-00-210-802. No discrepancies noted at this time.	
2401-5	2504376	Visual Check of the Oil-Filter Impending-Bypass Indicator	Complied with task 79-00-00-203R, Perform RH Visual Check of the Oil-Filter Impending-Bypass Indicator, in accordance with CL650 AMM 79-30-10-210-801. No defects noted	
2401-6	2504378	Visual Check of the C-Sump Drain Outlet (RH)	Complied with task 79-00-00-207R, Perform RH Visual Check of the C-Sump Drain Outlet., in accordance with CL650 AMM 71-71-04-210-801. No defects noted.	

Sequence #	2401-1	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504368	Aircraft Reg #	XA-SOL	Parent WO #	2503655

2401-1	WO #	2504368	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Fan Blades	
General Visual Inspection of the Fan Blades (RH)				
Task / IRN # : 72-20-00-201R				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 72-20-00-201R, Performed RH General Visual Inspection of the Fan Blades, in accordance with CL 650 AMM 72-20-00-210-801. No defects noted	B1017798 - Hunter Van Der Heide Feb 05, 2026 01:04 AM	72-20
	Perform RH General Visual Inspection of the Fan Blades		B0623124 - Michael Stacy Feb 05, 2026 01:11 AM	
	200	Removed all tools, equipment, and unwanted materials form the area	B1017798 - Hunter Van Der Heide Feb 05, 2026 01:04 AM	
	Remove all tools, equipment, and unwanted materials form the area		B0623124 - Michael Stacy Feb 05, 2026 01:11 AM	

Sequence #	2401-2	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	2504370	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2503655

2401-2	**WO #**	**2504370**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		General Visual Inspection of the Fan Spinner	
General Visual Inspection of the Fan Spinner				
Task / IRN # : 72-20-00-202R				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 72-20-00-202, Perform RH General Visual Inspection of the Fan Spinner, in accordance with CL650 AMM 72-20-00-210-802. No defects noted	B0580384 - Patrick Arceneaux Feb 05, 2026 04:32 AM	72-20
	Perform RH General Visual Inspection of the Fan Spinner		B0623124 - Michael Stacy Feb 05, 2026 04:36 AM	
	200	Removed all tools, equipment and unwanted materials from the work area	B0580384 - Patrick Arceneaux Feb 05, 2026 04:32 AM	
	Remove all tools, equipment and unwanted materials from the work area		B0623124 - Michael Stacy Feb 05, 2026 04:36 AM	

Sequence #	2401-3	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504372	Aircraft Reg #	XA-SOL	Parent WO #	2503655

2401-3	WO #	2504372	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Fan Shroud Core Material	
General Visual Inspection of the Fan Shroud Core Material				
Task / IRN # : 72-20-00-210R				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with Task 72-20-00-210. Performed RH General Visual Inspection of the Fan Shroud Core Material, in reference to CL-650 AMM 72-20-00-210-805. No defects were noted at this time.	B0638589 - Sean Dodder Feb 05, 2026 12:48 AM	72-20
	Perform RH General Visual Inspection of the Fan Shroud Core Material		B0623124 - Michael Stacy Feb 05, 2026 01:09 AM	
	200	Removed all tools, equipment and unwanted materials from the work area.	B0638589 - Sean Dodder Feb 05, 2026 12:48 AM	
	Remove all tools, equipment and unwanted materials from the work area.		B0623124 - Michael Stacy Feb 05, 2026 01:09 AM	

Sequence #	2401-4	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504374	Aircraft Reg #	XA-SOL	Parent WO #	2503655

2401-4	WO #	2504374	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		General Visual Inspection of the Thermal Blanket	
General Visual Inspection of the Thermal Blanket				
Task / IRN # : 72-40-00-205R				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with Task Card 72-40-00-205R. Perform RH General Visual Inspection of the Thermal Blanket. Ref, CL 650 AMM 72-40-00-210-802. No discrepancies noted at this time.	K1018275 - Emmanuel Cocoa Feb 07, 2026 04:05 PM	72-40
	Perform RH General Visual Inspection of the Thermal Blanket		B0142244 - Todd Bridges Feb 07, 2026 04:59 PM	
	200	Removed all tools equipment and unwanted materials.	K1018275 - Emmanuel Cocoa Feb 07, 2026 04:05 PM	
	Remove all tools equipment and unwanted materials.		B0142244 - Todd Bridges Feb 07, 2026 04:59 PM	

Sequence #	2401-5	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504376	Aircraft Reg #	XA-SOL	Parent WO #	2503655

2401-5	WO #	2504376	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Visual Check of the Oil-Filter Impending-Bypass Indicator	
Visual Check of the Oil-Filter Impending-Bypass Indicator				
Task / IRN # : 79-00-00-203R				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 79-00-00-203R, Perform RH Visual Check of the Oil-Filter Impending-Bypass Indicator, in accordance with CL650 AMM 79-30-10-210-801. No defects noted	B1019545 - Tharathorn Locham Feb 12, 2026 01:58 PM	79-30
	Perform RH Visual Check of the Oil-Filter Impending-Bypass Indicator		B1013522 - Brandon Jennings Feb 12, 2026 02:50 PM	
	200	Removed all tools equipment and unwanted material from work area	B1019545 - Tharathorn Locham Feb 12, 2026 03:22 PM	
	Remove all tools equipment and unwanted material from work area		B1013522 - Brandon Jennings Feb 12, 2026 03:45 PM	

Sequence #	2401-6	Aircraft SN #	6111	MWPWO #	2498069
WO #	2504378	Aircraft Reg #	XA-SOL	Parent WO #	2503655

2401-6	WO #	2504378	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		Visual Check of the C-Sump Drain Outlet	
Visual Check of the C-Sump Drain Outlet (RH)				
Task / IRN # : 79-00-00-207R				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with task 79-00-00-207R, Perform RH Visual Check of the C-Sump Drain Outlet., in accordance with CL650 AMM 71-71-04-210-801. No defects noted.	B1019545 - Tharathorn Locham Feb 12, 2026 02:14 PM	71-70
	Perform RH Visual Check of the C-Sump Drain Outlet.		B1013522 - Brandon Jennings Feb 12, 2026 03:46 PM	
	200	Removed all tools equipment and unwanted material from work area	B1019545 - Tharathorn Locham Feb 12, 2026 03:23 PM	
	Remove all tools equipment and unwanted material from work area		B1013522 - Brandon Jennings Feb 12, 2026 03:46 PM	

Sequence #	2402	Aircraft SN #	6111	MWPWO #	2498069
WO #	4292716	Aircraft Reg #	XA-SOL	Parent WO #	2498069

2402	WO #	4292716	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13429468	200 HOUR Engine Inspection (RH)	
200 HOUR Engine Inspection (RH)				
Task / IRN # : C30832				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			72-00
	72-20-00-207 NO. 2 ENGINE - DETAILED INSPECTION ENGINE MASTER CHIP DETECTOR INDICATOR			

CHILD WORK ORDER DETAILS

	WO #	Description	Corrective Action	AMENDED
2402-1	4292731	72-20-00-207 NO. 2 ENGINE - DETAILED INSPECTION ENGINE MASTER CHIP DETECTOR INDICATOR	Complied with Task Card 72-20-00-207. NO. 2 ENGINE DETAILED INSPECTION ENGINE MASTER CHIP DETECTOR INDICATOR. Ref. CL650 AMM 79−21−13−220−801. No discrepancies noted at this time.	

Sequence #	2402-1	Aircraft SN #	6111	MWPWO #	2498069
WO #	4292731	Aircraft Reg #	XA-SOL	Parent WO #	4292716

2402-1	WO #	4292731	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		72-20-00-207 NO. 2 Engine - Detailed Inspection Engine Master Chip Detector Indicator	
72-20-00-207 NO. 2 ENGINE - DETAILED INSPECTION ENGINE MASTER CHIP DETECTOR INDICATOR				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with Task Card 72-20-00-207. NO. 2 ENGINE - DETAILED INSPECTION ENGINE MASTER CHIP DETECTOR INDICATOR. Ref. CL650 AMM 79−21−13−220−801. No discrepancies noted at this time.	K1018275 - Emmanuel Cocoa Feb 16, 2026 08:02 PM	
	Task Card 72-20-00-207 NO. 2 ENGINE - DETAILED INSPECTION ENGINE MASTER CHIP DETECTOR INDICATOR		B1019908 - Joseph Barnes Feb 16, 2026 08:30 PM	
	200	Removed all tools equipment and unwanted materials.	K1018275 - Emmanuel Cocoa Feb 16, 2026 08:03 PM	
	Remove all tools equipment and unwanted materials.		B1019908 - Joseph Barnes Feb 16, 2026 08:30 PM	

Sequence #	2801	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	2498411	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

			LOG BOOK VERBIAGE	Deferrals
2801	**WO #**	**2498411**		
	SAP SVO #	13276315	Honeywell SIL APU-49 R13 - APU 36-150 - Spectrometric Oil and filter Analysis Program (SOAP) (601/604/605/650)	
Honeywell SIL APU-49 R13 - APU 36-150 - Spectrometric Oil and filter Analysis Program (SOAP) (601/604/605/650)				
Task / IRN # : SIL APU-49 R13				

Sequence #	2801	Aircraft SN #	6111	MWPWO #	2498069
WO #	2498411	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			49-90
	Verify Revision and effectivity of SIL to current document in Customer Portal Library			
	200	Complied with task SIL APU-49 R13 with oil sampling procedures per Honeywell SIL Publication Number APU-49 Dated 9/3/1996 Rev 13 Dated 11/23/2023. Soap samples shipped, awaiting results.	B0580384 - Patrick Arceneaux Feb 07, 2026 03:01 AM	49-90
	C/W Oil Sampling Procedures per SIL APU-49		B0623124 - Michael Stacy Feb 07, 2026 03:15 AM	
	300			49-90
	C/W Evaluating Spectromatric Oil Analysis per SIL APU-49			
	400			49-90
	C/W Evaluating Filter Analysis per SIL APU-49			
	500			49-90
	C/W Recording of the findings in the Log Book			
	600	Installed new APU oil filter element REF CL650 AMM 49-91-07-400-801	B0580384 - Patrick Arceneaux Feb 07, 2026 03:01 AM	
	Removed APU oil filter element REF CL650 AMM 49-91-07-000-801		B0623124 - Michael Stacy Feb 07, 2026 03:15 AM	
	700			
	Service APU REF CL650 AMM 12-13-49-612-801			
	800			
	Perform operational test of APU REF CL650 49-10-00-710-801			
	900			
	Perform fuel and oil leak check on APU REF CL650 AMM 49-10-00-790-801			

Sequence #	2801	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	2498411	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

REMOVE AND RE-INSTALL DETAILS

	Removed Part # Removed Serial #	Removed By	Removed - Part Description	Reference	Installed Part # Installed Serial #	Installed By
	Removed Status	**Removed Date-Time**	**Position**	**Installed Part Status**	**Installed Part Description**	**Installed Date-Time**
	365303-1 23-70916	B0580384 - Patrick Arceneaux	ELEMENT, OIL FILTER	49-91-07-000-801	365303-1 23-73176	B0580384 - Patrick Arceneaux
	UNSERVICEABLE	Feb 6, 2026 8:05 PM	APU	NEW	ELEMENT, OIL FILTER	Feb 6, 2026 8:05 PM

TOOL INFORMATION

Tool ID	Tool Description	Calibration Due Date
TUSS2036	Torque wrench	May 30, 2026 5:00 PM

Sequence #	3001	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	2616874	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

			LOG BOOK VERBIAGE	Deferrals
3001	**WO #**	**2616874**		
	SAP SVO #	13276162	***Checklist required - SB 650-25-018 Rev Basic - Modification - Side Panels - Window Shade Replacement (650)	
SB 650-25-018 Rev Basic - Modification - Side Panels - Window Shade Replacement (650)				
Task / IRN # : SB 650-25-018 REV BASIC				

Sequence #	3001	Aircraft SN #	6111	MWPWO #	2498069
WO #	2616874	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	1			25-20
	Verify Revision and effectivity of SB to current document in Customer Portal Library			
	100			25-20
	C/W Section 2.B - Modification			
	200			25-20
	C/W Section 2.B - PART A - Modification - Window Shade Replacement, Installation -1, -3			
	300			25-20
	C/W Section 2.C - PART B - Modification - Galley False Window Shade Replacement, Installation -5 (Optional)			
	400			25-60
	C/W Section 2.D - PART C - Modification - Aft Lavatory False Window Shade Replacement, Installation - 7 (Optional)			
	500			25-20
	C/W Section 2.E - PART D - Modification - Emergency - Exit Window Shade Replacement, Installation - 9			
	600			25-20
	C/W Section 2.F - Testing			
	700			25-20
	C/W Section 2.G - Close - Out			
	800			25-20
	C/W Section 2.H - Recording			

Sequence #	3002	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	2498418	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

			LOG BOOK VERBIAGE	Deferrals
3002	**WO #**	**2498418**		
	SAP SVO #	13276044	FAA 2021-20-13 Para (H) - DVI of the LH/RH MLG Shock Strut lower pins having PN 19146-3	
FAA 2021-20-13 Para (H) - DVI of the LH/RH MLG Shock Strut lower pins having PN 19146-3				
Task / IRN # : FAA 2021-20-13				

Bombardier

Sequence #	3003	Aircraft SN #	6111	MWPWO #	2498069
WO #	4292985	Aircraft Reg #	XA-SOL	Parent WO #	2498069

3003	WO #	4292985	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13429431	TCCA CF-2025-05 LANDING GEAR - UNCOMMANDED STEERING	
*TCCA CF-2025-05 LANDING GEAR - UNCOMMANDED STEERING				
Task / IRN # : TCCA CF-2025-05				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			32-00
	*TCCA CF-2025-05 LANDING GEAR - UNCOMMANDED STEERING			

Sequence #	3004	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4364758	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

			LOG BOOK VERBIAGE	Deferrals
3004	**WO #**	**4364758**		
	SAP SVO #	13440226	***Checklist required - SB 650-25-021 REV BASIC - Modification - Side Panels-Window Shade Replacement	
***Checklist required - SB 650-25-021 REV BASIC - Modification - Side Panels-Window Shade Replacement				
Task / IRN # : SB 650-25-021 REV BASIC				

Sequence #	3004	Aircraft SN #	6111	MWPWO #	2498069
WO #	4364758	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			25-00
	Verify Revision and effectivity of SB to current document in Customer Portal Library			
	200			25-00
	C/W Section 2.A - Aircraft Setup			
	300			25-00
	C/W Section 2.B - PART A - Modification - Cabin Window Shade Replacement, Installation -3 (LHS), -3 (LHS)			
	400			25-00
	C/W Section 2.C - PART B - Modification - Cabin Window Shade Replacement, Installation -5 (RHS)			
	500			25-00
	C/W Section 2.D - PART C - Modification - Galley False Window Shade Replacement, Installation -7 (Optional)			
	600			25-00
	C/W Section 2.E - PART D - Modification - AFT Lavatory False Window Shade Replacement Installation (Optional)			
	700			25-00
	C/W Section 2.F - PART E - Modification - Overwing Emergency - Exit Door (OWEED) Window Shade Replacement, Installation -11			
	800			25-00
	C/W Section 2.G - PART F - Modification - OWEED Window Shade Light Bleed, Installation -13			

Sequence #	3004	Aircraft SN #	6111	MWPWO #	2498069
WO #	4364758	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	900			
	C/W Section 2.H - Testing			
	1000			25-00
	C/W Section 2.I - Close - Out			
	1100			25-00
	C/W Section 2.J - Recording			

Sequence #	3005	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4650845	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

			LOG BOOK VERBIAGE	Deferrals
3005	**WO #**	**4650845**		
	SAP SVO #	13485394	GE SB 72-0347 Rev 2 - (LH) No. 1 Engine - General (72-00-00) - One - Time Compressor Inner Diameter Inspection For Corrosion and Variable Geometry System Functional Check	
GE SB 72-0347 Rev 2 - (LH) No. 1 Engine - General (72-00-00) - One - Time Compressor Inner Diameter Inspection For Corrosion and Variable Geometry System Functional Check				
Task / IRN # : GE SB 72-0347 REV 2 - (LH)				

Sequence #	3005	Aircraft SN #	6111	MWPWO #	2498069
WO #	4650845	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with Verify Revision and effectivity of SB to current document in Customer Portal Library. REF GE SB 72-0347 Rev 2 Dated 10/30/2025 Reference work copy for work performed Dated Feb, 6 2026	B0648431 - Caleb Sexton Feb 09, 2026 06:51 PM	72-00
	Verify Revision and effectivity of SB to current document in Customer Portal Library		B1019908 - Joseph Barnes Feb 09, 2026 07:22 PM	
	200	Complied with Section 3.A - General Step (5) REF GE SB 72-0347 Rev 2 Dated 10/30/2025 Reference work copy for work performed Dated Feb, 6 2026	B0648431 - Caleb Sexton Feb 09, 2026 06:51 PM	72-00
	C/W Section 3.A - General		B1019908 - Joseph Barnes Feb 09, 2026 07:22 PM	
	300	Section 3.B - Engine Heat Soak Restart Test (RH) Not Applicable per Section 3.A - General Step (5) performed VG system functional test. REF GE SB 72-0347 Rev 2 Dated 10/30/2025 Reference work copy for work performed Dated Feb, 6 2026	B0648431 - Caleb Sexton Feb 09, 2026 06:51 PM	72-00
	C/W Section 3.B - Engine Heat Soak Restart Test (LH)		B1019908 - Joseph Barnes Feb 09, 2026 07:22 PM	
	400	Section 3.C - Inspection of Compressor Case Stage 6 Front Side and Stage 5 Rear Side Flow Patch (RH) Not Applicable per Section 3.A - General Step (5) performed VG system functional test. REF GE SB 72-0347 Rev 2 Dated 10/30/2025 Reference work copy for work performed Dated Feb, 6 2026	B0648431 - Caleb Sexton Feb 09, 2026 06:51 PM	72-00
	C/W Section 3.C - Inspection of Compressor Case Stage 6 Front Side and Stage 5 Rear Side Flow Patch (LH)		B1019908 - Joseph Barnes Feb 09, 2026 07:22 PM	
	500	Complied with Section 3.C - VG System - Functional Check (RH) REF GE SB 72-0347 Rev 2 Dated 10/30/2025 Reference work copy for work performed Dated Feb, 6 2026	B0648431 - Caleb Sexton Feb 09, 2026 06:51 PM	72-00
	C/W Section 3.C - VG System - Functional Check (LH)		B1019908 - Joseph Barnes Feb 09, 2026 07:22 PM	
	600	Complied with Section 3.E Step 3 - Disposition of Results (RH) REF GE SB 72-0347 Rev 2 Dated 10/30/2025. Fully extended psi recorded at 29 psi and fully retract recorded at 35 psi. FT good no defects noted at this time. Reference work copy for work performed Dated Feb, 6 2026	B0648431 - Caleb Sexton Feb 09, 2026 06:51 PM	72-00
	C/W Section 3.E - Disposition of Results (LH)		B1019908 - Joseph Barnes Feb 09, 2026 07:22 PM	

Sequence #	3005	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4650845	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	700	Complied with Section 3.F - Inspection Report (RH) REF GE SB 72-0347 Rev 2 Dated 10/30/2025 Reference work copy for work performed Dated Feb, 6 2026	B0648431 - Caleb Sexton Feb 09, 2026 06:51 PM	72-00
	C/W Section 3.F - Inspection Report (LH)		B1019908 - Joseph Barnes Feb 09, 2026 07:22 PM	
	800			
	C/W Variable Geometry System fuel lines leak test after maintenance. REF CF34BJ SM 72-00-00 TESTING Fig-510.			
	900	Removed all tools, equipment, and unwanted materials from the work area	B0648431 - Caleb Sexton Feb 09, 2026 07:27 PM	
	Remove all tools, equipment, and unwanted materials from the work area			

TOOL INFORMATION

Tool ID	Tool Description	Calibration Due Date
TUSS2243	TW	Dec 30, 2026 5:00 PM
TUSS4231	TW	Jul 30, 2026 5:00 PM

Sequence #	3006	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4650861	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

			LOG BOOK VERBIAGE	Deferrals
3006	**WO #**	**4650861**		
	SAP SVO #	13485371	GE SB 72-0347 Rev 2 - (RH) No. 2 Engine - General (72-00-00) - One - Time Compressor Inner Diameter Inspection For Corrosion and Variable Geometry System Functional Check	
GE SB 72-0347 Rev 2 - (RH) No. 2 Engine - General (72-00-00) - One - Time Compressor Inner Diameter Inspection For Corrosion and Variable Geometry System Functional Check				
Task / IRN # : GE SB 72-0347 REV 2 - (RH)				

Sequence #	3006	Aircraft SN #	6111	MWPWO #	2498069
WO #	4650861	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with Verify Revision and effectivity of SB to current document in Customer Portal Library. REF GE SB 72-0347 Rev 2 Dated 10/30/2025 Reference work copy for work performed Dated Feb, 6 2026	B0648431 - Caleb Sexton Feb 09, 2026 06:53 PM	72-00
	Verify Revision and effectivity of SB to current document in Customer Portal Library		B1019908 - Joseph Barnes Feb 09, 2026 07:24 PM	
	200	Complied with Section 3.A - General Step (5) REF GE SB 72-0347 Rev 2 Dated 10/30/2025 Reference work copy for work performed Dated Feb, 6 2026	B0648431 - Caleb Sexton Feb 09, 2026 06:53 PM	72-00
	C/W Section 3.A - General		B1019908 - Joseph Barnes Feb 09, 2026 07:24 PM	
	300	Section 3.B - Engine Heat Soak Restart Test (RH) Not Applicable per Section 3.A - General Step (5) performed VG system functional test. REF GE SB 72-0347 Rev 2 Dated 10/30/2025 Reference work copy for work performed Dated Feb, 6 2026	B0648431 - Caleb Sexton Feb 09, 2026 06:53 PM	72-00
	C/W Section 3.B - Engine Heat Soak Restart Test (RH)		B1019908 - Joseph Barnes Feb 09, 2026 07:24 PM	
	400	Section 3.C - Inspection of Compressor Case Stage 6 Front Side and Stage 5 Rear Side Flow Patch (RH) Not Applicable per Section 3.A - General Step (5) performed VG system functional test. REF GE SB 72-0347 Rev 2 Dated 10/30/2025 Reference work copy for work performed Dated Feb, 6 2026	B0648431 - Caleb Sexton Feb 09, 2026 06:53 PM	72-00
	C/W Section 3.C - Inspection of Compressor Case Stage 6 Front Side and Stage 5 Rear Side Flow Patch (RH)		B1019908 - Joseph Barnes Feb 09, 2026 07:24 PM	
	500	Complied with Section 3.C - VG System - Functional Check (RH) REF GE SB 72-0347 Rev 2 Dated 10/30/2025 Reference work copy for work performed Dated Feb, 6 2026	B0648431 - Caleb Sexton Feb 09, 2026 06:53 PM	72-00
	C/W Section 3.C - VG System - Functional Check (RH)		B1019908 - Joseph Barnes Feb 09, 2026 07:24 PM	
	600	Complied with Section 3.E Step 3 - Disposition of Results (RH) REF GE SB 72-0347 Rev 2 Dated 10/30/2025. Fully extended psi recorded at 29 psi and fully retract recorded at 35 psi. FT good no defects noted at this time. Reference work copy for work performed Dated Feb, 6 2026	B0648431 - Caleb Sexton Feb 09, 2026 06:53 PM	72-00
	C/W Section 3.E - Disposition of Results (RH)		B1019908 - Joseph Barnes Feb 09, 2026 07:24 PM	

Sequence #	3006	Aircraft SN #	6111	MWPWO #	2498069
WO #	4650861	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	700	Complied with Section 3.F - Inspection Report (RH) REF GE SB 72-0347 Rev 2 Dated 10/30/2025 Reference work copy for work performed Dated Feb, 6 2026	B0648431 - Caleb Sexton Feb 09, 2026 06:53 PM	72-00
	C/W Section 3.F - Inspection Report (RH)		B1019908 - Joseph Barnes Feb 09, 2026 07:24 PM	
	800			
	C/W Variable Geometry System fuel lines leak test after maintenance. REF CF34BJ SM 72-00-00 TESTING Fig-510.			
	900	Removed all tools, equipment, and unwanted materials from the work area	B0648431 - Caleb Sexton Feb 09, 2026 07:28 PM	
	Remove all tools, equipment, and unwanted materials from the work area		B1019908 - Joseph Barnes Feb 09, 2026 08:09 PM	

TOOL INFORMATION

Tool ID	Tool Description	Calibration Due Date
TUSS4231	TW	Jul 30, 2026 5:00 PM
TUSS2243	TW	Dec 30, 2026 5:00 PM

Sequence #	3007	Aircraft SN #	6111	MWPWO #	2498069
WO #	4650889	Aircraft Reg #	XA-SOL	Parent WO #	2498069

3007	WO #	4650889	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13485373	Revising the Existing Maintenance Program due to the Accumulation fo Fuel in the APU Muffler. Complied with Paragraph (g), Verified TLMC Current Revision has been Implemented into the Aircraft Library. No Further Action Required.	
*FAA 2025-24-11 ACCUMULATION OF FUEL IN THE AUXILIARY POWER UNI				
Task / IRN # : FAA 2025-24-11				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with FAA AD 2025-24-11 ACCUMULATION OF FUEL IN THE AUXILIARY POWER UNIT. verified TLMC current revision has been implemented into aircraft library no further action required.	B0161867 - Jeremy Kucera Feb 18, 2026 05:41 AM	49-00
	*FAA 2025-24-11 ACCUMULATION OF FUEL IN THE AUXILIARY POWER UNIT		B0609145 - Miguel Pacheco Feb 18, 2026 05:49 AM	
	200	Complied with IAW Paragraph (g).	B0161867 - Jeremy Kucera Feb 18, 2026 05:47 AM	
	Add AD Paragraph to Operation 100.		B0609145 - Miguel Pacheco Feb 18, 2026 05:49 AM	

Bombardier

Sequence #	3008	Aircraft SN #	6111	MWPWO #	2498069
WO #	4651102	Aircraft Reg #	XA-SOL	Parent WO #	2498069

3008	WO #	4651102	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13485393	FAA 2025-26-06 APPLIANCE AD - INCORRECT USAGE OF PORTABLE BREATHING EQUIPMENT	
*FAA 2025-26-06 APPLIANCE AD - INCORRECT USAGE OF PORTABLE BREATHING EQUIPMENT				
Task / IRN # : FAA 2025-26-06				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			25-00
	*FAA 2025-26-06 APPLIANCE AD - INCORRECT USAGE OF PORTABLE BREATHING EQUIPMENT			

Sequence #	3009	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4651219	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

3009	**WO #**	**4651219**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #	13485392	SB 650-26-002 Rev Basic - Modification - Portable Fire Extinguishing System - Installation of Non-Halon Fire Extinguisher	
SB 650-26-002 Rev Basic - Modification - Portable Fire Extinguishing System - Installation of Non-Halon Fire Extinguisher				
Task / IRN # : SB 650-26-002 REV BASIC				

Sequence #	3009	Aircraft SN #	6111	MWPWO #	2498069
WO #	4651219	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			26-20
	Verify Revision and effectivity of SB to current document in Customer Portal Library			
	200			26-20
	Verify Revision and effectivity of SB to current document in Customer Portal Library			
	300			26-20
	C/W Section 2.B - PART A - Installation of Non-Halon Fire Extinguisher in the Cockpit			
	400			26-20
	C/W Section 2.C - PART B - Installation of Non-Halon Fire Extinguisher in the Forward Cabin			
	500			26-20
	C/W Section 2.D - PART C - Installation of Non-Halon Fire Extinguisher and Placard in the Divan Storage			
	600			26-20
	C/W Section 2.E - Testing (Not Required)			
	700			26-20
	C/W Section 2.F - Close-Out			
	800			26-20
	C/W Section 2.G - Recording			
	900			
	Verify Revision and effectivity of SB to current d			

Sequence #	4001	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	3303462	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

4001	**WO #**	**3303462**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #	13276351	No Log Entry	
4001//C/W INCOMING PICTURES OF THE INTERIOR, COSMETIC FINISH ITEMS, AND SOFT GOODS.				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	COMPLIED WITH INCOMING PICTURES OF THE INTERIOR, COSMETIC FINISH ITEMS, AND SOFT GOODS	B1001500 - Victor Gallego Feb 03, 2026 07:00 PM	25-00
	4001//C/W INCOMING PICTURES OF THE INTERIOR, COSMETIC FINISH ITEMS, AND SOFT GOODS.		B1013522 - Brandon Jennings Feb 03, 2026 07:36 PM	

Bombardier

Sequence #	4002	Aircraft SN #	6111	MWPWO #	2498069
WO #	2528784	Aircraft Reg #	XA-SOL	Parent WO #	2498069

4002	WO #	2528784	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13276163	No Log Entry	
Interior Access - CH650 Inspection Bundles				
Task / IRN # : INT ACCESS - CH 600 SERIES				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	10	Complied with Interior Access to perform inspections. See children workorders for work performed. see op 20 for interior restoration.	B0599115 - Mark Fierro Feb 12, 2026 04:51 PM	25-00
	Remove interior as required to perform inspections		Not Required	
	20			25-00
	Install Interior post inspections & mods			
	100	Turned off the oxygen supply system to facilitate interior access by turning the primary and additional oxygen cylinder regulators to OFF and installing lockwire REF CL 650 SMM 35-11-11-000-801	B1017798 - Hunter Van Der Heide Feb 09, 2026 11:55 PM	
	Turn off the oxygen supply system to facilitate interior access		Not Required	
	200			
	Turn on the the oxygen supply system and perform operational tests as required			

Sequence #	4002	Aircraft SN #	6111	MWPWO #	2498069
WO #	2528784	Aircraft Reg #	XA-SOL	Parent WO #	2498069

CHILD WORK ORDER DETAILS

	WO #	Description	Corrective Action	AMENDED
4002-1	4707941	01/4002 - CW EMERGENCY EQUIPMENT REMOVAL AND INSTALL FOR INSECTION ACCESS.		
4002-2	4720489	02/4002 - CW CABIN SEATING REMOVAL AND INSTALLATION	NO CHARGE WO - ONLY FOR DOCUMENTATITON . USE INTERIOR ACCESS WO FOR BILLABLE TIME RESPECTFULLY.	
4002-3	4720571	03/4002 - CW LH FWD CABIN BULKHEAD REMOVAL AND INSTALLATION.	NO CHARGE WO - ONLY FOR DOCUMENTATITON . USE INTERIOR ACCESS WO FOR BILLABLE TIME RESPECTFULLY.	
4002-4	4720581	04/4002 - CW RH FWD CABIN BULKHEAD REMOVAL AND INSTALLATION.	NO CHARGE WO - ONLY FOR DOCUMENTATITON . USE INTERIOR ACCESS WO FOR BILLABLE TIME RESPECTFULLY.	
4002-5	4720638	05/4002- CW GALLEY TOWER REMOVAL AND INSTALLATION	NO CHARGE WO - ONLY FOR DOCUMENTATITON . USE INTERIOR ACCESS WO FOR BILLABLE TIME RESPECTFULLY.	
4002-6	4720641	06/4002 - CW GALLEY UPPER REMOVAL AND INSTALLATION	NO CHARGE WO - ONLY FOR DOCUMENTATITON . USE INTERIOR ACCESS WO FOR BILLABLE TIME RESPECTFULLY.	
4002-7	4720644	07/4002 - CW GALLEY LOWER REMOVAL AND INSTALLATION	NO CHARGE WO - ONLY FOR DOCUMENTATITON . USE INTERIOR ACCESS WO FOR BILLABLE TIME RESPECTFULLY.	
4002-8	4720649	08/4002 - CW ENTRY HEADLINER REMOVAL AND INSTALLATON	NO CHARGE WO - ONLY FOR DOCUMENTATITON . USE INTERIOR ACCESS WO FOR BILLABLE TIME RESPECTFULLY.	
4002-9	4720664	09/4002 - CW LH SIDE PANEL REMOVAL AND INSTALLATION	NO CHARGE WO - ONLY FOR DOCUMENTATITON . USE INTERIOR ACCESS WO FOR BILLABLE TIME RESPECTFULLY.	
4002-10	4720685	10/4002 - CW RH SIDE PANEL REMOVAL AND INSTALLATION	NO CHARGE WO - ONLY FOR DOCUMENTATITON . USE INTERIOR ACCESS WO FOR BILLABLE TIME RESPECTFULLY.	
4002-11	4720725	11/4002 - CW LH FWD WARDROBE CABINET REMOVAL AND INSTALLATION.	NO CHARGE WO - ONLY FOR DOCUMENTATITON . USE INTERIOR ACCESS WO FOR BILLABLE TIME RESPECTFULLY.	

Sequence #	4002	Aircraft SN #	6111	MWPWO #	2498069
WO #	2528784	Aircraft Reg #	XA-SOL	Parent WO #	2498069

CHILD WORK ORDER DETAILS

	WO #	Description	Corrective Action	AMENDED
4002-12	4720728	12/4002 - CW LH ARMLEDGES REMOVAL AND INSTALLATION	NO CHARGE WO - ONLY FOR DOCUMENTATITON . USE INTERIOR ACCESS WO FOR BILLABLE TIME RESPECTFULLY.	
4002-13	4720905	13/4002 - CW RH ARMLEDGES REMOVAL AND INSTALLATION	NO CHARGE WO - ONLY FOR DOCUMENTATITON . USE INTERIOR ACCESS WO FOR BILLABLE TIME RESPECTFULLY.	
4002-14	4720974	14/4002 - CW CABIN HEADLINER REMOVAL AND INSTALLATION.	NO CHARGE WO - ONLY FOR DOCUMENTATITON . USE INTERIOR ACCESS WO FOR BILLABLE TIME RESPECTFULLY.	
4002-15	4721003	15/4002 - CW DIVAN W/ENDACBINETS REMOVAL AND INSTALLATION	NO CHARGE WO - ONLY FOR DOCUMENTATITON . USE INTERIOR ACCESS WO FOR BILLABLE TIME RESPECTFULLY.	
4002-16	4721006	16/4002 - CW AFT CABIN LH BULKHEAD REMOVAL AND INSTALLATION	NO CHARGE WO - ONLY FOR DOCUMENTATITON . USE INTERIOR ACCESS WO FOR BILLABLE TIME RESPECTFULLY.	
4002-17	4721027	17/4002 - CW AFT CABIN RH BULKHEAD REMOVAL AND INSTALLATION	NO CHARGE WO - ONLY FOR DOCUMENTATITON . USE INTERIOR ACCESS WO FOR BILLABLE TIME RESPECTFULLY.	
4002-18	4721034	18/4002 - CW LAVATORY VANITY W/CURIO ASSEMBLY REMOVAL AND INSTALLATION.	NO CHARGE WO - ONLY FOR DOCUMENTATITON . USE INTERIOR ACCESS WO FOR BILLABLE TIME RESPECTFULLY.	
4002-19	4721066	19/4002 - CW LAVATORY HEADLINER REMOVAL AND INSTALLATION.	NO CHARGE WO - ONLY FOR DOCUMENTATITON . USE INTERIOR ACCESS WO FOR BILLABLE TIME RESPECTFULLY.	
4002-20	4721067	20/4002 - CW LAVATORY TOILET ENCLOUSRE REMOVAL AND INSTALLATION.	NO CHARGE WO - ONLY FOR DOCUMENTATITON . USE INTERIOR ACCESS WO FOR BILLABLE TIME RESPECTFULLY.	
4002-21	4721143	21/4002 - CW BAGGAGE COMPARTMENT BULKHEADS REMOVAL AND INSTALLATION.	NO CHARGE WO - ONLY FOR DOCUMENTATITON . USE INTERIOR ACCESS WO FOR BILLABLE TIME RESPECTFULLY.	
4002-22	4721171	22/4002 - CW BAGGAGE COMPARTMENT PANELS REMOVAL AND INSTALLATION.	NO CHARGE WO - ONLY FOR DOCUMENTATITON . USE INTERIOR ACCESS WO FOR BILLABLE TIME RESPECTFULLY.	

Sequence #	4002	Aircraft SN #	6111	MWPWO #	2498069
WO #	2528784	Aircraft Reg #	XA-SOL	Parent WO #	2498069

CHILD WORK ORDER DETAILS

	WO #	Description	Corrective Action	AMENDED
4002-23	4721220	23/4002 - CW BAGGAGE COMPARTMENT HEADLINER REMOVAL AND INSTALLTION.	NO CHARGE WO - ONLY FOR DOCUMENTATITON . USE INTERIOR ACCESS WO FOR BILLABLE TIME RESPECTFULLY.	
4002-24	4721226	24/4002 - CW MISC. COCKPIT ITEMS REMOVAL AND INSTALLATION.	NO CHARGE WO - ONLY FOR DOCUMENTATITON . USE INTERIOR ACCESS WO FOR BILLABLE TIME RESPECTFULLY.	
4002-25	4721292	25/4002 - CW CABIN FLOORING (FLIGHT DECK , MAINCABIN , BAGGAGE) REMOVAL AND INSTALL	NO CHARGE WO - ONLY FOR DOCUMENTATITON . USE INTERIOR ACCESS WO FOR BILLABLE TIME RESPECTFULLY.	

FINDINGS DETAILS

Finding #	Long Description	Status	Reported By / Date	Defect Source / Disposition	Defect Type	Priority	Follow-up WO #
79061	Interior Access - CH650 Inspection Bundles Missing two ea fwd cutting table track rubbers.	CLOSED	B0141448 - Graciela Pino Feb 5, 2026 12:47 PM	MAINTENANCE 300-QA002	OTHER	3	4805713-INPRG

Sequence #	4002-1	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4707941	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2528784

4002-1	**WO #**	**4707941**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		No Log Entry	
01/4002 - CW EMERGENCY EQUIPMENT REMOVAL AND INSTALL FOR INSECTION ACCESS.				

Sequence #	4002-1	Aircraft SN #	6111	MWPWO #	2498069
WO #	4707941	Aircraft Reg #	XA-SOL	Parent WO #	2528784

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Removed life vest from R/H #1 seat REF : A/C 6111 SMM 25-21-01-000-801 PN: 63600-105 SN: L5944206	B1018553 - Joshua Jackson Feb 04, 2026 02:32 PM	
	Remove life vest from R/H #1 seat REF : A/C 6111 SMM 25-21-01-000-801 PN: 63600-105 SN: L5944206		Not Required	
	200			
	Install life vest into R/H #1 seat REF : A/C 6111 SMM 25-21-01-400-801 PN: 63600-105 SN: L5944206			
	300	Removed life vest from R/H #2 seat REF : A/C 6111 SMM 25-21-01-000-801 PN: 63600-105 SN: L5944207	B1018553 - Joshua Jackson Feb 04, 2026 02:32 PM	
	Remove life vest from R/H #2 seat REF : A/C 6111 SMM 25-21-01-000-801 PN: 63600-105 SN: L5944207		Not Required	
	400			
	Install life vest into R/H #2 seat REF : A/C 6111 SMM 25-21-01-400-801 PN: 63600-105 SN: L5944207			
	500	Removed life vest from L/H #1 seat REF : A/C 6111 SMM 25-21-01-000-801 PN: 63600-105 SN: L5944201	B1018553 - Joshua Jackson Feb 04, 2026 02:32 PM	
	Remove life vest from L/H #1 seat REF : A/C 6111 SMM 25-21-01-000-801 PN: 63600-105 SN: L5944201		Not Required	

Bombardier

Sequence #	4002-1	Aircraft SN #	6111	MWPWO #	2498069
WO #	4707941	Aircraft Reg #	XA-SOL	Parent WO #	2528784

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	600 Install life vest into L/H #1 seat REF : A/C 6111 SMM 25-21-01-400-801 PN: 63600-105 SN: L5944201			
	700 Remove life vest from L/H #2 seat REF : A/C 6111 SMM 25-21-01-000-801 PN: 63600-105 SN: L5944200	Removed life vest from L/H #2 seat REF : A/C 6111 SMM 25-21-01-000-801 PN: 63600-105 SN: L5944200	B1018553 - Joshua Jackson Feb 04, 2026 02:32 PM Not Required	
	800 Install life vest into L/H #2 seat REF : A/C 6111 SMM 25-21-01-400-801 PN: 63600-105 SN: L5944200			
	900 Remove Defibrillator from aft divan stowage box. In ref to AC6111 SMM 25-21-05-000-801	Removed Defibrillator from aft divan stowage box.In ref to AC6111 SMM 25-21-05-000-801 PN# 500247 SN#18G00002863	B1018553 - Joshua Jackson Feb 04, 2026 02:32 PM Not Required	
	1000 Install Defibrillator into aft divan stowage box. In ref to AC6111 SMM 25-21-05-000-801 PN# 500247 SN#18G00002863			
	1100 Remove Life raft from Divan FWD stowage box. In ref to AC6111 SMM 25-21-05-000-801	Removed Life raft from Divan FWD stowage box. In ref to AC6111 SMM 25-21-05-000-801 PN# 1015FASA-6K4-1-150 SN# 10UL-02627	B1018553 - Joshua Jackson Feb 04, 2026 02:32 PM Not Required	

Sequence #	4002-1	Aircraft SN #	6111	MWPWO #	2498069
WO #	4707941	Aircraft Reg #	XA-SOL	Parent WO #	2528784

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	1200 Install Life raft from Divan FWD stowage box. In ref to AC6111 SMM 25-21-05-400-801 PN# 1015FASA-6K4-1-150 SN# 10UL-02627			
	1300 Remove Life raft from Divan FWD stowage box. In ref to AC6111 SMM 25-21-05-000-801 PN# 1015FASA-6K4-1-150 SN# 10UL-02628	Removed Life raft from Divan FWD stowage box. In ref to AC6111 SMM 25-21-05-000-801 PN# 1015FASA-6K4-1-150 SN# 10UL-02628	B1018553 - Joshua Jackson Feb 04, 2026 02:32 PM Not Required	
	1400 Install Life raft To Divan FWD stowage box. In ref to AC6111 SMM 25-21-05-400-801 PN# 1015FASA-6K4-1-150 SN# 10UL-02628			
	1500 Remove fire extinguisher from aft divan stowage box REF: A/C 6111 SMM 25-21-05-000-801 PN# 466090 SN#D00726736	Removed fire extinguisher from aft divan stowage box REF: A/C 6111 SMM 25-21-05-000-801 PN# 466090 SN#D00726736	B1018553 - Joshua Jackson Feb 04, 2026 02:32 PM Not Required	
	1600 Install fire extinguisher To aft divan stowage box REF: A/C 6111 SMM 25-21-05-400-801 PN# 466090 SN#D00726736			

Sequence #	4002-1	Aircraft SN #	6111	MWPWO #	2498069
WO #	4707941	Aircraft Reg #	XA-SOL	Parent WO #	2528784

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	1700	Removed med kit from FWD wardrobe cabinet REF: A/C 6111 SMM 25-24-01-000-801 PN# 501240 SN# 040815013	B1018553 - Joshua Jackson Feb 04, 2026 02:32 PM	
	Remove med kit from FWD wardrobe cabinet REF: A/C 6111 SMM 25-24-01-000-801 PN# 501240 SN# 040815013		Not Required	
	1800			
	Install med kit from FWD wardrobe cabinet REF: A/C 6111 SMM 25-24-01-400-801 PN# 501240 SN# 040815013			
	1900	Removed first aid kit from FWD wardrobe cabinet REF: A/C 6111 SMM 25-24-01-000-801 PN# B212-DC SN# BA-C-314	B1018553 - Joshua Jackson Feb 04, 2026 02:32 PM	
	Remove first aid kit from FWD wardrobe cabinet REF: A/C 6111 SMM 25-24-01-000-801 PN# B212-DC SN# BA-C-314		Not Required	
	2000			
	Install first aid kit from FWD wardrobe cabinet REF: A/C 6111 SMM 25-24-01-400-801 PN# B212-DC SN# BA-C-314			
	2100	Removed L/H FWD cabin fire extinguisher REF: A/C 6111 SMM 25-23-01-000-801 PN# 30H673 SN# D-05889336	B1018553 - Joshua Jackson Feb 04, 2026 02:32 PM	
	Remove L/H FWD cabin fire extinguisher REF: A/C 6111 SMM 25-23-01-000-801 PN# 30H673 SN# D-05889336		Not Required	

Sequence #	4002-1	Aircraft SN #	6111	MWPWO #	2498069
WO #	4707941	Aircraft Reg #	XA-SOL	Parent WO #	2528784

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	2200 Install L/H FWD cabin fire extinguisher REF: A/C 6111 SMM 25-23-01-400-801 PN# 30H673 SN# D-05889336			
	2300 Remove cockpit fire extinguisher REF: CL650 AMM 26-23-01-000-801 PN# 30H673 SN# D-05889350	Removed cockpit fire extinguisher REF: CL650 AMM 26-23-01-000-801 PN# 30H673 SN# D-05889350	B1018553 - Joshua Jackson Feb 04, 2026 02:32 PM Not Required	
	2400 Install cockpit fire extinguisher REF: CL650 AMM 26-23-01-400-801 PN# 30H673 SN# D-05889350			
	2500 Remove life vest from FWD divan stowage box REF: A/C 6111 SMM 25-21-05-000-801 PN# 63600-105 SN# L5944209	Removed life vest from FWD divan stowage box REF: A/C 6111 SMM 25-21-05-000-801 PN# 63600-105 SN# L5944209	B1018553 - Joshua Jackson Feb 05, 2026 12:24 PM Not Required	
	2600 Install life vest from FWD divan stowage box REF: A/C 6111 SMM 25-21-05-400-801 PN# 63600-105 SN# L5944209			

Sequence #	4002-1	Aircraft SN #	6111	MWPWO #	2498069
WO #	4707941	Aircraft Reg #	XA-SOL	Parent WO #	2528784

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	2700	Removed life vest from FWD divan stowage box REF: A/C 6111 SMM 25-21-05-000-801 PN# 63600-105 SN# L5944208	B1018553 - Joshua Jackson Feb 05, 2026 12:24 PM	
	Remove life vest from FWD divan stowage box REF: A/C 6111 SMM 25-21-05-000-801 PN# 63600-105 SN# L5944208		Not Required	
	2800			
	Install life vest from FWD divan stowage box REF: A/C 6111 SMM 25-21-05-400-801 PN# 63600-105 SN# L5944208			
	2900	Removed Life vest from FWD Double seat inboard REF: A/C 6111 SMM 25-21-03-000-801 PN# 63600-105 SN# L5944202	B1018553 - Joshua Jackson Feb 05, 2026 12:24 PM	
	Remove Life vest from FWD Double seat inboard REF: A/C 6111 SMM 25-21-03-000-801 PN# 63600-105 SN# L5944202		Not Required	
	3000			
	Install Life vest from FWD Double seat inboard REF: A/C 6111 SMM 25-21-03-400-801 PN# 63600-105			
	3100	Removed Life vest from FWD Double seat outboard REF: A/C 6111 SMM 25-21-03-000-801 PN# 63600-105 SN# L5944203	B1018553 - Joshua Jackson Feb 05, 2026 12:24 PM	
	Remove Life vest from FWD Double seat outboard REF: A/C 6111 SMM 25-21-03-000-801 PN# 63600-105 SN# L5944203		Not Required	

Sequence #	4002-1	Aircraft SN #	6111	MWPWO #	2498069
WO #	4707941	Aircraft Reg #	XA-SOL	Parent WO #	2528784

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	3200 Install Life vest from FWD Double seat outboard REF: A/C 6111 SMM 25-21-03-400-801 PN# 63600-105 SN# L5944203			
	3300 Remove Life vest from AFT Double seat inboard REF: A/C 6111 SMM 25-21-03-000-801 PN# 63600-105 SN# L5944204	Removed Life vest from AFT Double seat inboard REF: A/C 6111 SMM 25-21-03-000-801 PN# 63600-105 SN# L5944204	B1018553 - Joshua Jackson Feb 05, 2026 12:24 PM Not Required	
	3400 Install Life vest from AFT Double seat inboard REF: A/C 6111 SMM 25-21-03-400-801 PN# 63600-105 SN# L5944204			
	3500 Remove Life vest from AFT Double seat outboard REF: A/C 6111 SMM 25-21-03-000-801 PN# 63600-105 SN# L5944205	Removed Life vest from AFT Double seat outboard REF: A/C 6111 SMM 25-21-03-000-801 PN# 63600-105 SN# L5944205	B1018553 - Joshua Jackson Feb 05, 2026 12:24 PM Not Required	
	3600 Install Life vest from AFT Double seat outboard REF: A/C 6111 SMM 25-21-03-400-801 PN# 63600-105 SN# L5944205			

Sequence #	4002-1	Aircraft SN #	6111	MWPWO #	2498069
WO #	4707941	Aircraft Reg #	XA-SOL	Parent WO #	2528784

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	3700	Removed hardware for 4 single cabin seats and 2 cabin double seat Ref CL-650 SMM TASK 25-21-01-000-801	B0141448 - Graciela Pino Feb 05, 2026 09:59 PM	
	Remove hardware for 4 single cabin seats and 2 cabin double seat Ref CL-650 SMM TASK 25-21-01-000-801		Not Required	
	3800			
	Install hardware for 4 single cabin seats and 2 cabin double seat Ref CL-650 SMM TASK 25-21-01-400-801			
	3900	Removed life vest from AFT divan stowage box REF: A/C 6111 SMM 25-21-05-000-801 PN# 63600-105 SN# L5944234	B1019045 - Isaac Pallanes Feb 10, 2026 09:50 PM	
	Remove life vest from AFT divan stowage box REF: A/C 6111 SMM 25-21-05-000-801 PN# 63600-105 SN# L5944234		Not Required	
	4000			
	Install life vest from AFT divan stowage box REF: A/C 6111 SMM 25-21-05-000-801 PN# 63600-105 SN# L5944234			
	4100	Removed life vest from AFT divan stowage box REF: A/C 6111 SMM 25-21-05-000-801 PN# 63600-105 SN# L5944234	B1019045 - Isaac Pallanes Feb 10, 2026 09:50 PM	
	Remove life vest from AFT divan stowage box REF: A/C 6111 SMM 25-21-05-000-801 PN# 63600-105 SN# L5944234		Not Required	
	4200			
	Install life vest from AFT divan stowage box REF: A/C 6111 SMM 25-21-05-400-801 PN# 63600-105 SN# L5944234			

Sequence #	4002-1	Aircraft SN #	6111	MWPWO #	2498069
WO #	4707941	Aircraft Reg #	XA-SOL	Parent WO #	2528784

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	4300			

Sequence #	4002-2	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4720489	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2528784

			LOG BOOK VERBIAGE	Deferrals
4002-2	**WO #**	**4720489**		
	SAP SVO #		No Log Entry	
02/4002 - CW CABIN SEATING REMOVAL AND INSTALLATION				

Sequence #	4002-2	Aircraft SN #	6111	MWPWO #	2498069
WO #	4720489	Aircraft Reg #	XA-SOL	Parent WO #	2528784

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Removed LH#1 seat PN 2524.014.01-3312C.22 SN 170926-02 REF CL-650 SMM TASK 25-21-01-000-801	B0141448 - Graciela Pino Feb 06, 2026 12:00 AM	
	Remove LH#1 seat PN 2524.014.01-3312C.22 SN 170926-02 REF CL-650 SMM TASK 25-21-01-000-801		Not Required	
	200			
	INSTALL LH#1 seat PN 2524.014.01-3312C.22 SN 170926-02 REF CL-650 SMM TASK 25-21-01-400-801			
	300	Removed LH#2 seat PN 2524.014.01-3311B.22 SN 170926-04 REF CL-650 SMM TASK 25-21-01-000-801	B0141448 - Graciela Pino Feb 06, 2026 12:00 AM	
	Remove LH#2 seat PN 2524.014.01-3311B.22 SN 170926-04 REF CL-650 SMM TASK 25-21-01-000-801		Not Required	
	400			
	INSTALL LH#2 seat PN 2524.014.01-3311B.22 SN 170926-04 REF CL-650 SMM TASK 25-21-01-400-801			
	500	Removed LH#3 double seat PN 2424.015.01-811C.22 PN 170926-07 Ref CL-650 SMM TASK 25-21-03-000-801	B0141448 - Graciela Pino Feb 06, 2026 12:00 AM	
	Remove LH#3 double seat PN 2424.015.01-811C.22 PN 170926-07 Ref CL-650 SMM TASK 25-21-03-000-801		Not Required	
	600			
	Install LH#3 double seat PN 2424.015.01-811C.22 PN 170926-07 Ref CL-650 SMM TASK 25-21-03-400-801			

Sequence #	4002-2	Aircraft SN #	6111	MWPWO #	2498069
WO #	4720489	Aircraft Reg #	XA-SOL	Parent WO #	2528784

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	700	Removed LH#4 double seat PN 2424.015.01-810B.22 PN 170926-06 Ref CL-650 SMM TASK 25-21-03-000-801	B0141448 - Graciela Pino Feb 06, 2026 12:00 AM	
	Remove LH#4 double seat PN 2424.015.01-810B.22 PN 170926-06 Ref CL-650 SMM TASK 25-21-03-000-801		Not Required	
	800			
	Install LH#4 double seat PN 2424.015.01-810B.22 PN 170926-06 Ref CL-650 SMM TASK 25-21-03-400-801			
	900	Removed RH#1 seat PN 2524.014.01-3313D.22 SN 170926-03 REF CL-650 SMM TASK 25-21-01-000-801	B0141448 - Graciela Pino Feb 06, 2026 12:00 AM	
	Remove RH#1 seat PN 2524.014.01-3313D.22 SN 170926-03 REF CL-650 SMM TASK 25-21-01-000-801		Not Required	
	1000			
	Install RH#1 seat PN 2524.014.01-3313D.22 SN 170926-03 REF CL-650 SMM TASK 25-21-01-400-801			
	1100	Removed RH#2 seat PN 2524.014.01-3338A.22 SN 170926-05 REF CL-650 SMM TASK 25-21-01-000-801	B0141448 - Graciela Pino Feb 06, 2026 12:00 AM	
	Remove RH#2 seat PN 2524.014.01-3338A.22 SN 170926-05 REF CL-650 SMM TASK 25-21-01-000-801		Not Required	
	1200			
	Install RH#2 seat PN 2524.014.01-3338A.22 SN 170926-05 REF CL-650 SMM TASK 25-21-01-400-801			

Sequence #	4002-2	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4720489	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2528784

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	1300	Removed seat studs REF CL-650 SMM TASK 25-21-01-000-801	B0141448 - Graciela Pino Feb 06, 2026 05:22 AM	
	Remove seat studs REF CL-650 SMM TASK 25-21-01-000-801		Not Required	
	1400			
	Install seat studs REF CL-650 SMM TASK 25-21-01-000-801			

Sequence #	4002-3	Aircraft SN #	6111	MWPWO #	2498069
WO #	4720571	Aircraft Reg #	XA-SOL	Parent WO #	2528784

4002-3	WO #	4720571	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		No Log Entry	
03/4002 - CW LH FWD CABIN BULKHEAD REMOVAL AND INSTALLATION.				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Removed LH FWD Cabin AFT Bulkhead Partition Ref: CL-650 SMM TASK 25-23-01-000-801	B1019231 - Ivan Bojorquez Feb 08, 2026 08:49 PM	
	Remove LH FWD Cabin AFT Bulkhead Partition Ref: CL-650 SMM TASK 25-23-01-000-801		Not Required	
	200			
	Install LH FWD Cabin AFT Bulkhead Partition Ref: CL-650 SMM TASK 25-23-01-400-801			
	300	Removed LH FWD Cabin FWD Bulkhead Partition Ref: CL-650 SMM TASK 25-23-01-000-802	B1019231 - Ivan Bojorquez Feb 08, 2026 08:49 PM	
	Remove LH FWD Cabin FWD Bulkhead Partition Ref: CL-650 SMM TASK 25-23-01-000-802		Not Required	
	400			
	Install LH FWD Cabin FWD Bulkhead Partition Ref: CL-650 SMM TASK 25-23-01-400-802			
	500	Removed LH FWD Cabin Bulkhead Bullnose panel Ref: CL-650 SMM TASK 25-23-01-000-801	B1019231 - Ivan Bojorquez Feb 08, 2026 08:49 PM	
	Remove LH FWD Cabin Bulkhead Bullnose panel Ref: CL-650 SMM TASK 25-23-01-000-801		Not Required	
	600			
	Install LH FWD Cabin Bulkhead Bullnose panel Ref: CL-650 SMM TASK 25-23-01-400-801			

Bombardier

Sequence #	4002-4	Aircraft SN #	6111	MWPWO #	2498069
WO #	4720581	Aircraft Reg #	XA-SOL	Parent WO #	2528784

4002-4	WO #	4720581	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		No Log Entry	
04/4002 - CW RH FWD CABIN BULKHEAD REMOVAL AND INSTALLATION.				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Removed FWD Cabin R/H AFT Bulkhead Partition Ref: CL-650 SMM TASK 25-23-01-000-803	B1019231 - Ivan Bojorquez Feb 11, 2026 01:48 AM	
	Remove FWD Cabin R/H AFT Bulkhead Partition Ref: CL-650 SMM TASK 25-23-01-000-803		Not Required	
	200			
	Install FWD Cabin R/H AFT Bulkhead Partition Ref: CL-650 SMM TASK 25-23-01-400-803			
	300	Removed FWD Cabin R/H FWD Bulkhead Partition Ref: CL-650 SMM TASK 25-23-01-000-803	B1019231 - Ivan Bojorquez Feb 11, 2026 01:48 AM	
	Remove FWD Cabin R/H FWD Bulkhead Partition Ref: CL-650 SMM TASK 25-23-01-000-803		Not Required	
	400			
	Install FWD Cabin R/H FWD Bulkhead Partition Ref: CL-650 SMM TASK 25-23-01-400-803			
	500	Removed Fwd Cabin Bulkheads Spreader Ref: CL-650 SMM TASK 25-23-01-000-803	B1019231 - Ivan Bojorquez Feb 11, 2026 07:03 AM	
	Remove Fwd Cabin Bulkheads Spreader Ref: CL-650 SMM TASK 25-23-01-000-803		Not Required	
	600			
	Install Fwd Cabin Bulkheads Spreader Ref: CL-650 SMM TASK 25-23-01-400-803			

Sequence #	4002-5	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4720638	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2528784

4002-5	**WO #**	**4720638**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		No Log Entry	
05/4002- CW GALLEY TOWER REMOVAL AND INSTALLATION				

Sequence #	4002-5	Aircraft SN #	6111	MWPWO #	2498069
WO #	4720638	Aircraft Reg #	XA-SOL	Parent WO #	2528784

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	removed customer loose items from galley tower	B1015989 - Victor Palazuelos Feb 11, 2026 08:15 PM	
	Remove customer loose items from galley tower		Not Required	
	200			
	Install customer loose items on galley tower			
	300	Removed Galley Oven Ref: CL-650 SMM TASK 25-30-03-000-801	B1019231 - Ivan Bojorquez Feb 11, 2026 07:00 AM	
	Remove Galley Oven Ref: CL-650 SMM TASK 25-30-03-000-801		Not Required	
	301			
	Remove Galley Oven Ref: CL-650 SMM TASK 25-30-03-000-801		Not Required	09
	400			
	Install Galley Oven Ref: CL-650 SMM TASK 25-30-03-100-801			
	500	Removed galley microwave IAW ch650 smm 25-30-03-000-801	B1015989 - Victor Palazuelos Feb 11, 2026 08:15 PM	
	Remove galley microwave IAW ch650 smm 25-30-03-000-801		Not Required	
	600			
	Install galley microwave IAW ch650 smm 25-30-03-400-801			
	700	Removed oven bezel IAW ch650 smm 25-30-01-000-804	B1015989 - Victor Palazuelos Feb 11, 2026 08:15 PM	
	Remove oven bezel IAW ch650 smm 25-30-01-000-803		Not Required	
	800			
	Install oven bezel IAW ch650 smm 25-30-01-400-804			

Sequence #	4002-5	Aircraft SN #	6111	MWPWO #	2498069
WO #	4720638	Aircraft Reg #	XA-SOL	Parent WO #	2528784

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	900	Removed microwave bezel IAW ch650 smm 25-30-01-000-804	B1015989 - Victor Palazuelos Feb 11, 2026 08:15 PM	
	Remove microwave bezel IAW ch650 smm 25-30-01-000-804		Not Required	
	1000			
	Install microwave bezel IAW ch650 smm 25-30-01-400-804			
	1100	Removed oven LWR pnl IAW ch650 smm 25-30-01-000-804	B1015989 - Victor Palazuelos Feb 11, 2026 08:15 PM	
	Remove oven LWR pnl IAW ch650 smm 25-30-01-000-804		Not Required	
	1200			
	Install oven LWR pnl IAW ch650 smm 25-30-01-400-804			
	1300	Removed Galley tower Ref CL-650 SMM TASK 25-30-01-000-804	B0141448 - Graciela Pino Feb 11, 2026 11:51 PM	
	Remove Galley tower Ref CL-650 SMM TASK 25-30-01-000-804		Not Required	
	1400			
	Install Galley tower Ref CL-650 SMM TASK 25-30-01-400-804			
	1500	Removed top shelf and C/O with frame panel on galley tower Ref CL-650 SMM TASK 25-30-01-000-804	B0141448 - Graciela Pino Feb 11, 2026 11:51 PM	
	Remove top shelf and C/O with frame panel on galley tower Ref CL-650 SMM TASK 25-30-01-000-804		Not Required	
	1600			
	Install top shelf and C/O with frame panel on galley tower Ref CL-650 SMM TASK 25-30-01-400-804			

Sequence #	4002-5	Aircraft SN #	6111	MWPWO #	2498069
WO #	4720638	Aircraft Reg #	XA-SOL	Parent WO #	2528784

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	1700	Removed 2 C/O panels from galley tower Ref CL-650 SMM TASK 25-30-01-000-804	B0141448 - Graciela Pino Feb 11, 2026 11:51 PM	
	Remove 2 C/O panels from galley tower Ref CL-650 SMM TASK 25-30-01-000-804		Not Required	
	1800			
	Install 2 C/O panels from galley tower Ref CL-650 SMM TASK 25-30-01-400-804			
	1900	Removed 2 ea sliding doors from galley tower Ref CL-650 SMM TASK 25-30-01-000-804	B0141448 - Graciela Pino Feb 11, 2026 11:51 PM	
	Remove 2 ea sliding doors from galley tower Ref CL-650 SMM TASK 25-30-01-000-804		Not Required	
	2000			
	Install 2 ea sliding doors from galley tower Ref CL-650 SMM TASK 25-30-01-400-804			
	2100	Removed EIU from Galley tower PNEIU3009-001-001 SN 000968. Ref CL-650 SMM TASK 44-10-09-000-801	B0141448 - Graciela Pino Feb 11, 2026 11:51 PM	
	Remove EIU from Galley tower PNEIU3009-001-001 SN 000968. Ref CL-650 SMM TASK 44-10-09-000-801		Not Required	
	2200			
	Install EIU from Galley tower PN EIU3009-001-001 SN 000968. Ref CL-650 SMM TASK 44-10-09-400-801			
	2300	Removed Oven control PN 9050029-01 SN 17-04-05909 Ref CL-605 SMM TASK 25-30-03-000-801	B0141448 - Graciela Pino Feb 11, 2026 11:51 PM	
	Remove Oven control PN 9050029-01 SN 17-04-05909 Ref CL-605 SMM TASK 25-30-03-000-801		Not Required	

Sequence #	4002-5	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4720638	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2528784

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	2400			
	Install Oven control PN 9050029-01 SN 17-04-05909 Ref CL-605 SMM TASK 25-30-03-400-801			

REMOVE AND RE-INSTALL DETAILS

	Removed Part # / Removed Serial #	Removed By	Removed - Part Description	Reference	Installed Part # / Installed Serial #	Installed By
	Removed Status	**Removed Date-Time**	**Position**	**Installed Part Status**	**Installed Part Description**	**Installed Date-Time**
	910-0011-01 16-12-05308	B1015989 - Victor Palazuelos	microwave	access		
	SERVICEABLE	Feb 11, 2026 7:23 AM				

Sequence #	4002-6	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4720641	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2528784

4002-6	**WO #**	**4720641**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		No Log Entry	
06/4002 - CW GALLEY UPPER REMOVAL AND INSTALLATION				

Bombardier

Sequence #	4002-6	Aircraft SN #	6111	MWPWO #	2498069
WO #	4720641	Aircraft Reg #	XA-SOL	Parent WO #	2528784

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Removed 2 ea top galley cutting boards Ref CL-650 SMM TASK 25-30-01-000-802		
	Remove 2 ea top galley cutting boards Ref CL-650 SMM TASK 25-30-01-000-802		Not Required	
	200			
	Install 2 ea top galley cutting boards Ref CL-650 SMM TASK 25-30-01-400-802			
	300	Removed drawer cubby box from upper galley Ref CL-650 SMM TASK 25-30-01-000-802		
	Remove drawer cubby box from upper galley Ref CL-650 SMM TASK 25-30-01-000-802		Not Required	
	400			
	install drawer cubby box from upper galley Ref CL-650 SMM TASK 25-30-01-400-802			
	500	Removed upper galley sink water faucet Ref CL-650 SMM TASK 25-30-01-000-802		
	Remove upper galley sink water faucet Ref CL-650 SMM TASK 25-30-01-000-802		Not Required	
	600			
	Install upper galley sink water faucet Ref CL-650 SMM TASK 25-30-01-400-802			
	700	Removed upper galley countertop Ref CL-650 SMM TASK 25-30-01-000-802		
	Remove upper galley countertop Ref CL-650 SMM TASK 25-30-01-000-802		Not Required	
	800			
	Install upper galley countertop Ref CL-650 SMM TASK 25-30-01-400-802			
	900	Removed expresso maker from upper galley PN 925-0018-01 SN 16-10-04945 Ref CL-650 SMM TASK 25-30-03-000-801		
	Remove expresso maker from upper galley PN 925-0018-01 SN 16-10-04945 Ref CL-650 SMM TASK 25-30-03-000-801		Not Required	

Bombardier

Sequence #	4002-6	Aircraft SN #	6111	MWPWO #	2498069
WO #	4720641	Aircraft Reg #	XA-SOL	Parent WO #	2528784

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	1000			
	Install expresso maker from upper galley PN 925-0018-01 SN 16-10-04945 Ref CL-650 SMM TASK 25-30-03-400-80			
	1100	Removed nespresso machine from upper galley. Ref BAS 00270032		
	Remove nespresso machine from upper galley. Ref BAS 00270032		Not Required	
	1200			
	Install nespresso machine from upper galley. Ref BAS 00270032			
	1300	Removed galley header Ref CL-650 SMM TASK 25-15-03-000-801		
	Remove galley header Ref CL-650 SMM TASK 25-15-03-000-801		Not Required	
	1400			
	Install galley header Ref CL-650 SMM TASK SMM TASK 25-15-03-400-801			
	1500	Removed Galley tower header Ref SPM 20-21-00-910-80		
	Remove Galley tower header Ref SPM 20-21-00-910-801		Not Required	
	1600			
	Install Galley tower header Ref SPM 20-21-00-910-80			
	1700	Removed upper galley 2ea sliding doors Ref CL-650 SMM TASK 25-30-01-000-802		
	Remove upper galley 2ea sliding doors Ref CL-650 SMM TASK 25-30-01-000-802		Not Required	
	1800			
	Install upper galley 2ea sliding doors Ref CL-650 SMM TASK 25-30-01-400-802			

Sequence #	4002-6	Aircraft SN #	6111	MWPWO #	2498069
WO #	4720641	Aircraft Reg #	XA-SOL	Parent WO #	2528784

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	1900	Removed galley sink Ref CL-650 SMM TASK 25-30-01-000-802		
	Remove galley sink Ref CL-650 SMM TASK 25-30-01-000-802		Not Required	
	2000			
	Install galley sink Ref CL-650 SMM TASK 25-30-01-400-802			
	2100	Removed Upper Galley Ref: CL-650 SMM TASK 25-30-01-000-802	B1019231 - Ivan Bojorquez Feb 11, 2026 06:55 AM	
	Remove Upper Galley Ref: CL-650 SMM TASK 25-30-01-000-802		Not Required	
	2200			
	Install Upper Galley Ref: CL-650 SMM TASK 25-30-01-400-802			
	2300	Removed Circuit Breaker Panel at Upper Galley Ref: CL-650 SMM TASK 25-30-01-000-802	B1019231 - Ivan Bojorquez Feb 11, 2026 06:55 AM	
	Remove Circuit Breaker Panel at Upper Galley Ref: CL-650 SMM TASK 25-30-01-000-802		Not Required	
	2400			
	Install Circuit Breaker Panel at Upper Galley Ref: CL-650 SMM TASK 25-30-01-400-802			

Sequence #	4002-7	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4720644	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2528784

4002-7	**WO #**	**4720644**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		No Log Entry	
07/4002 - CW GALLEY LOWER REMOVAL AND INSTALLATION				

Sequence #	4002-7	Aircraft SN #	6111	MWPWO #	2498069
WO #	4720644	Aircraft Reg #	XA-SOL	Parent WO #	2528784

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Removed 5 ea lower galley drawers Ref Cl-650 SMM TASK 25-30-01-000-803	B1019045 - Isaac Pallanes Feb 11, 2026 07:27 PM	
	Remove 5 ea lower galley drawers Ref Cl-650 SMM TASK 25-30-01-000-803		Not Required	
	200			
	Install 5 ea lower galley drawers Ref Cl-650 SMM TASK 25-30-01-400-803			
	300	Removed Ice drawer Ref CL-650 SMM TASK 25-30-01-000-80	B1019045 - Isaac Pallanes Feb 11, 2026 07:27 PM	
	Remove Ice drawer Ref CL-650 SMM TASK 25-30-01-000-80		Not Required	
	400			
	Install Ice drawer Ref CL-650 SMM TASK 25-30-01-400-803		Not Required	
	500	Removed Jump seat at lower galley Ref CL-650 SMM 25-21-07-000-801 PN: JS600A-(RH1) SN: PJ3519	B1001641 - Alonzo Rodriguez Feb 08, 2026 11:38 PM	
	Remove Jump seat at lower galley Ref CL-650 SMM 25-21-07-000-801		Not Required	
	600			
	Install Jump seat at lower galley Ref CL-650 SMM 25-21-07-400-801 PN: JS600A-(RH1) SN: PJ3519			
	700	removed customer loose cups and plates from galley	B1015989 - Victor Palazuelos Feb 11, 2026 08:24 PM	
	Remove customer loose cups and plates from galley		Not Required	
	800			
	Install customer loose cups and plates in galley			

Sequence #	4002-7	Aircraft SN #	6111	MWPWO #	2498069
WO #	4720644	Aircraft Reg #	XA-SOL	Parent WO #	2528784

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	900	Removed lower galley IAW ch650 smm 25-30-01-000-803	B1015989 - Victor Palazuelos Feb 11, 2026 08:24 PM	
	Remove lower galley IAW ch650 smm 25-30-01-000-803		Not Required	
	1000			
	Install lower galley IAW ch650 smm 25-30-01-400-803			
	1100	Removed lower galley water heater access pnl IAW ch650 smm 25-30-01-000-803	B1015989 - Victor Palazuelos Feb 11, 2026 08:24 PM	
	Remove lower galley water heater access pnl IAW ch650 smm 25-30-01-000-803		Not Required	
	1200			
	Install lower galley water heater access pnl IAW ch650 smm 25-30-01-400-803			
	1300	Removed lower galley trash can upper pnl IAW ch650 smm 25-30-01-000-803	B1015989 - Victor Palazuelos Feb 11, 2026 08:25 PM	
	Remove lower galley trash can upper pnl IAW ch650 smm 25-30-01-000-803		Not Required	
	1400			
	Install lower galley water heater access pnl IAW ch650 smm 25-30-01-400-803			

Sequence #	4002-8	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4720649	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2528784

4002-8	**WO #**	**4720649**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		No Log Entry	
08/4002 - CW ENTRY HEADLINER REMOVAL AND INSTALLATON				

Sequence #	4002-8	Aircraft SN #	6111	MWPWO #	2498069
WO #	4720649	Aircraft Reg #	XA-SOL	Parent WO #	2528784

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Removed entry acoustic curtain Ref CL-650 SMM TASK 25-15-01-000-801	B0141448 - Graciela Pino Feb 05, 2026 11:24 PM	
	Remove entry acoustic curtain Ref CL-650 SMM TASK 25-15-01-000-801		Not Required	
	200			
	Install entry acoustic curtain Ref CL-650 SMM TASK 25-15-01-400-801			
	300	Removed entry headliner Ref CL-650 SMM TASK 25-15-03-000-801	B1019231 - Ivan Bojorquez Feb 08, 2026 08:37 PM	
	Remove entry headliner Ref CL-650 SMM TASK 25-15-03-000-801		Not Required	
	400			
	Install entry headliner Ref CL-650 SMM TASK 25-15-03-400-801			
	500	Removed Entry to Cabin Curtain Track and cover Ref: CL-650 SMM TASK 25-15-03-000-801	B1019231 - Ivan Bojorquez Feb 08, 2026 08:37 PM	
	Remove Entry to Cabin Curtain Track and cover Ref: CL-650 SMM TASK 25-15-03-000-801		Not Required	
	600			
	Install Entry to Cabin Curtain Track and cover Ref: CL-650 SMM TASK 25-15-03-400-801			
	700	Removed Entry headliner Filler Ref: CL-650 SMM TASK 25-15-03-000-801	B1019231 - Ivan Bojorquez Feb 08, 2026 08:37 PM	
	Remove Entry headliner Filler Ref: CL-650 SMM TASK 25-15-03-000-801		Not Required	
	800			
	Install Entry headliner Filler Ref: CL-650 SMM TASK 25-15-03-400-801			

Sequence #	4002-8	Aircraft SN #	6111	MWPWO #	2498069
WO #	4720649	Aircraft Reg #	XA-SOL	Parent WO #	2528784

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	900	Removed Entry headliner door shroud Ref: CL-650 SMM TASK 25-15-03-000-801	B1019231 - Ivan Bojorquez Feb 08, 2026 08:37 PM	
	Remove Entry headliner door shroud Ref: CL-650 SMM TASK 25-15-03-000-801		Not Required	
	1000			
	Install Entry headliner door shroud Ref: CL-650 SMM TASK 25-15-03-400-801			

Sequence #	4002-9	Aircraft SN #	6111	MWPWO #	2498069
WO #	4720664	Aircraft Reg #	XA-SOL	Parent WO #	2528784

4002-9	WO #	4720664	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		No Log Entry	
09/4002 - CW LH SIDE PANEL REMOVAL AND INSTALLATION				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Removed L/H Fwd PSU Ref CL-650 SMM 25-26-03-000-801	B1001500 - Victor Gallego Feb 09, 2026 05:02 PM	
	Remove L/H Fwd PSU Ref CL-650 SMM 25-26-03-000-801		Not Required	
	200			
	Install L/H Fwd PSU Ref CL-650 SMM 25-26-03-400-801			
	300	Removed L/H Aft PSU Ref CL-650 SMM 25-26-03-000-801	B1001500 - Victor Gallego Feb 09, 2026 05:02 PM	
	Remove L/H Aft PSU Ref CL-650 SMM 25-26-03-000-801		Not Required	
	400			
	Install L/H Aft PSU Ref CL-650 SMM 25-26-03-400-801			
	500	Removed LH SIDE PANEL REF CL 650 SMM 25-26-13-000-801	B1017008 - Cesar Castro Feb 09, 2026 07:33 PM	
	Remove LH SIDE PANEL REF CL 650 SMM 25-26-13-000-801		Not Required	
	600			
	Install LH SIDE PANEL REF CL 650 SMM 25-26-13-400-801			

Sequence #	4002-9	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4720664	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2528784

FINDINGS DETAILS

Finding #	Long Description	Status	Reported By / Date	Defect Source / Disposition	Defect Type	Priority	Follow-up WO #
79499	During removal found L/H and R/H sidewall PSU padding disbounding	CLOSED	B1001500 - Victor Gallego Feb 9, 2026 9:58 AM	MAINTENANCE 300-QA002	OTHER	3	4748820-APPR

Sequence #	4002-10	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4720685	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2528784

4002-10	**WO #**	**4720685**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		No Log Entry	
10/4002 - CW RH SIDE PANEL REMOVAL AND INSTALLATION				

Sequence #	4002-10	Aircraft SN #	6111	MWPWO #	2498069
WO #	4720685	Aircraft Reg #	XA-SOL	Parent WO #	2528784

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Removed RH Fwd PSU Ref CL-650 SMM 25-26-03-000-801	B1017008 - Cesar Castro Feb 09, 2026 05:10 PM	
	Remove RH Fwd PSU Ref CL-650 SMM 25-26-03-000-801		Not Required	
	200			
	Install RH Fwd PSU Ref CL-650 SMM 25-26-03-400-801			
	300	Removed RH Aft PSU Ref CL-650 SMM 25-26-03-000-801	B1017008 - Cesar Castro Feb 09, 2026 05:10 PM	
	Remove RH Aft PSU Ref CL-650 SMM 25-26-03-000-801		Not Required	
	400			
	Install RH Aft PSU Ref CL-650 SMM 25-26-03-400-801			
	500	Removed RH side wall panel Ref CL-650 SMM TASK 25-26-13-000-801	B0141448 - Graciela Pino Feb 11, 2026 03:22 AM	
	Remove RH side wall panel Ref CL-650 SMM TASK 25-26-13-000-801		Not Required	
	600			
	Install RH side wall panel Ref CL-650 SMM TASK 25-26-13-400-801			
	700	Removed R/H Emer. Door Side Panel Ref CL-650 SPM 20-21-00-910-801	B1001500 - Victor Gallego Mar 04, 2026 10:05 PM	
	Remove R/H Emer. Door Side Panel Ref CL-650 SPM 20-21-00-910-801		Not Required	
	800			
	Install R/H Emer. Door Side Panel Ref CL-650 SPM 20-21-00-910-801			

Sequence #	4002-10	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4720685	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2528784

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	900	Removed R/H Emer. Door Window Bucket Ref CL-650 SPM 20-21-00-910-801	B1001500 - Victor Gallego Mar 04, 2026 10:05 PM	
	Remove R/H Emer. Door Window Bucket Ref CL-650 SPM 20-21-00-910-801		Not Required	
	1000			
	Install R/H Emer. Door Window Bucket Ref CL-650 SPM 20-21-00-910-801			

FINDINGS DETAILS

Finding #	Long Description	Status	Reported By / Date	Defect Source / Disposition	Defect Type	Priority	Follow-up WO #
79515	Upon discovery it was found lanyard on RH Aft Psu is broken	CLOSED	B1017008 - Cesar Castro Feb 9, 2026 10:34 AM	MAINTENANCE 300-QA002	OTHER	3	4805026-APPR

Sequence #	4002-11	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4720725	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2528784

4002-11	**WO #**	**4720725**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		No Log Entry	
11/4002 - CW LH FWD WARDROBE CABINET REMOVAL AND INSTALLATION.				

Sequence #	4002-11	Aircraft SN #	6111	MWPWO #	2498069
WO #	4720725	Aircraft Reg #	XA-SOL	Parent WO #	2528784

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Removed Fwd wardrobe curtain Ref CL-650 SMM TASK 25-24-01-000-801	B0141448 - Graciela Pino Feb 05, 2026 10:51 PM	
	Remove Fwd wardrobe curtain Ref CL-650 SMM TASK 25-24-01-000-801		Not Required	
	200			
	Install Fwd wardrobe curtain Ref CL-650 SMM TASK 25-24-01-400-801			
	300	Removed RH and LH entry banana trims Ref BAS 00270032	B0141448 - Graciela Pino Feb 05, 2026 10:51 PM	
	Remove RH and LH entry banana trims Ref BAS 00270032		Not Required	
	400			
	INSTALL RH and LH entry banana trims Ref BAS 00270032			
	500	Removed customer goods from fwd wardrobe, including flashlight. Ref BAS 00270032	B0141448 - Graciela Pino Feb 09, 2026 10:02 PM	
	Remove customer goods from fwd wardrobe, including flashlight. Ref BAS 00270032		Not Required	
	600			
	Install customer goods from fwd wardrobe, including flashlight. Ref BAS 00270032			
	700	Removed OBSERVER OXYGEN SYSTEM MASK PN MC10-13-03 SER 110854 Ref CL-650 SMM TASK 35-11-01-000-801	B0141448 - Graciela Pino Feb 09, 2026 10:02 PM	
	Remove OBSERVER OXYGEN SYSTEM MASK PN MC10-13-03 SER 110854 Ref CL-650 SMM TASK 35-11-01-000-801		Not Required	

Sequence #	4002-11	Aircraft SN #	6111	MWPWO #	2498069
WO #	4720725	Aircraft Reg #	XA-SOL	Parent WO #	2528784

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	800			
	Install OBSERVER OXYGEN SYSTEM MASK PN MC10-13-03 SER 110854 Ref CL-650 SMM TASK 35-11-01-400-801			
	900	Removed 13ea fwd wardrobe C/O panels Ref CL-650 SMM TASK 25-24-13-000-801	B0141448 - Graciela Pino Feb 10, 2026 03:47 AM	
	Remove 13ea fwd wardrobe C/O panels Ref CL-650 SMM TASK 25-24-13-000-801		Not Required	
	1000			
	Install 13ea fwd wardrobe C/O panels Ref CL-650 SMM TASK 25-24-13-400-801			
	1100	Removed fwd wardrobe heade Ref CL-650 SMM TASK 25-24-01-000-801	B0141448 - Graciela Pino Feb 10, 2026 03:47 AM	
	Remove fwd wardrobe heade Ref CL-650 SMM TASK 25-24-01-000-801		Not Required	
	1200			
	Install fwd wardrobe headed Ref CL-650 SMM TASK 25-24-01-400-801			
	1300	Removed fwd wardrobe Ref CL-650 SMM TASK 25-24-01-000-801	B0141448 - Graciela Pino Feb 10, 2026 03:47 AM	
	Remove fwd wardrobe Ref CL-650 SMM TASK 25-24-01-000-801		Not Required	
	1400			
	Install fwd wardrobe Ref CL-650 SMM TASK 25-24-01-400-801			

Sequence #	4002-11	Aircraft SN #	6111	MWPWO #	2498069
WO #	4720725	Aircraft Reg #	XA-SOL	Parent WO #	2528784

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	1500	REMOVED DIGITAL MEDIA PLAYER PN BDP3009-001-001 SN 000649 REF CL-650 SMM TASK 44-22-01-000-801	B0141448 - Graciela Pino Feb 10, 2026 03:47 AM	
	REMOVE DIGITAL MEDIA PLAYER PN BDP3009-001-001 SN 000649 REF CL-650 SMM TASK 44-22-01-000-801		Not Required	
	1600			
	INSTALL DIGITAL MEDIA PLAYER PN BDP3009-001-001 SN 000649 REF CL-650 SMM TASK 44-22-01-400-801			
	1700	Removed Bottom drawer from fwd wardrobe Ref CL-650 SMM TASK 25-24-01-000-801	B0141448 - Graciela Pino Feb 10, 2026 03:47 AM	
	Remove Bottom drawer from fwd wardrobe Ref CL-650 SMM TASK 25-24-01-000-801		Not Required	
	1800			
	Install Bottom drawer from fwd wardrobe Ref CL-650 SMM TASK 25-24-01-400-801			
	1900	Removed customer goods from fwd wardrobe bottom drawer. Ref BAS 00270032	B0141448 - Graciela Pino Feb 10, 2026 03:47 AM	
	Remove customer goods from fwd wardrobe bottom drawer. Ref BAS 00270032		Not Required	
	2000			
	Install customer goods from fwd wardrobe bottom drawer. Ref BAS 00270032			

Sequence #	4002-12	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4720728	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2528784

4002-12	**WO #**	**4720728**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		No Log Entry	
12/4002 - CW LH ARMLEDGES REMOVAL AND INSTALLATION				

Bombardier

Sequence #	4002-12	Aircraft SN #	6111	MWPWO #	2498069
WO #	4720728	Aircraft Reg #	XA-SOL	Parent WO #	2528784

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Removed LH FWD DADO PANEL REF CL 650 SMM 25-26-09-000-801	B1017008 - Cesar Castro Feb 09, 2026 07:44 PM	
	Remove LH FWD DADO PANEL REF CL 650 SMM 25-26-09-000-801		Not Required	
	200			
	Install LH FWD DADO PANEL REF CL 650 SMM 25-26-09-400-801			
	300	Removed LH AFT DADO PANEL REF CL 650 SMM 25-26-09-000-801	B1017008 - Cesar Castro Feb 09, 2026 07:44 PM	
	Remove LH AFT DADO PANEL REF CL 650 SMM 25-26-09-000-801		Not Required	
	400			
	Install LH AFT DADO PANEL REF CL 650 SMM 25-26-09-400-801			
	500	Removed LH FWD PULL OUT TABLE REF CL650 SMM 25-25-01-000-801	B1017008 - Cesar Castro Feb 09, 2026 08:49 PM	
	Remove LH FWD PULL OUT TABLE REF CL650 SMM 25-25-01-000-801		Not Required	
	600			
	Install LH FWD PULL OUT TABLE REF CL650 SMM 25-25-01-400-801			
	700	Removed LH AFT arm ledge REF CL-650 25-26-05-000-801	B1019045 - Isaac Pallanes Feb 10, 2026 04:18 PM	
	Remove LH AFT arm ledge REF CL-650 25-26-05-000-801		Not Required	
	800			
	Install LH AFT arm ledge REF CL-650 25-26-05-400-801			

Sequence #	4002-12	Aircraft SN #	6111	MWPWO #	2498069
WO #	4720728	Aircraft Reg #	XA-SOL	Parent WO #	2528784

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	900	Removed LH FWD arm ledge REF CL-650 25-26-05-000-801	B1019045 - Isaac Pallanes Feb 10, 2026 09:09 PM	
	Remove LH FWD arm ledge REF CL-650 25-26-05-000-801		Not Required	
	1000			
	Install LH FWD arm ledge REF CL-650 25-26-05-400-801			
	1100	Removed to each left-hand arm ledge, storage boxes REF CL650 SMM 25-26-05-000-801	B1019045 - Isaac Pallanes Feb 10, 2026 09:25 PM	
	Remove to each left-hand arm ledge, storage boxes REF CL650 SMM 25-26-05-000-801		Not Required	
	1200			
	Install to each left-hand arm ledge, storage boxes REF CL650 SMM 25-26-05-400-801			
	1300	Removed LH dado insulation Bas00270032 section 3.3 Rev B Jan 02 2017	B0641900 - Enrique Gaxiola Feb 11, 2026 08:03 PM	
	Remove LH dado insulation Bas00270032 section 3.3 Rev B Jan 02 2017		Not Required	
	1400			
	Install LH dado insulation Bas00270032 section 3.3 Rev B Jan 02 2017			

FINDINGS DETAILS

Finding #	Long Description	Status	Reported By / Date	Defect Source / Disposition	Defect Type	Priority	Follow-up WO #
79500	L/H Fwd armledge has adhesive tape on soft good	CLOSED	B1001500 - Victor Gallego Feb 9, 2026 10:04 AM	MAINTENANCE 300-QA002	OTHER	3	4805645-APPR

Sequence #	4002-13	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4720905	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2528784

4002-13	**WO #**	**4720905**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		No Log Entry	
13/4002 - CW RH ARMLEDGES REMOVAL AND INSTALLATION				

Sequence #	4002-13	Aircraft SN #	6111	MWPWO #	2498069
WO #	4720905	Aircraft Reg #	XA-SOL	Parent WO #	2528784

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Removed R/H Fwd Dado Ref CL-650 SMM 25-26-09-000-801	B1001500 - Victor Gallego Feb 09, 2026 08:57 PM	
	Remove R/H Fwd Dado Ref CL-650 SMM 25-26-09-000-801		Not Required	
	200			
	Install R/H Fwd Dado Ref CL-650 SMM 25-26-09-400-801			
	300	Removed R/H Aft Dado Ref CL-650 SMM 25-26-09-000-801	B1001500 - Victor Gallego Feb 10, 2026 06:47 PM	
	Remove R/H Aft Dado Ref CL-650 SMM 25-26-09-000-801		Not Required	
	400			
	Install R/H Aft Dado Ref CL-650 SMM 25-26-09-400-801			
	500	Removed R/H Emer Dado Ref CL-650 SMM 25-26-09-000-801	B1001500 - Victor Gallego Feb 10, 2026 06:47 PM	
	Remove R/H Emer Dado Ref CL-650 SMM 25-26-09-000-801		Not Required	
	600			
	Install R/H Emer Dado Ref CL-650 SMM 25-26-09-400-801			
	700	Removed RH aft armledge Ref CL-650 SMM TASK 25-26-05-000-801	B0141448 - Graciela Pino Feb 11, 2026 02:28 AM	
	Remove RH aft armledge Ref CL-650 SMM TASK 25-26-05-000-801		Not Required	
	800			
	Install RH aft armledge Ref CL-650 SMM TASK 25-26-05-400-801			

Sequence #	4002-13	Aircraft SN #	6111	MWPWO #	2498069
WO #	4720905	Aircraft Reg #	XA-SOL	Parent WO #	2528784

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	900	Removed RH aft storage box #3 Ref CL-650 SMM TASK 25-26-29-000-801	B0141448 - Graciela Pino Feb 11, 2026 02:28 AM	
	Remove RH #3 storage box #3 Ref CL-650 SMM TASK 25-26-29-000-801		Not Required	
	1000			
	Install RH aft storage box #3 Ref CL-650 SMM TASK 25-26-29-400-801			
	1100	Removed RH aft storage box #4 Ref CL-650 SMM TASK 25-26-29-000-801	B0141448 - Graciela Pino Feb 11, 2026 02:28 AM	
	Remove RH aft storage box #4 Ref CL-650 SMM TASK 25-26-29-000-801		Not Required	
	1200			
	Install RH storage box #4 Ref CL-650 SMM TASK 25-26-29-400-801			
	1300	Removed RH fwd armledge Ref CL-650 SMM TASK 25-26-05-000-801	B0141448 - Graciela Pino Feb 11, 2026 02:28 AM	
	Remove RH fwd armledge Ref CL-650 SMM TASK 25-26-05-000-801		Not Required	
	1400			
	Install RH fwd armledge Ref CL-650 SMM TASK 25-26-05-400-801			
	1500	Removed RH storage box #1 Ref CL-650 SMM TASK 25-26-29-000-801	B0141448 - Graciela Pino Feb 11, 2026 02:28 AM	
	Remove RH fwd storage box #1 Ref CL-650 SMM TASK 25-26-29-000-801		Not Required	
	1600			
	Install RH storage box #1 Ref CL-650 SMM TASK 25-26-29-400-801			

Sequence #	4002-13	Aircraft SN #	6111	MWPWO #	2498069
WO #	4720905	Aircraft Reg #	XA-SOL	Parent WO #	2528784

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	1700	Removed RH storage box #2 Ref CL-650 SMM TASK 25-26-29-000-801	B0141448 - Graciela Pino Feb 11, 2026 02:28 AM	
	Remove RH storage box #2 Ref CL-650 SMM TASK 25-26-29-000-801		Not Required	
	1800			
	Install RH storage box #2 Ref CL-650 SMM TASK 25-26-29-400-801			
	1900	Removed RH pullout table Ref CL-650 SMM TASK 25-25-01-000-801	B0141448 - Graciela Pino Feb 11, 2026 02:28 AM	
	Remove RH pullout table Ref CL-650 SMM TASK 25-25-01-000-801		Not Required	
	2000			
	Install RH pullout table Ref CL-650 SMM TASK 25-25-01-400-801			
	2100	Removed customer goods from RH armledges Ref BAS 00270032		
	remove customer goods from RH armledges Ref BAS 00270032		Not Required	
	2200			
	Install customer goods from RH armledges Ref BAS 00270032			
	2300	Removed RH Insulation under armledge Ref CL-650 TASK 25−80−01−000−801		
	Remove RH Insulation under armledge Ref CL-650 TASK 25−80−01−000−801		Not Required	
	2400			
	Install RH Insulation under armledge Ref CL-650 TASK 25−80−01−400−801			

Sequence #	4002-14	Aircraft SN #	6111	MWPWO #	2498069
WO #	4720974	Aircraft Reg #	XA-SOL	Parent WO #	2528784

4002-14	WO #	4720974	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		No Log Entry	
14/4002 - CW CABIN HEADLINER REMOVAL AND INSTALLATION.				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Removed L/H Fwd and Aft Cabin Upwash Lights Ref CL-650 SMM 33-20-01-000-801	B1001500 - Victor Gallego Feb 11, 2026 02:39 PM	
	Remove L/H Fwd and Aft Cabin Upwash Lights Ref CL-650 SMM 33-20-01-000-801		Not Required	
	200			
	Install L/H Fwd and Aft Cabin Upwash Lights Ref CL-650 SMM 33-20-01-400-801			
	300	Removed R/H Fwd and Aft Cabin Upwash Lights Ref CL-650 SMM 33-20-01-000-801	B1001500 - Victor Gallego Feb 11, 2026 02:39 PM	
	Remove R/H Fwd and Aft Cabin Upwash Lights Ref CL-650 SMM 33-20-01-000-801		B1013522 - Brandon Jennings Feb 11, 2026 02:45 PM	
	400			
	Install R/H Fwd and Aft Cabin Upwash Lights Ref CL-650 SMM 33-20-01-400-801			
	500	Removed Cabin Headliner Ref CL-650 SMM 25-26-01-000-801	B1001500 - Victor Gallego Feb 11, 2026 02:39 PM	
	Remove Cabin Headliner Ref CL-650 SMM 25-26-01-000-801		Not Required	
	600			
	Install Cabin Headliner Ref CL-650 SMM 25-26-01-400-801			

Sequence #	4002-15	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4721003	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2528784

4002-15	**WO #**	**4721003**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		No Log Entry	
15/4002 - CW DIVAN W/ENDACBINETS REMOVAL AND INSTALLATION				

Sequence #	4002-15	Aircraft SN #	6111	MWPWO #	2498069
WO #	4721003	Aircraft Reg #	XA-SOL	Parent WO #	2528784

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Removed Fwd Divan End Cabinet Ref CL-650 SMM 25-24-07-000-801	B1001500 - Victor Gallego Feb 09, 2026 08:12 PM	
	Remove Fwd Divan End Cabinet Ref CL-650 SMM 25-24-07-000-801		Not Required	
	200			
	Install Fwd Divan End Cabinet Ref CL-650 SMM 25-24-07-400-801			
	300	Removed Divan and Divan End Cabinets Customer Goods Ref CL-650 SMM 25-24-07-000-801	B1001500 - Victor Gallego Feb 09, 2026 08:25 PM	
	Remove Divan and Divan End Cabinets Customer Goods Ref CL-650 SMM 25-24-07-000-801		Not Required	
	400			
	Install Divan and Divan End Cabinets Customer Goods Ref CL-650 SMM 25-24-07-400-801			
	500	REMOVED UNDERNEATH DIVAN CLOSE OUTS(8 PANELS) REF CL-650 SMM 25-21-05-000-801	B0646494 - Leopoldo Rocha Feb 09, 2026 08:29 PM	
	REMOVE UNDERNEATH DIVAN CLOSE OUTS(8 PANELS) REF CL-650 SMM 25-21-05-000-801		Not Required	
	600			
	INSTALL UNDERNEATH DIVAN CLOSE OUTS(8 PANELS) REF CL-650 SMM 25-21-05-400-801			
	700	Removed Aft Divan End Cabinet Ref CL-650 SMM 25-24-07-000-801	B1001500 - Victor Gallego Feb 10, 2026 06:51 PM	
	Remove Aft Divan End Cabinet Ref CL-650 SMM 25-24-07-000-801		Not Required	

Sequence #	4002-15	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4721003	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2528784

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	800			
	Install Aft Divan End Cabinet Ref CL-650 SMM 25-24-07-400-801			

Sequence #	4002-16	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4721006	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2528784

4002-16	**WO #**	**4721006**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		No Log Entry	
16/4002 - CW AFT CABIN LH BULKHEAD REMOVAL AND INSTALLATION				

Bombardier

Sequence #	4002-16	Aircraft SN #	6111	MWPWO #	2498069
WO #	4721006	Aircraft Reg #	XA-SOL	Parent WO #	2528784

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Removed AFT Cabin Bulkhead Door Ref: CL-650 SMM TASK 25-23-07-000-801	B1019231 - Ivan Bojorquez Feb 09, 2026 10:27 PM	
	Remove AFT Cabin Bulkhead Door Ref: CL-650 SMM TASK 25-23-07-000-801		Not Required	
	200			
	Install AFT Cabin Bulkhead Door Ref: CL-650 SMM TASK 25-23-07-400-801			
	300	Removed AFT Cabin L/H Bulkhead Bullnose panel Ref: CL-650 SMM TASK 25-23-05-000-803	B1019231 - Ivan Bojorquez Feb 09, 2026 10:27 PM	
	Remove AFT Cabin L/H Bulkhead Bullnose panel Ref: CL-650 SMM TASK 25-23-05-000-803		Not Required	
	400			
	Install AFT Cabin L/H Bulkhead Bullnose panel Ref: CL-650 SMM TASK 25-23-05-400-803			
	500	Removed AFT Cabin to lav Bulkhead Track and cover Ref: CL-650 SMM TASK 25-23-07-000-801	B1019231 - Ivan Bojorquez Feb 10, 2026 04:49 AM	
	Remove AFT Cabin to lav Bulkhead Track and cover Ref: CL-650 SMM TASK 25-23-07-000-801		Not Required	
	600			
	Install AFT Cabin to lav Bulkhead Track and cover Ref: CL-650 SMM TASK 25-23-05-000-803.			
	700	Removed AFT Cabin LH FWD Bulkhead Partition Ref: CL-650 SMM TASK 25-23-05-000-803	B1019231 - Ivan Bojorquez Feb 10, 2026 05:00 AM	
	Remove AFT Cabin LH FWD Bulkhead Partition Ref: CL-650 SMM TASK 25-23-05-000-803		Not Required	
	800			
	Install AFT Cabin LH FWD Bulkhead Partition Ref: CL-650 SMM TASK 25-23-05-400-803			

Sequence #	4002-16	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4721006	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2528784

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	900	Removed AFT Cabin LH AFT Bulkhead Partition Ref: CL-650 SMM TASK 25-23-05-000-804	B1019231 - Ivan Bojorquez Feb 10, 2026 05:00 AM	
	Remove AFT Cabin LH AFT Bulkhead Partition Ref: CL-650 SMM TASK 25-23-05-000-804		Not Required	
	1000			
	Install AFT Cabin LH AFT Bulkhead Partition Ref: CL-650 SMM TASK 25-23-05-400-804			

Sequence #	4002-17	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4721027	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2528784

			LOG BOOK VERBIAGE	Deferrals
4002-17	**WO #**	**4721027**		
	SAP SVO #		No Log Entry	
17/4002 - CW AFT CABIN RH BULKHEAD REMOVAL AND INSTALLATION				

Sequence #	4002-17	Aircraft SN #	6111	MWPWO #	2498069
WO #	4721027	Aircraft Reg #	XA-SOL	Parent WO #	2528784

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Removed RH baggage bulkhead ref CL650 SMM TASK 25-53-01-000-802	B0641900 - Enrique Gaxiola Feb 10, 2026 08:00 PM	
	Remove RH baggage bulkhead ref CL650 SMM TASK 25-53-01-000-802		Not Required	
	200			
	Install RH baggage bulkhead ref CL650 SMM TASK 25-53-01-400-802			
	300	Removed LH baggage bulkhead ref CL650 SMM TASK 25-53-01-000-801	B0641900 - Enrique Gaxiola Feb 10, 2026 08:00 PM	
	Remove LH baggage bulkhead ref CL650 SMM TASK 25-53-01-000-801		Not Required	
	400			
	Install LH baggage bulkhead ref CL650 SMM TASK 25-53-01-400-801			
	500	Removed LAV vanity ref CL650 SMM TASK 25-40-01-000-801	B0641900 - Enrique Gaxiola Feb 10, 2026 08:00 PM	
	Remove LAV vanity ref CL650 SMM TASK 25-40-01-000-801		Not Required	
	600			
	Install LAV vanity ref CL650 SMM TASK 25-40-01-400-801			
	700	Removed aft bulkhead spreader bar ref CL650 SMM TASK 25-23-05-000-802	B0641900 - Enrique Gaxiola Feb 11, 2026 02:41 PM	
	Remove aft bulkhead spreader bar ref CL650 SMM TASK 25-23-05-000-802		Not Required	
	800			
	Install aft bulkhead spreader bar ref CL650 SMM TASK 25-23-05-400-802			

Sequence #	4002-17	Aircraft SN #	6111	MWPWO #	2498069
WO #	4721027	Aircraft Reg #	XA-SOL	Parent WO #	2528784

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	900	Removed RH aft bulkhead monitor ref CL650 SMM TASK 44-22-05-000-801	B0641900 - Enrique Gaxiola Feb 11, 2026 02:48 PM	
	Remove RH aft bulkhead monitor ref CL650 SMM TASK 44-22-05-000-801		Not Required	
	1000			
	Install RH aft bulkhead monitor ref CL650 SMM TASK 44-22-05-400-801			
	1100	Removed RH aft bulkhead monitor cover ref CL650 TASK 25-53-01-000-802	B0641900 - Enrique Gaxiola Feb 11, 2026 02:50 PM	
	Remove RH aft bulkhead monitor cover ref CL650 TASK 25-53-01-000-802		Not Required	
	1200			
	Install RH aft bulkhead monitor cover ref CL650 TASK 25-53-01-400-802			

Sequence #	4002-18	Aircraft SN #	6111	MWPWO #	2498069
WO #	4721034	Aircraft Reg #	XA-SOL	Parent WO #	2528784

4002-18	WO #	4721034	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		No Log Entry	
18/4002 - CW LAVATORY VANITY W/CURIO ASSEMBLY REMOVAL AND INSTALLATION.				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Removed customer goods at medicine cabinet as required	B1019231 - Ivan Bojorquez Feb 10, 2026 06:04 AM	
	Remove customer goods at medicine cabinet as required		Not Required	
	200			
	Install customer goods at medicine cabinet as required			
	300	Removed curio assembly Ref: CL-650 SMM TASK 25-40-15-000-801	B1019231 - Ivan Bojorquez Feb 10, 2026 06:04 AM	
	Remove curio assembly Ref: CL-650 SMM TASK 25-40-15-000-801		Not Required	
	400			
	Install curio assembly Ref: CL-650 SMM TASK 25-40-15-400-801			
	500	Removed floor mat switch ref CL650:SMM TASK 38-10-09-000-801	B0641900 - Enrique Gaxiola Feb 11, 2026 07:42 PM	
	Remove floor mat switch ref CL650:SMM TASK 38-10-09-000-801		Not Required	
	600			
	Install floor mat switch ref CL650:SMM TASK 38-10-09-400-801			

Sequence #	4002-19	Aircraft SN #	6111	MWPWO #	2498069
WO #	4721066	Aircraft Reg #	XA-SOL	Parent WO #	2528784

4002-19	WO #	4721066	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		No Log Entry	
19/4002 - CW LAVATORY HEADLINER REMOVAL AND INSTALLATION.				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Removed R/H Lav Headliner Ref: CL-650 SMM Task 25-40-05-000-801.	B1019231 - Ivan Bojorquez Feb 10, 2026 04:37 AM	
	Remove R/H Lav Headliner Ref: CL-650 SMM Task 25-40-05-000-801.		Not Required	
	200			
	Install R/H Lav Headliner Ref: CL-650 SMM Task 25-40-05-400-801.			
	300	Removed Center Lav Headliner Ref: CL-650 SMM Task 25-40-05-000-801.	B1019231 - Ivan Bojorquez Feb 10, 2026 04:37 AM	
	Remove Center Lav Headliner Ref: CL-650 SMM Task 25-40-05-000-801.		Not Required	
	400			
	Install Center Lav Headliner Ref: CL-650 SMM Task 25-40-05-400-801.			
	500	Removed L/H Lav Headliner Ref: CL-650 SMM Task 25-40-05-000-801.	B1019231 - Ivan Bojorquez Feb 10, 2026 04:37 AM	
	Remove L/H Lav Headliner Ref: CL-650 SMM Task 25-40-05-000-801.		Not Required	
	600			
	Install L/H Lav Headliner Ref: CL-650 SMM Task 25-40-05-400-801.			

Sequence #	4002-20	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4721067	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2528784

4002-20	**WO #**	**4721067**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		No Log Entry	
20/4002 - CW LAVATORY TOILET ENCLOUSRE REMOVAL AND INSTALLATION.				

Sequence #	4002-20	Aircraft SN #	6111	MWPWO #	2498069
WO #	4721067	Aircraft Reg #	XA-SOL	Parent WO #	2528784

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Removed Customer Goods at Toilet upper enclosure as required	B1019231 - Ivan Bojorquez Feb 10, 2026 06:26 AM	
	Remove Customer Goods at Toilet upper enclosure as required		Not Required	
	200			
	Install Customer Goods at Toilet upper enclosure as required			
	300	Removed toilet cover Ref CL-650 SMM TASK 25-40-03-000-801	B0141448 - Graciela Pino Feb 11, 2026 04:43 AM	
	Remove toilet cover Ref CL-650 SMM TASK 25-40-03-000-801		Not Required	
	400			
	Install toilet cover Ref CL-650 SMM TASK 25-40-03-400-801			
	500	Removed toilet enclosure Ref CL-650 SMM TASK 25-40-000-801	B0141448 - Graciela Pino Feb 11, 2026 04:43 AM	
	Remove toilet enclosure Ref CL-650 SMM TASK 25-40-000-801		Not Required	
	600			
	Install toilet enclosure Ref CL-650 SMM TASK 25-40-400-801			
	700	Removed toilet shroud storage cabinet ref CL650 SMM TASK 25-40-03-000-801	B0641900 - Enrique Gaxiola Feb 11, 2026 02:36 PM	
	Remove toilet shroud storage cabinet ref CL650 SMM TASK 25-40-03-000-801		Not Required	
	800			
	Install toilet shroud storage cabinet ref CL650 SMM TASK 25-40-03-400-801			

Bombardier

Sequence #	4002-21	Aircraft SN #	6111	MWPWO #	2498069
WO #	4721143	Aircraft Reg #	XA-SOL	Parent WO #	2528784

4002-21	WO #	4721143	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		No Log Entry	
21/4002 - CW BAGGAGE COMPARTMENT BULKHEADS REMOVAL AND INSTALLATION.				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Removed lav to baggage door REF CL-650 SMM 25-53-13-000-801	B1019045 - Isaac Pallanes Feb 06, 2026 09:50 PM	
	Remove lav to baggage door REF CL-650 SMM 25-53-13-000-801		Not Required	
	200			
	Install lav to baggage door REF CL-650 SMM 25-53-13-400-801			
	300	Removed sub threshold assembly by removing 6 screws ea. SPM 20-21-00-910-801	B0641900 - Enrique Gaxiola Feb 11, 2026 07:48 PM	
	Remove sub threshold assembly SPM 20-21-00-910-801		Not Required	
	400			
	Install sub threshold assembly by installing 6 screws ea. SPM 20-21-00-910-801			

Sequence #	4002-22	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4721171	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2528784

			LOG BOOK VERBIAGE	Deferrals
4002-22	**WO #**	**4721171**		
	SAP SVO #		No Log Entry	
22/4002 - CW BAGGAGE COMPARTMENT PANELS REMOVAL AND INSTALLATION.				

Sequence #	4002-22	Aircraft SN #	6111	MWPWO #	2498069
WO #	4721171	Aircraft Reg #	XA-SOL	Parent WO #	2528784

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Removed baggage compartment shelves 3ea. Ref CL650 SMM 25-53-07-000-801	B0641900 - Enrique Gaxiola Feb 09, 2026 05:50 PM	
	Remove baggage compartment shelves 3ea. Ref CL650 SMM 25-53-07-000-801		Not Required	
	200			
	Install baggage compartment shelves 3ea. Ref CL650 SMM 25-53-07-400-801			
	300	Removed the baggage right headliner panel ref CL650 SMM TASK 25-53-03-000-803	B0641900 - Enrique Gaxiola Feb 09, 2026 05:50 PM	
	Remove the right headliner panel ref CL650 SMM TASK 25-53-03-000-803		Not Required	
	400			
	Install the baggage right headliner panel ref CL650 SMM TASK 25-53-03-400-803			
	500	Removed baggage water tank closeout ref CL650 SMM TASK 25-53-11-000-801	B0641900 - Enrique Gaxiola Feb 09, 2026 05:50 PM	
	Remove water tank closeout ref CL650 SMM TASK 25-53-11-000-801		Not Required	
	600			
	Install baggage water tank closeout ref CL650 SMM TASK 25-53-11-400-801			
	700	Removed RH baggage FS619 panel ref CL650 SMM TASK 25-53-05-000-8011	B0641900 - Enrique Gaxiola Feb 09, 2026 05:50 PM	
	Remove RH baggage FS619 panel ref CL650 SMM TASK 25-53-05-000-8011		Not Required	
	800	Removed baggage net with hooks ref CL650 SMM TASK 25-53-05-000-801	B0641900 - Enrique Gaxiola Feb 09, 2026 05:50 PM	
	Remove baggage net with hooks ref CL650 SMM TASK 25-53-05-000-801		Not Required	

Sequence #	4002-22	Aircraft SN #	6111	MWPWO #	2498069
WO #	4721171	Aircraft Reg #	XA-SOL	Parent WO #	2528784

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	900 Install baggage net with hooks ref CL650 SMM TASK 25-53-05-400-801			
	1000 Install RH baggage FS619 panel ref CL650 SMM TASK 25-53-05-400-801			
	1100 Remove baggage LH aft cargo door panels 9ea. Ref CL650 SMM TASK 25-53-05-000-801	Removed baggage LH aft cargo door panels 9ea. Ref CL650 SMM TASK 25-53-05-000-801	B0641900 - Enrique Gaxiola Feb 09, 2026 08:31 PM Not Required	
	1200 Install baggage LH aft cargo door panels 9ea. Ref CL650 SMM TASK 25-53-05-400-801			
	1300 Remove baggage LH headliner panel SMM TASK 25-53-03-000-801	Removed baggage LH headliner panel SMM TASK 25-53-03-000-801	B0641900 - Enrique Gaxiola Feb 09, 2026 08:31 PM Not Required	
	1400 Install baggage LH headliner panel SMM TASK 25-53-03-400-801			
	1500 Remove baggage mid pressure panel ref CL650 SMM TASK 25-53-05-000-801	Removed baggage mid pressure panel ref CL650 SMM TASK 25-53-05-000-801	B0641900 - Enrique Gaxiola Feb 09, 2026 08:31 PM Not Required	
	1600 Install baggage mid pressure panel ref CL650 SMM TASK 25-53-05-400-801			

Sequence #	4002-22	Aircraft SN #	6111	MWPWO #	2498069
WO #	4721171	Aircraft Reg #	XA-SOL	Parent WO #	2528784

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	1700	Removed baggage LH fwd cargo door panels 10ea. Ref CL650 SMM TASK 25-53-05-000-801	B0641900 - Enrique Gaxiola Feb 09, 2026 08:31 PM	
	Remove baggage LH fwd cargo door panels 10ea. Ref CL650 SMM TASK 25-53-05-000-801		Not Required	
	1800			
	Install baggage LH fwd cargo door panels 10ea. Ref CL650 SMM TASK 25-53-05-400-801			
	1900	Removed LAV to baggage door header ref CL650 SMM TASK 25-53-01-000-801	B0641900 - Enrique Gaxiola Feb 09, 2026 08:31 PM	
	Remove LAV to baggage door header ref CL650 SMM TASK 25-53-01-000-801		Not Required	
	2000			
	Install LAV to baggage door header ref CL650 SMM TASK 25-53-01-400-801			
	2100	Removed cargo door closeout panel by disengaging Velcro	B0641900 - Enrique Gaxiola Feb 09, 2026 08:31 PM	
	Remove cargo door closeout panel by disengaging Velcro		Not Required	
	2200			
	Install cargo door closeout panel by engaging Velcro			
	2300	Removed baggage customer goods as required	B0641900 - Enrique Gaxiola Feb 09, 2026 08:52 PM	
	Remove baggage customer goods as required		Not Required	
	2400			
	Install baggage customer goods as required			

Sequence #	4002-23	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4721220	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2528784

4002-23	**WO #**	**4721220**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		No Log Entry	
23/4002 - CW BAGGAGE COMPARTMENT HEADLINER REMOVAL AND INSTALLTION.				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Removed baggage headliner REF CL650 SMM 25-53-03-000-801	B1019045 - Isaac Pallanes Feb 06, 2026 09:48 PM	
	Remove baggage headliner REF CL650 SMM 25-53-03-000-801		Not Required	
	200			
	Install baggage headliner REF CL650 SMM 25-53-03-400-801			

Sequence #	4002-24	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4721226	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2528784

4002-24	**WO #**	**4721226**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		No Log Entry	
24/4002 - CW MISC. COCKPIT ITEMS REMOVAL AND INSTALLATION.				

Sequence #	4002-24	Aircraft SN #	6111	MWPWO #	2498069
WO #	4721226	Aircraft Reg #	XA-SOL	Parent WO #	2528784

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Removed Pilot seat PN 1406-07SS010BF SN 1219-1406 REF CL-650 AMM TASK 25−11−01−000−801	B0141448 - Graciela Pino Feb 05, 2026 10:53 PM	
	Remove Pilot seat PN 1406-07SS010BF SN 1219-1406 REF CL-650 AMM TASK 25−11−01−000−801		Not Required	
	200			
	Install Pilot seat PN 1406-07SS010BF SN 1219-1406 REF CL-650 AMM TASK 25−11−01−400−801			
	300	Removed Co-Pilot seat PN 1406-08SS010BF SN 1220-1406 REF CL-650 AMM TASK 25−11−01−000−801	B0141448 - Graciela Pino Feb 05, 2026 10:53 PM	
	Remove Co-Pilot seat PN 1406-08SS010BF SN 1220-1406 REF CL-650 AMM TASK 25−11−01−000−801		Not Required	
	400			
	Installed Co-Pilot seat PN 1406-08SS010BF SN 1220-1406 REF CL-650 AMM TASK 25−11−01−400−801			
	500	Removed flight comp curtain Ref CL-650 SMM TASK 25-11-05-000-801	B0141448 - Graciela Pino Feb 05, 2026 10:53 PM	
	Remove flight comp curtain Ref CL-650 SMM TASK 25-11-05-000-801		Not Required	
	600			
	Install flight comp curtain Ref CL-650 SMM TASK 25-11-05-400-801			
	700	Removed cockpit step from (top of jet box area) Ref BAS 00270032	B0141448 - Graciela Pino Feb 11, 2026 11:54 PM	
	Remove cockpit step from (top of jet box area) Ref BAS 00270032		Not Required	

Sequence #	4002-24	Aircraft SN #	6111	MWPWO #	2498069
WO #	4721226	Aircraft Reg #	XA-SOL	Parent WO #	2528784

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	800 Install cockpit step (top of jet box area) Ref BAS 00270032			
	900 Remove LH and RH Horse collar panels at flight compartment. Refer to BAS 00270032 SEC 3.3.Rev A	Removed LH and RH Horse collar panels at flight compartment. Refer to BAS 00270032 SEC 3.3.Rev A	B0143864 - Aaric Cerna Feb 09, 2026 04:39 PM Not Required	
	1000 Install LH and RH Horse collar panels at flight compartment. Refer to BAS 00270032 SEC 3.3.Rev A			
	1100 Remove LH and RH Center Pedestal Cover panels at flight compartment. Refer to BAS 00270032 SEC 3.3.Rev A	Removed LH and RH Center Pedestal Cover panels at flight compartment. Refer to BAS 00270032 SEC 3.3.Rev A	B0143864 - Aaric Cerna Feb 09, 2026 05:08 PM Not Required	
	1200 Install LH and RH Center Pedestal Cover panels at flight compartment. Refer to BAS 00270032 SEC 3.3.Rev A			
	1300 Remove Glareshield panel 220AZ IAW. CL 650 AMM 31-14-03-000-802.	Removed Glareshield panel 220AZ IAW. CL 650 AMM 31-14-03-000-802.	B0143864 - Aaric Cerna Feb 09, 2026 07:37 PM Not Required	
	1400 Install Glareshield panel 220AZ IAW. CL 650 AMM 31-14-03-400-802.			

Sequence #	4002-25	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4721292	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2528784

4002-25	**WO #**	**4721292**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		No Log Entry	
25/4002 - CW CABIN FLOORING (FLIGHT DECK , MAINCABIN , BAGGAGE) REMOVAL AND INSTALL				

Sequence #	4002-25	Aircraft SN #	6111	MWPWO #	2498069
WO #	4721292	Aircraft Reg #	XA-SOL	Parent WO #	2528784

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Removed entry threshold Ref SPM 20-21-00-910-801	B0141448 - Graciela Pino Feb 05, 2026 10:57 PM	
	Remove entry threshold Ref SPM 20-21-00-910-801		Not Required	
	200			
	Install entry threshold Ref SPM 20-21-00-910-801			
	300	Removed baggage threshold and flap Ref SPM 20-21-00-910-801	B0141448 - Graciela Pino Feb 06, 2026 01:23 AM	
	Remove baggage threshold and flap Ref SPM 20-21-00-910-801		Not Required	
	400			
	Install baggage threshold and flap Ref SPM 20-21-00-910-801			
	500	Removed Baggage carpet and pad from baggage by releasing Velcro hook from loop	B0141448 - Graciela Pino Feb 06, 2026 01:23 AM	
	Remove Baggage carpet and pad from baggage by releasing Velcro hook from loop		Not Required	
	600			
	Install Baggage carpet and pad baggage by engaging Velcro hook from loop			
	700	Removed Lavatory runner Ref BAS 00270032	B0141448 - Graciela Pino Feb 06, 2026 01:23 AM	
	Remove Lavatory runner Ref BAS 00270032		Not Required	
	800			
	Install Lavatory runner Ref BAS 00270032			
	900	Removed entry runner Ref BAS 00270032	B0141448 - Graciela Pino Feb 06, 2026 01:23 AM	
	Remove entry runner Ref BAS 00270032		Not Required	

Sequence #	4002-25	Aircraft SN #	6111	MWPWO #	2498069
WO #	4721292	Aircraft Reg #	XA-SOL	Parent WO #	2528784

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	1000			
	Install entry runner Ref BAS 00270032			
	1100	Removed entry pad Ref CL-650 SMM TASK 25-26-15-000-801	B0141448 - Graciela Pino Feb 06, 2026 01:23 AM	
	Remove entry pad Ref CL-650 SMM TASK 25-26-15-000-801		Not Required	
	1200			
	Install entry pad Ref CL-650 SMM TASK 25-26-15-400-801			
	1300	Removed lav pad Ref CL-650 SMM TASK 25-26-15-000-801	B0141448 - Graciela Pino Feb 06, 2026 01:23 AM	
	Remove lav pad Ref CL-650 SMM TASK 25-26-15-000-801		Not Required	
	1400			
	Install lav pad Ref CL-650 SMM TASK 25-26-15-400-801			
	1500	Removed cabin carpet and pad Ref CL-650 SMM TASK 25-26-15-000-801	B0141448 - Graciela Pino Feb 08, 2026 08:19 PM	
	Removed cabin carpet and pad Ref CL-650 SMM TASK 25-26-15-000-801		Not Required	
	1600			
	Install cabin carpet and pad Ref CL-650 SMM TASK 25-26-15-400-801			
	1700	Removed lav to baggage threshold Ref SPM 20-21-00-910-801	B0141448 - Graciela Pino Feb 08, 2026 08:19 PM	
	Remove lav to baggage threshold Ref SPM 20-21-00-910-801		Not Required	

Sequence #	4002-25	Aircraft SN #	6111	MWPWO #	2498069
WO #	4721292	Aircraft Reg #	XA-SOL	Parent WO #	2528784

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	1800 Instal lav to baggage threshold Ref SPM 20-21-00-910-801			
	1900 REMOVE CABIN CONFERENCE TABLE REF CL-650 SMM 25-25-03-000-801	REMOVED CABIN CONFERENCE TABLE REF CL 650 SMM 25-25-03-000-801	B0646494 - Leopoldo Rocha Feb 09, 2026 05:40 PM Not Required	
	2000 INSTALL CABIN CONFERENCE TABLE REF CL-650 SMM 25-25-03-400-801			
	2100 REMOVE DIVAN ASSEMBLY REF CL 650 SMM 25-21-05-000-801	REMOVED DIVAN ASSEMBLY REF CL 650 SMM 25-21-05-000-801	B0646494 - Leopoldo Rocha Feb 09, 2026 09:18 PM Not Required	
	2200 INSTALL DIVAN ASSEMBLY REF CL 650 SMM 25-21-05-400-801 CARPET PAD UNDER DIVAN			
	2300 REMOVE DIVAN ASSEMBLY DOORS REF CL-650 SMM 25-21-05-000-801	REMOVED DIVAN ASSEMBLY DOORS REF CL-650 SMM 25-21-05-000-801	B0646494 - Leopoldo Rocha Feb 09, 2026 09:18 PM Not Required	
	2400 INSTALL DIVAN ASSEMBLY DOORS REF CL-650 SMM 25-21-05-400-801			

Sequence #	4003	Aircraft SN #	6111	MWPWO #	2498069
WO #	2588167	Aircraft Reg #	XA-SOL	Parent WO #	2498069

4003	WO #	2588167	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13276369	No Log Entry	
Interior - Replace carpet in main cabin and lavatory with a machine made carpet, to include a set of throw rugs (604,605,650)				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			25-00
	Interior - Replace carpet in main cabin and lavatory to include a set of throw rugs			
	200			25-00
	Burn Coupons			

CHILD WORK ORDER DETAILS

	WO #	Description	Corrective Action	AMENDED
4003-1	4431401	7001/4003-FABRICATE 1EA 604DX2522390-003 CARPET ASSY IAW DWG 604DX2522380 REV A		

Sequence #	4003-1	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4431401	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2588167

4003-1	**WO #**	**4431401**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		No Log Entry	
7001/4003-FABRICATE 1EA 604DX2522390-003 CARPET ASSY IAW DWG 604DX2522380 REV A				

Sequence #	4003-1	Aircraft SN #	6111	MWPWO #	2498069
WO #	4431401	Aircraft Reg #	XA-SOL	Parent WO #	2588167

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			
	VERIFY MATERIAL/COMPONENTS: P/N: 604DX2522390-003,CABIN CARPET ASSY, MADE IN THIS OPERATION P/N: RR-130+RR-110, RS-5008, ATRIUM EMBOSSED RED ROCK CARPET, P.O.# P/N: _____ULTRALI BACKING P.O.#, P/N: _____ ADHESIVE, P.O.# P/N: _____ VELCRO LOOP,P.O.#P/N: _____ VELCRO HOOK,P.O.#			
	200			
	MAKE CABIN FLOOR CARPET ASSY FROM RED ROCK RR-130+RR-110 CARPET (FS 349 TO FS 544 ONLY) USING EXISTING CARPET AS TEMPLATE PER BAS00270032 SECTION 3.4 (CARPET REPLACEMENT). REFERENCING 604DX2522390 REV A		Not Required	
	300			
	IDENTIFY CARPET ASSY, CSO SERVICE ORDER NUMBER, DATE IAW BAPS 144-005, SECTION 9.5.1.1, IDENTIFICATION OF AIRCRAFT PARTS AND ASSEMBLIES		Not Required	
	400			
	VERIFY COMPLETED CARPETASSY IAW BAS00270032 REV (____).			

Sequence #	4003-1	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4431401	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2588167

OPERATIONAL DETAILS

	Operation #	Corrective Action Long Description	Tech Sign Off	ATA Code
	Operation Description		Insp Sign Off	Reason for Work

QA005 RTS Statement

The component identified above was repaired and inspected in accordance with current Federal Aviation Regulations, found airworthy and is approved for return to service with respect to the work performed

Sequence #	4004	Aircraft SN #	6111	MWPWO #	2498069
WO #	2508733	Aircraft Reg #	XA-SOL	Parent WO #	2498069

4004	WO #	2508733	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13276365	No Log Entry	
Interior - Replace flightdeck carpet with Tretford carpet (604/605/650)				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			25-00
	Perform Replace flightdeck carpet with Tretford carpet			

CHILD WORK ORDER DETAILS

	WO #	Description	Corrective Action	AMENDED
4004-1	4431498	7002/4004-FABRICATE 1EA 604DX2511026-005 PILOT CARPET ASSY IAW DWG 604DX2511026 REV C	VERIFIED COMPLETED CARPET ASSEMBLY(S) IAW BAS00270032 REV (__A__). AND 604DX2511026 REV F REF W/O 4717709 FOR FLAMMABILITYVERIFIED COMPLETED CARPET ASSEMBLY(S) IAW BAS00270032 REV (__A__). AND 604DX2511026 REV F REF W/O 4717709 FOR FLAMMABILITY	
4004-2	4431503	7003/4004-FABRICATE 1EA 604DX2511027-005 CO PILOT CARPET ASSY IAW DWG 604DX2511026 REV C	VERIFIED COMPLETED CARPET ASSEMBLY(S) IAW BAS00270032 REV (__A__). AND 604DX2511027 REV F REF W/O 4717709 FOR FLAMMABILITY	

Sequence #	4004-1	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4431498	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2508733

			LOG BOOK VERBIAGE	Deferrals
4004-1	**WO #**	**4431498**		
	SAP SVO #		No Log Entry	
7002/4004-FABRICATE 1EA 604DX2511026-005 PILOT CARPET ASSY IAW DWG 604DX2511026 REV C				

Bombardier

Sequence #	4004-1	Aircraft SN #	6111	MWPWO #	2498069
WO #	4431498	Aircraft Reg #	XA-SOL	Parent WO #	2508733

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	VERIFIED MATERIAL/COMPONENTS: P/N: 604DX2511026-007 PILOT CARPET ASSY, MADE IN THIS OPERATION P/N: 534 TRETFORD, AIP CARPET, P.O.# 5002470057 P/N: ____021200-19928_ ___ADHESIVE, P.O.# 5002450281 P/N: _N384-7187 _____ VELCRO LOOP, P.O.#5002413357	B0141989 - Martin Romo Mar 03, 2026 05:23 PM	
	VERIFY MATERIAL/COMPONENTS: P/N: 604DX2511026-007 PILOT CARPET ASSY, MADE IN THIS OPERATION P/N: 534 TRETFORD, AIP CARPET, P.O.# P/N: _____ ADHESIVE, P.O.# P/N: _____ VELCRO LOOP,P.O.#P/N: _____ VELCRO HOOK,P.O.#		B1013522 - Brandon Jennings Mar 04, 2026 03:20 PM	
	101	VERIFIED MATERIAL/COMPONENTS: P/N: 604DX2511027-005 CO-PILOT CARPET ASSY, MADE IN THIS OPERATION P/N: 534 TRETFORD, AIP CARPET, P.O.#50002470057 P/N: ___021200-19928 p/o 5002450281_____ ADHESIVE, P.O.# P/N: _n384-7187 _, VELCRO LOOP P.O.# 5002413357 USED N384-7187 LOOP VELCRO IN LIEU OF P/N AB40R0025L694SC	B0141989 - Martin Romo Mar 04, 2026 08:29 PM	
	VERIFY MATERIAL/COMPONENTS: P/N: 604DX2511027-005 CO-PILOT CARPET ASSY, MADE IN THIS OPERATION P/N: 534 TRETFORD, AIP CARPET, P.O.#50002470057 P/N: ___021200-19928 p/o 5002450281_____ ADHESIVE, P.O.# P/N: _n384-7187 _, VELCRO LOOP P.O.# 5002413357VELCRO HOOK,P.O.#		B0142171 - John Williams Mar 04, 2026 09:38 PM	09

Sequence #	4004-1	Aircraft SN #	6111	MWPWO #	2498069
WO #	4431498	Aircraft Reg #	XA-SOL	Parent WO #	2508733

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	200	MADE PILOT FLOOR CARPET FROM 534 TRETFORD CARPET USING EXISTING CARPET AS TEMPLATE PER BAS00270032 SECTION 3.4 (CARPET REPLACEMENT).REFERENCING 604DX2511026 REV F	B0141989 - Martin Romo Mar 03, 2026 05:23 PM	
	MAKE PILOT FLOOR CARPET FROM 534 TRETFORD CARPET USING EXISTING CARPET AS TEMPLATE PER BAS00270032 SECTION 3.4 (CARPET REPLACEMENT).REFERENCING 604DX2511026 REV F		Not Required	
	300	IDENTIFIED CARPET ASSEMBLY, CSO SERVICE ORDER NUMBER, DATE IAW BAPS 144-005, SECTION 9.5.1.1, IDENTIFICATION OF AIRCRAFT PARTS AND ASSEMBLIES.	B0141989 - Martin Romo Mar 03, 2026 05:23 PM	
	IDENTIFY CARPET ASSEMBLY, CSO SERVICE ORDER NUMBER, DATE IAW BAPS 144-005, SECTION 9.5.1.1, IDENTIFICATION OF AIRCRAFT PARTS AND ASSEMBLIES.		Not Required	
	400	VERIFY COMPLETED CARPET ASSEMBLY(S) IAW BAS00270032 REV (__A__).	B0141989 - Martin Romo Mar 03, 2026 05:23 PM	
	VERIFY COMPLETED CARPET ASSEMBLY(S) IAW BAS00270032 REV (____).		B1013522 - Brandon Jennings Mar 04, 2026 03:20 PM	
	500	VERIFIED COMPLETED CARPET ASSEMBLY(S) IAW BAS00270032 REV (__A__). AND 604DX2511067 REV F REF W/O 4717709 FOR FLAMMABILITY	B0141989 - Martin Romo Mar 03, 2026 06:59 PM	
	ADMIN CORRECTION TO OP 400		B1013522 - Brandon Jennings Mar 04, 2026 03:20 PM	
	600	VERIFIED COMPLETED CARPET ASSEMBLY(S) IAW BAS00270032 REV (__A__). AND 604DX2511026 REV F REF W/O 4717709 FOR FLAMMABILITY	B0141989 - Martin Romo Mar 03, 2026 07:25 PM	
	ADMIN CORRECTION TO OP 500		B1013522 - Brandon Jennings Mar 04, 2026 03:20 PM	

Sequence #	4004-1	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4431498	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2508733

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	601	VERIFIED COMPLETED CARPET ASSEMBLY(S) IAW BAS00270032 REV (__A__). AND 604DX2511067 REV F REF W/O 4717709 FOR FLAMMABILITY	B0141989 - Martin Romo Mar 04, 2026 08:54 PM	
	ADMIN CORRECTION TO OP 500		B0142171 - John Williams Mar 04, 2026 09:38 PM	09

QA005 RTS Statement

The component identified above was repaired and inspected in accordance with current Federal Aviation Regulations, found airworthy and is approved for return to service with respect to the work performed

Inspected By :

B0142171 > John Williams **Date:** 2026-03-04

Sequence #	4004-2	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4431503	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2508733

			LOG BOOK VERBIAGE	Deferrals
4004-2	**WO #**	**4431503**		
	SAP SVO #		No Log Entry	
7003/4004-FABRICATE 1EA 604DX2511027-005 CO PILOT CARPET ASSY IAW DWG 604DX2511026 REV C				

Sequence #	4004-2	Aircraft SN #	6111	MWPWO #	2498069
WO #	4431503	Aircraft Reg #	XA-SOL	Parent WO #	2508733

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	VERIFY MATERIAL/COMPONENTS: P/N: 604DX2511027-007 CO-PILOT CARPET ASSY, MADE IN THIS OPERATION P/N: 534 TRETFORD, AIP CARPET, P.O.#5002470057 P/N: _021200-19928 p/o 5002450281 ____adhesive_____ A P/N: _n384-7187 VELCRO LOOP,P.O.#5002413357	B0141989 - Martin Romo Mar 03, 2026 05:47 PM	
	VERIFY MATERIAL/COMPONENTS: P/N: 604DX2511027-005 CO-PILOT CARPET ASSY, MADE IN THIS OPERATION P/N: 534 TRETFORD, AIP CARPET, P.O.# P/N: _____ ADHESIVE, P.O.# P/N: _____ VELCRO LOOP,P.O.#P/N: _____ VELCRO HOOK,P.O.#		B1013522 - Brandon Jennings Mar 04, 2026 03:30 PM	
	101	VERIFIED MATERIAL/COMPONENTS: P/N: 604DX2511027-005 CO-PILOT CARPET ASSY, MADE IN THIS OPERATION P/N: 534 TRETFORD, AIP CARPET, P.O.#50002470057 P/N: ___021200-19928 p/o 5002450281_____ ADHESIVE, P.O.# P/N: _n384-7187 _, VELCRO LOOP P.O.# 5002413357 USED P/N N384-7187 LOOP VELCRO IN LIEU OF P/N A840R0025L694SC	B0141989 - Martin Romo Mar 04, 2026 08:23 PM	
	VERIFY MATERIAL/COMPONENTS: P/N: 604DX2511027-005 CO-PILOT CARPET ASSY, MADE IN THIS OPERATION P/N: 534 TRETFORD, AIP CARPET, P.O.#50002470057 P/N: ___021200-19928 p/o 5002450281_____ ADHESIVE, P.O.# P/N: _n384-7187 _, VELCRO LOOP,P.O.# P/N: _VELCRO HOOK,P.O.# 5002413357		B0142171 - John Williams Mar 04, 2026 08:49 PM	09

Sequence #	4004-2	Aircraft SN #	6111	MWPWO #	2498069
WO #	4431503	Aircraft Reg #	XA-SOL	Parent WO #	2508733

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	200	MADE CO-PILOT FLOOR CARPET FROM 534 TRETFORD CARPET USING EXISTING CARPET AS TEMPLATE PER BAS00270032 REV A SECTION 3.4 (CARPET REPLACEMENT).REFERENCING 604DX2511027 REV F	B0141989 - Martin Romo Mar 03, 2026 05:47 PM	
	MAKE CO-PILOT FLOOR CARPET FROM 534 TRETFORD CARPET USING EXISTING CARPET AS TEMPLATE PER BAS00270032 SECTION 3.4 (CARPET REPLACEMENT).REFERENCING 604DX2511027 REV C		Not Required	
	300	IDENTIFIED CARPET ASSEMBLY, CSO SERVICE ORDER NUMBER, DATE IAW BAPS 144-005, SECTION 9.5.1.1, IDENTIFICATION OF AIRCRAFT PARTS AND ASSEMBLIES.	B0141989 - Martin Romo Mar 03, 2026 05:47 PM	
	IDENTIFY CARPET ASSEMBLY, CSO SERVICE ORDER NUMBER, DATE IAW BAPS 144-005, SECTION 9.5.1.1, IDENTIFICATION OF AIRCRAFT PARTS AND ASSEMBLIES.		Not Required	
	400	VERIFY COMPLETED CARPET ASSEMBLY(S) IAW BAS00270032 REV (__A__). AND 604DX2511027 REV F	B0141989 - Martin Romo Mar 03, 2026 05:47 PM	
	VERIFY COMPLETED CARPET ASSEMBLY(S) IAW BAS00270032 REV (____).		B1013522 - Brandon Jennings Mar 04, 2026 03:30 PM	
	500	VERIFIED COMPLETED CARPET ASSEMBLY(S) IAW BAS00270032 REV (__A__). AND 604DX2511027 REV F REF W/O 4717709 FOR FLAMMABILITY	B0141989 - Martin Romo Mar 03, 2026 09:28 PM	
	admin correction to op 400		B1013522 - Brandon Jennings Mar 04, 2026 03:30 PM	
	501	VERIFIED COMPLETED CARPET ASSEMBLY(S) IAW BAS00270032 REV (__A__). AND 604DX2511027 REV F REF W/O 4717709 FOR FLAMMABILITY	B0141989 - Martin Romo Mar 04, 2026 08:36 PM	
	admin correction to op 400		B0142171 - John Williams Mar 04, 2026 08:49 PM	09

QA005 RTS Statement

Sequence #	4004-2	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4431503	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2508733

The component identified above was repaired and inspected in accordance with current Federal Aviation Regulations, found airworthy and is approved for return to service with respect to the work performed

Inspected By :	
B0142171 > John Williams	**Date:** 2026-03-04

Sequence #	4005	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	2584105	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

			LOG BOOK VERBIAGE	Deferrals
4005	**WO #**	**2584105**		
	SAP SVO #	13275984	No Log Entry	
Interior - Install stone flooring in entry, galley, and aft lavatory (650)				

Sequence #	4006	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	2508905	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

4006	**WO #**	**2508905**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #	13276366	No Log Entry	
Remove and replace MED tread with new material.				

CHILD WORK ORDER DETAILS

	WO #	Description	Corrective Action	AMENDED
4006-1	4431598	7004/4006-FABRICATE 1EA 604DX5216002-KIT STAIR TREAD KIT IAW DWG 604DX5216002 REV A		

Sequence #	4006-1	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4431598	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2508905

			LOG BOOK VERBIAGE	Deferrals
4006-1	**WO #**	**4431598**		
	SAP SVO #		No Log Entry	
7004/4006-FABRICATE 1EA 604DX5216002-KIT STAIR TREAD KIT IAW DWG 604DX5216002 REV A				

Sequence #	4006-1	Aircraft SN #	6111	MWPWO #	2498069
WO #	4431598	Aircraft Reg #	XA-SOL	Parent WO #	2508905

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			
	VERIFY MATERIAL/COMPONENTS: P/N: 604DX5216002-KIT, MADE IN THIS OPERATION P/N: SLATE, AERO FLOOR, AIP, P.O.# P/N: ADHESIVE, P.O.#			
	200			
	MAKE TREADS FOR 604DX5216002-KIT FROM SLATE AERO FLOOR LISTED BELOW.REFERENCING 604DX5216002 REV A * (a) FABRICATE 1EA 604DX5216002-005 TOP TREAD IAW 604DX5216002 REV A (b) FABRICATE 1EA 604DX5216002-009 BOTTOM TREAD IAW 604DX5216002 REV A (c) FABRICATE 4EA 604DX5216002-003 DETAIL TREAD IAW 604DX5216002 REV A (d) FABRICATE 1EA 604DX5216002-001 DETAIL TREAD IAW 604DX5216002 REV A		Not Required	
	300			
	IDENTIFY TREAD KIT, CSO SERVICE ORDER NUMBER, DATE IAW BAPS 144-005, SECTION 9.5.1.1, IDENTIFICATION OF AIRCRAFT PARTS AND ASSEMBLIES.		Not Required	
	400			
	VERIFY COMPLETED 604DX5216002-KIT IAW 604DX5126 REV A			

Sequence #	4006-1	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4431598	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2508905

QA005 RTS Statement
The component identified above was repaired and inspected in accordance with current Federal Aviation Regulations, found airworthy and is approved for return to service with respect to the work performed

Bombardier

Sequence #	4007	Aircraft SN #	6111	MWPWO #	2498069
WO #	4294352	Aircraft Reg #	XA-SOL	Parent WO #	2498069

4007	WO #	4294352	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13429571	No Log Entry	
*Customer has requested a second set of cabin throw mats. Note: customer has already approved a full carpet change which already comes with a set of mats but needs a second set).				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			25-00
	Customer has requested a second set of cabin throw mats. Note: customer has already approved a full carpet change which already comes with a set of mats but needs a second set).			

Sequence #	4008	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4363158	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

			LOG BOOK VERBIAGE	Deferrals
4008	**WO #**	**4363158**		
	SAP SVO #	13440092	SB 650-25-021 REV BASIC - Required for Interior Access to Accomplish the SB	
SB 650-25-021 REV BASIC - Required for Interior Access to Accomplish the SB				
Task / IRN # : SB 650-25-021 REV BASIC				

Sequence #	4008	Aircraft SN #	6111	MWPWO #	2498069
WO #	4363158	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			25-00
	Verify Revision and effectivity of SB to current document in Customer Portal Library			
	200			25-00
	C/W opening and closing of the Zone 2 Entry Furnishings R Upper galley, Entry carpet, Entry headliner			
	300			25-00
	C/W opening and closing of the Zone 3a Cabin Furnishings R Sidewall, PSU, Dados, Seats, FWD/ AFT bulkheads			
	400			25-00
	C/W opening and closing of the Zone 3a Cabin Furnishings L Sidewall, PSU, Dados, Seats, Conf table, FWD/AFT bulkheads			
	500			25-00
	C/W opening and closing of the Zone 4 ALL Lav Sidewall, PSU, Mirror, Towel bar			
	600			25-00
	C/W opening and closing of the Zone 4 Furnishings L Wardrobe cabinet, Baggage bulkhead			
	700			25-00
	Provide Avionics Assistance			

Sequence #	4009	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4715587	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

4009	**WO #**	**4715587**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #	13493707	No Log Entry	
Missing Decorative cover on Upper FWD baggage door stop bracket				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			
	Missing Decorative cover on Upper FWD baggage door stop bracket			

Sequence #	4010	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4715740	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

4010	**WO #**	**4715740**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #	13493711	No Log Entry	
Right side, bottom Divian storage door, does not latch properly upon closing door. This was found during retrieval of the Aft Portable Fire Extinguisher for the weight test.				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			
	Right side, bottom Divian storage door, does not latch properly upon closing door. This was found during retrieval of the Aft Portable Fire Extinguisher for the weight test.			

Sequence #	4011	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4715747	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

			LOG BOOK VERBIAGE	Deferrals
4011	**WO #**	**4715747**		
	SAP SVO #	13493692	STLMC - Detailed Inspection of the Interior Cabinets, Doors and Drawers. Galley drawer #3 latch sticks out (not flushed). Galley drawer #6 latch gets stuck. Galley drawer #8 latch sticks out (not flushed).	
STLMC - Detailed Inspection of the Interior Cabinets, Doors and Drawers. Galley drawer #3 latch sticks out (not flushed). Galley drawer #6 latch gets stuck. Galley drawer #8 latch sticks out (not flushed).				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			
	STLMC - Detailed Inspection of the Interior Cabinets, Doors and Drawers. Galley drawer #3 latch sticks out (not flushed). Galley drawer #6 latch gets stuck. Galley drawer #8 latch sticks out (not flushed).			

Bombardier

Sequence #	4012	Aircraft SN #	6111	MWPWO #	2498069
WO #	4718493	Aircraft Reg #	XA-SOL	Parent WO #	2498069

4012	WO #	4718493	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13493934	No Log Entry	
Provide support for F/list flooring template request. Entry area.				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			
	Provide support for F/list flooring template request. Entry area and lavatory.			

Sequence #	4013	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4748820	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

4013	**WO #**	**4748820**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #	13498373	No Log Entry	
During removal found L/H and R/H sidewall PSU padding disbounding				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			
	During removal found L/H and R/H sidewall PSU padding disbounding			

Sequence #	4014	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4805026	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

4014	**WO #**	**4805026**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #	13507072	No Log Entry	
Upon discovery it was found lanyard on RH Aft Psu is broken				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			
	Upon discovery it was found lanyard on RH Aft Psu is broken			

Bombardier

Sequence #	4015	Aircraft SN #	6111	MWPWO #	2498069
WO #	4805645	Aircraft Reg #	XA-SOL	Parent WO #	2498069

4015	WO #	4805645	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13507055	No Log Entry	
L/H Fwd armledge has adhesive tape on soft good				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			
	L/H Fwd armledge has adhesive tape on soft good			

Bombardier

Sequence #	4016	Aircraft SN #	6111	MWPWO #	2498069
WO #	4805713	Aircraft Reg #	XA-SOL	Parent WO #	2498069

4016	WO #	4805713	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13507074	No Log Entry	
Missing 2 ea fwd cutting table track rubbers.				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			
	Interior Access - CH650 Inspection Bundles Missing two ea fwd cutting table track rubbers.			

Sequence #	4017	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4842709	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

4017	**WO #**	**4842709**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #	13512058	No Log Entry	
Coffee Maker Assembly requires additional time to access Inlet filter within Unit.				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Task Does not apply to aircraft due to different coffee maker not being equipped. Aircraft is equipped with Expresso Maker PN# 925-0018-01 SN# 16-10-04945 Model 1804 . No Filter for water inlet		
	Coffee Maker Assembly requires additional time to access Inlet filter within Unit.			

Bombardier

Sequence #	4018	Aircraft SN #	6111	MWPWO #	2498069
WO #	4842723	Aircraft Reg #	XA-SOL	Parent WO #	2498069

4018	WO #	4842723	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13512177	No Log Entry	
During restoration of the bleed air filter regulator and filter it was noticed that one of the mounting brackets for one of the air lines is disbonded				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Reattached disbonded clickbond fastener. REF CL650 SPM 51-21-27-340-801.	B1016542 - Carlos Ochoa Mar 04, 2026 03:37 AM	
	During restoration of the bleed air filter regulator and filter it was noticed that one of the mounting brackets for one of the air lines is disbonded		B0161691 - Thomas Mitchell Mar 04, 2026 04:01 AM	
	200	Prepared the mating surfaces for cementing of the clickbond fastener. REF CL650 SPM 51-21-67-100-801.	B1016542 - Carlos Ochoa Mar 04, 2026 03:37 AM	
	Prepare the mating surfaces for cementing of clickbond fastener. REF CL650 SPM 51-21-67-100-801.		B0161691 - Thomas Mitchell Mar 04, 2026 04:01 AM	
	300	Reinstalled clamp on affected fastener. REF CL650 SPM 20-21-00-910-801.	B1016542 - Carlos Ochoa Mar 04, 2026 03:37 AM	
	Removed clamp attached to disbonded fastener. REF CL650 SPM 20−21−00−910−801.		B0161691 - Thomas Mitchell Mar 04, 2026 04:01 AM	
	400	Removed all tools, equipment, and unwanted materials.	B1016542 - Carlos Ochoa Mar 04, 2026 03:37 AM	
	Remove all tools, equipment, and unwanted materials.		B0161691 - Thomas Mitchell Mar 04, 2026 04:01 AM	

TOOL INFORMATION

Tool ID	Tool Description	Calibration Due Date
TUSS5176	Torque Screwdriver	Oct 30, 2026 5:00 PM

Bombardier

Sequence #	4019	Aircraft SN #	6111	MWPWO #	2498069
WO #	4862404	Aircraft Reg #	XA-SOL	Parent WO #	2498069

4019	WO #	4862404	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13516617	No Log Entry	
Request seat vendor to Re-dye the following - 8 Cabin seats, 2 Window side panels W/Psus, 1 Mirror Surround				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			
	Request seat vendor to re-dye the following - 8 Cabin seats, 2 Window side panels W/Psus, 1 Mirror Surround			

Bombardier

Sequence #	4501	Aircraft SN #	6111	MWPWO #	2498069
WO #	2508713	Aircraft Reg #	XA-SOL	Parent WO #	2498069

4501	WO #	2508713	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13276345	No Log Entry	
Interior - Fabricate new LAV closet curtain (604/605/650)				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	10	REFERENCE W.O.4717709 FOR FAR25.853(a) MATERIALS FLAMMABILITY TEST REPORT.	B0132745 - Ray Shumate Mar 05, 2026 09:40 PM	25-00
	Burn test coupons and confirmatory			
	20	FABRICATED 1 NEW CLOSET CURTAIN REFERENCE W.O.4432383 FOR WORK PERFORMED.	B0132745 - Ray Shumate Mar 05, 2026 09:40 PM	25-00
	Perform fabrication of new lavatory closet curtain			

CHILD WORK ORDER DETAILS

	WO #	Description	Corrective Action	AMENDED
4501-1	4432383	Interior Refurb: CURTAIN - COCKPIT (FAB)	7004/4501-FABRICATED 1EA CL650-6111-LWC LAV WARDROBE CURTAIN REFERENCE OPERATIONS 100-500 FOR WORK PERFORMED.	

Sequence #	4501-1	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4432383	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2508713

4501-1	**WO #**	**4432383**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		No Log Entry	
Interior Refurb: CURTAIN - COCKPIT (FAB)				
Task / IRN # : CURTAIN - COCKPIT (FAB)				

Sequence #	4501-1	Aircraft SN #	6111	MWPWO #	2498069
WO #	4432383	Aircraft Reg #	XA-SOL	Parent WO #	2508713

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with: Comply with Preliminary Inspection	B0132745 - Ray Shumate Mar 05, 2026 09:34 PM	
	Comply with Preliminary Inspection			
	200	Complied with: VERIFY COMPONENT/ MATERIALS: 1) P/N: T23031, 002, DEDAR, APLICATORS PLUS , P.O.#500246657	B0132745 - Ray Shumate Mar 05, 2026 09:34 PM	
	VERIFY COMPONENT/MATERIALS: 1) P/N: T23031, 002, DEDAR, APLICATORS PLUS , P.O.#			
	300	Complied with: FABRICATE NEW CLOSET CURTAIN ASSEMBLY USING EXISTING CURTAIN AS TEMPLATE, STITCH PER ASTMD 6193 IAW BAS00270032,SECTION 3.5 REV(B), CABIN TYPICAL REPAIR PROCESS SPECIFICATIONS.	B0132745 - Ray Shumate Mar 05, 2026 09:34 PM	
	FABRICATE NEW CLOSET CURTAIN ASSEMBLY USING EXISTING CURTAIN AS TEMPLATE, STITCH PER ASTMD 6193 IAW BAS00270032,SECTION 3.5, CABIN TYPICAL REPAIR PROCESS SPECIFICATIONS.		Not Required	
	400	Complied with: IDENTIFY CLOSET CURTAIN, STRAP ASSEMBLY, CSO SERVICE ORDER NUMBER, DATE IAW BAPS 144-005, SECTION 9.5.1.1, IDENTIFICATION OF AIRCRAFT PARTS AND ASSEMBLIES.	B0132745 - Ray Shumate Mar 05, 2026 09:34 PM	
	IDENTIFY CLOSET CURTAIN, STRAP ASSEMBLY, CSO SERVICE ORDER NUMBER, DATE IAW BAPS 144-005, SECTION 9.5.1.1, IDENTIFICATION OF AIRCRAFT PARTS AND ASSEMBLIES.		Not Required	
	500	Complied with: VERIFY COMPLETED ASSEMBLY(S) IAW BAS00270032,3.5 REV (B).	B0132745 - Ray Shumate Mar 05, 2026 09:34 PM	
	VERIFY COMPLETED ASSEMBLY(S) IAW BAS00270032 REV (____).			

QA005 RTS Statement

The component identified above was repaired and inspected in accordance with current Federal Aviation Regulations, found airworthy and is approved for return to service with respect to the work performed

Sequence #	4502	Aircraft SN #	6111	MWPWO #	2498069
WO #	2508724	Aircraft Reg #	XA-SOL	Parent WO #	2498069

4502	WO #	2508724	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13276347	No Log Entry	
Interior - Recover main cabin and lavatory upper sidewalls to include PSU pods (650)				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	10	Do Not Work Per Customer Request.	B1014141 - Christopher Drawdy Feb 12, 2026 05:18 PM	25-00
	Provide Interior support to recover main cabin and lavatory upper sidewalls to include PSU pods		B1013522 - Brandon Jennings Feb 12, 2026 05:52 PM	
	20	Do Not Work Per Customer Request.	B1014141 - Christopher Drawdy Feb 12, 2026 05:18 PM	25-00
	Provide Interior support to Burn Coupons		B1013522 - Brandon Jennings Feb 12, 2026 05:52 PM	

CHILD WORK ORDER DETAILS

	WO #	Description	Corrective Action	AMENDED
4502-1	4432394	Interior Refurb: WINDOW OVERLAY PNL (RECOVER)		
4502-2	4432454	Interior Refurb: WINDOW OVERLAY PNL (RECOVER)		
4502-3	4432460	Interior Refurb: WINDOW OVERLAY PNL (RECOVER)		
4502-4	4432463	Interior Refurb: WINDOW OVERLAY PNL (RECOVER)		
4502-5	4432465	Interior Refurb: WINDOW OVERLAY PNL (RECOVER)		
4502-6	4432471	Interior Refurb: WINDOW OVERLAY PNL (RECOVER)		

Sequence #	4502-1	Aircraft SN #	6111	MWPWO #	2498069
WO #	4432394	Aircraft Reg #	XA-SOL	Parent WO #	2508724

4502-1	WO #	4432394	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		No Log Entry	
Interior Refurb: WINDOW OVERLAY PNL (RECOVER)				
Task / IRN # : WINDOW OVERLAY PNL (RECOVER)				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			
	Comply with Preliminary Inspection			
	200			
	Verify P/N's XXXX			
	300			
	STRIP MATERIAL AND CLEAN IAW BAS00270032 SECTION 3.2, CABIN TYPICAL REPAIR PROCESS SPECIFICATIONS.		Not Required	
	400			
	VERIFY FOAM/SUBSTRATE INTEGRITY IAW AC 43.13-1B PAR 5-18.			
	500			
	CONTACT BOND NEW MATERIAL USING EC-1357 ADHESIVE IAW BAS00270032 SECTION 3.2, CABIN TYPICAL REPAIR PROCESS SPECIFICATIONS.		Not Required	
	600			
	VERIFY COMPLETED ASSEMBLY(S) IAW BAS00270032 REV (____).			

Sequence #	4502-1	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4432394	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2508724

QA005 RTS Statement
The component identified above was repaired and inspected in accordance with current Federal Aviation Regulations, found airworthy and is approved for return to service with respect to the work performed

Sequence #	4502-2	Aircraft SN #	6111	MWPWO #	2498069
WO #	4432454	Aircraft Reg #	XA-SOL	Parent WO #	2508724

4502-2	WO #	4432454	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		No Log Entry	
Interior Refurb: WINDOW OVERLAY PNL (RECOVER)				
Task / IRN # : WINDOW OVERLAY PNL (RECOVER)				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			
	Comply with Preliminary Inspection			
	200			
	Verify P/N's XXXX			
	300			
	STRIP MATERIAL AND CLEAN IAW BAS00270032 SECTION 3.2, CABIN TYPICAL REPAIR PROCESS SPECIFICATIONS.		Not Required	
	400			
	VERIFY FOAM/SUBSTRATE INTEGRITY IAW AC 43.13-1B PAR 5-18.			
	500			
	CONTACT BOND NEW MATERIAL USING EC-1357 ADHESIVE IAW BAS00270032 SECTION 3.2, CABIN TYPICAL REPAIR PROCESS SPECIFICATIONS.		Not Required	
	600			
	VERIFY COMPLETED ASSEMBLY(S) IAW BAS00270032 REV (____).			

Sequence #	4502-3	Aircraft SN #	6111	MWPWO #	2498069
WO #	4432460	Aircraft Reg #	XA-SOL	Parent WO #	2508724

4502-3	WO #	4432460	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		No Log Entry	
Interior Refurb: WINDOW OVERLAY PNL (RECOVER)				
Task / IRN # : WINDOW OVERLAY PNL (RECOVER)				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			
	Comply with Preliminary Inspection			
	200			
	Verify P/N's XXXX			
	300			
	STRIP MATERIAL AND CLEAN IAW BAS00270032 SECTION 3.2, CABIN TYPICAL REPAIR PROCESS SPECIFICATIONS.		Not Required	
	400			
	VERIFY FOAM/SUBSTRATE INTEGRITY IAW AC 43.13-1B PAR 5-18.			
	500			
	CONTACT BOND NEW MATERIAL USING EC-1357 ADHESIVE IAW BAS00270032 SECTION 3.2, CABIN TYPICAL REPAIR PROCESS SPECIFICATIONS.		Not Required	
	600			
	VERIFY COMPLETED ASSEMBLY(S) IAW BAS00270032 REV (____).			

Bombardier

Sequence #	4502-4	Aircraft SN #	6111	MWPWO #	2498069
WO #	4432463	Aircraft Reg #	XA-SOL	Parent WO #	2508724

4502-4	WO #	4432463	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		No Log Entry	
Interior Refurb: WINDOW OVERLAY PNL (RECOVER)				
Task / IRN # : WINDOW OVERLAY PNL (RECOVER)				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			
	Comply with Preliminary Inspection			
	200			
	Verify P/N's XXXX			
	300			
	STRIP MATERIAL AND CLEAN IAW BAS00270032 SECTION 3.2, CABIN TYPICAL REPAIR PROCESS SPECIFICATIONS.		Not Required	
	400			
	VERIFY FOAM/SUBSTRATE INTEGRITY IAW AC 43.13-1B PAR 5-18.			
	500			
	CONTACT BOND NEW MATERIAL USING EC-1357 ADHESIVE IAW BAS00270032 SECTION 3.2, CABIN TYPICAL REPAIR PROCESS SPECIFICATIONS.		Not Required	
	600			
	VERIFY COMPLETED ASSEMBLY(S) IAW BAS00270032 REV (____).			

Sequence #	4502-5	Aircraft SN #	6111	MWPWO #	2498069
WO #	4432465	Aircraft Reg #	XA-SOL	Parent WO #	2508724

4502-5	WO #	4432465	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		No Log Entry	
Interior Refurb: WINDOW OVERLAY PNL (RECOVER)				
Task / IRN # : WINDOW OVERLAY PNL (RECOVER)				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			
	Comply with Preliminary Inspection			
	200			
	Verify P/N's XXXX			
	300			
	STRIP MATERIAL AND CLEAN IAW BAS00270032 SECTION 3.2, CABIN TYPICAL REPAIR PROCESS SPECIFICATIONS.		Not Required	
	400			
	VERIFY FOAM/SUBSTRATE INTEGRITY IAW AC 43.13-1B PAR 5-18.			
	500			
	CONTACT BOND NEW MATERIAL USING EC-1357 ADHESIVE IAW BAS00270032 SECTION 3.2, CABIN TYPICAL REPAIR PROCESS SPECIFICATIONS.		Not Required	
	600			
	VERIFY COMPLETED ASSEMBLY(S) IAW BAS00270032 REV (____).			

Sequence #	4502-6	Aircraft SN #	6111	MWPWO #	2498069
WO #	4432471	Aircraft Reg #	XA-SOL	Parent WO #	2508724

4502-6	WO #	4432471	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		No Log Entry	
Interior Refurb: WINDOW OVERLAY PNL (RECOVER)				
Task / IRN # : WINDOW OVERLAY PNL (RECOVER)				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			
	Comply with Preliminary Inspection			
	200			
	Verify P/N's XXXX			
	300			
	STRIP MATERIAL AND CLEAN IAW BAS00270032 SECTION 3.2, CABIN TYPICAL REPAIR PROCESS SPECIFICATIONS.		Not Required	
	400			
	VERIFY FOAM/SUBSTRATE INTEGRITY IAW AC 43.13-1B PAR 5-18.			
	500			
	CONTACT BOND NEW MATERIAL USING EC-1357 ADHESIVE IAW BAS00270032 SECTION 3.2, CABIN TYPICAL REPAIR PROCESS SPECIFICATIONS.		Not Required	
	600			
	VERIFY COMPLETED ASSEMBLY(S) IAW BAS00270032 REV (____).			

Bombardier

Sequence #	4503	Aircraft SN #	6111	MWPWO #	2498069
WO #	2584086	Aircraft Reg #	XA-SOL	Parent WO #	2498069

4503	WO #	2584086	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13276164	No Log Entry	
Interior - Recover dado panels (600/601/604/605/650)				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			25-00
	Provide interior support for recovering dado panels			
	200			25-00
	Provide interior support for burn coupon testing			

CHILD WORK ORDER DETAILS

	WO #	Description	Corrective Action	AMENDED
4503-1	4432497	Interior Refurb: DADO PNL RECOVER		
4503-2	4432504	7012/4503-RECOVER 1EA C462102-517 DADO ASSY -LH AFT		
4503-3	4432509	Interior Refurb: DADO PNL RECOVER		
4503-4	4432512	Interior Refurb: DADO PNL RECOVER		
4503-5	4432524	Interior Refurb: DADO PNL RECOVER		

Sequence #	4503-1	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4432497	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2584086

4503-1	**WO #**	**4432497**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		No Log Entry	
Interior Refurb: DADO PNL RECOVER				
Task / IRN # : DADO PNL RECOVER				

Sequence #	4503-1	Aircraft SN #	6111	MWPWO #	2498069
WO #	4432497	Aircraft Reg #	XA-SOL	Parent WO #	2584086

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100 Comply with Preliminary Inspection	Complied with: Comply with Preliminary Inspection		
	200 VERIFY MATERIAL/COMPONENTS: 1) P/N: C4628APN-101 DADO PANEL - LH FWD, EXISTING 2) P/N: PP-6204-MSG, LONG FOG, PERFECTLY PEBBLE.TOWNSEND P.O.# 3) P/N: _____FOAM P.O.#4) P/N: 048011-98648 EC-1357 ADHESIVE, P.O.#	Complied with: VERIFY MATERIAL/ COMPONENTS: 1) P/N: C4628APN-101 DADO PANEL - LH FWD, EXISTING 2) P/N: PP-6204-MSG, LONG FOG, PERFECTLY PEBBLE.TOWNSEND P.O.# 3) P/N: SKAHC.125 ENSOLITE FOAM P.O.#5002451905 4) P/N: 048011-98648 EC-1357 ADHESIVE, P.O.#5002405713		
	300 STRIP MATERIAL AND CLEAN IAW BAS00270032 SECTION 3.2, CABIN TYPICAL REPAIR PROCESS SPECIFICATIONS.	Complied with: STRIP MATERIAL AND CLEAN IAW BAS00270032 SECTION 3.2 REV(B), CABIN TYPICAL REPAIR PROCESS SPECIFICATIONS.	Not Required	
	400 VERIFY FOAM /SUBSTRATE INTEGRITY IAW AC 43.13-1B PAR 5-18.	Complied with: VERIFY FOAM /SUBSTRATE INTEGRITY IAW AC 43.13-1B PAR 5-18.		
	500 CONTACT BOND NEW MATERIAL USING EC-1357 ADHESIVE IAW BAS00270032 SECTION 3.2, CABIN TYPICAL REPAIR PROCESS SPECIFICATIONS.	Complied with: CONTACT BOND NEW MATERIAL USING EC-1357 ADHESIVE IAW BAS00270032 SECTION 3.2 REV(B), CABIN TYPICAL REPAIR PROCESS SPECIFICATIONS.	Not Required	
	600 VERIFY COMPLETED ASSEMBLY(S) IAW BAS00270032 REV (____).	Complied with: VERIFY COMPLETED ASSEMBLY(S) IAW BAS00270032 REV (B).		

QA005 RTS Statement

Sequence #	4503-1	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4432497	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2584086

The component identified above was repaired and inspected in accordance with current Federal Aviation Regulations, found airworthy and is approved for return to service with respect to the work performed

Sequence #	4503-2	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4432504	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2584086

4503-2	**WO #**	**4432504**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		No Log Entry	
7012/4503-RECOVER 1EA C462102-517 DADO ASSY -LH AFT				
Task / IRN # : DADO PNL RECOVER				

Sequence #	4503-2	Aircraft SN #	6111	MWPWO #	2498069
WO #	4432504	Aircraft Reg #	XA-SOL	Parent WO #	2584086

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100 Comply with Preliminary Inspection	Complied with: Comply with Preliminary Inspection		
	200 VERIFY MATERIAL/COMPONENTS: 1) P/N: C462102-517 DADO ASSY -RH FWD, EXISTING 2) P/N: PP-6204-MSG, LONG FOG, PERFECTLY PEBBLE.TOWNSEND P.O.# 3) P/N: _____FOAM P.O.#4) P/N: 048011-98648 EC-1357 ADHESIVE, P.O.#	Complied with: VERIFY MATERIAL/ COMPONENTS: 1) P/N: C462102-517 DADO ASSY -RH FWD, EXISTING 2) P/N: PP-6204-MSG, LONG FOG, PERFECTLY PEBBLE.TOWNSEND P.O.# 3) P/N: SKAHC.125 ENSOLITE FOAM P.O.#5002451905 4) P/N: 048011-98648 EC-1357 ADHESIVE, P.O.#5002405713		
	300 STRIP MATERIAL AND CLEAN IAW BAS00270032 SECTION 3.2, CABIN TYPICAL REPAIR PROCESS SPECIFICATIONS.	Complied with: STRIP MATERIAL AND CLEAN IAW BAS00270032 SECTION 3.2 REV(B), CABIN TYPICAL REPAIR PROCESS SPECIFICATIONS.	Not Required	
	400 VERIFY FOAM /SUBSTRATE INTEGRITY IAW AC 43.13-1B PAR 5-18.	Complied with: VERIFY FOAM /SUBSTRATE INTEGRITY IAW AC 43.13-1B PAR 5-18.		
	500 CONTACT BOND NEW MATERIAL USING EC-1357 ADHESIVE IAW BAS00270032 SECTION 3.2, CABIN TYPICAL REPAIR PROCESS SPECIFICATIONS.	Complied with: CONTACT BOND NEW MATERIAL USING EC-1357 ADHESIVE IAW BAS00270032 SECTION 3.2 REV(B), CABIN TYPICAL REPAIR PROCESS SPECIFICATIONS.	Not Required	
	600 VERIFY COMPLETED ASSEMBLY(S) IAW BAS00270032 REV (____).	Complied with: VERIFY COMPLETED ASSEMBLY(S) IAW BAS00270032 REV (B).		

QA005 RTS Statement

Sequence #	4503-2	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4432504	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2584086

The component identified above was repaired and inspected in accordance with current Federal Aviation Regulations, found airworthy and is approved for return to service with respect to the work performed

Sequence #	4503-3	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4432509	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2584086

4503-3	**WO #**	**4432509**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		No Log Entry	
Interior Refurb: DADO PNL RECOVER				
Task / IRN # : DADO PNL RECOVER				

Sequence #	4503-3	Aircraft SN #	6111	MWPWO #	2498069
WO #	4432509	Aircraft Reg #	XA-SOL	Parent WO #	2584086

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100 Comply with Preliminary Inspection	Complied with: Comply with Preliminary Inspection		
	200 VERIFY MATERIAL/COMPONENTS: 1) P/N: C4628APN-103 DADO PANEL - RH FWD, EXISTING 2) P/N: PP-6204-MSG, LONG FOG, PERFECTLY PEBBLE.TOWNSEND P.O.# 3) P/N: _____FOAM P.O.#4) P/N: 048011-98648 EC-1357 ADHESIVE, P.O.#	Complied with: VERIFY MATERIAL/ COMPONENTS: 1) P/N: C4628APN-103 DADO PANEL - RH FWD, EXISTING 2) P/N: PP-6204-MSG, LONG FOG, PERFECTLY PEBBLE.TOWNSEND P.O.# 3) P/N: SKAHC.125 ENSOLITE FOAM P.O.#5002451905 4) P/N: 048011-98648 EC-1357 ADHESIVE, P.O.#5002405713		
	300 STRIP MATERIAL AND CLEAN IAW BAS00270032 SECTION 3.2, CABIN TYPICAL REPAIR PROCESS SPECIFICATIONS.	Complied with: STRIP MATERIAL AND CLEAN IAW BAS00270032 SECTION 3.2 REV(B), CABIN TYPICAL REPAIR PROCESS SPECIFICATIONS.	Not Required	
	400 VERIFY FOAM /SUBSTRATE INTEGRITY IAW AC 43.13-1B PAR 5-18.	Complied with: VERIFY FOAM /SUBSTRATE INTEGRITY IAW AC 43.13-1B PAR 5-18.		
	500 CONTACT BOND NEW MATERIAL USING EC-1357 ADHESIVE IAW BAS00270032 SECTION 3.2, CABIN TYPICAL REPAIR PROCESS SPECIFICATIONS.	Complied with: CONTACT BOND NEW MATERIAL USING EC-1357 ADHESIVE IAW BAS00270032 SECTION 3.2 REV(B), CABIN TYPICAL REPAIR PROCESS SPECIFICATIONS.	Not Required	
	600 VERIFY COMPLETED ASSEMBLY(S) IAW BAS00270032 REV (____).	Complied with: VERIFY COMPLETED ASSEMBLY(S) IAW BAS00270032 REV (B).		

QA005 RTS Statement

Sequence #	4503-3	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4432509	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2584086

The component identified above was repaired and inspected in accordance with current Federal Aviation Regulations, found airworthy and is approved for return to service with respect to the work performed

Sequence #	4503-4	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4432512	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2584086

4503-4	**WO #**	**4432512**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		No Log Entry	
Interior Refurb: DADO PNL RECOVER				
Task / IRN # : DADO PNL RECOVER				

Sequence #	4503-4	Aircraft SN #	6111	MWPWO #	2498069
WO #	4432512	Aircraft Reg #	XA-SOL	Parent WO #	2584086

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100 Comply with Preliminary Inspection	Complied with: Comply with Preliminary Inspection		
	200 VERIFY MATERIAL/COMPONENTS: 1) P/N: C4628APN-113 DADO PANEL - RH AFT, EXISTING 2) P/N: PP-6204-MSG, LONG FOG, PERFECTLY PEBBLE.TOWNSEND P.O.# 3) P/N: _____FOAM P.O.#4) P/N: 048011-98648 EC-1357 ADHESIVE, P.O.#	Complied with: VERIFY MATERIAL/ COMPONENTS: 1) P/N: C4628APN-113 DADO PANEL - RH AFT, EXISTING 2) P/N: PP-6204-MSG, LONG FOG, PERFECTLY PEBBLE.TOWNSEND P.O.# 3) P/N: SKAHC.125 ENSOLITE FOAM P.O.#5002451905 4) P/N: 048011-98648 EC-1357 ADHESIVE, P.O.#5002405713		
	300 STRIP MATERIAL AND CLEAN IAW BAS00270032 SECTION 3.2, CABIN TYPICAL REPAIR PROCESS SPECIFICATIONS.	Complied with: STRIP MATERIAL AND CLEAN IAW BAS00270032 SECTION 3.2 REV(B), CABIN TYPICAL REPAIR PROCESS SPECIFICATIONS.	Not Required	
	400 VERIFY FOAM /SUBSTRATE INTEGRITY IAW AC 43.13-1B PAR 5-18.	Complied with: VERIFY FOAM /SUBSTRATE INTEGRITY IAW AC 43.13-1B PAR 5-18.		
	500 CONTACT BOND NEW MATERIAL USING EC-1357 ADHESIVE IAW BAS00270032 SECTION 3.2, CABIN TYPICAL REPAIR PROCESS SPECIFICATIONS.	Complied with: CONTACT BOND NEW MATERIAL USING EC-1357 ADHESIVE IAW BAS00270032 SECTION 3.2 REV(B), CABIN TYPICAL REPAIR PROCESS SPECIFICATIONS.	Not Required	
	600 VERIFY COMPLETED ASSEMBLY(S) IAW BAS00270032 REV (____).	Complied with: VERIFY COMPLETED ASSEMBLY(S) IAW BAS00270032 REV (B).		

QA005 RTS Statement

Sequence #	4503-4	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4432512	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2584086

The component identified above was repaired and inspected in accordance with current Federal Aviation Regulations, found airworthy and is approved for return to service with respect to the work performed

Sequence #	4503-5	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4432524	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2584086

4503-5	**WO #**	**4432524**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		No Log Entry	
Interior Refurb: DADO PNL RECOVER				
Task / IRN # : DADO PNL RECOVER				

Sequence #	4503-5	Aircraft SN #	6111	MWPWO #	2498069
WO #	4432524	Aircraft Reg #	XA-SOL	Parent WO #	2584086

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100 Comply with Preliminary Inspection	Complied with: Comply with Preliminary Inspection		
	200 VERIFY MATERIAL/COMPONENTS: 1) P/N: C462105-515 EMER DADO ASSY - RH MID, EXISTING 2) P/N: PP-6204-MSG, LONG FOG, PERFECTLY PEBBLE.TOWNSEND P.O.# 3) P/N: _____FOAM P.O.#4) P/N: 048011-98648 EC-1357 ADHESIVE, P.O.#	Complied with: VERIFY MATERIAL/ COMPONENTS: 1) P/N: C462105-515 EMER DADO ASSY - RH MID, EXISTING 2) P/N: PP-6204-MSG, LONG FOG, PERFECTLY PEBBLE.TOWNSEND P.O.# 3) P/N: SKAHC.125 ENSOLITE FOAM P.O.#5002451905 4) P/N: 048011-98648 EC-1357 ADHESIVE, P.O.#5002405713		
	300 STRIP MATERIAL AND CLEAN IAW BAS00270032 SECTION 3.2, CABIN TYPICAL REPAIR PROCESS SPECIFICATIONS.	Complied with: STRIP MATERIAL AND CLEAN IAW BAS00270032 SECTION 3.2 REV(B), CABIN TYPICAL REPAIR PROCESS SPECIFICATIONS.	Not Required	
	400 VERIFY FOAM /SUBSTRATE INTEGRITY IAW AC 43.13-1B PAR 5-18.	Complied with: VERIFY FOAM /SUBSTRATE INTEGRITY IAW AC 43.13-1B PAR 5-18.		
	500 CONTACT BOND NEW MATERIAL USING EC-1357 ADHESIVE IAW BAS00270032 SECTION 3.2, CABIN TYPICAL REPAIR PROCESS SPECIFICATIONS.	Complied with: CONTACT BOND NEW MATERIAL USING EC-1357 ADHESIVE IAW BAS00270032 SECTION 3.2 REV(B), CABIN TYPICAL REPAIR PROCESS SPECIFICATIONS.	Not Required	
	600 VERIFY COMPLETED ASSEMBLY(S) IAW BAS00270032 REV (____).	Complied with: VERIFY COMPLETED ASSEMBLY(S) IAW BAS00270032 REV (B).		

QA005 RTS Statement

Sequence #	4503-5	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4432524	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2584086

The component identified above was repaired and inspected in accordance with current Federal Aviation Regulations, found airworthy and is approved for return to service with respect to the work performed

Sequence #	4504	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	2508720	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

4504	**WO #**	**2508720**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #	13276346	No Log Entry	
Interior - Recover entry, main cabin and lavatory headliners (604/605/650)				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	STRIPPED AND RECOVERED ENTRY, CABIN AND LAV HEADLINERS REFERENCE THE FOLLOWING W.O.'S FOR WORK PERFORMED. 4432538 ENTRY HEADLINER 4432543 CABIN HEADLINER 4432550 L/H LAV HEADLINER 4432561 MID LAV HEADLINER 4432568 R/H LAV HEADLINER	B0132745 - Ray Shumate Mar 04, 2026 03:51 PM	25-00
	C/W the interior support to recover entry, main cabin and lavatory headliners			
	200	REFERENCE W.O. 4717709 FOR FAR25.853(a) MATERIALS FLAMMABILITY TEST REPORT.	B0132745 - Ray Shumate Mar 04, 2026 03:51 PM	25-00
	C/W the interior support to do the burn coupons			

Sequence #	4504	Aircraft SN #	6111	MWPWO #	2498069
WO #	2508720	Aircraft Reg #	XA-SOL	Parent WO #	2498069

CHILD WORK ORDER DETAILS

	WO #	Description	Corrective Action	AMENDED
4504-1	4432538	Interior Refurb: HEADLINER PNL (RECOVER)	7016/4504-RECOVERED 1EA C2718APN-101 ENTRY HEADLINER REFERENCE OPERATIONS 100-600 FOR WORK PERFORMED.	
4504-2	4432543	Interior Refurb: HEADLINER PNL (RECOVER)	7017/4504-RECOVERED 1EA C2718APN-103 CABIN HEADLINER REFERENCE OPERATIONS 100-600 FOR WORK PERFORMED.	
4504-3	4432550	Interior Refurb: HEADLINER PNL (RECOVER)	7018/4504-RECOVERED 1EA C275304-501 HEADLINER ASSY - LH LAV REFERENCE OPERATIONS 100-600 FOR WORK PWERFORMED.	
4504-4	4432561	Interior Refurb: HEADLINER PNL (RECOVER)	7019/4504-RECOVERED 1EA C275305-503 HEADLINER ASSY -MID LAV REFERENCE OPERATIONS 100-600 FOR WORK PERFORMED .	
4504-5	4432568	Interior Refurb: HEADLINER PNL (RECOVER)	7020/4504-RECOVERED 1EA C275306-501 HEADLINER ASSY -RH LAV REFERENCE OPERATIONS 100-600 FOR WORK PERFORMED.	

Sequence #	4504-1	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4432538	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2508720

4504-1	**WO #**	**4432538**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		No Log Entry	
Interior Refurb: HEADLINER PNL (RECOVER)				
Task / IRN # : HEADLINER PNL (RECOVER)				

Sequence #	4504-1	Aircraft SN #	6111	MWPWO #	2498069
WO #	4432538	Aircraft Reg #	XA-SOL	Parent WO #	2508720

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100 Comply with Preliminary Inspection	Complied with: Comply with Preliminary Inspection	B0132745 - Ray Shumate Mar 04, 2026 02:48 PM	
	200 VERIFY MATERIAL/COMPONENTS: 1) P/N: C2718APN-101 ENTRY HEADLINER, EXISTING 2) P/N: ULFR5684, ARCTIC TAPIS ULTRALEATHER, P.O.# 3) P/N:_____FOAM, P.O.# 4) P/N: 048011-98648 EC-1357 ADHESIVE, P.O.#	Complied with: VERIFY MATERIAL/ COMPONENTS: 1) P/N: C2718APN-101 ENTRY HEADLINER, EXISTING 2) P/N: ULFR5684, ARCTIC TAPIS ULTRALEATHER, P.O.# 5002478132 3) P/N: AL70.125 FOAM, P.O.#5002476620 4) P/N: 048011-98648 EC-1357 ADHESIVE, P.O.#5002405713	B0132745 - Ray Shumate Mar 04, 2026 02:48 PM	
	300 STRIP MATERIAL AND CLEAN IAW BAS00270032 SECTION 3.2, CABIN TYPICAL REPAIR PROCESS SPECIFICATIONS.	Complied with: STRIP MATERIAL AND CLEAN IAW BAS00270032 SECTION 3.2 REV(B), CABIN TYPICAL REPAIR PROCESS SPECIFICATIONS.	B0132745 - Ray Shumate Mar 04, 2026 02:48 PM Not Required	
	400 VERIFY FOAM /SUBSTRATE INTEGRITY IAW AC 43.13-1B PAR 5-18.	Complied with: VERIFY FOAM /SUBSTRATE INTEGRITY IAW AC 43.13-1B PAR 5-18.	B0132745 - Ray Shumate Mar 04, 2026 02:48 PM	
	500 CONTACT BOND NEW MATERIAL USING EC-1357 ADHESIVE IAW BAS00270032 SECTION 3.2, CABIN TYPICAL REPAIR PROCESS SPECIFICATIONS	Complied with: CONTACT BOND NEW MATERIAL USING EC-1357 ADHESIVE IAW BAS00270032 SECTION 3.2 REV(B), CABIN TYPICAL REPAIR PROCESS SPECIFICATIONS	B0132745 - Ray Shumate Mar 04, 2026 02:48 PM Not Required	

Sequence #	4504-1	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4432538	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2508720

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	600	Complied with: VERIFY COMPLETED ASSEMBLY(S) IAW BAS00270032,3.2 REV (B).	B0132745 - Ray Shumate Mar 04, 2026 02:48 PM	
	VERIFY COMPLETED ASSEMBLY(S) IAW BAS00270032 REV (____).			

QA005 RTS Statement

The component identified above was repaired and inspected in accordance with current Federal Aviation Regulations, found airworthy and is approved for return to service with respect to the work performed

Sequence #	4504-2	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4432543	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2508720

4504-2	**WO #**	**4432543**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		No Log Entry	
Interior Refurb: HEADLINER PNL (RECOVER)				
Task / IRN # : HEADLINER PNL (RECOVER)				

Sequence #	4504-2	Aircraft SN #	6111	MWPWO #	2498069
WO #	4432543	Aircraft Reg #	XA-SOL	Parent WO #	2508720

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100 Comply with Preliminary Inspection	Complied with: Comply with Preliminary Inspection	B0132745 - Ray Shumate Mar 06, 2026 03:00 PM	
	200 VERIFY MATERIAL/COMPONENTS: 1) P/N: C2718APN-103 CABIN HEADLINER, EXISTING 2) P/N: ULFR5684, ARCTIC TAPIS ULTRALEATHER, P.O.# 3) P/N:_____FOAM, P.O.# 4) P/N: 048011-98648 EC-1357 ADHESIVE, P.O.#	Complied with: VERIFY MATERIAL/ COMPONENTS: 1) P/N: C2718APN-103 CABIN HEADLINER, EXISTING 2) P/N: ULFR5684, ARCTIC TAPIS ULTRALEATHER, P.O.# 5002478132 3) P/N: AL70.125 FOAM, P.O.#5002476620 4) P/N: 048011-98648 EC-1357 ADHESIVE, P.O.#5002405713	B0132745 - Ray Shumate Mar 06, 2026 03:00 PM	
	300 STRIP MATERIAL AND CLEAN IAW BAS00270032 SECTION 3.2, CABIN TYPICAL REPAIR PROCESS SPECIFICATIONS.	Complied with: STRIP MATERIAL AND CLEAN IAW BAS00270032 SECTION 3.2 REV(B), CABIN TYPICAL REPAIR PROCESS SPECIFICATIONS.	B0132745 - Ray Shumate Mar 06, 2026 03:00 PM Not Required	
	400 VERIFY FOAM /SUBSTRATE INTEGRITY IAW AC 43.13-1B PAR 5-18.	Complied with: VERIFY FOAM /SUBSTRATE INTEGRITY IAW AC 43.13-1B PAR 5-18.	B0132745 - Ray Shumate Mar 06, 2026 03:00 PM	
	500 CONTACT BOND NEW MATERIAL USING EC-1357 ADHESIVE IAW BAS00270032 SECTION 3.2, CABIN TYPICAL REPAIR PROCESS SPECIFICATIONS	Complied with: CONTACT BOND NEW MATERIAL USING EC-1357 ADHESIVE IAW BAS00270032 SECTION 3.2 REV(B), CABIN TYPICAL REPAIR PROCESS SPECIFICATIONS	B0132745 - Ray Shumate Mar 06, 2026 03:00 PM Not Required	

Sequence #	4504-2	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4432543	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2508720

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	600	Complied with: VERIFY COMPLETED ASSEMBLY(S) IAW BAS00270032,3.2 REV (B).	B0132745 - Ray Shumate Mar 06, 2026 03:00 PM	
	VERIFY COMPLETED ASSEMBLY(S) IAW BAS00270032 REV (____).			

QA005 RTS Statement

The component identified above was repaired and inspected in accordance with current Federal Aviation Regulations, found airworthy and is approved for return to service with respect to the work performed

Sequence #	4504-3	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4432550	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2508720

4504-3	**WO #**	**4432550**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		No Log Entry	
Interior Refurb: HEADLINER PNL (RECOVER)				
Task / IRN # : HEADLINER PNL (RECOVER)				

Sequence #	4504-3	Aircraft SN #	6111	MWPWO #	2498069
WO #	4432550	Aircraft Reg #	XA-SOL	Parent WO #	2508720

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100 Comply with Preliminary Inspection	Complied with: Comply with Preliminary Inspection	B0132745 - Ray Shumate Mar 04, 2026 03:18 PM	
	200 VERIFY MATERIAL/COMPONENTS: 1) P/N: C275304-501 HEADLINER ASSY - LH LAV, EXISTING 2) P/N: ULFR5684, ARCTIC TAPIS ULTRALEATHER, P.O.# 3) P/N:_____FOAM, P.O.# 4) P/N: 048011-98648 EC-1357 ADHESIVE, P.O.#	Complied with: VERIFY MATERIAL/ COMPONENTS: 1) P/N: C275304-501 HEADLINER ASSY - LH LAV, EXISTING 2) P/N: ULFR5684, ARCTIC TAPIS ULTRALEATHER, P.O.# 5002478132 3) P/N: AL70.125 FOAM, P.O.#5002476620 4) P/N: 048011-98648 EC-1357 ADHESIVE, P.O.#5002405713	B0132745 - Ray Shumate Mar 04, 2026 03:18 PM	
	300 STRIP MATERIAL AND CLEAN IAW BAS00270032 SECTION 3.2, CABIN TYPICAL REPAIR PROCESS SPECIFICATIONS.	Complied with: STRIP MATERIAL AND CLEAN IAW BAS00270032 SECTION 3.2 REV(B), CABIN TYPICAL REPAIR PROCESS SPECIFICATIONS.	B0132745 - Ray Shumate Mar 04, 2026 03:18 PM Not Required	
	400 VERIFY FOAM /SUBSTRATE INTEGRITY IAW AC 43.13-1B PAR 5-18.	Complied with: VERIFY FOAM /SUBSTRATE INTEGRITY IAW AC 43.13-1B PAR 5-18.	B0132745 - Ray Shumate Mar 04, 2026 03:18 PM	
	500 CONTACT BOND NEW MATERIAL USING EC-1357 ADHESIVE IAW BAS00270032 SECTION 3.2, CABIN TYPICAL REPAIR PROCESS SPECIFICATIONS	Complied with: CONTACT BOND NEW MATERIAL USING EC-1357 ADHESIVE IAW BAS00270032 SECTION 3.2 REV(B), CABIN TYPICAL REPAIR PROCESS SPECIFICATIONS	B0132745 - Ray Shumate Mar 04, 2026 03:18 PM Not Required	

Sequence #	4504-3	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4432550	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2508720

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	600	Complied with: VERIFY COMPLETED ASSEMBLY(S) IAW BAS00270032,3.2 REV (B).	B0132745 - Ray Shumate Mar 04, 2026 03:18 PM	
	VERIFY COMPLETED ASSEMBLY(S) IAW BAS00270032 REV (____).			

QA005 RTS Statement

The component identified above was repaired and inspected in accordance with current Federal Aviation Regulations, found airworthy and is approved for return to service with respect to the work performed

Sequence #	4504-4	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4432561	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2508720

4504-4	**WO #**	**4432561**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		No Log Entry	
Interior Refurb: HEADLINER PNL (RECOVER)				
Task / IRN # : HEADLINER PNL (RECOVER)				

Sequence #	4504-4	Aircraft SN #	6111	MWPWO #	2498069
WO #	4432561	Aircraft Reg #	XA-SOL	Parent WO #	2508720

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100 Comply with Preliminary Inspection	Complied with: Comply with Preliminary Inspection	B0132745 - Ray Shumate Mar 04, 2026 03:27 PM	
	200 VERIFY MATERIAL/COMPONENTS: 1) P/N: C275305-503 HEADLINER ASSY -MID LAV, EXISTING 2) P/N: ULFR5684, ARCTIC TAPIS ULTRALEATHER, P.O.# 3) P/N:_____FOAM, P.O.# 4) P/N: 048011-98648 EC-1357 ADHESIVE, P.O.#	Complied with: VERIFY MATERIAL/ COMPONENTS: 1) P/N: C275305-503 HEADLINER ASSY -MID LAV, EXISTING 2) P/N: ULFR5684, ARCTIC TAPIS ULTRALEATHER, P.O.# 5002478132 3) P/N: AL70.125 FOAM, P.O.#5002476620 4) P/N: 048011-98648 EC-1357 ADHESIVE, P.O.#5002405713	B0132745 - Ray Shumate Mar 04, 2026 03:27 PM	
	300 STRIP MATERIAL AND CLEAN IAW BAS00270032 SECTION 3.2, CABIN TYPICAL REPAIR PROCESS SPECIFICATIONS.	Complied with: STRIP MATERIAL AND CLEAN IAW BAS00270032 SECTION 3.2 REV(B), CABIN TYPICAL REPAIR PROCESS SPECIFICATIONS.	B0132745 - Ray Shumate Mar 04, 2026 03:27 PM Not Required	
	400 VERIFY FOAM /SUBSTRATE INTEGRITY IAW AC 43.13-1B PAR 5-18.	Complied with: VERIFY FOAM /SUBSTRATE INTEGRITY IAW AC 43.13-1B PAR 5-18.	B0132745 - Ray Shumate Mar 04, 2026 03:27 PM	
	500 CONTACT BOND NEW MATERIAL USING EC-1357 ADHESIVE IAW BAS00270032 SECTION 3.2, CABIN TYPICAL REPAIR PROCESS SPECIFICATIONS	Complied with: CONTACT BOND NEW MATERIAL USING EC-1357 ADHESIVE IAW BAS00270032 SECTION 3.2 REV(B), CABIN TYPICAL REPAIR PROCESS SPECIFICATIONS	B0132745 - Ray Shumate Mar 04, 2026 03:27 PM Not Required	

Sequence #	4504-4	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4432561	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2508720

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	600	Complied with: VERIFY COMPLETED ASSEMBLY(S) IAW BAS00270032,3.2 REV (B).	B0132745 - Ray Shumate Mar 04, 2026 03:27 PM	
	VERIFY COMPLETED ASSEMBLY(S) IAW BAS00270032 REV (____).			

QA005 RTS Statement

The component identified above was repaired and inspected in accordance with current Federal Aviation Regulations, found airworthy and is approved for return to service with respect to the work performed

Sequence #	4504-5	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4432568	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2508720

4504-5	**WO #**	**4432568**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		No Log Entry	
Interior Refurb: HEADLINER PNL (RECOVER)				
Task / IRN # : HEADLINER PNL (RECOVER)				

Sequence #	4504-5	Aircraft SN #	6111	MWPWO #	2498069
WO #	4432568	Aircraft Reg #	XA-SOL	Parent WO #	2508720

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100 Comply with Preliminary Inspection	Complied with: Comply with Preliminary Inspection	B0132745 - Ray Shumate Mar 04, 2026 03:44 PM	
	200 VERIFY MATERIAL/COMPONENTS: 1) P/N: C275306-501 HEADLINER ASSY -RH LAV, EXISTING 2) P/N: ULFR5684, ARCTIC TAPIS ULTRALEATHER, P.O.# 3) P/N:_____FOAM, P.O.# 4) P/N: 048011-98648 EC-1357 ADHESIVE, P.O.#	Complied with: VERIFY MATERIAL/ COMPONENTS: 1) P/N: C275306-501 HEADLINER ASSY -RH LAV, EXISTING 2) P/N: ULFR5684, ARCTIC TAPIS ULTRALEATHER, P.O.# 5002478132 3) P/N: AL70.125 FOAM, P.O.#5002476620 4) P/N: 048011-98648 EC-1357 ADHESIVE, P.O.#5002405713	B0132745 - Ray Shumate Mar 04, 2026 03:44 PM	
	300 STRIP MATERIAL AND CLEAN IAW BAS00270032 SECTION 3.2, CABIN TYPICAL REPAIR PROCESS SPECIFICATIONS.	Complied with: STRIP MATERIAL AND CLEAN IAW BAS00270032 SECTION 3.2 REV(B), CABIN TYPICAL REPAIR PROCESS SPECIFICATIONS.	B0132745 - Ray Shumate Mar 04, 2026 03:44 PM Not Required	
	400 VERIFY FOAM /SUBSTRATE INTEGRITY IAW AC 43.13-1B PAR 5-18.	Complied with: VERIFY FOAM /SUBSTRATE INTEGRITY IAW AC 43.13-1B PAR 5-18.	B0132745 - Ray Shumate Mar 04, 2026 03:44 PM	
	500 CONTACT BOND NEW MATERIAL USING EC-1357 ADHESIVE IAW BAS00270032 SECTION 3.2, CABIN TYPICAL REPAIR PROCESS SPECIFICATIONS	Complied with: CONTACT BOND NEW MATERIAL USING EC-1357 ADHESIVE IAW BAS00270032 SECTION 3.2 REV(B), CABIN TYPICAL REPAIR PROCESS SPECIFICATIONS	B0132745 - Ray Shumate Mar 04, 2026 03:44 PM Not Required	

Sequence #	4504-5	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4432568	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2508720

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	600	Complied with: VERIFY COMPLETED ASSEMBLY(S) IAW BAS00270032 REV (B).	B0132745 - Ray Shumate Mar 04, 2026 03:44 PM	
	VERIFY COMPLETED ASSEMBLY(S) IAW BAS00270032 REV (____).			

QA005 RTS Statement

The component identified above was repaired and inspected in accordance with current Federal Aviation Regulations, found airworthy and is approved for return to service with respect to the work performed

Bombardier

Sequence #	4505	Aircraft SN #	6111	MWPWO #	2498069
WO #	2584091	Aircraft Reg #	XA-SOL	Parent WO #	2498069

4505	WO #	2584091	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13276328	No Log Entry	
Interior - Fabricate new acoustical curtain (604/605/650)				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			25-00
	C/W fabrication of new acoustical curtain			
	200			25-00
	C/W providing burn test coupons and conformity			

CHILD WORK ORDER DETAILS

	WO #	Description	Corrective Action	AMENDED
4505-1	4432575	Interior Refurb: CURTAIN - ACOUSTIC (FAB)		

Sequence #	4505-1	Aircraft SN #	6111	MWPWO #	2498069
WO #	4432575	Aircraft Reg #	XA-SOL	Parent WO #	2584091

4505-1	WO #	4432575	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		No Log Entry	
Interior Refurb: CURTAIN - ACOUSTIC (FAB)				
Task / IRN # : CURTAIN - ACOUSTIC (FAB)				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with: Comply with Preliminary Inspection		
	Comply with Preliminary Inspection			
	200	Complied with: VERIFY COMPONENT/ MATERIALS: 1) P/N: DEDAR MILLEMIGLIA T23031FABRIC, P.O.#5002466357 2) P/N: ULCOFR5652 CONTOUR STRETCH ARCTIC 5652 ULTRALEATHER P.O.#5002466358		
	VERIFY COMPONENT/MATERIALS: 1)P/N: DEDAR MILLEMIGLIA T23031FABRIC, P.O.# 2)P/N: ULCOFR5652 CONTOUR STRETCH ARCTIC 5652 ULTRALEATHER			
	300	Complied with: FABRICATE ACOUSTIC CURTAIN ASSEMBLY USING EXISTING CURTAIN AS TEMPLATE, STITCH PER ASTMD 6193 IAW BAS00270032, SECTION 3.5 REV(B), CABIN TYPICAL REPAIR PROCESS SPECIFICATIONS.		
	FABRICATE ACOUSTIC CURTAIN ASSEMBLY USING EXISTING CURTAIN AS TEMPLATE, STITCH PER ASTMD 6193 IAW BAS00270032, SECTION 3.5, CABIN TYPICAL REPAIR PROCESS SPECIFICATIONS.		Not Required	
	400	Complied with: IDENTIFY ACOUSTIC CURTAIN, STRAP ASSEMBLY, CSO SERVICE ORDER NUMBER, DATE IAW BAPS 144-005, SECTION 9.5.1.1, IDENTIFICATION OF AIRCRAFT PARTS AND ASSEMBLIES.		
	IDENTIFY ACOUSTIC CURTAIN, STRAP ASSEMBLY, CSO SERVICE ORDER NUMBER, DATE IAW BAPS 144-005, SECTION 9.5.1.1, IDENTIFICATION OF AIRCRAFT PARTS AND ASSEMBLIES.		Not Required	
	500	Complied with: VERIFY COMPLETED ASSEMBLY(S) IAW BAS00270032 REV (B).		
	VERIFY COMPLETED ASSEMBLY(S) IAW BAS00270032 REV (____).			

Sequence #	4505-1	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4432575	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2584091

QA005 RTS Statement
The component identified above was repaired and inspected in accordance with current Federal Aviation Regulations, found airworthy and is approved for return to service with respect to the work performed

Bombardier

Sequence #	4506	Aircraft SN #	6111	MWPWO #	2498069
WO #	2515179	Aircraft Reg #	XA-SOL	Parent WO #	2498069

4506	WO #	2515179	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13276161	No Log Entry	
Interior - Complete reupholster pilot and co-pilot seats with new OEM foam (650)				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			25-10
	C/W complete reupholster of pilot and co-pilot seats with new OEM foam			
	200			25-10
	Provide support for burn coupon testing			

CHILD WORK ORDER DETAILS

	WO #	Description	Corrective Action	AMENDED
4506-1	4432593	Interior Refurb: CL600 PILOT SEAT_GOODRICH_WITH FOAM		
4506-2	4432596	Interior Refurb: CL600 COPILOT SEAT_GOODRICH_WITH FOAM		

Sequence #	4506-1	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4432593	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2515179

4506-1	**WO #**	**4432593**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		No Log Entry	
Interior Refurb: CL600 PILOT SEAT_GOODRICH_WITH FOAM				
Task / IRN # : CL600 PILOT SEAT_GOODRICH_WITH				

Bombardier

Sequence #	4506-1	Aircraft SN #	6111	MWPWO #	2498069
WO #	4432593	Aircraft Reg #	XA-SOL	Parent WO #	2515179

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			
	Comply with Preliminary Inspection			
	200			
	VERIFY MATERIAL/COMPONENTS: 1) P/N: 1406-07-SS010BF PILOT SEAT ASSEMBLY, EXISTING 2) P/N:_____LEATHER, P.O.# 3) P/N:_____SHEEPSKIN, P.O.# 4) P/N:_____OEM FOAM, BOTTOM CUSHION, P.O.# 5) P/N:_____OEM FOAM, BACKREST CUSHION, P.O.# 6) P/N: 048011-98648 EC-1357 ADHESIVE, P.O.# 7) P/N: RE-WEBBED PILOT SEAT BELT, P.O.#			
	300			
	STRIP SEAT MATERIALS IAW GOODRICH CMM 25-14-11, DISCARD OLD SEAT CUSHIONS.		Not Required	
	400			
	REMOVE SEAT BELTS IAW GOODRICH CMM 25-14-11.		Not Required	
	500			
	VERIFY SUBSTRATE INTEGRITY IAW AC 43.13-1B PAR 5-18.			
	600			
	INSTALL NEW SEAT CUSHIONS IAW GOODRICH CMM 25-14-11.		Not Required	

Bombardier

Sequence #	4506-1	Aircraft SN #	6111	MWPWO #	2498069
WO #	4432593	Aircraft Reg #	XA-SOL	Parent WO #	2515179

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	700			
	FABRICATE AND INSTALL NEW SHEEPSKIN SEAT COVER IAW GOODRICH CMM 25-14-11.		Not Required	
	800			
	REINSTALL RE-WEBBED SEAT BELTS IAW GOODRICH CMM 25-14-11.		Not Required	
	900			
	REASSEMBLE PILOT SEAT ASSEMBLY IAW GOODRICH CMM 25-14-11.		Not Required	
	1000			
	VERIFY COMPLETED ASSEMBLY(S) IAW GOODRICH CMM 25-14-11 REV (____).			

QA005 RTS Statement

The component identified above was repaired and inspected in accordance with current Federal Aviation Regulations, found airworthy and is approved for return to service with respect to the work performed

Sequence #	4506-2	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4432596	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2515179

4506-2	**WO #**	**4432596**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		No Log Entry	
Interior Refurb: CL600 COPILOT SEAT_GOODRICH_WITH FOAM				
Task / IRN # : CL600 COPILOT SEAT_GOODRICH_WI				

Bombardier

Sequence #	4506-2	Aircraft SN #	6111	MWPWO #	2498069
WO #	4432596	Aircraft Reg #	XA-SOL	Parent WO #	2515179

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			
	Comply with Preliminary Inspection			
	200			
	VERIFY MATERIAL/COMPONENTS: 1) P/N: 1406-08-SS010BF CO-PILOT SEAT ASSEMBLY, EXISTING 2) P/N:_____LEATHER, P.O.# 3) P/N:_____SHEEPSKIN, P.O.# 4) P/N:_____OEM FOAM, BOTTOM CUSHION, P.O.# 5) P/N:_____OEM FOAM, BACKREST CUSHION, P.O.# 6) P/N: 048011-98648 EC-1357 ADHESIVE, P.O.# 7) P/N: RE-WEBBED PILOT SEAT BELT, P.O.#			
	300			
	STRIP SEAT MATERIALS IAW GOODRICH CMM 25-14-11, DISCARD OLD SEAT CUSHIONS.		Not Required	
	400			
	REMOVE SEAT BELTS IAW GOODRICH CMM 25-14-11.		Not Required	
	500			
	VERIFY SUBSTRATE INTEGRITY IAW AC 43.13-1B PAR 5-18.			
	600			
	INSTALL NEW SEAT CUSHIONS IAW GOODRICH CMM 25-14-11.		Not Required	

Bombardier

Sequence #	4506-2	Aircraft SN #	6111	MWPWO #	2498069
WO #	4432596	Aircraft Reg #	XA-SOL	Parent WO #	2515179

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	700			
	FABRICATE AND INSTALL NEW SHEEPSKIN SEAT COVER IAW GOODRICH CMM 25-14-11.		Not Required	
	800			
	REINSTALL RE-WEBBED SEAT BELTS IAW GOODRICH CMM 25-14-11.		Not Required	
	900			
	REASSEMBLE PILOT SEAT ASSEMBLY IAW GOODRICH CMM 25-14-11.		Not Required	
	1000			
	VERIFY COMPLETED ASSEMBLY(S) IAW GOODRICH CMM 25-14-11 REV (____).			

QA005 RTS Statement

The component identified above was repaired and inspected in accordance with current Federal Aviation Regulations, found airworthy and is approved for return to service with respect to the work performed

Sequence #	4507	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	2508442	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

4507	**WO #**	**2508442**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #	13276326	No Log Entry	
Interior - Complete reupholster pilot and co-pilot seats without foam seat build ups				

Bombardier

Sequence #	4508	Aircraft SN #	6111	MWPWO #	2498069
WO #	2508439	Aircraft Reg #	XA-SOL	Parent WO #	2498069

4508	WO #	2508439	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13276325	No Log Entry	
Interior - Refinish all cabinetry throughout aircraft (604/605/650)				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			25-20
	Perform Refinishing of all cabinetry throughout aircraft (604/605/650)			
	200			25-20
	Record work accomplished			
	300			
	C/W Interior fit and FT			
	400			
	graphic arts / placard replace			

Sequence #	4508	Aircraft SN #	6111	MWPWO #	2498069
WO #	2508439	Aircraft Reg #	XA-SOL	Parent WO #	2498069

CHILD WORK ORDER DETAILS

	WO #	Description	Corrective Action	AMENDED
4508-1	4662958	Interior: STRIP-FINISH (GLOSS)		
4508-2	4662964	Interior: STRIP-FINISH (GLOSS)	7040/4508-REFINISHED 1EA C4418APN-101 GALLEY ANNEX IAW BAS00270032 REV (B) SECTION 3.15. REFERENCE OPERATIONS 100-140 FOR WORK ACCOMPLISHED	
4508-3	4662977	Interior: STRIP-FINISH (GLOSS)		
4508-4	4662984	Interior: STRIP-FINISH (GLOSS)		
4508-5	4663008	Interior: STRIP-FINISH (GLOSS)		
4508-6	4663019	Interior: STRIP-FINISH (GLOSS)		
4508-7	4663023	Interior: STRIP-FINISH (GLOSS)		
4508-8	4663028	Interior: STRIP-FINISH (GLOSS)		
4508-9	4663036	Interior: STRIP-FINISH (GLOSS)		
4508-10	4663039	Interior: STRIP-FINISH (GLOSS)		
4508-11	4663046	Interior: STRIP-FINISH (GLOSS)		
4508-12	4663051	Interior: STRIP-FINISH (GLOSS)		
4508-13	4663053	Interior: STRIP-FINISH (GLOSS)		
4508-14	4663055	Interior: STRIP-FINISH (GLOSS)		
4508-15	4663057	Interior: STRIP-FINISH (GLOSS)		
4508-16	4663061	Interior: STRIP-FINISH (GLOSS)		
4508-17	4663070	Interior: STRIP-FINISH (GLOSS)		
4508-18	4663085	Interior: STRIP-FINISH (GLOSS)		
4508-19	4663093	Interior: STRIP-FINISH (GLOSS)		
4508-20	4663096	Interior: STRIP-FINISH (GLOSS)		
4508-21	4663101	Interior: STRIP-FINISH (GLOSS)		

Sequence #	4508	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	2508439	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

CHILD WORK ORDER DETAILS

	WO #	Description	Corrective Action	AMENDED
4508-22	4663109	Interior: STRIP-FINISH (GLOSS)		
4508-23	4663113	Interior: STRIP-FINISH (GLOSS)		
4508-24	4663125	Interior: STRIP-FINISH (GLOSS)		
4508-25	4663126	Interior: STRIP-FINISH (GLOSS)		
4508-26	4665056	Interior Refurb: FAB - INT PLACARD KIT BY DWG NUM - JJ		

Sequence #	4508-1	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4662958	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2508439

4508-1	**WO #**	**4662958**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		No Log Entry	
Interior: STRIP-FINISH (GLOSS)				
Task / IRN # : STRIP-FINISH (GLOSS)				

Bombardier

Sequence #	4508-1	Aircraft SN #	6111	MWPWO #	2498069
WO #	4662958	Aircraft Reg #	XA-SOL	Parent WO #	2508439

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			
	Comply with Preliminary Inspection			
	200			
	VERIFY MATERIAL/COMPONENT: 1) P/N: C3818APN-101 LHF FWD WARDROBE (EXISTING) 2) P/N: N381-7488 PST-917 FLEXIBLE POLYESTER TOPCOAT, P.O.# 3) P/N: N381-7490 XP-N-C91 HI GLOSS ACRYLIC LINEAR POLY TOPCOAT, P.O.#			
	300			
	STRIP AND PREPARE SURFACE IAW TES-1103, SECTION 7.0.1, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	400			
	VERIFY SUBSTRATE IAW AC 43.13-1B PAR 5-18.		Not Required	
	500			
	APPLY SEALING COATS IAW TES-1103, SECTION 7.0.2, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	600			
	APPLY INTERMEDIATE COATS IAW TES-1103, SECTION 7.0.3, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	700			
	SAND SURFACE IAW TES-1103, SECTION 7.0.3.1, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	

Bombardier

Sequence #	4508-1	Aircraft SN #	6111	MWPWO #	2498069
WO #	4662958	Aircraft Reg #	XA-SOL	Parent WO #	2508439

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	800			
	POSI TEST: MIL THICKNESS:			
	900			
	APPLY FINISH COAT IAW TES-1103, SECTION 7.0.4, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	1000			
	SAND SURFACE IAW TES-1103, SECTION 7.0.5, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	1100			
	BUFF FINISH IAW TES-1103, SECTION 7.0.6, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	1200			
	POSI TEST: MIL THICKNESS:			
	1300			
	INSPECT FOR ANY VISIBLE FINISH IMPERFECTIONS OR DAMAGE. NO DISCREPANCIES NOTED.		Not Required	
	1400			
	VERIFY COMPLETED ASSEMBLY IAW BAS00270032 REV (____) SECTION 3.15.			

QA005 RTS Statement

The component identified above was repaired and inspected in accordance with current Federal Aviation Regulations, found airworthy and is approved for return to service with respect to the work performed

Sequence #	4508-2	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4662964	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2508439

4508-2	**WO #**	**4662964**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		No Log Entry	
Interior: STRIP-FINISH (GLOSS)				
Task / IRN # : STRIP-FINISH (GLOSS)				

Sequence #	4508-2	Aircraft SN #	6111	MWPWO #	2498069
WO #	4662964	Aircraft Reg #	XA-SOL	Parent WO #	2508439

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with: Comply with Preliminary Inspection	B0140833 - Salvador Jury Mar 05, 2026 06:06 PM	
	Comply with Preliminary Inspection			
	200	Complied with: VERIFY MATERIAL/COMPONENT: 1) P/N: C4418APN-101 GALLEY ANNEX (EXISTING) 2) P/N: N381-7488 PST-917 FLEXIBLE POLYESTER TOPCOAT, P.O.# 3) P/N: N381-7490 XP-N-C91 HI GLOSS ACRYLIC LINEAR POLY TOPCOAT, P.O.#	B0140833 - Salvador Jury Mar 05, 2026 06:06 PM	
	VERIFY MATERIAL/COMPONENT: 1) P/N: C4418APN-101 GALLEY ANNEX (EXISTING) 2) P/N: N381-7488 PST-917 FLEXIBLE POLYESTER TOPCOAT, P.O.# 3) P/N: N381-7490 XP-N-C91 HI GLOSS ACRYLIC LINEAR POLY TOPCOAT, P.O.#			
	300	Complied with: STRIP AND PREPARE SURFACE IAW TES-1103, SECTION 7.0.1, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.	B0140833 - Salvador Jury Mar 05, 2026 06:06 PM	
	STRIP AND PREPARE SURFACE IAW TES-1103, SECTION 7.0.1, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	400	Complied with: VERIFY SUBSTRATE IAW AC 43.13-1B PAR 5-18.	B0140833 - Salvador Jury Mar 05, 2026 06:06 PM	
	VERIFY SUBSTRATE IAW AC 43.13-1B PAR 5-18.		Not Required	
	500	Complied with: APPLY SEALING COATS IAW TES-1103, SECTION 7.0.2, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.	B0140833 - Salvador Jury Mar 05, 2026 06:06 PM	
	APPLY SEALING COATS IAW TES-1103, SECTION 7.0.2, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	600	Complied with: APPLY INTERMEDIATE COATS IAW TES-1103, SECTION 7.0.3, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.	B0140833 - Salvador Jury Mar 05, 2026 06:06 PM	
	APPLY INTERMEDIATE COATS IAW TES-1103, SECTION 7.0.3, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	

Sequence #	4508-2	Aircraft SN #	6111	MWPWO #	2498069
WO #	4662964	Aircraft Reg #	XA-SOL	Parent WO #	2508439

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	700 SAND SURFACE IAW TES-1103, SECTION 7.0.3.1, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.	Complied with: SAND SURFACE IAW TES-1103, SECTION 7.0.3.1, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.	Not Required	
	800 POSI TEST: MIL THICKNESS:	POSI TEST: MIL THICKNESS: 25.1 TOOL#: TUSS4466A CAL DUE: FEB 28 2027		
	900 APPLY FINISH COAT IAW TES-1103, SECTION 7.0.4, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.	Complied with: APPLY FINISH COAT IAW TES-1103, SECTION 7.0.4, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.	Not Required	
	1000 SAND SURFACE IAW TES-1103, SECTION 7.0.5, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.	Complied with: SAND SURFACE IAW TES-1103, SECTION 7.0.5, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.	Not Required	
	1100 BUFF FINISH IAW TES-1103, SECTION 7.0.6, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.	Complied with: BUFF FINISH IAW TES-1103, SECTION 7.0.6, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.	Not Required	
	1200 POSI TEST: MIL THICKNESS:	POSI TEST: MIL THICKNESS: 26.2 TOOL#: TUSS4466A CAL DUE: FEB 28 2027		
	1300 INSPECT FOR ANY VISIBLE FINISH IMPERFECTIONS OR DAMAGE. NO DISCREPANCIES NOTED.	Complied with: INSPECT FOR ANY VISIBLE FINISH IMPERFECTIONS OR DAMAGE. NO DISCREPANCIES NOTED.	Not Required	
	1400 VERIFY COMPLETED ASSEMBLY IAW BAS00270032 REV (____) SECTION 3.15.	VERIFIED COMPLETED ASSEMBLY IAW BAS00270032 REV (B) SECTION 3.15.		

Sequence #	4508-2	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4662964	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2508439

TOOL INFORMATION

Tool ID	Tool Description	Calibration Due Date
TUSS4466A	MIL THICKNESS GAUGE	Feb 27, 2027 5:00 PM

QA005 RTS Statement

The component identified above was repaired and inspected in accordance with current Federal Aviation Regulations, found airworthy and is approved for return to service with respect to the work performed

Sequence #	4508-3	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4662977	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2508439

4508-3	**WO #**	**4662977**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		No Log Entry	
Interior: STRIP-FINISH (GLOSS)				
Task / IRN # : STRIP-FINISH (GLOSS)				

Sequence #	4508-3	Aircraft SN #	6111	MWPWO #	2498069
WO #	4662977	Aircraft Reg #	XA-SOL	Parent WO #	2508439

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			
	Comply with Preliminary Inspection			
	200			
	VERIFY MATERIAL/COMPONENT: 1) P/N: C4418APN-101UG UPPER GALLEY (EXISTING) 2) P/N: N381-7488 PST-917 FLEXIBLE POLYESTER TOPCOAT, P.O.# 3) P/N: N381-7490 XP-N-C91 HI GLOSS ACRYLIC LINEAR POLY TOPCOAT, P.O.#			
	300			
	STRIP AND PREPARE SURFACE IAW TES-1103, SECTION 7.0.1, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	400			
	VERIFY SUBSTRATE IAW AC 43.13-1B PAR 5-18.		Not Required	
	500			
	APPLY SEALING COATS IAW TES-1103, SECTION 7.0.2, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	600			
	APPLY INTERMEDIATE COATS IAW TES-1103, SECTION 7.0.3, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	700			
	SAND SURFACE IAW TES-1103, SECTION 7.0.3.1, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	

Bombardier

Sequence #	4508-3	Aircraft SN #	6111	MWPWO #	2498069
WO #	4662977	Aircraft Reg #	XA-SOL	Parent WO #	2508439

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	800			
	POSI TEST: MIL THICKNESS:			
	900			
	APPLY FINISH COAT IAW TES-1103, SECTION 7.0.4, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	1000			
	SAND SURFACE IAW TES-1103, SECTION 7.0.5, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	1100			
	BUFF FINISH IAW TES-1103, SECTION 7.0.6, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	1200			
	POSI TEST: MIL THICKNESS:			
	1300			
	INSPECT FOR ANY VISIBLE FINISH IMPERFECTIONS OR DAMAGE. NO DISCREPANCIES NOTED.		Not Required	
	1400			
	VERIFY COMPLETED ASSEMBLY IAW BAS00270032 REV (____) SECTION 3.15.			

QA005 RTS Statement

The component identified above was repaired and inspected in accordance with current Federal Aviation Regulations, found airworthy and is approved for return to service with respect to the work performed

Sequence #	4508-4	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4662984	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2508439

4508-4	**WO #**	**4662984**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		No Log Entry	
Interior: STRIP-FINISH (GLOSS)				
Task / IRN # : STRIP-FINISH (GLOSS)				

Bombardier

Sequence #	4508-4	Aircraft SN #	6111	MWPWO #	2498069
WO #	4662984	Aircraft Reg #	XA-SOL	Parent WO #	2508439

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			
	Comply with Preliminary Inspection			
	200			
	VERIFY MATERIAL/COMPONENT: 1) P/N: C4418APN-101LG LOWER GALLEY EXISTING 2) P/N: N381-7488 PST-917 FLEXIBLE POLYESTER TOPCOAT, P.O.# 3) P/N: N381-7490 XP-N-C91 HI GLOSS ACRYLIC LINEAR POLY TOPCOAT, P.O.#			
	300			
	STRIP AND PREPARE SURFACE IAW TES-1103, SECTION 7.0.1, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	400			
	VERIFY SUBSTRATE IAW AC 43.13-1B PAR 5-18.		Not Required	
	500			
	APPLY SEALING COATS IAW TES-1103, SECTION 7.0.2, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	600			
	APPLY INTERMEDIATE COATS IAW TES-1103, SECTION 7.0.3, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	700			
	SAND SURFACE IAW TES-1103, SECTION 7.0.3.1, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	

Sequence #	4508-4	Aircraft SN #	6111	MWPWO #	2498069
WO #	4662984	Aircraft Reg #	XA-SOL	Parent WO #	2508439

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	800			
	POSI TEST: MIL THICKNESS:			
	900			
	APPLY FINISH COAT IAW TES-1103, SECTION 7.0.4, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	1000			
	SAND SURFACE IAW TES-1103, SECTION 7.0.5, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	1100			
	BUFF FINISH IAW TES-1103, SECTION 7.0.6, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	1200			
	POSI TEST: MIL THICKNESS:			
	1300			
	INSPECT FOR ANY VISIBLE FINISH IMPERFECTIONS OR DAMAGE. NO DISCREPANCIES NOTED.		Not Required	
	1400			
	VERIFY COMPLETED ASSEMBLY IAW BAS00270032 REV (____) SECTION 3.15.			

QA005 RTS Statement

The component identified above was repaired and inspected in accordance with current Federal Aviation Regulations, found airworthy and is approved for return to service with respect to the work performed

Sequence #	4508-5	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4663008	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2508439

4508-5	**WO #**	**4663008**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		No Log Entry	
Interior: STRIP-FINISH (GLOSS)				
Task / IRN # : STRIP-FINISH (GLOSS)				

Sequence #	4508-5	Aircraft SN #	6111	MWPWO #	2498069
WO #	4663008	Aircraft Reg #	XA-SOL	Parent WO #	2508439

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			
	Comply with Preliminary Inspection			
	200			
	VERIFY MATERIAL/COMPONENT: 1) P/N: C4518APN-101 BULKHEAD ASSY - FS350.25 LH (EXISTING) 2) P/N: N381-7488 PST-917 FLEXIBLE POLYESTER TOPCOAT, P.O.# 3) P/N: N381-7490 XP-N-C91 HI GLOSS ACRYLIC LINEAR POLY TOPCOAT, P.O.#			
	300			
	STRIP AND PREPARE SURFACE IAW TES-1103, SECTION 7.0.1, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	400			
	VERIFY SUBSTRATE IAW AC 43.13-1B PAR 5-18.		Not Required	
	500			
	APPLY SEALING COATS IAW TES-1103, SECTION 7.0.2, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	600			
	APPLY INTERMEDIATE COATS IAW TES-1103, SECTION 7.0.3, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	700			
	SAND SURFACE IAW TES-1103, SECTION 7.0.3.1, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	

Bombardier

Sequence #	4508-5	Aircraft SN #	6111	MWPWO #	2498069
WO #	4663008	Aircraft Reg #	XA-SOL	Parent WO #	2508439

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	800			
	POSI TEST: MIL THICKNESS:			
	900			
	APPLY FINISH COAT IAW TES-1103, SECTION 7.0.4, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	1000			
	SAND SURFACE IAW TES-1103, SECTION 7.0.5, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	1100			
	BUFF FINISH IAW TES-1103, SECTION 7.0.6, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	1200			
	POSI TEST: MIL THICKNESS:			
	1300			
	INSPECT FOR ANY VISIBLE FINISH IMPERFECTIONS OR DAMAGE. NO DISCREPANCIES NOTED.		Not Required	
	1400			
	VERIFY COMPLETED ASSEMBLY IAW BAS00270032 REV (____) SECTION 3.15.			

QA005 RTS Statement

The component identified above was repaired and inspected in accordance with current Federal Aviation Regulations, found airworthy and is approved for return to service with respect to the work performed

Sequence #	4508-6	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4663019	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2508439

4508-6	**WO #**	**4663019**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		No Log Entry	
Interior: STRIP-FINISH (GLOSS)				
Task / IRN # : STRIP-FINISH (GLOSS)				

Sequence #	4508-6	Aircraft SN #	6111	MWPWO #	2498069
WO #	4663019	Aircraft Reg #	XA-SOL	Parent WO #	2508439

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			
	Comply with Preliminary Inspection			
	200			
	VERIFY MATERIAL/COMPONENT: 1) P/N: C4518APN-103 BULKHEAD ASSY - FS350.25 RH (EXISTING) 2) P/N: N381-7488 PST-917 FLEXIBLE POLYESTER TOPCOAT, P.O.# 3) P/N: N381-7490 XP-N-C91 HI GLOSS ACRYLIC LINEAR POLY TOPCOAT, P.O.#			
	300			
	STRIP AND PREPARE SURFACE IAW TES-1103, SECTION 7.0.1, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	400			
	VERIFY SUBSTRATE IAW AC 43.13-1B PAR 5-18.		Not Required	
	500			
	APPLY SEALING COATS IAW TES-1103, SECTION 7.0.2, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	600			
	APPLY INTERMEDIATE COATS IAW TES-1103, SECTION 7.0.3, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	700			
	SAND SURFACE IAW TES-1103, SECTION 7.0.3.1, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	

Bombardier

Sequence #	4508-6	Aircraft SN #	6111	MWPWO #	2498069
WO #	4663019	Aircraft Reg #	XA-SOL	Parent WO #	2508439

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	800			
	POSI TEST: MIL THICKNESS:			
	900			
	APPLY FINISH COAT IAW TES-1103, SECTION 7.0.4, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	1000			
	SAND SURFACE IAW TES-1103, SECTION 7.0.5, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	1100			
	BUFF FINISH IAW TES-1103, SECTION 7.0.6, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	1200			
	POSI TEST: MIL THICKNESS:			
	1300			
	INSPECT FOR ANY VISIBLE FINISH IMPERFECTIONS OR DAMAGE. NO DISCREPANCIES NOTED.		Not Required	
	1400			
	VERIFY COMPLETED ASSEMBLY IAW BAS00270032 REV (____) SECTION 3.15.			

QA005 RTS Statement

The component identified above was repaired and inspected in accordance with current Federal Aviation Regulations, found airworthy and is approved for return to service with respect to the work performed

Sequence #	4508-7	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4663023	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2508439

4508-7	**WO #**	**4663023**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		No Log Entry	
Interior: STRIP-FINISH (GLOSS)				
Task / IRN # : STRIP-FINISH (GLOSS)				

Sequence #	4508-7	Aircraft SN #	6111	MWPWO #	2498069
WO #	4663023	Aircraft Reg #	XA-SOL	Parent WO #	2508439

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			
	Comply with Preliminary Inspection			
	200			
	VERIFY MATERIAL/COMPONENT: 1) P/N: 3519-249-3-1051 349 DOOR (EXISTING) 2) P/N: N381-7488 PST-917 FLEXIBLE POLYESTER TOPCOAT, P.O.# 3) P/N: N381-7490 XP-N-C91 HI GLOSS ACRYLIC LINEAR POLY TOPCOAT, P.O.#			
	300			
	STRIP AND PREPARE SURFACE IAW TES-1103, SECTION 7.0.1, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	400			
	VERIFY SUBSTRATE IAW AC 43.13-1B PAR 5-18.		Not Required	
	500			
	APPLY SEALING COATS IAW TES-1103, SECTION 7.0.2, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	600			
	APPLY INTERMEDIATE COATS IAW TES-1103, SECTION 7.0.3, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	700			
	SAND SURFACE IAW TES-1103, SECTION 7.0.3.1, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	

Bombardier

Sequence #	4508-7	Aircraft SN #	6111	MWPWO #	2498069
WO #	4663023	Aircraft Reg #	XA-SOL	Parent WO #	2508439

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	800			
	POSI TEST: MIL THICKNESS:			
	900			
	APPLY FINISH COAT IAW TES-1103, SECTION 7.0.4, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	1000			
	SAND SURFACE IAW TES-1103, SECTION 7.0.5, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	1100			
	BUFF FINISH IAW TES-1103, SECTION 7.0.6, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	1200			
	POSI TEST: MIL THICKNESS:			
	1300			
	INSPECT FOR ANY VISIBLE FINISH IMPERFECTIONS OR DAMAGE. NO DISCREPANCIES NOTED.		Not Required	
	1400			
	VERIFY COMPLETED ASSEMBLY IAW BAS00270032 REV (____) SECTION 3.15.			

QA005 RTS Statement

The component identified above was repaired and inspected in accordance with current Federal Aviation Regulations, found airworthy and is approved for return to service with respect to the work performed

Sequence #	4508-8	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4663028	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2508439

4508-8	**WO #**	**4663028**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		No Log Entry	
Interior: STRIP-FINISH (GLOSS)				
Task / IRN # : STRIP-FINISH (GLOSS)				

Sequence #	4508-8	Aircraft SN #	6111	MWPWO #	2498069
WO #	4663028	Aircraft Reg #	XA-SOL	Parent WO #	2508439

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			
	Comply with Preliminary Inspection			
	200			
	VERIFY MATERIAL/COMPONENT: 1) P/N: C3918APN-101 BULKHEAD ASSY - FS560.29LH (EXISTING) 2) P/N: N381-7488 PST-917 FLEXIBLE POLYESTER TOPCOAT, P.O.# 3) P/N: N381-7490 XP-N-C91 HI GLOSS ACRYLIC LINEAR POLY TOPCOAT, P.O.#			
	300			
	STRIP AND PREPARE SURFACE IAW TES-1103, SECTION 7.0.1, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	400			
	VERIFY SUBSTRATE IAW AC 43.13-1B PAR 5-18.		Not Required	
	500			
	APPLY SEALING COATS IAW TES-1103, SECTION 7.0.2, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	600			
	APPLY INTERMEDIATE COATS IAW TES-1103, SECTION 7.0.3, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	700			
	SAND SURFACE IAW TES-1103, SECTION 7.0.3.1, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	

Bombardier

Sequence #	4508-8	Aircraft SN #	6111	MWPWO #	2498069
WO #	4663028	Aircraft Reg #	XA-SOL	Parent WO #	2508439

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	800			
	POSI TEST: MIL THICKNESS:			
	900			
	APPLY FINISH COAT IAW TES-1103, SECTION 7.0.4, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	1000			
	SAND SURFACE IAW TES-1103, SECTION 7.0.5, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	1100			
	BUFF FINISH IAW TES-1103, SECTION 7.0.6, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	1200			
	POSI TEST: MIL THICKNESS:			
	1300			
	INSPECT FOR ANY VISIBLE FINISH IMPERFECTIONS OR DAMAGE. NO DISCREPANCIES NOTED.		Not Required	
	1400			
	VERIFY COMPLETED ASSEMBLY IAW BAS00270032 REV (____) SECTION 3.15.			

QA005 RTS Statement

The component identified above was repaired and inspected in accordance with current Federal Aviation Regulations, found airworthy and is approved for return to service with respect to the work performed

Sequence #	4508-9	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4663036	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2508439

4508-9	**WO #**	**4663036**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		No Log Entry	
Interior: STRIP-FINISH (GLOSS)				
Task / IRN # : STRIP-FINISH (GLOSS)				

Sequence #	4508-9	Aircraft SN #	6111	MWPWO #	2498069
WO #	4663036	Aircraft Reg #	XA-SOL	Parent WO #	2508439

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			
	Comply with Preliminary Inspection			
	200			
	VERIFY MATERIAL/COMPONENT: 1) P/N: C3918APN-103 BULKHEAD ASSY - FS560.29RH (EXISTING) 2) P/N: N381-7488 PST-917 FLEXIBLE POLYESTER TOPCOAT, P.O.# 3) P/N: N381-7490 XP-N-C91 HI GLOSS ACRYLIC LINEAR POLY TOPCOAT, P.O.#			
	300			
	STRIP AND PREPARE SURFACE IAW TES-1103, SECTION 7.0.1, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	400			
	VERIFY SUBSTRATE IAW AC 43.13-1B PAR 5-18.		Not Required	
	500			
	APPLY SEALING COATS IAW TES-1103, SECTION 7.0.2, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	600			
	APPLY INTERMEDIATE COATS IAW TES-1103, SECTION 7.0.3, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	700			
	SAND SURFACE IAW TES-1103, SECTION 7.0.3.1, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	

Bombardier

Sequence #	4508-9	Aircraft SN #	6111	MWPWO #	2498069
WO #	4663036	Aircraft Reg #	XA-SOL	Parent WO #	2508439

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	800			
	POSI TEST: MIL THICKNESS:			
	900			
	APPLY FINISH COAT IAW TES-1103, SECTION 7.0.4, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	1000			
	SAND SURFACE IAW TES-1103, SECTION 7.0.5, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	1100			
	BUFF FINISH IAW TES-1103, SECTION 7.0.6, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	1200			
	POSI TEST: MIL THICKNESS:			
	1300			
	INSPECT FOR ANY VISIBLE FINISH IMPERFECTIONS OR DAMAGE. NO DISCREPANCIES NOTED.		Not Required	
	1400			
	VERIFY COMPLETED ASSEMBLY IAW BAS00270032 REV (____) SECTION 3.15.			

QA005 RTS Statement

The component identified above was repaired and inspected in accordance with current Federal Aviation Regulations, found airworthy and is approved for return to service with respect to the work performed

Sequence #	4508-10	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4663039	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2508439

4508-10	**WO #**	**4663039**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		No Log Entry	
Interior: STRIP-FINISH (GLOSS)				
Task / IRN # : STRIP-FINISH (GLOSS)				

Sequence #	4508-10	Aircraft SN #	6111	MWPWO #	2498069
WO #	4663039	Aircraft Reg #	XA-SOL	Parent WO #	2508439

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			
	Comply with Preliminary Inspection			
	200			
	VERIFY MATERIAL/COMPONENT: 1) P/N: C392113-501 FS 560 DOOR (EXISTING) 2) P/N: N381-7488 PST-917 FLEXIBLE POLYESTER TOPCOAT, P.O.# 3) P/N: N381-7490 XP-N-C91 HI GLOSS ACRYLIC LINEAR POLY TOPCOAT, P.O.#			
	300			
	STRIP AND PREPARE SURFACE IAW TES-1103, SECTION 7.0.1, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	400			
	VERIFY SUBSTRATE IAW AC 43.13-1B PAR 5-18.		Not Required	
	500			
	APPLY SEALING COATS IAW TES-1103, SECTION 7.0.2, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	600			
	APPLY INTERMEDIATE COATS IAW TES-1103, SECTION 7.0.3, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	700			
	SAND SURFACE IAW TES-1103, SECTION 7.0.3.1, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	

Bombardier

Sequence #	4508-10	Aircraft SN #	6111	MWPWO #	2498069
WO #	4663039	Aircraft Reg #	XA-SOL	Parent WO #	2508439

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	800			
	POSI TEST: MIL THICKNESS:			
	900			
	APPLY FINISH COAT IAW TES-1103, SECTION 7.0.4, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	1000			
	SAND SURFACE IAW TES-1103, SECTION 7.0.5, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	1100			
	BUFF FINISH IAW TES-1103, SECTION 7.0.6, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	1200			
	POSI TEST: MIL THICKNESS:			
	1300			
	INSPECT FOR ANY VISIBLE FINISH IMPERFECTIONS OR DAMAGE. NO DISCREPANCIES NOTED.		Not Required	
	1400			
	VERIFY COMPLETED ASSEMBLY IAW BAS00270032 REV (____) SECTION 3.15.			

QA005 RTS Statement

The component identified above was repaired and inspected in accordance with current Federal Aviation Regulations, found airworthy and is approved for return to service with respect to the work performed

Sequence #	4508-11	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4663046	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2508439

4508-11	**WO #**	**4663046**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		No Log Entry	
Interior: STRIP-FINISH (GLOSS)				
Task / IRN # : STRIP-FINISH (GLOSS)				

Bombardier

Sequence #	4508-11	Aircraft SN #	6111	MWPWO #	2498069
WO #	4663046	Aircraft Reg #	XA-SOL	Parent WO #	2508439

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with Preliminary Inspection		
	Comply with Preliminary Inspection			
	200	VERIFIED MATERIAL/COMPONENT: 1) P/N: C9118APN-103 BULKHEAD ASSY - FS587RH (EXISTING) 2) P/N: N381-7488 PST-917 FLEXIBLE POLYESTER TOPCOAT, P.O.#5002410208 3) P/N: N381-7490 XP-N-C91 HI GLOSS ACRYLIC LINEAR POLY TOPCOAT, P.O.#5002410208		
	VERIFY MATERIAL/COMPONENT: 1) P/N: C9118APN-103 BULKHEAD ASSY - FS587RH (EXISTING) 2) P/N: N381-7488 PST-917 FLEXIBLE POLYESTER TOPCOAT, P.O.# 3) P/N: N381-7490 XP-N-C91 HI GLOSS ACRYLIC LINEAR POLY TOPCOAT, P.O.#			
	300	STRIPPED AND PREPARED SURFACE IAW TES-1103, SECTION 7.0.1, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		
	STRIP AND PREPARE SURFACE IAW TES-1103, SECTION 7.0.1, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	400	VERIFIED SUBSTRATE IAW AC 43.13-1B PAR 5-18.		
	VERIFY SUBSTRATE IAW AC 43.13-1B PAR 5-18.		Not Required	
	500	APPLY SEALING COATS IAW TES-1103, SECTION 7.0.2, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		
	APPLY SEALING COATS IAW TES-1103, SECTION 7.0.2, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	600			
	APPLY INTERMEDIATE COATS IAW TES-1103, SECTION 7.0.3, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	700			
	SAND SURFACE IAW TES-1103, SECTION 7.0.3.1, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	

Bombardier

Sequence #	4508-11	Aircraft SN #	6111	MWPWO #	2498069
WO #	4663046	Aircraft Reg #	XA-SOL	Parent WO #	2508439

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	800			
	POSI TEST: MIL THICKNESS:			
	900			
	APPLY FINISH COAT IAW TES-1103, SECTION 7.0.4, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	1000			
	SAND SURFACE IAW TES-1103, SECTION 7.0.5, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	1100			
	BUFF FINISH IAW TES-1103, SECTION 7.0.6, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	1200			
	POSI TEST: MIL THICKNESS:			
	1300			
	INSPECT FOR ANY VISIBLE FINISH IMPERFECTIONS OR DAMAGE. NO DISCREPANCIES NOTED.		Not Required	
	1400			
	VERIFY COMPLETED ASSEMBLY IAW BAS00270032 REV (____) SECTION 3.15.			

QA005 RTS Statement

The component identified above was repaired and inspected in accordance with current Federal Aviation Regulations, found airworthy and is approved for return to service with respect to the work performed

Sequence #	4508-12	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4663051	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2508439

4508-12	**WO #**	**4663051**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		No Log Entry	
Interior: STRIP-FINISH (GLOSS)				
Task / IRN # : STRIP-FINISH (GLOSS)				

Bombardier

Sequence #	4508-12	Aircraft SN #	6111	MWPWO #	2498069
WO #	4663051	Aircraft Reg #	XA-SOL	Parent WO #	2508439

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with Preliminary Inspection		
	Comply with Preliminary Inspection			
	200	VERIFIED MATERIAL/COMPONENT: 1) P/N: C9118APN-101 BULKHEAD ASSY - FS587LH (EXISTING) 2) P/N: N381-7488 PST-917 FLEXIBLE POLYESTER TOPCOAT, P.O.# 5002410208 3) P/N: N381-7490 XP-N-C91 HI GLOSS ACRYLIC LINEAR POLY TOPCOAT, P.O.#5002410208		
	VERIFY MATERIAL/COMPONENT: 1) P/N: C9118APN-101 BULKHEAD ASSY - FS587LH (EXISTING) 2) P/N: N381-7488 PST-917 FLEXIBLE POLYESTER TOPCOAT, P.O.# 3) P/N: N381-7490 XP-N-C91 HI GLOSS ACRYLIC LINEAR POLY TOPCOAT, P.O.#			
	300	STRIPPED AND PREPARED SURFACE IAW TES-1103, SECTION 7.0.1, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		
	STRIP AND PREPARE SURFACE IAW TES-1103, SECTION 7.0.1, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	400	VERIFIED SUBSTRATE IAW AC 43.13-1B PAR 5-18.		
	VERIFY SUBSTRATE IAW AC 43.13-1B PAR 5-18.		Not Required	
	500	APPLIED SEALING COATS IAW TES-1103, SECTION 7.0.2, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		
	APPLY SEALING COATS IAW TES-1103, SECTION 7.0.2, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	600			
	APPLY INTERMEDIATE COATS IAW TES-1103, SECTION 7.0.3, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	700			
	SAND SURFACE IAW TES-1103, SECTION 7.0.3.1, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	

Bombardier

Sequence #	4508-12	Aircraft SN #	6111	MWPWO #	2498069
WO #	4663051	Aircraft Reg #	XA-SOL	Parent WO #	2508439

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	800			
	POSI TEST: MIL THICKNESS:			
	900			
	APPLY FINISH COAT IAW TES-1103, SECTION 7.0.4, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	1000			
	SAND SURFACE IAW TES-1103, SECTION 7.0.5, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	1100			
	BUFF FINISH IAW TES-1103, SECTION 7.0.6, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	1200			
	POSI TEST: MIL THICKNESS:			
	1300			
	INSPECT FOR ANY VISIBLE FINISH IMPERFECTIONS OR DAMAGE. NO DISCREPANCIES NOTED.		Not Required	
	1400			
	VERIFY COMPLETED ASSEMBLY IAW BAS00270032 REV (____) SECTION 3.15.			

QA005 RTS Statement

The component identified above was repaired and inspected in accordance with current Federal Aviation Regulations, found airworthy and is approved for return to service with respect to the work performed

Sequence #	4508-13	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4663053	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2508439

4508-13	**WO #**	**4663053**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		No Log Entry	
Interior: STRIP-FINISH (GLOSS)				
Task / IRN # : STRIP-FINISH (GLOSS)				

Bombardier

Sequence #	4508-13	Aircraft SN #	6111	MWPWO #	2498069
WO #	4663053	Aircraft Reg #	XA-SOL	Parent WO #	2508439

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with Preliminary Inspection		
	Comply with Preliminary Inspection			
	200			
	VERIFY MATERIAL/COMPONENT: 1) P/N: C912130-505FS 587 DOOR (EXISTING) 2) P/N: N381-7488 PST-917 FLEXIBLE POLYESTER TOPCOAT, P.O.# 3) P/N: N381-7490 XP-N-C91 HI GLOSS ACRYLIC LINEAR POLY TOPCOAT, P.O.#			
	300	STRIPPED AND PREPARED SURFACE IAW TES-1103, SECTION 7.0.1, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		
	STRIP AND PREPARE SURFACE IAW TES-1103, SECTION 7.0.1, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	400	VERIFIED SUBSTRATE IAW AC 43.13-1B PAR 5-18.		
	VERIFY SUBSTRATE IAW AC 43.13-1B PAR 5-18.		Not Required	
	500			
	APPLY SEALING COATS IAW TES-1103, SECTION 7.0.2, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	600			
	APPLY INTERMEDIATE COATS IAW TES-1103, SECTION 7.0.3, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	700			
	SAND SURFACE IAW TES-1103, SECTION 7.0.3.1, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	

Bombardier

Sequence #	4508-13	Aircraft SN #	6111	MWPWO #	2498069
WO #	4663053	Aircraft Reg #	XA-SOL	Parent WO #	2508439

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	800			
	POSI TEST: MIL THICKNESS:			
	900			
	APPLY FINISH COAT IAW TES-1103, SECTION 7.0.4, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	1000			
	SAND SURFACE IAW TES-1103, SECTION 7.0.5, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	1100			
	BUFF FINISH IAW TES-1103, SECTION 7.0.6, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	1200			
	POSI TEST: MIL THICKNESS:			
	1300			
	INSPECT FOR ANY VISIBLE FINISH IMPERFECTIONS OR DAMAGE. NO DISCREPANCIES NOTED.		Not Required	
	1400			
	VERIFY COMPLETED ASSEMBLY IAW BAS00270032 REV (____) SECTION 3.15.			

QA005 RTS Statement

The component identified above was repaired and inspected in accordance with current Federal Aviation Regulations, found airworthy and is approved for return to service with respect to the work performed

Sequence #	4508-14	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4663055	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2508439

4508-14	**WO #**	**4663055**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		No Log Entry	
Interior: STRIP-FINISH (GLOSS)				
Task / IRN # : STRIP-FINISH (GLOSS)				

Bombardier

Sequence #	4508-14	Aircraft SN #	6111	MWPWO #	2498069
WO #	4663055	Aircraft Reg #	XA-SOL	Parent WO #	2508439

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			
	Comply with Preliminary Inspection			
	200			
	Verify P/N's XXXX			
	300			
	STRIP AND PREPARE SURFACE IAW TES-1103, SECTION 7.0.1, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	400			
	VERIFY SUBSTRATE IAW AC 43.13-1B PAR 5-18.		Not Required	
	500			
	APPLY SEALING COATS IAW TES-1103, SECTION 7.0.2, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	600			
	APPLY INTERMEDIATE COATS IAW TES-1103, SECTION 7.0.3, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	700			
	SAND SURFACE IAW TES-1103, SECTION 7.0.3.1, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	800			
	POSI TEST: MIL THICKNESS:			

Bombardier

Sequence #	4508-14	Aircraft SN #	6111	MWPWO #	2498069
WO #	4663055	Aircraft Reg #	XA-SOL	Parent WO #	2508439

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	900			
	APPLY FINISH COAT IAW TES-1103, SECTION 7.0.4, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	1000			
	SAND SURFACE IAW TES-1103, SECTION 7.0.5, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	1100			
	BUFF FINISH IAW TES-1103, SECTION 7.0.6, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	1200			
	POSI TEST: MIL THICKNESS:			
	1300			
	INSPECT FOR ANY VISIBLE FINISH IMPERFECTIONS OR DAMAGE. NO DISCREPANCIES NOTED.		Not Required	
	1400			
	VERIFY COMPLETED ASSEMBLY IAW BAS00270032 REV (____) SECTION 3.15.			

Sequence #	4508-15	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4663057	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2508439

4508-15	**WO #**	**4663057**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		No Log Entry	
Interior: STRIP-FINISH (GLOSS)				
Task / IRN # : STRIP-FINISH (GLOSS)				

Sequence #	4508-15	Aircraft SN #	6111	MWPWO #	2498069
WO #	4663057	Aircraft Reg #	XA-SOL	Parent WO #	2508439

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			
	Comply with Preliminary Inspection			
	200			
	VERIFY MATERIAL/COMPONENT: 1) P/N: C4318APN-111 FWD DIVAN END CABINET (EXISTING) 2) P/N: N381-7488 PST-917 FLEXIBLE POLYESTER TOPCOAT, P.O.# 3) P/N: N381-7490 XP-N-C91 HI GLOSS ACRYLIC LINEAR POLY TOPCOAT, P.O.#			
	300			
	STRIP AND PREPARE SURFACE IAW TES-1103, SECTION 7.0.1, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	400			
	VERIFY SUBSTRATE IAW AC 43.13-1B PAR 5-18.		Not Required	
	500			
	APPLY SEALING COATS IAW TES-1103, SECTION 7.0.2, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	600			
	APPLY INTERMEDIATE COATS IAW TES-1103, SECTION 7.0.3, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	700			
	SAND SURFACE IAW TES-1103, SECTION 7.0.3.1, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	

Bombardier

Sequence #	4508-15	Aircraft SN #	6111	MWPWO #	2498069
WO #	4663057	Aircraft Reg #	XA-SOL	Parent WO #	2508439

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	800			
	POSI TEST: MIL THICKNESS:			
	900			
	APPLY FINISH COAT IAW TES-1103, SECTION 7.0.4, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	1000			
	SAND SURFACE IAW TES-1103, SECTION 7.0.5, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	1100			
	BUFF FINISH IAW TES-1103, SECTION 7.0.6, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	1200			
	POSI TEST: MIL THICKNESS:			
	1300			
	INSPECT FOR ANY VISIBLE FINISH IMPERFECTIONS OR DAMAGE. NO DISCREPANCIES NOTED.		Not Required	
	1400			
	VERIFY COMPLETED ASSEMBLY IAW BAS00270032 REV (____) SECTION 3.15.			

QA005 RTS Statement

The component identified above was repaired and inspected in accordance with current Federal Aviation Regulations, found airworthy and is approved for return to service with respect to the work performed

Sequence #	4508-16	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4663061	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2508439

4508-16	**WO #**	**4663061**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		No Log Entry	
Interior: STRIP-FINISH (GLOSS)				
Task / IRN # : STRIP-FINISH (GLOSS)				

Sequence #	4508-16	Aircraft SN #	6111	MWPWO #	2498069
WO #	4663061	Aircraft Reg #	XA-SOL	Parent WO #	2508439

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			
	Comply with Preliminary Inspection			
	200			
	VERIFY MATERIAL/COMPONENT: 1) P/N: C4318APN-113 AFT DIVAN END CABINET (EXISTING) 2) P/N: N381-7488 PST-917 FLEXIBLE POLYESTER TOPCOAT, P.O.# 3) P/N: N381-7490 XP-N-C91 HI GLOSS ACRYLIC LINEAR POLY TOPCOAT, P.O.#			
	300			
	STRIP AND PREPARE SURFACE IAW TES-1103, SECTION 7.0.1, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	400			
	VERIFY SUBSTRATE IAW AC 43.13-1B PAR 5-18.		Not Required	
	500			
	APPLY SEALING COATS IAW TES-1103, SECTION 7.0.2, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	600			
	APPLY INTERMEDIATE COATS IAW TES-1103, SECTION 7.0.3, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	700			
	SAND SURFACE IAW TES-1103, SECTION 7.0.3.1, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	

Bombardier

Sequence #	4508-16	Aircraft SN #	6111	MWPWO #	2498069
WO #	4663061	Aircraft Reg #	XA-SOL	Parent WO #	2508439

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	800			
	POSI TEST: MIL THICKNESS:			
	900			
	APPLY FINISH COAT IAW TES-1103, SECTION 7.0.4, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	1000			
	SAND SURFACE IAW TES-1103, SECTION 7.0.5, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	1100			
	BUFF FINISH IAW TES-1103, SECTION 7.0.6, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	1200			
	POSI TEST: MIL THICKNESS:			
	1300			
	INSPECT FOR ANY VISIBLE FINISH IMPERFECTIONS OR DAMAGE. NO DISCREPANCIES NOTED.		Not Required	
	1400			
	VERIFY COMPLETED ASSEMBLY IAW BAS00270032 REV (____) SECTION 3.15.			

QA005 RTS Statement

The component identified above was repaired and inspected in accordance with current Federal Aviation Regulations, found airworthy and is approved for return to service with respect to the work performed

Sequence #	4508-17	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4663070	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2508439

4508-17	**WO #**	**4663070**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		No Log Entry	
Interior: STRIP-FINISH (GLOSS)				
Task / IRN # : STRIP-FINISH (GLOSS)				

Sequence #	4508-17	Aircraft SN #	6111	MWPWO #	2498069
WO #	4663070	Aircraft Reg #	XA-SOL	Parent WO #	2508439

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			
	Comply with Preliminary Inspection			
	200			
	VERIFY MATERIAL/COMPONENT: 1) P/N: C2818APN-101 PULL-OUT TABLE ASSY'S (EXISTING) 2) P/N: N381-7488 PST-917 FLEXIBLE POLYESTER TOPCOAT, P.O.# 3) P/N: N381-7490 XP-N-C91 HI GLOSS ACRYLIC LINEAR POLY TOPCOAT, P.O.#			
	300			
	STRIP AND PREPARE SURFACE IAW TES-1103, SECTION 7.0.1, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	400			
	VERIFY SUBSTRATE IAW AC 43.13-1B PAR 5-18.		Not Required	
	500			
	APPLY SEALING COATS IAW TES-1103, SECTION 7.0.2, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	600			
	APPLY INTERMEDIATE COATS IAW TES-1103, SECTION 7.0.3, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	700			
	SAND SURFACE IAW TES-1103, SECTION 7.0.3.1, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	

Bombardier

Sequence #	4508-17	Aircraft SN #	6111	MWPWO #	2498069
WO #	4663070	Aircraft Reg #	XA-SOL	Parent WO #	2508439

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	800			
	POSI TEST: MIL THICKNESS:			
	900			
	APPLY FINISH COAT IAW TES-1103, SECTION 7.0.4, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	1000			
	SAND SURFACE IAW TES-1103, SECTION 7.0.5, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	1100			
	BUFF FINISH IAW TES-1103, SECTION 7.0.6, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	1200			
	POSI TEST: MIL THICKNESS:			
	1300			
	INSPECT FOR ANY VISIBLE FINISH IMPERFECTIONS OR DAMAGE. NO DISCREPANCIES NOTED.		Not Required	
	1400			
	VERIFY COMPLETED ASSEMBLY IAW BAS00270032 REV (____) SECTION 3.15.			

QA005 RTS Statement

The component identified above was repaired and inspected in accordance with current Federal Aviation Regulations, found airworthy and is approved for return to service with respect to the work performed

Sequence #	4508-18	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4663085	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2508439

4508-18	**WO #**	**4663085**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		No Log Entry	
Interior: STRIP-FINISH (GLOSS)				
Task / IRN # : STRIP-FINISH (GLOSS)				

Sequence #	4508-18	Aircraft SN #	6111	MWPWO #	2498069
WO #	4663085	Aircraft Reg #	XA-SOL	Parent WO #	2508439

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			
	Comply with Preliminary Inspection			
	200			
	VERIFY MATERIAL/COMPONENT: 1) P/N: C2818APN-105 CONFERENCE TABLE (EXISTING) 2) P/N: N381-7488 PST-917 FLEXIBLE POLYESTER TOPCOAT, P.O.# 3) P/N: N381-7490 XP-N-C91 HI GLOSS ACRYLIC LINEAR POLY TOPCOAT, P.O.#			
	300			
	STRIP AND PREPARE SURFACE IAW TES-1103, SECTION 7.0.1, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	400			
	VERIFY SUBSTRATE IAW AC 43.13-1B PAR 5-18.		Not Required	
	500			
	APPLY SEALING COATS IAW TES-1103, SECTION 7.0.2, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	600			
	APPLY INTERMEDIATE COATS IAW TES-1103, SECTION 7.0.3, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	700			
	SAND SURFACE IAW TES-1103, SECTION 7.0.3.1, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	

Bombardier

Sequence #	4508-18	Aircraft SN #	6111	MWPWO #	2498069
WO #	4663085	Aircraft Reg #	XA-SOL	Parent WO #	2508439

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	800			
	POSI TEST: MIL THICKNESS:			
	900			
	APPLY FINISH COAT IAW TES-1103, SECTION 7.0.4, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	1000			
	SAND SURFACE IAW TES-1103, SECTION 7.0.5, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	1100			
	BUFF FINISH IAW TES-1103, SECTION 7.0.6, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	1200			
	POSI TEST: MIL THICKNESS:			
	1300			
	INSPECT FOR ANY VISIBLE FINISH IMPERFECTIONS OR DAMAGE. NO DISCREPANCIES NOTED.		Not Required	
	1400			
	VERIFY COMPLETED ASSEMBLY IAW BAS00270032 REV (____) SECTION 3.15.			

QA005 RTS Statement

The component identified above was repaired and inspected in accordance with current Federal Aviation Regulations, found airworthy and is approved for return to service with respect to the work performed

Sequence #	4508-19	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4663093	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2508439

4508-19	**WO #**	**4663093**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		No Log Entry	
Interior: STRIP-FINISH (GLOSS)				
Task / IRN # : STRIP-FINISH (GLOSS)				

Sequence #	4508-19	Aircraft SN #	6111	MWPWO #	2498069
WO #	4663093	Aircraft Reg #	XA-SOL	Parent WO #	2508439

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with Preliminary Inspection		
	Comply with Preliminary Inspection			
	200	VERIFIED MATERIAL/COMPONENT: 1) P/N: C4638APN-101 SIDELEDGE - LH FWD (EXISTING) 2) P/N: N381-7488 PST-917 FLEXIBLE POLYESTER TOPCOAT, P.O.# 5002410208 3) P/N: N381-7490 XP-N-C91 HI GLOSS ACRYLIC LINEAR POLY TOPCOAT, P.O.#5002410208		
	VERIFY MATERIAL/COMPONENT: 1) P/N: C4638APN-101 SIDELEDGE - LH FWD (EXISTING) 2) P/N: N381-7488 PST-917 FLEXIBLE POLYESTER TOPCOAT, P.O.# 3) P/N: N381-7490 XP-N-C91 HI GLOSS ACRYLIC LINEAR POLY TOPCOAT, P.O.#			
	300	STRIPPED AND PREPARED SURFACE IAW TES-1103, SECTION 7.0.1, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		
	STRIP AND PREPARE SURFACE IAW TES-1103, SECTION 7.0.1, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	400	VERIFIED SUBSTRATE IAW AC 43.13-1B PAR 5-18.		
	VERIFY SUBSTRATE IAW AC 43.13-1B PAR 5-18.		Not Required	
	500			
	APPLY SEALING COATS IAW TES-1103, SECTION 7.0.2, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	600			
	APPLY INTERMEDIATE COATS IAW TES-1103, SECTION 7.0.3, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	700			
	SAND SURFACE IAW TES-1103, SECTION 7.0.3.1, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	

Sequence #	4508-19	Aircraft SN #	6111	MWPWO #	2498069
WO #	4663093	Aircraft Reg #	XA-SOL	Parent WO #	2508439

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	800			
	POSI TEST: MIL THICKNESS:			
	900			
	APPLY FINISH COAT IAW TES-1103, SECTION 7.0.4, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	1000			
	SAND SURFACE IAW TES-1103, SECTION 7.0.5, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	1100			
	BUFF FINISH IAW TES-1103, SECTION 7.0.6, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	1200			
	POSI TEST: MIL THICKNESS:			
	1300			
	INSPECT FOR ANY VISIBLE FINISH IMPERFECTIONS OR DAMAGE. NO DISCREPANCIES NOTED.		Not Required	
	1400			
	VERIFY COMPLETED ASSEMBLY IAW BAS00270032 REV (____) SECTION 3.15.			

QA005 RTS Statement

The component identified above was repaired and inspected in accordance with current Federal Aviation Regulations, found airworthy and is approved for return to service with respect to the work performed

Sequence #	4508-20	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4663096	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2508439

4508-20	**WO #**	**4663096**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		No Log Entry	
Interior: STRIP-FINISH (GLOSS)				
Task / IRN # : STRIP-FINISH (GLOSS)				

Bombardier

Sequence #	4508-20	Aircraft SN #	6111	MWPWO #	2498069
WO #	4663096	Aircraft Reg #	XA-SOL	Parent WO #	2508439

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with Preliminary Inspection		
	Comply with Preliminary Inspection			
	200	VERIFIED MATERIAL/COMPONENT: 1) P/N: C4638APN-103 SIDELEDGE - RH FWD (EXISTING) 2) P/N: N381-7488 PST-917 FLEXIBLE POLYESTER TOPCOAT, P.O.# 5002410208 3) P/N: N381-7490 XP-N-C91 HI GLOSS ACRYLIC LINEAR POLY TOPCOAT, P.O.#500241020		
	VERIFY MATERIAL/COMPONENT: 1) P/N: C4638APN-103 SIDELEDGE - RH FWD (EXISTING) 2) P/N: N381-7488 PST-917 FLEXIBLE POLYESTER TOPCOAT, P.O.# 3) P/N: N381-7490 XP-N-C91 HI GLOSS ACRYLIC LINEAR POLY TOPCOAT, P.O.#			
	300	STRIPPED AND PREPARED SURFACE IAW TES-1103, SECTION 7.0.1, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		
	STRIP AND PREPARE SURFACE IAW TES-1103, SECTION 7.0.1, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	400	VERIFIED SUBSTRATE IAW AC 43.13-1B PAR 5-18.		
	VERIFY SUBSTRATE IAW AC 43.13-1B PAR 5-18.		Not Required	
	500			
	APPLY SEALING COATS IAW TES-1103, SECTION 7.0.2, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	600			
	APPLY INTERMEDIATE COATS IAW TES-1103, SECTION 7.0.3, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	700			
	SAND SURFACE IAW TES-1103, SECTION 7.0.3.1, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	

Bombardier

Sequence #	4508-20	Aircraft SN #	6111	MWPWO #	2498069
WO #	4663096	Aircraft Reg #	XA-SOL	Parent WO #	2508439

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	800			
	POSI TEST: MIL THICKNESS:			
	900			
	APPLY FINISH COAT IAW TES-1103, SECTION 7.0.4, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	1000			
	SAND SURFACE IAW TES-1103, SECTION 7.0.5, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	1100			
	BUFF FINISH IAW TES-1103, SECTION 7.0.6, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	1200			
	POSI TEST: MIL THICKNESS:			
	1300			
	INSPECT FOR ANY VISIBLE FINISH IMPERFECTIONS OR DAMAGE. NO DISCREPANCIES NOTED.		Not Required	
	1400			
	VERIFY COMPLETED ASSEMBLY IAW BAS00270032 REV (____) SECTION 3.15.			

QA005 RTS Statement

The component identified above was repaired and inspected in accordance with current Federal Aviation Regulations, found airworthy and is approved for return to service with respect to the work performed

Sequence #	4508-21	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4663101	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2508439

4508-21	**WO #**	**4663101**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		No Log Entry	
Interior: STRIP-FINISH (GLOSS)				
Task / IRN # : STRIP-FINISH (GLOSS)				

Bombardier

Sequence #	4508-21	Aircraft SN #	6111	MWPWO #	2498069
WO #	4663101	Aircraft Reg #	XA-SOL	Parent WO #	2508439

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			
	Comply with Preliminary Inspection			
	200	VERIFY MATERIAL/COMPONENT: 1) P/N: C4638APN-113 SIDELEDGE - RH AFT (EXISTING) 2) P/N: N381-7488 PST-917 FLEXIBLE POLYESTER TOPCOAT, P.O.#5002410208 3) P/N: N381-7490 XP-N-C91 HI GLOSS ACRYLIC LINEAR POLY TOPCOAT, P.O.#5002410208		
	VERIFY MATERIAL/COMPONENT: 1) P/N: C4638APN-113 SIDELEDGE - RH AFT (EXISTING) 2) P/N: N381-7488 PST-917 FLEXIBLE POLYESTER TOPCOAT, P.O.# 3) P/N: N381-7490 XP-N-C91 HI GLOSS ACRYLIC LINEAR POLY TOPCOAT, P.O.#			
	300			
	STRIP AND PREPARE SURFACE IAW TES-1103, SECTION 7.0.1, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	400	VERIFIED SUBSTRATE IAW AC 43.13-1B PAR 5-18.		
	VERIFY SUBSTRATE IAW AC 43.13-1B PAR 5-18.		Not Required	
	500			
	APPLY SEALING COATS IAW TES-1103, SECTION 7.0.2, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	600			
	APPLY INTERMEDIATE COATS IAW TES-1103, SECTION 7.0.3, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	700			
	SAND SURFACE IAW TES-1103, SECTION 7.0.3.1, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	

Bombardier

Sequence #	4508-21	Aircraft SN #	6111	MWPWO #	2498069
WO #	4663101	Aircraft Reg #	XA-SOL	Parent WO #	2508439

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	800			
	POSI TEST: MIL THICKNESS:			
	900			
	APPLY FINISH COAT IAW TES-1103, SECTION 7.0.4, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	1000			
	SAND SURFACE IAW TES-1103, SECTION 7.0.5, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	1100			
	BUFF FINISH IAW TES-1103, SECTION 7.0.6, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	1200			
	POSI TEST: MIL THICKNESS:			
	1300			
	INSPECT FOR ANY VISIBLE FINISH IMPERFECTIONS OR DAMAGE. NO DISCREPANCIES NOTED.		Not Required	
	1400			
	VERIFY COMPLETED ASSEMBLY IAW BAS00270032 REV (____) SECTION 3.15.			

QA005 RTS Statement

The component identified above was repaired and inspected in accordance with current Federal Aviation Regulations, found airworthy and is approved for return to service with respect to the work performed

Sequence #	4508-22	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4663109	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2508439

4508-22	**WO #**	**4663109**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		No Log Entry	
Interior: STRIP-FINISH (GLOSS)				
Task / IRN # : STRIP-FINISH (GLOSS)				

Bombardier

Sequence #	4508-22	Aircraft SN #	6111	MWPWO #	2498069
WO #	4663109	Aircraft Reg #	XA-SOL	Parent WO #	2508439

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with Preliminary Inspection		
	Comply with Preliminary Inspection			
	200	VERIFIED MATERIAL/COMPONENT: 1) P/N: C4638APN-117 SIDELEDGE - LH AFT (EXISTING) 2) P/N: N381-7488 PST-917 FLEXIBLE POLYESTER TOPCOAT, P.O.# 5002410208 3) P/N: N381-7490 XP-N-C91 HI GLOSS ACRYLIC LINEAR POLY TOPCOAT, P.O.#5002410208		
	VERIFY MATERIAL/COMPONENT: 1) P/N: C4638APN-117 SIDELEDGE - LH AFT (EXISTING) 2) P/N: N381-7488 PST-917 FLEXIBLE POLYESTER TOPCOAT, P.O.# 3) P/N: N381-7490 XP-N-C91 HI GLOSS ACRYLIC LINEAR POLY TOPCOAT, P.O.#			
	300	STRIPPED AND PREPARED SURFACE IAW TES-1103, SECTION 7.0.1, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		
	STRIP AND PREPARE SURFACE IAW TES-1103, SECTION 7.0.1, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	400	VERIFIED SUBSTRATE IAW AC 43.13-1B PAR 5-18.		
	VERIFY SUBSTRATE IAW AC 43.13-1B PAR 5-18.		Not Required	
	500			
	APPLY SEALING COATS IAW TES-1103, SECTION 7.0.2, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	600			
	APPLY INTERMEDIATE COATS IAW TES-1103, SECTION 7.0.3, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	700			
	SAND SURFACE IAW TES-1103, SECTION 7.0.3.1, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	

Bombardier

Sequence #	4508-22	Aircraft SN #	6111	MWPWO #	2498069
WO #	4663109	Aircraft Reg #	XA-SOL	Parent WO #	2508439

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	800			
	POSI TEST: MIL THICKNESS:			
	900			
	APPLY FINISH COAT IAW TES-1103, SECTION 7.0.4, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	1000			
	SAND SURFACE IAW TES-1103, SECTION 7.0.5, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	1100			
	BUFF FINISH IAW TES-1103, SECTION 7.0.6, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	1200			
	POSI TEST: MIL THICKNESS:			
	1300			
	INSPECT FOR ANY VISIBLE FINISH IMPERFECTIONS OR DAMAGE. NO DISCREPANCIES NOTED.		Not Required	
	1400			
	VERIFY COMPLETED ASSEMBLY IAW BAS00270032 REV (____) SECTION 3.15.			

QA005 RTS Statement

The component identified above was repaired and inspected in accordance with current Federal Aviation Regulations, found airworthy and is approved for return to service with respect to the work performed

Sequence #	4508-23	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4663113	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2508439

4508-23	**WO #**	**4663113**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		No Log Entry	
Interior: STRIP-FINISH (GLOSS)				
Task / IRN # : STRIP-FINISH (GLOSS)				

Sequence #	4508-23	Aircraft SN #	6111	MWPWO #	2498069
WO #	4663113	Aircraft Reg #	XA-SOL	Parent WO #	2508439

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with Preliminary Inspection		
	Comply with Preliminary Inspection			
	200	VERIFIED MATERIAL/COMPONENT: 1) P/N: C4638APN-105 EMER LEDGE (EXISTING) 2) P/N: N381-7488 PST-917 FLEXIBLE POLYESTER TOPCOAT, P.O.# 5002410208 3) P/N: N381-7490 XP-N-C91 HI GLOSS ACRYLIC LINEAR POLY TOPCOAT, P.O.#5002410208		
	VERIFY MATERIAL/COMPONENT: 1) P/N: C4638APN-105 EMER LEDGE (EXISTING) 2) P/N: N381-7488 PST-917 FLEXIBLE POLYESTER TOPCOAT, P.O.# 3) P/N: N381-7490 XP-N-C91 HI GLOSS ACRYLIC LINEAR POLY TOPCOAT, P.O.#			
	300	STRIPPED AND PREPARED SURFACE IAW TES-1103, SECTION 7.0.1, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		
	STRIP AND PREPARE SURFACE IAW TES-1103, SECTION 7.0.1, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	400	VERIFIED SUBSTRATE IAW AC 43.13-1B PAR 5-18.		
	VERIFY SUBSTRATE IAW AC 43.13-1B PAR 5-18.		Not Required	
	500	APPLIED SEALING COATS IAW TES-1103, SECTION 7.0.2, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		
	APPLY SEALING COATS IAW TES-1103, SECTION 7.0.2, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	600			
	APPLY INTERMEDIATE COATS IAW TES-1103, SECTION 7.0.3, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	700			
	SAND SURFACE IAW TES-1103, SECTION 7.0.3.1, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	

Bombardier

Sequence #	4508-23	Aircraft SN #	6111	MWPWO #	2498069
WO #	4663113	Aircraft Reg #	XA-SOL	Parent WO #	2508439

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	800			
	POSI TEST: MIL THICKNESS:			
	900			
	APPLY FINISH COAT IAW TES-1103, SECTION 7.0.4, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	1000			
	SAND SURFACE IAW TES-1103, SECTION 7.0.5, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	1100			
	BUFF FINISH IAW TES-1103, SECTION 7.0.6, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	1200			
	POSI TEST: MIL THICKNESS:			
	1300			
	INSPECT FOR ANY VISIBLE FINISH IMPERFECTIONS OR DAMAGE. NO DISCREPANCIES NOTED.		Not Required	
	1400			
	VERIFY COMPLETED ASSEMBLY IAW BAS00270032 REV (____) SECTION 3.15.			

QA005 RTS Statement

The component identified above was repaired and inspected in accordance with current Federal Aviation Regulations, found airworthy and is approved for return to service with respect to the work performed

Sequence #	4508-24	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4663125	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2508439

4508-24	**WO #**	**4663125**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		No Log Entry	
Interior: STRIP-FINISH (GLOSS)				
Task / IRN # : STRIP-FINISH (GLOSS)				

Sequence #	4508-24	Aircraft SN #	6111	MWPWO #	2498069
WO #	4663125	Aircraft Reg #	XA-SOL	Parent WO #	2508439

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with Preliminary Inspection		
	Comply with Preliminary Inspection			
	200	VERIFIED MATERIAL/COMPONENT: 1) P/N: C4028APN-101 VANITY ASSY (EXISTING) 2) P/N: N381-7488 PST-917 FLEXIBLE POLYESTER TOPCOAT, P.O.#5002410208 3) P/N: N381-7490 XP-N-C91 HI GLOSS ACRYLIC LINEAR POLY TOPCOAT, P.O.#5002410208		
	VERIFY MATERIAL/COMPONENT: 1) P/N: C4028APN-101 VANITY ASSY (EXISTING) 2) P/N: N381-7488 PST-917 FLEXIBLE POLYESTER TOPCOAT, P.O.# 3) P/N: N381-7490 XP-N-C91 HI GLOSS ACRYLIC LINEAR POLY TOPCOAT, P.O.#			
	300	STRIPPED AND PREPARED SURFACE IAW TES-1103, SECTION 7.0.1, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		
	STRIP AND PREPARE SURFACE IAW TES-1103, SECTION 7.0.1, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	400	VERIFIED SUBSTRATE IAW AC 43.13-1B PAR 5-18.		
	VERIFY SUBSTRATE IAW AC 43.13-1B PAR 5-18.		Not Required	
	500	APPLIED SEALING COATS IAW TES-1103, SECTION 7.0.2, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		
	APPLY SEALING COATS IAW TES-1103, SECTION 7.0.2, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	600			
	APPLY INTERMEDIATE COATS IAW TES-1103, SECTION 7.0.3, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	700			
	SAND SURFACE IAW TES-1103, SECTION 7.0.3.1, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	

Bombardier

Sequence #	4508-24	Aircraft SN #	6111	MWPWO #	2498069
WO #	4663125	Aircraft Reg #	XA-SOL	Parent WO #	2508439

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	800			
	POSI TEST: MIL THICKNESS:			
	900			
	APPLY FINISH COAT IAW TES-1103, SECTION 7.0.4, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	1000			
	SAND SURFACE IAW TES-1103, SECTION 7.0.5, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	1100			
	BUFF FINISH IAW TES-1103, SECTION 7.0.6, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	1200			
	POSI TEST: MIL THICKNESS:			
	1300			
	INSPECT FOR ANY VISIBLE FINISH IMPERFECTIONS OR DAMAGE. NO DISCREPANCIES NOTED.		Not Required	
	1400			
	VERIFY COMPLETED ASSEMBLY IAW BAS00270032 REV (____) SECTION 3.15.			

QA005 RTS Statement

The component identified above was repaired and inspected in accordance with current Federal Aviation Regulations, found airworthy and is approved for return to service with respect to the work performed

Sequence #	4508-25	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4663126	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2508439

4508-25	**WO #**	**4663126**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		No Log Entry	
Interior: STRIP-FINISH (GLOSS)				
Task / IRN # : STRIP-FINISH (GLOSS)				

Bombardier

Sequence #	4508-25	Aircraft SN #	6111	MWPWO #	2498069
WO #	4663126	Aircraft Reg #	XA-SOL	Parent WO #	2508439

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with Preliminary Inspection		
	Comply with Preliminary Inspection			
	200	VERIFIED MATERIAL/COMPONENT: 1) P/N: C4018APN-101 TOILET SHROUD ASSY (EXISTING) 2) P/N: N381-7488 PST-917 FLEXIBLE POLYESTER TOPCOAT, P.O.# 5002410208 3) P/N: N381-7490 XP-N-C91 HI GLOSS ACRYLIC LINEAR POLY TOPCOAT, P.O.#5002410208		
	VERIFY MATERIAL/COMPONENT: 1) P/N: C4018APN-101 TOILET SHROUD ASSY (EXISTING) 2) P/N: N381-7488 PST-917 FLEXIBLE POLYESTER TOPCOAT, P.O.# 3) P/N: N381-7490 XP-N-C91 HI GLOSS ACRYLIC LINEAR POLY TOPCOAT, P.O.#			
	300	STRIPPED AND PREPARED SURFACE IAW TES-1103, SECTION 7.0.1, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		
	STRIP AND PREPARE SURFACE IAW TES-1103, SECTION 7.0.1, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	400	VERIFIED SUBSTRATE IAW AC 43.13-1B PAR 5-18.		
	VERIFY SUBSTRATE IAW AC 43.13-1B PAR 5-18.		Not Required	
	500	APPLIED SEALING COATS IAW TES-1103, SECTION 7.0.2, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		
	APPLY SEALING COATS IAW TES-1103, SECTION 7.0.2, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	600			
	APPLY INTERMEDIATE COATS IAW TES-1103, SECTION 7.0.3, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	700			
	SAND SURFACE IAW TES-1103, SECTION 7.0.3.1, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	

Bombardier

Sequence #	4508-25	Aircraft SN #	6111	MWPWO #	2498069
WO #	4663126	Aircraft Reg #	XA-SOL	Parent WO #	2508439

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	800			
	POSI TEST: MIL THICKNESS:			
	900			
	APPLY FINISH COAT IAW TES-1103, SECTION 7.0.4, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	1000			
	SAND SURFACE IAW TES-1103, SECTION 7.0.5, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	1100			
	BUFF FINISH IAW TES-1103, SECTION 7.0.6, FINISH PROCESS FOR HARDWOOD AND VENEER, AXON-HENTZEN PRODUCTS.		Not Required	
	1200			
	POSI TEST: MIL THICKNESS:			
	1300			
	INSPECT FOR ANY VISIBLE FINISH IMPERFECTIONS OR DAMAGE. NO DISCREPANCIES NOTED.		Not Required	
	1400			
	VERIFY COMPLETED ASSEMBLY IAW BAS00270032 REV (____) SECTION 3.15.			

QA005 RTS Statement

The component identified above was repaired and inspected in accordance with current Federal Aviation Regulations, found airworthy and is approved for return to service with respect to the work performed

Sequence #	4508-26	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4665056	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2508439

4508-26	**WO #**	**4665056**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		No Log Entry	
Interior Refurb: FAB - INT PLACARD KIT BY DWG NUM - JJ				
Task / IRN # : FAB - INT PLACARD KIT BY DWG				

Sequence #	4508-26	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4665056	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2508439

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			
	Comply with Preliminary Inspection			
	200			
	VERIFY COMPONENT/MATERIAL: P/N: HP92S GE LEXAN FILM .007 THICK, P.O.# P/N: 467MP HI-PERFORMANCE ADHESIVE (3M), P.O.# P/N: CL600-6111-PKIT1 PLACARD KIT, MADE IN THIS OPERATION			

Sequence #	4508-26	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4665056	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2508439

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	300			
			Not Required	

Sequence #	4508-26	Aircraft SN #	6111	MWPWO #	2498069
WO #	4665056	Aircraft Reg #	XA-SOL	Parent WO #	2508439

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	FABRICATE 1EA CL600-6111-PKIT1 PLACARD KIT IAW ASSIGN DWG * ENTRY / GALLEY BAS63037698 REV NC (a) FABRICATE 1EA 604DX1131019-293-A-A PLACARD IAW 604DX1131019 REV (K). (b) FABRICATE 1EA 604DX1131019-124-A-A PLACARD IAW 604DX1131019 REV (K). (c) FABRICATE 1EA 604DX1131019-152-A-K PLACARD IAW 604DX1131019 REV (K). (d) FABRICATE 2EA 604DX1131019-112-A-A PLACARD IAW 604DX1131019 REV (K). (e) FABRICATE 1EA 604DX1131019-016-A-A PLACARD IAW 604DX1131019 REV (K). (f) FABRICATE 1EA 604DX1131019-233-A-A PLACARD IAW 604DX1131019 REV (K). (g) FABRICATE 1EA 604DX1131019-041-A-B PLACARD IAW 604DX1131019 REV (K). (h) FABRICATE 1EA 604DX1131019-223-A-A PLACARD IAW 604DX1131019 REV (K). (i) FABRICATE 1EA 604DX1131019-239-A-A PLACARD IAW 604DX1131019 REV (K). (j) FABRICATE 1EA 604DX1131019-041-A-A PLACARD IAW 604DX1131019 REV (K). (j) FABRICATE 1EA 604DX1131019-231-A-A PLACARD IAW 604DX1131019 REV (K). (k) FABRICATE 6EA 604DX1131000-362-A-K PLACARD IAW 604DX1131000 REV (DB). (m) FABRICATE 3EA 604DX1131019-012-A-A PLACARD IAW 604DX1131019 REV (K). (n) FABRICATE 1EA BAS63037701-205 PLACARD IAW BAS63037701 REV (NC). (o) FABRICATE 1EA 604DX1131019-014-A-B PLACARD IAW 604DX1131019 REV (K). (p) FABRICATE 1EA 604DX1131019-243-A-A PLACARD IAW 604DX1131019 REV (K).			

Sequence #	4508-26	Aircraft SN #	6111	MWPWO #	2498069
WO #	4665056	Aircraft Reg #	XA-SOL	Parent WO #	2508439

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	(q) FABRICATE 1EA 604DX1131019-299-A-B PLACARD IAW 604DX1131019 REV (K). (r) FABRICATE 4EA 604DX1131019-009-A-B PLACARD IAW 604DX1131019 REV (K). (s) FABRICATE 1EA 604DX1131019-222-A-B PLACARD IAW 604DX1131019 REV (K). * MAIN CABIN BAS63037697 REV NC (a) FABRICATE 2EA 604DX1131019-262-A-A PLACARD IAW 604DX1131019 REV (K). (b) FABRICATE 4EA 604DX1131019-172-A-A PLACARD IAW 604DX1131019 REV (K). (c) FABRICATE 2EA 604DX1131019-073-A-A PLACARD IAW 604DX1131019 REV (K). (d) FABRICATE 2EA 604DX1131019-260-A-A PLACARD IAW 604DX1131019 REV (K). (e) FABRICATE 2EA 604DX1131000-365-A-K PLACARD IAW 604DX1131000 REV (A). (f) FABRICATE 2EA 604DX1131019-260-A-A PLACARD IAW 604DX1131019 REV (K). (g) FABRICATE 2EA 604DX1131000-395-A-K PLACARD IAW 604DX1131000 REV (DB). (h) FABRICATE 6EA 604DX1131019-007-A-A PLACARD IAW 604DX1131019 REV (K). (i) FABRICATE 4EA 604DX1131019-135-A-A PLACARD IAW 604DX1131019 REV (K). (j) FABRICATE 4EA 101132049-068-A-A PLACARD IAW 101132049 REV (A). (k) FABRICATE 6EA BAS63037701-205 PLACARD IAW BAS63037701 REV (NC). (m) FABRICATE 1EA 604DX1131000-404-A-K PLACARD IAW 604DX1131000 REV (DB). (n) FABRICATE 7EA 604DX1131019-039-A-A PLACARD IAW 604DX1131019 REV (K).			

Sequence #	4508-26	Aircraft SN #	6111	MWPWO #	2498069
WO #	4665056	Aircraft Reg #	XA-SOL	Parent WO #	2508439

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	(o) FABRICATE 1EA 604DX1131019-290-A-B PLACARD IAW 604DX1131019 REV (K). (p) FABRICATE 2EA 604DX1131019-136-A-A PLACARD IAW 604DX1131019 REV (K). (q) FABRICATE 4EA 604DX1131019-068-A-A PLACARD IAW 604DX1131019 REV (K). (r) FABRICATE 2EA 604DX1131019-171-A-A PLACARD IAW 604DX1131019 REV (K). (s) FABRICATE 1EA 604DX1131019-071-A-A PLACARD IAW 604DX1131019 REV (K). (t) FABRICATE 1EA 604DX1131019-137-A-A PLACARD IAW 604DX1131019 REV (K). (u) FABRICATE 1EA 604DX1131019-017-A-A PLACARD IAW 604DX1131019 REV (K). (v) FABRICATE 1EA 604DX1131000-360-A-K PLACARD IAW 604DX1131000 REV (DB). (w) FABRICATE 1EA 604DX1131000-346-A-K PLACARD IAW 604DX1131000 REV (DB). (x) FABRICATE 1EA 604DX1131000-365-A-K PLACARD IAW 604DX1131000 REV (DB). (y) FABRICATE 1EA 604DX1131019-209-A-D PLACARD IAW 604DX1131019 REV (K). (z) FABRICATE 2EA 604DX1131019-116-A-A PLACARD IAW 604DX1131019 REV (K). (aa)FABRICATE 4EA 604DX1131019-242-A-A PLACARD IAW 604DX1131019 REV (K). (bb) FABRICATE 1EA 604DX1131000-353-A-K PLACARD IAW 604DX1131000 REV (DB). (cc) FABRICATE 1EA 604DX1131000-406-A-K PLACARD IAW 604DX1131000 REV (DB). (dd) FABRICATE 5EA 604DX1131019-117-A-A PLACARD IAW 604DX1131019 REV (K). (ee) FABRICATE 1EA 604DX1131019-184-A-D PLACARD IAW 604DX1131019 REV (K). (ff) FABRICATE 1EA 604DX1131019-307-A-A PLACARD IAW 604DX1131019 REV (K).			

Sequence #	4508-26	Aircraft SN #	6111	MWPWO #	2498069
WO #	4665056	Aircraft Reg #	XA-SOL	Parent WO #	2508439

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	(gg) FABRICATE 1EA 604DX1131019-090-A-A PLACARD IAW 604DX1131019 REV (K). (hh) FABRICATE 1EA 604DX1131019-065-A-A PLACARD IAW 604DX1131019 REV (K). * LAV DWG BAS63037699 REV NC (a) FABRICATE 1EA 604DX1131019-242-A-A PLACARD IAW 604DX1131019 REV (K). (b) FABRICATE 1EA 604DX1131019-046-A-A PLACARD IAW 604DX1131019 REV (K). (c) FABRICATE 1EA 604DX1131019-110-A-A PLACARD IAW 604DX1131019 REV (K). (d) FABRICATE 1EA 604DX1131019-306-A-A PLACARD IAW 604DX1131019 REV (K). (e) FABRICATE 2EA 604DX1131019-238-A-A PLACARD IAW 604DX1131019 REV (K). (f) FABRICATE 1EA 604DX1131019-120-A-A PLACARD IAW 604DX1131019 REV (K). (e) FABRICATE 1EA 604DX1131019-117-A-A PLACARD IAW 604DX1131019 REV (K). (f) FABRICATE 1EA 604DX1131019-184-A-D PLACARD IAW 604DX1131019 REV (K). (g) FABRICATE 1EA 604DX1131019-252-A-A PLACARD IAW 604DX1131019 REV (K). (h) FABRICATE 1EA 604DX1131019-120-A-B PLACARD IAW 604DX1131019 REV (K). (i) FABRICATE 1EA 604DX1131019-213-A-B PLACARD IAW 604DX1131019 REV (K). (j) FABRICATE 1EA 604DX1131019-213-B-G-2 PLACARD IAW 604DX1131019 REV (K). (k) FABRICATE 1EA 604DX1131019-219-B-G-2 PLACARD IAW 604DX1131019 REV (K). (l) FABRICATE 1EA 604DX1131019-034-B-G-2			

Sequence #	4508-26	Aircraft SN #	6111	MWPWO #	2498069
WO #	4665056	Aircraft Reg #	XA-SOL	Parent WO #	2508439

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	PLACARD IAW 604DX1131019 REV (K).			
	400			
	IDENTIFY CL600-6111-PKIT1 INTERIOR PLACARD KIT, CSO SERVICE ORDER NUMBER, DATE IAW BAPS 144-005, SECTION 9.5.1.1, IDENTIFICATION OF AIRCRAFT PARTS AND ASSEMBLIES.			
	500			
	VERIFY CL600-6111-PKIT1 PLACARD KIT COMPLETED IAW ASSIGNED DWG			

QA005 RTS Statement

The component identified above was repaired and inspected in accordance with current Federal Aviation Regulations, found airworthy and is approved for return to service with respect to the work performed

Bombardier

Sequence #	4509	Aircraft SN #	6111	MWPWO #	2498069
WO #	2508727	Aircraft Reg #	XA-SOL	Parent WO #	2498069

4509	WO #	2508727	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13276323	No Log Entry	
Interior - Reupholster of 4 ea. cabin single seats, 2 ea. cabin double seats, 1ea. 3 place divan, 1 ea. lavatory potty seat with back rest, and 1 ea. jump seat, excludes new foam				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Do Not Work Per Customer Request.	B1014141 - Christopher Drawdy Feb 12, 2026 05:14 PM	25-20
	Perform reupholstering of 4 ea. cabin single seats, 2 ea. cabin double seats, 1ea. 3 places divan, 1 ea. lavatory potty seat with back rest. and 1 ea. jump seat, excluding new foam		B1013522 - Brandon Jennings Feb 12, 2026 05:51 PM	
	200	Do Not Work Per Customer Request.	B1014141 - Christopher Drawdy Feb 12, 2026 05:14 PM	25-20
	Perform support required for paint		B1013522 - Brandon Jennings Feb 12, 2026 05:51 PM	
	300	Do Not Work Per Customer Request.	B1014141 - Christopher Drawdy Feb 12, 2026 05:14 PM	25-20
	Perform work in support of flammability testing		B1013522 - Brandon Jennings Feb 12, 2026 05:51 PM	

Sequence #	4509	Aircraft SN #	6111	MWPWO #	2498069
WO #	2508727	Aircraft Reg #	XA-SOL	Parent WO #	2498069

CHILD WORK ORDER DETAILS

	WO #	Description	Corrective Action	AMENDED
4509-1	4432624	7024/4509-REUPHOLSTER 1EA 2524.014.01-3312C.22 RH #1	DO NOT WORK PER CUSTOMER REQUEST	
4509-2	4432632	7025/4509-REUPHOLSTER 1EA 2524.014.01-3313D.22 LH#1	DO NOT WORK PER CUSTOMER REQUEST	
4509-3	4432641	7026/4509-REUPHOLSTER 1EA 2524.014.01-3311B.22 LH#2	DO NOT WORK PER CUSTOMER REQUEST	
4509-4	4432656	7027/4509-REUPHOLSTER 1EA 2524.014.01-3338A.22 RH#2	DO NOT WORK PER CUSTOMER REQUEST	
4509-5	4432660	7028/4509-REUPHOLSTER 1EA 2524.015.01-811C.22 LH#3 AF	DO NOT WORK - CUSTOMER REQUEST.	
4509-6	4432661	7029/4509-REUPHOLSTER 1EA 2524.015.01-810B.22 LH#4 FF	DO NOT WORK - CUSTOMER REQUEST.	
4509-7	4432700	Interior Refurb: RH DIVAN CL 9G-RH RECOVER (WITH FOAM)	DO NOT WORK , WO# 4432700 - 7030/4509-REUPHOLSTER 1EA 2523.559.01-46.22 DIVAN CL 9G-RH RECOVER (WITH FOAM). WORK WILL BE PERFORMED ON NEW CSO WO# 4701047 Deferral Code: Do Not Work Reason: Customer Request Details: DO NOT WORK , WO# 4432700 - 7030/4509-REUPHOLSTER 1EA 2523.559.01-46.22 DIVAN CL 9G-RH RECOVER (WITH FOAM). WORK WILL BE PERFORMED ON NEW CSO WO# 4701047	
4509-8	4432709	7031/4509-REUPHOLSTER 1EA CL650-6111-LTSC LAV TOILET SEAT CUSHION	DO NOT WORK - CUSTOMER REQUEST. SEE NEW CSO WO# 4775718	
4509-9	4432718	7032/4509-REUPHOLSTER 1EA CL650-6111-LTBR BACKREST ASSY LAV TOILET	DO NOT WORK - CUSTOMER REQUEST.	
4509-10	4432730	7033/4509-REUPHOLSTER 1EA JS600A-(RH1) JUMPSEAT	DO NOT WORK - CUSTOMER REQUEST. SEE NEW CSO WO# 4701158	

Sequence #	4509-1	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4432624	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2508727

4509-1	**WO #**	**4432624**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		No Log Entry	
7024/4509-REUPHOLSTER 1EA 2524.014.01-3312C.22 RH #1				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	DO NOT WORK PER CUSTOMER REQUEST	B0599115 - Mark Fierro Feb 26, 2026 07:41 PM	
	7024/4509-REUPHOLSTER 1EA 2524.014.01-3312C.22 RH #1		Not Required	

Sequence #	4509-2	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4432632	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2508727

4509-2	**WO #**	**4432632**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		No Log Entry	
7025/4509-REUPHOLSTER 1EA 2524.014.01-3313D.22 LH#1				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	DO NOT WORK PER CUSTOMER REQUEST	B0599115 - Mark Fierro Feb 26, 2026 08:08 PM	
	7025/4509-REUPHOLSTER 1EA 2524.014.01-3313D.22 LH#1		Not Required	

Bombardier

Sequence #	4509-3	Aircraft SN #	6111	MWPWO #	2498069
WO #	4432641	Aircraft Reg #	XA-SOL	Parent WO #	2508727

4509-3	WO #	4432641	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		No Log Entry	
7026/4509-REUPHOLSTER 1EA 2524.014.01-3311B.22 LH#2				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	DO NOT WORK PER CUSTOMER REQUEST	B0599115 - Mark Fierro Feb 26, 2026 08:14 PM	
	7026/4509-REUPHOLSTER 1EA 2524.014.01-3311B.22 LH#2		Not Required	

Sequence #	4509-4	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4432656	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2508727

4509-4	**WO #**	**4432656**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		No Log Entry	
7027/4509-REUPHOLSTER 1EA 2524.014.01-3338A.22 RH#2				

OPERATIONAL DETAILS

	Operation # / **Operation Description**	**Corrective Action Long Description**	**Tech Sign Off** / **Insp Sign Off**	**ATA Code** / **Reason for Work**
	100	DO NOT WORK PER CUSTOMER REQUEST	B0599115 - Mark Fierro Feb 26, 2026 08:38 PM	
	7027/4509-REUPHOLSTER 1EA 2524.014.01-3338A.22 RH#2			

Bombardier

Sequence #	4509-5	Aircraft SN #	6111	MWPWO #	2498069
WO #	4432660	Aircraft Reg #	XA-SOL	Parent WO #	2508727

4509-5	WO #	4432660	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		No Log Entry	
7028/4509-REUPHOLSTER 1EA 2524.015.01-811C.22 LH#3 AF				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	DO NOT WORK - CUSTOMER REQUEST.	B0599115 - Mark Fierro Feb 26, 2026 08:45 PM	
	7028/4509-REUPHOLSTER 1EA 2524.015.01-811C.22 LH#3 AF		Not Required	

Bombardier

Sequence #	4509-6	Aircraft SN #	6111	MWPWO #	2498069
WO #	4432661	Aircraft Reg #	XA-SOL	Parent WO #	2508727

4509-6	WO #	4432661	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		No Log Entry	
7029/4509-REUPHOLSTER 1EA 2524.015.01-810B.22 LH#4 FF				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	DO NOT WORK - CUSTOMER REQUEST.	B0599115 - Mark Fierro Feb 26, 2026 08:49 PM	
	7029/4509-REUPHOLSTER 1EA 2524.015.01-810B.22 LH#4 FF		Not Required	

Sequence #	4509-7	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4432700	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2508727

4509-7	**WO #**	**4432700**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		No Log Entry	Do Not Work
Interior Refurb: RH DIVAN CL 9G-RH RECOVER (WITH FOAM)				Customer Request
Task / IRN # : RH DIVAN CL 9G-RH RECOVER				

Sequence #	4509-7	Aircraft SN #	6111	MWPWO #	2498069
WO #	4432700	Aircraft Reg #	XA-SOL	Parent WO #	2508727

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	DO NOT WORK , WO# 4432700 - 7030/4509-REUPHOLSTER 1EA 2523.559.01-46.22 DIVAN CL 9G-RH RECOVER (WITH FOAM). WORK WILL BE PERFORMED ON NEW CSO WO# 4701047	B0599115 - Mark Fierro Feb 23, 2026 07:38 PM	
	Comply with Preliminary Inspection		Not Required	
	200	DO NOT WORK , WO# 4432700 - 7030/4509-REUPHOLSTER 1EA 2523.559.01-46.22 DIVAN CL 9G-RH RECOVER (WITH FOAM). WORK WILL BE PERFORMED ON NEW CSO WO# 4701047	B0599115 - Mark Fierro Feb 23, 2026 07:38 PM	
	VERIFY MATERIAL/COMPONENTS: 1) P/N: 2523.559.01-46.22 DIVAN 3PL DIVAN ASSY, EXISTING 2) P/N: T23031 , 002, DEDAR MALLEMIGLIA FABRIC P.O.# 3) P/N: CL-84487-1110, WINTER NIGHT, CLASSIC C/H TOWNSEND, P.O.# 4) P/N: _____FOAM, P.O.# 5) P/N: _____FOAM, P.O.# 6) P/N: _____LOOP FABRIC, P.O.# 7) P/N: _____HOOK FABRIC, P.O.# 8) P/N: RE-WEBBED DIVAN SEAT BELT, P.O.# 9) P/N: 048011-98648 EC-1357 ADHESIVE, P.O.# 10) P/N: 309 SIMALFA ADHESIVE, P.O.#		Not Required	
	300	DO NOT WORK , WO# 4432700 - 7030/4509-REUPHOLSTER 1EA 2523.559.01-46.22 DIVAN CL 9G-RH RECOVER (WITH FOAM). WORK WILL BE PERFORMED ON NEW CSO WO# 4701047	B0599115 - Mark Fierro Feb 23, 2026 07:38 PM	
	DISASSEMBLE DIVAN ASSEMBLY IAW TM412521-145-1.		Not Required	
	400	DO NOT WORK , WO# 4432700 - 7030/4509-REUPHOLSTER 1EA 2523.559.01-46.22 DIVAN CL 9G-RH RECOVER (WITH FOAM). WORK WILL BE PERFORMED ON NEW CSO WO# 4701047	B0599115 - Mark Fierro Feb 23, 2026 07:38 PM	
	VERFIY SUBSTRATE INTEGRITY IAW AC 43.13-1B PAR 5-18.		Not Required	

Sequence #	4509-7	Aircraft SN #	6111	MWPWO #	2498069
WO #	4432700	Aircraft Reg #	XA-SOL	Parent WO #	2508727

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	500	DO NOT WORK , WO# 4432700 - 7030/4509-REUPHOLSTER 1EA 2523.559.01-46.22 DIVAN CL 9G-RH RECOVER (WITH FOAM). WORK WILL BE PERFORMED ON NEW CSO WO# 4701047	B0599115 - Mark Fierro Feb 23, 2026 07:38 PM	
	PAINT EXISTING DIVAN FRAME AND HARDWARE AS REQUIRED USING MATCHING JETFLEX PAINT APPLIED IAW MANUFACTURES INSTRUCIONS.		Not Required	
	600	DO NOT WORK , WO# 4432700 - 7030/4509-REUPHOLSTER 1EA 2523.559.01-46.22 DIVAN CL 9G-RH RECOVER (WITH FOAM). WORK WILL BE PERFORMED ON NEW CSO WO# 4701047	B0599115 - Mark Fierro Feb 23, 2026 07:38 PM	
	FABRICATE DIVAN CUSHIONS AND UPHOLSTER IAW ACES DWG:		Not Required	
	700	DO NOT WORK , WO# 4432700 - 7030/4509-REUPHOLSTER 1EA 2523.559.01-46.22 DIVAN CL 9G-RH RECOVER (WITH FOAM). WORK WILL BE PERFORMED ON NEW CSO WO# 4701047	B0599115 - Mark Fierro Feb 23, 2026 07:38 PM	
	UPHOLSTER 2EA DIVAN END-CABINET ARMRESTS IAW ACES DWG:		Not Required	
	800	DO NOT WORK , WO# 4432700 - 7030/4509-REUPHOLSTER 1EA 2523.559.01-46.22 DIVAN CL 9G-RH RECOVER (WITH FOAM). WORK WILL BE PERFORMED ON NEW CSO WO# 4701047	B0599115 - Mark Fierro Feb 23, 2026 07:38 PM	
	REINSTALL SEAT BELTS IAW TE-55025000-SMM SECTION 25-21-30		Not Required	
	900	DO NOT WORK , WO# 4432700 - 7030/4509-REUPHOLSTER 1EA 2523.559.01-46.22 DIVAN CL 9G-RH RECOVER (WITH FOAM). WORK WILL BE PERFORMED ON NEW CSO WO# 4701047	B0599115 - Mark Fierro Feb 23, 2026 07:38 PM	
	RE-ASSEMBLE DIVAN ASSEMBLY IAW TM412521-145-1		Not Required	
	1000	DO NOT WORK , WO# 4432700 - 7030/4509-REUPHOLSTER 1EA 2523.559.01-46.22 DIVAN CL 9G-RH RECOVER (WITH FOAM). WORK WILL BE PERFORMED ON NEW CSO WO# 4701047	B0599115 - Mark Fierro Feb 23, 2026 07:38 PM	
	VERIFY COMPLETED ASSEMBLY(S) IAW TM412521-145-1		Not Required	

QA005 RTS Statement

The component identified above was repaired and inspected in accordance with current Federal Aviation Regulations, found airworthy and is approved for return to service with respect to the work performed

Sequence #	4509-7	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4432700	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2508727

Inspected By :	
B0141354 > Karl Tuxhorn	**Date:** 2026-02-23

Sequence #	4509-8	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4432709	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2508727

4509-8	**WO #**	**4432709**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		No Log Entry	
7031/4509-REUPHOLSTER 1EA CL650-6111-LTSC LAV TOILET SEAT CUSHION				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	DO NOT WORK - CUSTOMER REQUEST. SEE NEW CSO WO# 4775718	B0599115 - Mark Fierro Feb 26, 2026 09:06 PM	
	7031/4509-REUPHOLSTER 1EA CL650-6111-LTSC LAV TOILET SEAT CUSHION		Not Required	

Sequence #	4509-9	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4432718	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2508727

4509-9	**WO #**	**4432718**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		No Log Entry	
7032/4509-REUPHOLSTER 1EA CL650-6111-LTBR BACKREST ASSY LAV TOILET				

OPERATIONAL DETAILS

	Operation # / **Operation Description**	**Corrective Action Long Description**	**Tech Sign Off** / **Insp Sign Off**	**ATA Code** / **Reason for Work**
	100	DO NOT WORK - CUSTOMER REQUEST.	B0599115 - Mark Fierro Feb 26, 2026 09:12 PM	
	7032/4509-REUPHOLSTER 1EA CL650-6111-LTBR BACKREST ASSY LAV TOILET		Not Required	

Bombardier

Sequence #	4509-10	Aircraft SN #	6111	MWPWO #	2498069
WO #	4432730	Aircraft Reg #	XA-SOL	Parent WO #	2508727

4509-10	WO #	4432730	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		No Log Entry	
7033/4509-REUPHOLSTER 1EA JS600A-(RH1) JUMPSEAT				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	DO NOT WORK - CUSTOMER REQUEST. SEE NEW CSO WO# 4701158	B0599115 - Mark Fierro Feb 26, 2026 09:17 PM	
	7033/4509-REUPHOLSTER 1EA JS600A-(RH1) JUMPSEAT		Not Required	

Bombardier

Sequence #	4510	Aircraft SN #	6111	MWPWO #	2498069
WO #	2508708	Aircraft Reg #	XA-SOL	Parent WO #	2498069

4510	WO #	2508708	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13276321	No Log Entry	
Interior - Replace aft baggage door flap (604/605/650)				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			25-50
	Perform replacing of the aft baggage door flap			
	200			25-50
	Perform burn coupon testing			
	300			25-50
	Record work accomplished			

CHILD WORK ORDER DETAILS

	WO #	Description	Corrective Action	AMENDED
4510-1	4432744	7034/4510-FABRICATE 1EA CL650-6111-BDF BAGGAGE DOOR FLAP		

Bombardier

Sequence #	4510-1	Aircraft SN #	6111	MWPWO #	2498069
WO #	4432744	Aircraft Reg #	XA-SOL	Parent WO #	2508708

4510-1	WO #	4432744	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		No Log Entry	
7034/4510-FABRICATE 1EA CL650-6111-BDF BAGGAGE DOOR FLAP				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	VERIFY COMPONENT/MATERIALS: 1) P/N: CL-84487-1110 CLASSIC WINTER NIGHT LEATHER, P.O.# 5002470194 2) P/N: 5003 DURASONIC, P.O.#5002412749 3) P/N: ENSOLITE FOAM 0.125", P.O.#5002451905		
	VERIFY COMPONENT/MATERIALS: 1) P/N:_____LEATHE P.O.# 2) P/N:_____, P.O.# 3) P/N: ENSOLITE FOAM 0.125", P.O.#			
	200			
	FABRICATE BAGGAGE COMPARTMENT FLAP ASSEMBLY USING EXISTING BAGGAGE COMPARTMENT FLAP AS TEMPLATE, STITCH PER ASTMD 6193 TYPE 301 IAW BAS00270032, SECTION 3.5, CABIN TYPICAL REPAIR PROCESS SPECIFICATIONS		Not Required	
	300			
	IDENTIFY BAGGACE COMPARTMENT FLAP, CSO SERVICE ORDER NUMBER, DATE IAW BAPS 144-005, SECTION 9.5.1.1, IDENTIFICATION OF AIRCRAFT PARTS AND ASSEMBLIES.		Not Required	
	400			
	VERIFY COMPLETED ASSEMBLY(S) IAW BAS00270032 REV (____).			

Sequence #	4511	Aircraft SN #	6111	MWPWO #	2498069
WO #	2508717	Aircraft Reg #	XA-SOL	Parent WO #	2498069

4511	WO #	2508717	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13276322	No Log Entry	
Interior - Recover AFT baggage storage compartment gross point (604/605/650)				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			25-50
	Perform recovering the AFT baggage storage compartment gross point			
	200			25-50
	Perform burn testing			

CHILD WORK ORDER DETAILS

	WO #	Description	Corrective Action	AMENDED
4511-1	4432765	7035/4511-RECOVER C6618APN BAGGAGE COMPARTMENT AS REQUIRED		

Sequence #	4511-1	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4432765	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2508717

4511-1	**WO #**	**4432765**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		No Log Entry	
7035/4511-RECOVER C6618APN BAGGAGE COMPARTMENT AS REQUIRED				

Sequence #	4511-1	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4432765	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2508717

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with: VERIFY MATERIAL/ COMPONENTS: 1) P/N: C6618APN-1 BAGGAGE COMPARTMENT ASSEMBLY, EXISTING 2) P/N: GPFR0015. TOBACO, TAPIS GROSPOINT, P.O.# 5002470191 3) P/N: 048011-98648 EC-1357 ADHESIVE, P.O.#5002405713		
	VERIFY MATERIAL/COMPONENTS: 1) P/N: C6618APN-1 BAGGAGE COMPARTMENT ASSEMBLY, EXISTING 2) P/N: GPFR0015. TOBACO, TAPIS GROSPOINT, P.O.# 3) P/N: 048011-98648 EC-1357 ADHESIVE, P.O.#			

Sequence #	4511-1	Aircraft SN #	6111	MWPWO #	2498069
WO #	4432765	Aircraft Reg #	XA-SOL	Parent WO #	2508717

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	200 RECOVER 1EA C6618APN-1 BAGGAGE COMPARTMENT PANELS LISTED BELOW IN CUSTOMER SELECTED MATERIALS. A) C661523-501 BAGGAGE BAY HEADLINER ASSY, LHS B) C661525-501 BAGGAGE BAY HEADLINER ASSY, MID C) C661521-501 BAGGAGE BAY HEADLINER ASSY, RHS D) C661512-503 RHS CLOSEOUT ASSY E) C661219-501 TOP SHELF ASSY F) C661219-505 BOTTOM SHELF ASSY G) C661506-501 BULKHEAD 619 ASSY H) C661218-501 CLOSEOUT PANEL ASSY - FWD BLKHD 589 I) C661218-503 CLOSEOUT PANEL ASSY - AFT BLKHD 62 J) C661218-549 COVER ASSY – DOOR COVER K) C661218-515 CLOSEOUT PANEL ASSY - FWD BLKHD 589 (7EA) L) C661218-525 CLOSEOUT PANEL ASSY - AFT BLKHD 621 (6EA) M) C661218-543 CLOSEOUT BOX ASSY (HEADLINER) N) C661218-541 CLOSEOUT BOX ASSY (CABLE) O) C661218-539 CLOSEOUT BOX ASSY (CABLE) STRIP MATERIAL AND CLEAN IAW BAS00270032 SECTION 3.2, CABIN TYPICAL REPAIR PROCESS SPECIFICATIONS.	Complied with: RECOVER 1EA C6618APN-1 BAGGAGE COMPARTMENT PANELS LISTED BELOW IN CUSTOMER SELECTED MATERIALS. A) C661523-501 BAGGAGE BAY HEADLINER ASSY, LHS B) C661525-501 BAGGAGE BAY HEADLINER ASSY, MID C) C661521-501 BAGGAGE BAY HEADLINER ASSY, RHS D) C661512-503 RHS CLOSEOUT ASSY E) C661219-501 TOP SHELF ASSY F) C661219-505 BOTTOM SHELF ASSY G) C661506-501 BULKHEAD 619 ASSY H) C661218-501 CLOSEOUT PANEL ASSY - FWD BLKHD 589 I) C661218-503 CLOSEOUT PANEL ASSY - AFT BLKHD 62 J) C661218-549 COVER ASSY – DOOR COVER K) C661218-515 CLOSEOUT PANEL ASSY - FWD BLKHD 589 (7EA) L) C661218-525 CLOSEOUT PANEL ASSY - AFT BLKHD 621 (6EA) M) C661218-543 CLOSEOUT BOX ASSY (HEADLINER) N) C661218-541 CLOSEOUT BOX ASSY (CABLE) O) C661218-539 CLOSEOUT BOX ASSY (CABLE) STRIP MATERIAL AND CLEAN IAW BAS00270032 SECTION 3.2 REV (B), CABIN TYPICAL REPAIR PROCESS SPECIFICATIONS.	Not Required	
	300 VERIFY FOAM/SUBSTRATE INTEGRITY IAW AC 43.13-1B PAR 5-18	Complied with: VERIFY FOAM/SUBSTRATE INTEGRITY IAW AC 43.13-1B PAR 5-18	Not Required	

Sequence #	4511-1	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4432765	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2508717

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	400	Complied with: RECOVER BAGGAGE COMPARTMENT BULKHEADS/POSTS/ SIDEWALLS/HEADLINERS/CLOSEOUTS/SHELFS IAW BAS00270032 SECTION 3.2 REV(B), CABIN TYPICAL REPAIR PROCESS SPECIFICATIONS.		
	RECOVER BAGGAGE COMPARTMENT BULKHEADS/POSTS/SIDEWALLS/HEADLINERS/ CLOSEOUTS/SHELFS IAW BAS00270032 SECTION 3.2, CABIN TYPICAL REPAIR PROCESS SPECIFICATIONS.		Not Required	
	500	Complied with: VERIFY COMPLETED ASSEMBLY(S) IAW BAS00270032 REV (B).		
	VERIFY COMPLETED ASSEMBLY(S) IAW BAS00270032 REV (____).			

QA005 RTS Statement

The component identified above was repaired and inspected in accordance with current Federal Aviation Regulations, found airworthy and is approved for return to service with respect to the work performed

Sequence #	4512	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	2583511	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

4512	**WO #**	**2583511**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #	13276331	No Log Entry	
Interior - Reupholster of 1ea. 3 place divan, excludes new foam (650)				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			25-00
	Perform reupholster of 1ea. 3 place divan, excludes new foam			
	200			25-00
	Interior access			

CHILD WORK ORDER DETAILS

	WO #	Description	Corrective Action	AMENDED
4512-1	4701047	7064-REUPHOLSTER 1EA 2523.559.01-46.22 DIVAN		

Sequence #	4512-1	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4701047	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2583511

4512-1	**WO #**	**4701047**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		No Log Entry	
7064-REUPHOLSTER 1EA 2523.559.01-46.22 DIVAN				

Sequence #	4512-1	Aircraft SN #	6111	MWPWO #	2498069
WO #	4701047	Aircraft Reg #	XA-SOL	Parent WO #	2583511

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with: VERIFY MATERIAL/ COMPONENTS: 1) P/N: 2523.559.01-46.22 DIVAN 3PL DIVAN ASSY, EXISTING 2) P/N: T23031 , 002, DEDAR MALLEMIGLIA FABRIC P.O.# 5002466357 3) P/N: CL-84487-1110, WINTER NIGHT, CLASSIC C/H TOWNSEND, P.O.#5002470194 4) P/N: SABGE 1.0 LOOP VELCRO, P.O.#5002440001 5) P/N: SABGE 1.0 HOOK VELCRO, P.O.#5002398986 6) P/N: RE-WEBBED DIVAN SEAT BELT, P.O.# 7) P/N: 048011-98648 EC-1357 ADHESIVE, P.O.#5002405713 8) P/N: 309 SIMALFA ADHESIVE, P.O.#5002451922		
	VERIFY MATERIAL/COMPONENTS: 1) P/N: 2523.559.01-46.22 DIVAN 3PL DIVAN ASSY, EXISTING 2) P/N: T23031 , 002, DEDAR MALLEMIGLIA FABRIC P.O.# 5002466357 3) P/N: CL-84487-1110, WINTER NIGHT, CLASSIC C/H TOWNSEND, P.O.#5002470194 4) P/N: SABGE 1.0 LOOP VELCRO, P.O.# 5) P/N: SABGE 1.0 HOOK VELCRO, P.O.# 6) P/N: RE-WEBBED DIVAN SEAT BELT, P.O.# 7) P/N: 048011-98648 EC-1357 ADHESIVE, P.O.#5002405713 8) P/N: 309 SIMALFA ADHESIVE, P.O.#5002451922			
	200	Complied with: DISASSEMBLE DIVAN ASSEMBLY IAW CMM 25-28-78 REV (B).		
	DISASSEMBLE DIVAN ASSEMBLY IAW		Not Required	
	300	Complied with: VERFIY SUBSTRATE INTEGRITY IAW AC 43.13-1B PAR 5-18		
	VERFIY SUBSTRATE INTEGRITY IAW AC 43.13-1B PAR 5-18		Not Required	
	400	Complied with: PAINT EXISTING DIVAN FRAME AND HARDWARE AS REQUIRED USING MATCHING JETFLEX PAINT APPLIED IAW MANUFACTURES INSTRUCIONS		
	PAINT EXISTING DIVAN FRAME AND HARDWARE AS REQUIRED USING MATCHING JETFLEX PAINT APPLIED IAW MANUFACTURES INSTRUCIONS		Not Required	
	500			
	UPHOLSTER EXISTING DIVAN CUSHIONS IAW ACES DWG		Not Required	
	600	Complied with: UPHOLSTER 2EA DIVAN END-CABINET ARMRESTS IAW BAS00270032, 3.2 REV(B).		
	UPHOLSTER 2EA DIVAN END-CABINET ARMRESTS IAW ACES DWG		Not Required	

Sequence #	4512-1	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4701047	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2583511

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	700	Complied with: REINSTALL SEAT BELTS IAW CMM 25-28-78 REV (B).		
	REINSTALL SEAT BELTS IAW CMM		Not Required	
	800	Complied with: RE-ASSEMBLE DIVAN ASSEMBLY IAW CMM 25-28-78 REV (B).		
	RE-ASSEMBLE DIVAN ASSEMBLY IAW CMM		Not Required	
	900	Complied with: VERIFY COMPLETED ASSEMBLY(S) IAW CMM 25-28-78 REV (B) & ACES DWG		
	VERIFY COMPLETED ASSEMBLY(S) IAW CMM & ACES DWG			

QA005 RTS Statement

The component identified above was repaired and inspected in accordance with current Federal Aviation Regulations, found airworthy and is approved for return to service with respect to the work performed

Bombardier

Sequence #	4513	Aircraft SN #	6111	MWPWO #	2498069
WO #	2508741	Aircraft Reg #	XA-SOL	Parent WO #	2498069

4513	WO #	2508741	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13276367	No Log Entry	
Interior - Install new solid surface countertops in galley and aft lavatory (604/605/650)				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			25-00
	C/W removal and installation of new solid surface countertops in galley and aft lavatory			
	200			25-00
	C/W engineering documentation support for installation of new solid countertops in galley and aft lavatoryC/W engineering documentation support for installation of new solid countertops in galley and aft			

CHILD WORK ORDER DETAILS

	WO #	Description	Corrective Action	AMENDED
4513-1	4717879	7065/4513-FABRICATE 1EA BASXXXXXX GALLEY COUNTERTOP IAW DWG BASXXXXXXX		
4513-2	4717880	7066/4513-FABRICATE 1EA BASXXXXXX LAV COUNTERTOP IAW DWG BASXXXXXXX		
4513-3	4717882	7067/4513-FABRICATE 1EA BASXXXXXX SINK TOP / CUTTING BOARD IAW DWG BASXXXXXXX		

Sequence #	4513-1	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4717879	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2508741

4513-1	**WO #**	**4717879**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		No Log Entry	
7065/4513-FABRICATE 1EA BASXXXXXX GALLEY COUNTERTOP IAW DWG BASXXXXXXX				

Sequence #	4513-2	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4717880	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2508741

4513-2	**WO #**	**4717880**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		No Log Entry	
7066/4513-FABRICATE 1EA BASXXXXXX LAV COUNTERTOP IAW DWG BASXXXXXXX				

Sequence #	4513-3	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4717882	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2508741

4513-3	**WO #**	**4717882**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		No Log Entry	
7067/4513-FABRICATE 1EA BASXXXXXX SINK TOP / CUTTING BOARD IAW DWG BASXXXXXXX				

Bombardier

Sequence #	4514	Aircraft SN #	6111	MWPWO #	2498069
WO #	2583835	Aircraft Reg #	XA-SOL	Parent WO #	2498069

4514	WO #	2583835	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13276385	No Log Entry	
Interior - Fabricate new night flying cockpit curtain (604/605/650)				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			25-00
	Remove and replace the night flying cockpit curtain			
	200			25-00
	Provide burn test coupons and conformity			

CHILD WORK ORDER DETAILS

	WO #	Description	Corrective Action	AMENDED
4514-1	4432879	Interior Refurb: CURTAIN - COCKPIT (FAB)		

Bombardier

Sequence #	4514-1	Aircraft SN #	6111	MWPWO #	2498069
WO #	4432879	Aircraft Reg #	XA-SOL	Parent WO #	2583835

4514-1	WO #	4432879	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		No Log Entry	
Interior Refurb: CURTAIN - COCKPIT (FAB)				
Task / IRN # : CURTAIN - COCKPIT (FAB)				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with: Comply with Preliminary Inspection		
	Comply with Preliminary Inspection			
	200	Complied with: VERIFY COMPONENT/ MATERIALS: 1) P/N: T23031, 002, DEDAR MILLEMIGLIA APPLICATORS PLUS FABRIC, P.O.#5002466357		
	VERIFY COMPONENT/MATERIALS: 1) P/N: T23031, 002, DEDAR MILLEMIGLIA APPLICATORS PLUS FABRIC, P.O.#			
	300	Complied with: FABRICATE NEW COCKPIT CURTAIN ASSEMBLY USING EXISTING CURTAIN AS TEMPLATE, STITCH PER ASTMD 6193 IAW BAS00270032,SECTION 3.5 REV(B), CABIN TYPICAL REPAIR PROCESS SPECIFICATIONS.		
	FABRICATE NEW COCKPIT CURTAIN ASSEMBLY USING EXISTING CURTAIN AS TEMPLATE, STITCH PER ASTMD 6193 IAW BAS00270032,SECTION 3.5, CABIN TYPICAL REPAIR PROCESS SPECIFICATIONS.		Not Required	
	400	Complied with: IDENTIFY COCKPIT CURTAIN, STRAP ASSEMBLY, CSO SERVICE ORDER NUMBER, DATE IAW BAPS 144-005, SECTION 9.5.1.1, IDENTIFICATION OF AIRCRAFT PARTS AND ASSEMBLIES.		
	IDENTIFY COCKPIT CURTAIN, STRAP ASSEMBLY, CSO SERVICE ORDER NUMBER, DATE IAW BAPS 144-005, SECTION 9.5.1.1, IDENTIFICATION OF AIRCRAFT PARTS AND ASSEMBLIES.		Not Required	
	500	Complied with: VERIFY COMPLETED ASSEMBLY(S) IAW BAS00270032 REV (B).		
	VERIFY COMPLETED ASSEMBLY(S) IAW BAS00270032 REV (____).			

Sequence #	4514-1	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4432879	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2583835

QA005 RTS Statement
The component identified above was repaired and inspected in accordance with current Federal Aviation Regulations, found airworthy and is approved for return to service with respect to the work performed

Bombardier

Sequence #	4515	Aircraft SN #	6111	MWPWO #	2498069
WO #	2508595	Aircraft Reg #	XA-SOL	Parent WO #	2498069

4515	WO #	2508595	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13275983	No Log Entry	
Interior - Recover entry door trim (604/605/650)				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			25-00
	Perform recovery of entry door trim			

CHILD WORK ORDER DETAILS

	WO #	Description	Corrective Action	AMENDED
4515-1	4432925	7037/4515-RECOVER CL650-6111-FTC FWD PAX DOOR FRAME TRIM CLOSEOUTS		
4515-2	4432944	7038/4514-RECOVER CL650-6111-ATC AFT PAX DOOR FRAME TRIM CLOSEOUTS		

Bombardier

Sequence #	4515-1	Aircraft SN #	6111	MWPWO #	2498069
WO #	4432925	Aircraft Reg #	XA-SOL	Parent WO #	2508595

4515-1	WO #	4432925	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		No Log Entry	
7037/4515-RECOVER CL650-6111-FTC FWD PAX DOOR FRAME TRIM CLOSEOUTS				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with: VERIFY MATERIAL/ COMPONENTS: 1) P/N: CL650-6111-FTC FWD PAX DOOR FRAME TRIM CLOSEOUTS, EXISTING 2) P/N: ULFR5684 ARTIC ULTRALEATHER, P.O.# 5002478132 3) P/N: 048011-98648 EC-1357 ADHESIVE, P.O.#5002405713		
	VERIFY MATERIAL/COMPONENTS: 1) P/N: CL650-6111-FTC FWD PAX DOOR FRAME TRIM CLOSEOUTS, EXISTING 2) P/N: ULFR5684 ARTIC ULTRALEATHER, P.O.# 3) P/N: 048011-98648 EC-1357 ADHESIVE, P.O.#			
	200	Complied with: STRIP MATERIAL AND CLEAN IAW BAS00270032 SECTION 3.2 REV(B), CABIN TYPICAL REPAIR PROCESS SPECIFICATIONS.		
	STRIP MATERIAL AND CLEAN IAW BAS00270032 SECTION 3.2, CABIN TYPICAL REPAIR PROCESS SPECIFICATIONS.		Not Required	
	300	Complied with: VERIFY FOAM /SUBSTRATE INTEGRITY IAW AC 43.13-1B PAR 5-18.		
	VERIFY FOAM /SUBSTRATE INTEGRITY IAW AC 43.13-1B PAR 5-18.		Not Required	
	400	Complied with: CONTACT BOND NEW MATERIAL USING EC-1357 ADHESIVE IAW BAS00270032 SECTION 3.2 REV(B), CABIN TYPICAL REPAIR PROCESS SPECIFICATIONS.		
	CONTACT BOND NEW MATERIAL USING EC-1357 ADHESIVE IAW BAS00270032 SECTION 3.2, CABIN TYPICAL REPAIR PROCESS SPECIFICATIONS.		Not Required	
	500	Complied with: VERIFY COMPLETED ASSEMBLY(S) IAW BAS00270032 REV (B).		
	VERIFY COMPLETED ASSEMBLY(S) IAW BAS00270032 REV (____).			

QA005 RTS Statement

Sequence #	4515-1	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4432925	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2508595

The component identified above was repaired and inspected in accordance with current Federal Aviation Regulations, found airworthy and is approved for return to service with respect to the work performed

Sequence #	4515-2	Aircraft SN #	6111	MWPWO #	2498069
WO #	4432944	Aircraft Reg #	XA-SOL	Parent WO #	2508595

4515-2	WO #	4432944	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		No Log Entry	
7038/4514-RECOVER CL650-6111-ATC AFT PAX DOOR FRAME TRIM CLOSEOUTS				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with: VERIFY MATERIAL/ COMPONENTS: 1) P/N: CL650-6111-ATC AFT PAX DOOR FRAME TRIM CLOSEOUTS, EXISTING 2) P/N: ULFR5684 ARTIC ULTRALEATHER, P.O.# 5002478132 3) P/N: 048011-98648 EC-1357 ADHESIVE, P.O.#5002405713		
	VERIFY MATERIAL/COMPONENTS: 1) P/N: CL650-6111-ATC AFT PAX DOOR FRAME TRIM CLOSEOUTS, EXISTING 2) P/N: ULFR5684 ARTIC ULTRALEATHER, P.O.# 3) P/N: 048011-98648 EC-1357 ADHESIVE, P.O.#			
	200	Complied with: STRIP MATERIAL AND CLEAN IAW BAS00270032 SECTION 3.2 REV(B), CABIN TYPICAL REPAIR PROCESS SPECIFICATIONS.		
	STRIP MATERIAL AND CLEAN IAW BAS00270032 SECTION 3.2, CABIN TYPICAL REPAIR PROCESS SPECIFICATIONS.		Not Required	
	300	Complied with: VERIFY FOAM /SUBSTRATE INTEGRITY IAW AC 43.13-1B PAR 5-18.		
	VERIFY FOAM /SUBSTRATE INTEGRITY IAW AC 43.13-1B PAR 5-18.		Not Required	
	400	Complied with: CONTACT BOND NEW MATERIAL USING EC-1357 ADHESIVE IAW BAS00270032 SECTION 3.2 REV(B), CABIN TYPICAL REPAIR PROCESS SPECIFICATIONS.		
	CONTACT BOND NEW MATERIAL USING EC-1357 ADHESIVE IAW BAS00270032 SECTION 3.2, CABIN TYPICAL REPAIR PROCESS SPECIFICATIONS.		Not Required	
	500	Complied with: VERIFY COMPLETED ASSEMBLY(S) IAW BAS00270032 REV (B).		
	VERIFY COMPLETED ASSEMBLY(S) IAW BAS00270032 REV (____).			

QA005 RTS Statement

Sequence #	4515-2	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4432944	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2508595

The component identified above was repaired and inspected in accordance with current Federal Aviation Regulations, found airworthy and is approved for return to service with respect to the work performed

Sequence #	4516	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	2508901	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

4516	**WO #**	**2508901**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #	13276333	No Log Entry	
Re-webb all passenger seat belts.				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	DO NOT WORK PER CUSTOMER REQUEST.	B0599115 - Mark Fierro Mar 02, 2026 07:05 PM	
	Re-webb all passenger seat belts.		Not Required	

Bombardier

Sequence #	4517	Aircraft SN #	6111	MWPWO #	2498069
WO #	4294264	Aircraft Reg #	XA-SOL	Parent WO #	2498069

4517	WO #	4294264	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13429569	No Log Entry	
*Interior- Recover Jump Seat and Lavatory potty seat lid. Include foam replacement.				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			25-00
	*Interior- Recover Jump Seat and Lavatory potty seat lid. Include foam replacement.			

CHILD WORK ORDER DETAILS

	WO #	Description	Corrective Action	AMENDED
4517-1	4701158	7065/4517-REUPHOLSTER 1EA JS600A-(RH1)JUMP SEAT		
4517-2	4775718	Interior Refurb: TOILET SEAT LID CUSHION (RECOVER)		

Sequence #	4517-1	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4701158	**Aircraft Reg #**	XA-SOL	**Parent WO #**	4294264

4517-1	**WO #**	**4701158**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		No Log Entry	
7065/4517-REUPHOLSTER 1EA JS600A-(RH1)JUMP SEAT				

Sequence #	4517-1	Aircraft SN #	6111	MWPWO #	2498069
WO #	4701158	Aircraft Reg #	XA-SOL	Parent WO #	4294264

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100 VERIFY MATERIAL/COMPONENTS: 1) P/N: JS600A-(RH1)JUMP SEAT ASSEMBLY, EXISTING 2) P/N: _____LEATHER, P.O.# 3) P/N:_____FOAM, P.O.# 4) P/N:_____FOAM, P.O.# 5) P/N: RE-WEBBED SEAT BELT, P.O.# 6) P/N: 048011-98648 EC-1357 ADHESIVE, P.O.#	VERIFY MATERIAL/COMPONENTS: 1) P/N: JS600A-(RH1)JUMP SEAT ASSEMBLY, EXISTING 2) P/N: A206 GARRETT AVION HAZE LEATHER, P.O.#5002481654 3) P/N: DAX55 1.0 FOAM, P.O.#5002480008 4) P/N:_____NA_____FOAM, P.O.# 5) P/N: RE-WEBBED SEAT BELT, P.O.# 6) P/N: 048011-98648 EC-1357 ADHESIVE, P.O.#5002405713		
	200 STRIP SEAT MATERIALS IAW DECRANE CMM_____AND CLEAN FRAME, DISCARD OLD SEAT CUSHIONS	Complied with: STRIP SEAT MATERIALS IAW PAC CMM 25-20-01 REV(IR) AND CLEAN FRAME, DISCARD OLD SEAT CUSHIONS	Not Required	
	300 VERIFY SUBSTRATE INTEGRITY IAW AC 43.13-1B PAR 5-18.	Complied with: VERIFY SUBSTRATE INTEGRITY IAW AC 43.13-1B PAR 5-18.		
	400 FABRICATE NEW JUMP SEAT CUSHIONS AND UPHOLSTER IAW ACES DWG	Complied with: FABRICATE NEW JUMP SEAT CUSHIONS AND UPHOLSTER IAW ACES DWG: CH600-010011 REV(IR)	Not Required	
	500 RE-INSTALL SEAT BELT ASSEMBLY IAW DECRANE CMM	Complied with: RE-INSTALL SEAT BELT ASSEMBLY IAW PAC CMM 25-20-01 REV(IR).	Not Required	
	600 RE-ASSEMBLE JUMP SEAT ASSEMBLY IAW DECRANE CMM	Complied with: RE-ASSEMBLE JUMP SEAT ASSEMBLY IAW PAC CMM 25-20-01 REV(IR).	Not Required	

Sequence #	4517-1	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4701158	**Aircraft Reg #**	XA-SOL	**Parent WO #**	4294264

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	700	Complied with: VERIFY COMPLETED ASSEMBLY(S) IAW PAC CMM 25-20-01 REV(IR).		
	VERIFY COMPLETED ASSEMBLY(S) IAW DECRANE CMM_____REV (__).			

QA005 RTS Statement

The component identified above was repaired and inspected in accordance with current Federal Aviation Regulations, found airworthy and is approved for return to service with respect to the work performed

Sequence #	4517-2	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4775718	**Aircraft Reg #**	XA-SOL	**Parent WO #**	4294264

4517-2	**WO #**	**4775718**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		No Log Entry	
Interior Refurb: TOILET SEAT LID CUSHION (RECOVER)				
Task / IRN # : TOILET SEAT LID CUSHION (RECOV				

Bombardier

Sequence #	4517-2	Aircraft SN #	6111	MWPWO #	2498069
WO #	4775718	Aircraft Reg #	XA-SOL	Parent WO #	4294264

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with: Comply with Preliminary Inspection		
	Comply with Preliminary Inspection			
	200	VERIFY MATERIAL/COMPONENTS: 1) P/N: CL604-6111-LTS LAV TOILET SEAT CUSHION, EXISTING 2) P/N: A206 GARRETT AVION HAZE LEATHER P.O.#5002481654 3) P/N: SKF6231.25 RUBATEX FOAM, P.O.# 4) P/N: DAX55 .5 FOAM, P.O.# 5) P/N: 048011-98648 EC-1357 ADHESIVE, P.O.#5002405713 6) P/N:_____NA____LOOP, P.O.# 7) P/N:_____NA____HOOK, P.O.#		
	VERIFY MATERIAL/COMPONENTS: 1) P/N: CL604-6111-LTS LAV TOILET SEAT CUSHION, EXISTING 2) P/N:_____LEATHER P.O.# 3) P/N:_____FOAM, P.O.# 4) P/N:_____FOAM, P.O.# 5) P/N: 048011-98648 EC-1357 ADHESIVE, P.O.# 6) P/N:_____LOOP, P.O.# 7) P/N:_____HOOK, P.O.#			
	300			
	STRIP MATERIAL AND CLEAN SUBSTRATE IAW BAS00270032 SECTION 3.2, CABIN TYPICAL REPAIR PROCESS SPECIFICATIONS.		Not Required	
	400			
	VERIFY SUBSTRATE INTEGRITY IAW AC 43.13-1B PAR 5-18.			
	500			
	CONTACT BOND NEW SEAT MATERIAL USING EC-1357 ADHESIVE IAW BAS00270032 SECTION 3.2,CABIN TYPICAL REPAIR PROCESS SPECIFICATIONS.		Not Required	
	600			
	VERIFY COMPLETED ASSEMBLY(S) IAW BAS00270032 REV (____).			

QA005 RTS Statement

Sequence #	4517-2	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4775718	**Aircraft Reg #**	XA-SOL	**Parent WO #**	4294264

The component identified above was repaired and inspected in accordance with current Federal Aviation Regulations, found airworthy and is approved for return to service with respect to the work performed

Sequence #	4518	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4717709	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

4518	**WO #**	**4717709**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #	13493852	No Log Entry	
4518-C/W FAR 25.853(A) MINOR BURN REQUIREMENT				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			
	4518-C/W FAR 25.853(A) MINOR BURN REQUIREMENT			

Bombardier

Sequence #	4519	Aircraft SN #	6111	MWPWO #	2498069
WO #	4717714	Aircraft Reg #	XA-SOL	Parent WO #	2498069

4519	WO #	4717714	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13493829	No Log Entry	
4519-C/W C BURN DATA REQUIREMENT				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			
	4519-C/W C BURN DATA REQUIREMENT			

Sequence #	4520	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4719407	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

4520	**WO #**	**4719407**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #	13493995	No Log Entry	
4520-C/W ACES SLIP TEST REQUIREMENT				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			
	4520-C/W ACES SLIP TEST REQUIREMENT			

Bombardier

Sequence #	5001	Aircraft SN #	6111	MWPWO #	2498069
WO #	2530186	Aircraft Reg #	XA-SOL	Parent WO #	2498069

5001	WO #	2530186	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13276332	No Log Entry	
Paint - Standard strip and repaint - A single color base, two stripes, non-metallic (601/604/605/650)				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			20-00
	Engineering Support			
	200			20-00
	Perform Paint			
	300			20-00
	Perform Top Charge of Batteries			
	400	Complied with Pre-Paint Bond Checks of Aircraft #6111 save for the Bond Check of the Nose Radome Diverter Strips IAW CL650 SPM 51-80-00-760-801. Bond Checks “Good.” No Findings Noted.	K1019185 - Michael Perkin Feb 14, 2026 07:50 PM	20-00
	Perform Bonding Checks		B0142244 - Todd Bridges Feb 14, 2026 08:02 PM	
	401			
	Perform Bonding Checks of Nose Radome Diverter Strips.			
	500			20-00
	Perform Stair tread remove/replacement			
	600			20-00
	Perform Pre/Post Paint Support			

TOOL INFORMATION

Tool ID	Tool Description	Calibration Due Date
TUSS0607	Bond Checker	Jan 30, 2027 5:00 PM

Sequence #	5002	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	2526984	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

5002	**WO #**	**2526984**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #	13276334	No Log Entry	
Paint - Standard strip and repaint - Pre/post paint support (300/350/650)				

Bombardier

Sequence #	5002	Aircraft SN #	6111	MWPWO #	2498069
WO #	2526984	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Duplicate WO see WO: 4755078 for Work Performed.	B0162034 - Tyler Poggi Feb 11, 2026 10:59 PM	20-00
	C/W Pre Paint Support		B0161691 - Thomas Mitchell Feb 14, 2026 04:28 AM	
	200	Duplicate WO see WO: 4755078 for Work Performed.	B0162034 - Tyler Poggi Feb 11, 2026 10:59 PM	20-00
	C/W Post Paint Support		B0161691 - Thomas Mitchell Feb 14, 2026 04:28 AM	
	300	Duplicate WO see WO: 4755078 for Work Performed.	B0162034 - Tyler Poggi Feb 11, 2026 10:59 PM	20-00
	C/W Pre/Post Paint Support (FT/QA)		B0161691 - Thomas Mitchell Feb 14, 2026 04:28 AM	
	400	Duplicate WO see WO: 4755078 for Pre/Post Paint Support and Work Performed	B0143806 - Alejandro Cabanillas Mar 06, 2026 04:24 PM	20-00
	C/W AMM Task 27-52-00-710-802 - Pre-Paint, Ensure Flap Control Surfaces are at 30 Degrees Prior to Delivery to Paint Shop		B1013522 - Brandon Jennings Mar 06, 2026 05:09 PM	
	500	Duplicate WO see WO: 4755078 for Pre/Post Paint Support and Work Performed	B0143806 - Alejandro Cabanillas Mar 06, 2026 04:24 PM	20-00
	C/W AMM Task 33-51-05-000-801 - Check with Customer to see if Wing Inspection Lenses will be Polished or Painted		B1013522 - Brandon Jennings Mar 06, 2026 05:09 PM	
	600	Duplicate WO see WO: 4755078 for Pre/Post Paint Support and Work Performed	B0143806 - Alejandro Cabanillas Mar 06, 2026 04:24 PM	20-00
	C/W AMM Task 33-51-01-000-801 - Check with Customer to see if Passenger-Door Emergency Light will be Polished or Painted		B1013522 - Brandon Jennings Mar 06, 2026 05:09 PM	

Sequence #	5002	Aircraft SN #	6111	MWPWO #	2498069
WO #	2526984	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	700	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 pre/ post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 06, 2026 04:24 PM	20-00
	C/W AMM Task 52-45-01-000-801 - Check with Customer to see if the Kidney Panels 141AL, 141BL, 142AR, and 142BL on the Forward end of the Fuselage will have the Fastener Surrounds Painted or Polished. If the Surrounds are to be Polished, Leave all Kidney Panels and Fasteners Installed. If they are to be Painted, Remove Kidney Panels for Paint and have the Screws Painted Separately		B1013522 - Brandon Jennings Mar 06, 2026 05:09 PM	
	800	Duplicate WO see WO: 4755078 for Pre/Post Paint Support and Work Performed	B0143806 - Alejandro Cabanillas Mar 06, 2026 04:24 PM	20-00
	C/W Pre-Paint - AMM Task 52-11-29-220-801 - Detailed Inspection of the Passenger Door Seal. If the Door Seal requires removal do so per AMM Task 52-11-29-000-801 - Removal of the Passenger Door Seal and AMM Task 52-11-29-400-801 Installation of the Passenger Door Seal.		B1013522 - Brandon Jennings Mar 06, 2026 05:09 PM	
	900	Duplicate WO see WO: 4755078 for Pre/Post Paint Support and Work Performed	B0143806 - Alejandro Cabanillas Mar 06, 2026 04:24 PM	20-00
	C/W Post-Paint - AMM Task 52-11-29-220-801 - Detailed Inspection of the Passenger Door Seal. If the Door Seal requires removal do so per AMM Task 52-11-29-000-801 - Removal of the Passenger Door Seal and AMM Task 52-11-29-400-801 Installation of the Passenger Door Seal.		B1013522 - Brandon Jennings Mar 06, 2026 05:09 PM	

Sequence #	5002	Aircraft SN #	6111	MWPWO #	2498069
WO #	2526984	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	1000	Duplicate WO see WO: 4755078 for Pre/Post Paint Support and Work Performed	B0143806 - Alejandro Cabanillas Mar 06, 2026 04:24 PM	20-00
	C/W Pre-Paint - AMM Task 52-31-09-220-801 - Detailed Inspection of the Baggage Bay Door Seal. If the Door Seal requires removal do so per AMM Task 52-31-09-000-801 - Removal of the Baggage Door Seal and AMM Task 52-11-29-400-801 Installation of the Passenger Door Seal.		B1013522 - Brandon Jennings Mar 06, 2026 05:09 PM	
	1100	Duplicate WO see WO: 4755078 for Pre/Post Paint Support and Work Performed	B0143806 - Alejandro Cabanillas Mar 06, 2026 04:24 PM	20-00
	C/W Post-Paint - AMM Task 52-31-09-220-801 - Detailed Inspection of the Baggage Bay Door Seal. If the Door Seal requires removal do so per AMM Task 52-31-09-000-801 - Removal of the Baggage Door Seal and AMM Task 52-11-29-400-801 Installation of the Passenger Door Seal.		B1013522 - Brandon Jennings Mar 06, 2026 05:09 PM	
	1200	Duplicate WO see WO: 4755078 for Pre/Post Paint Support and Work Performed	B0143806 - Alejandro Cabanillas Mar 06, 2026 04:24 PM	20-00
	C/W AMM Task 52-21-01-000-801 Removal of the Over-Wing Emergency Exit Door-Removal/Installation		B1013522 - Brandon Jennings Mar 06, 2026 05:09 PM	
	1300	Duplicate WO see WO: 4755078 for Pre/Post Paint Support and Work Performed	B0143806 - Alejandro Cabanillas Mar 06, 2026 04:24 PM	20-00
	C/W (Pre-Paint) AMM Task 52-21-09-220-801 - Detailed Inspection of the Over - Wing Emergency - Exit Seal		B1013522 - Brandon Jennings Mar 06, 2026 05:09 PM	
	1400	Duplicate WO see WO: 4755078 for Pre/Post Paint Support and Work Performed	B0143806 - Alejandro Cabanillas Mar 06, 2026 04:24 PM	20-00
	C/W (Post-Paint) AMM Task 52-21-09-220-801 - Detailed Inspection of the Over - Wing Emergency - Exit Seal		B1013522 - Brandon Jennings Mar 06, 2026 05:09 PM	

Sequence #	5002	Aircraft SN #	6111	MWPWO #	2498069
WO #	2526984	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	1500	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft only.	B0143806 - Alejandro Cabanillas Feb 27, 2026 06:49 PM	20-00
	C/W AMM Task 57-33-01-000-801 - (LH) Removal of the Winglet Lenses - Wing Tip (541AT)		B1013522 - Brandon Jennings Feb 27, 2026 07:06 PM	
	1501	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 operation 4,000 for work performed.	B0143806 - Alejandro Cabanillas Feb 27, 2026 08:15 PM	
	C/W AMM Task 57-33-01-000-801 - (LH) Removal of the Winglet Lenses - Wing Tip (541AT)		B1013522 - Brandon Jennings Feb 27, 2026 08:31 PM	09
	1600	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft only.	B0143806 - Alejandro Cabanillas Feb 27, 2026 06:49 PM	20-00
	C/W AMM Task 57-33-01-000-801 - (RH) Removal of the Winglet Lenses - Wing Tip (641AT)		B1013522 - Brandon Jennings Feb 27, 2026 07:06 PM	
	1601	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 operation 4,200 for work performed.	B0143806 - Alejandro Cabanillas Feb 27, 2026 08:15 PM	
	C/W AMM Task 57-33-01-000-801 - (RH) Removal of the Winglet Lenses - Wing Tip (641AT)		B1013522 - Brandon Jennings Feb 27, 2026 08:31 PM	09
	1700	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft only.	B0143806 - Alejandro Cabanillas Feb 27, 2026 06:49 PM	20-00
	C/W AMM Task 57-33-01-400-801 - (LH) Installation of the Winglet Lenses - Wing Tip (541AT)		B1013522 - Brandon Jennings Feb 27, 2026 07:06 PM	
	1800	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft only.	B0143806 - Alejandro Cabanillas Feb 27, 2026 06:49 PM	20-00
	C/W AMM Task 57-33-01-400-801 - (RH) Installation of the Winglet Lenses - Wing Tip (641AT)		B1013522 - Brandon Jennings Feb 27, 2026 07:06 PM	
	1801	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 operation 4,300 for work performed.	B0143806 - Alejandro Cabanillas Feb 27, 2026 08:15 PM	
	C/W AMM Task 57-33-01-400-801 - (RH) Installation of the Winglet Lenses - Wing Tip (641AT)		B1013522 - Brandon Jennings Feb 27, 2026 08:31 PM	09

Sequence #	5002	Aircraft SN #	6111	MWPWO #	2498069
WO #	2526984	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	1900	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft.	B0143806 - Alejandro Cabanillas Feb 27, 2026 06:49 PM	20-00
	C/W AMM Task 33-41-17-000-801 - (LH) - Removal of the Landing Light Cover		B1013522 - Brandon Jennings Feb 27, 2026 07:06 PM	
	1901	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 for pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 05:04 PM	
	C/W AMM Task 33-41-17-000-801 - (LH) - Removal of the Landing Light Cover		B0142491 - George Ambrose Mar 05, 2026 07:34 PM	09
	2000	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft.	B0143806 - Alejandro Cabanillas Feb 27, 2026 06:49 PM	20-00
	C/W AMM Task 33-41-17-000-801 - (RH) - Removal of the Landing Light Cover		B1013522 - Brandon Jennings Feb 27, 2026 07:06 PM	
	2001	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 for pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 05:04 PM	
	C/W AMM Task 33-41-17-000-801 - (RH) - Removal of the Landing Light Cover		B0142491 - George Ambrose Mar 05, 2026 07:34 PM	09
	2100	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 for pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 05:04 PM	20-00
	C/W AMM Task 33-41-17-400-801 - (LH) - Installation of the Landing Light Cover		B0142491 - George Ambrose Mar 05, 2026 07:28 PM	
	2200	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 for pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 05:04 PM	20-00
	C/W AMM Task 33-41-17-400-801 - (RH) - Installation of the Landing Light Cover		B0142491 - George Ambrose Mar 05, 2026 07:28 PM	
	2300	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 operation 6,100 for work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 02:45 PM	20-00
	C/W AMM Task 33-45-01-000-801 - (LH) - Removal of the Wing Inspection Light		B1013522 - Brandon Jennings Mar 05, 2026 03:22 PM	

Sequence #	5002	Aircraft SN #	6111	MWPWO #	2498069
WO #	2526984	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	2400	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 operation 6,200 for work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 02:45 PM	20-00
	C/W AMM Task 33-45-01-400-801 - (LH) - Installation of the Wing Inspection Light		B1013522 - Brandon Jennings Mar 05, 2026 03:22 PM	
	2500	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 operation 6,300 for work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 02:45 PM	20-00
	C/W AMM Task 33-45-01-000-801 - (RH) - Removal of the Wing Inspection Light		B1013522 - Brandon Jennings Mar 05, 2026 03:22 PM	
	2600	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 operation 6,400 for work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 02:45 PM	20-00
	C/W AMM Task 33-45-01-400-801 - (RH) - Installation of the Wing Inspection Light		B1013522 - Brandon Jennings Mar 05, 2026 03:22 PM	
	2700	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 operation 6,701 for work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 02:45 PM	20-00
	C/W AMM Task 33-51-01-000-801 - Removal of the Passenger - Door Emergency Light		B1013522 - Brandon Jennings Mar 05, 2026 03:22 PM	
	2800	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 operation 6,800 for work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 02:45 PM	20-00
	C/W AMM Task 33-51-01-400-801 - Installation of the Passenger - Door Emergency Light		B1013522 - Brandon Jennings Mar 05, 2026 03:22 PM	
	2900	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 operation 6,800 for work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 02:45 PM	20-00
	C/W AMM Task 33-51-01-400-801 - Installation of the Passenger - Door Emergency Light		B1013522 - Brandon Jennings Mar 05, 2026 03:22 PM	
	3000	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 operation 6,900 for work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 02:45 PM	20-00
	C/W AMM Task 33-51-05-000-801 (RH Forward) Removal of the Over - Wing Emergency - Exit Light		B1013522 - Brandon Jennings Mar 05, 2026 03:22 PM	

Sequence #	5002	Aircraft SN #	6111	MWPWO #	2498069
WO #	2526984	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	3100	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 operation 7,000 for work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 02:45 PM	20-00
	C/W AMM Task 33-51-05-400-801 (RH Forward) Installation of the Over - Wing Emergency - Exit Light		B1013522 - Brandon Jennings Mar 05, 2026 03:22 PM	
	3200	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 operation 7,100 for work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 02:45 PM	20-00
	C/W AMM Task 33-51-05-000-801 (RH Aft) Removal of the Over - Wing Emergency - Exit Light		B1013522 - Brandon Jennings Mar 05, 2026 03:22 PM	
	3300	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 operation 7,200 for work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 02:45 PM	20-00
	C/W AMM Task 33-51-05-400-801 (RH Aft) Installation of the Over - Wing Emergency - Exit Light		B0142491 - George Ambrose Mar 05, 2026 07:28 PM	
	3400	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 for pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 05:04 PM	20-00
	C/W AMM Task 33-31-09-000-801 - Removal of the Baggage - Compartment External Light		B0142491 - George Ambrose Mar 05, 2026 07:28 PM	
	3500	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 for pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 05:04 PM	20-00
	C/W AMM Task 33-31-09-400-801 - Installation of the Baggage - Compartment External Light		B0142491 - George Ambrose Mar 05, 2026 07:28 PM	
	3600	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 operation 1,200 for work performed.	B0143806 - Alejandro Cabanillas Mar 04, 2026 08:12 PM	20-00
	C/W AMM Task 23-61-01-000-801 (LH Winglet) - Removal of the Static Discharger		B1013522 - Brandon Jennings Mar 04, 2026 08:52 PM	
	3700	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 operation 1,300 for work performed.	B0143806 - Alejandro Cabanillas Mar 04, 2026 08:12 PM	20-00
	C/W AMM Task 23-61-01-400-801 (LH Winglet) - Installation of the Static Discharger		B1013522 - Brandon Jennings Mar 04, 2026 08:52 PM	

Sequence #	5002	Aircraft SN #	6111	MWPWO #	2498069
WO #	2526984	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	3800	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 operation 1,400 for work performed.	B0143806 - Alejandro Cabanillas Mar 04, 2026 08:12 PM	20-00
	C/W AMM Task 23-61-01-000-801 (RH Winglet) - Removal of the Static Discharger		B1013522 - Brandon Jennings Mar 04, 2026 08:52 PM	
	3900	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 operation 1,500 for work performed.	B0143806 - Alejandro Cabanillas Mar 04, 2026 08:12 PM	20-00
	C/W AMM Task 23-61-01-400-801 (RH Winglet) - Installation of the Static Discharger		B1013522 - Brandon Jennings Mar 04, 2026 08:52 PM	
	4000	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 operation 800 for work performed.	B0143806 - Alejandro Cabanillas Mar 04, 2026 08:12 PM	20-00
	C/W AMM Task 23-61-01-000-801 (LH Aileron) - Removal of the Static Discharger		B1013522 - Brandon Jennings Mar 04, 2026 08:52 PM	
	4100	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 operation 900 for work performed.	B0143806 - Alejandro Cabanillas Mar 04, 2026 08:12 PM	20-00
	C/W AMM Task 23-61-01-400-801 (LH Aileron) - Installation of the Static Discharger		B1013522 - Brandon Jennings Mar 04, 2026 08:52 PM	
	4200	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 operation 1,000 for work performed.	B0143806 - Alejandro Cabanillas Mar 04, 2026 08:12 PM	20-00
	C/W AMM Task 23-61-01-000-801 (RH Aileron) - Removal of the Static Discharger		B1013522 - Brandon Jennings Mar 04, 2026 08:52 PM	
	4300	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 operation 1,100 for work performed.	B0143806 - Alejandro Cabanillas Mar 04, 2026 08:12 PM	20-00
	C/W AMM Task 23-61-01-400-801 (RH Aileron) - Installation of the Static Discharger		B1013522 - Brandon Jennings Mar 04, 2026 08:52 PM	
	4400	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 operation 1,600 for work performed.	B0143806 - Alejandro Cabanillas Mar 04, 2026 08:12 PM	20-00
	C/W AMM Task 23-61-01-000-801 (LH Elevator) - Removal of the Static Discharger		B1013522 - Brandon Jennings Mar 04, 2026 08:52 PM	

Sequence #	5002	Aircraft SN #	6111	MWPWO #	2498069
WO #	2526984	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	4500	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 operation 1,700 for work performed.	B0143806 - Alejandro Cabanillas Mar 04, 2026 08:12 PM	20-00
	C/W AMM Task 23-61-01-400-801 (LH Elevator) - Installation of the Static Discharger		B1013522 - Brandon Jennings Mar 04, 2026 08:52 PM	
	4600	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 operation 1,800 for work performed.	B0143806 - Alejandro Cabanillas Mar 04, 2026 08:12 PM	20-00
	C/W AMM Task 23-61-01-000-801 (RH Elevator) - Removal of the Static Discharger		B1013522 - Brandon Jennings Mar 04, 2026 08:52 PM	
	4700	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 operation 1,900 for work performed.	B0143806 - Alejandro Cabanillas Mar 04, 2026 08:12 PM	20-00
	C/W AMM Task 23-61-01-400-801 (RH Elevator) - Installation of the Static Discharger		B1013522 - Brandon Jennings Mar 04, 2026 08:52 PM	
	4800	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 operation 2,000 for work performed.	B0143806 - Alejandro Cabanillas Mar 04, 2026 08:12 PM	20-00
	C/W AMM Task 23-61-01-000-801 (Rudder) - Removal of the Static Discharger		B1013522 - Brandon Jennings Mar 04, 2026 08:52 PM	
	4900	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 operation 13,600 for work performed.	B0143806 - Alejandro Cabanillas Mar 04, 2026 08:12 PM	20-00
	C/W AMM Task 23-61-01-400-801 (Rudder) - Installation of the Static Discharger		B1013522 - Brandon Jennings Mar 04, 2026 08:52 PM	
	5000	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 operation 2,100 for work performed.	B0143806 - Alejandro Cabanillas Mar 04, 2026 08:12 PM	20-00
	C/W AMM Task 23-61-01-000-801 (Lower Tailcone) - Removal of the Static Discharger		B1013522 - Brandon Jennings Mar 04, 2026 08:52 PM	
	5100	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 operation 12,700 for work performed.	B0143806 - Alejandro Cabanillas Mar 04, 2026 08:12 PM	20-00
	C/W AMM Task 23-61-01-400-801 (Lower Tailcone) - Installation of the Static Discharger		B1013522 - Brandon Jennings Mar 04, 2026 08:52 PM	

Sequence #	5002	Aircraft SN #	6111	MWPWO #	2498069
WO #	2526984	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	5200	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 operation 2,200 for work performed.	B0143806 - Alejandro Cabanillas Mar 04, 2026 08:12 PM	20-00
	C/W AMM Task 23-61-01-000-801 (V-Stab Tailcone) - Removal of the Static Discharger		B1013522 - Brandon Jennings Mar 04, 2026 08:52 PM	
	5300	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 operation 12,800 for work performed.	B0143806 - Alejandro Cabanillas Mar 04, 2026 08:12 PM	20-00
	C/W AMM Task 23-61-01-400-801 (V-Stab Tailcone) - Installation of the Static Discharger		B1013522 - Brandon Jennings Mar 04, 2026 08:52 PM	
	5400	See WO 4755078 operation 13,700 pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 08:48 PM	20-00
	C/W AMM Task 23-61-01-720-801 - (LH Winglet) - Functional Test of the Static Dischargers (Post Paint)		B1013522 - Brandon Jennings Mar 06, 2026 02:38 PM	
	5500	See WO 4755078 operation 13,700 pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 08:48 PM	20-00
	C/W AMM Task 23-61-01-720-801 - (RH Winglet) - Functional Test of the Static Dischargers (Post Paint)		B1013522 - Brandon Jennings Mar 06, 2026 02:38 PM	
	5600	See WO 4755078 operation 13,700 pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 08:48 PM	20-00
	C/W AMM Task 23-61-01-720-801 - (LH Aileron) - Functional Test of the Static Dischargers (Post Paint)		B1013522 - Brandon Jennings Mar 06, 2026 02:38 PM	
	5700	See WO 4755078 operation 13,700 pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 08:48 PM	20-00
	C/W AMM Task 23-61-01-720-801 - (RH Aileron) - Functional Test of the Static Dischargers (Post Paint)		B1013522 - Brandon Jennings Mar 06, 2026 02:38 PM	
	5800	See WO 4755078 operation 13,700 pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 08:48 PM	20-00
	C/W AMM Task 23-61-01-720-801 - (LH Elevator) - Functional Test of the Static Dischargers (Post Paint)		B1013522 - Brandon Jennings Mar 06, 2026 02:38 PM	

Sequence #	5002	Aircraft SN #	6111	MWPWO #	2498069
WO #	2526984	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	5900	See WO 4755078 operation 13,700 pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 08:48 PM	
	C/W AMM Task 23-61-01-720-801 - (RH Elevator) - Functional Test of the Static Dischargers (Post Paint)		B1013522 - Brandon Jennings Mar 06, 2026 02:38 PM	
	6000	See WO 4755078 operation 13,700 pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 08:48 PM	20-00
	C/W AMM Task 23-61-01-720-801 - (Rudder) - Functional Test of the Static Dischargers (Post Paint)		B1013522 - Brandon Jennings Mar 06, 2026 02:38 PM	
	6100	See WO 4755078 operation 13,700 pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 08:48 PM	20-00
	C/W AMM Task 23-61-01-720-801 - (Lower Tailcone) - Functional Test of the Static Dischargers (Post Paint)		B1013522 - Brandon Jennings Mar 06, 2026 02:38 PM	
	6200	See WO 4755078 operation 13,700 pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 08:48 PM	20-00
	C/W AMM Task 23-61-01-720-801 - (V-Stab Tailcone) - Functional Test of the Static Dischargers (Post Paint)		B1013522 - Brandon Jennings Mar 06, 2026 02:38 PM	
	6300	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 for pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 07:07 PM	20-00
	C/W AMM Task 28-23-01-000-801 - Removal of the Refuel/Defuel Control Panel		B0142491 - George Ambrose Mar 05, 2026 07:28 PM	
	6400	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 for pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 07:07 PM	20-00
	C/W AMM Task 28-23-01-400-801 - Installation of the Refuel/Defuel Control Panel		B0142491 - George Ambrose Mar 05, 2026 07:28 PM	
	6500	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 for pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 07:07 PM	20-00
	C/W AMM Task 28-23-01-710-801 - (Post Paint) - Operational Test of the Refuel/Defuel Control Panel		B0142491 - George Ambrose Mar 05, 2026 07:28 PM	

Sequence #	5002	Aircraft SN #	6111	MWPWO #	2498069
WO #	2526984	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	6600	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 for pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 07:07 PM	20-00
	C/W AMM Task 57-41-11-000-801 - LH Outboard Removal of the Leading Edge Vortillon		B0142491 - George Ambrose Mar 05, 2026 07:28 PM	
	6700	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 for pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 07:07 PM	20-00
	C/W AMM Task 57-41-11-400-801 - LH Outboard Installation of the Leading Edge Vortillon		B0142491 - George Ambrose Mar 05, 2026 07:28 PM	
	6800	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 for pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 07:07 PM	20-00
	C/W AMM Task 57-41-11-000-801 - LH Mid Removal of the Leading Edge Vortillon		B0142491 - George Ambrose Mar 05, 2026 07:29 PM	
	6900	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 for pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 07:07 PM	20-00
	C/W AMM Task 57-41-11-400-801 - LH Mid Installation of the Leading Edge Vortillon		B0142491 - George Ambrose Mar 05, 2026 07:29 PM	
	7000	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 for pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 07:07 PM	20-00
	C/W AMM Task 57-41-11-000-801 - LH Inboard Removal of the Leading Edge Vortillon		B0142491 - George Ambrose Mar 05, 2026 07:29 PM	
	7100	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 for pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 07:07 PM	20-00
	C/W AMM Task 57-41-11-400-801 - LH Inboard Installation of the Leading Edge Vortillon		B0142491 - George Ambrose Mar 05, 2026 07:29 PM	
	7200	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 for pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 07:07 PM	20-00
	C/W AMM Task 57-41-11-000-801 - RH Outboard Removal of the Leading Edge Vortillon		B0142491 - George Ambrose Mar 05, 2026 07:29 PM	

Sequence #	5002	Aircraft SN #	6111	MWPWO #	2498069
WO #	2526984	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	7300	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 for pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 07:07 PM	20-00
	C/W AMM Task 57-41-11-400-801 - RH Outboard Installation of the Leading Edge Vortillon		B0142491 - George Ambrose Mar 05, 2026 07:29 PM	
	7400	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 for pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 07:07 PM	20-00
	C/W AMM Task 57-41-11-000-801 - RH Mid Removal of the Leading Edge Vortillon		B0142491 - George Ambrose Mar 05, 2026 07:29 PM	
	7500	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 for pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 07:07 PM	20-00
	C/W AMM Task 57-41-11-400-801 - RH Mid Installation of the Leading Edge Vortillon		B0142491 - George Ambrose Mar 05, 2026 07:29 PM	
	7600	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 for pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 05:04 PM	20-00
	C/W AMM Task 57-41-11-000-801 - RH Inboard Removal of the Leading Edge Vortillon		B0142491 - George Ambrose Mar 05, 2026 07:29 PM	
	7700	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 for pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 05:04 PM	20-00
	C/W AMM Task 57-41-11-400-801 - RH Inboard Installation of the Leading Edge Vortillon		B0142491 - George Ambrose Mar 05, 2026 07:29 PM	
	7800	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 for pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 05:04 PM	20-00
	C/W AMM Task 57-51-01-820-801 - (LH Outboard) Rigging of the Flap Fairing		B0142491 - George Ambrose Mar 05, 2026 07:30 PM	
	7900	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 for pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 05:04 PM	20-00
	C/W AMM Task 57-51-01-820-801 - (LH Middle) Rigging of the Flap Fairing		B0142491 - George Ambrose Mar 05, 2026 07:30 PM	

Sequence #	5002	Aircraft SN #	6111	MWPWO #	2498069
WO #	2526984	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	8000	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 for pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 05:04 PM	20-00
	C/W AMM Task 57-51-01-820-801 - (LH Inboard) Rigging of the Flap Fairing		B0142491 - George Ambrose Mar 05, 2026 07:30 PM	
	8100	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 for pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 05:04 PM	20-00
	C/W AMM Task 57-51-01-820-801 - (RH Outboard) Rigging of the Flap Fairing		B0142491 - George Ambrose Mar 05, 2026 07:30 PM	
	8200	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 for pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 05:04 PM	20-00
	C/W AMM Task 57-51-01-820-801 - (RH Middle) Rigging of the Flap Fairing		B0142491 - George Ambrose Mar 05, 2026 07:30 PM	
	8300	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 for pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 05:04 PM	22-00
	C/W AMM Task 57-51-01-820-801 - (RH Inboard) Rigging of the Flap Fairing		B0142491 - George Ambrose Mar 05, 2026 07:30 PM	
	8400	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 for pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 05:04 PM	20-00
	C/W AMM Task 27-52-00-710-802 - Operational Test of the Flap System		B0142491 - George Ambrose Mar 05, 2026 07:30 PM	
	8500	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 for pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 05:04 PM	20-00
	C/W removal of the Forward Pax Door Handle Cover 832DZ, leave off to be painted separately from aircraft.		B0142491 - George Ambrose Mar 05, 2026 07:30 PM	
	8600	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 for pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 05:04 PM	20-00
	C/W installation of the Forward Pax Door Handle Cover 832DZ, after aircraft paint		B0142491 - George Ambrose Mar 05, 2026 07:30 PM	

Sequence #	5002	Aircraft SN #	6111	MWPWO #	2498069
WO #	2526984	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	8700	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 for pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 05:04 PM	20-00
	C/W the removal of the Lower Fuselage Maintenance Access Panel 181BL. Temporary install with a few fasteners and tape off the backside of the rest of the open holes		B0142491 - George Ambrose Mar 05, 2026 07:30 PM	
	8800	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 for pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 05:04 PM	20-00
	C/W the removal of the Lower Fuselage Maintenance Access Panel 182BL. Temporary install with a few fasteners and tape off the backside of the rest of the open holes		B0142491 - George Ambrose Mar 05, 2026 07:32 PM	
	8900	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 for pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 05:04 PM	20-00
	C/W removal of the APU Panel 320AB blocked off all access holes with tape, temporary install APU Panel with several fasteners and use tape to block off the back of all empty holes		B0142491 - George Ambrose Mar 05, 2026 07:32 PM	
	9000	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 for pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 05:04 PM	20-00
	C/W removal of the APU Panel 320BL blocked off all access holes with tape, temporary install APU Panel with several fasteners and use tape to block off the back of all empty holes		B0142491 - George Ambrose Mar 05, 2026 07:32 PM	
	9100	Panel Removed on Open access WO 3154420.	B0143806 - Alejandro Cabanillas Mar 05, 2026 05:21 PM	20-00
	C/W removal of the LH Upper Visor Fairing 346BLZ, Paint this panel separate from the aircraft. Do not install until elevator FT's are complete		B0142491 - George Ambrose Mar 05, 2026 07:32 PM	

Sequence #	5002	Aircraft SN #	6111	MWPWO #	2498069
WO #	2526984	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	9200	Panel removed on open access WO 3154420.	B0143806 - Alejandro Cabanillas Mar 05, 2026 05:21 PM	20-00
	C/W removal of the RH Upper Visor Fairing 346BRZ, Paint this panel separate from the aircraft. Do not install until elevator FT's are complete		B0142491 - George Ambrose Mar 05, 2026 07:32 PM	
	9300	Panel removed on open access WO 3154420.	B0143806 - Alejandro Cabanillas Mar 05, 2026 05:21 PM	20-00
	C/W removal of the LH Lower Visor Fairing 346ALZ, Paint this panel separate from the aircraft.		B0142491 - George Ambrose Mar 05, 2026 07:32 PM	
	9400	Panel removed on open access WO 3154420.	B0143806 - Alejandro Cabanillas Mar 05, 2026 05:21 PM	20-00
	C/W removal of the RH Lower Visor Fairing 346ARZ, Paint this panel separate from the aircraft.		B0142491 - George Ambrose Mar 05, 2026 07:32 PM	
	9500	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 for pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 05:04 PM	20-00
	C/W removal of the Horizontal LH Stab Cuff Panel 351AL, Do not remove seals from the panel.		B0142491 - George Ambrose Mar 05, 2026 07:32 PM	
	9600	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 for pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 07:07 PM	20-00
	C/W removal of the Horizontal RH Stab Cuff Panel 351AR, Do not remove seals from the panel.		B0142491 - George Ambrose Mar 05, 2026 07:32 PM	
	9700	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 for pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 07:07 PM	20-00
	C/W removal of the LH Elevator PCU Access Panel 351BB. Tack back on with several screws with back of open holes taped. Do not final install until elevator FT's are complete.		B0142491 - George Ambrose Mar 05, 2026 07:32 PM	

Sequence #	5002	Aircraft SN #	6111	MWPWO #	2498069
WO #	2526984	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	9800	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 for pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 07:07 PM	20-00
	C/W removal of the RH Elevator PCU Access Panel 361BB. Tack back on with several screws with back of open holes taped. Do not final install until elevator FT's are complete.		B0142491 - George Ambrose Mar 05, 2026 07:33 PM	
	9900	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 for pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 07:07 PM	20-00
	C/W removal of the LH Mid Rudder Hinge Panel 341EL. Tape off most of the screw holes and temporarily reinstall with two screws.		B0142491 - George Ambrose Mar 05, 2026 07:33 PM	
	10000	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 for pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 07:07 PM	20-00
	C/W removal of the RH Mid Rudder Hinge Panel 341ER. Tape off most of the screw holes and temporarily reinstall with two screws.		B0142491 - George Ambrose Mar 05, 2026 07:33 PM	
	10100	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 for pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 07:07 PM	20-00
	C/W AMM Task 71-00-00-210-804 General Visual Inspection of the Engine. Pre-Paint Inspect the LH Upper and Lower Engine Cowling Seals.		B0142491 - George Ambrose Mar 05, 2026 07:33 PM	
	10200	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 for pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 07:07 PM	20-00
	C/W AMM Task 71-00-00-210-804 General Visual Inspection of the Engine. Post-Paint Inspect the LH Upper and Lower Engine Cowling Seals.		B0142491 - George Ambrose Mar 05, 2026 07:33 PM	
	10300	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 for pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 07:07 PM	20-00
	C/W AMM Task 71-00-00-210-804 General Visual Inspection of the Engine. Pre-Paint Inspect the RH Upper and Lower Engine Cowling Seals.		B0142491 - George Ambrose Mar 05, 2026 07:33 PM	

Sequence #	5002	Aircraft SN #	6111	MWPWO #	2498069
WO #	2526984	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	10400	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 for pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 07:07 PM	20-00
	C/W AMM Task 71-00-00-210-804 General Visual Inspection of the Engine. Post-Paint Inspect the RH Upper and Lower Engine Cowling Seals.		B0142491 - George Ambrose Mar 05, 2026 07:33 PM	
	10500	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 for pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 07:07 PM	20-00
	C/W AMM Task 71-10-00-010-801 Opening of the Cowls (Left Engine). Apply tape to inner surface of all vents, ports, drains, and scoops.		B0142491 - George Ambrose Mar 05, 2026 07:33 PM	
	10600	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 for pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 07:07 PM	20-00
	C/W AMM Task 71-10-09-000-801 Removal of the Lower Cowling 432BB (Left Engine). To facilitate Left Upper Cowling Removal.		B0142491 - George Ambrose Mar 05, 2026 07:33 PM	
	10700	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 for pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 07:07 PM	20-00
	C/W AMM Task 71-10-05-000-801 Removal of the Upper Cowling 432BT (Left Engine). Apply tape to the inner surface of all vents, ports, drains, and scoops then temporarily reinstall.		B0142491 - George Ambrose Mar 05, 2026 07:33 PM	
	10800	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 for pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 07:07 PM	20-00
	C/W AMM Task 71-10-00-010-801 Opening of the Cowls (Right Engine). Apply tape to inner surface of all vents, ports, drains, and scoops.		B0142491 - George Ambrose Mar 05, 2026 07:34 PM	
	10900	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 for pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 07:07 PM	20-00
	C/W AMM Task 71-10-09-000-801 Removal of the Lower Cowling 442BB (Right Engine). To facilitate Left Upper Cowling Removal.		B0142491 - George Ambrose Mar 05, 2026 07:34 PM	

Sequence #	5002	Aircraft SN #	6111	MWPWO #	2498069
WO #	2526984	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	11000	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 for pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 07:07 PM	20-00
	C/W AMM Task 71-10-05-000-801 Removal of the Upper Cowling 442BT (Right Engine). Apply tape to the inner surface of all vents, ports, drains, and scoops then temporarily reinstall.		B0142491 - George Ambrose Mar 05, 2026 07:34 PM	
	11100	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 for pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 07:07 PM	
	C/W AMM Task 27-11-17-000-801 Removal of the Aileron Control Surfaces, Step 1.D(8). Record the Left Aileron Droop Readings: LH _____.		B0142491 - George Ambrose Mar 05, 2026 07:34 PM	
	11200	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 for pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 07:07 PM	20-00
	C/W AMM Task 27-11-17-000-801 Removal of the Aileron Control Surfaces (Left Aileron)		B0142491 - George Ambrose Mar 05, 2026 07:34 PM	
	11300	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 for pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 07:07 PM	20-00
	C/W Recording the Left Aileron Pre-Paint total Weight: LH _____.		B0142491 - George Ambrose Mar 05, 2026 07:34 PM	
	11400	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 for pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 07:07 PM	20-00
	C/W AMM Task 27-11-17-000-801 Removal of the Aileron Control Surfaces, Step 1.D(8). Record the Left Aileron Droop Readings: RH _____.		B0142491 - George Ambrose Mar 05, 2026 07:34 PM	
	11500	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 for pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 07:07 PM	20-00
	C/W AMM Task 27-11-17-000-801 Removal of the Aileron Control Surfaces (Right Aileron)		B0142491 - George Ambrose Mar 05, 2026 07:34 PM	

Sequence #	5002	Aircraft SN #	6111	MWPWO #	2498069
WO #	2526984	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	11600	Does not apply to 600 series Aircraft. See WO 4755078 for pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 08:25 PM	20-00
	C/W Recording the Left Aileron Pre-Paint total Weight: RH _____.		B1013522 - Brandon Jennings Mar 06, 2026 02:38 PM	
	11700	Does not apply to 600 series Aircraft. See WO 4755078 for pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 08:25 PM	20-00
	C/W AMM Task 27-11-17-820-802 Balancing of the Aileron Control Surfaces (Left Aileron) Post Paint.		B1013522 - Brandon Jennings Mar 06, 2026 03:51 PM	
	11800	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 for pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 08:25 PM	20-00
	C/W AMM Task 27-11-17-820-802 Balancing of the Aileron Control Surfaces (Right Aileron) Post Paint.		B1013522 - Brandon Jennings Mar 06, 2026 03:51 PM	
	11900	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 for pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 08:25 PM	20-00
	C/W AMM Task 27-11-17-820-801 Rigging of the Aileron Control Surfaces (Post Paint)		B1013522 - Brandon Jennings Mar 06, 2026 03:51 PM	
	12000	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 for pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 08:25 PM	20-00
	C/W AMM Task 27-11-21-820-801 Rigging of the Aileron Balance Geared-Tab (Left) (Post Paint)		B1013522 - Brandon Jennings Mar 06, 2026 03:51 PM	
	12100	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 for pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 08:25 PM	20-00
	C/W AMM Task 27-11-21-820-801 Rigging of the Aileron Balance Geared-Tab (Right) (Post Paint)		B1013522 - Brandon Jennings Mar 06, 2026 03:51 PM	
	12200	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 for pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 08:25 PM	20-00
	C/W AMM Task 27-11-00-720-806 Functional Test of the Aileron Control System - Friction Test (Post Paint)		B1013522 - Brandon Jennings Mar 06, 2026 03:51 PM	

Sequence #	5002	Aircraft SN #	6111	MWPWO #	2498069
WO #	2526984	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	12300	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 for pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 08:25 PM	22-00
	C/W AMM Task 27-11-00-710-802 Operational Test of the Aileron Control System (Post Paint)		B1013522 - Brandon Jennings Mar 06, 2026 03:51 PM	
	12400	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 for pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 08:25 PM	22-00
	C/W AMM Task 27-12-05-710-801 Operational Test of the Aileron Trim Actuator (Post Paint)		B1013522 - Brandon Jennings Mar 06, 2026 03:51 PM	
	12500	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 for pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 08:25 PM	20-00
	C/W AMM Task 53-32-01-000-801 Removal of the Main Landing Gear (MLG) Wheel-Bin Assembly, Remove the lower portion of the Right Wheel Bin (172BZ) which was temporarily installed until post paint checks are completed.		B1013522 - Brandon Jennings Mar 06, 2026 03:51 PM	
	12600	Does not apply to 600 series Aircraft. See WO 4755078 for pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 08:25 PM	20-00
	C/W the removal of the Left Geared Tab Fairing Panel 551DB, leave off to be painted separately from aircraft.		B1013522 - Brandon Jennings Mar 06, 2026 03:51 PM	
	12700	Does not apply to 600 series Aircraft. See WO 4755078 for pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 08:25 PM	20-00
	C/W the removal of the Right Geared Tab Fairing Panel 651DB, leave off to be painted separately from aircraft.		B1013522 - Brandon Jennings Mar 06, 2026 03:51 PM	
	12800	Does not apply to 600 series Aircraft. See WO 4755078 for pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 08:25 PM	20-00
	C/W removal of the left aileron Bellcrank access panel 531SB, tack back on with several screws with back of open holes taped after ailerons are removed.		B1013522 - Brandon Jennings Mar 06, 2026 03:51 PM	

Sequence #	5002	Aircraft SN #	6111	MWPWO #	2498069
WO #	2526984	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	12900	Does not apply to 600 series Aircraft. See WO 4755078 for pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 08:25 PM	20-00
	C/W removal of the right aileron Bellcrank access panel 631SB, tack back on with several screws with back of open holes taped after ailerons are removed.		B1013522 - Brandon Jennings Mar 06, 2026 03:51 PM	
	13000	Does not apply to 600 series Aircraft. See WO 4755078 for pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 08:25 PM	20-00
	C/W removal of the left aileron position transducer access panel 554AB, tack back on with several screws with back of open holes taped after ailerons are removed.		B1013522 - Brandon Jennings Mar 06, 2026 03:51 PM	
	13100	Does not apply to 600 series Aircraft. See WO 4755078 for pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 08:25 PM	20-00
	C/W removal of the right aileron position transducer access panel 654AB, tack back on with several screws with back of open holes taped after ailerons are removed.		B1013522 - Brandon Jennings Mar 06, 2026 03:51 PM	
	13200	Does not apply to 600 series Aircraft. See WO 4755078 for pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 08:25 PM	20-00
	C/W removal of the left inboard aileron hinge access panel 551AL, tack back on with several screws with back of open holes taped after ailerons are removed.		B1013522 - Brandon Jennings Mar 06, 2026 03:51 PM	
	13300	Does not apply to 600 series Aircraft. See WO 4755078 for pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 08:25 PM	20-00
	C/W removal of the left Mid aileron hinge access panel 551BL, tack back on with several screws with back of open holes taped after ailerons are removed.		B1013522 - Brandon Jennings Mar 06, 2026 03:51 PM	

Sequence #	5002	Aircraft SN #	6111	MWPWO #	2498069
WO #	2526984	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	13400	Does not apply to 600 series Aircraft. See WO 4755078 for pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 08:25 PM	20-00
	C/W removal of the left outboard aileron hinge access panel 551CL, tack back on with several screws with back of open holes taped after ailerons are removed.		B1013522 - Brandon Jennings Mar 06, 2026 03:51 PM	
	13500	Does not apply to 600 series Aircraft. See WO 4755078 for pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 08:25 PM	20-00
	C/W removal of the right inboard aileron hinge access panel 651AR, tack back on with several screws with back of open holes taped after ailerons are removed.		B1013522 - Brandon Jennings Mar 06, 2026 03:51 PM	
	13600	Does not apply to 600 series Aircraft. only applies to 300/350 series aircraft. See WO 4755078 for pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 08:25 PM	20-00
	C/W removal of the right Mid aileron hinge access panel 651BR, tack back on with several screws with back of open holes taped after ailerons are removed.		B1013522 - Brandon Jennings Mar 06, 2026 03:51 PM	
	13700	Does not apply to 600 series Aircraft. only applies to 300/350 series aircraft. See WO 4755078 for pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 08:25 PM	20-00
	C/W removal of the right outboard aileron hinge access panel 651CR, tack back on with several screws with back of open holes taped after ailerons are removed.		B1013522 - Brandon Jennings Mar 06, 2026 03:51 PM	
	13800	Does not apply to 600 series Aircraft. only applies to 300/350 series aircraft. See WO 4755078 for pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 08:25 PM	20-00
	C/W AMM Task 27-31-17-000-801 Removal of the Elevator Control Surfaces (Left Elevator)		B1013522 - Brandon Jennings Mar 06, 2026 03:51 PM	
	13900	Does not apply to 600 series Aircraft. AMM provided only applies to 300/350 series aircraft. See WO 4755078 for pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 08:25 PM	20-00
	C/W AMM Task 27-31-17-000-801 Removal of the Elevator Control Surfaces (Right Elevator)		B1013522 - Brandon Jennings Mar 06, 2026 03:51 PM	

Sequence #	5002	Aircraft SN #	6111	MWPWO #	2498069
WO #	2526984	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	14000	Does not apply to 600 series Aircraft. only applies to 300/350 series aircraft. See WO 4755078 for pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 08:25 PM	20-00
	C/W recording the left elevator pre-paint weight: LH _____		B1013522 - Brandon Jennings Mar 06, 2026 03:51 PM	
	14100	Does not apply to 600 series Aircraft. only applies to 300/350 series aircraft. See WO 4755078 for pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 08:25 PM	20-00
	C/W recording the right elevator pre-paint weight: RH _____		B1013522 - Brandon Jennings Mar 06, 2026 03:51 PM	
	14200	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 for pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 08:25 PM	20-00
	C/W AMM Task 27-31-17-820-801 Balancing of the Elevator Control Surface Post Paint (Left Elevator)		B1013522 - Brandon Jennings Mar 06, 2026 03:51 PM	
	14300	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 for pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 08:25 PM	20-00
	C/W AMM Task 27-31-17-820-801 Balancing of the Elevator Control Surface Post Paint (Right Elevator)		B1013522 - Brandon Jennings Mar 06, 2026 03:51 PM	
	14400	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 for pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 08:25 PM	20-00
	C/W AMM Task 27-31-00-720-802 Functional Test of the Elevator Control System Post Paint		B1013522 - Brandon Jennings Mar 06, 2026 03:51 PM	
	14500	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 for pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 08:25 PM	20-00
	C/W AMM Task 27-31-17-720-801 Functional Test of the Elevator Control-Surface Backlash Post Paint		B1013522 - Brandon Jennings Mar 06, 2026 03:51 PM	
	14600	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 for pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 08:25 PM	20-00
	C/W AMM Task 55-10-05-000-802 Removal of the Left Elevator-Linkage Lower Access Panel 351AB, tack back on with several screws with back of the open holes taped after elevator is removed.		B1013522 - Brandon Jennings Mar 06, 2026 03:51 PM	

Sequence #	5002	Aircraft SN #	6111	MWPWO #	2498069
WO #	2526984	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	14700	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 for pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 08:25 PM	20-00
	C/W AMM Task 55-10-05-000-802 Removal of the Right Elevator-Linkage Lower Access Panel 361AB, tack back on with several screws with back of the open holes taped after elevator is removed.		B1013522 - Brandon Jennings Mar 06, 2026 05:09 PM	
	14800	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 for pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 08:25 PM	20-00
	C/W AMM Task 55-20-01-000-802 Removal of the Left Inboard Elevator Access Panel 352GB, tack back on with several screws with back of the open holes taped after elevator is removed.		B1013522 - Brandon Jennings Mar 06, 2026 05:09 PM	
	14900	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 for pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 08:25 PM	20-00
	C/W AMM Task 55-20-01-000-802 Removal of the Left Mid Elevator Access Panel 352DB, tack back on with several screws with back of the open holes taped after elevator is removed.		B1013522 - Brandon Jennings Mar 06, 2026 05:09 PM	
	15000	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 for pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 08:25 PM	20-00
	C/W AMM Task 55-20-01-000-802 Removal of the Left outboard Elevator Access Panel 352EB, tack back on with several screws with back of the open holes taped after elevator is removed.		B1013522 - Brandon Jennings Mar 06, 2026 05:09 PM	
	15100	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 for pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 08:25 PM	20-00
	C/W AMM Task 55-20-01-000-802 Removal of the Right Inboard Elevator Access Panel 362GB, tack back on with several screws with back of the open holes taped after elevator is removed.		B1013522 - Brandon Jennings Mar 06, 2026 05:09 PM	

Sequence #	5002	Aircraft SN #	6111	MWPWO #	2498069
WO #	2526984	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	15200	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 for pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 08:25 PM	20-00
	C/W AMM Task 55-20-01-000-802 Removal of the Right Mid Elevator Access Panel 362DB, tack back on with several screws with back of the open holes taped after elevator is removed.		B1013522 - Brandon Jennings Mar 06, 2026 05:09 PM	
	15300	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 for pre/post paint support and work performed.	B0143806 - Alejandro Cabanillas Mar 05, 2026 08:25 PM	20-00
	C/W AMM Task 55-20-01-000-802 Removal of the Right outboard Elevator Access Panel 356EB, tack back on with several screws with back of the open holes taped after elevator is removed.		B1013522 - Brandon Jennings Mar 06, 2026 05:09 PM	
	15400	Does not apply to 600 series Aircraft. AMM provided applies to 300/350 series aircraft. See WO 4755078 operation 4,100 for work performed.	B0143806 - Alejandro Cabanillas Feb 27, 2026 08:15 PM	
	C/W AMM Task 57-33-01-400-801 - (LH) Installation of the Winglet Lenses - Wing Tip (541AT)		B1013522 - Brandon Jennings Feb 27, 2026 08:31 PM	

TOOL INFORMATION

Tool ID	Tool Description	Calibration Due Date
TUSS3756	Torque Wrench	Oct 30, 2026 5:00 PM

Bombardier

Sequence #	5003	Aircraft SN #	6111	MWPWO #	2498069
WO #	2526978	Aircraft Reg #	XA-SOL	Parent WO #	2498069

5003	WO #	2526978	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13276329	No Log Entry	
Paint - Standard strip and repaint - Passenger door stair tread replaced after door repaint (300/350/650)				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			52-10
	C/W AMM Task 52-11-01-000-801 Removal of the Passenger Door for paint			
	200			52-10
	Perform standard strip & repaint (hours included in main product)			
	300			52-10
	C/W AMM Task 52-11-01-400-801 Installation of the Passenger Door after paint			

Sequence #	5004	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4755078	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

5004	**WO #**	**4755078**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #	13499748	No Log Entry	
Paint - Standard strip and repaint - Pre/post paint support (601/604/605/650)				
CRITICAL MAINTENANCE TASK				

Sequence #	5004	Aircraft SN #	6111	MWPWO #	2498069
WO #	4755078	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			20-00
	C/W AMM Task 12-11-28-650-803 - Note any external fuel leaks, suction defuel then sump aircraft fuel until aircraft fuel system is empty.			
	200	Removed the NLG rear door to FOM REF CL650 32-22-04-000-801	B0580384 - Patrick Arceneaux Mar 04, 2026 01:23 AM	20-00
	C/W AMM Task 32-22-04-000-801 - Removal of the Nose Landing Gear (NLG) Rear Door		Not Required	
CMT	300	Complied with Installation of the Nose Landing Gear (NLG) Rear Door REF BD-100 AMM Task 32-22-04-400-801 Steps E.-F.(1)(7). Reference CMT working copy for work preformed dated Mar 3, 2026. Steps F. (8)(14) NA due to not disconnected.	B0648431 - Caleb Sexton Mar 05, 2026 08:02 PM	20-00
	C/W AMM Task 32-22-04-400-801 - Installation of the Nose Landing Gear (NLG) Rear Door		B0141354 - Karl Tuxhorn Mar 05, 2026 08:19 PM	
	400	Removed the MLG LH door to FOM REF CL650 AMM 32-12-01-000-801	B0580384 - Patrick Arceneaux Mar 04, 2026 01:23 AM	20-00
	C/W AMM Task 32-12-01-000-801 - (LH) Removal of the Main Landing Gear (MLG) Door		Not Required	
CMT	500	Reinstalled LH MLG Door. REF CL650 AMM 32-12-01-400-801 steps E.(1.) thru F.(13.). See working copy dated 03/04/26 for work performed	B1016542 - Carlos Ochoa Mar 05, 2026 01:07 AM	20-00
	C/W AMM Task 32-12-01-400-801 - (LH) Installation of the Main Landing Gear (MLG) Door		B0161691 - Thomas Mitchell Mar 05, 2026 01:23 AM	
CMT	501			
	Continue installation of the LH MLG Door CL650 AMM Task 32-12-01-400-801 steps F.(14.) thru closeout.			
	600	Removed the MLG RH door to FOM REF CL650 AMM 32-12-01-000-801	B0580384 - Patrick Arceneaux Mar 04, 2026 01:23 AM	20-00
	C/W AMM Task 32-12-01-000-801 - (RH) Removal of the Main Landing Gear (MLG) Door		Not Required	

Sequence #	5004	Aircraft SN #	6111	MWPWO #	2498069
WO #	4755078	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
CMT	700	Reinstalled RH MLG Door. REF CL650 AMM 32-12-01-400-801 steps E.(1.) thru F.(13.). See working copy dated 03/04/26 for work performed	B1016542 - Carlos Ochoa Mar 05, 2026 01:07 AM	20-00
	C/W AMM Task 32-12-01-400-801 - (RH) Installation of the Main Landing Gear (MLG) Door		B0161691 - Thomas Mitchell Mar 05, 2026 01:23 AM	
CMT	701			
	Continue installation of the RH MLG Door CL650 AMM Task 32-12-01-400-801 steps F.(14.) thru closeout.			
	800	Complied with removal of the Static Wicks (Left Aileron) in Ref CL-650 AMM 23-61-01-000-803	B0143806 - Alejandro Cabanillas Feb 18, 2026 05:10 PM	20-00
	C/W AMM Task 23-61-01-000-803 - Removal of the Static Wicks (Left Aileron)		Not Required	
	900			20-00
	C/W AMM Task 23-61-01-400-803 - Installation of the Static Wicks (Left Aileron)			
	1000	Complied with removal of the Static Wicks (Right Aileron) in Ref CL-650 AMM 23-61-01-000-803	B0143806 - Alejandro Cabanillas Feb 18, 2026 05:10 PM	20-00
	C/W AMM Task 23-61-01-000-803 - Removal of the Static Wicks (Right Aileron)		Not Required	
	1100			20-00
	C/W AMM Task 23-61-01-400-803 - Installation of the Static Wicks (Right Aileron)			
	1200	Complied with removal of the Static Wicks (Left wing tip)) in Ref CL-650 AMM 23-61-01-000-803	B0143806 - Alejandro Cabanillas Feb 18, 2026 05:10 PM	20-00
	C/W AMM Task 23-61-01-000-803 - Removal of the Static Wicks (Left Wing Tip)		Not Required	
	1300			20-00
	C/W AMM Task 23-61-01-400-803 - Installation of the Static Wicks (Left Wing Tip)			

Sequence #	5004	Aircraft SN #	6111	MWPWO #	2498069
WO #	4755078	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	1400	Complied with removal of the Static Wicks (Right wing tip) in Ref CL-650 AMM 23-61-01-000-803	B0143806 - Alejandro Cabanillas Feb 18, 2026 05:10 PM	20-00
	C/W AMM Task 23-61-01-000-803 - Removal of the Static Wicks (Right Wing Tip)		Not Required	
	1500			20-00
	C/W AMM Task 23-61-01-400-803 - Installation of the Static Wicks (Right Wing Tip)			
	1600	Complied with removal of the Static Wicks (Left Elevator) in Ref CL-650 AMM 23-61-01-000-803	B0143806 - Alejandro Cabanillas Feb 18, 2026 05:10 PM	20-00
	C/W AMM Task 23-61-01-000-803 - Removal of the Static Wicks (Left Elevator)		Not Required	
	1700			20-00
	C/W AMM Task 23-61-01-400-803 - Installation of the Static Wicks (Left Elevator)			
	1800	Complied with removal of the Static Wicks (Right elevator) in Ref CL-650 AMM 23-61-01-000-803	B0143806 - Alejandro Cabanillas Feb 18, 2026 05:10 PM	20-00
	C/W AMM Task 23-61-01-000-803 - Removal of the Static Wicks (Right Elevator)		Not Required	
	1900			20-00
	C/W AMM Task 23-61-01-400-803 - Installation of the Static Wicks (Right Elevator)			
	2000	Complied with removal of the Static Wicks (Rudder) in Ref CL-650 AMM 23-61-01-000-803	B0143806 - Alejandro Cabanillas Feb 18, 2026 05:10 PM	20-00
	C/W AMM Task 23-61-01-000-803 - Removal of the Static Wicks (Rudder)		Not Required	
	2100	Complied with removal of the Static Wicks (Tailcone) in Ref CL-650 AMM 23-61-01-000-803	B0143806 - Alejandro Cabanillas Feb 18, 2026 05:10 PM	20-00
	C/W AMM Task 23-61-01-000-803 - Removal of the Static Wicks (Tailcone)		Not Required	

Sequence #	5004	Aircraft SN #	6111	MWPWO #	2498069
WO #	4755078	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	2200	Complied with removal of the Static Wicks (bullet fairing) in Ref CL-650 AMM 23-61-01-000-803	B0143806 - Alejandro Cabanillas Feb 18, 2026 05:10 PM	20-00
	C/W AMM Task 23-61-01-000-803 - Removal of the Static Wicks (Bullet)		Not Required	
	2300			22-00
	C/W AMM Task 27-35-04-820-801 - Alignment Check of the Angle - Of - Attack Vane Transducer			
	2400	Complied with removal of LH AOA Vane to FOM. REF CL-650 AMM 27-35-31-000-801.	B0641378 - Calvin Ambrose Mar 05, 2026 07:08 PM	22-00
	C/W AMM Task 27-35-31-000-801 - Remove of the Angle - Of Attack (AOA) Vane (Left Hand)		Not Required	
	2500			20-00
	C/W AMM Task 27-35-31-400-801 - Installation of the Angle - Of Attack (AOA) Vane (Left Hand)			
	2600	Complied with removal of RH AOA Vane to FOM. REF CL-650 AMM 27-35-31-000-801.	B0641378 - Calvin Ambrose Mar 05, 2026 07:08 PM	20-00
	C/W AMM Task 27-35-31-000-801 - Remove of the Angle - Of Attack (AOA) Vane (Right Hand)		Not Required	
	2700			20-00
	C/W AMM Task 27-35-31-400-801 - Installation of the Angle - Of Attack (AOA) Vane (Right Hand)			
	2800	Complied with removal of the LH Inboard flap Aerodynamic seals in Ref CL-650 AMM 57-51-01-000-801.	B0143806 - Alejandro Cabanillas Feb 18, 2026 07:42 PM	20-00
	C/W AMM Task 57-51-01-000-801 (LH) Removal of Inboard Flap Aerodynamic Seals		Not Required	
	2900			20-00
	C/W AMM Task 57-51-01-400-801 (LH) Installation of Inboard Flap Aerodynamic Seals			

Sequence #	5004	Aircraft SN #	6111	MWPWO #	2498069
WO #	4755078	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	3000	Complied with removal of the RH Inboard flap aerodynamic seals in Ref CL-650 AMM 57-51-01-000-801.	B0143806 - Alejandro Cabanillas Feb 18, 2026 07:42 PM	20-00
	C/W AMM Task 57-51-01-000-801 (RH) Removal of Inboard Flap Aerodynamic Seals		Not Required	
	3100			20-00
	C/W AMM Task 57-51-01-400-801 (RH) Installation of Inboard Flap Aerodynamic Seals			
	3200	Complied with removal of the LH Outboard Flap Aerodynamic seals In ref CL-650 AMM 57-51-01-000-802.	B0143806 - Alejandro Cabanillas Feb 18, 2026 07:42 PM	20-00
	C/W AMM Task 57-51-01-000-802 (LH) Removal of Outboard Flap Aerodynamic Seals		Not Required	
	3300			20-00
	C/W AMM Task 57-51-01-400-802 (LH) Installation of Outboard Flap Aerodynamic Seals			
	3400	Complied with removal of the RH Outboard flap aerodynamic seals in Ref Cl-650 AMM 57-51-01-000-801.	B0143806 - Alejandro Cabanillas Feb 18, 2026 07:42 PM	20-00
	C/W AMM Task 57-51-01-000-802 (RH) Removal of Outboard Flap Aerodynamic Seals		Not Required	
	3500			20-00
	C/W AMM Task 57-51-01-400-802 (RH) Installation of Outboard Flap Aerodynamic Seals			
	3600	Complied with removal and discard of the windshield weather strip in ref CL-650 AMM 56-11-01-000-801.	B0143806 - Alejandro Cabanillas Feb 19, 2026 04:15 PM	20-00
	C/W AMM Task 56-11-01-000-801 - Remove and discard the windshield weather strip		Not Required	
	3700			20-00
	C/W AMM Task 56-11-01-400-801 - Install the windshield weather strip			

Sequence #	5004	Aircraft SN #	6111	MWPWO #	2498069
WO #	4755078	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	3800	Removed LWR nose compartment access panel (121AL) (fasteners only) IAW CL650 AMM TASK 52-45-25-000-801	B1022255 - Carson Chang Feb 19, 2026 04:11 PM	20-00
	C/W AMM Task 52-45-25-000-801 - Remove of the Lower Nose Compartment Access Panel (Fasteners Only)		Not Required	
	3900			20-00
	C/W AMM Task 52-45-25-400-801 - Installation of the Lower Nose Compartment Access Panel (Fasteners Only)			
	4000	Complied with removal of the Left Wing Tip Glazing Assembly in REF cl-650 AMM 57-31-04-000-801	B0143806 - Alejandro Cabanillas Feb 18, 2026 08:06 PM	20-00
	C/W AMM Task 57-31-04-000-801 Removal of the Left Wing Tip Glazing Assembly		Not Required	
	4100			20-00
	C/W AMM Task 57-31-04-400-801 Installation of the Left Wing Tip Glazing Assembly			
	4200	Complied with removal of the Right Wing tip glassing Assembly In ref CL-650 AMM 57-31-04-000-801.	B0143806 - Alejandro Cabanillas Feb 18, 2026 08:06 PM	20-00
	C/W AMM Task 57-31-04-000-801 Removal of the Right Wing Tip Glazing Assembly		Not Required	
	4300			20-00
	C/W AMM Task 57-31-04-400-801 Installation of the right Wing Tip Glazing Assembly			
	4400	APU exhaust shield and visor removed on work order 3154420 operation 1200. Visually inspected APU head shield and visor for defects IAW CL650 AMM task 49−81−07−210−801. No defects noted.	B1022255 - Carson Chang Feb 19, 2026 05:47 PM	20-00
	C/W AMM Task 49-81-07-000-801 Removal of the Auxiliary Power Unit (APU) Exhaust Shield and Visor Assembly and inspect for defects		Not Required	

Sequence #	5004	Aircraft SN #	6111	MWPWO #	2498069
WO #	4755078	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	4500			20-00
	C/W AMM Task 49-81-07-400-801 Installation of the Auxiliary Power Unit (APU) Exhaust Shield and Visor Assembly			
	4600			20-00
	C/W installation of Left Side Soft Covers over Fan and Spiller Dome and install soft bypass air covers between core cowls and trans cowls.			
	4700			20-00
	C/W removal of Left Side Soft Covers over Fan and Spiller Dome and install soft bypass air covers between core cowls and trans cowls.			
	4800			20-00
	C/W installation of Right Side Soft Covers over Fan and Spiller Dome and install soft bypass air covers between core cowls and trans cowls.			
	4900			20-00
	C/W removal of Right Side Soft Covers over Fan and Spiller Dome and install soft bypass air covers between core cowls and trans cowls.			
	5000	Panel opened on work order 3154420. Back taped all openings on LH upper core cowl door.	B1022255 - Carson Chang Feb 19, 2026 08:28 PM	20-00
	C/W AMM Task 71-12-01-010-801 LH Engine Opening of the Upper Core Cowl Door and Tape off all Openings		Not Required	
	5100			20-00
	C/W AMM Task 71-12-01-410-801 LH Engine Closing of the Upper Core Cowl Door			

Sequence #	5004	Aircraft SN #	6111	MWPWO #	2498069
WO #	4755078	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	5200	Panel opened on work order 3154420. Back taped all openings on RH upper core cowl door.	B1022255 - Carson Chang Feb 19, 2026 08:30 PM	20-00
	C/W AMM Task 71-12-01-010-801 RH Engine Opening of the Upper Core Cowl Door and Tape off all Openings		Not Required	
	5300			20-00
	C/W AMM Task 71-12-01-410-801 RH Engine Closing of the Upper Core Cowl Door			
	5400			20-00
	C/W AMM Task 27-54-00-710-801 Operational Test of the Inboard and Outboard Flaps to the Full Up position			
	5500			20-00
	C/W AMM Task 27-40-00-720-801 Functional Test of the Horizontal Stabilizer Trim System to set the Trim to Take-Off Position			
	5600	Complied with removal of the Passenger door step (upper) in Ref CL-650 AMM 54-11-10-000-801.	B0143806 - Alejandro Cabanillas Feb 19, 2026 08:53 PM	20-00
	C/W AMM Task 52-11-10-000-801 Removal of the Passenger Door Steps		Not Required	
	5601	Complied with removal of the passenger Door top step in Ref CL-650 AMM 51-11-10-000-801.	B0143806 - Alejandro Cabanillas Feb 26, 2026 07:55 PM	
	C/W AMM Task 52-11-10-000-801 Removal of the Passenger Door top step		Not Required	09
	5700			20-00
	C/W AMM Task 52-11-10-400-801 Installation of the Passenger Door Steps			
	5800			20-00
	C/W Noting if AOA Vane Decals are Installed			

Sequence #	5004	Aircraft SN #	6111	MWPWO #	2498069
WO #	4755078	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	5900			20-00
	C/W AMM Task 53-65-01-400-801 Installation of the Left Main Landing Gear (MLG) Wheel Bin confirming it is installed and all fasteners are installed.			
	6000			20-00
	C/W AMM Task 53-65-01-400-801 Installation of the Right Main Landing Gear (MLG) Wheel Bin confirming it is installed and all fasteners are installed.			
	6100	Complied with removal of the Wing inspection light (lens only) in Ref CL-650 33-43-01-000-801	B0143806 - Alejandro Cabanillas Feb 19, 2026 08:49 PM	20-00
	C/W AMM Task 33-43-01-000-801 Removal of the Wing Inspection Light (Lens Only) LH Side		Not Required	
	6200			20-00
	C/W AMM Task 33-43-01-400-801 Installation of the Wing Inspection Light (Lens Only) LH Side			
	6300	Complied with removal of the RH Wing inspection Light lens only in Ref CL-650 AMM 33-43-01-000-801.	B0143806 - Alejandro Cabanillas Feb 18, 2026 09:05 PM	20-00
	C/W AMM Task 33-43-01-000-801 Removal of the Wing Inspection Light (Lens Only) RH Side		Not Required	
	6400			20-00
	C/W AMM Task 33-43-01-400-801 Installation of the Wing Inspection Light (Lens Only) RH Side			
	6500	Complied with removal of the LH Wing Inspection light lens Only in ref CL-650 AMM 33-43-01-000-801.	B0143806 - Alejandro Cabanillas Feb 18, 2026 09:05 PM	20-00
	C/W AMM Task 33-51-04-000-801 Removal of the Wing Inspection Light (Lens Only) LH Side		Not Required	
	6600			20-00
	C/W AMM Task 33-51-04-400-801 Installation of the Wing Inspection Light (Lens Only) LH Side			

Sequence #	5004	Aircraft SN #	6111	MWPWO #	2498069
WO #	4755078	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	6700	Removed RH FWD exterior emergency lights lens Assy IAW CL650 AMM 33−51−04−000−801.	B1022255 - Carson Chang Feb 19, 2026 04:17 PM	20-00
	C/W AMM Task 33−51−04−000−801 Removal of the Exterior Emergency Light (Lens Only) LH Side		Not Required	
	6701	Removed LH exterior emergency lights lens Assy IAW CL650 AMM 33−51−04−000−801.	B1022255 - Carson Chang Feb 19, 2026 04:51 PM	
	C/W AMM Task 33−51−04−000−801 Removal of the Exterior Emergency Light (Lens Only) LH Side		Not Required	09
	6800			20-00
	C/W AMM Task 33−51−04−400−801 Installation of the Exterior Emergency Light (Lens Only) LH Side			
	6900	Removed RH two FWD exterior emergency lights lens Assy IAW CL650 AMM 33−51−04−000−801.	B1022255 - Carson Chang Feb 19, 2026 04:26 PM	20-00
	C/W AMM Task 33−51−04−000−801 Removal of the Exterior Emergency Light (Lens Only) RH Side		Not Required	
	7000			20-00
	C/W AMM Task 33−51−04−400−801 Installation of the Exterior Emergency Light (Lens Only) RH Side			
	7100	Removed RH AFT exterior emergency lights lens Assy IAW CL650 AMM 33−51−04−000−801.	B1022255 - Carson Chang Feb 19, 2026 05:04 PM	20-00
	C/W AMM Task 33-51-04-000-801 Removal of the Wing Exterior Emergency Light (Lens Only) RH Side Aft		Not Required	
	7200			20-00
	C/W AMM Task 33-51-04-400-801 Installation of the Wing Inspection Light (Lens Only) RH Side Aft			

Sequence #	5004	Aircraft SN #	6111	MWPWO #	2498069
WO #	4755078	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	7300 C/W Standard Practices Manual 51-25-00 Visually inspect all flight controls and landing gear actuator shafts, rods, slider tubes for any evidence of pint overspray. Note any evidence of overspray so it can be removed prior to moving any flight controls or landing gear components.			20-00
	7400 C/W AMM Task 52-11-28-210-801 General Visual Inspection of the Passenger Door Seal	Complied with general visual inspection of the Passenger door seal(Pre-Paint) In Ref CL-650 AMM 52-11-28-210-801.No defects noted at this time.	B0143806 - Alejandro Cabanillas Mar 06, 2026 03:43 PM B1013522 - Brandon Jennings Mar 06, 2026 05:25 PM	20-00
	7500 C/W AMM Task 52-31-01-210-801 General Visual Inspection of the Cargo Compartment Door - External	Complied with general visual inspection of the cargo compartment door- seal (Pre-Paint) In ref CL-650 AMM 52-31-01-210-801. No Defects noted at this time.	B0143806 - Alejandro Cabanillas Mar 06, 2026 03:43 PM B1013522 - Brandon Jennings Mar 06, 2026 05:25 PM	20-00
	7600 C/W AMM Task 52-21-01-210-801 General Visual Inspection of the Overwing Emergency-Exit Door-External	Complied with General visual inspection of the Overwing Emergency-Exit Door Seal (Pre Paint) In Ref CL-650 AMM 52-21-01-210-801. No defects noted at this time.	B0143806 - Alejandro Cabanillas Mar 06, 2026 03:43 PM B1013522 - Brandon Jennings Mar 06, 2026 05:25 PM	20-00
	7700 C/W Standard Practices Manual 51-25-00 Visually inspect all external sensor probes, static ports, and antennas for evidence of pint overspray or sanding damage.			20-00
	7800 C/W AMM Task 12-20-04-640-804 Lubrication of the Servicing Doors (Door, Air Driven Generator (ADG) Assembly)			20-00

Bombardier

Sequence #	5004	Aircraft SN #	6111	MWPWO #	2498069
WO #	4755078	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	7900			20-00
	C/W AMM Task 12-20-04-640-804 Lubrication of the Servicing Doors (Door, AC Ground−Power Connection)			
	8000			20-00
	C/W AMM Task 12-20-04-640-804 Lubrication of the Servicing Doors (Door, External Servicing Panel)			
	8100			20-00
	C/W AMM Task 12-20-04-640-804 Lubrication of the Servicing Doors (Door, Pressure Refuel/Defuel Adapter)			
	8200			20-00
	C/W AMM Task 12-20-04-640-804 Lubrication of the Servicing Doors (Door, Refuel/Defuel Control Panel)			
	8300			20-00
	C/W AMM Task 12-20-04-640-804 Lubrication of the Servicing Doors (Door, Forward Equipment Compartment)			
	8400			20-00
	C/W AMM Task 12-20-04-640-804 Lubrication of the Servicing Doors (Door, Oxygen Refill Connection)			
	8500			20-00
	C/W AMM Task 12-20-04-640-804 Lubrication of the Servicing Doors (Door, Systems Service)			
	8600			20-00
	C/W AMM Task 12-20-04-640-804 Lubrication of the Servicing Doors (Door, External−DC Ground−Power Connection)			

Sequence #	5004	Aircraft SN #	6111	MWPWO #	2498069
WO #	4755078	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	8700			20-00
	C/W AMM Task 12-20-04-640-808 Lubrication of the Aft Equipment Compartment Door			
	8800			20-00
	C/W AMM Task 12-20-04-640-806 Lubrication of the Cargo Compartment Door			
	8900			20-00
	C/W AMM Task 12-20-04-640-805 Lubrication of the Emergency Exit Door			
	9000			20-00
	C/W AMM Task 12-20-04-640-807 Lubrication of the Passenger Door (External)			
	9100			20-00
	C/W AMM Task 12-20-04-640-802 Lubrication of the Left Main Landing Gear (MLG)			
	9200			20-00
	C/W AMM Task 12-20-04-640-802 Lubrication of the Right Main Landing Gear (MLG)			
	9300			20-00
	C/W AMM Task 12-20-04-640-833 Lubrication of the Left Main Landing Gear (MLG) Doors			
	9400			20-00
	C/W AMM Task 12-20-04-640-833 Lubrication of the Right Main Landing Gear (MLG) Doors			
	9500			20-00
	C/W AMM Task 12-20-04-640-801 Lubrication of the Nose Landing Gear (NLG)			

Sequence #	5004	Aircraft SN #	6111	MWPWO #	2498069
WO #	4755078	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	9600			20-00
	C/W AMM Task 12-20-04-640-832 Lubrication of the Nose Landing Gear (NLG) Doors			
	9700			20-00
	C/W AMM Task 12-20-04-640-818 Lubrication of the Left Controlex Aileron Cable in the Wheel Well			
	9800			20-00
	C/W AMM Task 12-20-04-640-818 Lubrication of the Right Controlex Aileron Cable in the Wheel Well			
	9900			20-00
	C/W AMM Task 12-20-04-640-818 Lubrication of the Left Controlex Aileron Cable in the aft wing			
	10000			20-00
	C/W AMM Task 12-20-04-640-818 Lubrication of the Right Controlex Aileron Cable in the aft wing			
	10100			20-00
	C/W AMM Task 12-20-04-640-813 Lubrication of the Ball Nut of the Flap Actuator (Left Inboard Flap Inboard Actuator)			
	10200			20-00
	C/W AMM Task 12-20-04-640-813 Lubrication of the Ball Nut of the Flap Actuator (Left Inboard Flap Outboard Actuator)			
	10300			20-00
	C/W AMM Task 12-20-04-640-813 Lubrication of the Ball Nut of the Flap Actuator (Left Outboard Flap Inboard Actuator)			

Sequence #	5004	Aircraft SN #	6111	MWPWO #	2498069
WO #	4755078	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	10400			20-00
	C/W AMM Task 12-20-04-640-813 Lubrication of the Ball Nut of the Flap Actuator (Left Outboard Flap Middle Actuator)			
	10500			20-00
	C/W AMM Task 12-20-04-640-813 Lubrication of the Ball Nut of the Flap Actuator (Left Outboard Flap Outboard Actuator)			
	10600			20-00
	C/W AMM Task 12-20-04-640-813 Lubrication of the Ball Nut of the Flap Actuator (Right Inboard Flap Inboard Actuator)			
	10700			20-00
	C/W AMM Task 12-20-04-640-813 Lubrication of the Ball Nut of the Flap Actuator (Right Inboard Flap Outboard Actuator)			
	10800			20-00
	C/W AMM Task 12-20-04-640-813 Lubrication of the Ball Nut of the Flap Actuator (Right Outboard Flap Inboard Actuator)			
	10900			20-00
	C/W AMM Task 12-20-04-640-813 Lubrication of the Ball Nut of the Flap Actuator (Right Outboard Flap Middle Actuator)			
	11000			20-00
	C/W AMM Task 12-20-04-640-813 Lubrication of the Ball Nut of the Flap Actuator (Right Outboard Flap Outboard Actuator)			

Bombardier

Sequence #	5004	Aircraft SN #	6111	MWPWO #	2498069
WO #	4755078	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	11100			20-00
	C/W AMM Task 12-20-04-640-809 Lubrication of the Flap Vane Actuator Rod (Left Inboard Vane Actuator Rod)			
	11200			20-00
	C/W AMM Task 12-20-04-640-809 Lubrication of the Flap Vane Actuator Rod (Left Middle Vane Actuator Rod)			
	11300			20-00
	C/W AMM Task 12-20-04-640-809 Lubrication of the Flap Vane Actuator Rod (Left Outboard Vane Actuator Rod)			
	11400			20-00
	C/W AMM Task 12-20-04-640-809 Lubrication of the Flap Vane Actuator Rod (Right Inboard Vane Actuator Rod)			
	11500			20-00
	C/W AMM Task 12-20-04-640-809 Lubrication of the Flap Vane Actuator Rod (Right Middle Vane Actuator Rod)			
	11600			20-00
	C/W AMM Task 12-20-04-640-809 Lubrication of the Flap Vane Actuator Rod (Right Outboard Vane Actuator Rod)			
	11700			20-00
	C/W AMM Task 12-20-04-640-810 Lubrication of the Left Bent-Up Trailing Edge (BUTE) Door Hinge			

Sequence #	5004	Aircraft SN #	6111	MWPWO #	2498069
WO #	4755078	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	11800			20-00
	C/W AMM Task 12-20-04-640-810 Lubrication of the Right Bent-Up Trailing Edge (BUTE) Door Hinge			
	11900			20-00
	C/W AMM Task 12-20-04-640-811 Lubrication of the Left Bent-Up Trailing Edge (BUTE) Door Rollers (5 locations per side)			
	12000			20-00
	C/W AMM Task 12-20-04-640-811 Lubrication of the Right Bent-Up Trailing Edge (BUTE) Door Rollers (5 locations per side)			
	12100			20-00
	C/W AMM Task 12-20-04-640-8255 Lubrication of the Main Landing Gear (MLG) Brake Control Valve Assembly			
	12200			20-00
	Complete Post Paint Items NOTE: Add 20 hours			
	12300	Removed LH Horizontal stabilizer tip Fairing Static wicks in ref CL-650 AMM 23-61-01-000-803.	B0143806 - Alejandro Cabanillas Feb 18, 2026 08:22 PM	
	Remove LH H/Sab tip Fairing Static wicks in ref CL-650 AMM 23-61-01-000-803.		Not Required	
	12400			
	Install LH Horizontal stabilizer tip fairing static wicks in ref CL-650 AMM 23-61-01-400-803.			

Sequence #	5004	Aircraft SN #	6111	MWPWO #	2498069
WO #	4755078	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	12500	Removed RH Horizontal stabilizer tip fairing static wicks in ref CL-650 AMM 23-61-01-000-803.	B0143806 - Alejandro Cabanillas Feb 18, 2026 08:22 PM	
	Remove RH Horizontal stabilizer tip fairing static wicks in ref CL-650 AMM 23-61-01-000-803.		Not Required	
	12600			
	Install RH Horizontal stabilizer tip fairing static wicks in ref BC-650 AMM 23-61-01-400-803.			
	12700			
	C/W install of the lower tailcone static Wick in Ref CL-650 AMM 23-61-01-400-803.			
	12800			
	C/W install of the bullet fairing Static Wicks in ref CL-650 AMM 23-61-01-400-803.			
	12900	Panel opened on work order 3154420. Back taped all openings on LH lower core cowl door.	B1022255 - Carson Chang Feb 19, 2026 08:25 PM	
	C/W AMM Task 71-12-01-010-802 LH Engine Opening of the lower Core Cowl Door and Tape off all Openings		Not Required	
	13000	Panel opened on work order 3154420. Back taped all openings on RH lower core cowl door.	B1022255 - Carson Chang Feb 19, 2026 08:27 PM	
	C/W AMM Task 71-12-01-010-802 RH Engine Opening of the Lower Core Cowl Door and Tape off all Openings		Not Required	
	13100	Removed LH Pylon External service light (lens only) in Ref CL-650 AMM 33-32-01-960-801.	B0143806 - Alejandro Cabanillas Feb 19, 2026 08:40 PM	
	Remove LH Pylon External service light (lens only) in Ref CL-650 AMM 33-32-01-960-801.		Not Required	

Sequence #	5004	Aircraft SN #	6111	MWPWO #	2498069
WO #	4755078	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	13200 Install LH Pylon External service light (lens only) in Ref CL-650 AMM 33-32-01-960-801.			
	13300 Remove RH Pylon External service light (lens only) in Ref CL-650 AMM 33-32-01-960-801.	Removed RH Pylon External service light (lens only) in Ref CL-650 AMM 33-32-01-960-801.	B0143806 - Alejandro Cabanillas Feb 19, 2026 08:40 PM Not Required	
	13400 Install RH Pylon External service light (lens only) in Ref CL-650 AMM 33-32-01-960-801.			
	13500 C/W CL650 AMM 71−14−01−000−801 Removal of the R/H Upper Access Cowl and Tape off all Openings	R/H upper access cowl (442AT) removed in work order 3154420. Back taped off app openings	B1022255 - Carson Chang Feb 19, 2026 09:19 PM Not Required	
	13600 Comply with install of the Static Wicks (Rudder) in Ref CL-650 AMM 23-61-01-400-803.			
	13700 Comply with functional test of the static dischargers(Post Paint) in Ref CL-650 AMM 23-61-01-720-801.			
	13800 C/W Post-Paint - AMM Task 52-11-28-210-801 - Detailed Inspection of the Passenger Door Seal.			
	13900 C/W Post-Paint - AMM Task 52-31-01-210-801 - Detailed Inspection of the Baggage door seal.			

Sequence #	5004	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4755078	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	14000			
	C/W Post-Paint - AMM Task 52-21-01-210-801 - Detailed Inspection of the Passenger Door Seal.			

TOOL INFORMATION

Tool ID	Tool Description	Calibration Due Date
TUSS3500	TW	Jan 30, 2027 5:00 PM
TUSS3756	Torque Wrench	Oct 30, 2026 5:00 PM

Bombardier

Sequence #	6501	Aircraft SN #	6111	MWPWO #	2498069
WO #	3154414	Aircraft Reg #	XA-SOL	Parent WO #	2498069

6501	WO #	3154414	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13276349	No Log Entry	
Work Finalizing / RTS				
Task / IRN # : POST				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	200			
	Approve Aircraft to RTS		Not Required	
	400			
	Perform Final Walk Around		Not Required	

CHILD WORK ORDER DETAILS

	WO #	Description	Corrective Action	AMENDED
6501-1	3154415	A/C Final Close-Up		
6501-2	3154420	Open Access Panels		
6501-3	3154422	Close Access Panels		

Bombardier

Sequence #	6501-1	Aircraft SN #	6111	MWPWO #	2498069
WO #	3154415	Aircraft Reg #	XA-SOL	Parent WO #	3154414

6501-1	WO #	3154415	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		No Log Entry	
A/C Final Close-Up				
Task / IRN # : AC FINAL-CLOSE				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			
	Clean the Aircraft		Not Required	
	300			
	Perform Post Mechanical Check		Not Required	

Sequence #	6501-2	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	3154420	**Aircraft Reg #**	XA-SOL	**Parent WO #**	3154414

6501-2	**WO #**	**3154420**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		No Log Entry	
Open Access Panels				
Task / IRN # : ACCESS-OPEN				

Bombardier

Sequence #	6501-2	Aircraft SN #	6111	MWPWO #	2498069
WO #	3154420	Aircraft Reg #	XA-SOL	Parent WO #	3154414

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with Open of Access Panels as Required, See Access Panel Tab for Details	B0648431 - Caleb Sexton Feb 20, 2026 05:48 PM	20-00
	Open Access Panels			
	200	removed the LH upper access cowl. (432AT) REF. CL 650 AMM TASK 71−14−01−000−801	B1017711 - Isaac Ramirez Feb 05, 2026 08:43 PM	
	remove the LH upper access cowl		B0142244 - Todd Bridges Feb 07, 2026 03:28 PM	
	201	Removed the LH upper access cowl. (432AT) REF. CL 650 AMM TASK 71−14−01−000−801	B1014141 - Christopher Drawdy Feb 13, 2026 09:23 PM	
	remove the LH upper access cowl		B1017318 - Steve Pritchett Feb 13, 2026 09:42 PM	09
	300			
	install the LH upper access cowl. (432AT)			
	400	removed the LH Upper Translating Cowl Door (434AT) REF. CL-650 AMM TASK 71−11−01−000−801	B1017711 - Isaac Ramirez Feb 05, 2026 08:43 PM	
	remove the LH Upper Translating Cowl Door (434AT)		B0142244 - Todd Bridges Feb 07, 2026 03:28 PM	
	401	Removed the LH Upper Translating Cowl Door (434AT) REF. CL-650 AMM TASK 71−11−01−000−801	B1014141 - Christopher Drawdy Feb 13, 2026 09:23 PM	
	remove the LH Upper Translating Cowl Door (434AT)		Not Required	09
	500			
	install the LH Upper Translating Cowl Door (434AT)			
	600	removed the Upper Core Cowl Door (435AT) REF. CL-650 AMM TASK 71−12−01−000−801	B1017711 - Isaac Ramirez Feb 05, 2026 08:43 PM	
	remove the Upper Core Cowl Door (435AT)		B0142244 - Todd Bridges Feb 07, 2026 03:28 PM	

Sequence #	6501-2	Aircraft SN #	6111	MWPWO #	2498069
WO #	3154420	Aircraft Reg #	XA-SOL	Parent WO #	3154414

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	601	Removed the Upper Core Cowl Door (435AT) REF. CL-650 AMM TASK 71−12−01−000−801	B1014141 - Christopher Drawdy Feb 13, 2026 09:23 PM	
	remove the Upper Core Cowl Door (435AT)		Not Required	09
	700			
	Install the Upper Core Cowl Door (435AT)			
	800	Removed LH Horizontal Stabilizer Cuff Seal in Ref CL-650 AMM 55-10-16-000-801.	B0143806 - Alejandro Cabanillas Feb 06, 2026 09:25 PM	
	Remove LH Horizontal Stabilizer Cuff Seal in Ref CL-650 AMM 55-10-16-000-801.		Not Required	
	900			
	Install LH Horizontal Stabilizer Cuff Seal in Ref CL-650 AMM 55-10-16-400-801.			
	1000	Removed RH Horizontal Stabilizer Cuff Seal in Ref CL-650 AMM 55-10-16-000-801.	B0143806 - Alejandro Cabanillas Feb 06, 2026 09:25 PM	
	Remove RH Horizontal Stabilizer Cuff Seal in Ref CL-650 AMM 55-10-16-000-801.		Not Required	
	1100			
	Install RH Horizontal Stabilizer Cuff Seal in Ref CL-650 AMM 55-10-16-400-801.			
	1200	Removed Auxiliary Power Unit APU Exhaust shield and visor assembly IAW CL-650 AMM 49-81-07-000-801	B1018546 - Andres Velazquez Feb 08, 2026 05:17 PM	
	Remove Auxiliary Power Unit APU Exhaust shield and visor assembly		Not Required	
	1300			
	Install Auxiliary Power Unit APU Exhaust shield and visor assembly IAW CL-650 AMM 53-30-01-220-817			

Sequence #	6501-2	Aircraft SN #	6111	MWPWO #	2498069
WO #	3154420	Aircraft Reg #	XA-SOL	Parent WO #	3154414

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	1400	Removed LH flight deck flashlight and axe from 280 blkhd IAW ch350 SPM 20-21-00-910-801	B1015989 - Victor Palazuelos Feb 09, 2026 05:07 PM	
	Remove LH flight deck flashlight and axe from 280 blkhd IAW ch350 SPM 20-21-00-910-801		B0142491 - George Ambrose Feb 11, 2026 09:19 PM	
	1401	Removed LH flight deck flashlight and axe from 280 blkhd IAW ch650 SPM 20-21-00-910-801	B1015989 - Victor Palazuelos Feb 10, 2026 01:19 PM	
	Remove LH flight deck flashlight and axe from 280 blkhd IAW ch350 SPM 20-21-00-910-801		Not Required	
	1500			
	Install LH flight deck flashlight and axe from 280 blkhd IAW ch650 SPM 20-21-00-910-801			
	1600	Removed flight compartment carpet IAW ch650 smm 25-11-09-000-801	B1015989 - Victor Palazuelos Feb 11, 2026 05:22 PM	
	Remove flight compartment carpet IAW ch650 smm 25-11-09-000-801		Not Required	
	1700			
	Install flight compartment carpet IAW ch650 smm 25-11-09-400-801			
	1800	removed flight deck loose items	B1015989 - Victor Palazuelos Feb 11, 2026 05:22 PM	
	Remove flight deck loose items		Not Required	
	1900			
	Install flight deck loose items			
	2000	removed aircraft registration from flight deck 280 bulkhead and turned in to quality office	B1015989 - Victor Palazuelos Feb 11, 2026 05:22 PM	
	Remove aircraft registration from flight deck 280 bulkhead and turn in to quality office		Not Required	

Sequence #	6501-2	Aircraft SN #	6111	MWPWO #	2498069
WO #	3154420	Aircraft Reg #	XA-SOL	Parent WO #	3154414

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	2100			
	Remove aircraft registration from flight deck 280 bulkhead and turn in to quality office			
	2200	Removed Lower Translating Cowl REF CL650 AMM 71-11-01-000-802.	B1014141 - Christopher Drawdy Feb 13, 2026 09:30 PM	
	Remove Lower Translating Cowl		Not Required	
	2300			
	Install Lower Translating Cowl			
	2400	Removed Lower Core Cowl REF CL650 AMM 71-12-01-000-802.	B1014141 - Christopher Drawdy Feb 13, 2026 09:30 PM	
	Remove Lower Core Cowl		Not Required	
	2500			
	Install Lower Core Cowl			
	2600	Removed maintenance access panel on Floorboard 242FRF.	B0142041 - Timothy Winfree Feb 15, 2026 05:30 PM	
	Remove maintenance access panel on floorboard 242FRF to FOM.		Not Required	
	2700	Reinstalled maintenance access panel on floorboard 242FRF, Ref. 650 SPM task 20−21−00−910−801.	B0648431 - Caleb Sexton Feb 20, 2026 05:48 PM	
	Reinstall maintenance access panel on floorboard 242FRF, Ref. 650 SPM task 20−21−00−910−801.		B1013522 - Brandon Jennings Feb 20, 2026 07:11 PM	
	2800	Removed panels 142CLF and 142BLF to FOM REF CL-650 AMM 53-24-01-000-801.	B1002512 - Brandon Warne Feb 16, 2026 08:33 PM	
	Remove panels 142CLF and 142DLF to FOM		Not Required	
	2900	Installed panels 142CLF and 142BLF REF CL-650 AMM 53-24-01-400-801.	B1002512 - Brandon Warne Feb 19, 2026 02:42 PM	
	Install panels 142CLF and 142BLF.		B1013522 - Brandon Jennings Feb 19, 2026 02:53 PM	

Sequence #	6501-2	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	3154420	**Aircraft Reg #**	XA-SOL	**Parent WO #**	3154414

OPERATIONAL DETAILS

	Operation #	Corrective Action Long Description	Tech Sign Off	ATA Code
	Operation Description		Insp Sign Off	Reason for Work

Sequence #	6501-2	Aircraft SN #	6111	MWPWO #	2498069
WO #	3154420	Aircraft Reg #	XA-SOL	Parent WO #	3154414

FINDINGS DETAILS

Finding #	Long Description	Status	Reported By / Date	Defect Source / Disposition	Defect Type	Priority	Follow-up WO #
79075	LH (434AT) Upper trans cowl has dent.	CLOSED	B1017711 - Isaac Ramirez Feb 5, 2026 2:05 PM	MAINTENANCE 300-QA002	OTHER	3	4750012-RDYLT
79133	Access panel 520AB LH wing landing/taxi light window has 4 stripped fasteners. (P/N: CA2023-5 and CA2035)	CLOSED	B0142041 - Timothy Winfree Feb 6, 2026 7:15 AM	MAINTENANCE 300-QA002	OTHER	3	4784980-APPR
79170	LH Lower Pylon Access Panel 433AB is cracked along top edge of panel	CLOSED	B0613291 - Eric Strong Feb 6, 2026 9:12 AM	MAINTENANCE 300-QA002	OTHER	3	4750197-PSAP
79204	LH and RH Horizontal Stabilizer Cuff seals Are worn out.	CLOSED	B0143806 - Alejandro Cabanillas Feb 6, 2026 2:37 PM	MAINTENANCE 300-QA002	OTHER	3	4748584-PSAP
79216	AFT Attachment bracket for RH Upper Transcowl Fairing 444BT has pulled-through its rivets on RH Thrust Reverser track	CLOSED	B0613291 - Eric Strong Feb 6, 2026 4:36 PM	MAINTENANCE 300-QA002	OTHER	3	4750180-PSAP
79229	Disbonding phenolic fuel panel 540AB	CLOSED	B1018547 - Matthew Rossier Feb 6, 2026 8:12 PM	MAINTENANCE 300-QA002	OTHER	3	4750047-PSAP
79360	Surface Corrosion on APU exhaust muffler.	CLOSED	B1018546 - Andres Velazquez Feb 8, 2026 11:50 AM	MAINTENANCE 300-QA002	OTHER	3	4790162-RDYPM
79367	Panel 832DR seal disbanding.	CLOSED	B1018546 - Andres Velazquez Feb 8, 2026 12:47 PM	MAINTENANCE 300-QA002	OTHER	3	4750169-PSAP
79388	Passenger door cable pulley wheel worn .	CLOSED	B1018546 - Andres Velazquez Feb 8, 2026 4:48 PM	MAINTENANCE 300-QA002	OTHER	3	4791438-INPRG
79512	Open Access Panels	CLOSED	B1015989 - Victor Palazuelos Feb 9, 2026 10:33 AM	MAINTENANCE 300-QA002	OTHER	3	
79517	Fuel Panel 640AB phenolic strip is disbonded in multiple areas	CLOSED	B0613291 - Eric Strong Feb 9, 2026 10:39 AM	MAINTENANCE 300-QA002	OTHER	3	4750251-PSAP

Sequence #	6501-2	Aircraft SN #	6111	MWPWO #	2498069
WO #	3154420	Aircraft Reg #	XA-SOL	Parent WO #	3154414

FINDINGS DETAILS

Finding #	Long Description	Status	Reported By / Date	Defect Source / Disposition	Defect Type	Priority	Follow-up WO #
79557	Multiple Panels on Zone 300 have improperly installed face seal from factory.	CLOSED	B1014141 - Christopher Drawdy Feb 9, 2026 12:36 PM	MAINTENANCE 300-QA002	OTHER	3	4739575-PSAP
79588	Fairing (324AT) V-stab leading edge has some popped rivets. marked with a streamer.	CLOSED	B0143806 - Alejandro Cabanillas Feb 9, 2026 2:19 PM	MAINTENANCE 300-QA002	OTHER	3	4801974-PSAP
79589	Top cap fairing (326BT)portion of upper left lightning strip missing . see attachment.	CLOSED	B0143806 - Alejandro Cabanillas Feb 9, 2026 2:23 PM	MAINTENANCE 300-QA002	OTHER	3	4748839-PSAP
79590	During removal op Fairing (323AT) found Bent Attachment point tab LH lower. see attachment. marked with a streamer.	CLOSED	B0143806 - Alejandro Cabanillas Feb 9, 2026 2:31 PM	MAINTENANCE 300-QA002	OTHER	3	4784999-PSAP
79591	Open Access Panels	CLOSED	B0143806 - Alejandro Cabanillas Feb 9, 2026 2:32 PM	MAINTENANCE 300-QA002	OTHER	3	4766207-PSAP
79720	Torn Orcon Tape on both LH and RH IB Flaps, underneath Flap Fairings (572DB, 572GB, 672DB, 672GB).	CLOSED	B0646266 - Sergio Rodriguez Figueroa Feb 10, 2026 9:52 AM	MAINTENANCE 300-QA002	OTHER	3	4748980-PSAP
80147	191AL, 192AR(HDY SYS PNL) Spacer desponded next to key lock	CLOSED	B0648431 - Caleb Sexton Feb 13, 2026 7:48 AM	MAINTENANCE 300-QA002	OTHER	3	4802722-PSAP
81380	Horizontal stabilizer flutter dampener Access panel (332BB) has damage print seal.	CLOSED	B0143806 - Alejandro Cabanillas Feb 20, 2026 10:19 AM	MAINTENANCE 300-QA002	OTHER	3	4810267-RDYLT
82622	L/H MLG Door Jumper Cable (CL650 AIPC 32-12-01 Fig 1 item 55 P/N M83413-8A-004BB) requires replacement.	CLOSED	B1022255 - Carson Chang Mar 2, 2026 7:56 AM	MAINTENANCE 300-QA002	OTHER	3	4866456-RDYLT

Sequence #	6501-3	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	3154422	**Aircraft Reg #**	XA-SOL	**Parent WO #**	3154414

6501-3	**WO #**	**3154422**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		No Log Entry	
Close Access Panels				
CRITICAL MAINTENANCE TASK				
Task / IRN # : ACCESS-CLOSE				

Sequence #	6501-3	Aircraft SN #	6111	MWPWO #	2498069
WO #	3154422	Aircraft Reg #	XA-SOL	Parent WO #	3154414

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			20-00
	Close Access Panels			
	200	Disconnected the Pax Door Handrail Upper Support Rods from the Attachment Fittings Ref. CL605 AMM 52-11-13-000-802 & 52-11-13-000-801	B0162034 - Tyler Poggi Feb 06, 2026 11:09 PM	
	Disconnect Pax Door Handrail Upper Support Rods		Not Required	
	300			
	Re-connect the Pax Door Handrail Upper Support Rods to the Attachment Fittings Ref. CL605 AMM 52-11-13-400-802 & 52-11-13-400-801			
	400	Disconnected the Pax Door Bottom Folding Step, Actuator Rod Ref. CL605 AMM 52−11−10−000−801	B0162034 - Tyler Poggi Feb 06, 2026 11:21 PM	
	Disconnect the Pax Door Bottom Folding Step Actuator Rod		Not Required	
	500			
	Re-connect the Pax Door Bottom Folding Step, Actuator Rod Ref. CL605 AMM 52−11−10−400−801			
CMT	600			
	Perform retraction of the dry ADG. REF CL650 AMM 24-23-01-840-806.			
	700			
	C/W General Visual Inspection of the Fuel Tank Exterior after fuel panel install REF CL650 AMM 28−10−00−210−801			
	800	Performed functional test of the interspace lines, shrouds and fittings (blockage & pressure) IAW Ref: CL650 AMM 28-12-10-720-803. Functional test results: Pass	B1021822 - Joseph Cuoco Feb 19, 2026 07:47 PM	
	Perform functional test of the interspace lines, shrouds and fittings (blockage and pressure) ref: CL650 AMM28-12-10-720-803		B1013522 - Brandon Jennings Feb 19, 2026 08:00 PM	

Sequence #	6501-3	Aircraft SN #	6111	MWPWO #	2498069
WO #	3154422	Aircraft Reg #	XA-SOL	Parent WO #	3154414

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	900 Refuel the auxiliary tanks and do a check for leaks Ref CL650 AMM 12-11-28-650-801.			
	1000 Do the operational test of the level sensors ref: CL650 Amm (28-41-00-710-802)			
	1100 Perform operational test of the wing inspection light REF: CL650 AMM 33-43-00-710-801.			
	1200 Perform operational test of the warning switch for the pressure refuel/defuel adapter door REF: CL650 AMM 52-72-01-710-801.			
	1300 Verify sealant on zone 600			
	1400 Verify sealant zone 500			
	1500 Verify sealant 400 zone			
	1600 Verify sealant on 300 Zone.			
	1700 Perform 9 hour cure check of panel 361CB On 2/20/26 at 12:00AM REF: CL-650 SPM 51-23-00-390-801	Performed 9 hour cure check of panel 361CB on 2/20/26 at 5:00 PM, REF: CL-650 SPM 51-23-00-390-801. Cure check good. See panel log for panel status.	B1018547 - Matthew Rossier Feb 21, 2026 12:46 AM B0623124 - Michael Stacy Feb 21, 2026 01:05 AM	

Sequence #	6501-3	Aircraft SN #	6111	MWPWO #	2498069
WO #	3154422	Aircraft Reg #	XA-SOL	Parent WO #	3154414

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	1800	Installed the RH nose-cowl side panel REF: CL-650 AMM 71-14-04-400-801	B1018409 - Areida Cruz Feb 20, 2026 08:55 PM	
	Displace the RH nose-cowl side panel Ref: CL-650 AMM 71-14-04-000-801		B1013522 - Brandon Jennings Feb 27, 2026 01:17 PM	
	1900			
	Verify sealant on 100 Zone.			
	2000			
	Perform an Operational Test of the Engine Fire/ Overheat Detection System. Ref: CL650 AMM 26-11-00-710-801			
	2100			
	Perform operational test of pitch trim switch REF: CL-650 AMM 27-41-04-710-801			
	2200			
	C/W Operational Test of the Wing Inspection Light REF CL650 AMM 33−43−00−710−801.			
	2300			
	Perform operational test of the DME system. REF CL650 34-53-00-710-801.			

Sequence #	6501-3	Aircraft SN #	6111	MWPWO #	2498069
WO #	3154422	Aircraft Reg #	XA-SOL	Parent WO #	3154414

FINDINGS DETAILS

Finding #	Long Description	Status	Reported By / Date	Defect Source / Disposition	Defect Type	Priority	Follow-up WO #
80993	Close Access Panels	CLOSED	B1013522 - Brandon Jennings Feb 18, 2026 1:58 PM	MAINTENANCE 100-ERROR	OTHER	3	
80994	Panel 325CL print seal damaged	CLOSED	B1013522 - Brandon Jennings Feb 18, 2026 1:58 PM	MAINTENANCE 300-QA002	OTHER	3	4800751-RDYLT
81049	During install found delamination on forward LH wing to fuselage panel 191BB on aft bottom side see attachment for details.	CLOSED	B0641903 - Felipe Mendoza Cervantes Feb 18, 2026 7:16 PM	MAINTENANCE 300-QA002	OTHER	3	4796746-PSAP
81225	Found chafed engine fuel line located where Pylon access panel 412DB is located.	CLOSED	B0646266 - Sergio Rodriguez Figueroa Feb 19, 2026 12:41 PM	MAINTENANCE 100-ERROR	OTHER	3	
81430	Removed nut-plate underneath panel 422BT (RH side top of pylon)	CLOSED	B1018409 - Areida Cruz Feb 20, 2026 5:38 PM	MAINTENANCE 300-QA002	OTHER	3	4820720-RDYLT
81431	Enter by error	CLOSED	B1018409 - Areida Cruz Feb 20, 2026 5:39 PM	MAINTENANCE 100-ERROR	OTHER	3	
81432	Enter by error	CLOSED	B1018409 - Areida Cruz Feb 20, 2026 5:39 PM	MAINTENANCE 100-ERROR	OTHER	3	
81664	Panel stiffener (Hat Chanel) on panel 161FL has damage. See attachment for detail.	CLOSED	B1022255 - Carson Chang Feb 23, 2026 9:25 AM	MAINTENANCE 300-QA002	OTHER	3	4828066-PSAP
81802	Floor board 232WRF has a broken nut plate, left hand side of the panel, 2nd back from the front.	CLOSED	B1021822 - Joseph Cuoco Feb 24, 2026 7:06 AM	MAINTENANCE 300-QA002	OTHER	3	4828090-PSAP
82218	During operational test of the engine fire / overheat detection system, found that the EICAS shows no indication of Left Jetpipe OVHT.	CLOSED	B0645936 - Carlos Zerino Feb 26, 2026 3:01 PM	MAINTENANCE 300-QA002	OTHER	3	4882329-RDYLT

Sequence #	6501-3	Aircraft SN #	6111	MWPWO #	2498069
WO #	3154422	Aircraft Reg #	XA-SOL	Parent WO #	3154414

TOOL INFORMATION

Tool ID	Tool Description	Calibration Due Date
TUSS375	Torque Wrench	Oct 30, 2026 5:00 PM
TUSS4982	Torque Screwdriver	Jul 30, 2026 5:00 PM
TUSS2040	Torque Wrench	Dec 30, 2026 5:00 PM
TUSS4000	Torque Screwdriver	Oct 30, 2026 5:00 PM
TUSS0607	Bond Checker	Jan 30, 2027 5:00 PM
TUSS4000	Torque Driver	Oct 30, 2026 5:00 PM
TUSS2040	Torque wrench	Dec 30, 2026 5:00 PM
TUSS3500	Torque Wrench	Jan 30, 2027 5:00 PM
TUSS4982	torque screwdriver	Jul 30, 2026 5:00 PM
TUSS2036	Torque wrench	May 30, 2026 5:00 PM
TUSS5176	Torque Screwdriver	Oct 30, 2026 5:00 PM
TUSS4000	Torque screwdriver	Oct 30, 2026 5:00 PM
TUSS4982	Torque Screwdriver	Jul 30, 2026 5:00 PM
TUSS4982	Torque driver	Jul 30, 2026 5:00 PM
TUSS2036	Torque Wrench	May 30, 2026 5:00 PM
TUSS4000	Torque Wrench	Oct 30, 2026 5:00 PM
TUSS5176	Torque Screwdriver	Oct 30, 2026 5:00 PM
TUSJ2176	Torque Wrench 10-50 inlbs	Sep 29, 2026 5:00 PM
TUSS2243	TORQUEWRENCH	Dec 30, 2026 5:00 PM
TUSS4000	Torque Driver	Oct 30, 2026 5:00 PM
TUSS5176	Torque Driver	Oct 30, 2026 5:00 PM
TUSS4982	TORQUE DRIVER	Jul 30, 2026 5:00 PM
TUSS5176	Torque Screwdriver	Oct 30, 2026 5:00 PM
TUSS4982	TORQUE DRIVER	Oct 30, 2026 5:00 PM
TUSS5176	Torque Screwdriver	Oct 30, 2026 5:00 PM
TUSS0607	Milli-Ohm Meter	Jan 30, 2027 5:00 PM

Sequence #	6501-3	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	3154422	**Aircraft Reg #**	XA-SOL	**Parent WO #**	3154414

TOOL INFORMATION

Tool ID	Tool Description	Calibration Due Date
TUSS4000	Torque Driver	Oct 30, 2026 5:00 PM
TUSS4982	Torque Screwdriver 5-40 inlbs	Jul 30, 2026 5:00 PM
TUSS5176	Torque Screwdriver	Oct 30, 2026 5:00 PM
TUSS4000	Torque Driver	Oct 30, 2026 5:00 PM

Sequence #	6502	Aircraft SN #	6111	MWPWO #	2498069
WO #	3303481	Aircraft Reg #	XA-SOL	Parent WO #	2498069

6502	WO #	3303481	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13276353	No Log Entry	
Perform AD and Life Limit research as required for Inspections (Maintenance Record Review (FAR 43.15)). MAINTENANCE RECORDS RESEARCH FOR SB'S, ETC AS REQUIRED) AND CUSTOMER SPECIAL REQUIREMENTS (I.E.: FOREIGN PAPERWORK REQUIREMENTS, COMMERCIAL OPERATORS ETC.)				
Task / IRN # : AD AND LIFE LIMIT RESEARCH				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Performed AD and Life Limit Research as required for Inspections	B0141964 - Stephen Badolato Jr Feb 05, 2026 07:24 PM	05-00
	Perform AD and Life Limit Research as required for Inspections		Not Required	
	200			05-00
	Comply with Special Customer Requirements as Necessary		Not Required	
	300	Performed Airworthiness Directive Research upon Aircraft Arrival, As Required	B0141964 - Stephen Badolato Jr Feb 05, 2026 07:24 PM	05-00
	Perform Airworthiness Directive Research upon Aircraft Arrival, As Required		Not Required	
	400			05-00
	Perform Airworthiness Directive Research prior to Return to Service, As Required		Not Required	

Sequence #	6502	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	3303481	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

FINDINGS DETAILS

Finding #	Long Description	Status	Reported By / Date	Defect Source / Disposition	Defect Type	Priority	Follow-up WO #
79202	2025-24-11 The FAA is issuing this AD to address an accumulation of fuel in the auxiliary power unit (APU) muffler caused by a drainage block in the muffler	CLOSED	B0141964 - Stephen Badolato Jr Feb 6, 2026 2:30 PM	MAINTENANCE 200-DUPLICATE	OTHER	3	

Bombardier

Sequence #	7001	Aircraft SN #	6111	MWPWO #	2498069
WO #	4720663	Aircraft Reg #	XA-SOL	Parent WO #	2498069

7001	WO #	4720663	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	20321904	No Log Entry	
CSO/ 6111/ Main Battery/ Comply with task 24-30-00-202, Functional Test (Capacity Check) of the Main Battery. PN 601R59041-3, SN 09052001ED6B6.				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	INSPECTED. COMPLIED WITH TASK 24-30-00-202 FUNCTIONAL TEST (CAP CHECK) OF THE MAIN BATTERY. CAP CHECK GOOD. INSULATION CHECK GOOD. NO DEFECTS NOTED. ALL WORK DONE IAW SAFT CMM 24-32-06. PN: 601R59041-3, SN: 09052001ED6B6.	B0143837 - David Bohl Feb 09, 2026 07:54 PM	
	CSO/ 6111/ Main Battery/ Comply with task 24-30-00-202, Functional Test (Capacity Check) of the Main Battery. PN 601R59041-3, SN 09052001ED6B6.		B1013522 - Brandon Jennings Feb 09, 2026 08:18 PM	
	200	INSPECTED. COMPLIED WITH PRELIMINARY INSPECTION OF THE MAIN BATTERY. NO DEFECTS NOTED. ALL WORK DONE IAW SAFT CMM 24-32-06.	B0143837 - David Bohl Feb 09, 2026 07:54 PM	
	COMPLY WITH PRELIMINARY INSPECTION OF THE MAIN BATTERY.		B1013522 - Brandon Jennings Feb 09, 2026 08:18 PM	

TOOL INFORMATION

Tool ID	Tool Description	Calibration Due Date
TUSJ1726	MULTIMETER	Dec 30, 2026 5:00 PM
HC4423	TORQUE WRENCH 40-200	Dec 30, 2026 5:00 PM
TUSJ1779	MEGOHMMETER	Apr 29, 2026 5:00 PM
TUSJ1732	CHARGER	Jan 30, 2027 5:00 PM

QA005 RTS Statement

The component identified above was repaired and inspected in accordance with current Federal Aviation Regulations, found airworthy and is approved for return to service with respect to the work performed

Inspected By :

Sequence #	7001	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4720663	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

B1017318 > Steve Pritchett **Date:** 2026-02-12

Bombardier

Sequence #	7002	Aircraft SN #	6111	MWPWO #	2498069
WO #	4720737	Aircraft Reg #	XA-SOL	Parent WO #	2498069

7002	WO #	4720737	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	20321850	No Log Entry	
CSO/ 6111/ APU Battery/ Comply with task 24-30-00-203, Functional Test (Capacity Check) of the APU Battery. PN 600-59151-11. SN 09052001F098B.				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	INSPECTED. COMPLIED WITH TASK 24-30-00-203 FUNCTIONAL TEST (CAP CHECK) OF THE APU BATTERY. CAP CHECK GOOD. INSULATION CHECK GOOD. NO DEFECTS NOTED. ALL WORK DONE IAW SAFT CMM 24-32-05. PN: 600-59151-11, SN: 09052001F098B.	B0143837 - David Bohl Feb 09, 2026 07:44 PM	
	CSO/ 6111/ APU Battery/ Comply with task 24-30-00-203, Functional Test (Capacity Check) of the APU Battery. PN 600-59151-11. SN 09052001F098B.		B1013522 - Brandon Jennings Feb 09, 2026 08:12 PM	
	200	INSPECTED. COMPLIED WITH PRELIMINARY INSPECTION OF THE APU BATTERY. NO DEFECTS NOTED. ALL WORK DONE IAW SAFT CMM 24-32-05.	B0143837 - David Bohl Feb 09, 2026 07:44 PM	
	COMPLY WITH PRELIMINARY INSPECTION OF THE APU BATTERY.		B1013522 - Brandon Jennings Feb 09, 2026 08:12 PM	

TOOL INFORMATION

Tool ID	Tool Description	Calibration Due Date
TUSJ1726	MULTIMETER	Dec 30, 2026 5:00 PM
HC4423	TORQUE WRENCH 40-200	Dec 30, 2026 5:00 PM
TUSJ1779	MEGOHMMETER	Apr 29, 2026 5:00 PM
TUSJ2253	CHARGER	Sep 29, 2026 5:00 PM

QA005 RTS Statement

The component identified above was repaired and inspected in accordance with current Federal Aviation Regulations, found airworthy and is approved for return to service with respect to the work performed

Inspected By :

Sequence #	7002	Aircraft SN #	6111	MWPWO #	2498069
WO #	4720737	Aircraft Reg #	XA-SOL	Parent WO #	2498069

B1017318 > Steve Pritchett **Date:** 2026-02-12

Sequence #	7003	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4731591	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

			LOG BOOK VERBIAGE	Deferrals
7003	**WO #**	**4731591**		
	SAP SVO #	20322072	No Log Entry	
7003/CSO// 6111/Comply with Landing Gear 96 Month Inspection on RH MLG				

Bombardier

Sequence #	7003	Aircraft SN #	6111	MWPWO #	2498069
WO #	4731591	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	THE FOLLOWING WORK PERFORMED IS IN ACCORDANCE WITH BOMBARDIER CHALLENGER 650 AIRCRAFT MANUAL CHAPTER 05 TASK NO. 32-00-01-215 REV.35 DATED 15/OCT/2025, SAFRAN COMPONENT MAINTENANCE MANUAL 19090 CHAPTER 32-10-16 REV.27 DATED 01/JUN/2025. RECEIVED WITHOUT SIDE STRUT PIN ASSY OR TOP AUX ACTUATOR BOLT. BEGAN TEARDOWN.	B1020834 - Ezequiel Reyes Feb 12, 2026 05:23 AM	
	CSO// 6111/Comply with Landing Gear 96 Month Inspection on RH MLG		B0585124 - Michael Jones Feb 14, 2026 04:56 AM	
	101	COMPLETED DISASSEMBLY AND CLEANED.	B0127528 - Mark Curtis Feb 13, 2026 03:59 AM	
	CSO// 6111/Comply with Landing Gear 96 Month Inspection on RH MLG		B0585124 - Michael Jones Feb 14, 2026 04:56 AM	
	102	CLEANED HARNESS, POLISHED PISTON, PINS AND AXLE. COMPLETED VISUAL INSPECTION AND BEGAN PREPPING FOR PAINT. REJECTED LOCK RING FOR NON REPAIRABLE CORROSION.	B0127528 - Mark Curtis Feb 14, 2026 04:47 AM	
	CSO// 6111/Comply with Landing Gear 96 Month Inspection on RH MLG		B0585124 - Michael Jones Feb 14, 2026 04:56 AM	
	103	BELL CRANK NOT RECEIVED.	B0127528 - Mark Curtis Feb 14, 2026 04:52 AM	
	CSO// 6111/Comply with Landing Gear 96 Month Inspection on RH MLG		B0585124 - Michael Jones Feb 14, 2026 04:56 AM	
	104	CONTINUED PREPPING FOR PAINT.	B0127528 - Mark Curtis Feb 17, 2026 04:52 AM	
	CSO// 6111/Comply with Landing Gear 96 Month Inspection on RH MLG		B0585124 - Michael Jones Feb 19, 2026 09:45 PM	
	105	CONTINUED PAINT PREP.	B0127528 - Mark Curtis Feb 18, 2026 04:59 AM	
	CSO// 6111/Comply with Landing Gear 96 Month Inspection on RH MLG		B0585124 - Michael Jones Feb 19, 2026 09:45 PM	

Bombardier

Sequence #	7003	Aircraft SN #	6111	MWPWO #	2498069
WO #	4731591	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	106	COMPLETED PAINT PREP AND WIPED DOWN STRUT	B0127528 - Mark Curtis Feb 19, 2026 05:13 AM	
	CSO// 6111/Comply with Landing Gear 96 Month Inspection on RH MLG		B0585124 - Michael Jones Feb 19, 2026 09:45 PM	
	107	PRIMED ALL COMPONENTS.	B1017220 - Cameron Harrold Feb 19, 2026 07:07 PM	
	CSO// 6111/Comply with Landing Gear 96 Month Inspection on RH MLG		B0585124 - Michael Jones Feb 19, 2026 09:45 PM	
	108	PAINTED GREY	B1020834 - Ezequiel Reyes Feb 20, 2026 05:11 AM	
	CSO// 6111/Comply with Landing Gear 96 Month Inspection on RH MLG		B0585124 - Michael Jones Feb 24, 2026 05:09 AM	
	109	UNMASKED ALL PAINTED PARTS. ASSEMBLED SHOCK STRUT WITH CALIBRATED TOOLS. ID: 329003 DUE 29-DEC-26, ID:34903068 DUE 03-SEP-26 AND ID: K0012 DUE 04-AUG-26. PUT ON TEST STAND.	B1017591 - Stacy Kennedy Feb 20, 2026 08:56 PM	
	CSO// 6111/Comply with Landing Gear 96 Month Inspection on RH MLG		B0150944 - Adam Pummill Feb 26, 2026 02:07 PM	
	110	REPLACED HARNESS SEALS, INSTALLED TRAILING ARM AND REMOVED SHOCK STRUT FROM STAND. SEALED.	B0127528 - Mark Curtis Feb 21, 2026 05:12 AM	
	CSO// 6111/Comply with Landing Gear 96 Month Inspection on RH MLG		B0585124 - Michael Jones Feb 24, 2026 05:09 AM	
	111	INSTALLED HARNESS AND HONED BUSHINGS.	B0127528 - Mark Curtis Feb 24, 2026 05:08 AM	
	CSO// 6111/Comply with Landing Gear 96 Month Inspection on RH MLG		B0585124 - Michael Jones Feb 24, 2026 05:09 AM	
	112	INSTALLED CANON PLUGS AND VERIFIED CONTINUITY CHECK PASSED. SEALED AND SAFETY-WIRED SHOCK STRUT, THEN INSTALLED STRUT ASSEMBLY TO MAIN STRUCTURE.	B1017220 - Cameron Harrold Feb 24, 2026 08:42 PM	
	CSO// 6111/Comply with Landing Gear 96 Month Inspection on RH MLG		B0150944 - Adam Pummill Feb 26, 2026 02:07 PM	

Sequence #	7003	Aircraft SN #	6111	MWPWO #	2498069
WO #	4731591	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	113	TOUCHED UP PAINT, APPLIED TORQUE SEAL AND MARKINGS LUBED WITH AEROSHELL 7 AND REPAIRED CLAMPS ON HARNESS.	B0127528 - Mark Curtis Feb 25, 2026 02:41 AM	
	CSO// 6111/Comply with Landing Gear 96 Month Inspection on RH MLG		B0150944 - Adam Pummill Feb 26, 2026 02:07 PM	
	114	SERVICED SHOCK TO 45 PSI CURE DATE: 4Q22. CYCLES: 950.	B1017220 - Cameron Harrold Feb 25, 2026 02:44 PM	
	CSO// 6111/Comply with Landing Gear 96 Month Inspection on RH MLG		B0150944 - Adam Pummill Feb 26, 2026 02:07 PM	
	115	SERVICED SHOCK TO 45 PSI CURE DATE: 4Q22. CYCLES: 950.	B1017220 - Cameron Harrold Feb 25, 2026 02:48 PM	
	CSO// 6111/Comply with Landing Gear 96 Month Inspection on RH MLG		B0150944 - Adam Pummill Feb 26, 2026 02:07 PM	
	200	PERFORMED MAGNETIC PARTICLE INSPECTION TO MLG TRAILING ARM PIN PER ASTME 1444-21e1. NO RELEVANT INDICATIONS NOTED.	B0639786 - Christine Cannon Feb 17, 2026 03:27 AM	
	NDI SUPPORT - MAGNETIC PARTICLE		B0639786 - Christine Cannon Feb 17, 2026 03:28 AM	
	300	SIDE STAY PIN HAS NON-REPAIRABLE CORROSION. REJECTED AND ORDERED PART.	B0127528 - Mark Curtis Feb 20, 2026 04:42 AM	
	EVALUATE SIDE STAY PIN FOR REPAIR OF IDENTIFIED CORROSION		B0150944 - Adam Pummill Feb 26, 2026 02:07 PM	
	301	ENTERED IN ERROR		
			B0128603 - Rex Befort Feb 26, 2026 02:43 PM	
	400	ENTERDED IN ERROR	B0127528 - Mark Curtis Feb 20, 2026 04:45 AM	
			B0128603 - Rex Befort Feb 26, 2026 02:43 PM	

Bombardier

Sequence #	7003	Aircraft SN #	6111	MWPWO #	2498069
WO #	4731591	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	500	ENTERED IN EROR	B0127528 - Mark Curtis Feb 20, 2026 04:45 AM	
			B0128603 - Rex Befort Feb 26, 2026 02:43 PM	

REMOVE AND RE-INSTALL DETAILS

	Removed Part # / Removed Serial #	Removed By	Removed - Part Description	Reference	Installed Part # / Installed Serial #	Installed By
	Removed Status	**Removed Date-Time**	**Position**	**Installed Part Status**	**Installed Part Description**	**Installed Date-Time**
	6350-3 13CPS0142	B1017220 - Cameron Harrold	PIN ASSY, SIDESTAY	CORROSION	6350-3 24SPP01358	
	UNSERVICEABLE	Feb 16, 2026 9:15 AM		NEW	PIN ASSY, SIDESTAY	Feb 25, 2026 9:15 AM
	19130-101	B1017220 - Cameron Harrold	RING, ASSY, LOCK	CORROSION	19130-101	B1017220 - Cameron Harrold
	UNSERVICEABLE	Feb 16, 2026 9:19 AM		NEW	RING, ASSY, LOCK	Feb 20, 2026 9:19 AM
	19125-1	B1017220 - Cameron Harrold	BEARING, UPPER, MLG	CORROSION	19125-1	B1017220 - Cameron Harrold
	UNSERVICEABLE	Feb 16, 2026 9:21 AM		NEW	BEARING, UPPER, MLG	Feb 20, 2026 9:21 AM

TOOL INFORMATION

Tool ID	Tool Description	Calibration Due Date
L0287	MAG BENCH	May 12, 2026 5:00 PM
336096	GAUSS METER	Apr 26, 2026 5:00 PM
L1994	TORQUE WRENCH	Dec 28, 2026 5:00 PM

QA005 RTS Statement

The component identified above was repaired and inspected in accordance with current Federal Aviation Regulations, found airworthy and is approved for return to service with respect to the work performed

Sequence #	7003	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4731591	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

Inspected By :	
B0128603 > Rex Befort	**Date:** 2026-02-26

Sequence #	7004	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4738329	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

7004	**WO #**	**4738329**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #	20322023	No Log Entry	
7004/CSO// 6111/Comply with Landing Gear 96 Month Inspection on NLG Actuator				

Bombardier

Sequence #	7004	Aircraft SN #	6111	MWPWO #	2498069
WO #	4738329	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	THE FOLLOWING WORK IS PERFORMED IN ACCORDANCE WITH BOMBARDIER CHALLENGER 65 AMM (PART 2) REVISION 35 DATED 15 OCT. 2025 TASK 32-00-01-216 AND SAFRAN CMM 32-32-65 REVISION 17 DATED 1 JUNE 2025. PERFORMED PRELIMINARY INSPECTION, NO DEFECTS NOTED. DISASSEMBLED, CLEANED, INSPECTED, NO DEFECTS NOTED. REMOVED PAINT & CLEANED IN PREPARATION FOR REPAINT.	B0129180 - Aaron Carpenter Feb 11, 2026 04:45 AM	
	CSO// 6111/Comply with Landing Gear 96 Month Inspection on NLG Actuator		B0585124 - Michael Jones Feb 20, 2026 12:34 AM	
	101	MASKED, PRIMED, PAINTED, ORDERED PARTS.	B0129180 - Aaron Carpenter Feb 13, 2026 04:40 AM	
	CSO// 6111/Comply with Landing Gear 96 Month Inspection on NLG Actuator		B0585124 - Michael Jones Feb 19, 2026 11:53 PM	
	102	ASSEMBLED COMPLETELY. READY TO TEST.	B0129180 - Aaron Carpenter Feb 13, 2026 04:44 AM	
	CSO// 6111/Comply with Landing Gear 96 Month Inspection on NLG Actuator		B0585124 - Michael Jones Feb 19, 2026 11:53 PM	
	103	FUNCTION TEST PASSED.	B0129180 - Aaron Carpenter Feb 14, 2026 04:54 AM	
	CSO// 6111/Comply with Landing Gear 96 Month Inspection on NLG Actuator		B0585124 - Michael Jones Feb 19, 2026 11:53 PM	
	104	ENTERED IN ERROR	B0585124 - Michael Jones Feb 28, 2026 05:25 AM	
	ENTERED IN ERROR		B0585124 - Michael Jones Feb 28, 2026 05:26 AM	09

Sequence #	7004	Aircraft SN #	6111	MWPWO #	2498069
WO #	4738329	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	200	THE FOLLOWING WORK IS PERFORMED IN ACCORDANCE WITH BOMBARDIER CHALLENGER 650 AMM (PART 2) REVISION 35 DATED 15 OCT. 2025 TASK 32-00-01-216 AND SAFRAN CMM 32-32-65 REVISION 17 DATED 1 JUNE 2025. PERFORMED PRELIMINARY INSPECTION, NO DEFECTS NOTED. DISASSEMBLED, CLEANED, INSPECTED, NO DEFECTS NOTED. REMOVED PAINT & CLEANED IN PREPARATION FOR REPAINT.	B0129180 - Aaron Carpenter Feb 20, 2026 03:05 AM	
	CORRECTION FOR OPERATION 100.		B0585124 - Michael Jones Feb 20, 2026 03:51 AM	

TOOL INFORMATION

Tool ID	Tool Description	Calibration Due Date
34903068	TORQUE WRENCH	Sep 2, 2026 5:00 PM
361196	GAUGE	Sep 10, 2026 5:00 PM
372023	GAUGE	Sep 10, 2026 5:00 PM

QA005 RTS Statement

The component identified above was repaired and inspected in accordance with current Federal Aviation Regulations, found airworthy and is approved for return to service with respect to the work performed

Inspected By :

B0585124 > Michael Jones **Date:** 2026-02-27

Sequence #	7005	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4738325	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

			LOG BOOK VERBIAGE	Deferrals
7005	**WO #**	**4738325**		
	SAP SVO #	20321913	No Log Entry	
7005/CSO// 6111/Comply with Landing Gear 96 Month Inspection on LH MLG				

Sequence #	7005	Aircraft SN #	6111	MWPWO #	2498069
WO #	4738325	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	THE FOLLOWING WORK PERFORMED IS IN ACCORDANCE WITH BOMBARDIER CHALLENGER 650 AIRCRAFT MANUAL CHAPTER 05 TASK NO. 32-00-01-215 REV.35 DATED 15/OCT/2025, SAFRAN COMPONENT MAINTENANCE MANUAL 19090 CHAPTER 32-10-16 REV.27 DATED 01/JUN/2025. RECEIVED WITHOUT SIDE STRUT PIN ASSY OR TOP AUX ACTUATOR BOLT. BEGAN TEARDOWN.	B0127528 - Mark Curtis Feb 12, 2026 05:19 AM	
	CSO// 6111/Comply with Landing Gear 96 Month Inspection on LH MLG		B0585124 - Michael Jones Feb 14, 2026 04:53 AM	
	101	CONTINUED DISASSEMBLY AND WASHED PARTS AND HARNESS.	B1017591 - Stacy Kennedy Feb 12, 2026 08:57 PM	
	CSO// 6111/Comply with Landing Gear 96 Month Inspection on LH MLG		B0585124 - Michael Jones Feb 14, 2026 04:53 AM	
	102	FOUND TRAILING ARM SHOCK STRUT PIN WAS SEIZED IN SPHERICAL BEARING, SEND TO NDI TO CHECK FOR CRACKS OR DEFECTS. CLEANED ALL PARTS. POLISHED PISTON, PINS AND AXLE. COMPLETED VISUAL INSPECTION, REJECTED LOWER BEARING FOR NON-REPAIRABLE CORROSION.	B1020834 - Ezequiel Reyes Feb 13, 2026 04:24 AM	
	CSO// 6111/Comply with Landing Gear 96 Month Inspection on LH MLG		B0585124 - Michael Jones Feb 14, 2026 04:53 AM	
	103	BEGAN PREPPING FOR PAINT.	B1020834 - Ezequiel Reyes Feb 14, 2026 04:47 AM	
	CSO// 6111/Comply with Landing Gear 96 Month Inspection on LH MLG		B0585124 - Michael Jones Feb 14, 2026 04:54 AM	
	104	DID NOT RECEIVE BELL CRANK.	B1020834 - Ezequiel Reyes Feb 14, 2026 04:55 AM	
	CSO// 6111/Comply with Landing Gear 96 Month Inspection on LH MLG		B0585124 - Michael Jones Feb 14, 2026 04:58 AM	

Sequence #	7005	Aircraft SN #	6111	MWPWO #	2498069
WO #	4738325	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	105	BLASTED SMALL PARTS AND WASHED. CONTINUED PREPPING FOR PAINT.	B1017591 - Stacy Kennedy Feb 16, 2026 08:58 PM	
	CSO// 6111/Comply with Landing Gear 96 Month Inspection on LH MLG		B0585124 - Michael Jones Feb 19, 2026 09:51 PM	
	106	COMPLETED PREPPING FOR PAINT.	B1020834 - Ezequiel Reyes Feb 17, 2026 05:04 AM	
	CSO// 6111/Comply with Landing Gear 96 Month Inspection on LH MLG		B0585124 - Michael Jones Feb 19, 2026 09:51 PM	
	107	CONTINUED PREPPING FOR PAINT. PRIMED. ORDERED LOWER BEARING AND LOCK RING.	B1017591 - Stacy Kennedy Feb 17, 2026 08:57 PM	
	CSO// 6111/Comply with Landing Gear 96 Month Inspection on LH MLG		B0585124 - Michael Jones Feb 19, 2026 09:51 PM	
	108	PAINTED GREY.	B1020834 - Ezequiel Reyes Feb 18, 2026 04:27 AM	
	CSO// 6111/Comply with Landing Gear 96 Month Inspection on LH MLG		B0585124 - Michael Jones Feb 19, 2026 09:51 PM	
	109	HAD PAINT BOUGHT OFF AND UNMASKED ALL PARTS. HAD SERIAL NUMBERS VERIFIED AND INSTALLED AXLE IN TRAILING ARM AND SEALED. TORQUED USING ID: L1994 DUE 29-DEC-26. INSTALLED THE BRACKETS AND LOCKING PLATE ON MAIN AND SEALED.	B1017591 - Stacy Kennedy Feb 18, 2026 08:48 PM	
	CSO// 6111/Comply with Landing Gear 96 Month Inspection on LH MLG		B0150944 - Adam Pummill Feb 24, 2026 02:27 PM	
	110	ASSEMBLED SHOCK STRUT USING NEW PARTS AS LISTED. SEALED LOCK SEGMENTS. TORQUED AS REQUIRED. CURE DATE: 1Q21.	B1020834 - Ezequiel Reyes Feb 19, 2026 05:13 AM	
	CSO// 6111/Comply with Landing Gear 96 Month Inspection on LH MLG		B0150944 - Adam Pummill Feb 25, 2026 02:23 PM	
	111	PUT SHOCK STRUT ON LEAK AND PRESSURE TEST.	B1017220 - Cameron Harrold Feb 19, 2026 08:36 PM	
	CSO// 6111/Comply with Landing Gear 96 Month Inspection on LH MLG		B0585124 - Michael Jones Feb 19, 2026 09:51 PM	

Sequence #	7005	Aircraft SN #	6111	MWPWO #	2498069
WO #	4738325	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	112	INSTALLED TRAILING ARM AND BEGAN HARNESS INSTALL. SHOCK STRUT LEAK/ PRESSURE GOOD. SEALED.	B0127528 - Mark Curtis Feb 20, 2026 05:15 AM	
	CSO// 6111/Comply with Landing Gear 96 Month Inspection on LH MLG		B0150944 - Adam Pummill Feb 25, 2026 02:23 PM	
	113	COMPLETED HARNESS INSTALL REJECTED FITTING, DISCONNECT, QUICK FOR STICKING AND WEAR ORDERED NEW. SEALED AND SAFETY WIRED SHOCK STRUT.	B1017220 - Cameron Harrold Feb 20, 2026 08:35 PM	
	CSO// 6111/Comply with Landing Gear 96 Month Inspection on LH MLG		B0150944 - Adam Pummill Feb 25, 2026 02:23 PM	
	114	REPLACED HARNESS SEALS, INSTALLED HARNESS, SET WOW GAPS, CONTINUED ASSEMBLY, SEALED AND SAFETYWIRED.	B1020834 - Ezequiel Reyes Feb 21, 2026 05:04 AM	
	CSO// 6111/Comply with Landing Gear 96 Month Inspection on LH MLG		B0150944 - Adam Pummill Feb 25, 2026 02:23 PM	
	115	INSTALLED SHOCK STRUT. REPLACED QUICK DISCONNECT FITTINGS AND SEALS. INSTALLED NEW PLACARD. LUBRICATED WITH AEROSHELL 7, TORQUE SEALED, AND SERVICED SHOCK TO 45 PSI.	B1017220 - Cameron Harrold Feb 23, 2026 08:43 PM	
	CSO// 6111/Comply with Landing Gear 96 Month Inspection on LH MLG		B0150944 - Adam Pummill Feb 25, 2026 02:23 PM	
	116	COMPLETED FINAL TOUCH-UP AND CONTINUITY CHECK ON HARNESS. CURE DATE: 1Q21. 950 CYCLES.	B1017220 - Cameron Harrold Feb 24, 2026 02:06 PM	
	CSO// 6111/Comply with Landing Gear 96 Month Inspection on LH MLG		B0150944 - Adam Pummill Feb 25, 2026 02:23 PM	
	200	PERFORMED MAGNETIC PARTICLE INSPECTION TO MLG TRAILING ARM PIN PER ASTME 1444-21e1. NO RELEVANT INDICATIONS NOTED.	B0639786 - Christine Cannon Feb 17, 2026 02:33 AM	
	NDI SUPPORT - MAGNETIC PARTICLE		B0639786 - Christine Cannon Feb 17, 2026 02:34 AM	
	300	COMPLETED VERIFICATION OF SERIAL NUMBERS PRIOR TO PAINT.	B0585124 - Michael Jones Feb 17, 2026 03:52 AM	
	VERIFY SERIAL NUMBERS PRIOR TO PAINT.		B0585124 - Michael Jones Feb 17, 2026 03:52 AM	

Sequence #	7005	Aircraft SN #	6111	MWPWO #	2498069
WO #	4738325	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	400	FOD CHECK COMPLIED WITH PRIOR TO ASSEMBLY, NO FOD NOTED	B0585124 - Michael Jones Feb 19, 2026 05:15 AM	
	FOD CHECK REQUIRED PRIOR TO ASSEMBLY		B0150944 - Adam Pummill Feb 25, 2026 02:23 PM	
	500	SIDE STAY PIN HAS NON-REPAIRABLE CORROSION. REJECTED AND ORDERED PART.	B0150944 - Adam Pummill Feb 26, 2026 02:04 PM	
	EVALUATE SIDE STAY PIN FOR REPAIR OF IDENTIFIED CORROSION		B0128603 - Rex Befort Feb 26, 2026 02:17 PM	

REMOVE AND RE-INSTALL DETAILS

	Removed Part # / Removed Serial #	Removed By	Removed - Part Description	Reference	Installed Part # / Installed Serial #	Installed By
	Removed Status	Removed Date-Time	Position	Installed Part Status	Installed Part Description	Installed Date-Time
	19130-101	B1017220 - Cameron Harrold	RING, ASSY, LOCK	corrosion	19130-101	B1017220 - Cameron Harrold
	UNSERVICEABLE	Feb 13, 2026 8:48 AM		NEW	RING, ASSY, LOCK	Feb 19, 2026 8:48 AM
	19128-1	B1017220 - Cameron Harrold	BEARING, LOWER, MLG	corrosion	19128-1	B1017220 - Cameron Harrold
	UNSERVICEABLE	Feb 13, 2026 8:53 AM		NEW	BEARING, LOWER, MLG	Feb 19, 2026 8:53 AM
	6350-3 14SPP00580	B1017220 - Cameron Harrold	PIN ASSY, SIDESTAY	CORROSION	6350-3 24SPP01360	B1017220 - Cameron Harrold
	UNSERVICEABLE	Feb 13, 2026 8:57 AM		NEW	PIN ASSY, SIDESTAY	Feb 25, 2026 8:57 AM

Sequence #	7005	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4738325	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

TOOL INFORMATION

Tool ID	Tool Description	Calibration Due Date
L0287	MAG BENCH	May 12, 2026 5:00 PM
336096	GAUSS METER	Apr 26, 2026 5:00 PM
329003	TORQUE WRENCH	Dec 28, 2026 5:00 PM
K0012	TORQUE WRENCH	Aug 3, 2026 5:00 PM
L1786	TORQUE WRENCH	Nov 9, 2026 5:00 PM

QA005 RTS Statement

The component identified above was repaired and inspected in accordance with current Federal Aviation Regulations, found airworthy and is approved for return to service with respect to the work performed

Inspected By :

B0128603 > Rex Befort **Date:** 2026-02-26

Sequence #	7006	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4738356	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

			LOG BOOK VERBIAGE	Deferrals
7006	**WO #**	**4738356**		
	SAP SVO #	20322073	No Log Entry	
7006/CSO// 6111/Comply with Landing Gear 96 Month Inspection on NLG Drag Brace				

Sequence #	7006	Aircraft SN #	6111	MWPWO #	2498069
WO #	4738356	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	THE FOLLOWING WORK DONE IN ACCORDANCE WITH BOMBARDIER CHALLENGER 650 AIRCRAFT MAINTENANCE MANUAL (PART 2) PUBLICATION NUMBER CH-650 AMM REVISION 35 DATED OCT-15-2025 TASK 32-00-01-216 AND THE SAFRAN LANDING SYSTEMS NOSE LANDING GEAR DRAG BRACE COMPONENT MAINTENANCE MANUAL NUMBER 32-70-06 REVISION 13 DATED SEP-01-2025. DISASSEMBLED, CLEANED AND INSPECTED. CAM IS DAMAGED WHERE IT MATES TO THE LOCKING ROD. NO OTHER ISSUES NOTED. REMOVED PAINT & CLEANED TO PREPARE FOR REPAINT.	B0129180 - Aaron Carpenter Feb 11, 2026 04:34 AM	
	CSO// 6111/Comply with Landing Gear 96 Month Inspection on NLG Drag Brace		B0585124 - Michael Jones Feb 20, 2026 02:55 AM	
	101	MASKED, PRIMED, PAINTED MATTERHORN WHITE.	B0129180 - Aaron Carpenter Feb 13, 2026 04:35 AM	
	CSO// 6111/Comply with Landing Gear 96 Month Inspection on NLG Drag Brace		B0585124 - Michael Jones Feb 20, 2026 02:55 AM	
	102	BEGAN REASSEMBLY USING NEW CAM S/N MER8284, INSTALLED LOCK MECHANISM, BEGAN HARNESS INSTALL, WILL HAVE TO RE-SHIM CAM STOPS.	B0129180 - Aaron Carpenter Feb 13, 2026 04:38 AM	
	CSO// 6111/Comply with Landing Gear 96 Month Inspection on NLG Drag Brace		B0585124 - Michael Jones Feb 20, 2026 02:55 AM	
	103	COMPLETED ASSEMBLY. FUNCTION TEST PASSED.	B0129180 - Aaron Carpenter Feb 14, 2026 04:36 AM	
	CSO// 6111/Comply with Landing Gear 96 Month Inspection on NLG Drag Brace		B0585124 - Michael Jones Feb 20, 2026 02:55 AM	
	104	Complied with: CSO// 6111/Comply with Landing Gear 96 Month Inspection on NLG Drag Brace	B0129180 - Aaron Carpenter Feb 14, 2026 05:07 AM	
	CSO// 6111/Comply with Landing Gear 96 Month Inspection on NLG Drag Brace		B0585124 - Michael Jones Feb 20, 2026 02:55 AM	

Sequence #	7006	Aircraft SN #	6111	MWPWO #	2498069
WO #	4738356	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	200	COMPLETED FOD INSPECTION AND PAINT INSPECTION. NO FOD NOTED.	B0585124 - Michael Jones Feb 13, 2026 03:48 AM	
	FOD INSPECTION AND PAINT INSPECTION REQUIRED PRIOR TO ASSEMBLY		B0585124 - Michael Jones Feb 20, 2026 02:55 AM	

TOOL INFORMATION

Tool ID	Tool Description	Calibration Due Date
361196	GAUGE	Sep 10, 2026 5:00 PM

QA005 RTS Statement

The component identified above was repaired and inspected in accordance with current Federal Aviation Regulations, found airworthy and is approved for return to service with respect to the work performed

Inspected By :

B0585124 > Michael Jones **Date:** 2026-02-27

Bombardier

Sequence #	7007	Aircraft SN #	6111	MWPWO #	2498069
WO #	4738352	Aircraft Reg #	XA-SOL	Parent WO #	2498069

7007	WO #	4738352	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13497285	No Log Entry	
7007/CSO// 6111/Comply with Landing Gear 96 Month Inspection on NLG Shock Strut				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100 CSO// 6111/Comply with Landing Gear 96 Month Inspection on NLG Shock Strut	THE FOLLOWING WORK ACCOMPLISHED IAW CHALLENGER 650 MAINTENANCE MANUAL REV 35 DATED OCT 15/2025, CHAPTER 5, TASK NO. 32-00-01-216 96 MONTH DETAILED INSPECTION OF NLG ASSEMBLY AND SAFRAN NOSE LANDING GEAR COMPONENT MAINTENANCE MANUAL PART NUMBER 20020 32-20-05, REV 23 DATED SEP 01/2025. DID NOT RECEIEVE AXLE NUTS OR AXLE SPACERS. COMPLETED DISASSEMBLY. PREPPED CYLINDER FOR SLEEVE REMOVAL. HUNTER HOLT, 57292, 02/10/26.		
	200 COMPLETE SERIAL NUMBER VERIFICATION PRIOR TO PAINT	VERIFIED ALL SERIAL NUMBERS PRIOR TO PAINT	B0585124 - Michael Jones Feb 17, 2026 12:53 AM B0585124 - Michael Jones Feb 17, 2026 12:53 AM	

QA005 RTS Statement

The component identified above was repaired and inspected in accordance with current Federal Aviation Regulations, found airworthy and is approved for return to service with respect to the work performed

Sequence #	7008	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4738366	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

7008	**WO #**	**4738366**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #	20322084	No Log Entry	
7008/CSO// 6111/Comply with Landing Gear 96 Month Inspection on LH MLG Side Brace				

Sequence #	7008	Aircraft SN #	6111	MWPWO #	2498069
WO #	4738366	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	THE FOLLOWING WORK PERFORMED IS IN ACCORDANCE WITH BOMBARDIER CHALLENGER 650 AIRCRAFT MAINTENANCE MANUAL CHAPTER 5 TASK# 32-00-01-215 REV: 35 DATED:OCT 15/25 AND CMM 32-30-30, REV: 13 DATED:JUN 01/25. STARTED DISASSEMBLING ACTUATOR MARCUS LEONARD 57406, 2-17-2026	B0585124 - Michael Jones Feb 20, 2026 12:20 AM B1020692 - Marcus Leonard Feb 18, 2026 04:51 AM	
	CSO// 6111/Comply with Landing Gear 96 Month Inspection on LH MLG Side Brace		B0585124 - Michael Jones Feb 19, 2026 10:27 PM	
	101	COMPLETED DISASSEMBLY OF ACTUATOR. WASHED. RECORDED SERIAL #'S.	B1020692 - Marcus Leonard Feb 19, 2026 05:19 AM	
	CSO// 6111/Comply with Landing Gear 96 Month Inspection on LH MLG Side Brace		B0585124 - Michael Jones Feb 19, 2026 10:40 PM	
	102	SANDED AND BLASTED PARTS. WASHED PARTS. STARTED INSPECTION.	B1020692 - Marcus Leonard Feb 20, 2026 05:10 AM	
	CSO// 6111/Comply with Landing Gear 96 Month Inspection on LH MLG Side Brace		B0585124 - Michael Jones Feb 28, 2026 02:57 AM	
	103	FINISHED INSPECTION. COMPLETED ASSEMBLY OF ACTUATOR. READY FOR FUNCTION TESTING.	B1020692 - Marcus Leonard Feb 21, 2026 04:50 AM	
	CSO// 6111/Comply with Landing Gear 96 Month Inspection on LH MLG Side Brace		B0585124 - Michael Jones Feb 28, 2026 02:57 AM	
	104	IN THE PROCESS OF FUNCTION TESTING ACTUATOR.	B1020692 - Marcus Leonard Feb 25, 2026 03:56 AM	
	CSO// 6111/Comply with Landing Gear 96 Month Inspection on LH MLG Side Brace		B0585124 - Michael Jones Feb 28, 2026 02:57 AM	
	105	FOUND CORROSION IN ROD END CHROME. REPLACED ROD END. PASSED ALL FUNCTION TESTS. SAFETY WIRE INSTALLED AND PREPPED FOR SEALANT AND PAINT.	B1020692 - Marcus Leonard Feb 25, 2026 04:11 AM	
	CSO// 6111/Comply with Landing Gear 96 Month Inspection on LH MLG Side Brace		B0585124 - Michael Jones Feb 28, 2026 02:57 AM	

Sequence #	7008	Aircraft SN #	6111	MWPWO #	2498069
WO #	4738366	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	106	SEALED AND PRIMED ACTUATOR.	B1020692 - Marcus Leonard Feb 26, 2026 05:29 AM	
	CSO// 6111/Comply with Landing Gear 96 Month Inspection on LH MLG Side Brace		B0585124 - Michael Jones Feb 28, 2026 02:57 AM	
	107	PAINTED ACTUATOR. APPLIED TOUCH UP PAINT. INSTALLED CLAMPS.	B1020692 - Marcus Leonard Feb 27, 2026 05:15 AM	
	CSO// 6111/Comply with Landing Gear 96 Month Inspection on LH MLG Side Brace		B0585124 - Michael Jones Feb 28, 2026 02:57 AM	
	108	96 MONTH INSPECTION COMPLIED WITH. CURE DATE 2Q14. CYCLES 950. TAGGED REPAIRED.	B1020692 - Marcus Leonard Feb 28, 2026 03:32 AM	
	CSO// 6111/Comply with Landing Gear 96 Month Inspection on LH MLG Side Brace		B0585124 - Michael Jones Feb 28, 2026 05:34 AM	
	109	ENTERED IN ERROR	B0585124 - Michael Jones Feb 28, 2026 05:34 AM	
	ENTERED IN ERROR		B0585124 - Michael Jones Feb 28, 2026 05:34 AM	
	110	CORRECTED REV DATE ON CMM 32-30-30, REV: 12 TO MAY 31/25.	B0585124 - Michael Jones Feb 28, 2026 02:09 PM	
	CSO// 6111/Comply with Landing Gear 96 Month Inspection on LH MLG Side Brace		B0150944 - Adam Pummill Feb 28, 2026 02:11 PM	09
	200	COMPLETED FOD CHECK PRIOR TO ASSEMBLY, NO FOD NOTED.	B0585124 - Michael Jones Feb 21, 2026 01:59 AM	
	FOD CHECK REQUIRED PRIOR TO ASSEMBLY		B0585124 - Michael Jones Feb 21, 2026 02:00 AM	
	300	COMPLETED PAINT INSPECTION	B0585124 - Michael Jones Feb 28, 2026 02:46 AM	
	PAINT INSPECTION REQUIRED		B0585124 - Michael Jones Feb 28, 2026 02:46 AM	

Sequence #	7008	Aircraft SN #	6111	MWPWO #	2498069
WO #	4738366	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	400	THE FOLLOWING WORK PERFORMED IS IN ACCORDANCE WITH BOMBARDIER CHALLENGER 650 AIRCRAFT MAINTENANCE MANUAL CHAPTER 5 TASK# 32-00-01-215 REV: 35 DATED: OCT 15/25 AND CMM 32-30-30, REV: 12 DATED: JUN 01/25. STARTED DISASSEMBLING ACTUATOR	B1020692 - Marcus Leonard Feb 28, 2026 03:52 AM	
	CORRECTION FOR OPERATION 100		B0585124 - Michael Jones Feb 28, 2026 05:35 AM	

TOOL INFORMATION

Tool ID	Tool Description	Calibration Due Date
K0013	TORQUE WRENCH	Mar 18, 2026 5:00 PM
DDC3446	TORQUE WWRENCH	Aug 3, 2026 5:00 PM
809575	TORQUE WRENCH	Mar 9, 2026 5:00 PM
329003	TORQUE WRENCH	Dec 28, 2026 5:00 PM

QA005 RTS Statement

The component identified above was repaired and inspected in accordance with current Federal Aviation Regulations, found airworthy and is approved for return to service with respect to the work performed

Inspected By :

B0585124 > Michael Jones **Date:** 2026-02-28

Sequence #	7009	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4738376	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

7009	**WO #**	**4738376**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #	20321914	No Log Entry	
7009/CSO// 6111/Comply with Landing Gear 96 Month Inspection on RH MLG Side Brace				

Sequence #	7009	Aircraft SN #	6111	MWPWO #	2498069
WO #	4738376	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	THE FOLLOWING WORK PERFORMED IS IN ACCORDANCE WITH BOMBARDIER CHALLENGER 650 AIRCRAFT MAINTENANCE MANUAL CHAPTER 5 TASK# 32-00-01-215 REV: 35 DATED:OCT 15/25 AND CMM 32-30-30, REV: 13 DATED:JUN 01/25. STARTED DISASSEMBLING ACTUATOR MARCUS LEONARD 57406, 2-17-2026	B1020692 - Marcus Leonard Feb 18, 2026 04:52 AM	
	CSO// 6111/Comply with Landing Gear 96 Month Inspection on RH MLG Side Brace		B0585124 - Michael Jones Feb 28, 2026 03:04 AM	
	101	COMPLETED DISASSEMBLY OF ACTUATOR. WASHED AND RECORDED SERIAL #'S.	B1020692 - Marcus Leonard Feb 19, 2026 05:17 AM	
	CSO// 6111/Comply with Landing Gear 96 Month Inspection on RH MLG Side Brace		B0585124 - Michael Jones Feb 28, 2026 03:04 AM	
	102	SANDED AND BLASTED PARTS. WASHED PARTS. CONDUCTED INSPECTION. PUT ORINGS AND PACKINGS ON INTERNAL PARTS. STARTED ASSEMBLY.	B1020692 - Marcus Leonard Feb 20, 2026 05:04 AM	
	CSO// 6111/Comply with Landing Gear 96 Month Inspection on RH MLG Side Brace		B0585124 - Michael Jones Feb 28, 2026 03:04 AM	
	103	COMPLETED ASSEMBLY OF ACTUATOR. READY FOR FUNCTION TESTING.	B1020692 - Marcus Leonard Feb 21, 2026 04:58 AM	
	CSO// 6111/Comply with Landing Gear 96 Month Inspection on RH MLG Side Brace		B0585124 - Michael Jones Feb 28, 2026 03:04 AM	
	104	IN THE PROCESS OF FUNCTION TESTING ACTUATOR.	B1020692 - Marcus Leonard Feb 25, 2026 03:49 AM	
	CSO// 6111/Comply with Landing Gear 96 Month Inspection on RH MLG Side Brace		B0585124 - Michael Jones Feb 28, 2026 03:04 AM	
	105	FINISHED FUNCTION TESTING ACTUATOR. TRANSFER TUBE NEEDED REPLACEMENT DUE TO FAILURE ON THE HYDRAULIC TEST STAND. REPLACED TRANSFER TUBE. PASSED ALL FUNCTIONAL TESTS. BEGAN SAFETY WIRE, PREPPING FOR SEALENT AND PAINT.	B1020692 - Marcus Leonard Feb 25, 2026 04:13 AM	
	CSO// 6111/Comply with Landing Gear 96 Month Inspection on RH MLG Side Brace		B0585124 - Michael Jones Feb 28, 2026 03:04 AM	

Sequence #	7009	Aircraft SN #	6111	MWPWO #	2498069
WO #	4738376	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	106	SEALED AND PRIMED ACTUATOR.	B1020692 - Marcus Leonard Feb 26, 2026 05:28 AM	
	CSO// 6111/Comply with Landing Gear 96 Month Inspection on RH MLG Side Brace		B0585124 - Michael Jones Feb 28, 2026 03:04 AM	
	107	PAINTED ACTUATOR. APPLIED TOUCH UP PAINT. INSTALLED CLAMPS.	B1020692 - Marcus Leonard Feb 27, 2026 05:14 AM	
	CSO// 6111/Comply with Landing Gear 96 Month Inspection on RH MLG Side Brace		B0585124 - Michael Jones Feb 28, 2026 03:04 AM	
	108	96 MONTH INSPECTION COMPLIED. CURE DATE 2Q14. CYCLES 900. TAGGED REPAIRED.	B0585124 - Michael Jones Feb 28, 2026 05:58 AM B1020692 - Marcus Leonard Feb 28, 2026 03:34 AM	
	CSO// 6111/Comply with Landing Gear 96 Month Inspection on RH MLG Side Brace		B0585124 - Michael Jones Feb 28, 2026 03:56 AM	
	109	CORRECTED CMM REV DATE FOR 32-30-30, TO REV:12 DATED: MAY 31/25.	B0585124 - Michael Jones Feb 28, 2026 02:05 PM	
	CSO// 6111/Comply with Landing Gear 96 Month Inspection on RH MLG Side Brace		B0150944 - Adam Pummill Feb 28, 2026 02:10 PM	09
	110	CORRECTED CMM REV DATE FOR 32-30-30, TO REV:12 DATED: MAY 31/25.	B0585124 - Michael Jones Feb 28, 2026 02:47 PM	
	CSO// 6111/Comply with Landing Gear 96 Month Inspection on RH MLG Side Brace		B0150944 - Adam Pummill Feb 28, 2026 03:21 PM	09
	200	COMPLETED FOD CHECK PRIOR TO ASSEMBLY, NO FOD NOTED	B0585124 - Michael Jones Feb 21, 2026 02:02 AM	
	FOD CHECK REQUIRED PRIOR TO ASSEMBLY		B0585124 - Michael Jones Feb 21, 2026 02:02 AM	

Bombardier

Sequence #	7009	Aircraft SN #	6111	MWPWO #	2498069
WO #	4738376	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	300	PAINT INSPECTION COMPLETED	B0585124 - Michael Jones Feb 28, 2026 03:01 AM	
	PAINT INSPECTION REQUIRED		B0585124 - Michael Jones Feb 28, 2026 03:01 AM	
	400	THE FOLLOWING WORK PERFORMED IS IN ACCORDANCE WITH BOMBARDIER CHALLENGER 650 AIRCRAFT MAINTENANCE MANUAL CHAPTER 5 TASK# 32-00-01-215 REV: 35 DATED: OCT 15/25 AND CMM 32-30-30, REV: 12 DATED: JUN 01/25. STARTED DISASSEMBLING ACTUATOR	B1020692 - Marcus Leonard Feb 28, 2026 04:03 AM	
	CORRECTION TO OPERATION 100 IMPROPER REV LEVEL FOR CMM 32-30-30		B0585124 - Michael Jones Feb 28, 2026 05:50 AM	
	500	96 MONTH INSPECTION COMPLIED WITH. CURE DATE 2Q14. CYCLES 950. TAGGED REPAIRED.	B1020692 - Marcus Leonard Feb 28, 2026 04:03 AM	
	CORRECTION FOR OPERATION 108.		B0585124 - Michael Jones Feb 28, 2026 05:50 AM	

TOOL INFORMATION

Tool ID	Tool Description	Calibration Due Date
329003	torque wrench	Dec 28, 2026 5:00 PM
K0013	TORQUE WRENCH	Mar 18, 2026 5:00 PM
DDC3446	TORQUE WRENCH	Aug 3, 2026 5:00 PM
809575	TORQUE WRENCH	Mar 9, 2026 5:00 PM

QA005 RTS Statement

The component identified above was repaired and inspected in accordance with current Federal Aviation Regulations, found airworthy and is approved for return to service with respect to the work performed

Inspected By :

B0585124 > Michael Jones **Date:** 2026-02-28

Bombardier

Sequence #	7010	Aircraft SN #	6111	MWPWO #	2498069
WO #	4757584	Aircraft Reg #	XA-SOL	Parent WO #	2498069

7010	WO #	4757584	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	20322182	No Log Entry	
CSO/ 6111/ FWD ELPS/ Comply with TLMC Task 33-50-00-201, Functional Test of the Emergency Lights Power−Supply PN 60-1321-1, SN 26450.				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Entered in Error. Incorrect ELPS location. See WO 4757932 for work performed	B0629148 - Robert Greaves Feb 11, 2026 10:39 PM	
	CSO/ 6111/ FWD ELPS/ Comply with TLMC Task 33-50-00-201, Functional Test of the Emergency Lights Power−Supply PN 60-1321-1, SN 26450.		B0623124 - Michael Stacy Feb 11, 2026 11:07 PM	

QA005 RTS Statement

The component identified above was repaired and inspected in accordance with current Federal Aviation Regulations, found airworthy and is approved for return to service with respect to the work performed

Inspected By :

B1017318 > Steve Pritchett **Date:** 2026-02-18

Bombardier

Sequence #	7011	Aircraft SN #	6111	MWPWO #	2498069
WO #	4757612	Aircraft Reg #	XA-SOL	Parent WO #	2498069

7011	WO #	4757612	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	20322181	No Log Entry	
CSO/ 6111/ FWD ELPS/ Comply with TLMC Task 33-50-00-201, Functional Test of the Emergency Lights Power−Supply PN 60-1321-1, SN 26449				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Entered in Error. Incorrect ELPS location. See WO 4757940 for work performed	B0629148 - Robert Greaves Feb 11, 2026 10:41 PM	
	CSO/ 6111/ FWD ELPS/ Comply with TLMC Task 33-50-00-201, Functional Test of the Emergency Lights Power−Supply PN 60-1321-1, SN 26449		B0623124 - Michael Stacy Feb 11, 2026 11:10 PM	

QA005 RTS Statement

The component identified above was repaired and inspected in accordance with current Federal Aviation Regulations, found airworthy and is approved for return to service with respect to the work performed

Inspected By :

B1017318 > Steve Pritchett **Date:** 2026-02-12

Bombardier

Sequence #	7012	Aircraft SN #	6111	MWPWO #	2498069
WO #	4757603	Aircraft Reg #	XA-SOL	Parent WO #	2498069

7012	WO #	4757603	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	20322090	No Log Entry	
CSO/ 6111/ FWD ELPS/ Comply with TLMC Task 33-50-00-201, Functional Test of the Emergency Lights Power−Supply PN 60-1321-1, SN 26448.				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Entered in Error. Incorrect ELPS location. See WO 4757935 for work performed	B0629148 - Robert Greaves Feb 11, 2026 10:40 PM	
	CSO/ 6111/ FWD ELPS/ Comply with TLMC Task 33-50-00-201, Functional Test of the Emergency Lights Power−Supply PN 60-1321-1, SN 26448.		B0623124 - Michael Stacy Feb 11, 2026 11:08 PM	

QA005 RTS Statement

The component identified above was repaired and inspected in accordance with current Federal Aviation Regulations, found airworthy and is approved for return to service with respect to the work performed

Inspected By :

B1017318 > Steve Pritchett **Date:** 2026-02-12

Bombardier

Sequence #	7013	Aircraft SN #	6111	MWPWO #	2498069
WO #	4757558	Aircraft Reg #	XA-SOL	Parent WO #	2498069

7013	WO #	4757558	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	20322183	No Log Entry	
CSO/ 6111/ FWD ELPS/ Comply with TLMC Task 33-50-00-201, Functional Test of the Emergency Lights Power−Supply PN 60-1321-1, SN 26447.				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Entered in Error. Incorrect ELPS location. See WO 4757921 for work performed	B0629148 - Robert Greaves Feb 11, 2026 10:37 PM	
	CSO/ 6111/ FWD ELPS/ Comply with TLMC Task 33-50-00-201, Functional Test of the Emergency Lights Power−Supply PN 60-1321-1, SN 26447.		B0623124 - Michael Stacy Feb 11, 2026 11:06 PM	

QA005 RTS Statement

The component identified above was repaired and inspected in accordance with current Federal Aviation Regulations, found airworthy and is approved for return to service with respect to the work performed

Inspected By :

B1017318 > Steve Pritchett **Date:** 2026-02-12

Sequence #	7014	Aircraft SN #	6111	MWPWO #	2498069
WO #	4757921	Aircraft Reg #	XA-SOL	Parent WO #	2498069

7014	WO #	4757921	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	20322025	Complied with TLMC Task 33-50-00-201 - Functional Test of the Emergency Lights Power−Supply PN 60-1321-1, SN 26447.	
CSO/ 6111/ FS280 ELPS/ Comply with TLMC Task 33-50-00-201, Functional Test of the Emergency Lights Power−Supply PN 60-1321-1, SN 26447.				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	INSPECTED. COMPLIED WITH TASK 33-50-00-201 FUNCTIONAL TEST (CAP CHECK) OF THE FS 280 EMERGENCY LIGHTS POWER-SUPPLIES (ELPS). CAP CHECK FAILED. REMOVED AND REPLACED BATTERY ASSEMBLY PN: 61-0478-9. VOLTAGE CHECKED GOOD. NO DEFECTS NOTED. ALL WORK DONE IAW HONEYWELL CMM 33-50-42. PN: 60-1321-1, SN: 26447.	B0143837 - David Bohl Mar 02, 2026 08:15 PM	
	CSO/ 6111/ FS280 ELPS/ Comply with TLMC Task 33-50-00-201, Functional Test of the Emergency Lights Power−Supply PN 60-1321-1, SN 26447.		B1013522 - Brandon Jennings Mar 02, 2026 09:19 PM	
	200	COMPLIED WITH PRELIMINARY INSPECTION OF THE FS 280 ELPS. NO DEFECTS NOTED. ALL WORK DONE IAW HONEYWELL CMM 33-50-42.	B0143837 - David Bohl Mar 02, 2026 08:15 PM	
	COMPLY WITH PRELIMINARY INSPECTION OF THE FS 280 ELPS.		B1013522 - Brandon Jennings Mar 02, 2026 09:19 PM	

REMOVE AND RE-INSTALL DETAILS

	Removed Part # / Removed Serial #	Removed By	Removed - Part Description	Reference	Installed Part # / Installed Serial #	Installed By
	Removed Status	Removed Date-Time	Position	Installed Part Status	Installed Part Description	Installed Date-Time
	61-0478-9	B0143837 - David Bohl	BATTERY ASSY	FAILED CAP CHECK	61-0478-9	B0143837 - David Bohl
	UNSERVICEABLE	Mar 2, 2026 1:05 PM		NEW	BATTERY ASSY	Mar 2, 2026 1:05 PM

Sequence #	7014	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4757921	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

TOOL INFORMATION

Tool ID	Tool Description	Calibration Due Date
TUSJ1726	MULTIMETER	Dec 30, 2026 5:00 PM

QA005 RTS Statement

The component identified above was repaired and inspected in accordance with current Federal Aviation Regulations, found airworthy and is approved for return to service with respect to the work performed

Bombardier

Sequence #	7015	Aircraft SN #	6111	MWPWO #	2498069
WO #	4757932	Aircraft Reg #	XA-SOL	Parent WO #	2498069

7015	WO #	4757932	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	20322026	No Log Entry	
CSO/ 6111/ GALLEY ELPS/ Comply with TLMC Task 33-50-00-201, Functional Test of the Emergency Lights Power−Supply PN 60-1321-1, SN 26450.				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	INSPECTED. COMPLIED WITH TASK 33-50-00-201 FUNCTIONAL TEST (CAP CHECK) OF THE GALLEY EMERGENCY LIGHTS POWER-SUPPLIES (ELPS). CAP CHECK FAILED. REMOVED AND REPLACED BATTERY ASSEMBLY PN: 61-0478-9. VOLTAGE CHECKED GOOD. NO DEFECTS NOTED. ALL WORK DONE IAW HONEYWELL CMM 33-50-42. PN: 60-1321-1, SN: 26450.	B0143837 - David Bohl Mar 03, 2026 01:59 PM	
	CSO/ 6111/ GALLEY ELPS/ Comply with TLMC Task 33-50-00-201, Functional Test of the Emergency Lights Power−Supply PN 60-1321-1, SN 26450.		B1013522 - Brandon Jennings Mar 03, 2026 02:25 PM	
	200	COMPLIED WITH PRELIMINARY INSPECTION OF THE GALLEY ELPS, SN: 26450. NO DEFECTS NOTED. ALL WORK DONE IAW HONEYWELL CMM 33-50-42.	B0143837 - David Bohl Mar 03, 2026 01:59 PM	
	COMPLY WITH PRELIMINARY INSPECTION OF THE GALLEY ELPS, SN: 26450.		B1013522 - Brandon Jennings Mar 03, 2026 02:25 PM	

REMOVE AND RE-INSTALL DETAILS

	Removed Part # / Removed Serial #	Removed By	Removed - Part Description	Reference	Installed Part # / Installed Serial #	Installed By
	Removed Status	Removed Date-Time	Position	Installed Part Status	Installed Part Description	Installed Date-Time
	61-0478-1	B0143837 - David Bohl	BATTERY ASSY	FAILED CAP CHECK	61-0478-1	B0143837 - David Bohl
	UNSERVICEABLE	Mar 3, 2026 6:52 AM		NEW	BATTERY ASSY	Mar 3, 2026 6:52 AM

Sequence #	7015	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4757932	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

TOOL INFORMATION

Tool ID	Tool Description	Calibration Due Date
TUSJ1726	MULTIMETER	Dec 30, 2026 5:00 PM

QA005 RTS Statement

The component identified above was repaired and inspected in accordance with current Federal Aviation Regulations, found airworthy and is approved for return to service with respect to the work performed

Bombardier

Sequence #	7016	Aircraft SN #	6111	MWPWO #	2498069
WO #	4757940	Aircraft Reg #	XA-SOL	Parent WO #	2498069

7016	WO #	4757940	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	20322184	Complied with TLMC Task 33-50-00-201 - Functional Test of the Emergency Lights Power−Supply PN 60-1321-1, SN 26449.	
CSO/ 6111/ AFT Baggage AFT Position ELPS/ Comply with TLMC Task 33-50-00-201, Functional Test of the Emergency Lights Power−Supply PN 60-1321-1, SN 26449.				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	INSPECTED. COMPLIED WITH TASK 33-50-00-201 FUNCTIONAL TEST (CAP CHECK) OF THE AFT BAGGAGE AFT POS. EMERGENCY LIGHTS POWER-SUPPLIES (ELPS). CAP CHECK FAILED. REMOVED AND REPLACED BATTERY ASSEMBLY PN: 61-0478-9. VOLTAGE CHECKED GOOD. NO DEFECTS NOTED. ALL WORK DONE IAW HONEYWELL CMM 33-50-42. PN: 60-1321-1, SN: 26449.	B0143837 - David Bohl Mar 03, 2026 01:27 PM	
	CSO/ 6111/ AFT Baggage AFT Position ELPS/ Comply with TLMC Task 33-50-00-201, Functional Test of the Emergency Lights Power−Supply PN 60-1321-1, SN 26449.		B1013522 - Brandon Jennings Mar 03, 2026 02:51 PM	
	200	COMPLIED WITH PRELIMINARY INSPECTION OF THE AFT BAGGAGE AFT POSITION, SN: 26449 ELPS. NO DEFECTS NOTED. ALL WORK DONE IAW HONEYWELL CMM 33-50-42.	B0143837 - David Bohl Mar 03, 2026 01:27 PM	
	COMPLY WITH PRELIMINARY INSPECTION OF THE AFT BAGGAGE AFT POSITION, SN: 26449 ELPS.		B1013522 - Brandon Jennings Mar 03, 2026 02:51 PM	

REMOVE AND RE-INSTALL DETAILS

	Removed Part # / Removed Serial #	Removed By	Removed - Part Description	Reference	Installed Part # / Installed Serial #	Installed By
	Removed Status	Removed Date-Time	Position	Installed Part Status	Installed Part Description	Installed Date-Time
	61-0478-9	B0143837 - David Bohl	BATTERY ASSY	FAILED CAP CHECK	61-0478-9	B0143837 - David Bohl
	UNSERVICEABLE	Mar 3, 2026 6:22 AM		NEW	BATTERY ASSY	Mar 3, 2026 6:22 AM

Sequence #	7016	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4757940	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

TOOL INFORMATION

Tool ID	Tool Description	Calibration Due Date
TUSJ1726	MULTIMETER	Dec 30, 2026 5:00 PM

QA005 RTS Statement

The component identified above was repaired and inspected in accordance with current Federal Aviation Regulations, found airworthy and is approved for return to service with respect to the work performed

Bombardier

Sequence #	7017	Aircraft SN #	6111	MWPWO #	2498069
WO #	4757935	Aircraft Reg #	XA-SOL	Parent WO #	2498069

7017	WO #	4757935	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	20322027	No Log Entry	
CSO/ 6111/ AFT Baggage FWD Position ELPS/ Comply with TLMC Task 33-50-00-201, Functional Test of the Emergency Lights Power−Supply PN 60-1321-1, SN 26448.				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	INSPECTED. COMPLIED WITH TASK 33-50-00-201 FUNCTIONAL TEST (CAP CHECK) OF THE AFT BAGGAGE FWD EMERGENCY LIGHTS POWER-SUPPLIES (ELPS). CAP CHECK GOOD. NO DEFECTS NOTED. ALL WORK DONE IAW HONEYWELL CMM 33-50-42. PN: 60-1321-1, SN: 26448.	B0143837 - David Bohl Mar 02, 2026 08:22 PM	
	CSO/ 6111/ AFT Baggage FWD Position ELPS/ Comply with TLMC Task 33-50-00-201, Functional Test of the Emergency Lights Power−Supply PN 60-1321-1, SN 26448.		B1013522 - Brandon Jennings Mar 02, 2026 09:15 PM	
	200	COMPLIED WITH PRELIMINARY INSPECTION OF THE AFT BAGGAGE FWD ELPS. SN: 26448. NO DEFECTS NOTED. ALL WORK DONE IAW HONEYWELL CMM 33-50-42.	B0143837 - David Bohl Mar 02, 2026 08:22 PM	
	COMPLY WITH PRELIMINARY INSPECTION OF THE AFT BAGGAGE FWD ELPS. SN: 26448.		B1013522 - Brandon Jennings Mar 02, 2026 09:15 PM	

TOOL INFORMATION

Tool ID	Tool Description	Calibration Due Date
TUSJ1726	MULTIMETER	Dec 30, 2026 5:00 PM

QA005 RTS Statement

The component identified above was repaired and inspected in accordance with current Federal Aviation Regulations, found airworthy and is approved for return to service with respect to the work performed

Sequence #	7018	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4763124	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

7018	**WO #**	**4763124**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #	20322030	No Log Entry	
7018/CSO// 6111/Comply with Landing Gear 96 Month Inspection on NLG Shock Strut				

Bombardier

Sequence #	7018	Aircraft SN #	6111	MWPWO #	2498069
WO #	4763124	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100 7018/CSO// 6111/Comply with Landing Gear 96 Month Inspection on NLG Shock Strut	THE FOLLOWING WORK ACCOMPLISHED IAW CHALLENGER 650 MAINTENANCE MANUAL REV 35 DATED OCT 15/2025, CHAPTER 5, TASK NO. 32-00-01-216 96 MONTH DETAILED INSPECTION OF NLG ASSEMBLY AND SAFRAN NOSE LANDING GEAR COMPONENT MAINTENANCE MANUAL PART NUMBER 20020 32-20-05, REV 23 DATED SEP 01/2025. DIDNT RECIEVE "AXLE NUTS", "AXLE SPACERS", OR "RETRACTION ACTUATOR PIN". FINISHED DISASSEMBLY. PREPPED SLEEVE TO BE REMOVED.	B1019469 - Hunter Holt Feb 17, 2026 04:27 AM B0150944 - Adam Pummill Feb 26, 2026 05:02 PM	
	101 7018/CSO// 6111/Comply with Landing Gear 96 Month Inspection on NLG Shock Strut	COMPLETED CLEANING AND MEDIA BLASTING PARTS.	B1019469 - Hunter Holt Feb 17, 2026 04:30 AM B0585124 - Michael Jones Feb 17, 2026 04:31 AM	
	102 7018/CSO// 6111/Comply with Landing Gear 96 Month Inspection on NLG Shock Strut	BEGAN VISUAL INSPECTION. REJECTED "BODY", "COVER", "SPACER", "STEERING CUFF SPACER",AND "RACK SUPPORT" DUE TO CORROSION. MEDIA BLASTED CYLINDER AND SENT TO NDI FOR INSPECTION. BEGAN PAINT PREP OF SMALL PARTS.	B1019469 - Hunter Holt Feb 17, 2026 04:35 AM B0585124 - Michael Jones Feb 17, 2026 04:36 AM	
	103 7018/CSO// 6111/Comply with Landing Gear 96 Month Inspection on NLG Shock Strut	FINISHED PAINT PREP AND APPLIED PRIMER TO SMALL PARTS. REJECTED "UPPER BEARING" DUE TO BEING WORN. POLISHED PINS AND SLIDING TUBE.	B1019469 - Hunter Holt Feb 18, 2026 04:48 AM B0585124 - Michael Jones Feb 19, 2026 05:19 AM	
	104 7018/CSO// 6111/Comply with Landing Gear 96 Month Inspection on NLG Shock Strut	APPLIED PAINT TO SMALL PARTS AND UNMASKED THEM.	B1019469 - Hunter Holt Feb 19, 2026 05:18 AM B0585124 - Michael Jones Feb 19, 2026 05:20 AM	

Sequence #	7018	Aircraft SN #	6111	MWPWO #	2498069
WO #	4763124	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	105	ASSEMBLED STEERING ACTUATORS, SLIDING TUBE ASSEMBLY AND INNER TUBE ASSEMBLY.	B1019469 - Hunter Holt Feb 19, 2026 10:51 PM	
	7018/CSO// 6111/Comply with Landing Gear 96 Month Inspection on NLG Shock Strut		B0585124 - Michael Jones Feb 26, 2026 04:31 AM	
	106	BEGAN CORROSION REPAIR TO CYLINDER IAW SAFRAN LANDING SYSTEMS CONCESSION # RC-TO-0156380. PAINT PREPPED AND PRIMED "COVER ARM" AND "MAIN FITTING".	B1019469 - Hunter Holt Feb 21, 2026 04:59 AM	
	7018/CSO// 6111/Comply with Landing Gear 96 Month Inspection on NLG Shock Strut		B0585124 - Michael Jones Feb 26, 2026 04:31 AM	
	107	INSTALLED SPACER AND SLEEVE ONTO CYLINDER. HAD CYLINDER SLEEVE MACHINED THEN PAINT PREPPED. APPLIED PAINT TO CYLINDER AND SMALL PARTS.	B0650161 - Khanh Ta Feb 23, 2026 08:33 PM	
	7018/CSO// 6111/Comply with Landing Gear 96 Month Inspection on NLG Shock Strut		B0585124 - Michael Jones Feb 26, 2026 04:31 AM	
	108	UNMASKED CYLINDER AND SMALL PARTS, BEGAN REASSEMBLY.	B1019469 - Hunter Holt Feb 24, 2026 04:34 PM	
	7018/CSO// 6111/Comply with Landing Gear 96 Month Inspection on NLG Shock Strut		B0585124 - Michael Jones Feb 26, 2026 04:31 AM	
	109	RESUMED REASSEMBLY WITH PARTS LISTED.	B0650161 - Khanh Ta Feb 24, 2026 08:32 PM	
	7018/CSO// 6111/Comply with Landing Gear 96 Month Inspection on NLG Shock Strut		B0585124 - Michael Jones Feb 26, 2026 04:31 AM	
	110	RESUMED REASSEMBLY WITH PARTS LISTED. SERVICED GEAR WITH 5606 AND INSTALLED INTO STAND FOR HIGH PRESSURE TEST, DURING TEST FOUND A LEAK. REMOVED GEAR FROM STAND AND DISASSEMBLED PISTON TUBE ASSY AND INNER TUBE ASSY.	B1019469 - Hunter Holt Feb 25, 2026 03:44 AM	
	7018/CSO// 6111/Comply with Landing Gear 96 Month Inspection on NLG Shock Strut		B0585124 - Michael Jones Feb 25, 2026 03:45 AM	
	111	REPLACED DAMAGED SEALS AND REASSEMBLED NLG WITH PARTS LISTED. SERVICED STRUT WITH 5606. INSTALLED ONTO TEST STAND AND BEGAN HIGH PRESSURE TEST.	B0650161 - Khanh Ta Feb 25, 2026 06:29 PM	
	7018/CSO// 6111/Comply with Landing Gear 96 Month Inspection on NLG Shock Strut		B0585124 - Michael Jones Feb 26, 2026 04:31 AM	

Bombardier

Sequence #	7018	Aircraft SN #	6111	MWPWO #	2498069
WO #	4763124	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	112	PASSED HIGH PRESSURE TEST. BEGAN LOW PRESSURE TEST. COMPLETED REASSEMBLY AND PERFORMED STEERING F/T. F/T CHECKED GOOD. LOW PRESSURE TEST PASSED. PRESSURIZED STRUT TO 40 PSI.	B1019469 - Hunter Holt Feb 26, 2026 04:30 AM	
	7018/CSO// 6111/Comply with Landing Gear 96 Month Inspection on NLG Shock Strut		B0585124 - Michael Jones Feb 26, 2026 04:31 AM	
	113	RETURN TO SERVICE AS REPAIRED. COMPLIED WITH 96 MONTH INSPECTION REQUIREMENTS CSN:878	B0650161 - Khanh Ta Feb 26, 2026 03:18 PM	
	7018/CSO// 6111/Comply with Landing Gear 96 Month Inspection on NLG Shock Strut		B0150944 - Adam Pummill Feb 26, 2026 05:02 PM	
	200	VERIFIED ALL SERIAL NUMBERS PRIOR TO PAINT.	B0585124 - Michael Jones Feb 17, 2026 12:56 AM	
	COMPLETE SERIAL NUMBER VERIFICATION PRIOR TO PAINT		B0585124 - Michael Jones Feb 17, 2026 12:56 AM	
	300	COMPLETED FOD CHECK, NO FOD NOTED	B0585124 - Michael Jones Feb 23, 2026 11:47 PM	
	FOD CHECK REQUIRED PRIOR TO ASSEMBLY.		B0585124 - Michael Jones Feb 23, 2026 11:48 PM	
	400	RECEIVED RETRACT ACTUATOR PIN. (FOUND ATTACHED WITH RETRACT ACTUATOR)	B0650161 - Khanh Ta Feb 26, 2026 06:05 PM	
	RECEIVED RETRACT ACTUATOR PIN.		B0128603 - Rex Befort Feb 26, 2026 06:07 PM	

Bombardier

Sequence #	7018	Aircraft SN #	6111	MWPWO #	2498069
WO #	4763124	Aircraft Reg #	XA-SOL	Parent WO #	2498069

REMOVE AND RE-INSTALL DETAILS

	Removed Part # Removed Serial #	Removed By	Removed - Part Description	Reference	Installed Part # Installed Serial #	Installed By
	Removed Status	**Removed Date-Time**	**Position**	**Installed Part Status**	**Installed Part Description**	**Installed Date-Time**
	200812305 16CAM1604	B1019469 - Hunter Holt	BODY	CORROSION	200812305 23CAM4565	B1019469 - Hunter Holt
	UNSERVICEABLE	Feb 17, 2026 11:05 AM		NEW	BODY	
	200812303 MER4435	B1019469 - Hunter Holt	COVER, STEERING ACTUATOR	CORROSION	200812201 MER8066	B1019469 - Hunter Holt
	UNSERVICEABLE	Feb 17, 2026 11:07 AM		NEW	COVER	
	200811660 MY1550700	B1019469 - Hunter Holt	SPACER	CORROSION	200811660 MY3338060	B1019469 - Hunter Holt
	UNSERVICEABLE	Feb 17, 2026 11:08 AM		NEW	SPACER	
	200811669 CPS1320453	B1019469 - Hunter Holt	SPACER		200811669 MER62611	B1019469 - Hunter Holt
	UNSERVICEABLE	Feb 17, 2026 11:11 AM		NEW	SPACER	
	200812605 MER4422	B1019469 - Hunter Holt	SUPPORT, RACK	CORROSION	200812605 MER8419	B1019469 - Hunter Holt
	UNSERVICEABLE	Feb 17, 2026 11:15 AM		NEW	SUPPORT, RACK	
	200811621	B1019469 - Hunter Holt	SLEEVE	CORROSION	200811621	B0650161 - Khanh Ta
	UNSERVICEABLE	Feb 17, 2026 9:51 AM		NEW	SLEEVE	Feb 19, 2026 9:53 AM

TOOL INFORMATION

Tool ID	Tool Description	Calibration Due Date
L1787	TORQUE WRENCH	Jun 12, 2026 5:00 PM
D00768	TORQUE WRENCHD00768	Oct 2, 2026 5:00 PM
A1008	PSI GUAGE	Dec 23, 2026 5:00 PM

QA005 RTS Statement

The component identified above was repaired and inspected in accordance with current Federal Aviation Regulations, found airworthy and is approved

Sequence #	7018	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4763124	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

for return to service with respect to the work performed

Inspected By :	
B0128603 > Rex Befort	**Date:** 2026-02-26

Bombardier

Sequence #	7019	Aircraft SN #	6111	MWPWO #	2498069
WO #	4818595	Aircraft Reg #	XA-SOL	Parent WO #	2498069

7019	WO #	4818595	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	20322389	CSO// 6111// LH #1 MLG Tire	
CSO// 6111// LH #1 MLG Tire Replacement				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Disassembled, cleaned, inspected, and reassembled #1 MLG Wheel assembly with new Tire, packing and valve core. Ref CL-650 CMM 32-42-28 See CMT Working copy dated 2/23/26 for work performed. N/A: 5A.Balancing not required. 6B Tires Installed.	B0646266 - Sergio Rodriguez Figueroa Mar 03, 2026 05:46 PM	
	CSO// 6111// LH #1 MLG Tire Replacement		B1013522 - Brandon Jennings Mar 03, 2026 09:11 PM	
	101	Disassembled, cleaned, inspected, and reassembled #1 MLG Wheel assembly (PN: 604-85123-1/SN:AUG17-4595) with NEW Tire (PN: 027-697-0/SN:5260P05223), packing and valve core. Ref CL-650 CMM 32-42-28 See CMT Working copy dated 2/23/26 for work performed. N/A: 5A.Balancing not required. 6B Tires Installed.	B0646266 - Sergio Rodriguez Figueroa Mar 06, 2026 02:58 PM	
	CSO// 6111// LH #1 MLG Tire Replacement		B1013522 - Brandon Jennings Mar 06, 2026 04:21 PM	09
	102			
	CSO// 6111// LH #1 MLG Tire Replacement			09
	200	Performed a 3 hour leak/stretch check, 12 hour leak/stretch check, following 24 hour leak check. All checks good, no defects noted. Ref CL-650 AMM 12-15-00-614-801 Fill started 2/24/26 @1:pm	B0646266 - Sergio Rodriguez Figueroa Mar 03, 2026 05:46 PM	
	Perform 3 hour leak/stretch check, 12 hour leak/stretch check, following 24 hour leak check Ref CL-650 AMM 12-15-00-614-801 Fill started 2/24/26 @1:pm		B1013522 - Brandon Jennings Mar 03, 2026 09:11 PM	
	300	Removed all tools, equipment, and unwanted materials from the work area as required.	B0646266 - Sergio Rodriguez Figueroa Mar 03, 2026 06:01 PM	
	Remove all tools, equipment, and unwanted material from the work area.		B1013522 - Brandon Jennings Mar 03, 2026 09:11 PM	

Sequence #	7019	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4818595	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

REMOVE AND RE-INSTALL DETAILS

	Removed Part # Removed Serial #	Removed By	Removed - Part Description	Reference	Installed Part # Installed Serial #	Installed By
	Removed Status	**Removed Date-Time**	**Position**	**Installed Part Status**	**Installed Part Description**	**Installed Date-Time**
	027-697-0 UNKNOWN		TIRE, MLG	32-42-28	027-697-0 5260P05223	B0642051 - Terry Walters
	UNSERVICEABLE	Feb 23, 2026 9:04 AM	1	NEW	TIRE, MLG	Feb 23, 2026 9:04 AM

QA005 RTS Statement

The component identified above was repaired and inspected in accordance with current Federal Aviation Regulations, found airworthy and is approved for return to service with respect to the work performed

Sequence #	7020	Aircraft SN #	6111	MWPWO #	2498069
WO #	4818617	Aircraft Reg #	XA-SOL	Parent WO #	2498069

7020	WO #	4818617	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	20322582	No Log Entry	
CSO// 6111// LH #2 MLG Tire Replacement				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Disassembled, cleaned, inspected, and reassembled #2 MLG Wheel assembly with new Tire, packing and valve core. Ref CL-650 CMM 32-42-28 See CMT Working copy dated 2/23/26 for work performed. N/A: 5A.Balancing not required. 6B Tires Installed.	B0646266 - Sergio Rodriguez Figueroa Mar 03, 2026 05:50 PM	
	CSO// 6111// LH #2 MLG Tire Replacement		B1013522 - Brandon Jennings Mar 03, 2026 09:14 PM	
	101	Disassembled, cleaned, inspected, and reassembled #2 MLG Wheel assembly (PN: 604-85123-1/SN:AUG17-4594) with NEW Tire (PN: 027-697-0/SN:5159P05005), packing and valve core. Ref CL-650 CMM 32-42-28 See CMT Working copy dated 2/23/26 for work performed. N/A: 5A.Balancing not required. 6B Tires Installed.	B0646266 - Sergio Rodriguez Figueroa Mar 06, 2026 03:41 PM	
	CSO// 6111// LH #2 MLG Tire Replacement		B1013522 - Brandon Jennings Mar 06, 2026 04:25 PM	09
	102			
	CSO// 6111// LH #2 MLG Tire Replacement			09
	200	Performed a 3 hour leak/stretch check, 12 hour leak/stretch check, following 24 hour leak check. All checks good no defects noted. Ref CL-650 AMM 12-15-00-614-801 Fill started 2/24/26 @1:pm	B0646266 - Sergio Rodriguez Figueroa Mar 03, 2026 05:50 PM	
	Perform 3 hour leak/stretch check, 12 hour leak/stretch check, following 24 hour leak check Ref CL-650 AMM 12-15-00-614-801 Fill started 2/24/26 @1:pm		B1013522 - Brandon Jennings Mar 03, 2026 09:14 PM	
	300	Removed all tools, equipment, and unwanted material from the work area as required.	B0646266 - Sergio Rodriguez Figueroa Mar 03, 2026 05:50 PM	
	Remove all tools, equipment, and unwanted material from the work area.		B1013522 - Brandon Jennings Mar 03, 2026 09:14 PM	

Sequence #	7020	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4818617	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

REMOVE AND RE-INSTALL DETAILS

	Removed Part # Removed Serial #	Removed By	Removed - Part Description	Reference	Installed Part # Installed Serial #	Installed By
	Removed Status	**Removed Date-Time**	**Position**	**Installed Part Status**	**Installed Part Description**	**Installed Date-Time**
	027-697-0 UNKNOWN	B0642051 - Terry Walters	TIRE, MLG	32-42-28	027-697-0 5159P05005	B0642051 - Terry Walters
	UNSERVICEABLE	Feb 23, 2026 2:05 PM	2	NEW	TIRE, MLG	Feb 23, 2026 9:04 AM

QA005 RTS Statement

The component identified above was repaired and inspected in accordance with current Federal Aviation Regulations, found airworthy and is approved for return to service with respect to the work performed

Bombardier

Sequence #	7021	Aircraft SN #	6111	MWPWO #	2498069
WO #	4818674	Aircraft Reg #	XA-SOL	Parent WO #	2498069

7021	WO #	4818674	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	20322390	No Log Entry	
CSO// 6111// RH #3 MLG Tire Replacement				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Disassembled, cleaned, inspected, and reassembled #3 MLG Wheel assembly with new Tire, packing and valve core. Ref CL-650 CMM 32-42-28 See CMT Working copy dated 2/23/26 for work performed. N/A: 5A.Balancing not required. 6B Tires Installed.	B0646266 - Sergio Rodriguez Figueroa Mar 03, 2026 05:54 PM	
	CSO// 6111// RH #3 MLG Tire Replacement		B1013522 - Brandon Jennings Mar 03, 2026 09:16 PM	
	101	Disassembled, cleaned, inspected, and reassembled #3 MLG Wheel assembly (PN: 604-85123-1/SN:DEC16-4478) with NEW Tire (PN: 027-697-0/SN:5161P05197), packing and valve core. Ref CL-650 CMM 32-42-28 See CMT Working copy dated 2/23/26 for work performed. N/A: 5A.Balancing not required. 6B Tires Installed.	B0646266 - Sergio Rodriguez Figueroa Mar 06, 2026 03:45 PM	
	CSO// 6111// RH #3 MLG Tire Replacement		B1013522 - Brandon Jennings Mar 06, 2026 04:26 PM	09
	102			
	CSO// 6111// RH #3 MLG Tire Replacement			09
	200	Performed a 3 hour leak/stretch check, 12 hour leak/stretch check, following 24 hour leak check. All checks good no defects noted. Ref CL-650 AMM 12-15-00-614-801 Fill started 2/24/26 @1:pm	B0646266 - Sergio Rodriguez Figueroa Mar 03, 2026 05:54 PM	
	Perform 3 hour leak/stretch check, 12 hour leak/stretch check, following 24 hour leak check Ref CL-650 AMM 12-15-00-614-801 Fill started 2/24/26 @1:pm		B1013522 - Brandon Jennings Mar 03, 2026 09:16 PM	
	300	Removed all tools, equipment, and unwanted materials from the work area as required.	B0646266 - Sergio Rodriguez Figueroa Mar 03, 2026 05:54 PM	
	Remove all tools, equipment, and unwanted material from the work area.		B1013522 - Brandon Jennings Mar 03, 2026 09:16 PM	

Sequence #	7021	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4818674	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

REMOVE AND RE-INSTALL DETAILS

	Removed Part # Removed Serial #	Removed By	Removed - Part Description	Reference	Installed Part # Installed Serial #	Installed By
	Removed Status	**Removed Date-Time**	**Position**	**Installed Part Status**	**Installed Part Description**	**Installed Date-Time**
	027-697-0 UNKNOWN	B0642051 - Terry Walters	TIRE, MLG	32-42-28	027-697-0 5161P05197	B0646266 - Sergio Rodriguez Figueroa
	UNSERVICEABLE	Feb 23, 2026 9:12 AM	3	NEW	TIRE, MLG	Feb 23, 2026 9:12 AM

QA005 RTS Statement

The component identified above was repaired and inspected in accordance with current Federal Aviation Regulations, found airworthy and is approved for return to service with respect to the work performed

Bombardier

Sequence #	7022	Aircraft SN #	6111	MWPWO #	2498069
WO #	4818676	Aircraft Reg #	XA-SOL	Parent WO #	2498069

7022	WO #	4818676	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	20322391	CSO// 6111// RH #4 MLG Tire	
CSO// 6111// RH #4 MLG Tire Replacement				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Disassembled, cleaned, inspected, and reassembled #4 MLG Wheel assembly with new Tire, packing and valve core. Ref CL-650 CMM 32-42-28 See CMT Working copy dated 2/23/26 for work performed. N/A: 5A.Balancing not required. 6B Tires Installed.	B0646266 - Sergio Rodriguez Figueroa Mar 03, 2026 05:58 PM	
	CSO// 6111// RH #4 MLG Tire Replacement		B1013522 - Brandon Jennings Mar 03, 2026 09:18 PM	
	101	Disassembled, cleaned, inspected, and reassembled #4 MLG Wheel assembly (PN: 604-85123-1/SN:DEC16-4477) with new Tire (PN: 027-697-0/SN:5157P05034), packing and valve core. Ref CL-650 CMM 32-42-28 See CMT Working copy dated 2/23/26 for work performed. N/A: 5A.Balancing not required. 6B Tires Installed.	B0646266 - Sergio Rodriguez Figueroa Mar 06, 2026 03:48 PM	
	CSO// 6111// RH #4 MLG Tire Replacement		B1013522 - Brandon Jennings Mar 06, 2026 04:28 PM	09
	102			
	CSO// 6111// RH #4 MLG Tire Replacement			09
	200	Performed a 3 hour leak/stretch check, 12 hour leak/stretch check, following 24 hour leak check. All checks good no defects noted. Ref CL-650 AMM 12-15-00-614-801 Fill started 2/24/26 @1:pm	B0646266 - Sergio Rodriguez Figueroa Mar 03, 2026 05:58 PM	
	Perform 3 hour leak/stretch check, 12 hour leak/stretch check, following 24 hour leak check Ref CL-650 AMM 12-15-00-614-801 Fill started 2/24/26 @1:pm		B1013522 - Brandon Jennings Mar 03, 2026 09:18 PM	
	300	Removed all tools, equipment, and unwanted materials from the work area as required.	B0646266 - Sergio Rodriguez Figueroa Mar 03, 2026 05:58 PM	
	Remove all tools, equipment, and unwanted material from the work area.		B1013522 - Brandon Jennings Mar 03, 2026 09:18 PM	

Sequence #	7022	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4818676	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

REMOVE AND RE-INSTALL DETAILS

	Removed Part # Removed Serial #	Removed By	Removed - Part Description	Reference	Installed Part # Installed Serial #	Installed By
	Removed Status	**Removed Date-Time**	**Position**	**Installed Part Status**	**Installed Part Description**	**Installed Date-Time**
	027-697-0:68030 UNKNOWN	B0642051 - Terry Walters	TIRE, MLG	32-42-28	027-697-0:68030 5157P05034	B0642051 - Terry Walters
	UNSERVICEABLE	Feb 23, 2026 2:04 PM	4	NEW	TIRE, MLG	Feb 23, 2026 9:04 AM

QA005 RTS Statement

The component identified above was repaired and inspected in accordance with current Federal Aviation Regulations, found airworthy and is approved for return to service with respect to the work performed

Sequence #	7023	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4819305	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

7023	**WO #**	**4819305**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #	20322392	No Log Entry	
CSO// 6111// LH NLG Tire Replacement				
CRITICAL MAINTENANCE TASK				

Sequence #	7023	Aircraft SN #	6111	MWPWO #	2498069
WO #	4819305	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
CMT	100	Disassembled, cleaned, inspected, reassembled, and Balanced LH NLG Wheel assembly with new Tire, packing, valve core, Bolts, and Nuts. Ref CL-650 CMM 32-42-27 See CMT Working copy dated 2/23/26 for work performed	B0646266 - Sergio Rodriguez Figueroa Mar 03, 2026 02:13 PM	
	CSO// 6111// LH NLG Tire Replacement		B1013522 - Brandon Jennings Mar 03, 2026 07:07 PM	
CMT	200	Performed a 3 hour leak/stretch check, 12 hour leak/ stretch check, following 24 hour leak check. All checks good, no defects noted Ref CL-650 AMM 12-15-00-614-801 Fill started 2/24/26 @1:pm	B0646266 - Sergio Rodriguez Figueroa Mar 03, 2026 02:13 PM	
	Perform 3 hour leak/stretch check, 12 hour leak/ stretch check, following 24 hour leak check Ref CL-650 AMM 12-15-00-614-801 Fill started 2/24/26 @1:pm		B1013522 - Brandon Jennings Mar 03, 2026 07:07 PM	
CMT	201	Performed a 3 hour leak/stretch check, 12 hour leak/ stretch check, following 24 hour leak check. All checks good, no defects noted. Ref CL-650 AMM 12-15-00-614-801, CMM 32-46-27 Step B pg103, B(5) pg107 Fill started 2/24/26 @1:pm	B0646266 - Sergio Rodriguez Figueroa Mar 06, 2026 04:09 PM	
	Perform 3 hour leak/stretch check, 12 hour leak/ stretch check, following 24 hour leak check Ref CL-650 AMM 12-15-00-614-801 Fill started 2/24/26 @1:pm		B1013522 - Brandon Jennings Mar 06, 2026 05:10 PM	09
	300	Removed all tools, equipment, and unwanted materials from the work area as required.	B0646266 - Sergio Rodriguez Figueroa Mar 03, 2026 02:13 PM	
	Remove all tools, equipment, and unwanted material from the work area.		B1013522 - Brandon Jennings Mar 03, 2026 07:07 PM	
CMT	400	Disassembled, cleaned, inspected, reassembled, and Balanced LH NLG Wheel assembly with new Tire, packing, valve core, Bolts, and Nuts. Ref CL-650 CMM 32-42-27 See CMT Working copy dated 2/23/26 for work performed. N/A: 3A-3D(6) not removed. Temp Rev 32-13 Pg 4-5 of 6 Performed during install on AC. 3N-3N(4) performed during install on ac. 4.1(a) within limits. B3-B3(d) no leaks. B5(a) does not exceed. 5A-5C(4) not needed.	B0646266 - Sergio Rodriguez Figueroa Mar 03, 2026 05:17 PM	
	Administrative correction for operation 100. Wording.		B1013522 - Brandon Jennings Mar 03, 2026 07:07 PM	

Bombardier

Sequence #	7023	Aircraft SN #	6111	MWPWO #	2498069
WO #	4819305	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
CMT	401	Disassembled, cleaned, inspected, reassembled, and Balanced LH NLG Wheel assembly (PN: 5010600-1/SN:MAR17-8606) with NEW Tire (PN: 031-614-0/SN:5055T00278), packing, valve core, Bolts, and Nuts. Ref CL-650 CMM 5010598 32-46-27 See CMT Working copy dated 2/23/26 for work performed. N/A: 3A-3D(6) not removed. Temp Rev 32-13 Pg 4, pg 5. Performed during install on AC. 3N-3N(4) performed during install on ac. 4.1(a) within limits. B3-B3(d) no leaks. B5(a) does not exceed. 5A-5C(4) not needed.	B0646266 - Sergio Rodriguez Figueroa Mar 06, 2026 04:09 PM	
	Administrative correction for operation 100. Wording.		B1013522 - Brandon Jennings Mar 06, 2026 05:10 PM	09
CMT	402			
	Administrative correction for operation 100. Wording.			09

REMOVE AND RE-INSTALL DETAILS

	Removed Part # / Removed Serial #	Removed By	Removed - Part Description	Reference	Installed Part # / Installed Serial #	Installed By
	Removed Status	Removed Date-Time	Position	Installed Part Status	Installed Part Description	Installed Date-Time
	031-614-0 5011T00396	B1002512 - Brandon Warne	TIRE, NOSEWHEEL (12 PR)	Unserviceable	031-614-0 5055T00278	B1002512 - Brandon Warne
	UNSERVICEABLE	Feb 23, 2026 9:15 AM	LEFT	NEW	TIRE, NOSEWHEEL (12 PR)	Feb 23, 2026 9:15 AM

QA005 RTS Statement

The component identified above was repaired and inspected in accordance with current Federal Aviation Regulations, found airworthy and is approved for return to service with respect to the work performed

Sequence #	7024	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4819314	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

7024	**WO #**	**4819314**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #	20322488	No Log Entry	
CSO// 6111// RH NLG Tire Replacement				
CRITICAL MAINTENANCE TASK				

Sequence #	7024	Aircraft SN #	6111	MWPWO #	2498069
WO #	4819314	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Disassembled, cleaned, inspected, reassembled, and Balanced RH NLG Wheel assembly with new Tire, packing, valve core, Bolts, and Nuts. Ref CL-650 CMM 32-42-28 See CMT Working copy dated 2/23/26 for work performed	B0646266 - Sergio Rodriguez Figueroa Mar 03, 2026 02:18 PM	
	CSO// 6111// RH NLG Tire Replacement		B1013522 - Brandon Jennings Mar 03, 2026 08:20 PM	
	200	Performed a 3 hour leak/stretch check, 12 hour leak/ stretch check, following 24 hour leak check. All checks good, no defects noted. Ref CL-650 AMM 12-15-00-614-801 Fill started 2/24/26 @1:pm	B0646266 - Sergio Rodriguez Figueroa Mar 03, 2026 02:18 PM	
	Perform 3 hour leak/stretch check, 12 hour leak/ stretch check, following 24 hour leak check Ref CL-650 AMM 12-15-00-614-801 Fill started 2/24/26 @1:pm		B1013522 - Brandon Jennings Mar 03, 2026 08:20 PM	
CMT	201	Performed a 3 hour leak/stretch check, 12 hour leak/ stretch check, following 24 hour leak check. All checks good, no defects noted. Ref CL-650 AMM 12-15-00-614-801, CL650 CMM 32-46-27 Step B pg103, B(5) pg107. Fill started 2/24/26 @1:pm	B0646266 - Sergio Rodriguez Figueroa Mar 06, 2026 04:18 PM	
	Perform 3 hour leak/stretch check, 12 hour leak/ stretch check, following 24 hour leak check Ref CL-650 AMM 12-15-00-614-801 Fill started 2/24/26 @1:pm			09
	300	Removed all tools, equipment, and unwanted materials from the work area as required.	B0646266 - Sergio Rodriguez Figueroa Mar 03, 2026 02:18 PM	
	Remove all tools, equipment, and unwanted material from the work area.		B1013522 - Brandon Jennings Mar 03, 2026 08:20 PM	
	400	Disassembled, cleaned, inspected, reassembled, and Balanced LH NLG Wheel assembly with new Tire, packing, valve core, Bolts, and Nuts. Ref CL-650 CMM 32-42-27 See CMT Working copy dated 2/23/26 for work performed. N/A: 3A-3D(6) not removed. Temp Rev 32-13 Pg 4-5 of 6 Performed during install on AC. 3N-3N(4) performed during install on ac. 4.1(a) within limits. B3-B3(d) no leaks. B5(a) does not exceed. 5A-5C(4) not needed.	B0646266 - Sergio Rodriguez Figueroa Mar 03, 2026 05:20 PM	
	Administrative correction for operation 100.		B1013522 - Brandon Jennings Mar 03, 2026 08:20 PM	

Sequence #	7024	Aircraft SN #	6111	MWPWO #	2498069
WO #	4819314	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	401	Disassembled, cleaned, inspected, reassembled, and Balanced LH NLG Wheel assembly (PN: 5010600-1/SN:AUG17-8658) with NEW Tire (PN: 031-614-0/SN:5133T00242), packing, valve core, Bolts, and Nuts. Ref CL-650 CMM 32-46-27 See CMT Working copy dated 2/23/26 for work performed. N/A: 3A-3D(6) not removed. Temp Rev step (2) pg.4, pg.5 Performed during install on AC. 3N-3N(4) performed during install on ac. 4.1(a) within limits. B3-B3(d) no leaks. B5(a) does not exceed. 5A-5C(4) not needed.	B0646266 - Sergio Rodriguez Figueroa Mar 06, 2026 04:18 PM	
	Administrative correction for operation 100.			09

REMOVE AND RE-INSTALL DETAILS

	Removed Part # / Removed Serial #	Removed By	Removed - Part Description	Reference	Installed Part # / Installed Serial #	Installed By
	Removed Status	Removed Date-Time	Position	Installed Part Status	Installed Part Description	Installed Date-Time
	031-614-0 UNKNOWN	B0642051 - Terry Walters	TIRE, NOSEWHEEL (12 PR)		031-614-0 5133T00242	B0646266 - Sergio Rodriguez Figueroa
		Feb 24, 2026 1:42 PM	RIGHT	NEW	TIRE, NOSEWHEEL (12 PR)	Mar 3, 2026 7:20 AM

QA005 RTS Statement

The component identified above was repaired and inspected in accordance with current Federal Aviation Regulations, found airworthy and is approved for return to service with respect to the work performed

Sequence #	7501	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	3303490	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

7501	**WO #**	**3303490**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #	13276350	No Log Entry	
Fuel Services				
Task / IRN # : FUEL SERVICES				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Captured Fuel Service Requirements as Required	B0162034 - Tyler Poggi Feb 16, 2026 03:22 PM	05-00
	C/W Fuel requirements		B1013522 - Brandon Jennings Feb 20, 2026 05:11 PM	

Bombardier

Sequence #	7502	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	3303504	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

7502	**WO #**	**3303504**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #	13276289	No Log Entry	
7502//C/W FREIGHT CHARGES				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			20-00
	7502//C/W FREIGHT CHARGES			

Bombardier

Sequence #	7503	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	3303507	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

7503	**WO #**	**3303507**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #	13276368	No Log Entry	
7503//C/W AIRCRAFT CLEANING SERVICES				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			25-00
	7503//C/W AIRCRAFT CLEANING SERVICES			

Sequence #	8001	Aircraft SN #	6111	MWPWO #	2498069
WO #	4715414	Aircraft Reg #	XA-SOL	Parent WO #	2498069

8001	WO #	4715414	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13493672	No Log Entry	
Multiple locations of bare/lifting paint on the interior of the RH Exhaust Nozzle Fairing-Assembly. Photos included.				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	APPLIED ALUMINUM HEAT RESISTANT COATING TO ALL BARE AND LIFTING LOCATIONS ON INTERIOR RH EXHAUST FAIRING IAW CL 650 CMM 20-25-31-160-002-A01 .CURE CHECK GOOD	B0143507 - Todd Bailes Feb 10, 2026 04:00 PM	
	Multiple locations of bare/lifting paint on the interior of the RH Exhaust Nozzle Fairing-Assembly. Photos included.		B1013522 - Brandon Jennings Feb 10, 2026 04:29 PM	

Sequence #	8002	Aircraft SN #	6111	MWPWO #	2498069
WO #	4715439	Aircraft Reg #	XA-SOL	Parent WO #	2498069

8002	WO #	4715439	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13493686	No Log Entry	
Section of metal on interior of LH Exhaust Nozzle Fairing-Assembly, beginning to lift and oil can in appearance and touch. Photo included.				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	AFTER FURTHER EVALUATION NO OIL CANNING AT THIS TIME ONLY LIFTING PAINT AND HOT SPOTS APPLIED ALUMINUM HEAT RESISTANT COATING TO ALL HOT SPOTS AND LIFTING LOCATIONS ON INTERIOR LH EXHAUST FAIRING IAW CL 650 CMM 20-25-31-160-002-A01 .CURE CHECK GOOD	B0143507 - Todd Bailes Feb 10, 2026 07:23 PM	
	Section of metal on interior of LH Exhaust Nozzle Fairing-Assembly, beginning to lift and oil can in appearance and touch. Photo included.		B1013522 - Brandon Jennings Feb 10, 2026 07:52 PM	

Sequence #	8003	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4715648	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

8003	**WO #**	**4715648**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #	13493675	Found Gouges on INBD Side of LH/RH MLG Doors (Flagged)	
Found Gouges on INBD Side of LH/RH MLG Doors (Flagged)				

Sequence #	8003	Aircraft SN #	6111	MWPWO #	2498069
WO #	4715648	Aircraft Reg #	XA-SOL	Parent WO #	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Removed Gouges on INBD Side of LH/RH MLG Doors I.A.W REO 604-32-12-076 REV — dated 2014-04-03 step 1-2 Blend damages to smooth contour and did not blended over fasteners	B1021894 - Frederic Charlier Feb 11, 2026 02:21 PM	
	Found Gouges on INBD Side of LH/RH MLG Doors (Flagged)		B1013522 - Brandon Jennings Feb 11, 2026 04:18 PM	
	200	Should read : removed gouges on INBD side of L/H and R/H side MLG doors. I.A.W CL650 SRM 51-12-00-00	B1021894 - Frederic Charlier Feb 11, 2026 03:31 PM	
	Corrective statement for operation 100 At Corrective action		B1013522 - Brandon Jennings Feb 11, 2026 04:18 PM	
	300	Performed Eddy Current inspection for cracks/ corrosion and Ultrasonic thickness inspection for remaining thickness on the LH and RH MLG doors as marked. IAW CL650 NDT manual part 1, section 6D and part 1, section 4. Highest measurement taken LH - .037in Lowest measurement taken LH - . 033in Highest measurement taken RH - .037in Lowest measurement taken RH - .031in ET: No defects noted. UT: Measurements given to structures lead for disposition.	B0642788 - Gary Mendoza Feb 12, 2026 09:01 PM	
	Request NDT for crack check and remaining material thickness on LH and RH MLG doors		B1019685 - Wallace Warren Feb 12, 2026 09:04 PM	
	400	SUBMITTED SRPSA FOR LHS AND RHS MLG GEAR DOOR REFERENCE #000854040. RECIEVED REO #604-32-12-097 FOR LHS DOOR AND REO#604-32-12-098 FOR RHS DOOR	B0143507 - Todd Bailes Feb 26, 2026 07:25 PM	
	Evaluate gouges damage on RH and LH MLG doors		B1013522 - Brandon Jennings Feb 26, 2026 07:31 PM	
	500	COMPLIED WITH REO#604-32-12-097 STEPS 1 THRU 7 ON LHS MLG DOOR COMPLETED IN ITS ENTIRETY . SEE ATTACHED WORKING COPY FOR STEP SIGN OFFS.	B0143507 - Todd Bailes Feb 26, 2026 07:25 PM	
	COMPLY WITH REO#604-32-12-097 ON LHS MLG DOOR		B1013522 - Brandon Jennings Feb 26, 2026 07:31 PM	
	600	COMPLIED WITH REO#604-32-12-098STEPS 1 THRU 7 ON RHS MLG DOOR COMPLETED IN ITS ENTIRETY . SEE ATTACHED WORKING COPY FOR STEP SIGN OFFS.	B0143507 - Todd Bailes Feb 26, 2026 07:25 PM	
	COMPLY WITH REO#604-32-12-098 ON RHS MLG DOOR		B1013522 - Brandon Jennings Feb 26, 2026 07:31 PM	

Sequence #	8003	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4715648	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	700	REMOVED ALL TOOLS,EQUIPMENT AND UNWANTED MATERIALS FROM WORK AREA	B0143507 - Todd Bailes Feb 26, 2026 07:25 PM	
	REMOVE ALL TOOLS,EQUIPMENT AND UNWANTED MATERIALS FROM WORK AREA		B1013522 - Brandon Jennings Feb 26, 2026 07:31 PM	

Sequence #	8004	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4748839	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

8004	**WO #**	**4748839**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #	13498319	No Log Entry	
Top cap fairing (326BT)portion of upper left lightning strip missing . see attachment.				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	REMOVED AND REPLACED WITH NEW DIVERTER PN #LSSQWAE-580 ON TOP CAP (326BT) IAW DWG NO. M20-1003 REV A DATED 10/08/03	B0143507 - Todd Bailes Feb 23, 2026 08:38 PM	
	Top cap fairing (326BT)portion of upper left lightning strip missing . see attachment.		B1013522 - Brandon Jennings Feb 23, 2026 08:58 PM	

Bombardier

Sequence #	8005	Aircraft SN #	6111	MWPWO #	2498069
WO #	4750012	Aircraft Reg #	XA-SOL	Parent WO #	2498069

8005	WO #	4750012	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13498320	No Log Entry	
LH (434AT) Upper trans cowl has dent. Evaluate and advise.				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	DENT MEASURES 1.7 WIDTH BY .017 DEEP MAX ALLOWED 2.0 WIDTH .023 DEEP . WITH IN LIMITS IAW CL650 CMM 71-14-01 . REPAIRED DENT IAW CL 650 CMM 71-14-01 REPAIR # SRS010	B0143507 - Todd Bailes Mar 04, 2026 03:43 PM	
	LH (434AT) Upper trans cowl has dent.		B1013522 - Brandon Jennings Mar 04, 2026 04:37 PM	

TOOL INFORMATION

Tool ID	Tool Description	Calibration Due Date
TUSS2455	depth gauge	Mar 30, 2026 5:00 PM

Bombardier

Sequence #	8006	Aircraft SN #	6111	MWPWO #	2498069
WO #	4750180	Aircraft Reg #	XA-SOL	Parent WO #	2498069

8006	WO #	4750180	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13498334	No Log Entry	
AFT Attachment bracket for RH Upper Transcowl Fairing 444BT has pulled-through its rivets on RH Thrust Reverser track				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Re-installed with 2 solid rivets AFT Attachment bracket for RH Upper Transcowl Fairing 444BT on RH Thrust Reverser track I.A.W CL650 SRM 51-42-08-00	B1021894 - Frederic Charlier Feb 17, 2026 07:02 PM	
	AFT Attachment bracket for RH Upper Transcowl Fairing 444BT has pulled-through its rivets on RH Thrust Reverser track		B1013522 - Brandon Jennings Feb 17, 2026 07:25 PM	
	200	Removed all tools equipment and unwanted material from work area	B1021894 - Frederic Charlier Feb 17, 2026 07:39 PM	
	Remove all tools equipment and unwanted material from work area		B1013522 - Brandon Jennings Feb 19, 2026 07:23 PM	

Bombardier

Sequence #	8007	Aircraft SN #	6111	MWPWO #	2498069
WO #	4750197	Aircraft Reg #	XA-SOL	Parent WO #	2498069

8007	WO #	4750197	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13498413	No Log Entry	
LH Lower Pylon Access Panel 433AB is cracked along top edge of panel				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	RECIEVED NEW PYLON ACCESS PANEL 433AB PART# 228-50793-111 AND INSTALLED EXSISTING SEALS IAW CL 650 SRM 51-42-20	B0143507 - Todd Bailes Feb 21, 2026 12:49 PM	
	LH Lower Pylon Access Panel 433AB is cracked along top edge of panel		B0142244 - Todd Bridges Feb 21, 2026 03:15 PM	

Sequence #	8008	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4755838	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

8008	**WO #**	**4755838**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #	13501536	No Log Entry	
Deep scratches found on the LH/RH IB flap vane.				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	After further investigation damage is thru paint only. Applied Teflon paint on L/H and R/H I/B flap vane I.A.W CL650 SRM 51-01-12-00	B1021894 - Frederic Charlier Feb 28, 2026 10:10 PM	
	Deep scratches found on the LH/RH IB flap vane.		B0142244 - Todd Bridges Mar 02, 2026 03:49 PM	

Bombardier

Sequence #	8009	Aircraft SN #	6111	MWPWO #	2498069
WO #	4784999	Aircraft Reg #	XA-SOL	Parent WO #	2498069

8009	WO #	4784999	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13505321	No Log Entry	
During removal op Fairing (323AT) found Bent Attachment point tab LH lower. see attachment. marked with a streamer.				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Removed bent attachment point tab on LH lower vertical leading edge bracket (323AT), reshaped attachment point tab, and re-installed using CL-650 SRM 51-42-16.	B1018339 - Dwain Wolf Feb 20, 2026 04:55 PM	
	During removal op Fairing (323AT) found Bent Attachment point tab LH lower. see attachment. marked with a streamer.		B1013522 - Brandon Jennings Feb 20, 2026 05:08 PM	
	200	Removed all tools, equipment, and unwanted materials from the work area.	B1018339 - Dwain Wolf Feb 20, 2026 04:55 PM	
	Remove all tools, equipment, and unwanted materials from the work area.		B1013522 - Brandon Jennings Feb 20, 2026 05:08 PM	

Bombardier

Sequence #	8010	Aircraft SN #	6111	MWPWO #	2498069
WO #	4790162	Aircraft Reg #	XA-SOL	Parent WO #	2498069

8010	WO #	4790162	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13505585	No Log Entry	
Surface Corrosion on APU exhaust muffler.				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Cleaned surface with solvent and after further investigation no corrosion / rust found on APU exhaust muffler only dirt was found and removed with solvent cleaning. I.A.W CL650 SPM 51-25-00-110-801	B1021894 - Frederic Charlier Mar 02, 2026 04:27 PM	
	Surface Corrosion on APU exhaust muffler.		B1013522 - Brandon Jennings Mar 02, 2026 05:22 PM	
	200	Removed all tools, equipment, and unwanted materials from the work area	B1021894 - Frederic Charlier Mar 02, 2026 04:37 PM	
	Remove all tools, equipment, and unwanted materials from the work area		B1013522 - Brandon Jennings Mar 02, 2026 05:22 PM	

Sequence #	8011	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4790148	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

8011	**WO #**	**4790148**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #	13505586	No Log Entry	
Exposed graphite on floor Panel 232WRF, tape protection is torn and coming up on the panel.				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	REPAIRED EDGE TAPE ON 232WRF IAW CL 650 CMM 53-01-ND-CE-757 REV C REPAIR 3.5.2	B0143507 - Todd Bailes Feb 23, 2026 05:37 PM	
	Exposed graphite on floor Panel 232WRF, tape protection is torn and coming up on the panel.		B1013522 - Brandon Jennings Feb 23, 2026 06:59 PM	

Sequence #	8012	Aircraft SN #	6111	MWPWO #	2498069
WO #	4790143	Aircraft Reg #	XA-SOL	Parent WO #	2498069

8012	WO #	4790143	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13505605	No Log Entry	
Found paint damage on baggage door cutout at FWD bottom corner. See attached photo.				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	PAINTED FWD BOTTOM CORNER OF BAGGAGE DOOR CUTOUT IAW CL 650 SRM 51001-08	B0143507 - Todd Bailes Mar 02, 2026 01:52 PM	
	Found paint damage on baggage door cutout at FWD bottom corner. See attached photo.		B1013522 - Brandon Jennings Mar 02, 2026 02:11 PM	
	101	PAINTED FWD BOTTOM CORNER OF BAGGAGE DOOR CUTOUT IAW CL 650 SRM 51-01-08	B0143507 - Todd Bailes Mar 02, 2026 02:26 PM	
	Found paint damage on baggage door cutout at FWD bottom corner. See attached photo.		B1013522 - Brandon Jennings Mar 02, 2026 02:40 PM	09
	200	Removed all tools equipment and unwanted material from work area	B0143507 - Todd Bailes Mar 02, 2026 02:43 PM	
	Remove all tools equipment and unwanted material from work area			

Sequence #	8013	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4775764	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

8013	**WO #**	**4775764**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #	13505543	No Log Entry	
Circumference erosion tape lifting and cracking at the 12 o clock position on the forward side of FS 169, under the Nose Radome. Photo included. Location has streamer.				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			
	Circumference erosion tape lifting and cracking at the 12 o clock position on the forward side of FS 169, under the Nose Radome. Photo included. Location has streamer.			

Sequence #	8014	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4796746	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

8014	**WO #**	**4796746**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #	13505967	No Log Entry	
During install found delamination on forward LH wing to fuselage panel 191BB on aft bottom side see attachment for details.				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	REPAIRED EDGE DELAMINATION ON LH FWD WING TO BODY FAIRING # 191BB IAW CL 650 SRM 51-75-28	B0143507 - Todd Bailes Feb 28, 2026 11:49 AM	
	During install found delamination on forward LH wing to fuselage panel 191BB on aft bottom side see attachment for details.		B0142244 - Todd Bridges Feb 28, 2026 02:17 PM	

Bombardier

Sequence #	8015	Aircraft SN #	6111	MWPWO #	2498069
WO #	4820720	Aircraft Reg #	XA-SOL	Parent WO #	2498069

8015	WO #	4820720	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13509343	No Log Entry	
Removed nut-plate underneath panel 422BT (RH side top of pylon)				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Removed bad nutplate and installed new nutplate PN#1870-3-4 PO#6002833996/00001 at RH Pylon underneath Panel 422BT IAW Challenger 650 SRM 51-10-04 Page 3.	B1022767 - Michael Perkin Mar 05, 2026 09:04 PM	
	Removed nut-plate underneath panel 422BT (RH side top of pylon)		B0609145 - Miguel Pacheco Mar 06, 2026 01:09 AM	
	200	Removed tools, equipment, and unwanted materials from the work area (RH Pylon.)	B1022767 - Michael Perkin Mar 05, 2026 09:04 PM	
	Remove tools, equipment, and unwanted materials from work area.		B0609145 - Miguel Pacheco Mar 06, 2026 01:09 AM	

Bombardier

Sequence #	8016	Aircraft SN #	6111	MWPWO #	2498069
WO #	4828066	Aircraft Reg #	XA-SOL	Parent WO #	2498069

8016	WO #	4828066	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13510389	No Log Entry	
Panel stiffener (Hat Chanel) on panel 161FL has damage. See attachment for detail.				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	REPAIRED MINOR PIT ON STIFFENER ON PANEL 161FL IAW CL 650 SRM 51-75-20	B0143507 - Todd Bailes Feb 27, 2026 11:59 AM	
	Panel stiffener (Hat Chanel) on panel 161FL has damage. See attachment for detail.		B1013522 - Brandon Jennings Feb 27, 2026 02:29 PM	

Sequence #	8017	**Aircraft SN #**	6111	**MWPWO #**	2498069
WO #	4828090	**Aircraft Reg #**	XA-SOL	**Parent WO #**	2498069

8017	**WO #**	**4828090**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #	13510440	No Log Entry	
Floor board 232WRF has a broken nut plate, left hand side of the panel, 2nd back from the front.				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Removed and replaced broken nut plate , left hand side of the panel 232WRF, 2nd back from front with new IAW CL-650 SRM 51-42-16-00.	B1017644 - George Taljaard Feb 27, 2026 01:58 PM	
	Floor board 232WRF has a broken nut plate, left hand side of the panel, 2nd back from the front.		B1013522 - Brandon Jennings Feb 27, 2026 02:31 PM	
	200	Removed all tools, equipment, and unwanted materials from the work area.	B1017644 - George Taljaard Feb 27, 2026 02:01 PM	
	Remove all tools, equipment, and unwanted materials from the work area.		B1013522 - Brandon Jennings Feb 27, 2026 02:31 PM	

Bombardier

Sequence #	9001	Aircraft SN #	6111	MWPWO #	2498069
WO #	4801974	Aircraft Reg #	XA-SOL	Parent WO #	2498069

9001	WO #	4801974	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13506715	No Log Entry	
Fairing (324AT) V-stab leading edge has some popped rivets. marked with a streamer.				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	REMOVED POPPED RIVETS ON AREAS MARKED WITH STREAMER ON V-STAB LEADING EDGE (324AT) AND INSTALLED NEW RIVETS IAW REF CL 650 SRM 51-42-08	B0646498 - Abel Gaxiola Feb 20, 2026 11:40 PM	
	Fairing (324AT) V-stab leading edge has some popped rivets. marked with a streamer.		B0142244 - Todd Bridges Feb 21, 2026 12:36 AM	

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
111AL	Radome	2504024 / 53-10-00-201 2503760 / 53-ZL-00-202	OPENED	N	B0638589 - Sean Dodder Feb 5, 2026 9:48 PM
121AL	LH Lower Nose Compartment Panel	2503746 / 53-10-00-213 2504024 / 53-10-00-201 2504085 / 53-ZL-00-204 2504218 / 53-10-00-203 2504025 / 53-10-00-208	OPENED	N	B0650736 - Jesus Gonzalez A tondo Feb 9, 2026 9:10 AM
122AR		2503746 / 53-10-00-213 2504024 / 53-10-00-201 2503761 / 53-ZL-00-205 2504218 / 53-10-00-203 2503702 / 24-23-00-101 2503701 / 24-20-00-207	OPENED	N	B0650736 - Jesus Gonzalez A tondo Feb 9, 2026 11:48 AM
122BR	AC Ground Power Access Door	2504084 / 53-ZL-00-203			
			N/A	N	B1014141 - Christopher Draw dy Feb 11, 2026 7:58 AM
131AL	L/H FLT CNTLS ACCESS PNL	2503857 / 22-12-00-208 2503866 / 27-00-00-201 2503746 / 53-10-00-213 2503766 / 53-ZL-00-208 2504218 / 53-10-00-203 2504025 / 53-10-00-208	OPENED	N	B0613291 - Eric Strong Feb 5, 2026 1:46 PM
132AR	R/H FLT CNTLS ACCESS PNL	2503857 / 22-12-00-208 2503866 / 27-00-00-201 2503746 / 53-10-00-213 2503768 / 53-ZL-00-209 2504218 / 53-10-00-203 2504025 / 53-10-00-208	OPENED	N	B0613291 - Eric Strong Feb 5, 2026 1:47 PM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
141ALF	LOWER FWD FUSE FS235-FS280 FLOOR PNL	2504027 / 53-10-00-210 2504218 / 53-10-00-203	OPENED	N	B0143806 - Alejandro Cabani llas Feb 13, 2026 7:08 AM
141AL	Lower Nose Compartment Panel				
			N/A	N	B1014141 - Christopher Draw dy Feb 11, 2026 8:29 AM
141BLF	MAIN AVIONICS COMPT FS280-FS319 FLOOR PNL	2504222 / 53-20-00-207	OPENED	N	B0143806 - Alejandro Cabani llas Feb 13, 2026 7:08 AM
141BL	Lower Nose Compartment Panel				
			N/A	N	B1014141 - Christopher Draw dy Feb 11, 2026 8:29 AM
142AR	Lower Nose Compartment Panel				
			N/A	N	B1014141 - Christopher Draw dy Feb 11, 2026 8:29 AM
142BR	Lower Nose Compartment Panel				
			N/A	N	B1014141 - Christopher Draw dy Feb 11, 2026 8:29 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
151AZ	ACCESS PANEL, FUEL TANK	2504043 / 53-20-00-232	OPENED	N	B0143806 - Alejandro Cabani llas Feb 13, 2026 10:16 AM
			READYTOCLOSE	N	B1021822 - Joseph Cuoco Feb 19, 2026 6:31 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 19, 2026 7:03 AM
			CLOSED	N	B1021822 - Joseph Cuoco Feb 19, 2026 10:16 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 19, 2026 10:40 AM
151BZ	ACCESS PANEL, FUEL TANK	2504043 / 53-20-00-232	OPENED	N	B0143806 - Alejandro Cabani llas Feb 13, 2026 10:16 AM
			READYTOCLOSE	N	B1021822 - Joseph Cuoco Feb 18, 2026 1:50 PM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 18, 2026 2:00 PM
			CLOSED	N	B1021822 - Joseph Cuoco Feb 18, 2026 2:55 PM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 19, 2026 7:03 AM
151CZ	ACCESS PANEL, FUEL TANK	2504043 / 53-20-00-232	OPENED	N	B0143806 - Alejandro Cabani llas Feb 13, 2026 10:16 AM
			READYTOCLOSE	N	B1021822 - Joseph Cuoco Feb 19, 2026 6:31 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
151CZ	ACCESS PANEL, FUEL TANK	2504043 / 53-20-00-232	OPENED	N	B0143806 - Alejandro Cabani llas Feb 13, 2026 10:16 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 19, 2026 7:03 AM
			CLOSED	N	B1021822 - Joseph Cuoco Feb 19, 2026 10:16 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 19, 2026 10:40 AM
151DZ	ACCESS PANEL, FUEL TANK	2504043 / 53-20-00-232	OPENED	N	B0143806 - Alejandro Cabani llas Feb 13, 2026 10:16 AM
			READYTOCLOSE	N	B1021822 - Joseph Cuoco Feb 18, 2026 1:50 PM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 18, 2026 2:00 PM
			CLOSED	N	B1021822 - Joseph Cuoco Feb 18, 2026 2:55 PM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 19, 2026 7:03 AM
161AL	FWD FUEL TANK ACCESS PANEL	2504038 / 53-20-00-221 2504039 / 53-20-00-229 2504036 / 53-20-00-220 2504232 / 53-20-00-227 2504091 / 53-ZL-00-213 2503774 / 53-ZL-00-212 2503806 / 57-ZL-00-201	OPENED	N	B0650736 - Jesus Gonzalez A tondo Feb 9, 2026 12:05 PM
			READYTOCLOSE	N	B0142041 - Timothy Winfree Feb 20, 2026 8:33 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
161AL	FWD FUEL TANK ACCESS PANEL	2504038 / 53-20-00-221 2504039 / 53-20-00-229 2504036 / 53-20-00-220 2504232 / 53-20-00-227 2504091 / 53-ZL-00-213 2503774 / 53-ZL-00-212 2503806 / 57-ZL-00-201	OPENED	N	B0650736 - Jesus Gonzalez A tondo Feb 9, 2026 12:05 PM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 20, 2026 9:35 AM
			CLOSED	N	B0142041 - Timothy Winfree Feb 20, 2026 10:17 AM
			INSPECTED	N	B0142244 - Todd Bridges Feb 20, 2026 5:01 PM
161CL	L/H FWD OVRWG TO FUSE WG ATTACH FAIRING	2504261 / 57-10-00-224 2503806 / 57-ZL-00-201			
			N/A	N	B0650736 - Jesus Gonzalez A tondo Feb 9, 2026 12:06 PM
161DL	L/H FWD OVRWG TO FUSE FAIRING	2504039 / 53-20-00-229 2504036 / 53-20-00-220 2504232 / 53-20-00-227 2504091 / 53-ZL-00-213 2503774 / 53-ZL-00-212 2504247 / 57-10-00-204 2504261 / 57-10-00-224 2503806 / 57-ZL-00-201	OPENED	N	B1018547 - Matthew Rossier Feb 6, 2026 4:46 PM
			READYTOCLOSE	N	B1018547 - Matthew Rossier Feb 19, 2026 9:07 PM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 20, 2026 7:47 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
161DL	L/H FWD OVRWG TO FUSE FAIRING	2504039 / 53-20-00-229 2504036 / 53-20-00-220 2504232 / 53-20-00-227 2504091 / 53-ZL-00-213 2503774 / 53-ZL-00-212 2504247 / 57-10-00-204 2504261 / 57-10-00-224 2503806 / 57-ZL-00-201	OPENED	N	B1018547 - Matthew Rossier Feb 6, 2026 4:46 PM
			CLOSED	N	B0142041 - Timothy Winfree Feb 20, 2026 7:54 AM
			INSPECTED	N	B0142244 - Todd Bridges Feb 20, 2026 5:01 PM
161EL	L/H CENTER OVRWG TO FUSE FAIRING	2504039 / 53-20-00-229 2504364 / 53-20-00-222 2504226 / 53-20-00-225 2504036 / 53-20-00-220 2504232 / 53-20-00-227 2504091 / 53-ZL-00-213 2503774 / 53-ZL-00-212 2504247 / 57-10-00-204 2504261 / 57-10-00-224 2503806 / 57-ZL-00-201	OPENED	N	B1018547 - Matthew Rossier Feb 6, 2026 4:46 PM
			READYTOCLOSE	N	B0142041 - Timothy Winfree Feb 20, 2026 7:12 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 20, 2026 7:47 AM
			CLOSED	N	B0142041 - Timothy Winfree Feb 20, 2026 7:54 AM
			INSPECTED	N	B0142244 - Todd Bridges Feb 20, 2026 5:01 PM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
161FL	L/H AFT OVRWG TO FUSE FAIRING	2504039 / 53-20-00-229 2504361 / 53-20-00-223 2504224 / 53-20-00-224 2504036 / 53-20-00-220 2503917 / 53-20-00-233 2504232 / 53-20-00-227 2504091 / 53-ZL-00-213 2503774 / 53-ZL-00-212 2504247 / 57-10-00-204 2504261 / 57-10-00-224 2503806 / 57-ZL-00-201	OPENED	N	B1018547 - Matthew Rossier Feb 6, 2026 4:46 PM
			READYTOCLOSE	N	B1018547 - Matthew Rossier Feb 19, 2026 9:07 PM
			OKTOCLOSE	N	B0623124 - Michael Stacy Feb 19, 2026 9:09 PM
			CLOSED	N	B1018547 - Matthew Rossier Feb 19, 2026 9:25 PM
			INSPECTED	N	B0623124 - Michael Stacy Feb 19, 2026 9:32 PM
			INSPECTED	Y	B0623124 - Michael Stacy Feb 20, 2026 9:44 PM
			CLOSED	Y	B0623124 - Michael Stacy Feb 20, 2026 9:44 PM
			OKTOCLOSE	Y	B0623124 - Michael Stacy Feb 20, 2026 9:44 PM
			READYTOCLOSE	Y	B0623124 - Michael Stacy Feb 20, 2026 9:44 PM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
161FL	L/H AFT OVRWG TO FUSE FAIRING	2504039 / 53-20-00-229 2504361 / 53-20-00-223 2504224 / 53-20-00-224 2504036 / 53-20-00-220 2503917 / 53-20-00-233 2504232 / 53-20-00-227 2504091 / 53-ZL-00-213 2503774 / 53-ZL-00-212 2504247 / 57-10-00-204 2504261 / 57-10-00-224 2503806 / 57-ZL-00-201	OPENED	N	B1018547 - Matthew Rossier Feb 6, 2026 4:46 PM
			READYTOCLOSE	N	B0646266 - Sergio Rodriguez Figueroa Feb 25, 2026 6:28 AM
			READYTOCLOSE	Y	B0646266 - Sergio Rodriguez Figueroa Feb 25, 2026 6:32 AM
			READYTOCLOSE	N	B0641903 - Felipe Mendoza C ervantes Feb 27, 2026 4:41 PM
			OKTOCLOSE	N	B0161691 - Thomas Mitchell Feb 27, 2026 5:44 PM
			CLOSED	N	B0641903 - Felipe Mendoza C ervantes Feb 27, 2026 6:00 PM
			INSPECTED	N	B0161691 - Thomas Mitchell Feb 27, 2026 7:45 PM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
162AR	FWD FUEL TANK ACCESS PANEL	2504038 / 53-20-00-221 2504039 / 53-20-00-229 2504036 / 53-20-00-220 2504232 / 53-20-00-227 2504091 / 53-ZL-00-213 2503774 / 53-ZL-00-212 2503807 / 57-ZL-00-202	OPENED	N	B1018409 - Areida Cruz Feb 6, 2026 5:56 PM
			READYTOCLOSE	N	B0645936 - Carlos Zerino Feb 19, 2026 6:49 PM
			OKTOCLOSE	N	B0623124 - Michael Stacy Feb 19, 2026 6:57 PM
			CLOSED	N	B0645936 - Carlos Zerino Feb 19, 2026 9:22 PM
			INSPECTED	N	B0623124 - Michael Stacy Feb 19, 2026 9:32 PM
162BR	REFUEL/DEFUEL ADAPTER DOOR	2503774 / 53-ZL-00-212			
			N/A	N	B1014141 - Christopher Draw dy Feb 11, 2026 7:58 AM
162CL	R/H FWD OVRWG TO FUSE WG ATTACH FAIRING	2504232 / 53-20-00-227 2504261 / 57-10-00-224 2503807 / 57-ZL-00-202			
			N/A	N	B0650736 - Jesus Gonzalez A tondo Feb 9, 2026 12:07 PM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
162DL	R/H FWD OVRWG TO FUSE FAIRING	2504039 / 53-20-00-229 2504036 / 53-20-00-220 2504232 / 53-20-00-227 2504091 / 53-ZL-00-213 2503774 / 53-ZL-00-212 2504247 / 57-10-00-204 2504261 / 57-10-00-224 2503807 / 57-ZL-00-202			
			N/A	N	B0650736 - Jesus Gonzalez A tondo Feb 9, 2026 12:08 PM
162DR	REFUEL/DEFUEL CONTROL PANEL	2504039 / 53-20-00-229 2504036 / 53-20-00-220 2504232 / 53-20-00-227 2504091 / 53-ZL-00-213 2503774 / 53-ZL-00-212			
			N/A	N	B0162034 - Tyler Poggi Feb 18, 2026 3:08 PM
162EL	R/H CENTER OVRWG TO FUSE FAIRING	2504039 / 53-20-00-229 2504364 / 53-20-00-222 2504226 / 53-20-00-225 2504036 / 53-20-00-220 2504232 / 53-20-00-227 2504091 / 53-ZL-00-213 2503774 / 53-ZL-00-212 2504247 / 57-10-00-204 2504261 / 57-10-00-224 2503807 / 57-ZL-00-202	OPENED	N	B1018409 - Areida Cruz Feb 6, 2026 5:20 PM
			READYTOCLOSE	N	B0645936 - Carlos Zerino Feb 19, 2026 6:49 PM
			OKTOCLOSE	N	B0623124 - Michael Stacy Feb 19, 2026 6:57 PM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
162EL	R/H CENTER OVRWG TO FUSE FAIRING	2504039 / 53-20-00-229 2504364 / 53-20-00-222 2504226 / 53-20-00-225 2504036 / 53-20-00-220 2504232 / 53-20-00-227 2504091 / 53-ZL-00-213 2503774 / 53-ZL-00-212 2504247 / 57-10-00-204 2504261 / 57-10-00-224 2503807 / 57-ZL-00-202	OPENED	N	B1018409 - Areida Cruz Feb 6, 2026 5:20 PM
			CLOSED	N	B0645936 - Carlos Zerino Feb 19, 2026 9:22 PM
			INSPECTED	N	B0623124 - Michael Stacy Feb 19, 2026 9:32 PM
162FL	R/H AFT OVRWG TO FUSE FAIRING	2504039 / 53-20-00-229 2504361 / 53-20-00-223 2504224 / 53-20-00-224 2504036 / 53-20-00-220 2503917 / 53-20-00-233 2504232 / 53-20-00-227 2504091 / 53-ZL-00-213 2503774 / 53-ZL-00-212 2504247 / 57-10-00-204 2504261 / 57-10-00-224 2503807 / 57-ZL-00-202	OPENED	N	B1018409 - Areida Cruz Feb 6, 2026 5:20 PM
			READYTOCLOSE	N	B0645936 - Carlos Zerino Feb 19, 2026 6:49 PM
			OKTOCLOSE	N	B0623124 - Michael Stacy Feb 19, 2026 6:57 PM
			CLOSED	N	B0645936 - Carlos Zerino Feb 19, 2026 9:22 PM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
162FL	R/H AFT OVRWG TO FUSE FAIRING	2504039 / 53-20-00-229 2504361 / 53-20-00-223 2504224 / 53-20-00-224 2504036 / 53-20-00-220 2503917 / 53-20-00-233 2504232 / 53-20-00-227 2504091 / 53-ZL-00-213 2503774 / 53-ZL-00-212 2504247 / 57-10-00-204 2504261 / 57-10-00-224 2503807 / 57-ZL-00-202	OPENED	N	B1018409 - Areida Cruz Feb 6, 2026 5:20 PM
			INSPECTED	N	B0623124 - Michael Stacy Feb 19, 2026 9:32 PM
			INSPECTED	Y	B0623124 - Michael Stacy Feb 20, 2026 9:44 PM
			CLOSED	Y	B0623124 - Michael Stacy Feb 20, 2026 9:44 PM
			OKTOCLOSE	Y	B0623124 - Michael Stacy Feb 20, 2026 9:44 PM
			READYTOCLOSE	Y	B0623124 - Michael Stacy Feb 20, 2026 9:44 PM
			READYTOCLOSE	N	B1022255 - Carson Chang Feb 23, 2026 9:45 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 25, 2026 6:40 AM
			CLOSED	N	B1021822 - Joseph Cuoco Feb 25, 2026 7:01 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 25, 2026 7:26 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
163AB	ACCESS PANEL	2503774 / 53-ZL-00-212			
			N/A	N	B0162034 - Tyler Poggi Feb 18, 2026 3:09 PM
163AZ	L/H MLG WHEEL BIN	2504179 / REMOVE MLG 2503908 / 27-00-00-203 2503860 / 22-12-00-212 2503749 / 53-20-00-212 2504039 / 53-20-00-229 2504361 / 53-20-00-223 2504042 / 53-20-00-230 2504226 / 53-20-00-225 2504036 / 53-20-00-220 2503948 / 29-10-00-201 2504210 / 28-10-00-209 2504232 / 53-20-00-227 2504091 / 53-ZL-00-213 2503911 / 32-00-01-212 2504048 / 53-30-00-202 2503879 / 53-ZL-00-214 2504247 / 57-10-00-204 2504261 / 57-10-00-224 2503806 / 57-ZL-00-201	OPENED	N	B1002512 - Brandon Warne Feb 5, 2026 6:43 AM
163EZ	L/H MLG WHEEL BIN ACCESS PANEL	2504179 / REMOVE MLG			
			N/A	N	B0162034 - Tyler Poggi Feb 18, 2026 3:08 PM
163FZ	L/H MLG WHEEL BIN ACCESS PANEL	2504179 / REMOVE MLG			
			N/A	N	B0162034 - Tyler Poggi Feb 18, 2026 3:08 PM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
164AZ	R/H MLG WHEEL BIN	2504179 / REMOVE MLG 2503908 / 27-00-00-203 2503860 / 22-12-00-212 2503749 / 53-20-00-212 2504039 / 53-20-00-229 2504361 / 53-20-00-223 2504042 / 53-20-00-230 2504226 / 53-20-00-225 2504036 / 53-20-00-220 2503948 / 29-10-00-201 2504210 / 28-10-00-209 2504232 / 53-20-00-227 2504091 / 53-ZL-00-213 2503911 / 32-00-01-212 2504048 / 53-30-00-202 2503879 / 53-ZL-00-214 2504247 / 57-10-00-204 2504261 / 57-10-00-224 2503807 / 57-ZL-00-202	OPENED	N	B1002512 - Brandon Warne Feb 4, 2026 7:14 AM
164EZ	R/H MLG WHEEL BIN ACCESS PANEL	2504179 / REMOVE MLG			
			N/A	N	B0162034 - Tyler Poggi Feb 18, 2026 3:08 PM
164FZ	R/H MLG WHEEL BIN ACCESS PANEL	2504179 / REMOVE MLG			
			N/A	N	B0162034 - Tyler Poggi Feb 18, 2026 3:08 PM
171AZ	ACCESS PANEL, FUEL TANK	2504070 / 53-30-00-222	OPENED	N	B1016542 - Carlos Ochoa Feb 16, 2026 6:00 PM
			READYTOCLOSE	N	B1016542 - Carlos Ochoa Feb 16, 2026 6:37 PM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
171AZ	ACCESS PANEL, FUEL TANK	2504070 / 53-30-00-222	OPENED	N	B1016542 - Carlos Ochoa Feb 16, 2026 6:00 PM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 18, 2026 9:31 AM
			CLOSED	N	B1021822 - Joseph Cuoco Feb 18, 2026 12:10 PM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 26, 2026 10:12 AM
171BZ	ACCESS PANEL, FUEL TANK	2504070 / 53-30-00-222	OPENED	N	B1016542 - Carlos Ochoa Feb 16, 2026 6:00 PM
			READYTOCLOSE	N	B1016542 - Carlos Ochoa Feb 16, 2026 6:37 PM
			OKTOCLOSE	N	B0623124 - Michael Stacy Feb 16, 2026 6:40 PM
			CLOSED	N	B1016542 - Carlos Ochoa Feb 16, 2026 9:21 PM
			INSPECTED	N	B0623124 - Michael Stacy Feb 16, 2026 9:23 PM
181BL	Maintenance Access Panel				
			N/A	N	B1014141 - Christopher Draw dy Feb 11, 2026 8:26 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
182BL	Maintenance Access Panel				
			N/A	N	B1014141 - Christopher Draw dy Feb 11, 2026 8:26 AM
191AB	LOWER FWD WING KEEL BEAM ACCESS PNL	2503860 / 22-12-00-212 2504031 / 53-20-00-216 2504363 / 53-20-00-211 2504148 / 57-10-00-201 2504150 / 57-ZL-00-203	OPENED	N	B0142041 - Timothy Winfree Feb 6, 2026 6:19 PM
			READYTOCLOSE	N	B0648431 - Caleb Sexton Mar 2, 2026 10:03 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Mar 2, 2026 10:12 AM
			OKTOCLOSE	Y	B1013522 - Brandon Jennings Mar 2, 2026 12:38 PM
			READYTOCLOSE	Y	B1013522 - Brandon Jennings Mar 2, 2026 12:38 PM
			READYTOCLOSE	N	B1016542 - Carlos Ochoa Mar 3, 2026 8:50 PM
			OKTOCLOSE	N	B0161691 - Thomas Mitchell Mar 3, 2026 9:05 PM
			CLOSED	N	B1016542 - Carlos Ochoa Mar 3, 2026 9:41 PM
			INSPECTED	N	B0161691 - Thomas Mitchell Mar 3, 2026 10:08 PM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
191AL	L/H HYD SYS ACCESS PNL	2504093 / 53-ZL-00-216 2498677 / 29-12-00-301	OPENED	N	B0648431 - Caleb Sexton Feb 13, 2026 7:48 AM
			READYTOCLOSE	N	B0646266 - Sergio Rodriguez Figueroa Feb 25, 2026 6:28 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 25, 2026 6:40 AM
			CLOSED	N	B1021822 - Joseph Cuoco Feb 25, 2026 7:01 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 25, 2026 7:26 AM
191BB	L/H LOWER FWD WG TO FUSE FAIRING	2503860 / 22-12-00-212 2504038 / 53-20-00-221 2504039 / 53-20-00-229 2504031 / 53-20-00-216 2504000 / 28-10-00-210 2504247 / 57-10-00-204 2504148 / 57-10-00-201 2504150 / 57-ZL-00-203	OPENED	N	B0650736 - Jesus Gonzalez A tondo Feb 9, 2026 10:50 AM
			READYTOCLOSE	N	B0641903 - Felipe Mendoza C ervantes Feb 18, 2026 6:50 PM
			READYTOCLOSE	Y	B0641903 - Felipe Mendoza C ervantes Feb 18, 2026 7:25 PM
			READYTOCLOSE	N	B0648431 - Caleb Sexton Mar 2, 2026 7:03 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Mar 2, 2026 7:19 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
191BB	L/H LOWER FWD WG TO FUSE FAIRING	2503860 / 22-12-00-212 2504038 / 53-20-00-221 2504039 / 53-20-00-229 2504031 / 53-20-00-216 2504000 / 28-10-00-210 2504247 / 57-10-00-204 2504148 / 57-10-00-201 2504150 / 57-ZL-00-203	OPENED	N	B0650736 - Jesus Gonzalez A tondo Feb 9, 2026 10:50 AM
			CLOSED	N	B0648431 - Caleb Sexton Mar 2, 2026 9:27 AM
			INSPECTED	N	B1013522 - Brandon Jennings Mar 2, 2026 10:11 AM
192AR	HYD SYS/WASTE SYS SRVC CONNECTION ACCESS PNL	2504093 / 53-ZL-00-216 2498677 / 29-12-00-301	OPENED	N	B0648431 - Caleb Sexton Feb 13, 2026 8:28 AM
			READYTOCLOSE	N	B0646266 - Sergio Rodriguez Figueroa Feb 25, 2026 6:28 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 25, 2026 6:40 AM
			CLOSED	N	B1021822 - Joseph Cuoco Feb 25, 2026 7:01 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 25, 2026 7:26 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
192BB	R/H LOWER FWD WG TO FUSE FAIRING	2503860 / 22-12-00-212 2504038 / 53-20-00-221 2504039 / 53-20-00-229 2504031 / 53-20-00-216 2504000 / 28-10-00-210 2504247 / 57-10-00-204 2504148 / 57-10-00-201 2504150 / 57-ZL-00-203	OPENED	N	B0142041 - Timothy Winfree Feb 8, 2026 5:28 PM
			READYTOCLOSE	N	B0641903 - Felipe Mendoza C ervantes Feb 18, 2026 6:50 PM
			OKTOCLOSE	N	B0623124 - Michael Stacy Feb 18, 2026 7:17 PM
			CLOSED	N	B0641903 - Felipe Mendoza C ervantes Feb 18, 2026 9:33 PM
			INSPECTED	N	B0161691 - Thomas Mitchell Feb 25, 2026 3:48 PM
195AB	LOWER CENTER REAR WG TO FUSE FAIRING	2504093 / 53-ZL-00-216	OPENED	N	B0650736 - Jesus Gonzalez A tondo Feb 9, 2026 9:58 AM
			READYTOCLOSE	N	B1018546 - Andres Velazquez Feb 20, 2026 11:57 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 20, 2026 12:34 PM
			CLOSED	N	B1018546 - Andres Velazquez Feb 20, 2026 1:35 PM
			INSPECTED	N	B0142244 - Todd Bridges Feb 20, 2026 2:11 PM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
211AL	L/H FWD EQUIP COMPARTMENT DOOR	2504024 / 53-10-00-201 2503776 / 53-ZL-00-219 2504025 / 53-10-00-208 2498463 / 24-00-00-301	OPENED	N	B0638589 - Sean Dodder Feb 2, 2026 9:50 PM
212AR		2504024 / 53-10-00-201 2503761 / 53-ZL-00-205 2503776 / 53-ZL-00-219 2504025 / 53-10-00-208 2503702 / 24-23-00-101 2503701 / 24-20-00-207 2498463 / 24-00-00-301 4292870 / 24-23-00-101	OPENED	N	B0638589 - Sean Dodder Feb 2, 2026 9:50 PM
212BR	Oxygen Refill Connection Door	2504024 / 53-10-00-201			
			N/A	N	B1014141 - Christopher Draw dy Feb 11, 2026 7:58 AM
221ALW	L/H FS280 BLKHD ACCESS PNL	2504186 / 22-12-00-201	OPENED	N	B1015989 - Victor Palazuelo s Feb 9, 2026 9:49 AM
221AZ	L/H FWD COCKPIT CENTER PEDESTAL ACCESS PNL	2504186 / 22-12-00-201 2504025 / 53-10-00-208 2503778 / 53-ZL-00-221	OPENED	N	B0143864 - Aaric Cerna Feb 9, 2026 2:18 PM
221BLF	FLT COMPRTMT AVIONICS BAY FLOOR PNL	2504186 / 22-12-00-201			
			N/A	N	B0142041 - Timothy Winfree Feb 20, 2026 10:47 AM
221BZ	L/H AFT COCKPIT CENTER PEDESTAL ACCESS PNL	2504186 / 22-12-00-201 2504025 / 53-10-00-208 2503778 / 53-ZL-00-221	OPENED	N	B0143864 - Aaric Cerna Feb 9, 2026 2:18 PM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
221CLF	FLIGHT COMPARTMENT AVIONICS BAY FLOOR PNL	2504193 / 22-12-00-206 2504194 / 22-12-00-207 2503857 / 22-12-00-208 2504345 / 53-20-00-206 2503866 / 27-00-00-201 2504030 / 53-20-00-203 2504222 / 53-20-00-207 2503867 / 27-00-00-202 2504357 / 53-20-00-210 2503720 / 32-00-01-210 2503687 / 34-11-00-203 2503766 / 53-ZL-00-208 2503768 / 53-ZL-00-209 2504218 / 53-10-00-203 2503718 / 32-00-01-209 2503772 / 53-ZL-00-211 2504025 / 53-10-00-208	OPENED	N	B0641378 - Calvin Ambrose Feb 5, 2026 1:37 PM
221CLW	L/H FS280 BLKHD ACCESS PNL	2504186 / 22-12-00-201	OPENED	N	B1015989 - Victor Palazuelos Feb 9, 2026 9:54 AM
221CZ	L/H AFT PILOT SIDE CONSOLE SIDE PNL	2504186 / 22-12-00-201 2504025 / 53-10-00-208 2503778 / 53-ZL-00-221	OPENED	N	B0619443 - Tyler Herrera Feb 9, 2026 1:22 PM
221DLW	L/H FS280 BLKHD ACCESS PNL	2504186 / 22-12-00-201 2503668 / 33-50-00-201	OPENED	N	B1015989 - Victor Palazuelos Feb 9, 2026 9:56 AM
221DLX	FLIGHT COMPARTMENT PANEL	2504186 / 22-12-00-201	OPENED	N	B1015989 - Victor Palazuelos Feb 10, 2026 8:50 AM
			READYTOCLOSE	N	B0141989 - Martin Romo Mar 5, 2026 8:02 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
221DZ	L/H CENTER PILOT SIDE CONSOLE SIDE PNL	2504186 / 22-12-00-201 2504025 / 53-10-00-208 2503778 / 53-ZL-00-221	OPENED	N	B1015989 - Victor Palazuelos Feb 10, 2026 6:58 AM
221ELX	FLIGHT COMPARTMENT PANEL	2504186 / 22-12-00-201	OPENED	N	B0142041 - Timothy Winfree Feb 20, 2026 10:47 AM
			READYTOCLOSE	N	B0141989 - Martin Romo Mar 5, 2026 8:32 AM
221EZ	L/H FWD PILOT SIDE CONSOLE SIDE PNL	2504186 / 22-12-00-201 2504025 / 53-10-00-208 2503778 / 53-ZL-00-221 2498463 / 24-00-00-301	OPENED	N	B0142041 - Timothy Winfree Feb 20, 2026 10:47 AM
221KZ	FLIGHT COMPARTMENT PANEL	2503712 / 27-00-00-212	OPENED	N	B0650736 - Jesus Gonzalez Atondo Feb 11, 2026 12:43 PM
221LZ	FLIGHT COMPARTMENT PANEL	2503712 / 27-00-00-212	OPENED	N	B0142041 - Timothy Winfree Feb 20, 2026 10:46 AM
221NZ	FLIGHT COMPARTMENT PANEL	2503712 / 27-00-00-212	OPENED	N	B0142041 - Timothy Winfree Feb 20, 2026 10:46 AM
221PZ	FLIGHT COMPARTMENT PANEL	2503712 / 27-00-00-212	OPENED	N	B0142041 - Timothy Winfree Feb 20, 2026 10:46 AM
221QZ	FLIGHT COMPARTMENT PANEL	2503712 / 27-00-00-212	OPENED	N	B0142041 - Timothy Winfree Feb 20, 2026 10:46 AM
221RZ	L/H INNER RUDDER PEDAL PROTECTIVE ACCESS PNL	2504186 / 22-12-00-201	OPENED	N	B0143864 - Aaric Cerna Feb 9, 2026 12:56 PM
			READYTOCLOSE	N	B0141989 - Martin Romo Mar 5, 2026 12:53 PM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
221SZ	FLIGHT COMPARTMENT PANEL	2504186 / 22-12-00-201	OPENED	N	B0143864 - Aaric Cerna Feb 9, 2026 12:56 PM
			READYTOCLOSE	N	B0141989 - Martin Romo Mar 5, 2026 12:53 PM
221TZ	L/H OUTER RUDDER PEDAL PROTECTIVE ACCESS PNL	2504186 / 22-12-00-201	OPENED	N	B0143864 - Aaric Cerna Feb 9, 2026 12:56 PM
			READYTOCLOSE	N	B0141989 - Martin Romo Mar 5, 2026 12:53 PM
221VZ	FLIGHT COMPARTMENT PANEL	2504186 / 22-12-00-201	OPENED	N	B1015989 - Victor Palazuelo s Feb 10, 2026 10:02 AM
			READYTOCLOSE	N	B0141989 - Martin Romo Mar 5, 2026 8:04 AM
222ARW	ACCESS PANEL	2504186 / 22-12-00-201	OPENED	N	B1015989 - Victor Palazuelo s Feb 9, 2026 10:31 AM
222AZ	R/H FWD COCKPIT CENTER PEDESTAL ACCESS PNL	2504186 / 22-12-00-201 2504025 / 53-10-00-208 2503778 / 53-ZL-00-221	OPENED	N	B0143864 - Aaric Cerna Feb 9, 2026 2:18 PM
222BRF	FLT COMPRTMT AVIONICS BAY FLOOR PNL	2504186 / 22-12-00-201			
			N/A	N	B0142041 - Timothy Winfree Feb 20, 2026 10:45 AM
222BZ	R/H AFT COCKPIT CENTER PEDESTAL ACCESS PNL	2504186 / 22-12-00-201 2504025 / 53-10-00-208 2503778 / 53-ZL-00-221	OPENED	N	B0143864 - Aaric Cerna Feb 9, 2026 2:18 PM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
222CRW	L/H FS280 BLKHD ACCESS PNL	2504186 / 22-12-00-201	OPENED	N	B1015989 - Victor Palazuelos Feb 9, 2026 10:30 AM
222CZ	R/H AFT COPILOT SIDE CONSOLE SIDE PNL	2504186 / 22-12-00-201 2504025 / 53-10-00-208 2503778 / 53-ZL-00-221	OPENED	N	B0641378 - Calvin Ambrose Feb 5, 2026 1:39 PM
222DRW	L/H FS280 BLKHD ACCESS PNL	2504186 / 22-12-00-201	OPENED	N	B0641378 - Calvin Ambrose Feb 5, 2026 1:38 PM
222DRX	FLIGHT COMPARTMENT PANEL	2504186 / 22-12-00-201	OPENED	N	B1015989 - Victor Palazuelos Feb 9, 2026 12:50 PM
			READYTOCLOSE	N	B0141989 - Martin Romo Mar 5, 2026 8:08 AM
222DZ	R/H CENTER COPILOT SIDE CONSOLE SIDE PNL	2504186 / 22-12-00-201 2504025 / 53-10-00-208 2503778 / 53-ZL-00-221	OPENED	N	B1015989 - Victor Palazuelos Feb 10, 2026 6:40 AM
222ERX	FLIGHT COMPARTMENT PANEL	2504186 / 22-12-00-201	OPENED	N	B0142041 - Timothy Winfree Feb 20, 2026 10:45 AM
			READYTOCLOSE	N	B0141989 - Martin Romo Mar 5, 2026 8:20 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Mar 5, 2026 9:35 AM
			CLOSED	N	B0141989 - Martin Romo Mar 5, 2026 12:20 PM
			INSPECTED	N	B0141354 - Karl Tuxhorn Mar 5, 2026 1:49 PM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
222EZ	R/H FWD COPILOT SIDE CONSOLE SIDE PNL	2504186 / 22-12-00-201 2504025 / 53-10-00-208 2503778 / 53-ZL-00-221 2498463 / 24-00-00-301	OPENED	N	B0142041 - Timothy Winfree Feb 20, 2026 10:45 AM
			READYTOCLOSE	N	B0641378 - Calvin Ambrose Feb 27, 2026 7:53 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 27, 2026 8:27 AM
			CLOSED	N	B0641378 - Calvin Ambrose Feb 27, 2026 8:34 AM
			INSPECTED	N	B1013522 - Brandon Jennings Mar 2, 2026 9:32 AM
222KZ	FLIGHT COMPARTMENT PANEL	2503712 / 27-00-00-212	OPENED	N	B1015989 - Victor Palazuelo s Feb 9, 2026 1:44 PM
222LZ	FLIGHT COMPARTMENT PANEL	2503712 / 27-00-00-212	OPENED	N	B0142041 - Timothy Winfree Feb 20, 2026 10:44 AM
222NZ	FLIGHT COMPARTMENT PANEL	2503712 / 27-00-00-212	OPENED	N	B0142041 - Timothy Winfree Feb 20, 2026 10:44 AM
222PZ	FLIGHT COMPARTMENT PANEL	2503712 / 27-00-00-212	OPENED	N	B0142041 - Timothy Winfree Feb 20, 2026 10:44 AM
222QZ	FLIGHT COMPARTMENT PANEL	2503712 / 27-00-00-212	OPENED	N	B0142041 - Timothy Winfree Feb 20, 2026 10:44 AM
222RZ	R/H INNER RUDDER PEDAL PROTECTIVE ACCESS PNL	2504186 / 22-12-00-201	OPENED	N	B1015989 - Victor Palazuelo s Feb 9, 2026 1:10 PM
			READYTOCLOSE	N	B0141989 - Martin Romo Mar 5, 2026 12:55 PM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
222SZ	FLIGHT COMPARTMENT PANEL	2504186 / 22-12-00-201	OPENED	N	B0142041 - Timothy Winfree Feb 20, 2026 10:44 AM
			READYTOCLOSE	N	B0141989 - Martin Romo Mar 5, 2026 12:55 PM
222TZ	R/H OUTER RUDDER PEDAL PROTECTIVE ACCESS PNL	2504186 / 22-12-00-201	OPENED	N	B1015989 - Victor Palazuelos Feb 9, 2026 1:15 PM
			READYTOCLOSE	N	B0141989 - Martin Romo Mar 5, 2026 12:55 PM
222VZ	FLIGHT COMPARTMENT PANEL	2504186 / 22-12-00-201	OPENED	N	B1015989 - Victor Palazuelos Feb 9, 2026 12:51 PM
			READYTOCLOSE	N	B0141989 - Martin Romo Mar 5, 2026 8:13 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Mar 5, 2026 9:35 AM
			CLOSED	N	B0141989 - Martin Romo Mar 5, 2026 12:22 PM
			INSPECTED	N	B0141354 - Karl Tuxhorn Mar 5, 2026 1:49 PM
231ALF	PASSENGER COMPARTMENT - FLOOR PANEL	2504354 / 53-20-00-204 2504222 / 53-20-00-207 2504092 / 53-ZL-00-215	OPENED	N	B0143806 - Alejandro Cabanillas Feb 12, 2026 11:54 AM
			READYTOCLOSE	N	B1002512 - Brandon Warne Feb 19, 2026 12:56 PM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 19, 2026 1:10 PM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
231ALF	PASSENGER COMPARTMENT - FLOOR PANEL	2504354 / 53-20-00-204 2504222 / 53-20-00-207 2504092 / 53-ZL-00-215	OPENED	N	B0143806 - Alejandro Cabani llas Feb 12, 2026 11:54 AM
			CLOSED	N	B1002512 - Brandon Warne Feb 19, 2026 1:56 PM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 19, 2026 2:17 PM
231BLF	PASSENGER COMPARTMENT - FLOOR PANEL	2504043 / 53-20-00-232 2504354 / 53-20-00-204 2504222 / 53-20-00-207 2504092 / 53-ZL-00-215	OPENED	N	B0143806 - Alejandro Cabani llas Feb 12, 2026 11:54 AM
			READYTOCLOSE	N	B1002512 - Brandon Warne Feb 19, 2026 12:56 PM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 19, 2026 1:10 PM
			CLOSED	N	B1002512 - Brandon Warne Feb 19, 2026 1:56 PM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 19, 2026 2:17 PM
231CLF	PASSENGER COMPARTMENT - FLOOR PANEL	2504233 / 53-20-00-228 2504194 / 22-12-00-207 2504043 / 53-20-00-232 2504354 / 53-20-00-204 2504222 / 53-20-00-207 2504230 / 53-20-00-226 2504092 / 53-ZL-00-215 2504236 / 54-50-00-201	OPENED	N	B0143806 - Alejandro Cabani llas Feb 11, 2026 1:47 PM
			READYTOCLOSE	N	B1021822 - Joseph Cuoco Feb 20, 2026 6:35 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
231CLF	PASSENGER COMPARTMENT - FLOOR PANEL	2504233 / 53-20-00-228 2504194 / 22-12-00-207 2504043 / 53-20-00-232 2504354 / 53-20-00-204 2504222 / 53-20-00-207 2504230 / 53-20-00-226 2504092 / 53-ZL-00-215 2504236 / 54-50-00-201	OPENED	N	B0143806 - Alejandro Cabani llas Feb 11, 2026 1:47 PM
			READYTOCLOSE	Y	B1013522 - Brandon Jennings Feb 20, 2026 7:11 AM
			READYTOCLOSE	N	B1021822 - Joseph Cuoco Feb 23, 2026 6:53 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 23, 2026 9:05 AM
			CLOSED	N	B1021822 - Joseph Cuoco Feb 23, 2026 9:28 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 23, 2026 10:45 AM
231DLF	PASSENGER COMPARTMENT - FLOOR PANEL	2504233 / 53-20-00-228 2504230 / 53-20-00-226 2504092 / 53-ZL-00-215	OPENED	N	B0143806 - Alejandro Cabani llas Feb 11, 2026 11:57 AM
			READYTOCLOSE	N	B1018547 - Matthew Rossier Feb 18, 2026 6:47 PM
			OKTOCLOSE	N	B0623124 - Michael Stacy Feb 18, 2026 7:06 PM
			CLOSED	N	B1018547 - Matthew Rossier Feb 18, 2026 9:19 PM
			CLOSED	Y	B1013522 - Brandon Jennings Feb 24, 2026 10:49 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
231ELF	PASSENGER COMPARTMENT - FLOOR PANEL	2504354 / 53-20-00-204 2504222 / 53-20-00-207 2504010 / 32-00-01-211 2504092 / 53-ZL-00-215	OPENED	N	B0143806 - Alejandro Cabani llas Feb 12, 2026 11:54 AM
			READYTOCLOSE	N	B1002512 - Brandon Warne Feb 19, 2026 8:20 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 19, 2026 8:47 AM
			CLOSED	N	B1002512 - Brandon Warne Feb 19, 2026 10:21 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 19, 2026 10:52 AM
231FLF	PASSENGER COMPARTMENT - FLOOR PANEL	2504203 / 27-00-00-204 2504354 / 53-20-00-204 2504222 / 53-20-00-207 2504010 / 32-00-01-211 2504092 / 53-ZL-00-215	OPENED	N	B0143806 - Alejandro Cabani llas Feb 12, 2026 11:54 AM
			READYTOCLOSE	N	B1002512 - Brandon Warne Feb 19, 2026 8:20 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 19, 2026 8:47 AM
			CLOSED	N	B1002512 - Brandon Warne Feb 19, 2026 10:21 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 19, 2026 10:52 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
231GLF	PASSENGER COMPARTMENT - FLOOR PANEL	2504043 / 53-20-00-232 2504354 / 53-20-00-204 2504222 / 53-20-00-207 2504010 / 32-00-01-211 2504092 / 53-ZL-00-215	OPENED	N	B0143806 - Alejandro Cabani llas Feb 11, 2026 1:47 PM
			READYTOCLOSE	N	B1002512 - Brandon Warne Feb 19, 2026 8:20 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 19, 2026 8:47 AM
			CLOSED	N	B1002512 - Brandon Warne Feb 19, 2026 10:21 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 19, 2026 10:52 AM
231HLF	PASSENGER COMPARTMENT - FLOOR PANEL	2504203 / 27-00-00-204 2504043 / 53-20-00-232 2504354 / 53-20-00-204 2504222 / 53-20-00-207 2504357 / 53-20-00-210 2504010 / 32-00-01-211 2504092 / 53-ZL-00-215	OPENED	N	B0143806 - Alejandro Cabani llas Feb 11, 2026 1:47 PM
			READYTOCLOSE	N	B1002512 - Brandon Warne Feb 19, 2026 8:20 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 19, 2026 8:47 AM
			CLOSED	N	B1002512 - Brandon Warne Feb 19, 2026 10:21 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 19, 2026 10:52 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
231JLF	PASSENGER COMPARTMENT - FLOOR PANEL	2504233 / 53-20-00-228 2504043 / 53-20-00-232 2504354 / 53-20-00-204 2504222 / 53-20-00-207 2504230 / 53-20-00-226 2504010 / 32-00-01-211 2504092 / 53-ZL-00-215	OPENED	N	B0143806 - Alejandro Cabani llas Feb 11, 2026 11:57 AM
			READYTOCLOSE	N	B0613291 - Eric Strong Feb 20, 2026 7:47 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 20, 2026 8:39 AM
			CLOSED	N	B0613291 - Eric Strong Feb 20, 2026 10:38 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 20, 2026 11:46 AM
231KLF	PASSENGER COMPARTMENT - FLOOR PANEL	2504233 / 53-20-00-228 2504203 / 27-00-00-204 2504043 / 53-20-00-232 2504354 / 53-20-00-204 2504222 / 53-20-00-207 2504357 / 53-20-00-210 2504230 / 53-20-00-226 2504092 / 53-ZL-00-215	OPENED	N	B0143806 - Alejandro Cabani llas Feb 11, 2026 11:57 AM
			READYTOCLOSE	N	B0613291 - Eric Strong Feb 20, 2026 7:47 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 20, 2026 8:39 AM
			CLOSED	N	B0613291 - Eric Strong Feb 20, 2026 10:38 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
231KLF	PASSENGER COMPARTMENT - FLOOR PANEL	2504233 / 53-20-00-228 2504203 / 27-00-00-204 2504043 / 53-20-00-232 2504354 / 53-20-00-204 2504222 / 53-20-00-207 2504357 / 53-20-00-210 2504230 / 53-20-00-226 2504092 / 53-ZL-00-215	OPENED	N	B0143806 - Alejandro Cabani llas Feb 11, 2026 11:57 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 20, 2026 11:46 AM
231LLF	PASSENGER COMPARTMENT - FLOOR PANEL	2504233 / 53-20-00-228 2504220 / 53-20-00-201 2504230 / 53-20-00-226 2504010 / 32-00-01-211 2504092 / 53-ZL-00-215	OPENED	N	B0143806 - Alejandro Cabani llas Feb 11, 2026 11:57 AM
			READYTOCLOSE	N	B1018547 - Matthew Rossier Feb 18, 2026 6:47 PM
			OKTOCLOSE	N	B0623124 - Michael Stacy Feb 18, 2026 7:06 PM
			CLOSED	N	B1018547 - Matthew Rossier Feb 18, 2026 9:18 PM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 24, 2026 10:48 AM
231MLF	PASSENGER COMPARTMENT - FLOOR PANEL	2504233 / 53-20-00-228 2504203 / 27-00-00-204 2504230 / 53-20-00-226 2504092 / 53-ZL-00-215	OPENED	N	B0143806 - Alejandro Cabani llas Feb 11, 2026 11:57 AM
			READYTOCLOSE	N	B1018547 - Matthew Rossier Feb 18, 2026 6:47 PM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
231MLF	PASSENGER COMPARTMENT - FLOOR PANEL	2504233 / 53-20-00-228 2504203 / 27-00-00-204 2504230 / 53-20-00-226 2504092 / 53-ZL-00-215	OPENED	N	B0143806 - Alejandro Cabani llas Feb 11, 2026 11:57 AM
			OKTOCLOSE	N	B0623124 - Michael Stacy Feb 18, 2026 7:06 PM
			CLOSED	N	B1018547 - Matthew Rossier Feb 18, 2026 9:18 PM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 24, 2026 10:48 AM
231NLF	PASSENGER COMPARTMENT - FLOOR PANEL	2504233 / 53-20-00-228 2504230 / 53-20-00-226 2504092 / 53-ZL-00-215	OPENED	N	B0143806 - Alejandro Cabani llas Feb 11, 2026 11:57 AM
			READYTOCLOSE	N	B1018547 - Matthew Rossier Feb 18, 2026 6:47 PM
			OKTOCLOSE	N	B0623124 - Michael Stacy Feb 18, 2026 7:06 PM
			CLOSED	N	B1018547 - Matthew Rossier Feb 18, 2026 9:18 PM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 24, 2026 10:48 AM
231PLF	PASSENGER COMPARTMENT - FLOOR PANEL	2504203 / 27-00-00-204 2504354 / 53-20-00-204 2504222 / 53-20-00-207 2504092 / 53-ZL-00-215	OPENED	N	B0143806 - Alejandro Cabani llas Feb 12, 2026 11:54 AM
			READYTOCLOSE	N	B1002512 - Brandon Warne Feb 19, 2026 8:20 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
231PLF	PASSENGER COMPARTMENT - FLOOR PANEL	2504203 / 27-00-00-204 2504354 / 53-20-00-204 2504222 / 53-20-00-207 2504092 / 53-ZL-00-215	OPENED	N	B0143806 - Alejandro Cabani llas Feb 12, 2026 11:54 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 19, 2026 8:47 AM
			CLOSED	N	B1002512 - Brandon Warne Feb 19, 2026 10:21 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 19, 2026 10:52 AM
231QLF	PASSENGER COMPARTMENT - FLOOR PANEL	2504354 / 53-20-00-204 2504222 / 53-20-00-207 2504092 / 53-ZL-00-215	OPENED	N	B0143806 - Alejandro Cabani llas Feb 12, 2026 11:54 AM
			READYTOCLOSE	N	B1002512 - Brandon Warne Feb 19, 2026 8:20 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 19, 2026 8:47 AM
			CLOSED	N	B1002512 - Brandon Warne Feb 19, 2026 10:21 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 19, 2026 10:52 AM
231RLF	PASSENGER COMPARTMENT - FLOOR PANEL	2504043 / 53-20-00-232 2504354 / 53-20-00-204 2504222 / 53-20-00-207 2504092 / 53-ZL-00-215	OPENED	N	B0143806 - Alejandro Cabani llas Feb 11, 2026 1:47 PM
			READYTOCLOSE	N	B1002512 - Brandon Warne Feb 19, 2026 8:20 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
231RLF	PASSENGER COMPARTMENT - FLOOR PANEL	2504043 / 53-20-00-232 2504354 / 53-20-00-204 2504222 / 53-20-00-207 2504092 / 53-ZL-00-215	OPENED	N	B0143806 - Alejandro Cabani llas Feb 11, 2026 1:47 PM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 19, 2026 8:47 AM
			CLOSED	N	B1002512 - Brandon Warne Feb 19, 2026 10:21 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 19, 2026 10:52 AM
231SLF	PASSENGER COMPARTMENT - FLOOR PANEL	2504354 / 53-20-00-204 2504222 / 53-20-00-207 2504092 / 53-ZL-00-215	OPENED	N	B1018339 - Dwain Wolf Feb 12, 2026 12:58 PM
			READYTOCLOSE	N	B1002512 - Brandon Warne Feb 19, 2026 8:20 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 23, 2026 10:50 AM
			CLOSED	N	B1021822 - Joseph Cuoco Feb 23, 2026 1:54 PM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 23, 2026 2:00 PM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
231TLF	PASSENGER COMPARTMENT - FLOOR PANEL	2504352 / 22-12-00-211 2504233 / 53-20-00-228 2504043 / 53-20-00-232 2504354 / 53-20-00-204 2504222 / 53-20-00-207 2504230 / 53-20-00-226 2504092 / 53-ZL-00-215	OPENED	N	B0143806 - Alejandro Cabani llas Feb 11, 2026 11:57 AM
			READYTOCLOSE	N	B0613291 - Eric Strong Feb 20, 2026 7:47 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 20, 2026 8:39 AM
			CLOSED	N	B0613291 - Eric Strong Feb 20, 2026 10:38 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 20, 2026 11:46 AM
231ULF	PASSENGER COMPARTMENT - FLOOR PANEL	2504354 / 53-20-00-204 2504222 / 53-20-00-207 2504036 / 53-20-00-220 2504230 / 53-20-00-226 2504092 / 53-ZL-00-215	OPENED	N	B1018339 - Dwain Wolf Feb 12, 2026 12:58 PM
			READYTOCLOSE	N	B0613291 - Eric Strong Feb 20, 2026 7:47 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 20, 2026 8:39 AM
			CLOSED	N	B0613291 - Eric Strong Feb 20, 2026 10:38 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 20, 2026 11:46 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
231WLF	PASSENGER COMPARTMENT - FLOOR PANEL	2504036 / 53-20-00-220 2504230 / 53-20-00-226 2504092 / 53-ZL-00-215	OPENED	N	B1018339 - Dwain Wolf Feb 12, 2026 10:51 AM
			READYTOCLOSE	N	B1021822 - Joseph Cuoco Feb 23, 2026 10:14 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 23, 2026 10:50 AM
			CLOSED	N	B1021822 - Joseph Cuoco Feb 24, 2026 9:15 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 24, 2026 10:48 AM
231XLF	PASSENGER COMPARTMENT - FLOOR PANEL	2504233 / 53-20-00-228 2504230 / 53-20-00-226 2504092 / 53-ZL-00-215	OPENED	N	B0143806 - Alejandro Cabani llas Feb 11, 2026 11:57 AM
			READYTOCLOSE	N	B0648431 - Caleb Sexton Feb 20, 2026 8:50 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 20, 2026 9:37 AM
			CLOSED	N	B1022255 - Carson Chang Feb 20, 2026 10:11 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 24, 2026 10:48 AM
231YLF	PASSENGER COMPARTMENT - FLOOR PANEL	2504233 / 53-20-00-228 2504230 / 53-20-00-226 2504092 / 53-ZL-00-215	OPENED	N	B0143806 - Alejandro Cabani llas Feb 11, 2026 1:55 PM
			READYTOCLOSE	N	B1021822 - Joseph Cuoco Feb 20, 2026 11:55 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
231YLF	PASSENGER COMPARTMENT - FLOOR PANEL	2504233 / 53-20-00-228 2504230 / 53-20-00-226 2504092 / 53-ZL-00-215	OPENED	N	B0143806 - Alejandro Cabani llas Feb 11, 2026 1:55 PM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 20, 2026 12:09 PM
			CLOSED	N	B1021822 - Joseph Cuoco Feb 20, 2026 2:05 PM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 20, 2026 2:08 PM
232ERF	PASSENGER COMPARTMENT - FLOOR PANEL	2504354 / 53-20-00-204 2504222 / 53-20-00-207 2504092 / 53-ZL-00-215	OPENED	N	B0143806 - Alejandro Cabani llas Feb 12, 2026 11:54 AM
			READYTOCLOSE	N	B1002512 - Brandon Warne Feb 19, 2026 12:56 PM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 19, 2026 1:10 PM
			CLOSED	N	B1002512 - Brandon Warne Feb 19, 2026 1:56 PM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 19, 2026 2:17 PM
232FRF	PASSENGER COMPARTMENT - FLOOR PANEL	2504203 / 27-00-00-204 2504043 / 53-20-00-232 2504354 / 53-20-00-204 2504222 / 53-20-00-207 2504092 / 53-ZL-00-215	OPENED	N	B0143806 - Alejandro Cabani llas Feb 11, 2026 1:47 PM
			READYTOCLOSE	N	B1021822 - Joseph Cuoco Feb 20, 2026 6:35 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
232FRF	PASSENGER COMPARTMENT - FLOOR PANEL	2504203 / 27-00-00-204 2504043 / 53-20-00-232 2504354 / 53-20-00-204 2504222 / 53-20-00-207 2504092 / 53-ZL-00-215	OPENED	N	B0143806 - Alejandro Cabani llas Feb 11, 2026 1:47 PM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 20, 2026 7:10 AM
			CLOSED	N	B1021822 - Joseph Cuoco Feb 20, 2026 7:42 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 20, 2026 8:38 AM
232GRF	PASSENGER COMPARTMENT - FLOOR PANEL	2504043 / 53-20-00-232 2504354 / 53-20-00-204 2504222 / 53-20-00-207 2504357 / 53-20-00-210 2504092 / 53-ZL-00-215	OPENED	N	B0143806 - Alejandro Cabani llas Feb 11, 2026 1:47 PM
			READYTOCLOSE	N	B1021822 - Joseph Cuoco Feb 20, 2026 6:35 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 20, 2026 7:10 AM
			CLOSED	N	B1021822 - Joseph Cuoco Feb 20, 2026 7:42 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 20, 2026 8:38 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
232HRF	PASSENGER COMPARTMENT - FLOOR PANEL	2504233 / 53-20-00-228 2504203 / 27-00-00-204 2504043 / 53-20-00-232 2504354 / 53-20-00-204 2504222 / 53-20-00-207 2504230 / 53-20-00-226 2504092 / 53-ZL-00-215	OPENED	N	B0143806 - Alejandro Cabani llas Feb 11, 2026 11:57 AM
			READYTOCLOSE	N	B1021822 - Joseph Cuoco Feb 20, 2026 7:51 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 20, 2026 8:39 AM
			CLOSED	N	B1021822 - Joseph Cuoco Feb 20, 2026 10:40 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 20, 2026 11:46 AM
232JRF	PASSENGER COMPARTMENT - FLOOR PANEL	2504233 / 53-20-00-228 2504043 / 53-20-00-232 2504354 / 53-20-00-204 2504222 / 53-20-00-207 2504357 / 53-20-00-210 2504230 / 53-20-00-226 2504092 / 53-ZL-00-215	OPENED	N	B0143806 - Alejandro Cabani llas Feb 11, 2026 11:57 AM
			READYTOCLOSE	N	B1021822 - Joseph Cuoco Feb 20, 2026 7:51 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 20, 2026 8:39 AM
			CLOSED	N	B1021822 - Joseph Cuoco Feb 20, 2026 10:40 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 20, 2026 11:46 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
232KRF	PASSENGER COMPARTMENT - FLOOR PANEL	2504233 / 53-20-00-228 2504203 / 27-00-00-204 2504230 / 53-20-00-226 2504092 / 53-ZL-00-215	OPENED	N	B0143806 - Alejandro Cabani llas Feb 12, 2026 12:01 PM
			READYTOCLOSE	N	B1021822 - Joseph Cuoco Feb 23, 2026 6:53 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 23, 2026 9:05 AM
			CLOSED	N	B1021822 - Joseph Cuoco Feb 23, 2026 9:28 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 23, 2026 10:45 AM
232LRF	PASSENGER COMPARTMENT - FLOOR PANEL	2504233 / 53-20-00-228 2504230 / 53-20-00-226 2504092 / 53-ZL-00-215	OPENED	N	B0143806 - Alejandro Cabani llas Feb 11, 2026 11:57 AM
			READYTOCLOSE	N	B1021822 - Joseph Cuoco Feb 23, 2026 6:53 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 23, 2026 9:05 AM
			CLOSED	N	B1021822 - Joseph Cuoco Feb 23, 2026 9:28 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 23, 2026 10:45 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
232MRF	PASSENGER COMPARTMENT - FLOOR PANEL	2504193 / 22-12-00-206 2504233 / 53-20-00-228 2504203 / 27-00-00-204 2504191 / 22-12-00-205 2504230 / 53-20-00-226 2504092 / 53-ZL-00-215	OPENED	N	B0143806 - Alejandro Cabani llas Feb 11, 2026 11:57 AM
			READYTOCLOSE	N	B1021822 - Joseph Cuoco Feb 24, 2026 7:02 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 24, 2026 7:42 AM
			CLOSED	N	B1021822 - Joseph Cuoco Feb 24, 2026 8:36 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 24, 2026 10:48 AM
232NRF	PASSENGER COMPARTMENT - FLOOR PANEL	2504354 / 53-20-00-204 2504222 / 53-20-00-207 2504092 / 53-ZL-00-215	OPENED	N	B0143806 - Alejandro Cabani llas Feb 12, 2026 11:54 AM
			READYTOCLOSE	N	B1002512 - Brandon Warne Feb 19, 2026 12:56 PM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 19, 2026 1:10 PM
			CLOSED	N	B1002512 - Brandon Warne Feb 19, 2026 1:56 PM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 19, 2026 2:17 PM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
232PRF	PASSENGER COMPARTMENT - FLOOR PANEL	2504203 / 27-00-00-204 2504043 / 53-20-00-232 2504354 / 53-20-00-204 2504222 / 53-20-00-207 2504092 / 53-ZL-00-215	OPENED	N	B0143806 - Alejandro Cabani llas Feb 11, 2026 1:47 PM
			READYTOCLOSE	N	B1021822 - Joseph Cuoco Feb 20, 2026 6:35 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 20, 2026 7:10 AM
			CLOSED	N	B1021822 - Joseph Cuoco Feb 20, 2026 7:42 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 20, 2026 8:38 AM
232QRF	PASSENGER COMPARTMENT - FLOOR PANEL	2504354 / 53-20-00-204 2504222 / 53-20-00-207 2504092 / 53-ZL-00-215	OPENED	N	B0143806 - Alejandro Cabani llas Feb 12, 2026 11:54 AM
			READYTOCLOSE	N	B1021822 - Joseph Cuoco Feb 20, 2026 6:35 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 20, 2026 7:10 AM
			CLOSED	N	B1021822 - Joseph Cuoco Feb 20, 2026 7:42 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 20, 2026 8:38 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
232RRF	PASSENGER COMPARTMENT - FLOOR PANEL	2504352 / 22-12-00-211 2504233 / 53-20-00-228 2504043 / 53-20-00-232 2504354 / 53-20-00-204 2504222 / 53-20-00-207 2504230 / 53-20-00-226 2504092 / 53-ZL-00-215	OPENED	N	B0143806 - Alejandro Cabani llas Feb 11, 2026 11:57 AM
			READYTOCLOSE	N	B1021822 - Joseph Cuoco Feb 20, 2026 7:51 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 20, 2026 8:39 AM
			CLOSED	N	B1021822 - Joseph Cuoco Feb 20, 2026 10:40 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 20, 2026 11:46 AM
232SRF	PASSENGER COMPARTMENT - FLOOR PANEL	2504354 / 53-20-00-204 2504222 / 53-20-00-207 2504036 / 53-20-00-220 2504230 / 53-20-00-226 2504092 / 53-ZL-00-215	OPENED	N	B0143806 - Alejandro Cabani llas Feb 12, 2026 11:54 AM
			READYTOCLOSE	N	B1021822 - Joseph Cuoco Feb 20, 2026 7:51 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 20, 2026 8:39 AM
			CLOSED	N	B1021822 - Joseph Cuoco Feb 20, 2026 10:40 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 20, 2026 11:46 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
232URF	PASSENGER COMPARTMENT - FLOOR PANEL	2504036 / 53-20-00-220 2504230 / 53-20-00-226 2504092 / 53-ZL-00-215	OPENED	N	B0143806 - Alejandro Cabani llas Feb 12, 2026 11:54 AM
			READYTOCLOSE	N	B1018547 - Matthew Rossier Feb 18, 2026 3:41 PM
			OKTOCLOSE	N	B0161691 - Thomas Mitchell Feb 18, 2026 4:25 PM
			CLOSED	N	B1018547 - Matthew Rossier Feb 18, 2026 6:45 PM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 24, 2026 10:48 AM
232VRF	PASSENGER COMPARTMENT - FLOOR PANEL	2504233 / 53-20-00-228 2504230 / 53-20-00-226 2504092 / 53-ZL-00-215	OPENED	N	B0143806 - Alejandro Cabani llas Feb 11, 2026 11:57 AM
			READYTOCLOSE	N	B1018547 - Matthew Rossier Feb 18, 2026 3:41 PM
			OKTOCLOSE	N	B0161691 - Thomas Mitchell Feb 18, 2026 4:25 PM
			CLOSED	N	B1018547 - Matthew Rossier Feb 18, 2026 6:45 PM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 24, 2026 10:48 AM
232WRF	PASSENGER COMPARTMENT - FLOOR PANEL	2504233 / 53-20-00-228 2504230 / 53-20-00-226 2504092 / 53-ZL-00-215	OPENED	N	B0143806 - Alejandro Cabani llas Feb 11, 2026 11:57 AM
			READYTOCLOSE	N	B1018547 - Matthew Rossier Feb 18, 2026 3:41 PM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
232WRF	PASSENGER COMPARTMENT - FLOOR PANEL	2504233 / 53-20-00-228 2504230 / 53-20-00-226 2504092 / 53-ZL-00-215	OPENED	N	B0143806 - Alejandro Cabani llas Feb 11, 2026 11:57 AM
			OKTOCLOSE	N	B0161691 - Thomas Mitchell Feb 18, 2026 4:25 PM
			CLOSED	N	B1018547 - Matthew Rossier Feb 18, 2026 6:45 PM
			CLOSED	Y	B1013522 - Brandon Jennings Feb 24, 2026 10:49 AM
			OKTOCLOSE	Y	B1013522 - Brandon Jennings Feb 24, 2026 10:50 AM
			READYTOCLOSE	Y	B1013522 - Brandon Jennings Feb 24, 2026 10:51 AM
			READYTOCLOSE	N	B1021822 - Joseph Cuoco Mar 4, 2026 6:21 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Mar 4, 2026 6:36 AM
			CLOSED	N	B1021822 - Joseph Cuoco Mar 4, 2026 7:08 AM
			INSPECTED	N	B1013522 - Brandon Jennings Mar 4, 2026 7:34 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
241ALF	BAGGAGE COMPARTMENT - FLOOR PANEL	2504210 / 28-10-00-209 2504054 / 53-30-00-206 2504045 / 53-30-00-201 2504068 / 53-30-00-222 2504107 / 53-ZL-00-233 2504057 / 53-30-00-209	OPENED	N	B0143806 - Alejandro Cabani llas Feb 11, 2026 1:47 PM
			READYTOCLOSE	N	B1021822 - Joseph Cuoco Feb 24, 2026 7:02 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 24, 2026 7:42 AM
			CLOSED	N	B1021822 - Joseph Cuoco Feb 24, 2026 8:36 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 24, 2026 10:48 AM
			INSPECTED	Y	B1013522 - Brandon Jennings Feb 27, 2026 1:32 PM
			CLOSED	Y	B1013522 - Brandon Jennings Feb 27, 2026 1:32 PM
			OKTOCLOSE	Y	B1013522 - Brandon Jennings Feb 27, 2026 1:33 PM
			READYTOCLOSE	Y	B1013522 - Brandon Jennings Feb 27, 2026 1:33 PM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
241BLF		2504193 / 22-12-00-206 2504191 / 22-12-00-205 2504210 / 28-10-00-209 2504054 / 53-30-00-206 2504068 / 53-30-00-222 2503752 / 53-30-00-207 2504107 / 53-ZL-00-233 2504057 / 53-30-00-209	OPENED	N	B0143806 - Alejandro Cabani llas Feb 11, 2026 11:57 AM
			READYTOCLOSE	N	B1018547 - Matthew Rossier Feb 18, 2026 2:53 PM
			READYTOCLOSE	Y	B1018547 - Matthew Rossier Feb 18, 2026 3:40 PM
			READYTOCLOSE	N	B0648431 - Caleb Sexton Feb 20, 2026 8:48 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 20, 2026 9:37 AM
			CLOSED	N	B1022255 - Carson Chang Feb 20, 2026 10:11 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 24, 2026 10:48 AM
241CLF	BAGGAGE COMPARTMENT - FLOOR PANEL	2504210 / 28-10-00-209 2504054 / 53-30-00-206 2504045 / 53-30-00-201 2504068 / 53-30-00-222 2504107 / 53-ZL-00-233 2504057 / 53-30-00-209	OPENED	N	B0143806 - Alejandro Cabani llas Feb 11, 2026 1:47 PM
			READYTOCLOSE	N	B1018547 - Matthew Rossier Feb 18, 2026 2:42 PM
			READYTOCLOSE	Y	B1018547 - Matthew Rossier Feb 18, 2026 3:39 PM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
241CLF	BAGGAGE COMPARTMENT - FLOOR PANEL	2504210 / 28-10-00-209 2504054 / 53-30-00-206 2504045 / 53-30-00-201 2504068 / 53-30-00-222 2504107 / 53-ZL-00-233 2504057 / 53-30-00-209	OPENED	N	B0143806 - Alejandro Cabani llas Feb 11, 2026 1:47 PM
			READYTOCLOSE	N	B0648431 - Caleb Sexton Feb 20, 2026 8:48 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 20, 2026 9:37 AM
			CLOSED	N	B1022255 - Carson Chang Feb 20, 2026 10:10 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 24, 2026 10:48 AM
241DLF	BAGGAGE COMPARTMENT - FLOOR PANEL	2504193 / 22-12-00-206 2504191 / 22-12-00-205 2504210 / 28-10-00-209 2504054 / 53-30-00-206 2503693 / 53-ZL-00-217 2503668 / 33-50-00-201 2504068 / 53-30-00-222 2503752 / 53-30-00-207 2504107 / 53-ZL-00-233 2504057 / 53-30-00-209	OPENED	N	B0619443 - Tyler Herrera Feb 11, 2026 6:53 AM
			READYTOCLOSE	N	B1021822 - Joseph Cuoco Feb 24, 2026 1:16 PM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 24, 2026 1:17 PM
			CLOSED	N	B1021822 - Joseph Cuoco Feb 24, 2026 1:18 PM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
241DLF	BAGGAGE COMPARTMENT - FLOOR PANEL	2504193 / 22-12-00-206 2504191 / 22-12-00-205 2504210 / 28-10-00-209 2504054 / 53-30-00-206 2503693 / 53-ZL-00-217 2503668 / 33-50-00-201 2504068 / 53-30-00-222 2503752 / 53-30-00-207 2504107 / 53-ZL-00-233 2504057 / 53-30-00-209	OPENED	N	B0619443 - Tyler Herrera Feb 11, 2026 6:53 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 24, 2026 1:19 PM
241ELF	BAGGAGE COMPARTMENT - FLOOR PANEL	2503995 / 27-00-00-205 2504210 / 28-10-00-209 2504054 / 53-30-00-206 2504045 / 53-30-00-201 2504068 / 53-30-00-222 2504107 / 53-ZL-00-233 2504057 / 53-30-00-209	OPENED	N	B1018339 - Dwain Wolf Feb 12, 2026 10:51 AM
			READYTOCLOSE	N	B0648431 - Caleb Sexton Feb 20, 2026 8:48 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 20, 2026 9:37 AM
			CLOSED	N	B1022255 - Carson Chang Feb 20, 2026 10:10 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 24, 2026 10:48 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
241FLF	BAGGAGE COMPARTMENT - FLOOR PANEL	2503995 / 27-00-00-205 2504210 / 28-10-00-209 2504054 / 53-30-00-206 2504068 / 53-30-00-222 2503752 / 53-30-00-207 2504107 / 53-ZL-00-233 2504057 / 53-30-00-209 2504060 / 53-30-00-211	OPENED	N	B0143806 - Alejandro Cabani llas Feb 11, 2026 11:57 AM
			READYTOCLOSE	N	B1018547 - Matthew Rossier Feb 18, 2026 2:42 PM
			READYTOCLOSE	Y	B1018547 - Matthew Rossier Feb 18, 2026 2:54 PM
			READYTOCLOSE	N	B0648431 - Caleb Sexton Feb 20, 2026 8:48 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 20, 2026 9:37 AM
			CLOSED	N	B1022255 - Carson Chang Feb 20, 2026 10:10 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 24, 2026 10:48 AM
242CRF	BAGGAGE COMPARTMENT - FLOOR PANEL	2504210 / 28-10-00-209 2504054 / 53-30-00-206 2504045 / 53-30-00-201 2504068 / 53-30-00-222 2504107 / 53-ZL-00-233 2504057 / 53-30-00-209	OPENED	N	B1018547 - Matthew Rossier Feb 12, 2026 3:52 PM
			READYTOCLOSE	N	B1021822 - Joseph Cuoco Feb 24, 2026 10:52 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 24, 2026 12:49 PM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
242CRF	BAGGAGE COMPARTMENT - FLOOR PANEL	2504210 / 28-10-00-209 2504054 / 53-30-00-206 2504045 / 53-30-00-201 2504068 / 53-30-00-222 2504107 / 53-ZL-00-233 2504057 / 53-30-00-209	OPENED	N	B1018547 - Matthew Rossier Feb 12, 2026 3:52 PM
			CLOSED	N	B1021822 - Joseph Cuoco Feb 24, 2026 1:06 PM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 24, 2026 1:17 PM
242DRF	BAGGAGE COMPARTMENT - FLOOR PANEL	2504193 / 22-12-00-206 2504191 / 22-12-00-205 2504210 / 28-10-00-209 2504054 / 53-30-00-206 2503693 / 53-ZL-00-217 2504068 / 53-30-00-222 2503752 / 53-30-00-207 2504107 / 53-ZL-00-233 2504057 / 53-30-00-209	OPENED	N	B0143806 - Alejandro Cabani llas Feb 11, 2026 11:57 AM
			READYTOCLOSE	N	B1018547 - Matthew Rossier Feb 18, 2026 2:42 PM
			READYTOCLOSE	Y	B1018547 - Matthew Rossier Feb 18, 2026 3:39 PM
			READYTOCLOSE	N	B0648431 - Caleb Sexton Feb 20, 2026 8:50 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 20, 2026 9:37 AM
			CLOSED	N	B0648431 - Caleb Sexton Feb 20, 2026 10:09 AM

Bombardier

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
242DRF	BAGGAGE COMPARTMENT - FLOOR PANEL	2504193 / 22-12-00-206 2504191 / 22-12-00-205 2504210 / 28-10-00-209 2504054 / 53-30-00-206 2503693 / 53-ZL-00-217 2504068 / 53-30-00-222 2503752 / 53-30-00-207 2504107 / 53-ZL-00-233 2504057 / 53-30-00-209	OPENED	N	B0143806 - Alejandro Cabani llas Feb 11, 2026 11:57 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 24, 2026 10:48 AM
242FRF	BAGGAGE COMPARTMENT - FLOOR PANEL	2503995 / 27-00-00-205 2504210 / 28-10-00-209 2504054 / 53-30-00-206 2504068 / 53-30-00-222 2503752 / 53-30-00-207 2504107 / 53-ZL-00-233 2504057 / 53-30-00-209	OPENED	N	B1002512 - Brandon Warne Feb 16, 2026 6:52 AM
			READYTOCLOSE	N	B0648431 - Caleb Sexton Feb 20, 2026 8:50 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 20, 2026 9:37 AM
			CLOSED	N	B0648431 - Caleb Sexton Feb 20, 2026 10:09 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 24, 2026 10:48 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
242GRF	BAGGAGE COMPARTMENT - FLOOR PANEL	2503995 / 27-00-00-205 2504054 / 53-30-00-206 2504045 / 53-30-00-201 2504107 / 53-ZL-00-233 2504057 / 53-30-00-209			
			N/A	N	B0142041 - Timothy Winfree Feb 20, 2026 10:43 AM
242HRF	BAGGAGE COMPARTMENT - FLOOR PANEL	2503995 / 27-00-00-205 2504054 / 53-30-00-206 2504045 / 53-30-00-201 2504107 / 53-ZL-00-233 2504057 / 53-30-00-209			
			N/A	N	B0142041 - Timothy Winfree Feb 20, 2026 10:43 AM
311AL	L/H AFT APU SERVICE DOOR	2503780 / 53-ZL-00-227			
			N/A	N	B1014141 - Christopher Draw dy Feb 11, 2026 7:58 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
311BB	Aft Equipment Compartment Door	2503707 / 26-21-16-201 2503999 / 27-00-00-207 2503709 / 27-00-00-208 2503854 / 22-12-00-202 2504002 / 28-20-00-202 2503855 / 22-12-00-204 2503676 / 24-20-00-206 2504006 / 31-31-00-203 2504079 / 53-50-00-203 2503754 / 53-30-00-215 2504007 / 31-31-00-204 2503661 / 53-ZL-00-228 2504069 / 53-30-00-223 2504056 / 53-30-00-208 2504064 / 53-30-00-216 2504050 / 53-30-00-203 2504072 / 53-43-00-202 2504073 / 53-43-00-203 2503781 / 53-ZL-00-230 2503837 / 71-ZL-00-201 2503838 / 71-ZL-00-202 2498463 / 24-00-00-301			
			N/A	N	B1014141 - Christopher Draw dy Feb 11, 2026 7:58 AM
311BZ	ACCESS PANEL	2503676 / 24-20-00-206 2503661 / 53-ZL-00-228	OPENED	N	B0142041 - Timothy Winfree Feb 20, 2026 10:41 AM
312AR	R/H AFT EXTERNAL GRD PWR DOOR	2503780 / 53-ZL-00-227			
			N/A	N	B1014141 - Christopher Draw dy Feb 11, 2026 7:58 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
313AZ	L/H AFT FUSE CNTL PULLEY ACCESS COVER	2503699 / 27-00-00-206	OPENED	N	B1021822 - Joseph Cuoco Feb 10, 2026 6:38 AM
			READYTOCLOSE	N	B1002512 - Brandon Warne Feb 20, 2026 6:35 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 20, 2026 7:12 AM
			CLOSED	N	B1002512 - Brandon Warne Feb 20, 2026 7:28 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 20, 2026 7:58 AM
313BZ	L/H AFT FUSE CNTL PULLEY ACCESS COVER	2503699 / 27-00-00-206	OPENED	N	B1021822 - Joseph Cuoco Feb 10, 2026 6:38 AM
			READYTOCLOSE	N	B1002512 - Brandon Warne Feb 20, 2026 6:35 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 20, 2026 7:12 AM
			CLOSED	N	B1002512 - Brandon Warne Feb 20, 2026 7:28 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 20, 2026 7:58 AM
313CZ	L/H AFT FUSE CNTL PULLEY ACCESS COVER	2503699 / 27-00-00-206	OPENED	N	B1021822 - Joseph Cuoco Feb 10, 2026 6:38 AM
			READYTOCLOSE	N	B1002512 - Brandon Warne Feb 20, 2026 6:35 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 20, 2026 7:12 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
313CZ	L/H AFT FUSE CNTL PULLEY ACCESS COVER	2503699 / 27-00-00-206	OPENED	N	B1021822 - Joseph Cuoco Feb 10, 2026 6:38 AM
			CLOSED	N	B1002512 - Brandon Warne Feb 20, 2026 7:28 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 20, 2026 7:58 AM
314AZ	R/H AFT FUSE CNTL PULLEY ACCESS COVER	2503699 / 27-00-00-206	OPENED	N	B1021822 - Joseph Cuoco Feb 10, 2026 6:38 AM
			READYTOCLOSE	N	B1002512 - Brandon Warne Feb 20, 2026 6:35 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 20, 2026 7:12 AM
			CLOSED	N	B1002512 - Brandon Warne Feb 20, 2026 7:28 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 20, 2026 7:58 AM
314BZ	R/H AFT FUSE CNTL PULLEY ACCESS COVER	2503699 / 27-00-00-206	OPENED	N	B1021822 - Joseph Cuoco Feb 10, 2026 6:38 AM
			READYTOCLOSE	N	B1002512 - Brandon Warne Feb 20, 2026 6:35 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 20, 2026 7:12 AM
			CLOSED	N	B1002512 - Brandon Warne Feb 20, 2026 7:28 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 20, 2026 7:58 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
314CZ	R/H AFT FUSE CNTL PULLEY ACCESS COVER	2503699 / 27-00-00-206	OPENED	N	B1021822 - Joseph Cuoco Feb 10, 2026 6:38 AM
			READYTOCLOSE	N	B1002512 - Brandon Warne Feb 20, 2026 6:35 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 20, 2026 7:12 AM
			CLOSED	N	B1002512 - Brandon Warne Feb 20, 2026 7:28 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 20, 2026 7:58 AM
320AB	Auxiliary Power Unit (APU) Access Panel		OPENED	N	B0580384 - Patrick Arceneau x Feb 6, 2026 4:45 PM
320BL	Auxiliary Power Unit (APU) Left Access-Panel				
			N/A	N	B1014141 - Christopher Draw dy Feb 11, 2026 8:20 AM
323AT	VERT/HORIZ STAB RAM AIR-INLET DUCT FAIRING	2504129 / 55-ZL-00-202 2504120 / 55-30-00-201	OPENED	N	B0143806 - Alejandro Cabani llas Feb 9, 2026 2:17 PM
			READYTOCLOSE	N	B1016542 - Carlos Ochoa Feb 20, 2026 9:00 PM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 23, 2026 8:54 AM
			CLOSED	N	B1022255 - Carson Chang Feb 23, 2026 9:00 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
323AT	VERT/HORIZ STAB RAM AIR-INLET DUCT FAIRING	2504129 / 55-ZL-00-202 2504120 / 55-30-00-201	OPENED	N	B0143806 - Alejandro Cabani llas Feb 9, 2026 2:17 PM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 23, 2026 10:38 AM
324AT	V/STAB L/EDGE	2504123 / 55-30-00-206 2504130 / 55-ZL-00-203 2504120 / 55-30-00-201	OPENED	N	B0143806 - Alejandro Cabani llas Feb 9, 2026 2:17 PM
			READYTOCLOSE	N	B1018547 - Matthew Rossier Feb 20, 2026 6:03 PM
			OKTOCLOSE	N	B0623124 - Michael Stacy Feb 20, 2026 6:24 PM
			CLOSED	N	B1018547 - Matthew Rossier Feb 20, 2026 9:21 PM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 23, 2026 10:38 AM
325AL	L/H LOWER AFT V/STAB ACCESS PNL	2504123 / 55-30-00-206 2504132 / 55-ZL-00-204	OPENED	N	B0143806 - Alejandro Cabani llas Feb 4, 2026 2:05 PM
			READYTOCLOSE	N	K1018275 - Emmanuel Cocoa Feb 18, 2026 11:56 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 18, 2026 12:48 PM
			CLOSED	N	K1018275 - Emmanuel Cocoa Feb 18, 2026 12:57 PM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 18, 2026 1:56 PM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
325AR	R/H LOWER AFT V/STAB ACCESS PNL	2503999 / 27-00-00-207 2504189 / 22-12-00-203 2504123 / 55-30-00-206 2504132 / 55-ZL-00-204	OPENED	N	B0143806 - Alejandro Cabani llas Feb 5, 2026 2:14 PM
			READYTOCLOSE	N	B0143806 - Alejandro Cabani llas Feb 20, 2026 9:02 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 20, 2026 9:42 AM
			CLOSED	N	B0143806 - Alejandro Cabani llas Feb 20, 2026 10:16 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 20, 2026 11:49 AM
325BL	L/H LOWER FWD V/STAB ACCESS PNL	2503999 / 27-00-00-207 2504189 / 22-12-00-203 2503705 / 22-11-00-202 2504123 / 55-30-00-206 2504132 / 55-ZL-00-204 2504120 / 55-30-00-201	OPENED	N	B0143806 - Alejandro Cabani llas Feb 4, 2026 2:05 PM
			READYTOCLOSE	N	K1018275 - Emmanuel Cocoa Feb 18, 2026 11:56 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 18, 2026 12:48 PM
			CLOSED	N	K1018275 - Emmanuel Cocoa Feb 18, 2026 12:57 PM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 18, 2026 1:56 PM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
325BR	R/H LOWER FWD V/STAB ACCESS PNL	2503999 / 27-00-00-207 2504189 / 22-12-00-203 2504123 / 55-30-00-206 2504132 / 55-ZL-00-204	OPENED	N	B0143806 - Alejandro Cabani llas Feb 5, 2026 2:14 PM
			READYTOCLOSE	N	B0143806 - Alejandro Cabani llas Feb 20, 2026 9:02 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 20, 2026 9:42 AM
			CLOSED	N	B0143806 - Alejandro Cabani llas Feb 20, 2026 10:16 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 20, 2026 11:49 AM
325CL	L/H MID FWD V/STAB ACCESS PNL	2503999 / 27-00-00-207 2504123 / 55-30-00-206 2504132 / 55-ZL-00-204	OPENED	N	B0143806 - Alejandro Cabani llas Feb 4, 2026 2:05 PM
			READYTOCLOSE	N	K1018275 - Emmanuel Cocoa Feb 18, 2026 11:56 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 18, 2026 12:48 PM
			CLOSED	N	K1018275 - Emmanuel Cocoa Feb 18, 2026 12:57 PM
			CLOSED	Y	B0623124 - Michael Stacy Feb 20, 2026 6:20 PM
			OKTOCLOSE	Y	B0623124 - Michael Stacy Feb 20, 2026 6:20 PM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
325CL	L/H MID FWD V/STAB ACCESS PNL	2503999 / 27-00-00-207 2504123 / 55-30-00-206 2504132 / 55-ZL-00-204	OPENED	N	B0143806 - Alejandro Cabani llas Feb 4, 2026 2:05 PM
			READYTOCLOSE	Y	B0623124 - Michael Stacy Feb 20, 2026 6:20 PM
			READYTOCLOSE	N	B1018547 - Matthew Rossier Feb 20, 2026 6:23 PM
			OKTOCLOSE	N	B0623124 - Michael Stacy Feb 20, 2026 6:24 PM
			CLOSED	N	B1018547 - Matthew Rossier Feb 20, 2026 8:59 PM
			INSPECTED	N	B0623124 - Michael Stacy Feb 20, 2026 9:13 PM
325CR	R/H MID FWD V/STAB ACCESS PNL	2504189 / 22-12-00-203 2503705 / 22-11-00-202 2504123 / 55-30-00-206 2504132 / 55-ZL-00-204	OPENED	N	B0143806 - Alejandro Cabani llas Feb 5, 2026 2:14 PM
			READYTOCLOSE	N	B0143806 - Alejandro Cabani llas Feb 20, 2026 9:02 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 20, 2026 9:42 AM
			CLOSED	N	B0143806 - Alejandro Cabani llas Feb 20, 2026 10:16 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 20, 2026 11:49 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
325DL	L/H UPPER AFT V/STAB ACCESS PNL	2503999 / 27-00-00-207 2504123 / 55-30-00-206 2504132 / 55-ZL-00-204	OPENED	N	B0143806 - Alejandro Cabani llas Feb 4, 2026 2:05 PM
			READYTOCLOSE	N	B1020176 - Matthew Doyle Mar 5, 2026 10:32 AM
			OKTOCLOSE	N	B0141354 - Karl Tuxhorn Mar 5, 2026 12:23 PM
			CLOSED	N	B0638589 - Sean Dodder Mar 5, 2026 9:43 PM
			INSPECTED	N	B0161691 - Thomas Mitchell Mar 5, 2026 10:03 PM
325DR	R/H UPPER AFT V/STAB ACCESS PNL	2504123 / 55-30-00-206 2504132 / 55-ZL-00-204	OPENED	N	B0143806 - Alejandro Cabani llas Feb 5, 2026 2:14 PM
			READYTOCLOSE	N	B0143806 - Alejandro Cabani llas Feb 20, 2026 9:02 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 20, 2026 9:42 AM
			CLOSED	N	B0143806 - Alejandro Cabani llas Feb 20, 2026 10:16 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 20, 2026 11:49 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
325EL	L/H UPPER AFT V/STAB ACCESS PNL	2504123 / 55-30-00-206 2504132 / 55-ZL-00-204	OPENED	N	B0143806 - Alejandro Cabani llas Feb 4, 2026 2:05 PM
			READYTOCLOSE	N	K1018275 - Emmanuel Cocoa Feb 18, 2026 11:56 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 18, 2026 12:48 PM
			CLOSED	N	K1018275 - Emmanuel Cocoa Feb 18, 2026 12:57 PM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 18, 2026 1:56 PM
325ER	R/H UPPER AFT V/STAB ACCESS PNL	2504123 / 55-30-00-206 2504132 / 55-ZL-00-204	OPENED	N	B0143806 - Alejandro Cabani llas Feb 5, 2026 2:14 PM
			READYTOCLOSE	N	B1020176 - Matthew Doyle Mar 5, 2026 10:32 AM
			OKTOCLOSE	N	B0141354 - Karl Tuxhorn Mar 5, 2026 12:23 PM
			CLOSED	N	B1020176 - Matthew Doyle Mar 5, 2026 1:04 PM
			INSPECTED	N	B0141354 - Karl Tuxhorn Mar 5, 2026 2:08 PM
325FR	R/H UPPER AFT V/STAB ACCESS PNL	2503715 / 27-40-00-204 2504123 / 55-30-00-206 2504132 / 55-ZL-00-204	OPENED	N	B0143806 - Alejandro Cabani llas Feb 5, 2026 2:14 PM
			READYTOCLOSE	N	B0143806 - Alejandro Cabani llas Feb 20, 2026 9:02 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
325FR	R/H UPPER AFT V/STAB ACCESS PNL	2503715 / 27-40-00-204 2504123 / 55-30-00-206 2504132 / 55-ZL-00-204	OPENED	N	B0143806 - Alejandro Cabani llas Feb 5, 2026 2:14 PM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 20, 2026 9:42 AM
			CLOSED	N	B0143806 - Alejandro Cabani llas Feb 20, 2026 10:16 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 20, 2026 11:49 AM
325GR	R/H MID FWD V/STAB ACCESS PNL	2504132 / 55-ZL-00-204	OPENED	N	B0143806 - Alejandro Cabani llas Feb 5, 2026 2:14 PM
			READYTOCLOSE	N	B0143806 - Alejandro Cabani llas Feb 20, 2026 9:02 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 20, 2026 9:42 AM
			CLOSED	N	B0143806 - Alejandro Cabani llas Feb 20, 2026 10:16 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 20, 2026 11:49 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
325HR	R/H LOWER AFT V/STAB ACCESS PNL	2504132 / 55-ZL-00-204	OPENED	N	B0143806 - Alejandro Cabani llas Feb 5, 2026 2:14 PM
			READYTOCLOSE	N	B0143806 - Alejandro Cabani llas Feb 20, 2026 9:02 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 20, 2026 9:42 AM
			CLOSED	N	B0143806 - Alejandro Cabani llas Feb 20, 2026 10:16 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 20, 2026 11:49 AM
326AL	L/H V/STAB UPPER VISOR ACCESS PNL	2503715 / 27-40-00-204 2504113 / 55-10-00-201 2504135 / 55-ZL-00-205 2504117 / 55-10-00-203 2503800 / 55-10-00-207	OPENED	N	B0143806 - Alejandro Cabani llas Feb 4, 2026 2:05 PM
326AR	R/H V/STAB UPPER VISOR ACCESS PNL	2503715 / 27-40-00-204 2504113 / 55-10-00-201 2504135 / 55-ZL-00-205 2504117 / 55-10-00-203 2503800 / 55-10-00-207	OPENED	N	B0143806 - Alejandro Cabani llas Feb 5, 2026 2:14 PM
326AT	VERT/HORIZ STAB UPPER FWD FAIRING	2504113 / 55-10-00-201 2504115 / 55-10-00-202 2504135 / 55-ZL-00-205 2503800 / 55-10-00-207	OPENED	N	B0143806 - Alejandro Cabani llas Feb 5, 2026 2:14 PM
			READYTOCLOSE	N	B0650736 - Jesus Gonzalez A tondo Feb 23, 2026 8:17 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
326AT	VERT/HORIZ STAB UPPER FWD FAIRING	2504113 / 55-10-00-201 2504115 / 55-10-00-202 2504135 / 55-ZL-00-205 2503800 / 55-10-00-207	OPENED	N	B0143806 - Alejandro Cabani llas Feb 5, 2026 2:14 PM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 23, 2026 10:39 AM
			CLOSED	N	B0650736 - Jesus Gonzalez A tondo Feb 23, 2026 10:40 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 23, 2026 10:40 AM
326BL	L/H V/STAB LOWER VISOR ACCESS PNL	2504113 / 55-10-00-201 2504115 / 55-10-00-202 2504135 / 55-ZL-00-205 2504117 / 55-10-00-203 2503800 / 55-10-00-207	OPENED	N	B0143806 - Alejandro Cabani llas Feb 4, 2026 2:05 PM
326BR	R/H V/STAB LOWER VISOR ACCESS PNL	2504113 / 55-10-00-201 2504115 / 55-10-00-202 2504135 / 55-ZL-00-205 2504117 / 55-10-00-203 2503800 / 55-10-00-207	OPENED	N	B0143806 - Alejandro Cabani llas Feb 5, 2026 2:14 PM
326BT	VERT/HORIZ STAB UPPER CENTER FAIRING	2503715 / 27-40-00-204 2503714 / 27-40-00-202 2504113 / 55-10-00-201 2504135 / 55-ZL-00-205 2503800 / 55-10-00-207	OPENED	N	B0143806 - Alejandro Cabani llas Feb 9, 2026 2:17 PM
			READYTOCLOSE	N	B1018547 - Matthew Rossier Feb 26, 2026 6:41 PM
			OKTOCLOSE	N	B0161691 - Thomas Mitchell Feb 26, 2026 6:56 PM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
326BT	VERT/HORIZ STAB UPPER CENTER FAIRING	2503715 / 27-40-00-204 2503714 / 27-40-00-202 2504113 / 55-10-00-201 2504135 / 55-ZL-00-205 2503800 / 55-10-00-207	OPENED	N	B0143806 - Alejandro Cabani llas Feb 9, 2026 2:17 PM
			CLOSED	N	B1018547 - Matthew Rossier Feb 26, 2026 10:04 PM
326CL	L/H VERT/HORIZ STAB LOWER FAIRING	2503714 / 27-40-00-202 2504113 / 55-10-00-201 2504115 / 55-10-00-202 2504135 / 55-ZL-00-205 2503800 / 55-10-00-207	OPENED	N	B0143806 - Alejandro Cabani llas Feb 5, 2026 2:14 PM
			READYTOCLOSE	N	B0650736 - Jesus Gonzalez A tondo Feb 23, 2026 8:17 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 23, 2026 10:08 AM
			CLOSED	N	B1022275 - Kaitlynn Maxon Feb 23, 2026 10:16 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 26, 2026 10:12 AM
326CR	R/H VERT/HORIZ STAB LOWER FAIRING	2503714 / 27-40-00-202 2504113 / 55-10-00-201 2504115 / 55-10-00-202 2504135 / 55-ZL-00-205 2503800 / 55-10-00-207	OPENED	N	B0143806 - Alejandro Cabani llas Feb 5, 2026 2:14 PM
			READYTOCLOSE	N	B0650736 - Jesus Gonzalez A tondo Feb 23, 2026 8:17 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
326CR	R/H VERT/HORIZ STAB LOWER FAIRING	2503714 / 27-40-00-202 2504113 / 55-10-00-201 2504115 / 55-10-00-202 2504135 / 55-ZL-00-205 2503800 / 55-10-00-207	OPENED	N	B0143806 - Alejandro Cabani llas Feb 5, 2026 2:14 PM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 23, 2026 10:08 AM
			CLOSED	N	B1022275 - Kaitlynn Maxon Feb 23, 2026 10:16 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 26, 2026 10:12 AM
326CT	VERT/HORIZ STAB UPPER AFT FAIRING	2504135 / 55-ZL-00-205 2503800 / 55-10-00-207			
			N/A	N	B0142041 - Timothy Winfree Feb 20, 2026 10:41 AM
326DL	L/H INBD VERT/HORIZ STAB L/EDGE	2504115 / 55-10-00-202 2504144 / 55-ZL-00-210 2504117 / 55-10-00-203 2504141 / 55-ZL-00-208	OPENED	N	B0143806 - Alejandro Cabani llas Feb 6, 2026 2:36 PM
			READYTOCLOSE	N	B1002512 - Brandon Warne Feb 18, 2026 8:29 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 18, 2026 8:56 AM
			CLOSED	N	B1002512 - Brandon Warne Feb 18, 2026 9:36 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 26, 2026 10:12 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
326DR	R/H INBD VERT/HORIZ STAB L/EDGE	2504115 / 55-10-00-202 2504117 / 55-10-00-203 2504147 / 55-ZL-00-211 2504142 / 55-ZL-00-209	OPENED	N	B0143806 - Alejandro Cabani llas Feb 6, 2026 2:36 PM
			READYTOCLOSE	N	K1018275 - Emmanuel Cocoa Feb 18, 2026 7:09 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 18, 2026 8:45 AM
			CLOSED	N	K1018275 - Emmanuel Cocoa Feb 20, 2026 8:27 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 26, 2026 10:12 AM
326EL	L/H UPPER FWD V/STAB ACCESS PNL	2504120 / 55-30-00-201	OPENED	N	B0143806 - Alejandro Cabani llas Feb 4, 2026 2:05 PM
			READYTOCLOSE	N	B0650736 - Jesus Gonzalez A tondo Feb 23, 2026 8:17 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 23, 2026 10:08 AM
			CLOSED	N	B1022275 - Kaitlynn Maxon Feb 23, 2026 10:16 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 26, 2026 10:12 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
326ER	R/H UPPER FWD V/STAB ACCESS PNL	2504120 / 55-30-00-201	OPENED	N	B0143806 - Alejandro Cabani llas Feb 5, 2026 2:14 PM
			READYTOCLOSE	N	B0650736 - Jesus Gonzalez A tondo Feb 23, 2026 8:17 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 23, 2026 10:08 AM
			CLOSED	N	B1022275 - Kaitlynn Maxon Feb 23, 2026 10:16 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 26, 2026 10:12 AM
327AL	L/H LOWER V/STAB RUDDER HNG ACCESS PNL	2504334 / INSTALL RUDDER 2504342 / REMOVE RUDDER 2504126 / 55-40-00-202 2504132 / 55-ZL-00-204	OPENED	N	B0143806 - Alejandro Cabani llas Feb 4, 2026 2:05 PM
			READYTOCLOSE	N	B1018547 - Matthew Rossier Feb 27, 2026 5:47 PM
			OKTOCLOSE	N	B0161691 - Thomas Mitchell Feb 27, 2026 6:08 PM
			CLOSED	N	B1018547 - Matthew Rossier Feb 27, 2026 6:56 PM
			INSPECTED	N	B0161691 - Thomas Mitchell Feb 27, 2026 7:45 PM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
327BL	L/H MID V/STAB RUDDER HNG ACCESS PNL	2504334 / INSTALL RUDDER 2504342 / REMOVE RUDDER 2504126 / 55-40-00-202 2504132 / 55-ZL-00-204	OPENED	N	B0143806 - Alejandro Cabani llas Feb 4, 2026 2:05 PM
			READYTOCLOSE	N	B1018547 - Matthew Rossier Feb 27, 2026 5:47 PM
			OKTOCLOSE	N	B0161691 - Thomas Mitchell Feb 27, 2026 6:08 PM
			CLOSED	N	B1018547 - Matthew Rossier Feb 27, 2026 6:56 PM
			INSPECTED	N	B0161691 - Thomas Mitchell Feb 27, 2026 7:45 PM
327BR	R/H MID V/STAB RUDDER HNG ACCESS PNL	2504334 / INSTALL RUDDER 2504342 / REMOVE RUDDER 2504126 / 55-40-00-202 2504132 / 55-ZL-00-204	OPENED	N	B0143806 - Alejandro Cabani llas Feb 5, 2026 2:14 PM
			READYTOCLOSE	N	B1020176 - Matthew Doyle Mar 2, 2026 10:24 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Mar 2, 2026 10:37 AM
			CLOSED	N	B1020176 - Matthew Doyle Mar 2, 2026 10:40 AM
			INSPECTED	N	B1013522 - Brandon Jennings Mar 2, 2026 1:01 PM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
327CL	L/H UPPER V/STAB RUDDER HNG ACCESS PNL	2504334 / INSTALL RUDDER 2504342 / REMOVE RUDDER 2504126 / 55-40-00-202 2504132 / 55-ZL-00-204	OPENED	N	B0143806 - Alejandro Cabani llas Feb 4, 2026 2:05 PM
			READYTOCLOSE	N	B1018547 - Matthew Rossier Feb 27, 2026 5:47 PM
			OKTOCLOSE	N	B0161691 - Thomas Mitchell Feb 27, 2026 6:08 PM
			CLOSED	N	B1018547 - Matthew Rossier Feb 27, 2026 6:56 PM
			INSPECTED	N	B0161691 - Thomas Mitchell Feb 27, 2026 7:45 PM
331AL	L/H VERT/HORIZ STAB L/EDGE	2504115 / 55-10-00-202 2504144 / 55-ZL-00-210 2504117 / 55-10-00-203 2504141 / 55-ZL-00-208	OPENED	N	B0143806 - Alejandro Cabani llas Feb 6, 2026 2:36 PM
			READYTOCLOSE	N	K1018275 - Emmanuel Cocoa Feb 18, 2026 6:37 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 18, 2026 8:56 AM
			CLOSED	N	B1002512 - Brandon Warne Feb 18, 2026 9:36 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 26, 2026 10:12 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
332AB	L/H LOWER H/STAB ACCESS PNL	2504144 / 55-ZL-00-210 2504117 / 55-10-00-203	OPENED	N	B0143806 - Alejandro Cabani llas Feb 4, 2026 2:05 PM
			READYTOCLOSE	N	B1020176 - Matthew Doyle Mar 5, 2026 6:56 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Mar 5, 2026 7:48 AM
			CLOSED	N	B1020176 - Matthew Doyle Mar 5, 2026 10:14 AM
332BB	L/H LOWER H/STAB ACCESS PNL	2504144 / 55-ZL-00-210 2504117 / 55-10-00-203	OPENED	N	B0143806 - Alejandro Cabani llas Feb 4, 2026 2:05 PM
			READYTOCLOSE	N	B1020176 - Matthew Doyle Mar 5, 2026 6:56 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Mar 5, 2026 7:48 AM
			CLOSED	N	B1020176 - Matthew Doyle Mar 5, 2026 10:14 AM
333AL	L/H H/STAB TIP FAIRING	2504144 / 55-ZL-00-210	OPENED	N	B0143806 - Alejandro Cabani llas Feb 6, 2026 2:36 PM
			READYTOCLOSE	N	B0143806 - Alejandro Cabani llas Feb 20, 2026 6:35 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 20, 2026 7:14 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
333AL	L/H H/STAB TIP FAIRING	2504144 / 55-ZL-00-210	OPENED	N	B0143806 - Alejandro Cabani llas Feb 6, 2026 2:36 PM
			CLOSED	N	B0143806 - Alejandro Cabani llas Feb 20, 2026 7:15 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 20, 2026 7:50 AM
334AB	L/H LOWER H/STAB INBD HNG ACCESS PNL	2504337 / REMOVE ELEVATORS 2504328 / INSTALL ELEVATORS 2504144 / 55-ZL-00-210 2504117 / 55-10-00-203	OPENED	N	B0143806 - Alejandro Cabani llas Feb 5, 2026 2:14 PM
			READYTOCLOSE	N	B1020176 - Matthew Doyle Mar 5, 2026 6:56 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Mar 5, 2026 7:48 AM
			CLOSED	N	B1020176 - Matthew Doyle Mar 5, 2026 10:14 AM
334BB	L/H LOWER H/STAB MID HNG ACCESS PNL	2504337 / REMOVE ELEVATORS 2504328 / INSTALL ELEVATORS 2504144 / 55-ZL-00-210 2504117 / 55-10-00-203	OPENED	N	B0143806 - Alejandro Cabani llas Feb 6, 2026 2:36 PM
			READYTOCLOSE	N	B1020176 - Matthew Doyle Mar 5, 2026 6:56 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Mar 5, 2026 7:48 AM
			CLOSED	N	B1020176 - Matthew Doyle Mar 5, 2026 10:14 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
334CB	L/H LOWER H/STAB OUTBD HNG ACCESS PNL	2504337 / REMOVE ELEVATORS 2504328 / INSTALL ELEVATORS 2504144 / 55-ZL-00-210 2504117 / 55-10-00-203	OPENED	N	B0143806 - Alejandro Cabani llas Feb 6, 2026 2:36 PM
			READYTOCLOSE	N	B1020176 - Matthew Doyle Mar 5, 2026 6:56 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Mar 5, 2026 7:48 AM
			CLOSED	N	B1020176 - Matthew Doyle Mar 5, 2026 10:14 AM
341AR	R/H VERT/HORIZ STAB L/EDGE	2504115 / 55-10-00-202 2504117 / 55-10-00-203 2504147 / 55-ZL-00-211 2504142 / 55-ZL-00-209	OPENED	N	B0143806 - Alejandro Cabani llas Feb 18, 2026 6:48 AM
			READYTOCLOSE	N	K1018275 - Emmanuel Cocoa Feb 18, 2026 6:49 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 18, 2026 8:45 AM
			CLOSED	N	K1018275 - Emmanuel Cocoa Feb 20, 2026 8:26 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 26, 2026 10:12 AM
341EL	Vertical Stabilizer/Rudder Hinge Access Panel				
			N/A	N	B1014141 - Christopher Draw dy Feb 11, 2026 8:10 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
341FR	Vertical Stabilizer/Rudder Hinge Access Panel				
			N/A	N	B1014141 - Christopher Draw dy Feb 11, 2026 8:10 AM
342AB	R/H LOWER H/STAB ACCESS PNL	2504117 / 55-10-00-203 2504147 / 55-ZL-00-211	OPENED	N	B0143806 - Alejandro Cabani llas Feb 5, 2026 2:14 PM
342BB	R/H LOWER H/STAB ACCESS PNL	2504117 / 55-10-00-203 2504147 / 55-ZL-00-211	OPENED	N	B0143806 - Alejandro Cabani llas Feb 5, 2026 2:14 PM
			READYTOCLOSE	N	B1020176 - Matthew Doyle Mar 5, 2026 10:32 AM
			OKTOCLOSE	N	B0141354 - Karl Tuxhorn Mar 5, 2026 12:39 PM
			CLOSED	N	B1020176 - Matthew Doyle Mar 5, 2026 1:22 PM
			INSPECTED	N	B0141354 - Karl Tuxhorn Mar 5, 2026 2:15 PM
343AR	R/H H/STAB TIP FAIRING	2504147 / 55-ZL-00-211	OPENED	N	B0143806 - Alejandro Cabani llas Feb 6, 2026 2:36 PM
			READYTOCLOSE	N	B0143806 - Alejandro Cabani llas Feb 20, 2026 7:15 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 20, 2026 7:47 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
343AR	R/H H/STAB TIP FAIRING	2504147 / 55-ZL-00-211	OPENED	N	B0143806 - Alejandro Cabani llas Feb 6, 2026 2:36 PM
			CLOSED	N	B0143806 - Alejandro Cabani llas Feb 20, 2026 7:53 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 20, 2026 9:38 AM
344AB	R/H LOWER H/STAB INBD HNG ACCESS PNL	2504337 / REMOVE ELEVATORS 2504328 / INSTALL ELEVATORS 2504117 / 55-10-00-203 2504147 / 55-ZL-00-211	OPENED	N	B0143806 - Alejandro Cabani llas Feb 5, 2026 2:14 PM
344BB	R/H LOWER H/STAB MID HNG ACCESS PNL	2504337 / REMOVE ELEVATORS 2504328 / INSTALL ELEVATORS 2504117 / 55-10-00-203 2504147 / 55-ZL-00-211	OPENED	N	B0143806 - Alejandro Cabani llas Feb 5, 2026 2:14 PM
344CB	R/H LOWER H/STAB OUTBD HNG ACCESS PNL	2504337 / REMOVE ELEVATORS 2504328 / INSTALL ELEVATORS 2504117 / 55-10-00-203 2504147 / 55-ZL-00-211	OPENED	N	B0143806 - Alejandro Cabani llas Feb 6, 2026 2:36 PM
346ALZ	Lower Visor Fairing				
			N/A	N	B1014141 - Christopher Draw dy Feb 11, 2026 8:06 AM
346ARZ	Lower Visor Fairing				
			N/A	N	B1014141 - Christopher Draw dy Feb 11, 2026 8:06 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
346BLZ	Upper Visor Fairing				
			N/A	N	B1014141 - Christopher Draw dy Feb 11, 2026 8:06 AM
346BRZ	Upper Visor Fairing				
			N/A	N	B1014141 - Christopher Draw dy Feb 11, 2026 8:06 AM
351AL	Horizontal				
			N/A	N	B1014141 - Christopher Draw dy Feb 11, 2026 8:12 AM
351BB	Horizontal/Elevator PCU Access Panel				
			N/A	N	B1014141 - Christopher Draw dy Feb 11, 2026 8:21 AM
361AR	Inboard Leading Edge Access Panel				
			N/A	N	B1014141 - Christopher Draw dy Feb 11, 2026 8:23 AM
361BB	LOWER TAIL TANK DOOR	2503787 / 53-ZL-00-232	OPENED	N	B0642326 - Austin McQuilkin Feb 4, 2026 2:16 PM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
361BZ	ACCESS PANEL	2503787 / 53-ZL-00-232 2504076 / 53-50-00-201	OPENED	N	B0642051 - Terry Walters Feb 17, 2026 7:25 AM
			READYTOCLOSE	N	B1018339 - Dwain Wolf Feb 19, 2026 10:46 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 19, 2026 12:16 PM
			CLOSED	N	B1018339 - Dwain Wolf Feb 19, 2026 1:14 PM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 19, 2026 1:52 PM
361CB	LOWER TAIL TANK DOOR	2503787 / 53-ZL-00-232	OPENED	N	B0642326 - Austin McQuilkin Feb 4, 2026 2:16 PM
			READYTOCLOSE	N	B1018339 - Dwain Wolf Feb 19, 2026 1:25 PM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 19, 2026 1:53 PM
			CLOSED	N	B1018339 - Dwain Wolf Feb 19, 2026 1:55 PM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 19, 2026 2:16 PM
			INSPECTED	Y	B0623124 - Michael Stacy Feb 19, 2026 6:03 PM
			CLOSED	Y	B0623124 - Michael Stacy Feb 19, 2026 6:04 PM
			OKTOCLOSE	Y	B0623124 - Michael Stacy Feb 19, 2026 6:04 PM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
361CB	LOWER TAIL TANK DOOR	2503787 / 53-ZL-00-232	OPENED	N	B0642326 - Austin McQuilkin Feb 4, 2026 2:16 PM
			READYTOCLOSE	Y	B0623124 - Michael Stacy Feb 19, 2026 6:04 PM
			READYTOCLOSE	N	B1018547 - Matthew Rossier Feb 20, 2026 5:48 PM
			OKTOCLOSE	N	B0623124 - Michael Stacy Feb 20, 2026 6:24 PM
			CLOSED	N	B1018547 - Matthew Rossier Feb 20, 2026 9:00 PM
			INSPECTED	N	B0623124 - Michael Stacy Feb 20, 2026 9:13 PM
363AB	TAIL TANK INTERIOR FAIRING	2503787 / 53-ZL-00-232 2504078 / 53-50-00-202	OPENED	N	B0143806 - Alejandro Cabani llas Feb 10, 2026 7:20 AM
			READYTOCLOSE	N	B0648431 - Caleb Sexton Feb 20, 2026 6:36 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 20, 2026 7:14 AM
			CLOSED	N	B1022255 - Carson Chang Feb 20, 2026 7:16 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 20, 2026 7:50 AM
363BB	AFT TAIL CONE FAIRING	2503787 / 53-ZL-00-232 2504080 / 53-50-00-204			
			N/A	N	B0142041 - Timothy Winfree Feb 20, 2026 10:31 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
411AL	L/H ENG UPPER PYLON L/EDGE	2503793 / 54-ZL-00-203	OPENED	N	B0642326 - Austin McQuilkin Feb 4, 2026 3:17 PM
			READYTOCLOSE	N	K1018275 - Emmanuel Cocoa Feb 23, 2026 7:22 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 23, 2026 9:07 AM
			CLOSED	N	K1018275 - Emmanuel Cocoa Feb 23, 2026 9:14 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 23, 2026 10:43 AM
412AB	L/H ENG LOWER FWD MOUNT ACCESS PNL	2504238 / 54-50-00-203 2503797 / 54-ZL-00-205 2504066 / 53-30-00-219 2504301 / 71-13-00-202	OPENED	N	B0648431 - Caleb Sexton Feb 4, 2026 12:56 PM
			READYTOCLOSE	N	B0646266 - Sergio Rodriguez Figueroa Feb 19, 2026 12:35 PM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 19, 2026 12:50 PM
			OKTOCLOSE	Y	B1013522 - Brandon Jennings Feb 19, 2026 12:54 PM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 19, 2026 1:17 PM
			OKTOCLOSE	Y	B1013522 - Brandon Jennings Feb 19, 2026 2:12 PM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 20, 2026 7:22 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
412AB	L/H ENG LOWER FWD MOUNT ACCESS PNL	2504238 / 54-50-00-203 2503797 / 54-ZL-00-205 2504066 / 53-30-00-219 2504301 / 71-13-00-202	OPENED	N	B0648431 - Caleb Sexton Feb 4, 2026 12:56 PM
			CLOSED	N	B1018546 - Andres Velazquez Feb 20, 2026 7:52 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 20, 2026 9:40 AM
412AT	L/H ENG UPPER FWD MOUNT ACCESS PNL	2504238 / 54-50-00-203 2504236 / 54-50-00-201 2504306 / 71-20-00-202 2504309 / 71-20-00-203 2504301 / 71-13-00-202	OPENED	N	B0613291 - Eric Strong Feb 6, 2026 6:04 PM
			READYTOCLOSE	N	B1018546 - Andres Velazquez Feb 20, 2026 7:56 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 20, 2026 9:36 AM
			CLOSED	N	B1018546 - Andres Velazquez Feb 20, 2026 10:12 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 20, 2026 10:58 AM
412BB	L/H ENG LOWER LINE DISCONNECT ACCESS PNL	2503707 / 26-21-16-201 2504206 / 28-10-00-208 2504210 / 28-10-00-209 2504238 / 54-50-00-203 2504066 / 53-30-00-219	OPENED	N	B0646266 - Sergio Rodriguez Figueroa Feb 19, 2026 12:34 PM
			READYTOCLOSE	N	B0646266 - Sergio Rodriguez Figueroa Feb 19, 2026 12:35 PM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
412BB	L/H ENG LOWER LINE DISCONNECT ACCESS PNL	2503707 / 26-21-16-201 2504206 / 28-10-00-208 2504210 / 28-10-00-209 2504238 / 54-50-00-203 2504066 / 53-30-00-219	OPENED	N	B0646266 - Sergio Rodriguez Figueroa Feb 19, 2026 12:34 PM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 19, 2026 12:50 PM
			CLOSED	N	B0646266 - Sergio Rodriguez Figueroa Feb 19, 2026 1:46 PM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 19, 2026 2:15 PM
412BT	L/H ENG UPPER AFT LINE DISCONNECT ACCESS PNL	2504206 / 28-10-00-208 2504238 / 54-50-00-203	OPENED	N	B0613291 - Eric Strong Feb 6, 2026 6:04 PM
			READYTOCLOSE	N	B1018546 - Andres Velazquez Feb 20, 2026 7:56 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 20, 2026 9:36 AM
			CLOSED	N	B1018546 - Andres Velazquez Feb 20, 2026 10:12 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 20, 2026 10:58 AM
412CB	L/H ENG LOWER NACELLE/PYLON ACCESS PNL	2503797 / 54-ZL-00-205 2504066 / 53-30-00-219	OPENED	N	B0648431 - Caleb Sexton Feb 4, 2026 12:24 PM
			READYTOCLOSE	N	B0646266 - Sergio Rodriguez Figueroa Feb 19, 2026 12:35 PM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
412CB	L/H ENG LOWER NACELLE/PYLON ACCESS PNL	2503797 / 54-ZL-00-205 2504066 / 53-30-00-219	OPENED	N	B0648431 - Caleb Sexton Feb 4, 2026 12:24 PM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 19, 2026 12:50 PM
			CLOSED	N	B0646266 - Sergio Rodriguez Figueroa Feb 19, 2026 1:46 PM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 19, 2026 2:15 PM
412CT	L/H ENG UPPER AFT MOUNT ACCESS PNL	2504238 / 54-50-00-203 2504240 / 54-50-00-204 2504309 / 71-20-00-203	OPENED	N	B0613291 - Eric Strong Feb 6, 2026 6:04 PM
			READYTOCLOSE	N	B1018546 - Andres Velazquez Feb 20, 2026 8:35 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 20, 2026 9:36 AM
			CLOSED	N	B1018546 - Andres Velazquez Feb 20, 2026 10:12 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 20, 2026 10:58 AM
412DB	L/H ENG LOWER LINE DISCONNECT ACCESS PNL	2503707 / 26-21-16-201 2504206 / 28-10-00-208 2504210 / 28-10-00-209 2503797 / 54-ZL-00-205	OPENED	N	B0613291 - Eric Strong Feb 6, 2026 9:20 AM
			READYTOCLOSE	N	B0646266 - Sergio Rodriguez Figueroa Feb 19, 2026 12:35 PM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
412DB	L/H ENG LOWER LINE DISCONNECT ACCESS PNL	2503707 / 26-21-16-201 2504206 / 28-10-00-208 2504210 / 28-10-00-209 2503797 / 54-ZL-00-205	OPENED	N	B0613291 - Eric Strong Feb 6, 2026 9:20 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 19, 2026 12:50 PM
			CLOSED	N	B0646266 - Sergio Rodriguez Figueroa Feb 19, 2026 1:46 PM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 19, 2026 2:15 PM
412EB	L/H ENG LOWER NACELLE/PYLON ACCESS PNL	2503797 / 54-ZL-00-205	OPENED	N	B0646266 - Sergio Rodriguez Figueroa Feb 19, 2026 12:34 PM
			READYTOCLOSE	N	B0646266 - Sergio Rodriguez Figueroa Feb 19, 2026 12:35 PM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 19, 2026 12:50 PM
			CLOSED	N	B0646266 - Sergio Rodriguez Figueroa Feb 19, 2026 1:46 PM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 19, 2026 2:15 PM
413AL	L/H ENG LOWER PYLON T/EDGE	2504109 / 54-ZL-00-207 2503849 / 78-ZL-00-203	OPENED	N	B0638589 - Sean Dodder Feb 4, 2026 6:30 PM
			READYTOCLOSE	N	B1020176 - Matthew Doyle Feb 23, 2026 8:25 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
413AL	L/H ENG LOWER PYLON T/EDGE	2504109 / 54-ZL-00-207 2503849 / 78-ZL-00-203	OPENED	N	B0638589 - Sean Dodder Feb 4, 2026 6:30 PM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 25, 2026 10:35 AM
			CLOSED	N	B0646266 - Sergio Rodriguez Figueroa Feb 25, 2026 10:37 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 26, 2026 10:12 AM
413BB	L/H ENG LOWER NACELLE/PYLON ACCESS PNL	2504109 / 54-ZL-00-207 2504066 / 53-30-00-219	OPENED	N	B0648431 - Caleb Sexton Feb 4, 2026 10:27 AM
			READYTOCLOSE	N	B0646266 - Sergio Rodriguez Figueroa Feb 19, 2026 12:35 PM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 19, 2026 12:50 PM
			CLOSED	N	B0646266 - Sergio Rodriguez Figueroa Feb 19, 2026 1:46 PM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 19, 2026 2:15 PM
413CB	L/H ENG LOWER AFT ACCESS PNL	2504109 / 54-ZL-00-207	OPENED	N	B0648431 - Caleb Sexton Feb 4, 2026 1:10 PM
			READYTOCLOSE	N	B0646266 - Sergio Rodriguez Figueroa Feb 19, 2026 12:35 PM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 19, 2026 12:50 PM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
413CB	L/H ENG LOWER AFT ACCESS PNL	2504109 / 54-ZL-00-207	OPENED	N	B0648431 - Caleb Sexton Feb 4, 2026 1:10 PM
			CLOSED	N	B0646266 - Sergio Rodriguez Figueroa Feb 19, 2026 1:46 PM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 19, 2026 2:15 PM
421AL	R/H ENG UPPER PYLON L/EDGE	2503794 / 54-ZL-00-204	OPENED	N	B0642326 - Austin McQuilkin Feb 4, 2026 3:17 PM
			READYTOCLOSE	N	B1018409 - Areida Cruz Feb 20, 2026 6:57 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 23, 2026 9:07 AM
			CLOSED	N	B1020176 - Matthew Doyle Feb 23, 2026 9:13 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 23, 2026 10:44 AM
422AB	R/H ENG LOWER FWD MOUNT ACCESS PNL	2504238 / 54-50-00-203 2503799 / 54-ZL-00-206 2504066 / 53-30-00-219 2504301 / 71-13-00-202	OPENED	N	B0646464 - Jonathan Nelson Feb 4, 2026 9:40 PM
			READYTOCLOSE	N	B0646266 - Sergio Rodriguez Figueroa Feb 19, 2026 6:58 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 19, 2026 7:24 AM
			OKTOCLOSE	Y	B1013522 - Brandon Jennings Feb 19, 2026 12:54 PM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
422AB	R/H ENG LOWER FWD MOUNT ACCESS PNL	2504238 / 54-50-00-203 2503799 / 54-ZL-00-206 2504066 / 53-30-00-219 2504301 / 71-13-00-202	OPENED	N	B0646464 - Jonathan Nelson Feb 4, 2026 9:40 PM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 20, 2026 7:21 AM
			CLOSED	N	B1018409 - Areida Cruz Feb 20, 2026 10:04 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 20, 2026 10:57 AM
422AT	R/H ENG UPPER FWD MOUNT ACCESS PNL	2504238 / 54-50-00-203 2504236 / 54-50-00-201 2504309 / 71-20-00-203 2504301 / 71-13-00-202	OPENED	N	B0613291 - Eric Strong Feb 6, 2026 4:29 PM
			READYTOCLOSE	N	B1018409 - Areida Cruz Feb 20, 2026 10:25 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 20, 2026 11:53 AM
			CLOSED	N	B1018409 - Areida Cruz Feb 20, 2026 1:47 PM
			INSPECTED	N	B0142244 - Todd Bridges Feb 20, 2026 4:36 PM
			INSPECTED	Y	B0141354 - Karl Tuxhorn Mar 5, 2026 12:58 PM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
422BB	R/H ENG LOWER LINE DISCONNECT ACCESS PNL	2504206 / 28-10-00-208 2504210 / 28-10-00-209 2504238 / 54-50-00-203 2504066 / 53-30-00-219	OPENED	N	B0646464 - Jonathan Nelson Feb 4, 2026 9:28 PM
			READYTOCLOSE	N	B0646266 - Sergio Rodriguez Figueroa Feb 19, 2026 6:58 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 19, 2026 7:24 AM
			CLOSED	N	B0646266 - Sergio Rodriguez Figueroa Feb 19, 2026 12:19 PM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 19, 2026 12:53 PM
422BT	R/H ENG UPPER AFT LINE DISCONNECT ACCESS PNL	2504206 / 28-10-00-208 2504238 / 54-50-00-203	OPENED	N	B0613291 - Eric Strong Feb 6, 2026 4:28 PM
			READYTOCLOSE	N	B1018409 - Areida Cruz Feb 20, 2026 10:25 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 20, 2026 11:53 AM
			OKTOCLOSE	Y	B0141354 - Karl Tuxhorn Mar 5, 2026 12:59 PM
			READYTOCLOSE	Y	B0141354 - Karl Tuxhorn Mar 5, 2026 1:00 PM
			READYTOCLOSE	N	B0638589 - Sean Dodder Mar 5, 2026 7:05 PM
			OKTOCLOSE	N	B0609145 - Miguel Pacheco Mar 5, 2026 7:11 PM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
422BT	R/H ENG UPPER AFT LINE DISCONNECT ACCESS PNL	2504206 / 28-10-00-208 2504238 / 54-50-00-203	OPENED	N	B0613291 - Eric Strong Feb 6, 2026 4:28 PM
			CLOSED	N	B0638589 - Sean Dodder Mar 5, 2026 9:24 PM
			INSPECTED	N	B0161691 - Thomas Mitchell Mar 5, 2026 9:33 PM
422CB	R/H ENG LOWER NACELLE/PYLON ACCESS PNL	2503799 / 54-ZL-00-206 2504066 / 53-30-00-219	OPENED	N	B0646464 - Jonathan Nelson Feb 4, 2026 9:28 PM
			READYTOCLOSE	N	B0646266 - Sergio Rodriguez Figueroa Feb 19, 2026 6:58 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 19, 2026 7:24 AM
			CLOSED	N	B0646266 - Sergio Rodriguez Figueroa Feb 19, 2026 12:19 PM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 19, 2026 12:53 PM
422CT	R/H ENG UPPER AFT MOUNT ACCESS PNL	2504238 / 54-50-00-203 2504240 / 54-50-00-204 2504306 / 71-20-00-202 2504309 / 71-20-00-203	OPENED	N	B0613291 - Eric Strong Feb 6, 2026 4:28 PM
			READYTOCLOSE	N	B1018409 - Areida Cruz Feb 20, 2026 10:25 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 20, 2026 11:53 AM
			CLOSED	N	B1018409 - Areida Cruz Feb 20, 2026 1:47 PM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
422CT	R/H ENG UPPER AFT MOUNT ACCESS PNL	2504238 / 54-50-00-203 2504240 / 54-50-00-204 2504306 / 71-20-00-202 2504309 / 71-20-00-203	OPENED	N	B0613291 - Eric Strong Feb 6, 2026 4:28 PM
			INSPECTED	N	B0142244 - Todd Bridges Feb 20, 2026 4:36 PM
422DB	R/H ENG LOWER LINE DISCONNECT ACCESS PNL	2504206 / 28-10-00-208 2504210 / 28-10-00-209 2503799 / 54-ZL-00-206	OPENED	N	B0613291 - Eric Strong Feb 6, 2026 9:21 AM
			READYTOCLOSE	N	B0646266 - Sergio Rodriguez Figueroa Feb 19, 2026 6:58 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 20, 2026 7:21 AM
			CLOSED	N	B1018409 - Areida Cruz Feb 20, 2026 10:04 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 20, 2026 10:57 AM
422EB	R/H ENG LOWER NACELLE/PYLON ACCESS PNL	2503799 / 54-ZL-00-206	OPENED	N	B0646464 - Jonathan Nelson Feb 4, 2026 9:28 PM
			READYTOCLOSE	N	B0646266 - Sergio Rodriguez Figueroa Feb 19, 2026 6:58 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 19, 2026 7:24 AM
			CLOSED	N	B0646266 - Sergio Rodriguez Figueroa Feb 19, 2026 12:19 PM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
422EB	R/H ENG LOWER NACELLE/PYLON ACCESS PNL	2503799 / 54-ZL-00-206	OPENED	N	B0646464 - Jonathan Nelson Feb 4, 2026 9:28 PM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 19, 2026 12:53 PM
423AL	R/H ENG LOWER PYLON T/EDGE	2504110 / 54-ZL-00-208 2503850 / 78-ZL-00-204	OPENED	N	B0580384 - Patrick Arceneau x Feb 4, 2026 9:21 PM
			READYTOCLOSE	N	B1020176 - Matthew Doyle Feb 23, 2026 8:25 AM
			OKTOCLOSE	N	B0622205 - Cody Borgwald Feb 26, 2026 5:35 PM
			CLOSED	N	B1016542 - Carlos Ochoa Feb 26, 2026 6:29 PM
			INSPECTED	N	B0161691 - Thomas Mitchell Feb 26, 2026 9:36 PM
423BB	R/H ENG LOWER NACELLE/PYLON ACCESS PNL	2504110 / 54-ZL-00-208 2504066 / 53-30-00-219	OPENED	N	B0646266 - Sergio Rodriguez Figueroa Feb 19, 2026 6:57 AM
			READYTOCLOSE	N	B0646266 - Sergio Rodriguez Figueroa Feb 19, 2026 6:58 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 19, 2026 7:24 AM
			CLOSED	N	B0646266 - Sergio Rodriguez Figueroa Feb 19, 2026 12:19 PM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 19, 2026 12:53 PM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
423CB	R/H ENG LOWER AFT ACCESS PNL	2504110 / 54-ZL-00-208	OPENED	N	B0646266 - Sergio Rodriguez Figueroa Feb 19, 2026 6:57 AM
			READYTOCLOSE	N	B0646266 - Sergio Rodriguez Figueroa Feb 19, 2026 6:58 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 19, 2026 7:24 AM
			CLOSED	N	B0646266 - Sergio Rodriguez Figueroa Feb 19, 2026 12:19 PM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 19, 2026 12:53 PM
432AB	L/H ENG LOWER NOSE COWL	2504319 / 78-30-00-209 2504310 / 78-30-00-206 2504301 / 71-13-00-202 2504315 / 78-30-00-207 2504318 / 78-30-00-208	OPENED	N	B0642051 - Terry Walters Feb 5, 2026 10:19 AM
432AT	L/H ENG UPPER NOSE COWL	2504319 / 78-30-00-209 2504310 / 78-30-00-206 2504301 / 71-13-00-202 2504315 / 78-30-00-207 2504318 / 78-30-00-208	OPENED	N	B1017711 - Isaac Ramirez Feb 5, 2026 1:21 PM
432DT	ECU Access Panel				
			N/A	N	B1014141 - Christopher Draw dy Feb 11, 2026 8:15 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
433AB	L/H ENG LOWER T/R TRACKS ACCESS PNL	2503844 / 78-ZL-00-201	OPENED	N	B0613291 - Eric Strong Feb 6, 2026 9:22 AM
			READYTOCLOSE	N	K1018275 - Emmanuel Cocoa Feb 23, 2026 7:33 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 23, 2026 9:07 AM
			CLOSED	N	K1018275 - Emmanuel Cocoa Feb 23, 2026 9:13 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 23, 2026 10:43 AM
433AT	L/H ENG UPPER T/R TRACKS ACCESS PNL	2503844 / 78-ZL-00-201	OPENED	N	B0613291 - Eric Strong Feb 6, 2026 6:05 PM
			READYTOCLOSE	N	K1018275 - Emmanuel Cocoa Feb 23, 2026 7:33 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 23, 2026 9:07 AM
			CLOSED	N	K1018275 - Emmanuel Cocoa Feb 23, 2026 9:13 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 23, 2026 10:43 AM
434AB	L/H ENG LOWER TRANSLATING COWL	2503842 / 71-ZL-00-205 2503984 / 80-11-00-202 2503932 / 72-40-00-205L 2503986 / 80-11-00-203	OPENED	N	B0613291 - Eric Strong Feb 4, 2026 11:57 AM
434AT	L/H ENG UPPER TRANSLATING COWL	2503842 / 71-ZL-00-205 2503932 / 72-40-00-205L 2503986 / 80-11-00-203	OPENED	N	B0642051 - Terry Walters Feb 5, 2026 1:32 PM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
434BB	ACCESS PANEL	2503797 / 54-ZL-00-205	OPENED	N	B0613291 - Eric Strong Feb 6, 2026 9:22 AM
			READYTOCLOSE	N	B1018546 - Andres Velazquez Feb 20, 2026 7:00 AM
			OKTOCLOSE	N	B0161691 - Thomas Mitchell Feb 26, 2026 7:17 PM
			CLOSED	N	B1016542 - Carlos Ochoa Feb 26, 2026 9:13 PM
			INSPECTED	N	B0161691 - Thomas Mitchell Feb 26, 2026 9:36 PM
434BT	L/H ENG UPPER T/R TRACKS FAIRING	2498069 / PROJ-OPERATIONS	OPENED	N	B0613291 - Eric Strong Feb 6, 2026 6:05 PM
			READYTOCLOSE	N	B1016542 - Carlos Ochoa Feb 26, 2026 6:44 PM
			OKTOCLOSE	N	B0161691 - Thomas Mitchell Feb 26, 2026 7:17 PM
			CLOSED	N	B1016542 - Carlos Ochoa Feb 26, 2026 9:13 PM
			INSPECTED	N	B0161691 - Thomas Mitchell Feb 26, 2026 9:36 PM
435AB	L/H ENG LOWER CORE COWL	2503984 / 80-11-00-202 2504300 / 71-12-00-205	OPENED	N	B0613291 - Eric Strong Feb 4, 2026 11:57 AM
435AT	L/H ENG UPPER CORE COWL	2504300 / 71-12-00-205	OPENED	N	B0642051 - Terry Walters Feb 5, 2026 1:32 PM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
436AL	L/H ENG EXHAUST NOZZLE FAIRING	2503849 / 78-ZL-00-203	OPENED	N	B0580384 - Patrick Arceneau x Feb 4, 2026 9:26 PM
			READYTOCLOSE	N	K1018275 - Emmanuel Cocoa Feb 23, 2026 9:46 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 23, 2026 10:48 AM
			CLOSED	N	K1018275 - Emmanuel Cocoa Feb 23, 2026 2:18 PM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 25, 2026 9:20 AM
436BB	L/H ENG LOWER TAIL PIPE ACCESS PNL	2503849 / 78-ZL-00-203	OPENED	N	B0580384 - Patrick Arceneau x Feb 4, 2026 9:27 PM
			READYTOCLOSE	N	B0646266 - Sergio Rodriguez Figueroa Feb 25, 2026 9:01 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 25, 2026 9:21 AM
			CLOSED	N	B0646266 - Sergio Rodriguez Figueroa Feb 25, 2026 10:32 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 25, 2026 12:10 PM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
436BL	L/H ENG UPPER TAIL PIPE ACCESS PNL	2503849 / 78-ZL-00-203	OPENED	N	B0580384 - Patrick Arceneau x Feb 4, 2026 9:27 PM
			READYTOCLOSE	N	B0646266 - Sergio Rodriguez Figueroa Feb 25, 2026 9:01 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 25, 2026 9:21 AM
			CLOSED	N	B0646266 - Sergio Rodriguez Figueroa Feb 25, 2026 10:32 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 25, 2026 12:10 PM
436BR	L/H ENG TAIL PIPE ACCESS PNL	2503849 / 78-ZL-00-203	OPENED	N	B0580384 - Patrick Arceneau x Feb 4, 2026 9:27 PM
			READYTOCLOSE	N	B0646266 - Sergio Rodriguez Figueroa Feb 25, 2026 9:01 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 25, 2026 9:21 AM
			CLOSED	N	B0646266 - Sergio Rodriguez Figueroa Feb 25, 2026 10:32 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 25, 2026 12:10 PM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
442AB	R/H ENG LOWER NOSE COWL	2504319 / 78-30-00-209 2504310 / 78-30-00-206 2504301 / 71-13-00-202 2504315 / 78-30-00-207 2504318 / 78-30-00-208	OPENED	N	B0642051 - Terry Walters Feb 5, 2026 10:19 AM
442AT	R/H ENG UPPER NOSE COWL	2504319 / 78-30-00-209 2504310 / 78-30-00-206 2504301 / 71-13-00-202 2504315 / 78-30-00-207 2504318 / 78-30-00-208	OPENED	N	B0642051 - Terry Walters Feb 5, 2026 1:32 PM
442DT	ECU Access Panel				
			N/A	N	B1014141 - Christopher Draw dy Feb 11, 2026 8:15 AM
443AB	R/H ENG LOWER T/R TRACKS ACCESS PNL	2503848 / 78-ZL-00-202	OPENED	N	B0613291 - Eric Strong Feb 6, 2026 9:23 AM
			READYTOCLOSE	N	B1018409 - Areida Cruz Feb 20, 2026 6:49 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 20, 2026 7:21 AM
			CLOSED	N	B1018409 - Areida Cruz Feb 20, 2026 10:04 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 20, 2026 10:57 AM
443AT	R/H ENG UPPER T/R TRACKS ACCESS PNL	2503848 / 78-ZL-00-202	OPENED	N	B0613291 - Eric Strong Feb 6, 2026 4:29 PM
			READYTOCLOSE	N	B1018409 - Areida Cruz Feb 20, 2026 10:25 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
443AT	R/H ENG UPPER T/R TRACKS ACCESS PNL	2503848 / 78-ZL-00-202	OPENED	N	B0613291 - Eric Strong Feb 6, 2026 4:29 PM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 20, 2026 11:53 AM
			CLOSED	N	B1018409 - Areida Cruz Feb 20, 2026 1:47 PM
			INSPECTED	N	B0142244 - Todd Bridges Feb 20, 2026 4:37 PM
444AB	R/H ENG LOWER TRANSLATING COWL	2503984 / 80-11-00-202 2503843 / 71-ZL-00-206 2504374 / 72-40-00-205R 2503986 / 80-11-00-203	OPENED	N	B0613291 - Eric Strong Feb 4, 2026 11:57 AM
			READYTOCLOSE	N	B1020176 - Matthew Doyle Mar 2, 2026 6:55 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Mar 2, 2026 9:30 AM
			CLOSED	N	B1020176 - Matthew Doyle Mar 2, 2026 9:46 AM
			INSPECTED	N	B1013522 - Brandon Jennings Mar 2, 2026 10:31 AM
444AT	R/H ENG UPPER TRANSLATING COWL	2503843 / 71-ZL-00-206 2504374 / 72-40-00-205R 2503986 / 80-11-00-203	OPENED	N	B0642051 - Terry Walters Feb 5, 2026 1:32 PM
			READYTOCLOSE	N	B1020176 - Matthew Doyle Mar 2, 2026 6:55 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Mar 2, 2026 9:30 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
444AT	R/H ENG UPPER TRANSLATING COWL	2503843 / 71-ZL-00-206 2504374 / 72-40-00-205R 2503986 / 80-11-00-203	OPENED	N	B0642051 - Terry Walters Feb 5, 2026 1:32 PM
			CLOSED	N	B1020176 - Matthew Doyle Mar 2, 2026 9:46 AM
			INSPECTED	N	B1013522 - Brandon Jennings Mar 2, 2026 10:31 AM
			INSPECTED	Y	B0141354 - Karl Tuxhorn Mar 5, 2026 1:01 PM
			CLOSED	Y	B0141354 - Karl Tuxhorn Mar 5, 2026 1:02 PM
			OKTOCLOSE	Y	B0141354 - Karl Tuxhorn Mar 5, 2026 1:03 PM
			READYTOCLOSE	Y	B0141354 - Karl Tuxhorn Mar 5, 2026 1:03 PM
			READYTOCLOSE	N	B1021822 - Joseph Cuoco Mar 6, 2026 6:38 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Mar 6, 2026 8:35 AM
			CLOSED	N	B1021822 - Joseph Cuoco Mar 6, 2026 8:43 AM
			INSPECTED	N	B1013522 - Brandon Jennings Mar 6, 2026 8:48 AM
444BB	ACCESS PANEL	2503799 / 54-ZL-00-206	OPENED	N	B0613291 - Eric Strong Feb 6, 2026 9:24 AM
			READYTOCLOSE	N	B1018409 - Areida Cruz Feb 20, 2026 6:49 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
444BB	ACCESS PANEL	2503799 / 54-ZL-00-206	OPENED	N	B0613291 - Eric Strong Feb 6, 2026 9:24 AM
			OKTOCLOSE	N	B0161691 - Thomas Mitchell Feb 26, 2026 7:17 PM
			CLOSED	N	B1016542 - Carlos Ochoa Feb 26, 2026 9:13 PM
			INSPECTED	N	B0161691 - Thomas Mitchell Feb 26, 2026 9:36 PM
444BT	R/H ENG UPPER T/R TRACKS FAIRING	2498069 / PROJ-OPERATIONS	OPENED	N	B0613291 - Eric Strong Feb 6, 2026 4:44 PM
			READYTOCLOSE	N	B1016542 - Carlos Ochoa Feb 26, 2026 9:19 PM
			OKTOCLOSE	N	B0161691 - Thomas Mitchell Feb 26, 2026 10:12 PM
			CLOSED	N	B1016542 - Carlos Ochoa Feb 26, 2026 10:21 PM
			CLOSED	Y	B0141354 - Karl Tuxhorn Mar 5, 2026 1:01 PM
			OKTOCLOSE	Y	B0141354 - Karl Tuxhorn Mar 5, 2026 1:02 PM
			READYTOCLOSE	Y	B0141354 - Karl Tuxhorn Mar 5, 2026 1:03 PM
			READYTOCLOSE	N	B1021822 - Joseph Cuoco Mar 6, 2026 6:38 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Mar 6, 2026 7:25 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
444BT	R/H ENG UPPER T/R TRACKS FAIRING	2498069 / PROJ-OPERATIONS	OPENED	N	B0613291 - Eric Strong Feb 6, 2026 4:44 PM
			CLOSED	N	B1021822 - Joseph Cuoco Mar 6, 2026 7:45 AM
			INSPECTED	N	B1013522 - Brandon Jennings Mar 6, 2026 8:37 AM
445AB	R/H ENG LOWER CORE COWL	2503984 / 80-11-00-202 2504300 / 71-12-00-205	OPENED	N	B0613291 - Eric Strong Feb 4, 2026 11:57 AM
445AT	R/H ENG UPPER CORE COWL	2504300 / 71-12-00-205	OPENED	N	B0642051 - Terry Walters Feb 5, 2026 1:32 PM
446AL	R/H ENG EXHAUST NOZZLE FAIRING	2503850 / 78-ZL-00-204	OPENED	N	B0580384 - Patrick Arceneau x Feb 4, 2026 9:26 PM
			READYTOCLOSE	N	B0645936 - Carlos Zerino Feb 26, 2026 12:59 PM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 26, 2026 1:12 PM
			CLOSED	N	B0645936 - Carlos Zerino Feb 26, 2026 3:01 PM
			INSPECTED	N	B0161691 - Thomas Mitchell Feb 26, 2026 6:56 PM
446BB	R/H ENG LOWER TAIL PIPE ACCESS PNL	2503850 / 78-ZL-00-204	OPENED	N	B0580384 - Patrick Arceneau x Feb 4, 2026 9:27 PM
			READYTOCLOSE	N	B0645936 - Carlos Zerino Feb 26, 2026 6:45 PM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
446BB	R/H ENG LOWER TAIL PIPE ACCESS PNL	2503850 / 78-ZL-00-204	OPENED	N	B0580384 - Patrick Arceneau x Feb 4, 2026 9:27 PM
			OKTOCLOSE	N	B0161691 - Thomas Mitchell Feb 26, 2026 6:56 PM
			CLOSED	N	B0645936 - Carlos Zerino Feb 26, 2026 7:37 PM
			INSPECTED	N	B0161691 - Thomas Mitchell Feb 26, 2026 9:33 PM
446BL	R/H ENG UPPER TAIL PIPE ACCESS PNL	2503850 / 78-ZL-00-204	OPENED	N	B0580384 - Patrick Arceneau x Feb 4, 2026 9:27 PM
			READYTOCLOSE	N	B0645936 - Carlos Zerino Feb 26, 2026 6:45 PM
			OKTOCLOSE	N	B0161691 - Thomas Mitchell Feb 26, 2026 6:56 PM
			CLOSED	N	B0645936 - Carlos Zerino Feb 26, 2026 7:37 PM
			INSPECTED	N	B0161691 - Thomas Mitchell Feb 26, 2026 9:33 PM
446BR	R/H ENG TAIL PIPE ACCESS PNL	2503850 / 78-ZL-00-204	OPENED	N	B0580384 - Patrick Arceneau x Feb 4, 2026 9:27 PM
			READYTOCLOSE	N	B0645936 - Carlos Zerino Feb 26, 2026 6:45 PM
			OKTOCLOSE	N	B0161691 - Thomas Mitchell Feb 26, 2026 6:56 PM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
446BR	R/H ENG TAIL PIPE ACCESS PNL	2503850 / 78-ZL-00-204	OPENED	N	B0580384 - Patrick Arceneau x Feb 4, 2026 9:27 PM
			CLOSED	N	B0645936 - Carlos Zerino Feb 26, 2026 7:37 PM
			INSPECTED	N	B0161691 - Thomas Mitchell Feb 26, 2026 9:33 PM
510AB	L/H LOWER STBY FUEL PUMP ACCESS PNL	2504153 / 57-ZL-00-204 2504246 / 57-10-00-202	OPENED	N	B1018547 - Matthew Rossier Feb 6, 2026 8:10 PM
			READYTOCLOSE	N	B1022255 - Carson Chang Feb 18, 2026 10:44 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 18, 2026 1:57 PM
			CLOSED	N	B0648431 - Caleb Sexton Feb 18, 2026 1:57 PM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 26, 2026 10:12 AM
510BB	L/H LOWER BOOST PUMP COVER ACCESS PNL	2504153 / 57-ZL-00-204	OPENED	N	K1018275 - Emmanuel Cocoa Feb 10, 2026 6:52 AM
510CB	ACCESS PANEL	2504206 / 28-10-00-208 2504246 / 57-10-00-202	OPENED	N	B1018547 - Matthew Rossier Feb 6, 2026 8:10 PM
			READYTOCLOSE	N	B1022255 - Carson Chang Feb 18, 2026 10:44 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 18, 2026 12:05 PM
			CLOSED	N	B1022255 - Carson Chang Feb 18, 2026 12:39 PM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
510CB	ACCESS PANEL	2504206 / 28-10-00-208 2504246 / 57-10-00-202	OPENED	N	B1018547 - Matthew Rossier Feb 6, 2026 8:10 PM
			INSPECTED	N	B0142491 - George Ambrose Feb 18, 2026 1:03 PM
520AB	L/H WING LOWER TAXI/LDG LIGHT ACCESS PNL	2504155 / 57-ZL-00-208	OPENED	N	B0142041 - Timothy Winfree Feb 6, 2026 7:02 AM
			READYTOCLOSE	N	B0648431 - Caleb Sexton Mar 4, 2026 8:43 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Mar 4, 2026 9:09 AM
			CLOSED	N	B0648431 - Caleb Sexton Mar 4, 2026 10:05 AM
			INSPECTED	N	B1013522 - Brandon Jennings Mar 4, 2026 10:26 AM
520AT	L/H WING INBD L/EDGE	2504155 / 57-ZL-00-208 2504251 / 57-10-00-208	OPENED	N	B0645936 - Carlos Zerino Feb 4, 2026 10:51 PM
			READYTOCLOSE	N	B1020176 - Matthew Doyle Feb 19, 2026 11:48 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 19, 2026 12:15 PM
			CLOSED	N	B1020176 - Matthew Doyle Feb 19, 2026 1:18 PM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 19, 2026 2:21 PM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
520AZ	L/H WING INBD L/EDGE WS82 ACCESS PNL	2504155 / 57-ZL-00-208	OPENED	N	B0648431 - Caleb Sexton Feb 5, 2026 12:57 PM
			READYTOCLOSE	N	B0642051 - Terry Walters Feb 18, 2026 9:37 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 18, 2026 10:16 AM
			CLOSED	N	B0642051 - Terry Walters Feb 18, 2026 12:40 PM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 19, 2026 7:00 AM
520BL	L/H WING INBD L/EDGE	2504155 / 57-ZL-00-208 2504251 / 57-10-00-208	OPENED	N	B0645936 - Carlos Zerino Feb 4, 2026 10:53 PM
			READYTOCLOSE	N	B1020176 - Matthew Doyle Feb 19, 2026 6:47 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 19, 2026 7:02 AM
			CLOSED	N	B0642051 - Terry Walters Feb 19, 2026 10:50 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 19, 2026 12:14 PM
520BZ	L/H WING INBD L/EDGE WS98 ACCESS PNL	2504155 / 57-ZL-00-208	OPENED	N	B0648431 - Caleb Sexton Feb 5, 2026 12:57 PM
			READYTOCLOSE	N	B0642051 - Terry Walters Feb 18, 2026 9:37 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 18, 2026 10:16 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
520BZ	L/H WING INBD L/EDGE WS98 ACCESS PNL	2504155 / 57-ZL-00-208	OPENED	N	B0648431 - Caleb Sexton Feb 5, 2026 12:57 PM
			CLOSED	N	B0642051 - Terry Walters Feb 18, 2026 12:40 PM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 19, 2026 7:00 AM
520CZ	L/H WING INBD L/EDGE WS114 ACCESS PNL	2504155 / 57-ZL-00-208	OPENED	N	B0648431 - Caleb Sexton Feb 5, 2026 12:57 PM
			READYTOCLOSE	N	B0642051 - Terry Walters Feb 18, 2026 9:37 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 18, 2026 10:16 AM
			CLOSED	N	B0642051 - Terry Walters Feb 18, 2026 12:40 PM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 19, 2026 7:00 AM
520DZ	L/H WING INBD L/EDGE WS129 ACCESS PNL	2504155 / 57-ZL-00-208	OPENED	N	B0648431 - Caleb Sexton Feb 5, 2026 12:57 PM
			READYTOCLOSE	N	B0642051 - Terry Walters Feb 18, 2026 9:37 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 18, 2026 10:16 AM
			CLOSED	N	B0642051 - Terry Walters Feb 18, 2026 12:40 PM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 19, 2026 7:00 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
520EL	L/H WING TRANSITION L/EDGE	2504155 / 57-ZL-00-208 2504160 / 57-ZL-00-212 2504251 / 57-10-00-208	OPENED	N	B0645936 - Carlos Zerino Feb 4, 2026 10:51 PM
			READYTOCLOSE	N	B1020176 - Matthew Doyle Feb 19, 2026 11:48 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 19, 2026 12:15 PM
			CLOSED	N	B1020176 - Matthew Doyle Feb 19, 2026 1:18 PM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 19, 2026 2:21 PM
530AZ	L/H WING MID L/EDGE WS165 ACCESS PNL	2504160 / 57-ZL-00-212	OPENED	N	B0578429 - Cristian Noriega Feb 5, 2026 8:43 AM
			READYTOCLOSE	N	B0642051 - Terry Walters Feb 18, 2026 9:37 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 18, 2026 10:16 AM
			CLOSED	N	B1020176 - Matthew Doyle Feb 18, 2026 12:13 PM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 19, 2026 7:00 AM
530BL	L/H WING MIDDLE L/EDGE	2504160 / 57-ZL-00-212 2504251 / 57-10-00-208	OPENED	N	B0645936 - Carlos Zerino Feb 4, 2026 10:53 PM
			READYTOCLOSE	N	B1020176 - Matthew Doyle Feb 19, 2026 6:47 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 19, 2026 7:02 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
530BL	L/H WING MIDDLE L/EDGE	2504160 / 57-ZL-00-212 2504251 / 57-10-00-208	OPENED	N	B0645936 - Carlos Zerino Feb 4, 2026 10:53 PM
			CLOSED	N	B0642051 - Terry Walters Feb 19, 2026 10:50 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 19, 2026 12:14 PM
530BZ	L/H WING MID L/EDGE WS183 ACCESS PNL	2504160 / 57-ZL-00-212	OPENED	N	B0578429 - Cristian Noriega Feb 5, 2026 8:43 AM
			READYTOCLOSE	N	B0642051 - Terry Walters Feb 18, 2026 9:37 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 18, 2026 10:16 AM
			CLOSED	N	B1020176 - Matthew Doyle Feb 18, 2026 12:13 PM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 19, 2026 7:00 AM
530CL	L/H WING L/EDGE	2504160 / 57-ZL-00-212 2504251 / 57-10-00-208	OPENED	N	B0645936 - Carlos Zerino Feb 4, 2026 10:51 PM
			READYTOCLOSE	N	B1020176 - Matthew Doyle Feb 19, 2026 11:49 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 19, 2026 12:15 PM
			CLOSED	N	B1020176 - Matthew Doyle Feb 19, 2026 1:17 PM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 19, 2026 2:21 PM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
530CZ	L/H WING MID L/EDGE WS201 ACCESS PNL	2504160 / 57-ZL-00-212	OPENED	N	B0578429 - Cristian Noriega Feb 5, 2026 8:43 AM
			READYTOCLOSE	N	B0642051 - Terry Walters Feb 18, 2026 9:37 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 18, 2026 10:16 AM
			CLOSED	N	B1020176 - Matthew Doyle Feb 18, 2026 12:13 PM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 19, 2026 7:00 AM
530DL	L/H WING OUTBD L/EDGE	2504160 / 57-ZL-00-212 2504251 / 57-10-00-208	OPENED	N	B0648431 - Caleb Sexton Feb 5, 2026 10:37 AM
			READYTOCLOSE	N	B1020176 - Matthew Doyle Feb 19, 2026 6:47 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 19, 2026 7:02 AM
			CLOSED	N	B1020176 - Matthew Doyle Feb 19, 2026 8:39 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 19, 2026 12:14 PM
530DZ	L/H WING MID L/EDGE WS218 ACCESS PNL	2504160 / 57-ZL-00-212	OPENED	N	B0578429 - Cristian Noriega Feb 5, 2026 8:43 AM
			READYTOCLOSE	N	B0642051 - Terry Walters Feb 18, 2026 9:37 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 18, 2026 10:16 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
530DZ	L/H WING MID L/EDGE WS218 ACCESS PNL	2504160 / 57-ZL-00-212	OPENED	N	B0578429 - Cristian Noriega Feb 5, 2026 8:43 AM
			CLOSED	N	B1020176 - Matthew Doyle Feb 18, 2026 12:13 PM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 19, 2026 7:00 AM
530EZ	L/H WING MID L/EDGE WS235 ACCESS PNL	2504160 / 57-ZL-00-212	OPENED	N	B0578429 - Cristian Noriega Feb 5, 2026 8:43 AM
			READYTOCLOSE	N	B0642051 - Terry Walters Feb 18, 2026 9:37 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 18, 2026 10:16 AM
			CLOSED	N	B1020176 - Matthew Doyle Feb 18, 2026 12:13 PM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 19, 2026 7:00 AM
530FZ	L/H WING OUTBD L/EDGE WS267 ACCESS PNL	2504160 / 57-ZL-00-212	OPENED	N	B0648431 - Caleb Sexton Feb 5, 2026 1:05 PM
			READYTOCLOSE	N	B0642051 - Terry Walters Feb 18, 2026 9:37 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 18, 2026 10:16 AM
			CLOSED	N	B1020176 - Matthew Doyle Feb 18, 2026 12:13 PM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 19, 2026 7:00 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
530GZ	L/H WING OUTBD L/EDGE WS285 ACCESS PNL	2504160 / 57-ZL-00-212	OPENED	N	B0648431 - Caleb Sexton Feb 5, 2026 1:05 PM
			READYTOCLOSE	N	B0642051 - Terry Walters Feb 18, 2026 9:37 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 18, 2026 10:16 AM
			CLOSED	N	B1020176 - Matthew Doyle Feb 18, 2026 12:13 PM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 19, 2026 7:00 AM
530HZ	L/H WING OUTBD L/EDGE WS300 ACCESS PNL	2504160 / 57-ZL-00-212	OPENED	N	B0648431 - Caleb Sexton Feb 5, 2026 1:05 PM
			READYTOCLOSE	N	B0642051 - Terry Walters Feb 18, 2026 9:37 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 18, 2026 10:16 AM
			CLOSED	N	B1020176 - Matthew Doyle Feb 18, 2026 12:13 PM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 19, 2026 7:00 AM
530JZ	L/H WING OUTBD L/EDGE WS320 ACCESS PNL	2504160 / 57-ZL-00-212	OPENED	N	B0648431 - Caleb Sexton Feb 5, 2026 1:05 PM
			READYTOCLOSE	N	B0642051 - Terry Walters Feb 18, 2026 9:37 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 18, 2026 10:16 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
530JZ	L/H WING OUTBD L/EDGE WS320 ACCESS PNL	2504160 / 57-ZL-00-212	OPENED	N	B0648431 - Caleb Sexton Feb 5, 2026 1:05 PM
			CLOSED	N	B1020176 - Matthew Doyle Feb 18, 2026 12:13 PM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 19, 2026 7:00 AM
530KZ	L/H WING OUTBD L/EDGE WS338 ACCESS PNL	2504160 / 57-ZL-00-212	OPENED	N	B0648431 - Caleb Sexton Feb 5, 2026 1:05 PM
			READYTOCLOSE	N	B0642051 - Terry Walters Feb 18, 2026 9:37 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 18, 2026 10:16 AM
			CLOSED	N	B1020176 - Matthew Doyle Feb 18, 2026 12:13 PM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 19, 2026 7:00 AM
531SB	Aileron Control, Access Panel				
			N/A	N	B0162034 - Tyler Poggi Feb 10, 2026 3:44 PM
540AB	L/H WING LOWER INBD FUEL ACCESS PNL	2504165 / 57-ZL-00-216 2504255 / 57-10-00-209	OPENED	N	B1018547 - Matthew Rossier Feb 6, 2026 8:10 PM
			READYTOCLOSE	N	B1018547 - Matthew Rossier Feb 27, 2026 3:45 PM
			OKTOCLOSE	N	B0161691 - Thomas Mitchell Feb 27, 2026 4:17 PM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
540AB	L/H WING LOWER INBD FUEL ACCESS PNL	2504165 / 57-ZL-00-216 2504255 / 57-10-00-209	OPENED	N	B1018547 - Matthew Rossier Feb 6, 2026 8:10 PM
			CLOSED	N	B1018547 - Matthew Rossier Feb 27, 2026 4:36 PM
			INSPECTED	N	B0161691 - Thomas Mitchell Feb 27, 2026 5:42 PM
540BB	L/H WING LOWER INBD FUEL ACCESS PNL	2504165 / 57-ZL-00-216 2504255 / 57-10-00-209	OPENED	N	B1018547 - Matthew Rossier Feb 6, 2026 7:20 PM
			READYTOCLOSE	N	B1022255 - Carson Chang Feb 18, 2026 10:42 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 18, 2026 12:05 PM
			CLOSED	N	B1022255 - Carson Chang Feb 18, 2026 12:39 PM
			INSPECTED	N	B0142491 - George Ambrose Feb 18, 2026 12:59 PM
540CB	L/H WING LOWER INBD FUEL ACCESS PNL	2504165 / 57-ZL-00-216 2504255 / 57-10-00-209	OPENED	N	B1018547 - Matthew Rossier Feb 6, 2026 7:20 PM
			READYTOCLOSE	N	B1022255 - Carson Chang Feb 18, 2026 10:42 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 18, 2026 12:05 PM
			CLOSED	N	B0648431 - Caleb Sexton Feb 18, 2026 12:36 PM
			INSPECTED	N	B0142491 - George Ambrose Feb 18, 2026 12:59 PM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
540DB	L/H WING LOWER INBD FUEL ACCESS PNL	2504165 / 57-ZL-00-216 2504255 / 57-10-00-209	OPENED	N	B1018547 - Matthew Rossier Feb 6, 2026 7:20 PM
			READYTOCLOSE	N	B1022255 - Carson Chang Feb 18, 2026 10:42 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 18, 2026 12:05 PM
			CLOSED	N	B0648431 - Caleb Sexton Feb 18, 2026 12:36 PM
			INSPECTED	N	B0142491 - George Ambrose Feb 18, 2026 12:59 PM
540EB	L/H WING LOWER INBD FUEL ACCESS PNL	2504165 / 57-ZL-00-216 2504255 / 57-10-00-209	OPENED	N	B1018547 - Matthew Rossier Feb 6, 2026 7:20 PM
			READYTOCLOSE	N	B0648431 - Caleb Sexton Feb 18, 2026 7:39 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 18, 2026 9:27 AM
			CLOSED	N	B1022255 - Carson Chang Feb 18, 2026 9:44 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 18, 2026 10:24 AM
540FB	L/H WING LOWER INBD FUEL ACCESS PNL	2504165 / 57-ZL-00-216 2504255 / 57-10-00-209	OPENED	N	B1018547 - Matthew Rossier Feb 6, 2026 7:20 PM
			READYTOCLOSE	N	B0648431 - Caleb Sexton Feb 18, 2026 7:39 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 18, 2026 9:27 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
540FB	L/H WING LOWER INBD FUEL ACCESS PNL	2504165 / 57-ZL-00-216 2504255 / 57-10-00-209	OPENED	N	B1018547 - Matthew Rossier Feb 6, 2026 7:20 PM
			CLOSED	N	B1022255 - Carson Chang Feb 18, 2026 9:44 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 18, 2026 10:24 AM
541AT	L/H WING UPPER ACCESS PNL	2504165 / 57-ZL-00-216 2504255 / 57-10-00-209 2503885 / 57-10-00-217 2503881 / 57-10-00-211	OPENED	N	B0650736 - Jesus Gonzalez A tondo Feb 9, 2026 1:34 PM
			READYTOCLOSE	N	B1018546 - Andres Velazquez Feb 20, 2026 10:17 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 20, 2026 12:07 PM
			CLOSED	N	B1018546 - Andres Velazquez Feb 20, 2026 12:15 PM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 20, 2026 12:33 PM
550AB	L/H WING LOWER MID FUEL ACCESS PNL	2504167 / 57-ZL-00-220 2504255 / 57-10-00-209	OPENED	N	B0583361 - Brett Hurley Feb 6, 2026 10:05 AM
			READYTOCLOSE	N	B0648431 - Caleb Sexton Feb 18, 2026 7:38 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 18, 2026 9:27 AM
			CLOSED	N	B0648431 - Caleb Sexton Feb 18, 2026 9:37 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
550AB	L/H WING LOWER MID FUEL ACCESS PNL	2504167 / 57-ZL-00-220 2504255 / 57-10-00-209	OPENED	N	B0583361 - Brett Hurley Feb 6, 2026 10:05 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 18, 2026 10:24 AM
550BB	L/H WING LOWER MID FUEL ACCESS PNL	2504167 / 57-ZL-00-220 2504255 / 57-10-00-209	OPENED	N	B0583361 - Brett Hurley Feb 6, 2026 10:05 AM
			READYTOCLOSE	N	B0648431 - Caleb Sexton Feb 18, 2026 7:38 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 18, 2026 9:27 AM
			CLOSED	N	B0648431 - Caleb Sexton Feb 18, 2026 9:37 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 18, 2026 10:24 AM
550CB	L/H WING LOWER MID FUEL ACCESS PNL	2504167 / 57-ZL-00-220 2504255 / 57-10-00-209	OPENED	N	B0583361 - Brett Hurley Feb 6, 2026 10:05 AM
			READYTOCLOSE	N	B0648431 - Caleb Sexton Feb 18, 2026 7:38 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 18, 2026 8:24 AM
			CLOSED	N	B1022255 - Carson Chang Feb 18, 2026 9:00 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 18, 2026 10:24 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
550DB	L/H WING LOWER MID FUEL ACCESS PNL	2504167 / 57-ZL-00-220 2504255 / 57-10-00-209	OPENED	N	B0646266 - Sergio Rodriguez Figueroa Feb 10, 2026 12:15 PM
			READYTOCLOSE	N	B0648431 - Caleb Sexton Feb 18, 2026 7:38 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 18, 2026 8:24 AM
			CLOSED	N	B1022255 - Carson Chang Feb 18, 2026 9:00 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 18, 2026 10:24 AM
550DT	L/H WING UPPER OUTBD ACCESS PNL	2504256 / 57-10-00-213	OPENED	N	B0143806 - Alejandro Cabani llas Feb 10, 2026 12:10 PM
			READYTOCLOSE	N	B1016542 - Carlos Ochoa Feb 19, 2026 8:29 PM
			OKTOCLOSE	N	B0142244 - Todd Bridges Feb 20, 2026 4:55 PM
			CLOSED	N	B1018546 - Andres Velazquez Feb 20, 2026 5:24 PM
			INSPECTED	N	B0142244 - Todd Bridges Feb 20, 2026 5:40 PM
550EB	L/H WING LOWER OUTBD FUEL ACCESS PNL	2504167 / 57-ZL-00-220 2504255 / 57-10-00-209	OPENED	N	B0583361 - Brett Hurley Feb 6, 2026 10:05 AM
			READYTOCLOSE	N	B0648431 - Caleb Sexton Feb 18, 2026 7:36 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
550EB	L/H WING LOWER OUTBD FUEL ACCESS PNL	2504167 / 57-ZL-00-220 2504255 / 57-10-00-209	OPENED	N	B0583361 - Brett Hurley Feb 6, 2026 10:05 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 18, 2026 8:24 AM
			CLOSED	N	B1022255 - Carson Chang Feb 18, 2026 9:00 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 18, 2026 10:24 AM
550FB	L/H WING LOWER OUTBD FUEL ACCESS PNL	2504167 / 57-ZL-00-220 2504255 / 57-10-00-209	OPENED	N	B0583361 - Brett Hurley Feb 6, 2026 10:05 AM
			READYTOCLOSE	N	B0648431 - Caleb Sexton Feb 18, 2026 7:36 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 18, 2026 8:24 AM
			CLOSED	N	B0648431 - Caleb Sexton Feb 18, 2026 9:33 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 18, 2026 10:24 AM
550GB	L/H WING LOWER OUTBD FUEL ACCESS PNL	2504167 / 57-ZL-00-220 2504255 / 57-10-00-209	OPENED	N	B0583361 - Brett Hurley Feb 6, 2026 10:05 AM
			READYTOCLOSE	N	B0648431 - Caleb Sexton Feb 18, 2026 7:36 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 18, 2026 8:24 AM
			CLOSED	N	B0648431 - Caleb Sexton Feb 18, 2026 9:33 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
550GB	L/H WING LOWER OUTBD FUEL ACCESS PNL	2504167 / 57-ZL-00-220 2504255 / 57-10-00-209	OPENED	N	B0583361 - Brett Hurley Feb 6, 2026 10:05 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 18, 2026 10:24 AM
550HB	L/H WING LOWER OUTBD FUEL ACCESS PNL	2504167 / 57-ZL-00-220 2504255 / 57-10-00-209	OPENED	N	B0583361 - Brett Hurley Feb 6, 2026 10:05 AM
			READYTOCLOSE	N	B0648431 - Caleb Sexton Feb 18, 2026 7:36 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 18, 2026 8:24 AM
			CLOSED	N	B0648431 - Caleb Sexton Feb 18, 2026 9:33 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 18, 2026 10:24 AM
550JB	L/H WING LOWER OUTBD FUEL ACCESS PNL	2504167 / 57-ZL-00-220 2504256 / 57-10-00-213	OPENED	N	B0646266 - Sergio Rodriguez Figueroa Feb 10, 2026 12:17 PM
			READYTOCLOSE	N	B1016542 - Carlos Ochoa Feb 19, 2026 8:43 PM
			OKTOCLOSE	N	B0623124 - Michael Stacy Feb 19, 2026 8:46 PM
			CLOSED	N	B1016542 - Carlos Ochoa Feb 19, 2026 9:25 PM
			INSPECTED	N	B0623124 - Michael Stacy Feb 19, 2026 9:32 PM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
550KB	L/H WING LOWER OUTBD PCU ACCESS PNL	2503869 / 27-00-00-209 2504167 / 57-ZL-00-220 2504256 / 57-10-00-213	OPENED	N	B0648431 - Caleb Sexton Feb 5, 2026 7:27 AM
			READYTOCLOSE	N	B0650736 - Jesus Gonzalez A tondo Mar 5, 2026 9:17 AM
			OKTOCLOSE	N	B0142491 - George Ambrose Mar 5, 2026 12:10 PM
			CLOSED	N	B1022255 - Carson Chang Mar 5, 2026 12:36 PM
			INSPECTED	N	B1013522 - Brandon Jennings Mar 5, 2026 2:21 PM
550LB	L/H WING LOWER OUTBD ACCESS PNL	2504167 / 57-ZL-00-220 2504256 / 57-10-00-213	OPENED	N	B0648431 - Caleb Sexton Feb 5, 2026 7:27 AM
			READYTOCLOSE	N	B0650736 - Jesus Gonzalez A tondo Mar 5, 2026 9:17 AM
			OKTOCLOSE	N	B0142491 - George Ambrose Mar 5, 2026 12:10 PM
			CLOSED	N	B1022255 - Carson Chang Mar 5, 2026 12:36 PM
			INSPECTED	N	B1013522 - Brandon Jennings Mar 5, 2026 2:21 PM
550MB	L/H WING LOWER OUTBD ACCESS PNL	2503869 / 27-00-00-209			
			N/A	N	B0142041 - Timothy Winfree Feb 20, 2026 10:29 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
551DB	Aileron Gear Tab, Fairing				
			N/A	N	B1014141 - Christopher Draw dy Feb 11, 2026 8:17 AM
554AB	Trailing Edge, Access Panel				
			N/A	N	B1014141 - Christopher Draw dy Feb 11, 2026 8:17 AM
560AB	ACCESS PANEL	2504279 / 57-30-00-201	OPENED	N	K1018275 - Emmanuel Cocoa Feb 10, 2026 10:31 AM
			READYTOCLOSE	N	B0638589 - Sean Dodder Feb 19, 2026 6:24 PM
			OKTOCLOSE	N	B0623124 - Michael Stacy Feb 19, 2026 6:26 PM
			CLOSED	N	B0638589 - Sean Dodder Feb 19, 2026 7:14 PM
			INSPECTED	N	B0623124 - Michael Stacy Feb 19, 2026 7:20 PM
560AL	L/H WING NAV LIGHT LENS	2504279 / 57-30-00-201 2504256 / 57-10-00-213	OPENED	N	K1018275 - Emmanuel Cocoa Feb 10, 2026 10:31 AM
560BB	L/H WING LOWER OUTBD ACCESS PNL	2504279 / 57-30-00-201 2504256 / 57-10-00-213	OPENED	N	B0648431 - Caleb Sexton Feb 5, 2026 7:27 AM
			READYTOCLOSE	N	B1016542 - Carlos Ochoa Feb 19, 2026 8:31 PM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
560BB	L/H WING LOWER OUTBD ACCESS PNL	2504279 / 57-30-00-201 2504256 / 57-10-00-213	OPENED	N	B0648431 - Caleb Sexton Feb 5, 2026 7:27 AM
			OKTOCLOSE	N	B0623124 - Michael Stacy Feb 19, 2026 8:46 PM
			CLOSED	N	B0646275 - Hector Amaya Jr Feb 19, 2026 9:25 PM
			INSPECTED	N	B0623124 - Michael Stacy Feb 19, 2026 9:32 PM
560DB	L/H WING LOWER WING TO WINGLET FAIRING	2504279 / 57-30-00-201	OPENED	N	B0641903 - Felipe Mendoza C ervantes Feb 18, 2026 5:40 PM
			READYTOCLOSE	N	B1016542 - Carlos Ochoa Feb 19, 2026 8:33 PM
			OKTOCLOSE	N	B0623124 - Michael Stacy Feb 19, 2026 8:46 PM
			CLOSED	N	B0646275 - Hector Amaya Jr Feb 19, 2026 9:25 PM
			INSPECTED	N	B0623124 - Michael Stacy Feb 19, 2026 9:32 PM
571AB	L/H WING LOWER FWD INBD FLAP FAIRING	2503830 / 57-ZL-00-226 2503818 / 57-ZL-00-214 2504264 / 57-10-00-227 2504288 / 57-50-00-210	OPENED	N	B1020176 - Matthew Doyle Feb 5, 2026 1:30 PM
			READYTOCLOSE	N	B1021822 - Joseph Cuoco Mar 4, 2026 9:33 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Mar 4, 2026 9:44 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
571AB	L/H WING LOWER FWD INBD FLAP FAIRING	2503830 / 57-ZL-00-226 2503818 / 57-ZL-00-214 2504264 / 57-10-00-227 2504288 / 57-50-00-210	OPENED	N	B1020176 - Matthew Doyle Feb 5, 2026 1:30 PM
			CLOSED	N	B1021822 - Joseph Cuoco Mar 4, 2026 10:20 AM
			INSPECTED	N	B1013522 - Brandon Jennings Mar 4, 2026 10:29 AM
571BB	L/H WING LOWER INBD ACCESS PNL	2504165 / 57-ZL-00-216 2504255 / 57-10-00-209 2503885 / 57-10-00-217 2503881 / 57-10-00-211	OPENED	N	B0646266 - Sergio Rodriguez Figueroa Feb 10, 2026 12:22 PM
			READYTOCLOSE	N	B1020176 - Matthew Doyle Mar 3, 2026 12:13 PM
			OKTOCLOSE	N	B1017318 - Steve Pritchett Mar 3, 2026 1:19 PM
			CLOSED	N	B1020176 - Matthew Doyle Mar 3, 2026 1:37 PM
571CB	L/H WING LOWER INBD ACCESS PNL	2504165 / 57-ZL-00-216 2504255 / 57-10-00-209 2503885 / 57-10-00-217 2503881 / 57-10-00-211	OPENED	N	B0646266 - Sergio Rodriguez Figueroa Feb 10, 2026 12:22 PM
			READYTOCLOSE	N	B1020176 - Matthew Doyle Mar 3, 2026 12:13 PM
			OKTOCLOSE	N	B1017318 - Steve Pritchett Mar 3, 2026 1:19 PM
			CLOSED	N	B1020176 - Matthew Doyle Mar 3, 2026 1:37 PM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
571DB	L/H WING LOWER INBD ACCESS PNL	2504165 / 57-ZL-00-216 2504255 / 57-10-00-209 2503885 / 57-10-00-217 2503881 / 57-10-00-211	OPENED	N	B0646266 - Sergio Rodriguez Figueroa Feb 10, 2026 12:22 PM
			READYTOCLOSE	N	B1020176 - Matthew Doyle Mar 3, 2026 12:13 PM
			OKTOCLOSE	N	B1017318 - Steve Pritchett Mar 3, 2026 1:19 PM
			CLOSED	N	B1020176 - Matthew Doyle Mar 3, 2026 1:37 PM
571EB	L/H WING LOWER FWD INBD FLAP FAIRING	2503830 / 57-ZL-00-226 2503818 / 57-ZL-00-214 2504264 / 57-10-00-227 2504288 / 57-50-00-210	OPENED	N	B1020176 - Matthew Doyle Feb 5, 2026 11:52 AM
			READYTOCLOSE	N	B1020176 - Matthew Doyle Feb 20, 2026 8:58 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 20, 2026 9:46 AM
			CLOSED	N	B1020176 - Matthew Doyle Feb 20, 2026 12:20 PM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 20, 2026 12:35 PM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
572DB	L/H WING LOWER AFT INBD FLAP FAIRING	2504199 / 22-12-00-210 2503830 / 57-ZL-00-226 2503818 / 57-ZL-00-214 2504264 / 57-10-00-227 2504288 / 57-50-00-210 2504282 / 57-50-00-202	OPENED	N	B1020176 - Matthew Doyle Feb 5, 2026 1:31 PM
			READYTOCLOSE	N	B1020176 - Matthew Doyle Mar 3, 2026 1:37 PM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Mar 4, 2026 9:44 AM
			CLOSED	N	B1021822 - Joseph Cuoco Mar 4, 2026 10:20 AM
			INSPECTED	N	B1013522 - Brandon Jennings Mar 4, 2026 10:29 AM
572GB	L/H WING LOWER AFT INBD FLAP FAIRING	2503830 / 57-ZL-00-226 2503818 / 57-ZL-00-214 2504264 / 57-10-00-227 2504288 / 57-50-00-210 2504282 / 57-50-00-202	OPENED	N	B1020176 - Matthew Doyle Feb 5, 2026 11:53 AM
			READYTOCLOSE	N	B1020176 - Matthew Doyle Feb 20, 2026 8:58 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 20, 2026 9:46 AM
			CLOSED	N	B1020176 - Matthew Doyle Feb 20, 2026 12:20 PM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 20, 2026 12:35 PM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
573AB	Inboard Flap Fairing, Leading Edge				
			N/A	N	B1014141 - Christopher Draw dy Feb 11, 2026 7:52 AM
573BB	Inboard Flap Fairing				
			N/A	N	B1014141 - Christopher Draw dy Feb 11, 2026 7:52 AM
573BL	Inboard, Flap Fairing, Access Panel				
			N/A	N	B1014141 - Christopher Draw dy Feb 11, 2026 7:52 AM
573BR	Inboard, Flap Fairing, Access Panel				
			N/A	N	B1014141 - Christopher Draw dy Feb 11, 2026 7:52 AM
573CB	Inboard Flap Fairing, Trailing Edge				
			N/A	N	B1014141 - Christopher Draw dy Feb 11, 2026 7:52 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
574AB	Middle Flap Fairing, Leading Edge				
			N/A	N	B1014141 - Christopher Draw dy Feb 11, 2026 7:52 AM
574BB	Middle Flap Fairing				
			N/A	N	B1014141 - Christopher Draw dy Feb 11, 2026 7:52 AM
574BL	Middle, Flap Fairing, Access Panel				
			N/A	N	B1014141 - Christopher Draw dy Feb 11, 2026 7:52 AM
574BR	Middle, Flap Fairing, Access Panel				
			N/A	N	B1014141 - Christopher Draw dy Feb 11, 2026 7:52 AM
574CB	Middle Flap Fairing, Trailing Edge				
			N/A	N	B1014141 - Christopher Draw dy Feb 11, 2026 7:52 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
575AB	Outboard Flap Fairing, Leading Edge				
			N/A	N	B1014141 - Christopher Draw dy Feb 11, 2026 7:53 AM
575BB	Outboard Flap Fairing				
			N/A	N	B1014141 - Christopher Draw dy Feb 11, 2026 7:53 AM
575BL	Outboard, Flap Fairing, Access Panel				
			N/A	N	B1014141 - Christopher Draw dy Feb 11, 2026 7:53 AM
575BR	Outboard, Flap Fairing, Access Panel				
			N/A	N	B1014141 - Christopher Draw dy Feb 11, 2026 7:53 AM
575CB	Outboard Flap Fairing, Trailing Edge				
			N/A	N	B1014141 - Christopher Draw dy Feb 11, 2026 7:53 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
581AB	L/H WING LOWER OUTBD FLAP ACT BUTE DOOR	2504297 / 57-70-00-206 2503881 / 57-10-00-211	OPENED	N	B0613291 - Eric Strong Feb 9, 2026 2:12 PM
			READYTOCLOSE	N	K1018275 - Emmanuel Cocoa Feb 19, 2026 12:01 PM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 19, 2026 12:18 PM
			CLOSED	N	K1018275 - Emmanuel Cocoa Feb 19, 2026 1:25 PM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 19, 2026 1:53 PM
581AT	L/H WING UPPER ACCESS PNL	2504297 / 57-70-00-206 2503881 / 57-10-00-211	OPENED	N	B1020176 - Matthew Doyle Feb 4, 2026 1:51 PM
			READYTOCLOSE	N	B0613291 - Eric Strong Feb 20, 2026 5:11 PM
			OKTOCLOSE	N	B0142244 - Todd Bridges Feb 20, 2026 5:35 PM
			CLOSED	N	B0613291 - Eric Strong Feb 20, 2026 5:39 PM
			INSPECTED	N	B0142244 - Todd Bridges Feb 20, 2026 5:51 PM
581BB	L/H WING LOWER FWD OUTBD FLAP FAIRING	2503820 / 57-ZL-00-218 2504267 / 57-10-00-228 2504291 / 57-50-00-211	OPENED	N	B1020176 - Matthew Doyle Feb 5, 2026 11:50 AM
			READYTOCLOSE	N	B1020176 - Matthew Doyle Feb 20, 2026 8:57 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 20, 2026 9:46 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
581BB	L/H WING LOWER FWD OUTBD FLAP FAIRING	2503820 / 57-ZL-00-218 2504267 / 57-10-00-228 2504291 / 57-50-00-211	OPENED	N	B1020176 - Matthew Doyle Feb 5, 2026 11:50 AM
			CLOSED	N	B1020176 - Matthew Doyle Feb 20, 2026 12:18 PM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 20, 2026 12:35 PM
581BT	L/H WING UPPER INBD AILERON SHROUD PNL	2504255 / 57-10-00-209 2503881 / 57-10-00-211 2504270 / 57-10-00-229	OPENED	N	B0143806 - Alejandro Cabani llas Feb 10, 2026 12:03 PM
			READYTOCLOSE	N	B1018546 - Andres Velazquez Feb 20, 2026 2:24 PM
			OKTOCLOSE	N	B0142244 - Todd Bridges Feb 20, 2026 4:56 PM
			CLOSED	N	B1018546 - Andres Velazquez Feb 20, 2026 5:24 PM
			INSPECTED	N	B0142244 - Todd Bridges Feb 20, 2026 5:39 PM
581CB	L/H WING LOWER OUTBD FLAP ACT BUTE DOOR	2504297 / 57-70-00-206 2503881 / 57-10-00-211	OPENED	N	B0143806 - Alejandro Cabani llas Feb 10, 2026 1:42 PM
			READYTOCLOSE	N	K1018275 - Emmanuel Cocoa Feb 19, 2026 12:01 PM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 19, 2026 12:18 PM
			CLOSED	N	K1018275 - Emmanuel Cocoa Feb 19, 2026 1:25 PM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
581CB	L/H WING LOWER OUTBD FLAP ACT BUTE DOOR	2504297 / 57-70-00-206 2503881 / 57-10-00-211	OPENED	N	B0143806 - Alejandro Cabani llas Feb 10, 2026 1:42 PM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 19, 2026 1:53 PM
581CT	L/H WING UPPER MID INBD AILERON SHROUD PNL	2504255 / 57-10-00-209 2503881 / 57-10-00-211 2504270 / 57-10-00-229	OPENED	N	B0143806 - Alejandro Cabani llas Feb 10, 2026 12:03 PM
			READYTOCLOSE	N	B1018546 - Andres Velazquez Feb 20, 2026 2:24 PM
			OKTOCLOSE	N	B0142244 - Todd Bridges Feb 20, 2026 4:56 PM
			CLOSED	N	B1018546 - Andres Velazquez Feb 20, 2026 5:24 PM
			INSPECTED	N	B0142244 - Todd Bridges Feb 20, 2026 5:39 PM
581DB	L/H WING LOWER FWD OUTBD FLAP FAIRING	2503820 / 57-ZL-00-218 2504267 / 57-10-00-228 2504291 / 57-50-00-211	OPENED	N	B1020176 - Matthew Doyle Feb 5, 2026 11:50 AM
			READYTOCLOSE	N	B1020176 - Matthew Doyle Feb 20, 2026 8:57 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 20, 2026 9:46 AM
			CLOSED	N	B1020176 - Matthew Doyle Feb 20, 2026 12:18 PM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 20, 2026 12:35 PM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
581DT	L/H WING UPPER MID OUTBD AILERON SHROUD PNL	2504255 / 57-10-00-209 2503881 / 57-10-00-211 2504270 / 57-10-00-229 2504256 / 57-10-00-213	OPENED	N	B0143806 - Alejandro Cabani llas Feb 10, 2026 12:03 PM
			READYTOCLOSE	N	B1018546 - Andres Velazquez Feb 20, 2026 2:24 PM
			OKTOCLOSE	N	B0142244 - Todd Bridges Feb 20, 2026 4:56 PM
			CLOSED	N	B1018546 - Andres Velazquez Feb 20, 2026 5:24 PM
			INSPECTED	N	B0142244 - Todd Bridges Feb 20, 2026 5:39 PM
581EB	L/H WING LOWER OUTBD FLAP ACT BUTE DOOR	2504297 / 57-70-00-206 2503881 / 57-10-00-211	OPENED	N	B0648431 - Caleb Sexton Feb 9, 2026 2:00 PM
			READYTOCLOSE	N	K1018275 - Emmanuel Cocoa Feb 19, 2026 12:01 PM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 19, 2026 12:18 PM
			CLOSED	N	K1018275 - Emmanuel Cocoa Feb 19, 2026 1:25 PM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 19, 2026 1:53 PM
581ET	L/H WING UPPER OUTBD AILERON SHROUD PNL	2504255 / 57-10-00-209 2503881 / 57-10-00-211 2504270 / 57-10-00-229 2504256 / 57-10-00-213	OPENED	N	B0143806 - Alejandro Cabani llas Feb 10, 2026 12:03 PM
			READYTOCLOSE	N	B1018546 - Andres Velazquez Feb 20, 2026 2:24 PM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
581ET	L/H WING UPPER OUTBD AILERON SHROUD PNL	2504255 / 57-10-00-209 2503881 / 57-10-00-211 2504270 / 57-10-00-229 2504256 / 57-10-00-213	OPENED	N	B0143806 - Alejandro Cabani llas Feb 10, 2026 12:03 PM
			OKTOCLOSE	N	B0142244 - Todd Bridges Feb 20, 2026 4:56 PM
			CLOSED	N	B1018546 - Andres Velazquez Feb 20, 2026 5:24 PM
			INSPECTED	N	B0142244 - Todd Bridges Feb 20, 2026 5:39 PM
581FB	L/H WING LOWER FWD OUTBD FLAP FAIRING	2503820 / 57-ZL-00-218 2504267 / 57-10-00-228 2504291 / 57-50-00-211	OPENED	N	B1020176 - Matthew Doyle Feb 5, 2026 11:51 AM
			READYTOCLOSE	N	B1020176 - Matthew Doyle Feb 20, 2026 8:57 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 20, 2026 9:46 AM
			CLOSED	N	B1020176 - Matthew Doyle Feb 20, 2026 12:19 PM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 20, 2026 12:35 PM
581GB	L/H WING LOWER OUTBD FLAP ACT BUTE DOOR	2504297 / 57-70-00-206 2503881 / 57-10-00-211	OPENED	N	B0648431 - Caleb Sexton Feb 9, 2026 2:00 PM
			READYTOCLOSE	N	B1018547 - Matthew Rossier Feb 19, 2026 2:27 PM
			OKTOCLOSE	N	B0623124 - Michael Stacy Feb 19, 2026 3:39 PM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
581GB	L/H WING LOWER OUTBD FLAP ACT BUTE DOOR	2504297 / 57-70-00-206 2503881 / 57-10-00-211	OPENED	N	B0648431 - Caleb Sexton Feb 9, 2026 2:00 PM
			CLOSED	N	B0638589 - Sean Dodder Feb 19, 2026 5:54 PM
			INSPECTED	N	B0623124 - Michael Stacy Feb 19, 2026 6:03 PM
581HB	L/H WING LOWER OUTBD AILERON SHROUD PNL	2504336 / REMOVE AILERONS 2504327 / INSTALL AILERONS 2504172 / 57-ZL-00-234 2504255 / 57-10-00-209 2503881 / 57-10-00-211 2504270 / 57-10-00-229 2504256 / 57-10-00-213	OPENED	N	B0642051 - Terry Walters Feb 5, 2026 7:46 AM
			READYTOCLOSE	N	B0650736 - Jesus Gonzalez A tondo Mar 5, 2026 9:17 AM
			OKTOCLOSE	N	B0142491 - George Ambrose Mar 5, 2026 12:12 PM
			CLOSED	N	B0650736 - Jesus Gonzalez A tondo Mar 5, 2026 2:01 PM
			INSPECTED	N	B1013522 - Brandon Jennings Mar 5, 2026 2:21 PM
584BB	L/H WING LOWER AFT OUTBD FLAP FAIRING	2503832 / 57-ZL-00-230 2504267 / 57-10-00-228 2504291 / 57-50-00-211 2504283 / 57-50-00-207	OPENED	N	B1020176 - Matthew Doyle Feb 5, 2026 11:51 AM
			READYTOCLOSE	N	B1020176 - Matthew Doyle Feb 20, 2026 8:57 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
584BB	L/H WING LOWER AFT OUTBD FLAP FAIRING	2503832 / 57-ZL-00-230 2504267 / 57-10-00-228 2504291 / 57-50-00-211 2504283 / 57-50-00-207	OPENED	N	B1020176 - Matthew Doyle Feb 5, 2026 11:51 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 20, 2026 9:46 AM
			CLOSED	N	B1020176 - Matthew Doyle Feb 20, 2026 12:19 PM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 20, 2026 12:35 PM
584DB	L/H WING LOWER AFT OUTBD FLAP FAIRING	2503832 / 57-ZL-00-230 2504267 / 57-10-00-228 2504291 / 57-50-00-211 2504283 / 57-50-00-207	OPENED	N	B1020176 - Matthew Doyle Feb 5, 2026 11:51 AM
			READYTOCLOSE	N	B1020176 - Matthew Doyle Feb 20, 2026 8:57 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 20, 2026 9:46 AM
			CLOSED	N	B1020176 - Matthew Doyle Feb 20, 2026 12:19 PM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 20, 2026 12:35 PM
584FB	L/H WING LOWER AFT OUTBD FLAP FAIRING	2503832 / 57-ZL-00-230 2504267 / 57-10-00-228 2504291 / 57-50-00-211 2504283 / 57-50-00-207	OPENED	N	B1020176 - Matthew Doyle Feb 5, 2026 11:51 AM
			READYTOCLOSE	N	B1020176 - Matthew Doyle Feb 20, 2026 8:57 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
584FB	L/H WING LOWER AFT OUTBD FLAP FAIRING	2503832 / 57-ZL-00-230 2504267 / 57-10-00-228 2504291 / 57-50-00-211 2504283 / 57-50-00-207	OPENED	N	B1020176 - Matthew Doyle Feb 5, 2026 11:51 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 20, 2026 9:46 AM
			CLOSED	N	B1020176 - Matthew Doyle Feb 20, 2026 12:19 PM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 20, 2026 12:35 PM
585AB	L/H WING LOWER OUTBD AILERON ACCESS PNL	2504336 / REMOVE AILERONS 2504327 / INSTALL AILERONS 2504270 / 57-10-00-229	OPENED	N	B0143806 - Alejandro Cabani llas Feb 10, 2026 9:02 AM
			READYTOCLOSE	N	B0650736 - Jesus Gonzalez A tondo Mar 5, 2026 9:17 AM
			OKTOCLOSE	N	B0142491 - George Ambrose Mar 5, 2026 12:11 PM
			CLOSED	N	B1022255 - Carson Chang Mar 5, 2026 12:36 PM
			INSPECTED	N	B0141354 - Karl Tuxhorn Mar 5, 2026 1:39 PM
585BB	L/H WING LOWER OUTBD AILERON ACCESS PNL	2504336 / REMOVE AILERONS 2504327 / INSTALL AILERONS 2504270 / 57-10-00-229	OPENED	N	K1018275 - Emmanuel Cocoa Feb 10, 2026 8:30 AM
			READYTOCLOSE	N	B0650736 - Jesus Gonzalez A tondo Mar 5, 2026 9:17 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
585BB	L/H WING LOWER OUTBD AILERON ACCESS PNL	2504336 / REMOVE AILERONS 2504327 / INSTALL AILERONS 2504270 / 57-10-00-229	OPENED	N	K1018275 - Emmanuel Cocoa Feb 10, 2026 8:30 AM
			OKTOCLOSE	N	B0142491 - George Ambrose Mar 5, 2026 12:11 PM
			CLOSED	N	B0650736 - Jesus Gonzalez A tondo Mar 5, 2026 12:32 PM
			INSPECTED	N	B0141354 - Karl Tuxhorn Mar 5, 2026 1:39 PM
585CB	L/H WING LOWER OUTBD AILERON ACCESS PNL	2504336 / REMOVE AILERONS 2504327 / INSTALL AILERONS 2504270 / 57-10-00-229	OPENED	N	B0143806 - Alejandro Cabani llas Feb 10, 2026 9:02 AM
			READYTOCLOSE	N	B0650736 - Jesus Gonzalez A tondo Mar 5, 2026 9:17 AM
			OKTOCLOSE	N	B0142491 - George Ambrose Mar 5, 2026 12:11 PM
			CLOSED	N	B0650736 - Jesus Gonzalez A tondo Mar 5, 2026 12:32 PM
			INSPECTED	N	B0141354 - Karl Tuxhorn Mar 5, 2026 1:39 PM
610AB	R/H LOWER STBY FUEL PUMP ACCESS PNL	2504154 / 57-ZL-00-205 2504246 / 57-10-00-202	OPENED	N	B0613291 - Eric Strong Feb 9, 2026 10:59 AM
			READYTOCLOSE	N	B0648431 - Caleb Sexton Feb 19, 2026 10:30 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
610AB	R/H LOWER STBY FUEL PUMP ACCESS PNL	2504154 / 57-ZL-00-205 2504246 / 57-10-00-202	OPENED	N	B0613291 - Eric Strong Feb 9, 2026 10:59 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 19, 2026 10:54 AM
			CLOSED	N	B0648431 - Caleb Sexton Feb 19, 2026 12:24 PM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 19, 2026 12:45 PM
610BB	R/H LOWER APU FUEL PUMP ACCESS PNL	2504154 / 57-ZL-00-205			
			N/A	N	B0142041 - Timothy Winfree Feb 20, 2026 10:28 AM
610CB	ACCESS PANEL	2504246 / 57-10-00-202	OPENED	N	B0613291 - Eric Strong Feb 9, 2026 10:59 AM
			READYTOCLOSE	N	B0648431 - Caleb Sexton Feb 19, 2026 10:30 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 19, 2026 10:54 AM
			CLOSED	N	B0648431 - Caleb Sexton Feb 19, 2026 12:24 PM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 19, 2026 12:45 PM
620AB	R/H WING LOWER TAXI/LDG LIGHT ACCESS PNL	2504159 / 57-ZL-00-209	OPENED	N	B0142041 - Timothy Winfree Feb 6, 2026 7:03 AM
			READYTOCLOSE	N	B0648431 - Caleb Sexton Mar 4, 2026 8:43 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
620AB	R/H WING LOWER TAXI/LDG LIGHT ACCESS PNL	2504159 / 57-ZL-00-209	OPENED	N	B0142041 - Timothy Winfree Feb 6, 2026 7:03 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Mar 4, 2026 9:09 AM
			CLOSED	N	B0648431 - Caleb Sexton Mar 4, 2026 10:05 AM
			INSPECTED	N	B1013522 - Brandon Jennings Mar 4, 2026 10:26 AM
620AT	R/H WING INBD L/EDGE	2504159 / 57-ZL-00-209 2504251 / 57-10-00-208	OPENED	N	B1017711 - Isaac Ramirez Feb 4, 2026 2:13 PM
			READYTOCLOSE	N	B0642051 - Terry Walters Feb 19, 2026 10:53 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 19, 2026 12:15 PM
			CLOSED	N	B0642051 - Terry Walters Feb 19, 2026 12:49 PM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 19, 2026 2:21 PM
620AZ	R/H WING INBD L/EDGE WS82 ACCESS PNL	2504159 / 57-ZL-00-209	OPENED	N	B0648431 - Caleb Sexton Feb 5, 2026 1:53 PM
			READYTOCLOSE	N	B1020176 - Matthew Doyle Feb 18, 2026 6:48 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 18, 2026 8:26 AM
			CLOSED	N	B0642051 - Terry Walters Feb 18, 2026 9:35 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
620AZ	R/H WING INBD L/EDGE WS82 ACCESS PNL	2504159 / 57-ZL-00-209	OPENED	N	B0648431 - Caleb Sexton Feb 5, 2026 1:53 PM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 19, 2026 7:00 AM
620BL	R/H WING INBD L/EDGE	2504159 / 57-ZL-00-209 2504251 / 57-10-00-208	OPENED	N	B0646266 - Sergio Rodriguez Figueroa Feb 10, 2026 6:33 AM
			READYTOCLOSE	N	B1020176 - Matthew Doyle Feb 19, 2026 6:46 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 19, 2026 7:02 AM
			CLOSED	N	B1020176 - Matthew Doyle Feb 19, 2026 8:38 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 19, 2026 12:14 PM
620BZ	R/H WING INBD L/EDGE WS98 ACCESS PNL	2504159 / 57-ZL-00-209	OPENED	N	B0648431 - Caleb Sexton Feb 5, 2026 1:53 PM
			READYTOCLOSE	N	B1020176 - Matthew Doyle Feb 18, 2026 6:48 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 18, 2026 8:26 AM
			CLOSED	N	B0642051 - Terry Walters Feb 18, 2026 9:35 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 19, 2026 7:00 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
620CZ	R/H WING INBD L/EDGE WS114 ACCESS PNL	2504159 / 57-ZL-00-209	OPENED	N	B0648431 - Caleb Sexton Feb 5, 2026 1:53 PM
			READYTOCLOSE	N	B1020176 - Matthew Doyle Feb 18, 2026 6:48 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 18, 2026 8:26 AM
			CLOSED	N	B0642051 - Terry Walters Feb 18, 2026 9:35 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 19, 2026 7:00 AM
620DZ	R/H WING INBD L/EDGE WS129 ACCESS PNL	2504159 / 57-ZL-00-209	OPENED	N	B0648431 - Caleb Sexton Feb 5, 2026 1:53 PM
			READYTOCLOSE	N	B1020176 - Matthew Doyle Feb 18, 2026 6:48 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 18, 2026 8:26 AM
			CLOSED	N	B0642051 - Terry Walters Feb 18, 2026 9:35 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 19, 2026 7:00 AM
620EL	R/H WING TRANSITION L/EDGE	2504161 / 57-ZL-00-213 2504159 / 57-ZL-00-209 2504251 / 57-10-00-208	OPENED	N	B1017711 - Isaac Ramirez Feb 4, 2026 2:15 PM
			READYTOCLOSE	N	B0642051 - Terry Walters Feb 19, 2026 10:53 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 19, 2026 12:15 PM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
620EL	R/H WING TRANSITION L/EDGE	2504161 / 57-ZL-00-213 2504159 / 57-ZL-00-209 2504251 / 57-10-00-208	OPENED	N	B1017711 - Isaac Ramirez Feb 4, 2026 2:15 PM
			CLOSED	N	B0642051 - Terry Walters Feb 19, 2026 12:49 PM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 19, 2026 2:21 PM
630AZ	R/H WING MID L/EDGE WS165 ACCESS PNL	2504161 / 57-ZL-00-213	OPENED	N	B0142041 - Timothy Winfree Feb 6, 2026 3:14 PM
			READYTOCLOSE	N	B1020176 - Matthew Doyle Feb 18, 2026 6:47 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 18, 2026 8:27 AM
			CLOSED	N	B0642051 - Terry Walters Feb 18, 2026 9:35 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 19, 2026 7:00 AM
630BL	R/H WING MIDDLE L/EDGE	2504161 / 57-ZL-00-213 2504251 / 57-10-00-208	OPENED	N	B0646266 - Sergio Rodriguez Figueroa Feb 10, 2026 6:35 AM
			READYTOCLOSE	N	B1020176 - Matthew Doyle Feb 19, 2026 6:46 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 19, 2026 7:02 AM
			CLOSED	N	B1020176 - Matthew Doyle Feb 19, 2026 8:38 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
630BL	R/H WING MIDDLE L/EDGE	2504161 / 57-ZL-00-213 2504251 / 57-10-00-208	OPENED	N	B0646266 - Sergio Rodriguez Figueroa Feb 10, 2026 6:35 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 19, 2026 12:14 PM
630BZ	R/H WING MID L/EDGE WS183 ACCESS PNL	2504161 / 57-ZL-00-213	OPENED	N	B0142041 - Timothy Winfree Feb 6, 2026 3:14 PM
			READYTOCLOSE	N	B1020176 - Matthew Doyle Feb 18, 2026 6:47 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 18, 2026 8:27 AM
			CLOSED	N	B0642051 - Terry Walters Feb 18, 2026 9:35 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 19, 2026 7:00 AM
630CL	R/H WING L/EDGE	2504161 / 57-ZL-00-213 2504251 / 57-10-00-208	OPENED	N	B1017711 - Isaac Ramirez Feb 4, 2026 2:14 PM
			READYTOCLOSE	N	B0642051 - Terry Walters Feb 19, 2026 10:53 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 19, 2026 12:15 PM
			CLOSED	N	B0642051 - Terry Walters Feb 19, 2026 12:49 PM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 19, 2026 2:21 PM

Bombardier

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
630CZ	R/H WING MID L/EDGE WS201 ACCESS PNL	2504161 / 57-ZL-00-213	OPENED	N	B0142041 - Timothy Winfree Feb 6, 2026 3:14 PM
			READYTOCLOSE	N	B1020176 - Matthew Doyle Feb 18, 2026 6:47 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 18, 2026 8:27 AM
			CLOSED	N	B0642051 - Terry Walters Feb 18, 2026 9:35 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 19, 2026 7:00 AM
630DL	R/H WING OUTBD L/EDGE	2504161 / 57-ZL-00-213 2504251 / 57-10-00-208	OPENED	N	B1017711 - Isaac Ramirez Feb 4, 2026 2:16 PM
			READYTOCLOSE	N	B1020176 - Matthew Doyle Feb 19, 2026 6:46 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 19, 2026 7:02 AM
			CLOSED	N	B1020176 - Matthew Doyle Feb 19, 2026 8:38 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 19, 2026 12:14 PM
630DZ	R/H WING MID L/EDGE WS218 ACCESS PNL	2504161 / 57-ZL-00-213	OPENED	N	B0142041 - Timothy Winfree Feb 6, 2026 3:14 PM
			READYTOCLOSE	N	B1020176 - Matthew Doyle Feb 18, 2026 6:47 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 18, 2026 8:27 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
630DZ	R/H WING MID L/EDGE WS218 ACCESS PNL	2504161 / 57-ZL-00-213	OPENED	N	B0142041 - Timothy Winfree Feb 6, 2026 3:14 PM
			CLOSED	N	B0642051 - Terry Walters Feb 18, 2026 9:35 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 19, 2026 7:00 AM
630EZ	R/H WING MID L/EDGE WS235 ACCESS PNL	2504161 / 57-ZL-00-213	OPENED	N	B0142041 - Timothy Winfree Feb 6, 2026 3:14 PM
			READYTOCLOSE	N	B1020176 - Matthew Doyle Feb 18, 2026 6:47 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 18, 2026 8:27 AM
			CLOSED	N	B0642051 - Terry Walters Feb 18, 2026 9:35 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 19, 2026 7:00 AM
630FZ	R/H WING OUTBD L/EDGE WS267 ACCESS PNL	2504161 / 57-ZL-00-213	OPENED	N	B0142041 - Timothy Winfree Feb 6, 2026 3:14 PM
			READYTOCLOSE	N	B1020176 - Matthew Doyle Feb 18, 2026 6:37 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 18, 2026 8:27 AM
			CLOSED	N	B0642051 - Terry Walters Feb 18, 2026 9:35 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 19, 2026 7:00 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
630GZ	R/H WING OUTBD L/EDGE WS285 ACCESS PNL	2504161 / 57-ZL-00-213	OPENED	N	B0142041 - Timothy Winfree Feb 6, 2026 3:14 PM
			READYTOCLOSE	N	B1020176 - Matthew Doyle Feb 18, 2026 6:38 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 18, 2026 8:27 AM
			CLOSED	N	B0642051 - Terry Walters Feb 18, 2026 9:35 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 19, 2026 7:00 AM
630HZ	R/H WING OUTBD L/EDGE WS300 ACCESS PNL	2504161 / 57-ZL-00-213	OPENED	N	B0142041 - Timothy Winfree Feb 6, 2026 3:15 PM
			READYTOCLOSE	N	B1020176 - Matthew Doyle Feb 18, 2026 6:38 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 18, 2026 8:27 AM
			CLOSED	N	B0642051 - Terry Walters Feb 18, 2026 9:35 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 19, 2026 7:00 AM
630JZ	R/H WING OUTBD L/EDGE WS320 ACCESS PNL	2504161 / 57-ZL-00-213	OPENED	N	B0142041 - Timothy Winfree Feb 6, 2026 3:15 PM
			READYTOCLOSE	N	B1020176 - Matthew Doyle Feb 18, 2026 6:38 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 18, 2026 8:27 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
630JZ	R/H WING OUTBD L/EDGE WS320 ACCESS PNL	2504161 / 57-ZL-00-213	OPENED	N	B0142041 - Timothy Winfree Feb 6, 2026 3:15 PM
			CLOSED	N	B0642051 - Terry Walters Feb 18, 2026 9:35 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 19, 2026 7:00 AM
630KZ	R/H WING OUTBD L/EDGE WS338 ACCESS PNL	2504161 / 57-ZL-00-213	OPENED	N	B0142041 - Timothy Winfree Feb 6, 2026 3:15 PM
			READYTOCLOSE	N	B1020176 - Matthew Doyle Feb 18, 2026 6:38 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 18, 2026 8:27 AM
			CLOSED	N	B0642051 - Terry Walters Feb 18, 2026 9:35 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 19, 2026 7:00 AM
631SB	Aileron Control, Access Panel				
			N/A	N	B0162034 - Tyler Poggi Feb 10, 2026 3:44 PM
640AB	R/H WING LOWER INBD FUEL ACCESS PNL	2504166 / 57-ZL-00-217 2504255 / 57-10-00-209	OPENED	N	B0613291 - Eric Strong Feb 9, 2026 10:38 AM
			READYTOCLOSE	N	B1018547 - Matthew Rossier Feb 27, 2026 3:45 PM
			OKTOCLOSE	N	B0161691 - Thomas Mitchell Feb 27, 2026 4:17 PM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
640AB	R/H WING LOWER INBD FUEL ACCESS PNL	2504166 / 57-ZL-00-217 2504255 / 57-10-00-209	OPENED	N	B0613291 - Eric Strong Feb 9, 2026 10:38 AM
			CLOSED	N	B1018547 - Matthew Rossier Feb 27, 2026 4:36 PM
			INSPECTED	N	B0161691 - Thomas Mitchell Feb 27, 2026 5:42 PM
640BB	R/H WING LOWER INBD FUEL ACCESS PNL	2504166 / 57-ZL-00-217 2504255 / 57-10-00-209	OPENED	N	B0613291 - Eric Strong Feb 9, 2026 10:59 AM
			READYTOCLOSE	N	B0648431 - Caleb Sexton Feb 19, 2026 10:30 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 19, 2026 10:54 AM
			CLOSED	N	B0648431 - Caleb Sexton Feb 19, 2026 12:24 PM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 19, 2026 12:45 PM
640CB	R/H WING LOWER INBD FUEL ACCESS PNL	2504166 / 57-ZL-00-217 2504255 / 57-10-00-209	OPENED	N	B0613291 - Eric Strong Feb 9, 2026 10:59 AM
			READYTOCLOSE	N	B1016542 - Carlos Ochoa Feb 18, 2026 6:31 PM
			OKTOCLOSE	N	B0623124 - Michael Stacy Feb 18, 2026 8:23 PM
			CLOSED	N	B1016542 - Carlos Ochoa Feb 18, 2026 9:09 PM
			INSPECTED	N	B0623124 - Michael Stacy Feb 18, 2026 9:23 PM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
640DB	R/H WING LOWER INBD FUEL ACCESS PNL	2504166 / 57-ZL-00-217 2504255 / 57-10-00-209	OPENED	N	B0613291 - Eric Strong Feb 9, 2026 6:44 AM
			READYTOCLOSE	N	B1016542 - Carlos Ochoa Feb 18, 2026 6:31 PM
			OKTOCLOSE	N	B0623124 - Michael Stacy Feb 18, 2026 8:23 PM
			CLOSED	N	B1016542 - Carlos Ochoa Feb 18, 2026 9:09 PM
			INSPECTED	N	B0623124 - Michael Stacy Feb 18, 2026 9:23 PM
640EB	R/H WING LOWER INBD FUEL ACCESS PNL	2504166 / 57-ZL-00-217 2504255 / 57-10-00-209	OPENED	N	B0613291 - Eric Strong Feb 8, 2026 4:55 PM
			READYTOCLOSE	N	B1016542 - Carlos Ochoa Feb 18, 2026 6:31 PM
			OKTOCLOSE	N	B0623124 - Michael Stacy Feb 18, 2026 8:23 PM
			CLOSED	N	B1016542 - Carlos Ochoa Feb 18, 2026 9:09 PM
			INSPECTED	N	B0623124 - Michael Stacy Feb 18, 2026 9:23 PM
640FB	R/H WING LOWER INBD FUEL ACCESS PNL	2504166 / 57-ZL-00-217 2504255 / 57-10-00-209	OPENED	N	B0178935 - Stephen Lodge Feb 6, 2026 9:40 AM
			READYTOCLOSE	N	B0648431 - Caleb Sexton Feb 19, 2026 7:51 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 19, 2026 8:44 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
640FB	R/H WING LOWER INBD FUEL ACCESS PNL	2504166 / 57-ZL-00-217 2504255 / 57-10-00-209	OPENED	N	B0178935 - Stephen Lodge Feb 6, 2026 9:40 AM
			CLOSED	N	B0648431 - Caleb Sexton Feb 19, 2026 9:51 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 19, 2026 9:56 AM
641AT	R/H WING UPPER ACCESS PNL	2504166 / 57-ZL-00-217 2504255 / 57-10-00-209 2503885 / 57-10-00-217 2503881 / 57-10-00-211	OPENED	N	B0650736 - Jesus Gonzalez A tondo Feb 9, 2026 1:34 PM
			READYTOCLOSE	N	B1018546 - Andres Velazquez Feb 20, 2026 10:17 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 20, 2026 12:07 PM
			CLOSED	N	B1018546 - Andres Velazquez Feb 20, 2026 12:15 PM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 20, 2026 12:33 PM
650AB	R/H WING LOWER MID FUEL ACCESS PNL	2504171 / 57-ZL-00-221 2504255 / 57-10-00-209	OPENED	N	B0178935 - Stephen Lodge Feb 6, 2026 9:43 AM
			READYTOCLOSE	N	B0648431 - Caleb Sexton Feb 19, 2026 7:51 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 19, 2026 8:44 AM
			CLOSED	N	B0648431 - Caleb Sexton Feb 19, 2026 9:27 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
650AB	R/H WING LOWER MID FUEL ACCESS PNL	2504171 / 57-ZL-00-221 2504255 / 57-10-00-209	OPENED	N	B0178935 - Stephen Lodge Feb 6, 2026 9:43 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 19, 2026 9:56 AM
650AT	R/H WING UPPER OUTBD ACCESS PNL	2504255 / 57-10-00-209 2504256 / 57-10-00-213			
			N/A	N	B0142041 - Timothy Winfree Feb 20, 2026 10:19 AM
650BB	R/H WING LOWER MID FUEL ACCESS PNL	2504171 / 57-ZL-00-221 2504255 / 57-10-00-209	OPENED	N	B1020176 - Matthew Doyle Feb 4, 2026 12:40 PM
			READYTOCLOSE	N	B0648431 - Caleb Sexton Feb 19, 2026 7:51 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 19, 2026 8:44 AM
			CLOSED	N	B0648431 - Caleb Sexton Feb 19, 2026 9:27 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 19, 2026 9:56 AM
650CB	R/H WING LOWER MID FUEL ACCESS PNL	2504171 / 57-ZL-00-221 2504255 / 57-10-00-209	OPENED	N	B0178935 - Stephen Lodge Feb 6, 2026 9:43 AM
			READYTOCLOSE	N	B0648431 - Caleb Sexton Feb 19, 2026 7:51 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 19, 2026 8:44 AM
			CLOSED	N	B0648431 - Caleb Sexton Feb 19, 2026 9:27 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
650CB	R/H WING LOWER MID FUEL ACCESS PNL	2504171 / 57-ZL-00-221 2504255 / 57-10-00-209	OPENED	N	B0178935 - Stephen Lodge Feb 6, 2026 9:43 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 19, 2026 9:56 AM
650DB	R/H WING LOWER MID FUEL ACCESS PNL	2504171 / 57-ZL-00-221 2504255 / 57-10-00-209	OPENED	N	B0178935 - Stephen Lodge Feb 6, 2026 9:43 AM
			READYTOCLOSE	N	B0648431 - Caleb Sexton Feb 19, 2026 7:51 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 19, 2026 8:44 AM
			CLOSED	N	B0648431 - Caleb Sexton Feb 19, 2026 9:27 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 19, 2026 9:56 AM
650DT	R/H WING UPPER OUTBD ACCESS PNL	3154421 / ACCESS-OPEN	OPENED	N	B0143806 - Alejandro Cabani llas Feb 10, 2026 12:10 PM
			READYTOCLOSE	N	B1016542 - Carlos Ochoa Feb 19, 2026 8:29 PM
			OKTOCLOSE	N	B0142491 - George Ambrose Mar 5, 2026 12:15 PM
			CLOSED	N	B1022275 - Kaitlynn Maxon Mar 5, 2026 12:35 PM
			INSPECTED	N	B1013522 - Brandon Jennings Mar 5, 2026 2:24 PM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
650EB	R/H WING LOWER OUTBD FUEL ACCESS PNL	2504171 / 57-ZL-00-221 2504255 / 57-10-00-209	OPENED	N	B0178935 - Stephen Lodge Feb 6, 2026 9:43 AM
			READYTOCLOSE	N	B0648431 - Caleb Sexton Feb 19, 2026 7:51 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 19, 2026 8:44 AM
			CLOSED	N	B0648431 - Caleb Sexton Feb 19, 2026 9:27 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 19, 2026 9:56 AM
650FB	R/H WING LOWER OUTBD FUEL ACCESS PNL	2504171 / 57-ZL-00-221 2504255 / 57-10-00-209	OPENED	N	B0178935 - Stephen Lodge Feb 6, 2026 9:43 AM
			READYTOCLOSE	N	B0646275 - Hector Amaya Jr Feb 18, 2026 6:39 PM
			OKTOCLOSE	N	B0623124 - Michael Stacy Feb 18, 2026 8:23 PM
			CLOSED	N	B0646275 - Hector Amaya Jr Feb 18, 2026 9:09 PM
			INSPECTED	N	B0623124 - Michael Stacy Feb 18, 2026 9:23 PM
650GB	R/H WING LOWER OUTBD FUEL ACCESS PNL	2504171 / 57-ZL-00-221 2504255 / 57-10-00-209	OPENED	N	B0178935 - Stephen Lodge Feb 6, 2026 9:43 AM
			READYTOCLOSE	N	B0646275 - Hector Amaya Jr Feb 18, 2026 6:39 PM
			OKTOCLOSE	N	B0623124 - Michael Stacy Feb 18, 2026 8:23 PM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
650GB	R/H WING LOWER OUTBD FUEL ACCESS PNL	2504171 / 57-ZL-00-221 2504255 / 57-10-00-209	OPENED	N	B0178935 - Stephen Lodge Feb 6, 2026 9:43 AM
			CLOSED	N	B0646275 - Hector Amaya Jr Feb 18, 2026 9:09 PM
			INSPECTED	N	B0623124 - Michael Stacy Feb 18, 2026 9:23 PM
650HB	R/H WING LOWER OUTBD FUEL ACCESS PNL	2504171 / 57-ZL-00-221 2504255 / 57-10-00-209	OPENED	N	B0178935 - Stephen Lodge Feb 6, 2026 9:43 AM
			READYTOCLOSE	N	B0646275 - Hector Amaya Jr Feb 18, 2026 6:39 PM
			OKTOCLOSE	N	B0623124 - Michael Stacy Feb 18, 2026 8:23 PM
			CLOSED	N	B0646275 - Hector Amaya Jr Feb 18, 2026 9:09 PM
			INSPECTED	N	B0623124 - Michael Stacy Feb 18, 2026 9:23 PM
650JB	R/H WING LOWER OUTBD FUEL ACCESS PNL	2504171 / 57-ZL-00-221 2504256 / 57-10-00-213	OPENED	N	B0646266 - Sergio Rodriguez Figueroa Feb 10, 2026 7:36 AM
			READYTOCLOSE	N	B0580384 - Patrick Arceneau x Feb 19, 2026 4:31 PM
			OKTOCLOSE	N	B0623124 - Michael Stacy Feb 19, 2026 4:41 PM
			CLOSED	N	B0580384 - Patrick Arceneau x Feb 19, 2026 6:18 PM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
650JB	R/H WING LOWER OUTBD FUEL ACCESS PNL	2504171 / 57-ZL-00-221 2504256 / 57-10-00-213	OPENED	N	B0646266 - Sergio Rodriguez Figueroa Feb 10, 2026 7:36 AM
			INSPECTED	N	B0623124 - Michael Stacy Feb 19, 2026 6:28 PM
650KB	R/H WING LOWER OUTBD PCU ACCESS PNL	2503869 / 27-00-00-209 2504171 / 57-ZL-00-221 2504256 / 57-10-00-213	OPENED	N	B1020176 - Matthew Doyle Feb 4, 2026 12:47 PM
			READYTOCLOSE	N	B0650736 - Jesus Gonzalez A tondo Mar 5, 2026 9:17 AM
			OKTOCLOSE	N	B0142491 - George Ambrose Mar 5, 2026 12:14 PM
			CLOSED	N	B1022275 - Kaitlynn Maxon Mar 5, 2026 12:36 PM
			INSPECTED	N	B1013522 - Brandon Jennings Mar 5, 2026 2:23 PM
650LB	R/H WING LOWER OUTBD ACCESS PNL	2504171 / 57-ZL-00-221	OPENED	N	B1020176 - Matthew Doyle Feb 4, 2026 12:40 PM
			READYTOCLOSE	N	B1018547 - Matthew Rossier Feb 27, 2026 5:26 PM
			OKTOCLOSE	N	B0161691 - Thomas Mitchell Feb 27, 2026 6:08 PM
			CLOSED	N	B1018547 - Matthew Rossier Feb 27, 2026 6:57 PM
			INSPECTED	N	B0161691 - Thomas Mitchell Feb 27, 2026 7:45 PM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
650MB	R/H WING LOWER OUTBD ACCESS PNL	2503869 / 27-00-00-209			
			N/A	N	B0142041 - Timothy Winfree Feb 20, 2026 10:27 AM
651DB	Aileron Gear Tab Fairing				
			N/A	N	B1014141 - Christopher Draw dy Feb 11, 2026 8:19 AM
654AB	Trailing Edge, Access Panel				
			N/A	N	B1014141 - Christopher Draw dy Feb 11, 2026 8:19 AM
660AB	ACCESS PANEL	2504279 / 57-30-00-201	OPENED	N	K1018275 - Emmanuel Cocoa Feb 10, 2026 12:41 PM
			READYTOCLOSE	N	B0580384 - Patrick Arceneau x Feb 19, 2026 4:31 PM
			OKTOCLOSE	N	B0623124 - Michael Stacy Feb 19, 2026 4:41 PM
			CLOSED	N	B0580384 - Patrick Arceneau x Feb 19, 2026 6:18 PM
			INSPECTED	N	B0623124 - Michael Stacy Feb 19, 2026 6:28 PM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
660AL	R/H WING NAV LIGHT LENS	2504279 / 57-30-00-201 2504256 / 57-10-00-213	OPENED	N	B0646266 - Sergio Rodriguez Figueroa Feb 10, 2026 8:57 AM
660BB	R/H WING LOWER OUTBD ACCESS PNL	2504279 / 57-30-00-201 2504256 / 57-10-00-213	OPENED	N	B0646266 - Sergio Rodriguez Figueroa Feb 10, 2026 10:32 AM
			READYTOCLOSE	N	B0580384 - Patrick Arceneau x Feb 19, 2026 4:31 PM
			OKTOCLOSE	N	B0623124 - Michael Stacy Feb 19, 2026 4:41 PM
			CLOSED	N	B0580384 - Patrick Arceneau x Feb 19, 2026 6:18 PM
			INSPECTED	N	B0623124 - Michael Stacy Feb 19, 2026 6:28 PM
660DB	R/H WING LOWER WING TO WINGLET FAIRING	2504279 / 57-30-00-201	OPENED	N	K1018275 - Emmanuel Cocoa Feb 10, 2026 2:12 PM
			READYTOCLOSE	N	B0580384 - Patrick Arceneau x Feb 19, 2026 4:31 PM
			OKTOCLOSE	N	B0623124 - Michael Stacy Feb 19, 2026 4:41 PM
			CLOSED	N	B0580384 - Patrick Arceneau x Feb 19, 2026 6:18 PM
			INSPECTED	N	B0623124 - Michael Stacy Feb 19, 2026 6:28 PM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
671AB	R/H WING LOWER FWD INBD FLAP FAIRING	2503831 / 57-ZL-00-227 2503819 / 57-ZL-00-215 2504264 / 57-10-00-227 2504288 / 57-50-00-210	OPENED	N	B0646266 - Sergio Rodriguez Figueroa Feb 9, 2026 1:27 PM
			READYTOCLOSE	N	B1020176 - Matthew Doyle Feb 20, 2026 6:32 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Mar 4, 2026 9:00 AM
			CLOSED	N	B1021822 - Joseph Cuoco Mar 4, 2026 9:29 AM
			INSPECTED	N	B1013522 - Brandon Jennings Mar 4, 2026 9:44 AM
671BB	R/H WING LOWER INBD ACCESS PNL	2504166 / 57-ZL-00-217 2504255 / 57-10-00-209 2503885 / 57-10-00-217 2503881 / 57-10-00-211	OPENED	N	B0648431 - Caleb Sexton Feb 5, 2026 9:55 AM
			READYTOCLOSE	N	B1018409 - Areida Cruz Feb 20, 2026 4:50 PM
			OKTOCLOSE	N	B0623124 - Michael Stacy Feb 20, 2026 4:54 PM
671CB	R/H WING LOWER INBD ACCESS PNL	2504166 / 57-ZL-00-217 2504255 / 57-10-00-209 2503885 / 57-10-00-217 2503881 / 57-10-00-211	OPENED	N	B0648431 - Caleb Sexton Feb 5, 2026 9:55 AM
			READYTOCLOSE	N	B1018409 - Areida Cruz Feb 20, 2026 4:50 PM
			OKTOCLOSE	N	B0623124 - Michael Stacy Feb 20, 2026 4:54 PM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
671CB	R/H WING LOWER INBD ACCESS PNL	2504166 / 57-ZL-00-217 2504255 / 57-10-00-209 2503885 / 57-10-00-217 2503881 / 57-10-00-211	OPENED	N	B0648431 - Caleb Sexton Feb 5, 2026 9:55 AM
			CLOSED	N	B1018409 - Areida Cruz Feb 21, 2026 6:21 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 26, 2026 10:12 AM
671DB	R/H WING LOWER INBD ACCESS PNL	2504166 / 57-ZL-00-217 2504255 / 57-10-00-209 2503885 / 57-10-00-217 2503881 / 57-10-00-211	OPENED	N	B0648431 - Caleb Sexton Feb 5, 2026 9:55 AM
			READYTOCLOSE	N	B1018409 - Areida Cruz Feb 20, 2026 4:50 PM
			OKTOCLOSE	N	B0623124 - Michael Stacy Feb 20, 2026 4:54 PM
			CLOSED	N	B1018409 - Areida Cruz Feb 21, 2026 6:21 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 26, 2026 10:12 AM
671EB	R/H WING LOWER FWD INBD FLAP FAIRING	2503831 / 57-ZL-00-227 2503819 / 57-ZL-00-215 2504264 / 57-10-00-227 2504288 / 57-50-00-210	OPENED	N	B0646266 - Sergio Rodriguez Figueroa Feb 9, 2026 12:26 PM
			READYTOCLOSE	N	B1020176 - Matthew Doyle Feb 20, 2026 6:32 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 20, 2026 7:14 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
671EB	R/H WING LOWER FWD INBD FLAP FAIRING	2503831 / 57-ZL-00-227 2503819 / 57-ZL-00-215 2504264 / 57-10-00-227 2504288 / 57-50-00-210	OPENED	N	B0646266 - Sergio Rodriguez Figueroa Feb 9, 2026 12:26 PM
			CLOSED	N	B1020176 - Matthew Doyle Feb 20, 2026 8:51 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 20, 2026 9:42 AM
672DB	R/H WING LOWER AFT INBD FLAP FAIRING	2504199 / 22-12-00-210 2503831 / 57-ZL-00-227 2503819 / 57-ZL-00-215 2504264 / 57-10-00-227 2504288 / 57-50-00-210 2504279 / 57-30-00-201	OPENED	N	B0646266 - Sergio Rodriguez Figueroa Feb 9, 2026 1:27 PM
			READYTOCLOSE	N	B1020176 - Matthew Doyle Feb 20, 2026 6:32 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Mar 4, 2026 9:00 AM
			CLOSED	N	B1021822 - Joseph Cuoco Mar 4, 2026 9:29 AM
			INSPECTED	N	B1013522 - Brandon Jennings Mar 4, 2026 9:44 AM
672GB	R/H WING LOWER AFT INBD FLAP FAIRING	2503831 / 57-ZL-00-227 2503819 / 57-ZL-00-215 2504264 / 57-10-00-227 2504288 / 57-50-00-210 2504279 / 57-30-00-201	OPENED	N	B0646266 - Sergio Rodriguez Figueroa Feb 9, 2026 12:26 PM
			READYTOCLOSE	N	B1020176 - Matthew Doyle Feb 20, 2026 6:32 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
672GB	R/H WING LOWER AFT INBD FLAP FAIRING	2503831 / 57-ZL-00-227 2503819 / 57-ZL-00-215 2504264 / 57-10-00-227 2504288 / 57-50-00-210 2504279 / 57-30-00-201	OPENED	N	B0646266 - Sergio Rodriguez Figueroa Feb 9, 2026 12:26 PM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 20, 2026 7:14 AM
			CLOSED	N	B1020176 - Matthew Doyle Feb 20, 2026 8:51 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 20, 2026 9:42 AM
673AB	Inboard Flap Fairing, Leading Edge				
			N/A	N	B1014141 - Christopher Draw dy Feb 11, 2026 7:53 AM
673BB	Inboard Flap Fairing				
			N/A	N	B1014141 - Christopher Draw dy Feb 11, 2026 7:53 AM
673BL	Inboard, Flap Fairing, Access Panel				
			N/A	N	B1014141 - Christopher Draw dy Feb 11, 2026 7:53 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
673BR	Inboard, Flap Fairing, Access Panel				
			N/A	N	B1014141 - Christopher Draw dy Feb 11, 2026 7:53 AM
673CB	Inboard Flap Fairing, Trailing Edge				
			N/A	N	B1014141 - Christopher Draw dy Feb 11, 2026 7:53 AM
674AB	Middle Flap Fairing, Leading Edge				
			N/A	N	B1014141 - Christopher Draw dy Feb 11, 2026 7:54 AM
674BB	Middle Flap Fairing				
			N/A	N	B1014141 - Christopher Draw dy Feb 11, 2026 7:54 AM
674BL	Middle, Flap Fairing, Access Panel				
			N/A	N	B1014141 - Christopher Draw dy Feb 11, 2026 7:54 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
674BR	Middle, Flap Fairing, Access Panel				
			N/A	N	B1014141 - Christopher Draw dy Feb 11, 2026 7:54 AM
674CB	Middle Flap Fairing, Trailing Edge				
			N/A	N	B1014141 - Christopher Draw dy Feb 11, 2026 7:54 AM
675AB	Outboard Flap Fairing, Leading Edge				
			N/A	N	B1014141 - Christopher Draw dy Feb 11, 2026 7:54 AM
675BB	Outboard Flap Fairing				
			N/A	N	B1014141 - Christopher Draw dy Feb 11, 2026 7:54 AM
675BL	Outboard, Flap Fairing, Access Panel				
			N/A	N	B1014141 - Christopher Draw dy Feb 11, 2026 7:54 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
675BR	Outboard, Flap Fairing, Access Panel				
			N/A	N	B1014141 - Christopher Draw dy Feb 11, 2026 7:54 AM
675CB	Outboard Flap Fairing, Trailing Edge				
			N/A	N	B1014141 - Christopher Draw dy Feb 11, 2026 7:54 AM
681AB	R/H WING LOWER OUTBD FLAP ACT BUTE DOOR	2504297 / 57-70-00-206 2503881 / 57-10-00-211	OPENED	N	B1020712 - Kenneth Swarts Feb 9, 2026 1:56 PM
			READYTOCLOSE	N	K1018275 - Emmanuel Cocoa Feb 19, 2026 6:56 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 19, 2026 7:23 AM
			CLOSED	N	K1018275 - Emmanuel Cocoa Feb 19, 2026 9:45 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 19, 2026 9:58 AM
681AT	R/H WING UPPER ACCESS PNL	2504297 / 57-70-00-206 2503881 / 57-10-00-211	OPENED	N	B1020176 - Matthew Doyle Feb 4, 2026 1:08 PM
			READYTOCLOSE	N	K1018275 - Emmanuel Cocoa Feb 19, 2026 10:25 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 19, 2026 10:52 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
681AT	R/H WING UPPER ACCESS PNL	2504297 / 57-70-00-206 2503881 / 57-10-00-211	OPENED	N	B1020176 - Matthew Doyle Feb 4, 2026 1:08 PM
			CLOSED	N	K1018275 - Emmanuel Cocoa Feb 19, 2026 12:21 PM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 19, 2026 12:22 PM
681BB	R/H WING LOWER FWD OUTBD FLAP FAIRING	2503824 / 57-ZL-00-219 2504267 / 57-10-00-228 2504291 / 57-50-00-211	OPENED	N	B1020176 - Matthew Doyle Feb 6, 2026 7:28 AM
			READYTOCLOSE	N	B1020176 - Matthew Doyle Feb 20, 2026 6:30 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 20, 2026 7:14 AM
			CLOSED	N	B1020176 - Matthew Doyle Feb 20, 2026 8:50 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 20, 2026 9:42 AM
681BT	R/H WING UPPER INBD AILERON SHROUD PNL	2504255 / 57-10-00-209 2503881 / 57-10-00-211 2504270 / 57-10-00-229	OPENED	N	B0143806 - Alejandro Cabani llas Feb 10, 2026 12:03 PM
			READYTOCLOSE	N	B1002512 - Brandon Warne Feb 20, 2026 10:49 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 20, 2026 12:08 PM
			CLOSED	N	B1002512 - Brandon Warne Feb 20, 2026 12:19 PM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
681BT	R/H WING UPPER INBD AILERON SHROUD PNL	2504255 / 57-10-00-209 2503881 / 57-10-00-211 2504270 / 57-10-00-229	OPENED	N	B0143806 - Alejandro Cabani llas Feb 10, 2026 12:03 PM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 20, 2026 12:34 PM
681CB	R/H WING LOWER OUTBD FLAP ACT BUTE DOOR	2504297 / 57-70-00-206 2503881 / 57-10-00-211	OPENED	N	B1019545 - Tharathorn Locha m Feb 9, 2026 2:20 PM
			READYTOCLOSE	N	K1018275 - Emmanuel Cocoa Feb 19, 2026 6:56 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 19, 2026 7:23 AM
			CLOSED	N	K1018275 - Emmanuel Cocoa Feb 19, 2026 9:45 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 19, 2026 9:58 AM
681CT	R/H WING UPPER MID INBD AILERON SHROUD PNL	2504255 / 57-10-00-209 2503881 / 57-10-00-211 2504270 / 57-10-00-229	OPENED	N	B0143806 - Alejandro Cabani llas Feb 10, 2026 12:03 PM
			READYTOCLOSE	N	B1002512 - Brandon Warne Feb 20, 2026 10:49 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 20, 2026 12:08 PM
			CLOSED	N	B1002512 - Brandon Warne Feb 20, 2026 12:19 PM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 20, 2026 12:34 PM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
681DB	R/H WING LOWER FWD OUTBD FLAP FAIRING	2503824 / 57-ZL-00-219 2504267 / 57-10-00-228 2504291 / 57-50-00-211	OPENED	N	B1020176 - Matthew Doyle Feb 5, 2026 2:02 PM
			READYTOCLOSE	N	B1020176 - Matthew Doyle Feb 20, 2026 6:30 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 20, 2026 7:14 AM
			CLOSED	N	B1020176 - Matthew Doyle Feb 20, 2026 8:50 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 20, 2026 9:42 AM
681DT	R/H WING UPPER MID OUTBD AILERON SHROUD PNL	2504255 / 57-10-00-209 2503881 / 57-10-00-211 2504270 / 57-10-00-229	OPENED	N	B0143806 - Alejandro Cabani llas Feb 10, 2026 12:03 PM
			READYTOCLOSE	N	B1002512 - Brandon Warne Feb 20, 2026 10:49 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 20, 2026 12:08 PM
			CLOSED	N	B1002512 - Brandon Warne Feb 20, 2026 12:19 PM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 20, 2026 12:34 PM
681EB	R/H WING LOWER OUTBD FLAP ACT BUTE DOOR	2504297 / 57-70-00-206 2503881 / 57-10-00-211	OPENED	N	B0613291 - Eric Strong Feb 9, 2026 1:18 PM
			READYTOCLOSE	N	K1018275 - Emmanuel Cocoa Feb 19, 2026 6:56 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
681EB	R/H WING LOWER OUTBD FLAP ACT BUTE DOOR	2504297 / 57-70-00-206 2503881 / 57-10-00-211	OPENED	N	B0613291 - Eric Strong Feb 9, 2026 1:18 PM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 19, 2026 7:23 AM
			CLOSED	N	K1018275 - Emmanuel Cocoa Feb 19, 2026 9:03 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 19, 2026 9:58 AM
681ET	R/H WING UPPER OUTBD AILERON SHROUD PNL	2504255 / 57-10-00-209 2503881 / 57-10-00-211 2504270 / 57-10-00-229	OPENED	N	B0143806 - Alejandro Cabani llas Feb 10, 2026 12:03 PM
			READYTOCLOSE	N	B1002512 - Brandon Warne Feb 20, 2026 10:49 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 20, 2026 12:08 PM
			CLOSED	N	B1002512 - Brandon Warne Feb 20, 2026 12:19 PM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 20, 2026 12:34 PM
681FB	R/H WING LOWER FWD OUTBD FLAP FAIRING	2503824 / 57-ZL-00-219 2504267 / 57-10-00-228 2504291 / 57-50-00-211	OPENED	N	B0178935 - Stephen Lodge Feb 5, 2026 8:07 AM
			READYTOCLOSE	N	B1020176 - Matthew Doyle Feb 20, 2026 6:31 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 20, 2026 7:14 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
681FB	R/H WING LOWER FWD OUTBD FLAP FAIRING	2503824 / 57-ZL-00-219 2504267 / 57-10-00-228 2504291 / 57-50-00-211	OPENED	N	B0178935 - Stephen Lodge Feb 5, 2026 8:07 AM
			CLOSED	N	B1020176 - Matthew Doyle Feb 20, 2026 8:51 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 20, 2026 9:42 AM
681GB	R/H WING LOWER OUTBD FLAP ACT BUTE DOOR	2504297 / 57-70-00-206 2503881 / 57-10-00-211	OPENED	N	B0613291 - Eric Strong Feb 9, 2026 1:18 PM
			READYTOCLOSE	N	K1018275 - Emmanuel Cocoa Feb 19, 2026 6:56 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 19, 2026 7:23 AM
			CLOSED	N	K1018275 - Emmanuel Cocoa Feb 19, 2026 9:03 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 19, 2026 9:58 AM
681HB	R/H WING LOWER OUTBD AILERON SHROUD PNL	2504336 / REMOVE AILERONS 2504327 / INSTALL AILERONS 2504173 / 57-ZL-00-235 2504255 / 57-10-00-209 2503881 / 57-10-00-211 2504270 / 57-10-00-229	OPENED	N	B0642051 - Terry Walters Feb 5, 2026 7:46 AM
			READYTOCLOSE	N	B0650736 - Jesus Gonzalez A tondo Mar 5, 2026 9:17 AM
			OKTOCLOSE	N	B0142491 - George Ambrose Mar 5, 2026 12:13 PM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
681HB	R/H WING LOWER OUTBD AILERON SHROUD PNL	2504336 / REMOVE AILERONS 2504327 / INSTALL AILERONS 2504173 / 57-ZL-00-235 2504255 / 57-10-00-209 2503881 / 57-10-00-211 2504270 / 57-10-00-229	OPENED	N	B0642051 - Terry Walters Feb 5, 2026 7:46 AM
			CLOSED	N	B1022275 - Kaitlynn Maxon Mar 5, 2026 2:05 PM
			INSPECTED	N	B1013522 - Brandon Jennings Mar 5, 2026 2:22 PM
684BB	R/H WING LOWER AFT OUTBD FLAP FAIRING	2503836 / 57-ZL-00-231 2504267 / 57-10-00-228 2504291 / 57-50-00-211 2504283 / 57-50-00-207	OPENED	N	B1020176 - Matthew Doyle Feb 6, 2026 7:28 AM
			READYTOCLOSE	N	B1020176 - Matthew Doyle Feb 20, 2026 6:31 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 20, 2026 7:14 AM
			CLOSED	N	B1020176 - Matthew Doyle Feb 20, 2026 8:51 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 20, 2026 9:42 AM
684DB	R/H WING LOWER AFT OUTBD FLAP FAIRING	2503836 / 57-ZL-00-231 2504267 / 57-10-00-228 2504291 / 57-50-00-211 2504283 / 57-50-00-207	OPENED	N	B1020176 - Matthew Doyle Feb 6, 2026 7:28 AM
			READYTOCLOSE	N	B1020176 - Matthew Doyle Feb 20, 2026 6:31 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
684DB	R/H WING LOWER AFT OUTBD FLAP FAIRING	2503836 / 57-ZL-00-231 2504267 / 57-10-00-228 2504291 / 57-50-00-211 2504283 / 57-50-00-207	OPENED	N	B1020176 - Matthew Doyle Feb 6, 2026 7:28 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 20, 2026 7:14 AM
			CLOSED	N	B1020176 - Matthew Doyle Feb 20, 2026 8:51 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 20, 2026 9:42 AM
684FB	R/H WING LOWER AFT OUTBD FLAP FAIRING	2503836 / 57-ZL-00-231 2504267 / 57-10-00-228 2504291 / 57-50-00-211 2504283 / 57-50-00-207	OPENED	N	B0178935 - Stephen Lodge Feb 5, 2026 8:07 AM
			READYTOCLOSE	N	B1020176 - Matthew Doyle Feb 20, 2026 6:31 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 20, 2026 7:14 AM
			CLOSED	N	B1020176 - Matthew Doyle Feb 20, 2026 8:51 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 20, 2026 9:42 AM
685AB	R/H WING LOWER OUTBD AILERON ACCESS PNL	2504336 / REMOVE AILERONS 2504327 / INSTALL AILERONS 2504270 / 57-10-00-229	OPENED	N	B0143806 - Alejandro Cabani llas Feb 10, 2026 9:02 AM
			READYTOCLOSE	N	B0650736 - Jesus Gonzalez A tondo Mar 5, 2026 9:17 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
685AB	R/H WING LOWER OUTBD AILERON ACCESS PNL	2504336 / REMOVE AILERONS 2504327 / INSTALL AILERONS 2504270 / 57-10-00-229	OPENED	N	B0143806 - Alejandro Cabani llas Feb 10, 2026 9:02 AM
			OKTOCLOSE	N	B0142491 - George Ambrose Mar 5, 2026 12:13 PM
			CLOSED	N	B1022275 - Kaitlynn Maxon Mar 5, 2026 12:19 PM
			INSPECTED	N	B0141354 - Karl Tuxhorn Mar 5, 2026 1:40 PM
685BB	R/H WING LOWER OUTBD AILERON ACCESS PNL	2504336 / REMOVE AILERONS 2504327 / INSTALL AILERONS 2504270 / 57-10-00-229	OPENED	N	B0143806 - Alejandro Cabani llas Feb 10, 2026 9:02 AM
			READYTOCLOSE	N	B0650736 - Jesus Gonzalez A tondo Mar 5, 2026 9:17 AM
			OKTOCLOSE	N	B0142491 - George Ambrose Mar 5, 2026 12:13 PM
			CLOSED	N	B1022275 - Kaitlynn Maxon Mar 5, 2026 12:19 PM
			INSPECTED	N	B0141354 - Karl Tuxhorn Mar 5, 2026 1:40 PM
685CB	R/H WING LOWER OUTBD AILERON ACCESS PNL	2504336 / REMOVE AILERONS 2504327 / INSTALL AILERONS 2504270 / 57-10-00-229	OPENED	N	B0143806 - Alejandro Cabani llas Feb 10, 2026 9:02 AM
			READYTOCLOSE	N	B0650736 - Jesus Gonzalez A tondo Mar 5, 2026 9:17 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
685CB	R/H WING LOWER OUTBD AILERON ACCESS PNL	2504336 / REMOVE AILERONS 2504327 / INSTALL AILERONS 2504270 / 57-10-00-229	OPENED	N	B0143806 - Alejandro Cabani llas Feb 10, 2026 9:02 AM
			OKTOCLOSE	N	B0142491 - George Ambrose Mar 5, 2026 12:13 PM
			CLOSED	N	B1022275 - Kaitlynn Maxon Mar 5, 2026 12:19 PM
			INSPECTED	N	B0141354 - Karl Tuxhorn Mar 5, 2026 1:40 PM
711	L/H FWD NLG DOOR	2503861 / 22-12-00-213 2503873 / 32-00-01-208 2503764 / 53-ZL-00-206			
			N/A	N	B1014141 - Christopher Draw dy Feb 11, 2026 7:58 AM
712	R/H FWD NLG DOOR	2503861 / 22-12-00-213 2503873 / 32-00-01-208 2503764 / 53-ZL-00-206			
			N/A	N	B1014141 - Christopher Draw dy Feb 11, 2026 7:58 AM
732	L/H MLG DOOR	2504215 / 32-12-00-201			
			N/A	N	B1014141 - Christopher Draw dy Feb 11, 2026 7:58 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
742	R/H MLG DOOR	2504215 / 32-12-00-201			
			N/A	N	B1014141 - Christopher Draw dy Feb 11, 2026 7:58 AM
832AL	PASSENGER DOOR ACCESS PANEL	2503734 / 52-ZL-00-206 2504013 / 52-11-00-203 2503736 / 52-ZL-00-207 2503772 / 53-ZL-00-211 2503778 / 53-ZL-00-221	OPENED	N	B1018339 - Dwain Wolf Feb 6, 2026 8:32 AM
			READYTOCLOSE	N	B0646266 - Sergio Rodriguez Figueroa Feb 18, 2026 1:04 PM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 18, 2026 1:31 PM
			CLOSED	N	B0646266 - Sergio Rodriguez Figueroa Feb 18, 2026 1:57 PM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 26, 2026 10:12 AM
832AR	PASSENGER DOOR ACCESS PANEL	2504013 / 52-11-00-203 2503736 / 52-ZL-00-207	OPENED	N	B1018339 - Dwain Wolf Feb 6, 2026 11:46 AM
			READYTOCLOSE	N	B0646266 - Sergio Rodriguez Figueroa Feb 18, 2026 1:04 PM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 18, 2026 1:31 PM
			CLOSED	N	B1002512 - Brandon Warne Feb 18, 2026 1:45 PM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
832AR	PASSENGER DOOR ACCESS PANEL	2504013 / 52-11-00-203 2503736 / 52-ZL-00-207	OPENED	N	B1018339 - Dwain Wolf Feb 6, 2026 11:46 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 18, 2026 2:17 PM
832AT	PASSENGER DOOR ACCESS PANEL	2504013 / 52-11-00-203 2503736 / 52-ZL-00-207	OPENED	N	B1018339 - Dwain Wolf Feb 6, 2026 8:32 AM
			READYTOCLOSE	N	K1018275 - Emmanuel Cocoa Feb 20, 2026 7:14 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 20, 2026 7:49 AM
			CLOSED	N	B1022275 - Kaitlynn Maxon Feb 20, 2026 10:26 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 20, 2026 12:38 PM
832BL	PASSENGER DOOR ACCESS PANEL	2504013 / 52-11-00-203 2503736 / 52-ZL-00-207	OPENED	N	B1018339 - Dwain Wolf Feb 6, 2026 8:40 AM
			READYTOCLOSE	N	B0646266 - Sergio Rodriguez Figueroa Feb 18, 2026 1:04 PM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 18, 2026 1:31 PM
			CLOSED	N	B0646266 - Sergio Rodriguez Figueroa Feb 18, 2026 1:57 PM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 26, 2026 10:12 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
832BR	PASSENGER DOOR ACCESS PANEL	2504013 / 52-11-00-203 2503736 / 52-ZL-00-207	OPENED	N	B1018339 - Dwain Wolf Feb 6, 2026 11:46 AM
			READYTOCLOSE	N	B0646266 - Sergio Rodriguez Figueroa Feb 18, 2026 1:04 PM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 18, 2026 1:31 PM
			CLOSED	N	B1002512 - Brandon Warne Feb 18, 2026 1:45 PM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 18, 2026 2:17 PM
832BT	PASSENGER DOOR ACCESS PANEL	2504013 / 52-11-00-203 2503736 / 52-ZL-00-207	OPENED	N	B1018339 - Dwain Wolf Feb 6, 2026 8:32 AM
			READYTOCLOSE	N	K1018275 - Emmanuel Cocoa Feb 20, 2026 7:14 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 20, 2026 7:49 AM
			CLOSED	N	B1022275 - Kaitlynn Maxon Feb 20, 2026 10:26 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 20, 2026 12:38 PM
832CL	PASSENGER DOOR ACCESS PANEL	2504013 / 52-11-00-203 2503736 / 52-ZL-00-207	OPENED	N	B1018339 - Dwain Wolf Feb 6, 2026 8:32 AM
			READYTOCLOSE	N	B0646266 - Sergio Rodriguez Figueroa Feb 18, 2026 1:04 PM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
832CL	PASSENGER DOOR ACCESS PANEL	2504013 / 52-11-00-203 2503736 / 52-ZL-00-207	OPENED	N	B1018339 - Dwain Wolf Feb 6, 2026 8:32 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 18, 2026 1:31 PM
			CLOSED	N	B0646266 - Sergio Rodriguez Figueroa Feb 18, 2026 1:57 PM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 26, 2026 10:12 AM
832CR	PASSENGER DOOR ACCESS PANEL	2504013 / 52-11-00-203 2503736 / 52-ZL-00-207	OPENED	N	B1018339 - Dwain Wolf Feb 6, 2026 11:46 AM
			READYTOCLOSE	N	B0646266 - Sergio Rodriguez Figueroa Feb 18, 2026 1:04 PM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 18, 2026 1:31 PM
			CLOSED	N	B1002512 - Brandon Warne Feb 18, 2026 1:45 PM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 18, 2026 2:17 PM
832CT	PASSENGER DOOR ACCESS PANEL	2504013 / 52-11-00-203 2503736 / 52-ZL-00-207	OPENED	N	B1018339 - Dwain Wolf Feb 6, 2026 9:50 AM
			READYTOCLOSE	N	K1018275 - Emmanuel Cocoa Feb 20, 2026 7:14 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 20, 2026 7:49 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
832CT	PASSENGER DOOR ACCESS PANEL	2504013 / 52-11-00-203 2503736 / 52-ZL-00-207	OPENED	N	B1018339 - Dwain Wolf Feb 6, 2026 9:50 AM
			CLOSED	N	B1022275 - Kaitlynn Maxon Feb 20, 2026 10:26 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 20, 2026 12:38 PM
832DL	PASSENGER DOOR ACCESS PANEL	2504013 / 52-11-00-203 2503736 / 52-ZL-00-207	OPENED	N	B1018339 - Dwain Wolf Feb 6, 2026 8:40 AM
			READYTOCLOSE	N	B0646266 - Sergio Rodriguez Figueroa Feb 18, 2026 1:04 PM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 18, 2026 1:31 PM
			CLOSED	N	B0646266 - Sergio Rodriguez Figueroa Feb 18, 2026 1:57 PM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 26, 2026 10:12 AM
832DR	PASSENGER DOOR ACCESS PANEL	2504013 / 52-11-00-203 2503736 / 52-ZL-00-207	OPENED	N	B1018546 - Andres Velazquez Feb 8, 2026 12:50 PM
			READYTOCLOSE	N	B0646266 - Sergio Rodriguez Figueroa Feb 18, 2026 1:04 PM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 20, 2026 7:49 AM
			CLOSED	N	B1022275 - Kaitlynn Maxon Feb 20, 2026 10:26 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
832DR	PASSENGER DOOR ACCESS PANEL	2504013 / 52-11-00-203 2503736 / 52-ZL-00-207	OPENED	N	B1018546 - Andres Velazquez Feb 8, 2026 12:50 PM
			CLOSED	Y	B1013522 - Brandon Jennings Feb 23, 2026 12:04 PM
			CLOSED	N	B1020176 - Matthew Doyle Feb 23, 2026 12:12 PM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 23, 2026 1:15 PM
832DT	PASSENGER DOOR ACCESS PANEL	2504013 / 52-11-00-203 2503736 / 52-ZL-00-207	OPENED	N	B1018339 - Dwain Wolf Feb 6, 2026 9:50 AM
			READYTOCLOSE	N	K1018275 - Emmanuel Cocoa Feb 20, 2026 7:21 AM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 20, 2026 7:49 AM
			CLOSED	N	B1022275 - Kaitlynn Maxon Feb 20, 2026 10:26 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 20, 2026 12:38 PM
832DZ	Internal Handle Cover				
			N/A	N	B1014141 - Christopher Draw dy Feb 11, 2026 8:19 AM
832ET	PASSENGER DOOR ACCESS PANEL	2504013 / 52-11-00-203 2503736 / 52-ZL-00-207	OPENED	N	B1018339 - Dwain Wolf Feb 6, 2026 10:25 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
832FL	PASSENGER DOOR INNER VENT PANEL	2504013 / 52-11-00-203 2503736 / 52-ZL-00-207	OPENED	N	B1018339 - Dwain Wolf Feb 6, 2026 8:40 AM
			READYTOCLOSE	N	B0646266 - Sergio Rodriguez Figueroa Feb 18, 2026 1:04 PM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 18, 2026 1:31 PM
			OKTOCLOSE	Y	B1013522 - Brandon Jennings Feb 18, 2026 2:18 PM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 20, 2026 7:49 AM
			CLOSED	N	B1022275 - Kaitlynn Maxon Feb 20, 2026 10:26 AM
			CLOSED	Y	B1019908 - Joseph Barnes Feb 23, 2026 9:37 AM
			OKTOCLOSE	Y	B1019908 - Joseph Barnes Feb 23, 2026 9:37 AM
			OKTOCLOSE	N	B1019908 - Joseph Barnes Feb 23, 2026 9:37 AM
			CLOSED	N	B1020176 - Matthew Doyle Feb 23, 2026 12:13 PM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 23, 2026 1:15 PM
832FT	PASSENGER DOOR ACCESS PANEL	2504013 / 52-11-00-203 2503736 / 52-ZL-00-207	OPENED	N	B0142041 - Timothy Winfree Feb 13, 2026 5:39 PM
			READYTOCLOSE	N	K1018275 - Emmanuel Cocoa Feb 20, 2026 7:21 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
832FT	PASSENGER DOOR ACCESS PANEL	2504013 / 52-11-00-203 2503736 / 52-ZL-00-207	OPENED	N	B0142041 - Timothy Winfree Feb 13, 2026 5:39 PM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 20, 2026 7:49 AM
			CLOSED	N	B1022275 - Kaitlynn Maxon Feb 20, 2026 10:26 AM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 20, 2026 11:57 AM
832GL	PASSENGER DOOR ACCESS PANEL	2504013 / 52-11-00-203 2503736 / 52-ZL-00-207	OPENED	N	B1018339 - Dwain Wolf Feb 6, 2026 9:20 AM
			READYTOCLOSE	N	B0646266 - Sergio Rodriguez Figueroa Feb 18, 2026 1:04 PM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 18, 2026 1:31 PM
			OKTOCLOSE	Y	B1013522 - Brandon Jennings Feb 18, 2026 2:18 PM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 20, 2026 7:49 AM
			CLOSED	N	B1022275 - Kaitlynn Maxon Feb 20, 2026 10:26 AM
			CLOSED	Y	B1019908 - Joseph Barnes Feb 23, 2026 9:37 AM
			OKTOCLOSE	Y	B1019908 - Joseph Barnes Feb 23, 2026 9:37 AM
			OKTOCLOSE	N	B1019908 - Joseph Barnes Feb 23, 2026 9:37 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
832GL	PASSENGER DOOR ACCESS PANEL	2504013 / 52-11-00-203 2503736 / 52-ZL-00-207	OPENED	N	B1018339 - Dwain Wolf Feb 6, 2026 9:20 AM
			CLOSED	N	B1020176 - Matthew Doyle Feb 23, 2026 12:14 PM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 23, 2026 1:15 PM
832GR	PASSENGER DOOR ACCESS PANEL	2504013 / 52-11-00-203			
			N/A	N	B0142041 - Timothy Winfree Feb 13, 2026 4:30 PM
832GT	PASSENGER DOOR ACCESS PANEL	2504013 / 52-11-00-203 2503736 / 52-ZL-00-207	OPENED	N	B0142041 - Timothy Winfree Feb 20, 2026 10:21 AM
			READYTOCLOSE	N	K1018275 - Emmanuel Cocoa Feb 20, 2026 2:19 PM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 20, 2026 2:21 PM
			CLOSED	N	K1018275 - Emmanuel Cocoa Feb 20, 2026 2:22 PM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 26, 2026 1:11 PM
832HL	PASSENGER DOOR ACCESS PANEL	2504013 / 52-11-00-203 2503736 / 52-ZL-00-207	OPENED	N	B1018339 - Dwain Wolf Feb 6, 2026 9:20 AM
			READYTOCLOSE	N	B0646266 - Sergio Rodriguez Figueroa Feb 18, 2026 1:04 PM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 18, 2026 1:31 PM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
832HL	PASSENGER DOOR ACCESS PANEL	2504013 / 52-11-00-203 2503736 / 52-ZL-00-207	OPENED	N	B1018339 - Dwain Wolf Feb 6, 2026 9:20 AM
			OKTOCLOSE	Y	B1013522 - Brandon Jennings Feb 18, 2026 2:18 PM
			OKTOCLOSE	N	B1013522 - Brandon Jennings Feb 20, 2026 7:49 AM
			CLOSED	N	B1022275 - Kaitlynn Maxon Feb 20, 2026 10:26 AM
			CLOSED	Y	B1019908 - Joseph Barnes Feb 23, 2026 9:37 AM
			OKTOCLOSE	Y	B1019908 - Joseph Barnes Feb 23, 2026 9:37 AM
			OKTOCLOSE	N	B1019908 - Joseph Barnes Feb 23, 2026 9:37 AM
			CLOSED	N	B1020176 - Matthew Doyle Feb 23, 2026 12:13 PM
			INSPECTED	N	B1013522 - Brandon Jennings Feb 23, 2026 1:15 PM
832HR	PASSENGER DOOR ACCESS PANEL	2504013 / 52-11-00-203			
			N/A	N	B0142041 - Timothy Winfree Feb 13, 2026 4:31 PM
832HT	PASSENGER DOOR HINGED STEP PANEL	2503748 / 53-20-00-202	OPENED	N	K1018275 - Emmanuel Cocoa Feb 13, 2026 6:58 AM

Aircraft Reg #	XA-SOL	Aircraft SN #	6111	MWPWO #	2498069

ACCESS PANEL DETAILS

Panel #	Description	WO # / Reference	Action	Reversed	Signature Date/Time
834AL	CARGO COMPARTMENT DOOR	2504197 / 22-12-00-209 2503742 / 52-ZL-00-211 2504061 / 53-30-00-213 2504103 / 53-ZL-00-225 2503740 / 52-ZL-00-210 2504060 / 53-30-00-211			
			N/A	N	B0142041 - Timothy Winfree Feb 20, 2026 10:26 AM
841AR	OVERWING EMERGENCY EXIT DOOR	2504358 / 53-20-00-217 2504033 / 53-20-00-218 2504016 / 52-21-00-203 2503877 / 52-21-00-204 2504021 / 52-ZL-00-208 2503690 / 52-20-00-203 2503738 / 52-ZL-00-209	OPENED	N	B1001500 - Victor Gallego Feb 10, 2026 12:11 PM
843AZ	EMERG OVRWG EXIT DOOR LINING PNL	2504016 / 52-21-00-203 2503738 / 52-ZL-00-209	OPENED	N	K1018275 - Emmanuel Cocoa Feb 13, 2026 6:58 AM
843BZ	EMERG OVRWG EXIT DOOR ACCESS PNL	2503738 / 52-ZL-00-209	OPENED	N	K1018275 - Emmanuel Cocoa Feb 13, 2026 6:58 AM
843CZ	CARGO DOOR LINING PNL	2503742 / 52-ZL-00-211 2504019 / 52-31-00-203	OPENED	N	K1018275 - Emmanuel Cocoa Feb 13, 2026 6:58 AM