Work Order #	4843594	**Aircraft SN #**	20590	**Customer #**	27618
Description	N786QS/SAT WIFI	**Aircraft Reg #**	N786QS	**Customer Name**	NetJets Aviation, Inc.
Location	TUS-3050	**Model #**	350	**Proposal #**	BBD-23942
Service Center Reg #	KW3R646L	**A/C Hours**	10,709.9	**MWPWO #**	4843594
Status	INPRG	**A/C Cycles**	6,232	**SAP SO #**	294856
Lead	Christopher Drawdy	**Supervisor**	Bryen Sandoval	**CPM**	Daniel Reed

Sequence #	0002	**Aircraft SN #**	20590	**MWPWO #**	4843594
WO #	4850216	**Aircraft Reg #**	N786QS	**Parent WO #**	4843594

0002	**WO #**	**4850216**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #	13513312	No Log Entry	
Work Preparation / Administration / Initiation				
Task / IRN # : WORK PREP				

Sequence #	0002	Aircraft SN #	20590	MWPWO #	4843594
WO #	4850216	Aircraft Reg #	N786QS	Parent WO #	4843594

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Performed walk-around preliminary inspection - See attached QA032 and findings for defects noted.	B0142244 - Todd Bridges Mar 02, 2026 08:58 PM	
	Visual Walk-Around Preliminary Inspection		B0142244 - Todd Bridges Mar 02, 2026 08:52 PM	
	200			
	Disable the ADS-B System			
	300			
	Inventory the Aircraft for Customer Items		Not Required	
	400			
	Request the Log Books for the Aircraft From the Customer		Not Required	
	500	Protected the Exterior of the Aircraft	B1020176 - Matthew Doyle Mar 02, 2026 08:56 PM	
	Protect the Exterior of the Aircraft		Not Required	
	600			
	Protect the Interior of the Aircraft		Not Required	
	700			
	Perform Incoming Avionics/Electrical Inspection Checklist		Not Required	
	800	Installed nose ballast and removed nose nylon plug for FOM REF: BD-100 AMM 07−10−00−480−801	B1018547 - Matthew Rossier Mar 03, 2026 01:26 AM	
	Install nose ballast for FOM REF: BD-100 AMM 07−10−00−480−801		B0161691 - Thomas Mitchell Mar 03, 2026 01:34 AM	
	900			
	Remove nose ballast and install nose nylon plug REF: BD-100 AMM 7-10-00-080-801			

Sequence #	0002	Aircraft SN #	20590	MWPWO #	4843594
WO #	4850216	Aircraft Reg #	N786QS	Parent WO #	4843594

FINDINGS DETAILS

Finding #	Long Description	Status	Reported By / Date	Defect Source / Disposition	Defect Type	Priority	Follow-up WO #
82711	Pax door external service light lens bad	CLOSED	B0142244 - Todd Bridges Mar 2, 2026 1:55 PM	MAINTENANCE 300-QA002	OTHER	3	4880368-INPRG
82720	Emer door exterior service light lens bad	CLOSED	B0142244 - Todd Bridges Mar 2, 2026 2:03 PM	MAINTENANCE 300-QA002	OTHER	3	4880370-INPRG
82721	L/H MLG lower wheel bin has multiple fastener plates corroded - pn # 1005342821-005	CLOSED	B0142244 - Todd Bridges Mar 2, 2026 2:04 PM	MAINTENANCE 300-QA002	OTHER	3	4880377-APPR

Sequence #	0003	**Aircraft SN #**	20590	**MWPWO #**	4843594
WO #	4843709	**Aircraft Reg #**	N786QS	**Parent WO #**	4843594

0003	**WO #**	**4843709**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #	13512304	No Log Entry	
050202 (BOMBARDIER CHALLENGER 350 MAINTENANCE CHECKLIST (Use latest revision posted on Comply 365))				
Task / IRN # : 050202				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			05-00
	Perform 050202 (BOMBARDIER CHALLENGER 350 MAINTENANCE CHECKLIST (Use latest revision posted on Comply 365))			

Bombardier

Sequence #	0004	Aircraft SN #	20590	MWPWO #	4843594
WO #	4880370	Aircraft Reg #	N786QS	Parent WO #	4843594

0004	WO #	4880370	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13517490	No Log Entry	
Emer door exterior service light lens bad				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Removed and replaced Lens on Over-Wing Emer-Door Emergency Light with NEW part. REF BD100 AMM 33-51-01-906 steps E.(1.) thru F.(3.) and F.(6.) thru closeout. P/N: 9EL400042-00	B1016542 - Carlos Ochoa Mar 06, 2026 12:50 AM	
	Emer door exterior service light lens bad		B0609145 - Miguel Pacheco Mar 06, 2026 01:25 AM	
	200	Removed Lens on the Over-Wing Emer-Exit Light. REF BD100 AMM 33-51-05-960-801. P/N: 9EL400042-00	B1016542 - Carlos Ochoa Mar 05, 2026 10:55 PM	
	Remove Lens on the Over-Wing Emer-Exit Light. REF BD100 AMM 33-51-05-960-801.		Not Required	
	300			
	Perform 9 hour cure check of sealant on 03/05/26.			

Bombardier

Sequence #	0005	Aircraft SN #	20590	MWPWO #	4843594
WO #	4880368	Aircraft Reg #	N786QS	Parent WO #	4843594

0005	WO #	4880368	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13517420	No Log Entry	
Pax door external service light lens bad				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Removed and replaced Lens of the PAX Door Emergency Light with NEW part. REF BD100 AMM 33-51-01-906 steps E.(1.) thru F.(2.) and F.(6.) thru closeout. P/N: 9EL400042-00	B1016542 - Carlos Ochoa Mar 06, 2026 12:50 AM	
	Pax door external service light lens bad		B0609145 - Miguel Pacheco Mar 06, 2026 01:28 AM	
	200	Removed Lens on PAX Door Emergency Light. REF BD100 AMM 33-51-01-960-801. P/N: 9EL400042-00	B1016542 - Carlos Ochoa Mar 05, 2026 10:33 PM	
	Remove Lens on PAX Door Emergency Light. REF BD100 AMM 33-51-01-960-801.		Not Required	
	300			
	Perform 9 hour cure check of sealant on 03/05/26			

Bombardier

Sequence #	1001	Aircraft SN #	20590	MWPWO #	4843594
WO #	4843767	Aircraft Reg #	N786QS	Parent WO #	4843594

1001	WO #	4843767	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13512346	No Log Entry	
DISABLE ADS-B BY PULLING / LOCKING OUT TRANSPONDER AND GPS CIRCUIT BREAKERS (RIL# BA-0004 REV 3)				
Task / IRN # : 1001				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			05-00
	Perform Disable ADS-B by Pulling / Locking out Transponder and GPD circuit Breakers (RIL# BA-0004 Rev 3)			
	200			05-00
	Perform Re-Enable ADS-B System at the Completion of the Work Scope			

Sequence #	1002	**Aircraft SN #**	20590	**MWPWO #**	4843594
WO #	4865813	**Aircraft Reg #**	N786QS	**Parent WO #**	4843594

1002	**WO #**	**4865813**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #	13515814	No Log Entry	
Comply with incoming Avionics cabin sweep. Report observations to CPM.				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied with incoming Avionics cabin sweep. Reported observations to CPM.	B1001648 - Steve Cardenas Mar 03, 2026 02:25 AM	
	Comply with incoming Avionics cabin sweep. Report observations to CPM.		B0161691 - Thomas Mitchell Mar 03, 2026 04:00 AM	
	200	Removed all tools, equipment, and unwanted materials from the work area.	B1001648 - Steve Cardenas Mar 03, 2026 02:25 AM	
	Remove all tools, equipment, and unwanted materials from the work area.		B0161691 - Thomas Mitchell Mar 03, 2026 04:00 AM	

Sequence #	1003	**Aircraft SN #**	20590	**MWPWO #**	4843594
WO #	4892651	**Aircraft Reg #**	N786QS	**Parent WO #**	4843594

1003	**WO #**	**4892651**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #	13518833	No Log Entry	
VIP Seat RH seat 2 couldn't get audio from the headphone jacks.				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			
	VIP Seat RH seat 2 couldn't get audio from the headphone jacks.			

Bombardier

Sequence #	3501	Aircraft SN #	20590	MWPWO #	4843594
WO #	4844348	Aircraft Reg #	N786QS	Parent WO #	4843594

3501	WO #	4844348	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13511970	No Log Entry	
Communication - Deviations to the Starlink Satcom STC (350/3500)				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			
	Communication - Deviations to the Starlink Satcom			

Sequence #	3502	**Aircraft SN #**	20590	**MWPWO #**	4843594
WO #	4843740	**Aircraft Reg #**	N786QS	**Parent WO #**	4843594

3502	**WO #**	**4843740**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #	13512281	No Log Entry	
EO_B10-23-0001 (Bombardier Challenger 350 SpaceX Starlink Aviation System Installation (Use latest revision on Comply365))				
Task / IRN # : EO_B10-23-0001				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			05-00
	EO_B10-23-0001 (Bombardier Challenger 350 SpaceX Starlink Aviation System Installation (Use latest revision on Comply365))			

Sequence #	3503	Aircraft SN #	20590	MWPWO #	4843594
WO #	4843738	Aircraft Reg #	N786QS	Parent WO #	4843594

3503	WO #	4843738	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13512278	No Log Entry	
EO WC B10-23-0001_1(EO_B10-23-0001) (Bombardier Challenger 350 SpaceX Starlink Aviation System Installation)(Use Latest revision of Comply 365)				
Task / IRN # : EO B10-23-0001				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			05-00
	EO WC B10-23-0001_1(EO_B10-23-0001) (Bombardier Challenger 350 SpaceX Starlink Aviation System Installation)(Use Latest revision of Comply 365)			

Sequence #	3504	**Aircraft SN #**	20590	**MWPWO #**	4843594
WO #	4843746	**Aircraft Reg #**	N786QS	**Parent WO #**	4843594

3504	**WO #**	**4843746**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #	13512280	No Log Entry	
EO WC B10-23-0001_2(EO_B10-23-0001) (Bombardier Challenger 350 WiFi System Interior Equipment Removal (Use Latest Revision on Comply365))				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			
	EO WC B10-23-0001_2(EO_B10-23-0001) (Bombardier Challenger 350 WiFi System Interior Equipment Removal (Use Latest Revision on Comply365))			

Sequence #	3505	**Aircraft SN #**	20590	**MWPWO #**	4843594
WO #	4847016	**Aircraft Reg #**	N786QS	**Parent WO #**	4843594

3505	**WO #**	**4847016**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #	13512681	No Log Entry	
Communications - Modification - Starlink High-Speed Satcom installation without cockpit WLAN Switch per FAA STC ST11935CH (350/3500) - NetJets only				
Task / IRN # : STC ST11935CH				

Sequence #	3505	Aircraft SN #	20590	MWPWO #	4843594
WO #	4847016	Aircraft Reg #	N786QS	Parent WO #	4843594

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			23-00
	AIRCRAFT SETUP (1) Make sure the aircraft is in the standard configuration for maintenance. (2) Obey all electrical/electronic safety precautions. (3) Obey all the electrostatic-discharge safety precautions. CAUTION: OBEY ALL ELECTROSTATIC DISCHARGE-SENSITIVE (ESDS) PRECAUTIONS. STATIC VOLTAGES CAN CAUSE DAMAGE TO ESDS COMPONENTS. (4) Remove the electrical power from the aircraft. (5) Open and tag the necessary circuit breakers for the applicable systems to do this modification. (6) If necessary remove the applicable LRUs for access. (7) Remove all the necessary interiors, components and floorboards for access to do the modification.			
	200			23-00
	STARLINK AEROTERMINAL INSTALLATION NT0089-0424-03 (1) Install Aeroterminal per drawing Install per NT0089-0424-03			

Sequence #	3505	Aircraft SN #	20590	MWPWO #	4843594
WO #	4847016	Aircraft Reg #	N786QS	Parent WO #	4843594

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	300			23-00
	STARLINK POWER SUPPLY UNIT (PSU) AND WIFI ACCESS POINT (WAP) INSTALLATION NT0089-0424-04 (1) Create cutout for wiring in existing removable entertainment shelf per General Note 18 and as shown in Section C-C on sheet 4. (2) Locate C-Channel assembly on aft panel of existing closet structure as shown on Sheet 3 and match drill three holes for inserts. Install three inserts. (3) Locate one angle assembly on aft panel of existing closet structure as shown on Sheet 3 and match drill two holes for inserts. Install two inserts. (4) Locate two angle assemblies on existing removable entertainment shelf as shown on Sheet 3 and match drill two holes for inserts, per angle assembly. Install two inserts, per angle assembly. (5) Locate WAP on aft panel of existing closet structure as shown on Sheet 3 and match drill four holes for inserts. Install four inserts.			

Sequence #	3505	Aircraft SN #	20590	MWPWO #	4843594
WO #	4847016	Aircraft Reg #	N786QS	Parent WO #	4843594

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	400			23-00
	STARLINK POWER SUPPLY UNIT (PSU) AND WIFI ACCESS POINT (WAP) INSTALLATION NT0089-0424-04 (6) Locate PSU on aft panel of existing closet structure as shown on Sheet 3 and match drill four holes for inserts. Install four inserts. (7) Install C-Channel assembly on aft panel of existing closet structure with three screws and washers as shown on Sheet 3. (8) Install one angle assembly on aft panel of existing closet structure with two screws and washers as shown on Sheet 3. (9) Install two angle assemblies on existing removable entertainment shelf with two screws and washers, per angle assembly, as shown on Sheet 3			

Sequence #	3505	Aircraft SN #	20590	MWPWO #	4843594
WO #	4847016	Aircraft Reg #	N786QS	Parent WO #	4843594

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	500			23-00
	STARLINK POWER SUPPLY UNIT (PSU) AND WIFI ACCESS POINT (WAP) INSTALLATION NT0089-0424-04 (10) Install WAP on aft panel of existing closet structure with four screws, five washers, one lock washer, and grounding strap as shown on Sheet 3. (11) Install PSU on aft panel of existing closet structure with four screws, five washers, one lock washer, and both grounding straps as shown on Sheet 3. (12) Locate closeout on C-Channel assembly and angle assemblies as shown on Sheet 4 and match drill holes from assemblies into closeout per General Note 19. (13) Install grounding strap to nearest available aircraft ground per General Notes 8 and 20. (14) Install closeout to C-Channel assembly and angle assemblies with six screws as shown on Sheet 4.			

Sequence #	3505	Aircraft SN #	20590	MWPWO #	4843594
WO #	4847016	Aircraft Reg #	N786QS	Parent WO #	4843594

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	600			23-00
	STARLINK INVERTER INSTALLATION NT0089-0424-05 (1) Create cutout in existing upper lavatory vanity assy outboard closeout panel for wiring per General Note 12 and Section B-B. (2) Locate one Zee Channel assembly on existing lower lavatory vanity assy top removable panel and match drill two holes for inserts. Install two inserts. (3) Using marked Zee Channel assembly location and plate assembly as a guide, locate and match drill two holes for second Zee Channel assembly on top removable panel. Install two inserts. (4) Locate two angle assemblies on existing upper lavatory vanity assy aft panel and match drill two holes, per angle assembly, for inserts. Install two inserts per angle assembly. (5) Locate two angle assemblies on existing upper lavatory vanity assy fwd panel and match drill two holes, per angle assembly, for inserts. Install two inserts per angle assembly.			

Sequence #	3505	Aircraft SN #	20590	MWPWO #	4843594
WO #	4847016	Aircraft Reg #	N786QS	Parent WO #	4843594

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	700			23-00
	STARLINK INVERTER INSTALLATION NT0089-0424-05 (6) Install contactor to plate assembly with two screws and washers as shown on Sheet 4. (7) Install plate assembly to Zee Channel assembly with two screws and washers as shown on Sheet 4. (8) Install TI500 inverter and other Zee Channel assembly to Plate with four screws, four washers, and one grounding strap as shown on Sheet 3. (9) Install Plate and Zee Channel assemblies to existing lower lavatory vanity assy top removable panel with four screws and washers as shown on Sheet 4. (10) Install four Angle assemblies on existing upper lavatory vanity assy at insert locations with two screws and washers per angle assembly as shown. (11) Locate Closeout on Angle assemblies as shown and match drill four holes from Angle assemblies into Closeout per General Note 15. (12) Install grounding strap to nearest available aircraft ground per General Note 6.			

Sequence #	3505	Aircraft SN #	20590	MWPWO #	4843594
WO #	4847016	Aircraft Reg #	N786QS	Parent WO #	4843594

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	800			23-00
	STARLINK INVERTER INSTALLATION NT0089-0424-05 (13) Install closeout to angle assemblies with four screws as shown. (14) Both the honeycomb panels and inserts being installed need to be methodically cleaned using 4540 Methyl Ethyl Ketone or H.E.T. 1501 premium wash thinner to ensure that they are free of oil, grease, debris, and any other contaminants. Both are to be handled with clean rubber gloves with no powder additives. Before install and after cleaning, inserts will only be placed on surfaces that are solvent cleaned. Solvent cleaned surface need to be wiped dry before the solvent evaporates. After all the drilling processes have been completed and prior to installing the insert clean for the final time. All areas will be wiped clean with white linen cloths, when using solvents. (15) For blind inserts: Drill only the top face sheet of the honeycomb panel to the appropriate diameter. All holes for blind inserts are done with a 0.453 in. (29/64) counterbore regardless of the fastener size.			

Sequence #	3505	Aircraft SN #	20590	MWPWO #	4843594
WO #	4847016	Aircraft Reg #	N786QS	Parent WO #	4843594

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	900			23-20
	STARLINK INVERTER INSTALLATION NT0089-0424-05 (16) For through inserts: Drill both face sheets of the honeycomb panel to the appropriate hole diameter. All holes for through inserts are done with 0.563 in. (9/16) counterbore regardless of the fastener size. (17) Remove the honeycomb core to a diameter equal to the specified hole diameter plus a 0.50 in. as shown in the figure 1. Use caution to ensure that there is no damage done to the inner surfaces of the facesheets. Use a coring bit that is made from AISI M1 or T1 tool steel to remove the inner honeycomb core material. (18) Ensure that the coring bit has removed all of the inner core material from facesheet to facesheet. A razor knife should be used to remove any loose core ribbon interfering with insert installation making sure not to damage the facesheets. (19) For blind inserts: Use the coring bit to manually remove any remaining core on the inside surface of the facesheet on the opposite side of where the insert is to be installed. Do not pull any loose flaps of core ribbon, as it may result in a loss of structural integrity of the installation.			

Sequence #	3505	Aircraft SN #	20590	MWPWO #	4843594
WO #	4847016	Aircraft Reg #	N786QS	Parent WO #	4843594

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	1000			23-00
	STARLINK INVERTER INSTALLATION NT0089-0424-05 9.20 For through inserts: Use the coring bit to remove any remaining core on the inside surfaces of both facesheets. Do not pull any loose flaps of core ribbon, as it may result in a loss of structural integrity of the installation. (21) Deburr the external edges of the drilled hole. (22) Remove core fragments by vacuuming the hole out before potting the insert. (23) For through inserts: Aluminum tape should be used to cover up the hole on the side of the panel opposite of the installation tab. (24) Remove the paper from adhesive face of installation tab. (25) Put the adhesive side of installation tab on top of the insert. Align the holes in installation tab with the ones in the insert. Aligning the holes perfectly is not required, due to the holes in the installation tab being oversized to allow interchangeability.			

Sequence #	3505	Aircraft SN #	20590	MWPWO #	4843594
WO #	4847016	Aircraft Reg #	N786QS	Parent WO #	4843594

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	1100			23-00
	STARLINK INVERTER INSTALLATION NT0089-0424-05 (26) Install insert into the predrilled hole. If there is resistance due to loose core ribbon ensnared between insert and facesheet, rotate the insert in hole to dislocate the loose core ribbon. If unsuccessful in rotating the insert into the hole trim the core ribbon away with a razor knife. Put a slight pressure around edge of installation tab so it stays to panel surface. (27) Use a sealant gun equipped with a standard mixing nozzle to inject DP-420 (3m), EP-420NS (infinity bond), or ATR-525 (aeromatrix) into either of the two holes. The open hole allows excess air and potting material to escape. (28) After the potting compound has set remove the installation tab. Allow 6 hours for potting compound to cure at 73 deg. F. (29) For through inserts: Remove the aluminum tape from the panel. If sanding of the cured potting compound is necessary for cosmetic reasons, ensure that the facesheet is untouched and that the sanding does not remove the potting compound below the surface of the facesheet.			

Sequence #	3505	Aircraft SN #	20590	MWPWO #	4843594
WO #	4847016	Aircraft Reg #	N786QS	Parent WO #	4843594

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	1200			23-00
	STARLINK IRIDIUM ANTENNA RELOCATION NT0089-0424-06 (1) Remove and retain the existing Iridium antenna, spacer, and four antenna mounting screws at FS 474.87. (2) Remove and delete existing antenna gasket(s) from the previous Iridium antenna installation at FS 474.87. (3) Carefully drill out twelve stringer rivets located in doubler installation footprint as shown in Detail A. (4) Locate doubler and filler plate on existing fuselage skin and drill rivet pattern thru doubler, filler plate, and existing fuselage skin as shown on Sheets 3-4. (5) Match drill twelve holes from existing fuselage skin and stringer to doubler and filler plate as shown in Detail A. (6) Drill hole for Iridium antenna connector thru doubler, filler plate, and existing fuselage skin as shown on Sheets 3-4.			

Sequence #	3505	Aircraft SN #	20590	MWPWO #	4843594
WO #	4847016	Aircraft Reg #	N786QS	Parent WO #	4843594

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	1300			23-00
	STARLINK IRIDIUM ANTENNA RELOCATION NT0089-0424-06 (7) Temporarily locate Iridium antenna centered in connector thru hole and mark locations for antenna screw locations. (8) Drill four holes thru doubler, filler plate, and existing fuselage skin at marked locations for antenna installation. (9) Drill holes for domed nutplate rivets in doubler as shown in Detail B. (10) Install four domed nutplates to doubler with tow rivets each as shown on Sheet 3. (11) Locate and install doubler and filler plate to existing fuselage skin with rivets as shown on Sheet 3. (12) Locate Iridium antenna, two gaskets, and existing spacer on existing fuselage skin and install to doubler domed nutplates with four screws as shown.			
	1400			23-00
	OPITIONAL WIFI SWITCH INSTALLATION NT0089-0424-07 (1) Create cutout in existing co-pilot side instrument panel as shown in Detail A. (2) Install WLAN switch in cutout per applied avionics' installation instructions.			

Sequence #	3505	Aircraft SN #	20590	MWPWO #	4843594
WO #	4847016	Aircraft Reg #	N786QS	Parent WO #	4843594

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	1500			23-00
	STARLINK CIRCUIT BREAKER PANEL INSTALLATION NT0099-0424-08 (1) Locate and create cutout for wiring in existing lavatory circuit breaker panel closeout per General Note 12 and Section D-D. (2) Locate two angle assemblies on existing upper lavatory vanity assy top panel as shown on Sheet 4 and match drill two holes, per angle assembly, into the panel. Install four inserts (3) Locate one angle assembly on existing upper lavatory vanity assy aft panel as shown on Sheet 4 and match drill two holes into the panel. Install two inserts. (4) Install two angle assemblies to existing upper lavatory vanity assy top panel with two screws and washers, per angle assembly, as shown on Sheet 4. (5) Install one angle assembly to existing upper lavatory vanity assy aft panel with two screws and washers as shown on Sheet 4.			

Sequence #	3505	Aircraft SN #	20590	MWPWO #	4843594
WO #	4847016	Aircraft Reg #	N786QS	Parent WO #	4843594

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	1600			23-00
	STARLINK CIRCUIT BREAKER PANEL INSTALLATION NT0099-0424-08 (6) NT0089-0424-02-101 Configuration Only: Install panel plug to C/B panel assembly as shown on Sheet 3. (7) NT0089-0424-02-103 Configuration Only: Install circuit breaker, 1 amp to C/B panel assembly per manufacturers installation instructions. (8) Install circuit breaker, 5 amp to C/B panel assembly per manufacturer's installation instructions. (9) Install circuit breaker, 35 amp to C/B panel assembly with two screws per manufacturers installation instructions. (10) Install C/B panel assembly to three angle assemblies with three screws as shown.			
	1700			23-00
	WIRE ROUTING INSTRUCTIONS NT0089-0424-01 INCLUDE THE OPTIONAL WLAN SWITCH WIRING IF OPTION IS CHOSEN BY CUSTOMER (1) Route wiring per NT0089-0424-01			
	1800			23-00
	WIRE TERMINATION INSTRUCTIONS NT0089-0424-02 INCLUDE THE OPTIONAL WLAN SWITCH WIRING IF OPTION IS CHOSEN BY CUSTOMER (1) Terminate wiring per NT0089-0424-02			

Sequence #	3505	Aircraft SN #	20590	MWPWO #	4843594
WO #	4847016	Aircraft Reg #	N786QS	Parent WO #	4843594

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	1900			23-00
	GROUND TEST PROCEDURE NT0089-PGTP-0100 (1) Perform GTP NT0089-PGTP-0100			
	2000			23-00
	PAINT TOUCH UP AEROTERMINAL (1) Touch up area near Aeroterminal			
	2100			23-00
	FINAL INSPECTION STC ST11935CH is complete per MDL # NT0089-MDL0-0100 Rev A and Permission Letter.			
	2200			
	Engineering		Not Required	

FINDINGS DETAILS

Finding #	Long Description	Status	Reported By / Date	Defect Source / Disposition	Defect Type	Priority	Follow-up WO #
83286	Communications - Modification - Starlink High-Speed Satcom installation without cockpit WLAN Switch per FAA STC ST11935CH (350/3500) - NetJets only	CLOSED	B0143607 - Roberto Montano Mar 5, 2026 2:02 PM	MAINTENANCE 300-QA002	OTHER	3	4889726-APPR
83372	Evidence of corrosion found on upper fuselage skin FS474.87 on iridium antenna footprint.	RDYLT	B0143607 - Roberto Montano Mar 6, 2026 6:32 AM	MAINTENANCE 300-QA002	OTHER	3	

Bombardier

Sequence #	4001	Aircraft SN #	20590	MWPWO #	4843594
WO #	4843761	Aircraft Reg #	N786QS	Parent WO #	4843594

4001	WO #	4843761	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13512277	No Log Entry	
INTERIOR SUPPORT				
Task / IRN # : 4001				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100	Complied With Interior Incoming Inspection	B1001500 - Victor Gallego Mar 03, 2026 04:52 AM	05-00
	Interior Incoming Inspection		B0161691 - Thomas Mitchell Mar 03, 2026 05:11 AM	
	200	Complied With Aircraft Interior Protection	B1001500 - Victor Gallego Mar 03, 2026 05:19 AM	05-00
	Aircraft Interior Protection		Not Required	
	300			05-00
	Interior AD-HOC Task			

Bombardier

Sequence #	4002	Aircraft SN #	20590	MWPWO #	4843594
WO #	4846495	Aircraft Reg #	N786QS	Parent WO #	4843594

4002	WO #	4846495	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13512680	No Log Entry	
Communications - Interior Access - Starlink High-Speed Satcom installation without cockpit WLAN Switch per FAA STC ST11935CH (350/3500) - NetJets				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			25-00
	Provide Interior Access support for Starlink High-Speed Satcom installation without cockpit WLAN Switch per FAA STC ST11935CH (350/3500) - NetJets			
	200			
	Restore Interior Post Starlink High-Speed Satcom installation without cockpit WLAN Switch per FAA STC ST11935CH (350/3500) - NetJets.			

Sequence #	4002	Aircraft SN #	20590	MWPWO #	4843594
WO #	4846495	Aircraft Reg #	N786QS	Parent WO #	4843594

CHILD WORK ORDER DETAILS

	WO #	Description	Corrective Action	AMENDED
4002-1	4870995	01/4002 - Entry headliner removal and install for starlink access.	1.5 hours removed from parent WO, to apply time on this WO for techs to fill documentation. please don't go over	
4002-2	4871006	02/4002 - Entry wardrobe removal and install for starlink access.	1.5 hours removed from parent WO, to apply time on this WO for techs to fill documentation. Please dont go over	
4002-3	4871018	03/4002 - Cabin flooring (Entry, Main cabin , Lavatory) removal and install for starlink access.	1.5 hours removed from parent WO, to apply time on this WO for techs to fill documentation. Please do not go over	
4002-4	4871026	04/4002 - Cabin PAX seating removal and install for starlink access.	1.5 hours removed from parent WO, to apply time on this WO for techs to fill documentation. Please do not go over	
4002-5	4871031	05/4002 - Divan assembly W/end cabinets and storage , Removal and install for starlink access.	1.5 hours removed from parent WO, to apply time on this WO for techs to fill documentation.	
4002-6	4871738	06/4002 - Cabin sidewalls with PSU's LH and RH Removal and install for starllink access.	1.5 hours removed from parent WO, to apply time on this WO for techs to fill documentation. Please do not go over.	
4002-7	4871768	07/4002 - LH Arm ledge/Side ledge removal and install for starlink access.	1.5 hours removed from parent WO, to apply time on this WO for techs to fill documentation. Please do not go over	
4002-8	4871837	08/4002 - LH Aft cabin bulkhead removal and install for starlink access.	1.5 hours removed from parent WO, to apply time on this WO for techs to fill documentation. Please do not go over.	
4002-9	4871858	09/4002 - Lavatory Headliner removal and install for starlink access.	1.5 hours removed from parent WO, to apply time on this WO for techs to fill documentation. Please do not go over.	
4002-10	4871869	10/4002 - Lavtory vanity removal and install for starlink access.	1.5 hours removed from parent WO, to apply time on this WO for techs to fill documentation. Please do not go over.	
4002-11	4873021	11/4002 - INTERIOR AVIONICS FTS POST INTERIOR RESTORE FOR STARLINK .	16 hours removed from parent WO, to apply time on this WO for techs to fill documentation. Please do not go over.	

Sequence #	4002	Aircraft SN #	20590	MWPWO #	4843594
WO #	4846495	Aircraft Reg #	N786QS	Parent WO #	4843594

FINDINGS DETAILS

Finding #	Long Description	Status	Reported By / Date	Defect Source / Disposition	Defect Type	Priority	Follow-up WO #
83046	L/H FWD EXECUTIVE TABLE IS MISSING 1 fastener and 2 washers	QUEUED	B1018553 - Joshua Jackson Mar 4, 2026 8:11 AM	MAINTENANCE 300-QA002	OTHER	3	
83129	Found spinning isolator at L/H FS587.03 between PSU structure and aircraft structure	RDYLT	B1001500 - Victor Gallego Mar 4, 2026 4:14 PM	MAINTENANCE 300-QA002	OTHER	3	
83270	Upon removal of toilet enclosure it was discovered that the wire running to the Emer lights has an electrical connector J84152 to P854152 that has no retaining collar on it	QUEUED	B1018553 - Joshua Jackson Mar 5, 2026 11:55 AM	MAINTENANCE 300-QA002	OTHER	3	
83272	Upon removal of R/H aft pyramid cabinet it was found that 1 fastener was missing alligator nut	QUEUED	B1018553 - Joshua Jackson Mar 5, 2026 12:01 PM	MAINTENANCE 300-QA002	OTHER	3	

Sequence #	4002-1	**Aircraft SN #**	20590	**MWPWO #**	4843594
WO #	4870995	**Aircraft Reg #**	N786QS	**Parent WO #**	4846495

4002-1	**WO #**	**4870995**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		No Log Entry	
01/4002 - Entry headliner removal and install for starlink access.				

Sequence #	4002-1	Aircraft SN #	20590	MWPWO #	4843594
WO #	4870995	Aircraft Reg #	N786QS	Parent WO #	4846495

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			
	01/4002 - Entry headliner removal and install for starlink access.			
	200	Removed Entry Headliner REF: A/C 20590 SMM 25-10-03-000-801	B1018553 - Joshua Jackson Mar 03, 2026 08:47 PM	
	Remove Entry Headliner REF: A/C 20590 SMM 25-10-03-000-801		Not Required	
	300			
	Install Entry Headliner REF: A/C 20590 SMM 25-10-03-400-801			
	400	Removed passenger door header and Closeout REF: A/C 20590 SMM 25-10-03-000-801	B1018553 - Joshua Jackson Mar 03, 2026 08:47 PM	
	Remove passenger door header and Closeout REF: A/C 20590 SMM 25-10-03-000-801		Not Required	
	500			
	Install passenger door header and Closeout REF: A/C 20590 SMM 25-10-03-400-801			
	600	Removed entry to cabin curtain track REF: A/C 20590 SMM 25-10-03-000-801	B1018553 - Joshua Jackson Mar 03, 2026 08:47 PM	
	Remove entry to cabin curtain track REF: A/C 20590 SMM 25-10-03-000-801		Not Required	
	700			
	Install entry to cabin curtain track REF: A/C 20590 SMM 25-10-03-400-801			
	800	Removed Entry Curtain and track REF: A/C 20590 SMM 25-10-01-000-801	B1018553 - Joshua Jackson Mar 03, 2026 08:47 PM	
	Remove Entry Curtain and track REF: A/C 20590 SMM 25-10-01-000-801		Not Required	

Sequence #	4002-1	Aircraft SN #	20590	MWPWO #	4843594
WO #	4870995	Aircraft Reg #	N786QS	Parent WO #	4846495

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	900			
	Install Entry Curtain and track REF: A/C 20590 SMM 25-10-01-400-801			
	1000	Removed cockpit curtain and track REF: A/C 20590 SMM 25-10-05-000-801	B1018553 - Joshua Jackson Mar 03, 2026 08:47 PM	
	Remove cockpit curtain and track REF: A/C 20590 SMM 25-10-05-000-801		Not Required	
	1100			
	Install cockpit curtain and track REF: A/C 20590 SMM 25-10-05-400-801			
	1200	Removed the Fwd wardrobe closet header REF: A/C 20590 SMM 25-24-05-000-801	B1018553 - Joshua Jackson Mar 03, 2026 08:47 PM	
	Remove the Fwd wardrobe closet header REF: A/C 20590 SMM 25-24-05-000-801		Not Required	
	1300			
	Install the Fwd wardrobe closet header REF: A/C 20590 SMM 25-24-05-400-801			
	1400	Removed FWD Galley Header REF: A/C 20590 SMM 25-30-01-000-801	B1018553 - Joshua Jackson Mar 03, 2026 08:47 PM	
	Remove FWD Galley Header REF: A/C 20590 SMM 25-30-01-000-801		Not Required	
	1500			
	Install FWD Galley Header REF: A/C 20590 SMM 25-30-01-400-801			
	1600	Removed Upper Galley Header REF: A/C 20590 SMM 25-30-01-000-801	B1018553 - Joshua Jackson Mar 03, 2026 08:47 PM	
	Remove Upper Galley Header REF: A/C 20590 SMM 25-30-01-000-801		Not Required	

Sequence #	4002-1	Aircraft SN #	20590	MWPWO #	4843594
WO #	4870995	Aircraft Reg #	N786QS	Parent WO #	4846495

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	1700			
	Install Upper Galley Header REF: A/C 20590 SMM 25-30-01-400-801			

Sequence #	4002-2	**Aircraft SN #**	20590	**MWPWO #**	4843594
WO #	4871006	**Aircraft Reg #**	N786QS	**Parent WO #**	4846495

4002-2	**WO #**	**4871006**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		No Log Entry	
02/4002 - Entry wardrobe removal and install for starlink access.				

Sequence #	4002-2	Aircraft SN #	20590	MWPWO #	4843594
WO #	4871006	Aircraft Reg #	N786QS	Parent WO #	4846495

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100 02/4002 - Entry wardrobe removal and install for starlink access.			
	200 Remove fire extinguisher from FWD wardrobe cabinet REF: A/C 20590 SMM 25-24-05-000-801	Removed fire extinguisher from FWD wardrobe cabinet REF: A/C 20590 SMM 25-24-05-000-801	B1018553 - Joshua Jackson Mar 03, 2026 07:39 PM Not Required	
	300 Install fire extinguisher from FWD wardrobe cabinet REF: A/C 20590 SMM 25-24-05-400-801			
	400 Remove customer goods from the FWD wardrobe closet REF: A/C 20590 SMM TASK 25-24-05-000-801	Removed customer goods from the FWD wardrobe closet REF: A/C 20590 SMM TASK 25-24-05-000-801	B1018553 - Joshua Jackson Mar 03, 2026 07:39 PM Not Required	
	500 Install customer goods from the FWD wardrobe closet REF: A/C 20590 SMM TASK 25-24-05-400-801			
	600 Remove FWD. wardrobe closet REF: A/C 20590 SMM 25-24-05-000-801	Removed FWD. wardrobe closet REF: A/C 20590 SMM 25-24-05-000-801	B1018553 - Joshua Jackson Mar 03, 2026 07:39 PM Not Required	
	700 Install FWD. wardrobe closet REF: A/C 20590 SMM 25-24-05-400-801			
	800 Remove 3 EA upper and lower trim panels and air stair door lug covers from the FWD wardrobe cabinet REF :A/C 20590 SMM 25-24-05-000-801	Removed 3 EA upper and lower trim panels and air stair door lug covers from the FWD wardrobe cabinet REF :A/C 20590 SMM 25-24-05-000-801	B1018553 - Joshua Jackson Mar 03, 2026 07:39 PM Not Required	

Sequence #	4002-2	Aircraft SN #	20590	MWPWO #	4843594
WO #	4871006	Aircraft Reg #	N786QS	Parent WO #	4846495

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	900			
	Install 3 EA upper and lower trim panels and air stair door lug covers from the FWD wardrobe cabinet REF :A/C 20590 SMM 25-24-05-400-801			
	1000	Removed 2 EA L/H Avi Cabinet aft Panel Trim strips REF: A/C 20590 SMM 25-24-03-000-801	B1018553 - Joshua Jackson Mar 03, 2026 07:39 PM	
	Remove 2 EA L/H Avi Cabinet aft Panel Trim strips REF: A/C 20590 SMM 25-24-03-000-801		Not Required	
	1100			
	Install 2 EA L/H Avi Cabinet aft Panel Trim strips REF: A/C 20590 SMM 25-24-03-000-801			
	1200	Removed L/H Fwd Pyramid Cabinet Ref A/C: 20590 SMM 25-24-09-000-801	B1001500 - Victor Gallego Mar 03, 2026 09:24 PM	
	Remove L/H Fwd Pyramid Cabinet Ref A/C: 20590 SMM 25-24-09-000-801		Not Required	
	1300			
	Install L/H Fwd Pyramid Cabinet Ref A/C: 20590 SMM 25-24-09-400-801			
	1400	Removed L/H Fwd Pyramid Life Raft Ref A/C: 20590 SMM 25-24-09-000-801	B1001500 - Victor Gallego Mar 03, 2026 09:24 PM	
	Remove L/H Fwd Pyramid Life Raft Ref A/C: 20590 SMM 25-24-09-000-801		Not Required	
	1500			
	Install L/H Fwd Pyramid Life Raft Ref A/C: 20590 SMM 25-24-09-400-801			

Sequence #	4002-2	Aircraft SN #	20590	MWPWO #	4843594
WO #	4871006	Aircraft Reg #	N786QS	Parent WO #	4846495

REMOVE AND RE-INSTALL DETAILS

	Removed Part # Removed Serial #	Removed By	Removed - Part Description	Reference	Installed Part # Installed Serial #	Installed By
	Removed Status	**Removed Date-Time**	**Position**	**Installed Part Status**	**Installed Part Description**	**Installed Date-Time**
	30H673 I-48489446	B1018553 - Joshua Jackson	EXTINGUISHER, FIRE, PORTABLE	SMM TASK 25-24-05-000-801		
	SERVICEABLE	Mar 3, 2026 12:13 PM	CABIN			
	46FASA-6K2-1-20 1 4UL-02911	B1001500 - Victor Gallego	LIFERAFT, WINSLOW	SMM 25-24-09-000-801		
	SERVICEABLE	Mar 3, 2026 2:20 PM	CABIN			

Sequence #	4002-3	**Aircraft SN #**	20590	**MWPWO #**	4843594
WO #	4871018	**Aircraft Reg #**	N786QS	**Parent WO #**	4846495

4002-3	**WO #**	**4871018**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		No Log Entry	
03/4002 - Cabin flooring (Entry, Main cabin , Lavatory) removal and install for starlink access.				

Sequence #	4002-3	Aircraft SN #	20590	MWPWO #	4843594
WO #	4871018	Aircraft Reg #	N786QS	Parent WO #	4846495

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			
	03/4002 - Cabin flooring (Entry, Main cabin , Lavatory) removal and install for starlink access.			
	200	Removed entry to cabin threshold and block by removing the fasteners that secure it to the floor	B1018553 - Joshua Jackson Mar 03, 2026 07:58 PM	
	Remove entry to cabin threshold and block by removing the fasteners that secure it to the floor		Not Required	
	300			
	Install entry to cabin threshold and block by Installing the fasteners that secure it to the floor REF: BD-100 SPM 20-21-00-910-801			
	400	Removed entry threshold and block by removing the fasteners that secure it to the floor	B1018553 - Joshua Jackson Mar 03, 2026 07:58 PM	
	Remove entry threshold and block by removing the fasteners that secure it to the floor		Not Required	
	500			
	Install entry threshold and block by installing the fasteners that secure it to the floor REF: BD-100 SPM 20-21-00-910-801			
	600	Removed Entry Carpet and pad by disengaging hook and loop Velcro	B1018553 - Joshua Jackson Mar 03, 2026 07:58 PM	
	Remove Entry Carpet and pad by disengaging hook and loop Velcro		Not Required	
	700			
	Install Entry Carpet and pad by engaging hook and loop Velcro			

Sequence #	4002-3	Aircraft SN #	20590	MWPWO #	4843594
WO #	4871018	Aircraft Reg #	N786QS	Parent WO #	4846495

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	800	Removed Cabin Carpet and pad by disengaging hook and loop Velcro	B1001500 - Victor Gallego Mar 04, 2026 04:30 AM	
	Remove Cabin Carpet and pad by disengaging hook and loop Velcro		Not Required	
	900			
	Install Cabin Carpet and pad by engaging hook and loop Velcro			
	1000	Removed Under Divan Carpet and pad by disengaging hook and loop Velcro	B1001500 - Victor Gallego Mar 04, 2026 04:30 AM	
	Remove Under Divan Carpet and pad by disengaging hook and loop Velcro		Not Required	
	1100			
	Install Under Divan Carpet and pad by engaging hook and loop Velcro			
	1200	Removed (3ea) Cabin Throw Rugs As Required	B1001500 - Victor Gallego Mar 04, 2026 04:30 AM	
	Remove (3ea) Cabin Throw Rugs As Reqired		Not Required	
	1300			
	Install (3ea) Cabin Throw Rugs As Required			
	1400	Removed Cabin to LAV threshold and block by removing fastener that secure it to the floor	B1018553 - Joshua Jackson Mar 04, 2026 05:08 PM	
	Remove Cabin to LAV threshold and block by removing fastener that secure it to the floor		Not Required	
	1500			
	Install Cabin to LAV threshold and block by Installing fastener that secure it to the floor REF: BD-100 SPM 20-21-00-910-801			

Sequence #	4002-3	Aircraft SN #	20590	MWPWO #	4843594
WO #	4871018	Aircraft Reg #	N786QS	Parent WO #	4846495

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	1600	Removed lav carpet and pad by disengaging hook and loop velcro	B1018553 - Joshua Jackson Mar 04, 2026 05:08 PM	
	Remove lav carpet and pad by disengaging hook and loop velcro		Not Required	
	1700			
	Install lav carpet and pad by engaging hook and loop velcro			

Sequence #	4002-4	**Aircraft SN #**	20590	**MWPWO #**	4843594
WO #	4871026	**Aircraft Reg #**	N786QS	**Parent WO #**	4846495

4002-4	**WO #**	**4871026**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		No Log Entry	
04/4002 - Cabin PAX seating removal and install for starlink access.				

Sequence #	4002-4	Aircraft SN #	20590	MWPWO #	4843594
WO #	4871026	Aircraft Reg #	N786QS	Parent WO #	4846495

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100 04/4002 - Cabin PAX seating removal and install for starlink access.			
	200 Remove L/H #1 Single Seat Ref A/C: 20590 SMM 25-21-01-000-801	Removed L/H #1 Single Seat Ref A/C: 20590 SMM 25-21-01-000-801	B1001500 - Victor Gallego Mar 03, 2026 09:54 PM Not Required	
	300 Install L/H #1 Single Seat Ref A/C: 20590 SMM 25-21-01-400-801			
	400 Remove L/H #2 Single Seat Ref A/C: 20590 SMM 25-21-01-000-801	Removed L/H #2 Single Seat Ref A/C: 20590 SMM 25-21-01-000-801	B1001500 - Victor Gallego Mar 03, 2026 09:54 PM Not Required	
	500 Install L/H #2 Single Seat Ref A/C: 20590 SMM 25-21-01-400-801			
	600 Remove R/H #1 Single Seat Ref A/C: 20590 SMM 25-21-01-000-801	Removed R/H #1 Single Seat Ref A/C: 20590 SMM 25-21-01-000-801	B1001500 - Victor Gallego Mar 03, 2026 09:54 PM Not Required	
	700 Install R/H #1 Single Seat Ref A/C: 20590 SMM 25-21-01-400-801			
	800 Remove R/H #2 Single Seat Ref A/C: 20590 SMM 25-21-01-000-801	Removed R/H #2 Single Seat Ref A/C: 20590 SMM 25-21-01-000-801	B1001500 - Victor Gallego Mar 03, 2026 09:54 PM Not Required	

Sequence #	4002-4	Aircraft SN #	20590	MWPWO #	4843594
WO #	4871026	Aircraft Reg #	N786QS	Parent WO #	4846495

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	900			
	Install R/H #2 Single Seat Ref A/C: 20590 SMM 25-21-01-400-801			
	1000	Removed R/H #3 Single Seat Ref A/C: 20590 SMM 25-21-01-000-801	B1001500 - Victor Gallego Mar 03, 2026 09:54 PM	
	Remove R/H #3 Single Seat Ref A/C: 20590 SMM 25-21-01-000-801		Not Required	
	1100			
	Install R/H #3 Single Seat Ref A/C: 20590 SMM 25-21-01-400-801			
	1200	Removed R/H #4 Single Seat Ref A/C: 20590 SMM 25-21-01-000-801	B1001500 - Victor Gallego Mar 03, 2026 09:54 PM	
	Remove R/H #4 Single Seat Ref A/C: 20590 SMM 25-21-01-000-801		Not Required	
	1300			
	Install R/H #4 Single Seat Ref A/C: 20590 SMM 25-21-01-400-801			
	1400	Removed (2ea) L/H Seat Bases Ref A/C: 20590 SMM 25-21-01-000-801	B1001500 - Victor Gallego Mar 03, 2026 09:54 PM	
	Remove (2ea) L/H Seat Bases Ref A/C: 20590 SMM 25-21-01-000-801		Not Required	
	1500			
	Install (2ea) L/H Seat Bases Ref A/C: 20590 SMM 25-21-01-400-801			
	1600	Removed (4ea) R/H Seat Bases Ref A/C: 20590 SMM 25-21-01-000-801	B1001500 - Victor Gallego Mar 03, 2026 09:54 PM	
	Remove (4ea) R/H Seat Bases Ref A/C: 20590 SMM 25-21-01-000-801		Not Required	

Sequence #	4002-4	Aircraft SN #	20590	MWPWO #	4843594
WO #	4871026	Aircraft Reg #	N786QS	Parent WO #	4846495

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	1700			
	Install (4ea) R/H Seat Bases Ref A/C: 20590 SMM 25-21-01-400-801			

Sequence #	4002-4	Aircraft SN #	20590	MWPWO #	4843594
WO #	4871026	Aircraft Reg #	N786QS	Parent WO #	4846495

REMOVE AND RE-INSTALL DETAILS

	Removed Part # Removed Serial #	Removed By	Removed - Part Description	Reference	Installed Part # Installed Serial #	Installed By
	Removed Status	**Removed Date-Time**	**Position**	**Installed Part Status**	**Installed Part Description**	**Installed Date-Time**
	3A453-0050-201-1 77353	B1001500 - Victor Gallego	L/H #1 Single Seat	SMM 25-21-01-000-801		
	SERVICEABLE	Mar 3, 2026 2:27 PM	CABIN			
	3A453-0050-201-1 77353	B1001500 - Victor Gallego	R/H #1 Single Seat	SMM 25-21-01-000-801		
	SERVICEABLE	Mar 3, 2026 2:34 PM	CABIN			
	3A453-0045-301-1 77355	B1001500 - Victor Gallego	L/H #2 Single Seat	SMM 25-21-01-000-801		
		Mar 3, 2026 2:31 PM	CABIN			
	3A453-0046-302-1 77356	B1001500 - Victor Gallego	R/H #2 Single Seat	SMM 25-21-01-000-801		
	SERVICEABLE	Mar 3, 2026 2:37 PM	CABIN			
	3A453-0047-201-1 77357	B1001500 - Victor Gallego	R/H #3 Single Seat	SMM 25-21-01-000-801		
	SERVICEABLE	Mar 3, 2026 2:40 PM	CABIN			
	3A453-0048-201-1 77358	B1001500 - Victor Gallego	R/H #4 Single Seat	SMM 25-21-01-000-801		
	SERVICEABLE	Mar 3, 2026 2:44 PM	CABIN			

Sequence #	4002-5	**Aircraft SN #**	20590	**MWPWO #**	4843594
WO #	4871031	**Aircraft Reg #**	N786QS	**Parent WO #**	4846495

4002-5	**WO #**	**4871031**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		No Log Entry	
05/4002 - Divan assembly W/end cabinets and storage , Removal and install for starlink access.				

Sequence #	4002-5	Aircraft SN #	20590	MWPWO #	4843594
WO #	4871031	Aircraft Reg #	N786QS	Parent WO #	4846495

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			
	05/4002 - Divan assembly W/end cabinets and storage , Removal and install for starlink access.			
	200	Removed Fwd Divan End Cabinet Life Raft Ref A/C: 20590 SMM 25-24-13-000-801	B1001500 - Victor Gallego Mar 03, 2026 10:23 PM	
	Remove Fwd Divan End Cabinet Life Raft Ref A/C: 20590 SMM 25-24-13-000-801		Not Required	
	300			
	Install Fwd Divan End Cabinet Life Raft Ref A/C: 20590 SMM 25-24-13-400-801			
	400	Removed Fwd Divan End Cabinet Ref A/C: 20590 SMM 25-24-13-000-801	B1001500 - Victor Gallego Mar 03, 2026 10:23 PM	
	Remove Fwd Divan End Cabinet Ref A/C: 20590 SMM 25-24-13-000-801		Not Required	
	500			
	Install Fwd Divan End Cabinet Ref A/C: 20590 SMM 25-24-13-400-801			
	600	Removed Aft Divan End Cabinet Ref A/C: 20590 SMM 25-24-13-000-801	B1001500 - Victor Gallego Mar 03, 2026 10:23 PM	
	Remove Aft Divan End Cabinet Ref A/C: 20590 SMM 25-24-13-000-801		Not Required	
	700			
	Install Aft Divan End Cabinet Ref A/C: 20590 SMM 25-24-13-400-801			
	800	Removed Divan Front Fix Trim Ref A/C: 20590 SMM 25-21-03-000-801	B1001500 - Victor Gallego Mar 03, 2026 10:23 PM	
	Remove Divan Front Fix Trim Ref A/C: 20590 SMM 25-21-03-000-801		Not Required	

Sequence #	4002-5	Aircraft SN #	20590	MWPWO #	4843594
WO #	4871031	Aircraft Reg #	N786QS	Parent WO #	4846495

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	900			
	Install Divan Front Fix Trim Ref A/C: 20590 SMM 25-21-03-400-801			
	1000	Removed Fwd Divan Storage Box Ref A/C: 20590 SMM 25-21-03-000-801	B1001500 - Victor Gallego Mar 03, 2026 10:23 PM	
	Remove Fwd Divan Storage Box Ref A/C: 20590 SMM 25-21-03-000-801		Not Required	
	1100			
	Install Fwd Divan Storage Box Ref A/C: 20590 SMM 25-21-03-400-801			
	1200	Removed Mid Divan Storage Box Ref A/C: 20590 SMM 25-21-03-000-801	B1001500 - Victor Gallego Mar 03, 2026 10:23 PM	
	Remove Mid Divan Storage Box Ref A/C: 20590 SMM 25-21-03-000-801		Not Required	
	1300			
	Install Mid Divan Storage Box Ref A/C: 20590 SMM 25-21-03-400-801			
	1400	Removed Aft Divan Storage Box Ref A/C: 20590 SMM 25-21-03-000-801	B1001500 - Victor Gallego Mar 03, 2026 10:23 PM	
	Remove Aft Divan Storage Box Ref A/C: 20590 SMM 25-21-03-000-801		Not Required	
	1500			
	Install Aft Divan Storage Box Ref A/C: 20590 SMM 25-21-03-400-801			
	1600	Removed Fwd Divan Ref A/C: 20590 SMM 25-21-03-000-801	B1001500 - Victor Gallego Mar 03, 2026 10:23 PM	
	Remove Fwd Divan Ref A/C: 20590 SMM 25-21-03-000-801		Not Required	

Sequence #	4002-5	Aircraft SN #	20590	MWPWO #	4843594
WO #	4871031	Aircraft Reg #	N786QS	Parent WO #	4846495

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	1700			
	Install Fwd Divan Ref A/C: 20590 SMM 25-21-03-400-801			
	1800	Removed Mid Divan Ref A/C: 20590 SMM 25-21-03-000-801	B1001500 - Victor Gallego Mar 03, 2026 10:23 PM	
	Remove Mid Divan Ref A/C: 20590 SMM 25-21-03-000-801		Not Required	
	1900			
	Install Mid Divan Ref A/C: 20590 SMM 25-21-03-400-801			
	2000	Removed Aft Divan Ref A/C: 20590 SMM 25-21-03-000-801	B1001500 - Victor Gallego Mar 03, 2026 10:23 PM	
	Remove Aft Divan Ref A/C: 20590 SMM 25-21-03-000-801		Not Required	
	2100			
	Install Aft Divan Ref A/C: 20590 SMM 25-21-03-400-801			

Sequence #	4002-5	Aircraft SN #	20590	MWPWO #	4843594
WO #	4871031	Aircraft Reg #	N786QS	Parent WO #	4846495

REMOVE AND RE-INSTALL DETAILS

	Removed Part # Removed Serial #	Removed By	Removed - Part Description	Reference	Installed Part # Installed Serial #	Installed By
	Removed Status	**Removed Date-Time**	**Position**	**Installed Part Status**	**Installed Part Description**	**Installed Date-Time**
	46FASA-6K4-1-14 5 4UL-03170	B1001500 - Victor Gallego	LIFERAFT	SMM 25-24-13-000-801		
	SERVICEABLE	Mar 3, 2026 3:01 PM	CABIN			
	3A400-0061-304- 1 79738	B1001500 - Victor Gallego	Fwd Divan	SMM 25-21-03-000-801		
	SERVICEABLE	Mar 3, 2026 3:14 PM	CABIN			
	3A400-0063-304- 1 79738	B1001500 - Victor Gallego	Mid Divan	SMM 25-21-03-000-801		
	SERVICEABLE	Mar 3, 2026 3:17 PM	CABIN			
	3A400-0065-304- 1 79738	B1001500 - Victor Gallego	Aft Divan	SMM 25-21-03-000-801		
	SERVICEABLE	Mar 3, 2026 3:20 PM	CABIN			

Sequence #	4002-6	**Aircraft SN #**	20590	**MWPWO #**	4843594
WO #	4871738	**Aircraft Reg #**	N786QS	**Parent WO #**	4846495

4002-6	**WO #**	**4871738**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		No Log Entry	
06/4002 - Cabin sidewalls with PSU's LH and RH Removal and install for starllink access.				

Sequence #	4002-6	Aircraft SN #	20590	MWPWO #	4843594
WO #	4871738	Aircraft Reg #	N786QS	Parent WO #	4846495

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100 06/4002 - Cabin sidewalls with PSU's LH and RH Removal and install for starllink access.			
	200 Remove (2ea) R/H Upper PSU Cover Strips Ref A/C: 20590 SMM 25-26-03-010-801	Removed (2ea) R/H Upper PSU Cover Strips Ref A/C: 20590 SMM 25-26-03-010-801	B1001500 - Victor Gallego Mar 04, 2026 04:15 AM Not Required	
	300 Install (2ea) R/H Upper PSU Cover Strips Ref A/C: 20590 SMM 25-26-03-410-801			
	400 Remove (2ea) L/H Upper PSU Cover Strips Ref A/C: 20590 SMM 25-26-03-010-801	Removed (2ea) L/H Upper PSU Cover Strips Ref A/C: 20590 SMM 25-26-03-010-801	B1001500 - Victor Gallego Mar 04, 2026 04:15 AM Not Required	
	500 Install (2ea) L/H Upper PSU Cover Strips Ref A/C: 20590 SMM 25-26-03-410-801			
	600 Remove L/H Fwd PSU Ref A/C: 20590 SMM 25-26-03-000-801	Removed L/H Fwd PSU Ref A/C: 20590 SMM 25-26-03-000-801	B1001500 - Victor Gallego Mar 04, 2026 04:15 AM Not Required	
	700 Install L/H Fwd PSU Ref A/C: 20590 SMM 25-26-03-400-801			
	800 Remove L/H Aft PSU Ref A/C: 20590 SMM 25-26-03-000-801	Removed L/H Aft PSU Ref A/C: 20590 SMM 25-26-03-000-801	B1001500 - Victor Gallego Mar 04, 2026 04:15 AM Not Required	

Bombardier

Sequence #	4002-6	Aircraft SN #	20590	MWPWO #	4843594
WO #	4871738	Aircraft Reg #	N786QS	Parent WO #	4846495

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	900			
	Install L/H Aft PSU Ref A/C: 20590 SMM 25-26-03-400-801			
	1000	Removed R/H Fwd PSU Ref A/C: 20590 SMM 25-26-03-000-801	B1001500 - Victor Gallego Mar 04, 2026 04:15 AM	
	Remove R/H Fwd PSU Ref A/C: 20590 SMM 25-26-03-000-801		Not Required	
	1100			
	Install R/H Fwd PSU Ref A/C: 20590 SMM 25-26-03-400-801			
	1200	Removed R/H Aft PSU Ref A/C: 20590 SMM 25-26-03-000-801	B1001500 - Victor Gallego Mar 04, 2026 04:15 AM	
	Remove R/H Aft PSU Ref A/C: 20590 SMM 25-26-03-000-801		Not Required	
	1300			
	Install R/H Aft PSU Ref A/C: 20590 SMM 25-26-03-400-801			
	1400	Removed R/H side wall hand rail by removing the fasteners that secure it to the R/H sidewall	B1018553 - Joshua Jackson Mar 04, 2026 07:11 PM	
	Remove R/H side wall hand rail by removing the fasteners that secure it to the R/H sidewall		Not Required	
	1500			
	Installed R/H side wall hand rail by Installing the fasteners that secure it to the R/H sidewall REF: BD-100 SPM 20-21-00-910-801			
	1600	Removed R/H cabin indirect lights REF: A/C 20590 SMM 33-20-01-000-801	B1018553 - Joshua Jackson Mar 04, 2026 07:11 PM	
	Remove R/H cabin indirect lights REF: A/C 20590 SMM 33-20-01-000-801		B0142244 - Todd Bridges Mar 04, 2026 07:54 PM	

Sequence #	4002-6	Aircraft SN #	20590	MWPWO #	4843594
WO #	4871738	Aircraft Reg #	N786QS	Parent WO #	4846495

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	1700 Install R/H cabin indirect lights REF: A/C 20590 SMM 33-20-01-400-801			
	1800 Remove L/H Sidewall Ref A/C: 20590 SMM 25-26-11-000-801	Removed L/H Sidewall Ref A/C: 20590 SMM 25-26-11-000-801	B1001500 - Victor Gallego Mar 04, 2026 11:04 PM Not Required	
	1900 Install L/H Sidewall Ref A/C: 20590 SMM 25-26-11-400-801			
	2000 Remove L/H cabin indirect lights Ref A/C: 20590 SMM 33-20-01-000-801	Removed L/H cabin indirect lights Ref A/C: 20590 SMM 33-20-01-000-801	B1001500 - Victor Gallego Mar 04, 2026 11:04 PM Not Required	
	2100 Install L/H cabin indirect lights Ref A/C: 20590 SMM 33-20-01-400-801			
	2200 Remove Cabin Headliner Ref A/C: 20590 SMM 25-26-01-000-801	Removed Cabin Headliner Ref A/C: 20590 SMM 25-26-01-000-801	B1001500 - Victor Gallego Mar 04, 2026 11:04 PM Not Required	
	2300 Install Cabin Headliner Ref A/C: 20590 SMM 25-26-01-400-801			
	2400 Remove 12 EA insulation bags by removing tape and clips from F.S. 470.00-486.00	Removed 12 EA insulation bags by removing tape and clips from F.S. 470.00-486.00	B1018553 - Joshua Jackson Mar 05, 2026 04:10 PM Not Required	

Sequence #	4002-6	Aircraft SN #	20590	MWPWO #	4843594
WO #	4871738	Aircraft Reg #	N786QS	Parent WO #	4846495

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	2500			
	Install 12 EA insulation bags by Installing tape and clips from F.S. 470.00-486.00			
	2600	Removed 9 EA insulation bags by removing tape and clips from F.S. 486.00-501.00	B1018553 - Joshua Jackson Mar 05, 2026 04:10 PM	
	Remove 9 EA insulation bags by removing tape and clips from F.S. 486.00-501.00		Not Required	
	2700			
	Install 9 EA insulation bags by installing tape and clips from F.S. 486.00-501.00			
	2800	Removed 9 EA insulation bags by removing tape and clips from F.S. 454.00-470.00	B1018553 - Joshua Jackson Mar 05, 2026 04:10 PM	
	Remove 9 EA insulation bags by removing tape and clips from F.S. 454.00-470.00		Not Required	
	2900			
	Install 9 EA insulation bags by Installing tape and clips from F.S. 454.00-470.00			
	3000	Removed 9 EA insulation bags by removing tape and clips from F.S. 438.00-454.00	B1018553 - Joshua Jackson Mar 05, 2026 04:10 PM	
	Remove 9 EA insulation bags by removing tape and clips from F.S. 438.00-454.00		Not Required	
	3100			
	Install 9 EA insulation bags by Installing tape and clips from F.S. 438.00-454.00			

Sequence #	4002-7	**Aircraft SN #**	20590	**MWPWO #**	4843594
WO #	4871768	**Aircraft Reg #**	N786QS	**Parent WO #**	4846495

4002-7	**WO #**	**4871768**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		No Log Entry	
07/4002 - LH Arm ledge/Side ledge removal and install for starlink access.				

Sequence #	4002-7	Aircraft SN #	20590	MWPWO #	4843594
WO #	4871768	Aircraft Reg #	N786QS	Parent WO #	4846495

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100 07/4002 - LH Arm ledge/Side ledge removal and install for starlink access.			
	200 Remove L/H #1 Dado Ref A/C: 20590 SMM 25-26-09-000-801	Removed L/H #1 Dado Ref A/C: 20590 SMM 25-26-09-000-801	B1001500 - Victor Gallego Mar 04, 2026 04:40 AM Not Required	
	300 Install L/H #1 Dado Ref A/C: 20590 SMM 25-26-09-400-801			
	400 Remove L/H #2 Dado Ref A/C: 20590 SMM 25-26-09-000-801	Removed L/H #2 Dado Ref A/C: 20590 SMM 25-26-09-000-801	B1001500 - Victor Gallego Mar 04, 2026 04:40 AM Not Required	
	500 Install L/H #2 Dado Ref A/C: 20590 SMM 25-26-09-400-801			
	600 Remove L/H #3 Dado Ref A/C: 20590 SMM 25-26-09-000-801	Removed L/H #3 Dado Ref A/C: 20590 SMM 25-26-09-000-801	B1001500 - Victor Gallego Mar 04, 2026 04:40 AM Not Required	
	700 Install L/H #3 Dado Ref A/C: 20590 SMM 25-26-09-400-801			
	800 Remove L/H #4 Dado Ref A/C: 20590 SMM 25-26-09-000-801	Removed L/H #4 Dado Ref A/C: 20590 SMM 25-26-09-000-801	B1001500 - Victor Gallego Mar 04, 2026 04:40 AM Not Required	

Sequence #	4002-7	Aircraft SN #	20590	MWPWO #	4843594
WO #	4871768	Aircraft Reg #	N786QS	Parent WO #	4846495

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	900			
	Install L/H #4 Dado Ref A/C: 20590 SMM 25-26-09-400-801			
	1000	Removed 13 EA insulation bags from behind L/H Dado panels by removing them from there designated area	B1018553 - Joshua Jackson Mar 04, 2026 03:41 PM	
	Remove 13 EA insulation bags from behind L/H Dado panels by removing them from there designated area		Not Required	
	1100			
	Install 13 EA insulation bags from behind L/H Dado panels by installing them to there designated area			
	1200	Removed L/H executive table REF: A/C 20590 SMM 25-25-03-000-801	B1018553 - Joshua Jackson Mar 04, 2026 03:41 PM	
	Remove L/H executive table REF: A/C 20590 SMM 25-25-03-000-801		Not Required	
	1300			
	Install L/H executive table REF: A/C 20590 SMM 25-25-03-400-801			
	1400	Removed 5 EA L/H Storage Boxes REF: A/C 20590 SMM 25-26-07-000-801	B1018553 - Joshua Jackson Mar 04, 2026 03:41 PM	
	Remove 5 EA L/H Storage Boxes REF: A/C 20590 SMM 25-26-07-000-801		Not Required	
	1500			
	Install 5 EA L/H Storage Boxes REF: A/C 20590 SMM 25-26-07-400-801			

Sequence #	4002-8	**Aircraft SN #**	20590	**MWPWO #**	4843594
WO #	4871837	**Aircraft Reg #**	N786QS	**Parent WO #**	4846495

4002-8	**WO #**	**4871837**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		No Log Entry	
08/4002 - LH Aft cabin bulkhead removal and install for starlink access.				

Sequence #	4002-8	Aircraft SN #	20590	MWPWO #	4843594
WO #	4871837	Aircraft Reg #	N786QS	Parent WO #	4846495

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100 08/4002 - LH Aft cabin bulkhead removal and install for starlink access.			
	200 Remove L/H AFT Cabin Partition FWD panel REF: A/C 20590 SMM 25-23-01-000-801	Removed L/H AFT Cabin Partition FWD panel REF: A/C 20590 SMM 25-23-01-000-801	B1018553 - Joshua Jackson Mar 04, 2026 05:00 PM Not Required	
	300 Install L/H AFT Cabin Partition FWD panel REF: A/C 20590 SMM 25-23-01-400-801			
	400 Remove L/H AFT Cabin Partition AFT panel with pocket door REF: A/C 20590 SMM 25-23-01-000-801	Removed L/H AFT Cabin Partition AFT panel with pocket door REF: A/C 20590 SMM 25-23-01-000-801	B1018553 - Joshua Jackson Mar 04, 2026 05:00 PM Not Required	
	500 Install L/H AFT Cabin Partition AFT panel with pocket door REF: A/C 20590 SMM 25-23-01-400-801			
	600 Remove R/H AFT Cabin Partition REF: A/C 20590 SMM 25-23-01-000-801	Removed R/H AFT Cabin Partition REF: A/C 20590 SMM 25-23-01-000-801	B1018553 - Joshua Jackson Mar 05, 2026 07:55 PM B0142244 - Todd Bridges Mar 05, 2026 08:09 PM	
	700 Install R/H AFT Cabin Partition REF: A/C 20590 SMM 25-23-01-400-801			
	800 Remove R/H Aft cabin Pyramid cabinet REF: A/C 20590 SMM 25-24-09-000-801	Removed R/H Aft cabin Pyramid cabinet REF: A/C 20590 SMM 25-24-09-000-801	B1021707 - Miguel Dicochea Mar 05, 2026 08:35 PM Not Required	

Sequence #	4002-8	Aircraft SN #	20590	MWPWO #	4843594
WO #	4871837	Aircraft Reg #	N786QS	Parent WO #	4846495

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	900			
	Install R/H Aft cabin Pyramid cabinet REF: A/C 20590 SMM 25-24-09-400-801			
	1000	Removed R/H Baggage Bulkhead Outboard Deco Panel REF: A/C 20590 SMM 25-53-01-000-801	B1021707 - Miguel Dicochea Mar 05, 2026 08:35 PM	
	Remove R/H Baggage Bulkhead Outboard Deco Panel REF: A/C 20590 SMM 25-53-01-000-801		Not Required	
	1100			
	Install R/H Baggage Bulkhead Outboard Deco Panel REF: A/C 20590 SMM 25-53-01-400-801			
	1200	Removed R/H Baggage Bulkhead outboard panel REF: A/C 20590 SMM 25-53-01-000-801	B1021707 - Miguel Dicochea Mar 05, 2026 08:35 PM	
	Remove R/H Baggage Bulkhead outboard panel REF: A/C 20590 SMM 25-53-01-000-801		Not Required	
	1300			
	Install R/H Baggage Bulkhead outboard panel REF: A/C 20590 SMM 25-53-01-400-801			

Sequence #	4002-9	**Aircraft SN #**	20590	**MWPWO #**	4843594
WO #	4871858	**Aircraft Reg #**	N786QS	**Parent WO #**	4846495

4002-9	**WO #**	**4871858**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		No Log Entry	
09/4002 - Lavatory Headliner removal and install for starlink access.				

Sequence #	4002-9	Aircraft SN #	20590	MWPWO #	4843594
WO #	4871858	Aircraft Reg #	N786QS	Parent WO #	4846495

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100 09/4002 - Lavatory Headliner removal and install for starlink access.			
	200 Remove Toilet side panel hand rail REF: A/C 20590 SMM 25-41-05-000-801	Removed Toilet side panel hand rail REF: A/C 20590 SMM 25-41-05-000-801	B1021707 - Miguel Dicochea Mar 04, 2026 08:54 PM Not Required	
	300 Install Toilet side panel hand rail REF: A/C 20590 SMM 25-41-05-400-801			
	400 Remove Lav Headliner REF: A/C 20590 SMM 25-41-05-000-801	Removed Lav Headliner REF: A/C 20590 SMM 25-41-05-000-801	B1021707 - Miguel Dicochea Mar 04, 2026 08:54 PM Not Required	
	500 Install Lav Headliner REF: A/C 20590 SMM 25-41-05-400-801			
	600 Remove Lav Contact Pad REF: A/C 20590 SMM 44-22-05-000-801	Removed Lav Contact Pad REF: A/C 20590 SMM 44-22-05-000-801	B1021707 - Miguel Dicochea Mar 04, 2026 08:54 PM Not Required	
	700 Install Lav Contact Pad REF: A/C 20590 SMM 44-22-05-400-801			
	800 Remove Vanity Work Surface Light And Lens REF: A/C 20590 SMM 33-26-07-000-801	Removed Vanity Work Surface Light And Lens REF: A/C 20590 SMM 33-26-07-000-801	B1021707 - Miguel Dicochea Mar 04, 2026 08:54 PM Not Required	

Sequence #	4002-9	Aircraft SN #	20590	MWPWO #	4843594
WO #	4871858	Aircraft Reg #	N786QS	Parent WO #	4846495

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	900			
	Install Vanity Work Surface Light And Lens REF: A/C 20590 SMM 33-26-07-400-801			
	1000	Removed Cabin To Lav Header REF: A/C 20590 SMM 25-23-01-000-801	B1021707 - Miguel Dicochea Mar 04, 2026 08:54 PM	
	Remove Cabin To Lav Header REF: A/C 20590 SMM 25-23-01-000-801		Not Required	
	1100			
	Install Cabin To Lav Header REF: A/C 20590 SMM 25-23-01-400-801			

Sequence #	4002-10	**Aircraft SN #**	20590	**MWPWO #**	4843594
WO #	4871869	**Aircraft Reg #**	N786QS	**Parent WO #**	4846495

4002-10	**WO #**	**4871869**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		No Log Entry	
10/4002 - Lavtory vanity removal and install for starlink access.				

Sequence #	4002-10	Aircraft SN #	20590	MWPWO #	4843594
WO #	4871869	Aircraft Reg #	N786QS	Parent WO #	4846495

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100 10/4002 - Lavtory vanity removal and install for starlink access.			
	200 Remove potable water tank REF: A/C 20590 SMM 38-10-01-000-801	Removed potable water tank REF: A/C 20590 SMM 38-10-01-000-801	B1018553 - Joshua Jackson Mar 04, 2026 08:19 PM Not Required	
	300 Install potable water tank REF: A/C 20590 SMM 38-10-01-400-801			
	400 Remove lav Vanity REF: A/C 20590 SMM 25-41-01-000-801	Removed lav Vanity REF: A/C 20590 SMM 25-41-01-000-801	B1021707 - Miguel Dicochea Mar 04, 2026 09:00 PM Not Required	
	500 Install lav Vanity REF: A/C 20590 SMM 25-41-01-400-801			
	600 Remove Customer goods from lav vanity as required 1 30x30 bag and 3 totes REF: A/C 20590 SMM 25-41-01-000-801	Removed Customer goods from lav vanity as required 1 30x30 bag and 3 totes REF: A/C 20590 SMM 25-41-01-000-801	B1021707 - Miguel Dicochea Mar 04, 2026 09:00 PM Not Required	
	700 Install Customer goods to lav vanity as required 1 30x30 bag and 3 totes REF: A/C 20590 SMM 25-41-01-000-801			

Sequence #	4002-10	Aircraft SN #	20590	MWPWO #	4843594
WO #	4871869	Aircraft Reg #	N786QS	Parent WO #	4846495

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	800	Removed 1 Shelf from Aft side of lav vanity REF: A/C 20590 SMM 25-41-01-000-801	B1021707 - Miguel Dicochea Mar 04, 2026 09:00 PM	
	Remove 1 Shelf from Aft side of lav vanity REF: A/C 20590 SMM 25-41-01-000-801		Not Required	
	900			
	Install 1 Shelf from Aft side of lav vanity REF: A/C 20590 SMM 25-41-01-000-801			
	1000	Removed 5EA Drawers from lav vanity REF: A/C 20590 SMM 25-41-01-000-801	B1021707 - Miguel Dicochea Mar 04, 2026 09:00 PM	
	Remove 5EA Drawers from lav vanity REF: A/C 20590 SMM 25-41-01-000-801		Not Required	
	1100			
	Install 5EA Drawers from lav vanity REF: A/C 20590 SMM 25-41-01-400-801			
	1200	Removed Aft Vanity closeout REF: A/C 20590 SMM 25-41-01-000-801	B1021707 - Miguel Dicochea Mar 04, 2026 09:00 PM	
	Remove Aft Vanity closeout REF: A/C 20590 SMM 25-41-01-000-801		Not Required	
	1300			
	Install Aft Vanity closeout REF: A/C 20590 SMM 25-41-01-400-801			
	1400	Removed 2 EA vanity doors REF: A/C 20590 SMM 25-41-01-000-801	B1021707 - Miguel Dicochea Mar 04, 2026 09:00 PM	
	Remove 2 EA vanity doors REF: A/C 20590 SMM 25-41-01-000-801		Not Required	
	1500			
	Install 2 EA vanity doors REF: A/C 20590 SMM 25-41-01-400-801			

Sequence #	4002-10	Aircraft SN #	20590	MWPWO #	4843594
WO #	4871869	Aircraft Reg #	N786QS	Parent WO #	4846495

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	1600	Removed Vanity Mirror REF: A/C 20590 SMM 25-41-01-000-801	B1021707 - Miguel Dicochea Mar 04, 2026 09:00 PM	
	Remove Vanity Mirror REF: A/C 20590 SMM 25-41-01-000-801		Not Required	
	1700			
	Install Vanity Mirror REF: A/C 20590 SMM 25-41-01-400-801			
	1800	Removed Vanity Mirror Lights REF: A/C 20590 SMM 33-26-01-000-801	B1021707 - Miguel Dicochea Mar 04, 2026 09:00 PM	
	Remove Vanity Mirror Lights REF: A/C 20590 SMM 33-26-01-000-801		Not Required	
	1900			
	Install Vanity Mirror Lights REF: A/C 20590 SMM 33-26-01-400-801			
	2000	Removed Vanity Upper Trim REF: A/C 20590 SMM 25-41-01-000-801	B1021707 - Miguel Dicochea Mar 04, 2026 09:00 PM	
	Remove Vanity Upper Trim REF: A/C 20590 SMM 25-41-01-000-801		Not Required	
	2100			
	Install Vanity Upper Trim REF: A/C 20590 SMM 25-41-01-400-801			
	2200	Removed Vanity Water Purge cover REF: A/C 20590 SMM 25-41-01-000-801	B1021707 - Miguel Dicochea Mar 05, 2026 08:37 PM	
	Remove Vanity Water Purge cover REF: A/C 20590 SMM 25-41-01-000-801		Not Required	
	2300			
	Install Vanity Water Purge cover REF: A/C 20590 SMM 25-41-01-400-801			

Sequence #	4002-10	Aircraft SN #	20590	MWPWO #	4843594
WO #	4871869	Aircraft Reg #	N786QS	Parent WO #	4846495

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	2400	Removed Vanity Sidewall REF: A/C 20590 SMM 25-41-07-000-801	B1021707 - Miguel Dicochea Mar 05, 2026 08:37 PM	
	Remove Vanity Sidewall REF: A/C 20590 SMM 25-41-07-000-801		Not Required	
	2500			
	Install Vanity Sidewall REF: A/C 20590 SMM 25-41-07-400-801			
	2600	Removed 2 EA toilet enclosure drawers REF: A/C 20590 SMM 25-41-03-000-801	B1018553 - Joshua Jackson Mar 05, 2026 08:09 PM	
	Remove 2 EA toilet enclosure drawers REF: A/C 20590 SMM 25-41-03-000-801		Not Required	
	2700			
	Install 2 EA toilet enclosure drawers REF: A/C 20590 SMM 25-41-03-400-801			
	2800	Removed 3 Ea toilet seat back and arm rest cushions REF: A/C 20590 SMM 25-41-03-000-801	B1018553 - Joshua Jackson Mar 05, 2026 08:09 PM	
	Remove 3 Ea toilet seat back and arm rest cushions REF: A/C 20590 SMM 25-41-03-000-801		Not Required	
	2900			
	Install 3 Ea toilet seat back and arm rest cushions REF: A/C 20590 SMM 25-41-03-400-801			
	3000	Removed Lav Toilet Enclosure REF: A/C 20590 SMM 25-41-03-000-801	B1018553 - Joshua Jackson Mar 05, 2026 08:09 PM	
	Remove Lav Toilet Enclosure REF: A/C 20590 SMM 25-41-03-000-801		Not Required	
	3100			
	Install Lav Toilet Enclosure REF: A/C 20590 SMM 25-41-03-400-801			

Sequence #	4002-10	**Aircraft SN #**	20590	**MWPWO #**	4843594
WO #	4871869	**Aircraft Reg #**	N786QS	**Parent WO #**	4846495

REMOVE AND RE-INSTALL DETAILS

	Removed Part # Removed Serial #	Removed By	Removed - Part Description	Reference	Installed Part # Installed Serial #	Installed By
	Removed Status	**Removed Date-Time**	**Position**	**Installed Part Status**	**Installed Part Description**	**Installed Date-Time**
	09-400303-002 1134	B1018553 - Joshua Jackson	TANK, VANITY, 4.0 USG, PVDF	SMM 38-10-01-000-801		
	SERVICEABLE	Mar 4, 2026 1:20 PM	AFTER			

Bombardier

Sequence #	4002-11	Aircraft SN #	20590	MWPWO #	4843594
WO #	4873021	Aircraft Reg #	N786QS	Parent WO #	4846495

4002-11	WO #	4873021	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		No Log Entry	
11/4002 - INTERIOR AVIONICS FTS POST INTERIOR RESTORE FOR STARLINK .				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			
	11/4002 - INTERIOR AVIONICS FTS POST INTERIOR RESTORE FOR STARLINK .			

Sequence #	4003	**Aircraft SN #**	20590	**MWPWO #**	4843594
WO #	4893545	**Aircraft Reg #**	N786QS	**Parent WO #**	4843594

4003	**WO #**	**4893545**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		No Log Entry	
Fwd rh O2 psu cover need adjustment/resecuring				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			
	Fwd rh O2 psu cover need adjustment/resecuring			

Sequence #	4004	Aircraft SN #	20590	MWPWO #	4843594
WO #	4893557	Aircraft Reg #	N786QS	Parent WO #	4843594

4004	WO #	4893557	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		No Log Entry	
Window Shade behind Divan had FOD Between window bucket lenses. (Requires opening window shade, celaning and closeup)				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			
	Window Shade behind Divan had FOD Between window bucket lenses. (Requires opening window shade, celaning and closeup)			

Sequence #	4005	**Aircraft SN #**	20590	**MWPWO #**	4843594
WO #	4893540	**Aircraft Reg #**	N786QS	**Parent WO #**	4843594

4005	**WO #**	**4893540**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #	13519075	No Log Entry	
PAX door Stair Tread Material replacement w/Glow placards				

OPERATIONAL DETAILS

	Operation # / **Operation Description**	**Corrective Action Long Description**	**Tech Sign Off** / **Insp Sign Off**	**ATA Code** / **Reason for Work**
	100			
	PAX door Stair Tread Material replacement w/Glow placards			

Sequence #	5001	Aircraft SN #	20590	MWPWO #	4843594
WO #	4843803	Aircraft Reg #	N786QS	Parent WO #	4843594

5001	WO #	4843803	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13512365	No Log Entry	
GENERAL PAINT TOUCH UP (BRUSH ONLY)				
Task / IRN # : GENERAL PAINT TOUCH UP (BRUSH)				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			05-00
	Perform GENERAL PAINT TOUCH UP (BRUSH ONLY)			

Bombardier

Sequence #	6501	Aircraft SN #	20590	MWPWO #	4843594
WO #	4850224	Aircraft Reg #	N786QS	Parent WO #	4843594

6501	WO #	4850224	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13513311	No Log Entry	
Work Finalizing / RTS				
Task / IRN # : POST				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	200			
	Enable ADS-B System		Not Required	
	300			
	Approve Aircraft to RTS		Not Required	
	400			
	Perform Final Walk Around Clear customer property and parts cages Clear interior parts/parts racks Install all customer property and panels Perform Final Walk around of the Aircraft Interior and Exterior Prior to RTS			

CHILD WORK ORDER DETAILS

	WO #	Description	Corrective Action	AMENDED
6501-1	4850225	A/C Final Close-Up		
6501-2	4850233	Open Access Panels		
6501-3	4850235	Close Access Panels		

Bombardier

Sequence #	6501-1	Aircraft SN #	20590	MWPWO #	4843594
WO #	4850225	Aircraft Reg #	N786QS	Parent WO #	4850224

6501-1	WO #	4850225	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		No Log Entry	
A/C Final Close-Up				
Task / IRN # : AC FINAL-CLOSE				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			
	Clean the Aircraft		Not Required	
	300			
	Perform Post Mechanical Check		Not Required	
	400			
	Perform Outgoing Avionics/Electrical Inspection Checklist		Not Required	

Bombardier

Sequence #	6501-2	Aircraft SN #	20590	MWPWO #	4843594
WO #	4850233	Aircraft Reg #	N786QS	Parent WO #	4850224

6501-2	WO #	4850233	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #		No Log Entry	
Open Access Panels				
Task / IRN # : ACCESS-OPEN				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			20-00
	Open Access Panels			

Sequence #	6501-3	**Aircraft SN #**	20590	**MWPWO #**	4843594
WO #	4850235	**Aircraft Reg #**	N786QS	**Parent WO #**	4850224

6501-3	**WO #**	**4850235**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #		No Log Entry	
Close Access Panels				
Task / IRN # : ACCESS-CLOSE				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			20-00
	Close Access Panels			

Bombardier

Sequence #	6502	Aircraft SN #	20590	MWPWO #	4843594
WO #	4843774	Aircraft Reg #	N786QS	Parent WO #	4843594

6502	WO #	4843774	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13512366	No Log Entry	
05104 (REVIEW RII REQ REL FOR COMPLIANCE (SCHEDULED))				
Task / IRN # : 05104				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			05-00
	Perform REVIEW RII REQ REL FOR COMPLIANCE (SCHEDULED)			

Bombardier

Sequence #	6503	Aircraft SN #	20590	MWPWO #	4843594
WO #	4843770	Aircraft Reg #	N786QS	Parent WO #	4843594

6503	WO #	4843770	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13512324	No Log Entry	
Paperwork, Processing, Administrative Fees, and RTS (Billing Only)				
Task / IRN # : RTS-BILLING ONLY				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			05-00
	Paperwork, Processing, Administrative Fees, and RTS (Signoff Requirements)			

Sequence #	7001	**Aircraft SN #**	20590	**MWPWO #**	4843594
WO #	4843772	**Aircraft Reg #**	N786QS	**Parent WO #**	4843594

7001	**WO #**	**4843772**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #	13512347	No Log Entry	
Admin squawk for floor Crew Chief- no charge customer-no maintenance performed.				
Task / IRN # : 05-00				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			05-00
	Admin squawk for floor Crew Chief- no charge customer-no maintenance performed.		Not Required	

Sequence #	7501	**Aircraft SN #**	20590	**MWPWO #**	4843594
WO #	4843765	**Aircraft Reg #**	N786QS	**Parent WO #**	4843594

7501	**WO #**	**4843765**	**LOG BOOK VERBIAGE**	**Deferrals**
	SAP SVO #	13512345	No Log Entry	
FUELING REQUIREMENTS (BILLING ONLY)				
Task / IRN # : 7501				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			05-00
	Perform FUELING REQUIREMENTS (BILLING ONLY)			

Bombardier

Sequence #	8001	Aircraft SN #	20590	MWPWO #	4843594
WO #	4880377	Aircraft Reg #	N786QS	Parent WO #	4843594

8001	WO #	4880377	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13517430	No Log Entry	
L/H MLG lower wheel bin has multiple fastener plates corroded - pn # 1005342821-005				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			
	L/H MLG lower wheel bin has multiple fastener plates corroded - pn # 1005342821-005			

Bombardier

Sequence #	8002	Aircraft SN #	20590	MWPWO #	4843594
WO #	4889726	Aircraft Reg #	N786QS	Parent WO #	4843594

8002	WO #	4889726	LOG BOOK VERBIAGE	Deferrals
	SAP SVO #	13518498	No Log Entry	
Iridium antenna and spacer require replacement. Upon removal of Iridium antenna and spacer for relocation, found signs of possible corrosion on both components and Aircraft Skin.				

OPERATIONAL DETAILS

	Operation # / Operation Description	Corrective Action Long Description	Tech Sign Off / Insp Sign Off	ATA Code / Reason for Work
	100			
	Communications - Modification - Starlink High-Speed Satcom installation without cockpit WLAN Switch per FAA STC ST11935CH (350/3500) - NetJets only			