

TESTING THE .up Files AFTER YOU DOWNLOADED AND BEFORE YOU INSTALL THEM.

MAZDA FIRMWARE IN MAZDA/MZD CONNECT.

TESTING PRIOR TO FIRMWARE INSTALLATION OF CP/AA....CP/AA is Car Play and Android Auto.

IF YOU WANT TO BE **101% CERTAIN** THAT YOUR TWO FIRMWARE FILES .up DOWNLOADED PLUS YOUR HARDWARE TO INSTALL NEW FIRMWARE IS **101% CORRECT**, RELIABLE AND TESTED, **do this.**

ALL HARDWARE LIKE 'USB FLASH DRIVES' or 'USB THUMB DRIVES' CAN OR DO BECOME DEFECTIVE and CAN Corrupt your INSTALLATION PROCESS.

So BEFORE YOU SAY YOU ARE READY TO DO THIS MAJOR 70.00.021x FIRMWARE UPGRADE....

1. HAVE YOU TESTED YOUR Two SEPARATE .up CP/AA FILE Integrity You Just DOWNLOADED.

2. HAVE YOU TESTED YOUR USB FLASH DRIVE EQUIPMENT ?.. I bet that is a no.

This is either a YES or a NO, if it is a NO, THEN WE STRONGLY ADVISE THAT **YOU 'TEST' IT ALL....first.**

LET'S START...

The Two .up FIRMWARE FILES YOU DOWNLOADED to your Desktop, Must have their Checksum Hash # verified, this will tell you **'if'** each file was **corrupted during your download** either by your Internet Provider by line stalling or possibly your PC had a power supply interruption or hiccup, or ?

Many issues can cause 'A' installation issue with MZD Mazda Connect.

What you need to do is download this very small **Checksum Utility** which is available in the **Hi-Drive Server** URL link in Post #2 in 3 Revolution Forum. In this Server go to the **'MAZDA_FIRMWARE'** Folder, then to **'y Checksum'** Folder and you will see within the **'Checksum_Utility.rar'**, download this small .rar app and un-zip and run it, then see the **'2. Instructions MD5 HASH.txt'**.

The **HASH Value String Numbers** are separately listed in each .txt for **NA N, EU N, 4A N** Firmware.

Here is the 100% correct **CHECKSUM String #** for **70.00.021A 4A N (ADR).. SHA-1 Hash.**

cmu150_ADR_70.00.021A_failsafe.up is **657707D0B7D68C5471DAFB23CF8F1A5A8840346E**

cmu150_ADR_70.00.021A_reinstall.up is **E9B3A17D33666DD130F007C6E77E4F77DBBC3806**

So, the Correct **HASH String #** is **red** for those two files, you **VERIFY** the **'Calculated String'** from your newly Downloaded .up files, once app has scanned you will see **4 different values #**, **Paste the red** 100% correct **Failsafe Hash String** above **FIRST** in the **'Verify Hash'** box, click on **'Verify'**, you will see a **POP-UP Window** which will say either **'SHA-1 Hash matched'** or a **'Hash does not match!'**.

IF your Hash Values 'matched' then all is **good to go and use** your Downloaded **failsafe .up** File, do the exact same process with the **reinstall.up** File and it's **red string #**.

IF you are getting pop up '**Hash does not match**' means **THAT FILE MUST NOT BE USED** as it was corrupted when you downloaded it, **you MUST Delete this File**, **reboot your PC** and Download the File you need **AGAIN**, then recheck the **SHA-1 Hash** again so it matches, a **Matching # STRING** means your file is good to go and use to update your **Mazda Connect FIRMWARE**.

Naturally the **HASH String #** will be and is different for **NA N** and **EU N 70.00.021x.up TWO Files**.

NEXT, TESTING OF YOUR 'USB FLASH DRIVE' HARDWARE.

THERE IS A SMALL .exe File called **H2testw**, this file Tests the integrity of your USB Flash Drive as it '**WRITE + VERIFY**' randomly tests data onto your selected Flash Drive and then READs this written Data for errors, losses, corruption and Read/Write Speeds, etc.

Download App (.zip) from Server in Folder '**x H2TESTW USB Drive Tester**' extract and run.

You can select to test the entire USB Flash Drive or choose a random volume of Data within Drive to be tested.

IF YOU SELECT TO TEST ENTIRE FLASH DRIVE THIS CAN TAKE SOME TIME, BUT IT IS THE MOST COMPREHENSIVE TEST OF THIS SPECIFIC HARDWARE.

Below is a TEST REPORT of a USB Flash Drive which failed the **H2testw.exe**, I Only Tested **20MB** as I know this USB is a cheap no name China sold piece of rubbish that is defective.

The Report After Test Run...

Warning: Only 20 of 199986 MByte tested.

The media is likely to be defective.

18 MByte OK (36864 sectors)

2 MByte DATA LOST (4096 sectors)

Details: 0 KByte overwritten (0 sectors)

0 KByte slightly changed (< 8 bit/sector, 0 sectors)

2 MByte corrupted (4096 sectors)

0 KByte aliased memory (0 sectors)

First error at offset: 0x000000001044000

Expected: 0x000000001044000

Found: 0xffffffffffffff

H2testw version 1.3

Writing speed: 155 KByte/s

Reading speed: 9.97 MByte/s H2testw v1.4

MAKE SURE YOU DELETE ALL OF THE WRITTEN 'TEST FILES' NOW IN YOUR USB FLASH DRIVE AFTER THE H2testw testing App HAS FINISHED AND ISSUED a POP-UP REPORT.

AFTER YOU HAVE RUN AND TESTED A GOOD USB FLASH DRIVE, YOU WILL USUALLY SEE A GREEN or Go is GOOD REPORT ABOUT YOUR FLASH DRIVE TELLING YOU IT IS OK TO USE.

IF YOU SEE A RED BACKGROUND REPORT POP UP LIKE THE REPORT ABOVE THEN YOU KNOW **DO NOT TO USE THIS PARTICULAR USB FLASH DRIVE.**

IF 'USB Drive' FAILS TEST **DO NOT USE IT** TO UPDATE YOUR MZD MAZDA CONNECT.

PURCHASE A GOOD QUALITY NAMED **USB FLASH DRIVE OF ABOUT 16GB**, USB DRIVES WHICH ARE OVER 32-64GB in capacity can be too large as CMU PROCESSOR SOMETIMES WILL NOT SEE THE .up FILES loaded onto it.

AGAIN, JUST MAKE SURE YOU CLEAN THE DRIVE OF ALL THE 'TEST FILES' AND THEN YOU CAN LOAD YOUR TWO NEW .up 70.00.021 Files YOU PREVIOUSLY **Checksum Hash #** tested.

This is about the best you can do to ensure your two **.up Files and USB Flash Drive** are all good to use and use to update your MAZDA CMU with new CP/AA FIRMWARE.

AGAIN, Make sure you follow the new **2018 CMU FIRMWARE UPDATE PROCEDURE-WORLDWIDE** and the **#1 to #30** items listed within.

INSTALL NOT SUCCESSFUL -SYSTEM FAILURE

DO NOT START ENGINE OR DRIVE CAR UNTIL YOU HAVE DONE THESE CMU RESCUE ATTEMPTS LISTED BELOW....

NOTE: IF YOU ARE SEEING THE FOLLOWING SCREENS BELOW YOU EITHER HAVE A CORRUPTED REINSTALL.up FILE, YOU LET YOUR CMU GO TO-SLEEP (turn off), or a DEFECTIVE or SLOW or STALLED 'USB FLASH DRIVE'.

FIRST DO THE Checksum Hash # TESTING OF .up FILES as SHOWN ABOVE plus 'USB FLASH DRIVE', IF DEFECTIVE, DELETE FILES, RE-BOOT PC + DOWNLOAD files again, Hash Test again AND or Use a new USB FLASH DRIVE or Both!.

KEEP READING "RESCUE METHOD" AFTER THESE TWO PICS, DO NOT START ENGINE...!

**Install Not Successful :
System Failure**

**Make sure that the USB with update
package is inserted.
The system will then automatically retry
the update.**

**Install Not Successful :
The content of the update package is
wrong or not sufficient.**

**Make sure that the USB with update
package is inserted.
The system will then automatically retry
the update.**

ONCE YOU HAVE RE-CHECKED AND OR FIXED THE 'USB FLASH DRIVE' or .up FILES, DO THE FOLLOWING AS LISTED IN 2018 CMU FIRMWARE UPDATE PROCEDURE-WORLDWIDE.....

- a. Turn Ignition Switch OFF (Two Quick Presses of S/S Button) (Do not start the engine).*
- b. Wait until the Screen turns to Black.*
- c. Remove the USB Flash Drive. (Do USB TEST above + reload new TESTED Firmware).*
- d. Remove ROOM Fuse and wait for 6 minutes. (or Remove Negative Battery Terminal).*
- e. Install ROOM fuse. (or Install Negative Battery Terminal Clamp).*
- f. Turn Ignition switch to ACC Only, One S/S Press, No Feet on Pedals (Do Not Start Engine).*
- g. Confirm the Screen (s) above appears.*
- h. Connect the USB Flash Drive to the USB port.*
- i. Confirm that update process Auto RE-STARTS.*
- j. Continue from step 25 (update successful) again.*

REPEAT, YOU MUST PERFORM THE ABOVE From 'a to J' BEFORE YOU START CAR ENGINE OR DRIVE SAME CAR FOR THE FIRST TIME.

ALL FIRMWARE UPDATES MUST ONLY BE DONE WITH CAR IN 'ACC SWITCH' MODE. NO LIGHTS ON DASH METERS AND NEVER ENGINE RUNNING, KEEP FEET OFF AND AWAY FROM PEDALS.

ONLY START ENGINE ONCE YOU HAVE COMPLETED step # 25 to # 30, THEN SHUT DOWN (2 QUICK PRESSES OF S/S BUTTON) AND RE-INSTALL NAVIGATION 'SD CARD' IF RESCUE IS SUCCESSFUL.