DMP Electronics Inc. 瞻營全電子股份有限公司
No.15, Wugong 5th Rd., Xinzhuang Dist., New Taipei City, #24890, Taiwan, R.O.C
Tel:+886-2 22980770 Fax:+886-2 22991883 email:info@dmp.com.tw.

Application Note

Doc No. :Apn1503A

Date: 2015/03/31

Products : Vortex86DX3 (Item number:Vx86DX3-9126)

---

1. Due to the design limitation, the 32.678KHz clock input is a must in Vortex86DX3 board design, and 32.678KHz crystal/oscillator must oscillate before the Power Good signal. Please refer to the detail on Layout Guide 1.16 Power-ON Sequence.

2, In Vortex86DX3, the SATA PHY doesn't support the "SSD Trim function".

3, Due to the PCIe band width and CPU performance limitation, the external Gigabit Ethernet chip cannot reach the speed of 1000 Mbps. In DMP's test, the average speed of Gigabit Ethernet chips is around 540 Mbps when PCI bus set to 100MHz , and around 300 Mbps when PCI bus set to 33MHz.

4, For internal R6040 10/100 Mbps Ethernet in Vortex86DX3 board design, the Link/Active LED is always "On" when the 10 Mbps Ethernet connection is existed.
Please be noticed this is different from other design which 100 Mbps is "On" and 10 Mbps is blinking.

5, Vortex86DX3 doesn't support Windows 8 because lack of instruction set of PAE, NX and SSE2.