

Three-Phase Motor Control with STM32F401RET6U


For a good animation of what we are doing look at http://elabz.com/brushless-dc-motor-with-arduino/

Our brushless direct current three-phase motor - **BLD**C - is a CDROM-motor and its connector is on the next pictures. One can see two of the three HALL sensors:






To get workable rectangular Hall sensor signals we use 3 of the 4 differential comparators of chip LM339N.




We will use both, the rising and falling edge of the rectangular signals.




To conduct experiments with different three-phase BLDC-motors we need a suitable driver board.

We avoided a lot of soldering and bought some cheap 10€-boards in eBay and removed the JY01 BLDC-IC




and ended up with:





To switch the 6 MOSFETS we have to drive the 3 JY21L high speed power MOSFET drivers which are connected to the JY01-places of pin 7, 8 (first JY21L-IC), pin 9, 10 (second JY21L-IC) and pin 11, 12 (third JY21L-IC). To do this, we use the STM32 NUCLEO-F401RE prototype board and the port-pins CH1(PA6), CH2(PA7), CH3(PB0), sw1(PB6), sw2(PC7) and sw3(PC1). Some BLDC-motor driver boards JYQD_V6 have a comparator-IC too: LM339, that we do not use! Instead we use our own LM339N.



So much for the hardware. The software side consists of the SW4STM32 System Workbench http://www.st.com/en/development-tools/sw4stm32.html

STWB1 - C/C++ - Coils6/Src/main.c - Eclipse


File Edit Source Refactor Navigate Search Project Run Window Help




and the STM32CubeMX Workbench http://www.st.com/en/development-tools/stm32cubemx.html


▼ STM32CubeMX Coils6.ioc: STM32F401RETx NUCLEO-F401RE


File Project Pinout Window Help



CubeMX generates most of the code we use. All of the PWM-switches are driven by Timer 3 and the three switches sw1, sw2 and sw3 are GPIO-ports in OUTPUT-mode.







The via LM339 rectangular HALL sensor signals are event sources and generate external interrupts on the NUCLEO board. We are interested in changing edges of the signals and do that with GPIO port pins PC5, PC6 and PC8 in EXTI mode. But what is the chronological order of these signals for one rotation of the CDROM BLDC-motor?

We get an answer by these lines of code and GPIO_InitStruct.Mode = GPIO_MODE_IT_RISING;

```
void HAL_GPIO_EXTI_Callback(uint16_t GPIO_Pin) {
uint8_t hall1 = HAL_GPIO_ReadPin(GPIOC, GPIO_PIN_5);
uint8_t hall2 = HAL_GPIO_ReadPin(GPIOC, GPIO_PIN_6);
uint8_t hall3 = HAL_GPIO_ReadPin(GPIOC, GPIO_PIN_8);
Info_3d(hall1, hall2, hall3, " ");}
```

One clockwise rotation generates 6 times these sequence: 1 0 0 1 1 0 0 1 1 0 0 1 1 0 0 1 HALL_A, HALL_B, HALL_C or written as: hall1, hall2, hall3. In green step one is hall1=1, hall2=0, hall3=0, in yellow step two is hall1=1, hall2=1, hall3=0 and so on. As we can see we get 6 cases which we put in 6 different numbers: hall1 = 100*hall1 + 10*hall2 + hall3;

Each case calls for a different position of our switches of the JYQD_V6 driver board.

```
void HAL_GPIO_EXTI_Callback(uint16_t GPIO_Pin) {
hall1 = HAL_GPIO_ReadPin(GPIOC, GPIO_PIN_5);
hall2 = HAL_GPIO_ReadPin(GPIOC, GPIO_PIN_6);
hall3 = HAL_GPIO_ReadPin(GPIOC, GPIO_PIN_8);
new_step = 100*hall1 + 10*hall2 + hall3;
switch (new step){
  case 10://1,2
                                                       CH1
                                                                 CH2
                                                                           CH3
   TIM3->CCR2=0;
   TIM3->CCR3=0;
   GPIOB->ODR = GPIOB->ODR & \sim((1<<sw1));
   GPIOC->ODR = GPIOC->ODR & \sim((1<<sw3));
   TIM3->CCR1 = PWM dn;
                                                       sw1
                                                                 sw2
                                                                           sw3
   GPIOC->ODR = GPIOC->ODR \mid ((1<<sw2));
   break;
```

```
case 11://3,2
                                                    CH1
                                                            CH2
                                                                       CH3
 TIM3->CCR1=0;
 TIM3->CCR2=0;
 GPIOB->ODR = GPIOB->ODR & \sim((1<<sw1));
 GPIOC->ODR = GPIOC->ODR & \sim((1<<sw3));
                                                    sw1
                                                            sw2
                                                                       sw3
 TIM3->CCR3 = PWM_dn;
 GPIOC->ODR = GPIOC->ODR | ((1<<sw2));
 break;
case 1://3,1
 TIM3->CCR1=0;
                                                     CH1
                                                              CH2
                                                                       CH3
 TIM3->CCR2=0;
 GPIOC->ODR = GPIOC->ODR & \sim((1<<sw2));
 GPIOC->ODR = GPIOC->ODR & \sim((1<<sw3));
 TIM3->CCR3 = PWM_dn;
                                                     sw1
                                                              sw2
                                                                       sw3
 GPIOB \rightarrow ODR = GPIOB \rightarrow ODR \mid ((1 << sw1));
 break;
case 101://2,1
 TIM3->CCR1=0;
                                                     CH1
                                                              CH2
                                                                        CH3
 TIM3->CCR3=0;
 GPIOC->ODR = GPIOC->ODR & \sim((1<<sw2));
 GPIOC->ODR = GPIOC->ODR & \sim((1<<sw3));
 TIM3->CCR2 = PWM dn;
 GPIOB->ODR = GPIOB->ODR | ((1<<sw1));
                                                     sw1
                                                              sw2
                                                                        sw3
 break;
                                                    CH1
                                                              CH2
                                                                       CH3
case 100://2,3
 TIM3->CCR1=0;
 TIM3->CCR3=0;
 GPIOB->ODR = GPIOB->ODR & \sim((1<<sw1));
 GPIOC->ODR = GPIOC->ODR & \sim((1<<sw2));
                                                              sw2
                                                                       sw3
                                                    sw1
 TIM3->CCR2 = PWM dn;
 GPIOC->ODR = GPIOC->ODR | ((1<<sw3));
```

```
break;
case 110://1,3

TIM3->CCR2 = 0;

TIM3->CCR3 = 0;

GPIOB->ODR = GPIOB->ODR & ~((1<<sw1));

GPIOC->ODR = GPIOC->ODR & ~((1<<sw2));

TIM3->CCR1 = PWM_dn;

GPIOC->ODR = GPIOC->ODR | ((1<<sw3));

if(PWM_dn < 10000) PWM_dn += 1;

break;


default: //because of some noise

TIM3->CCR1 = 0;

TIM3->CCR2 = 0;

TIM3->CCR3 = 0;

}
```



In the code listed below CubeMX-code is black and our code is in red.

main.c

```
#include "main.h"
#include "stm32f4xx hal.h"
#include <string.h> //strlen(str)
TIM_HandleTypeDef htim3;
UART_HandleTypeDef huart2;
uint8_t hall1, hall2, hall3, new_step, start = 1;
uint16_t PWM_dn = 5000;
void CH123_sw123_off(void);
char* my_utoa(unsigned, char*);
void Info_d(unsigned, char*);
void Info_3d(unsigned, unsigned, unsigned, char*);
char txt[20];
void SystemClock Config(void);
static void MX_GPIO_Init(void);
static void MX_USART2_UART_Init(void);
static void MX_TIM3_Init(void);
void HAL_TIM_MspPostInit(TIM_HandleTypeDef *htim);
int main(void)
 HAL_Init();
 SystemClock_Config();
 MX_GPIO_Init();
 MX_USART2_UART_Init();
 MX_TIM3_Init();
 HAL_TIM_PWM_Start(&htim3, TIM_CHANNEL_1); //PA6
 HAL_TIM_PWM_Start(&htim3, TIM_CHANNEL_2); //PA7
 HAL_TIM_PWM_Start(&htim3, TIM_CHANNEL_3); //PB0
 CH123_sw123_off();
 while(1)\{\}
```

```
}
char* my_utoa(unsigned val, char *buffer)
char*cp = buffer;
unsigned v;
char c;
v = val;
do {
 v = 10;
 cp++;
} while(v != 0);
*cp--=0;
do {
 c = val \% 10;
 val = 10;
 c += '0';
 *cp-- = c;
} while(val != 0);
 return buffer;
void Info_d(unsigned n, char *str)
 my_utoa(n, txt);//size_t strlen(const char *str);
 HAL_UART_Transmit(&huart2, (uint8_t *) str, strlen(str), HAL_MAX_DELAY);
 HAL_UART_Transmit(&huart2, (uint8_t *) txt, strlen(txt), HAL_MAX_DELAY);
 HAL_UART_Transmit(&huart2, (uint8_t *) "\n\r", 2, HAL_MAX_DELAY);
void Info_3d(unsigned n1, unsigned n2, unsigned n3, char *str)
 my_utoa(n1, txt);//size_t strlen(const char *str);
 HAL_UART_Transmit(&huart2, (uint8_t *) str, strlen(str), HAL_MAX_DELAY);
```

```
HAL_UART_Transmit(&huart2, (uint8_t *) txt, strlen(txt), HAL_MAX_DELAY);
 my_utoa(n2, txt);//size_t strlen(const char *str);
 HAL_UART_Transmit(&huart2, (uint8_t *) str, strlen(str), HAL_MAX_DELAY);
 HAL_UART_Transmit(&huart2, (uint8_t *) txt, strlen(txt), HAL_MAX_DELAY);
 my_utoa(n3, txt);//size_t strlen(const char *str);
 HAL_UART_Transmit(&huart2, (uint8_t *) str, strlen(str), HAL_MAX_DELAY);
 HAL_UART_Transmit(&huart2, (uint8_t *) txt, strlen(txt), HAL_MAX_DELAY);
 HAL\_UART\_Transmit(\&huart2, (uint8\_t *) "\n\r", 2, HAL\_MAX\_DELAY);
void CH123 sw123 off(void){
//sConfigOC.Pulse = 0; means (A6)TIM3->CCR1 = 0; (A7)TIM3->CCR2 = 0; (B0)TIM3->CCR3 = 0;
 GPIOB->ODR = GPIOB->ODR \& \sim ((1<<sw1));//B6 \ off \ pwm_+ pol__/___/___/GND
 GPIOC->ODR = GPIOC->ODR \& \sim ((1 << sw2)); //C7 off + ___/ __/ GND
 GPIOC -> ODR = GPIOC -> ODR \& \sim ((1 << sw3)); //C1 off + ___/ ____ / ___ GND
void HAL_GPIO_EXTI_Callback(uint16_t GPIO_Pin) {
 hall1 = HAL\_GPIO\_ReadPin(GPIOC, GPIO\_PIN\_5);
 hall2 = HAL\_GPIO\_ReadPin(GPIOC, GPIO\_PIN\_6);
 hall3 = HAL\_GPIO\_ReadPin(GPIOC, GPIO\_PIN\_8);
 new\_step = 100*hall1 + 10*hall2 + hall3;
 switch (new step){
  case 10://1,2
   TIM3->CCR2=0;
   TIM3 -> CCR3 = 0:
   GPIOB \rightarrow ODR = GPIOB \rightarrow ODR \& \sim ((1 << sw1));
   GPIOC \rightarrow ODR = GPIOC \rightarrow ODR \& \sim ((1 < \langle sw3 \rangle));
   TIM3 -> CCR1 = PWM\_dn;
   GPIOC \rightarrow ODR = GPIOC \rightarrow ODR / ((1 < < sw2));
   break:
  case 11://3,2
    TIM3 -> CCR1 = 0;
```

```
TIM3->CCR2=0;
 GPIOB -> ODR = GPIOB -> ODR \& \sim ((1 << sw1));
 GPIOC \rightarrow ODR = GPIOC \rightarrow ODR \& \sim ((1 < < sw3));
 TIM3 -> CCR3 = PWM dn;
 GPIOC \rightarrow ODR = GPIOC \rightarrow ODR / ((1 < < sw2));
 break;
case 1://3,1
 TIM3 -> CCR1 = 0;
 TIM3->CCR2=0:
 GPIOC \rightarrow ODR = GPIOC \rightarrow ODR \& \sim ((1 < < sw2));
 GPIOC \rightarrow ODR = GPIOC \rightarrow ODR \& \sim ((1 < < sw3));
 TIM3 -> CCR3 = PWM dn;
 GPIOB -> ODR = GPIOB -> ODR / ((1 << sw1));
 break;
case 101://2,1
 TIM3 -> CCR1 = 0;
 TIM3 -> CCR3 = 0;
 GPIOC \rightarrow ODR = GPIOC \rightarrow ODR \& \sim ((1 < < sw2));
 GPIOC \rightarrow ODR = GPIOC \rightarrow ODR \& \sim ((1 << sw3));
 TIM3->CCR2 = PWM\_dn;
 GPIOB -> ODR = GPIOB -> ODR / ((1 << sw1));
 break;
case 100://2.3
 TIM3->CCR1=0:
 TIM3 -> CCR3 = 0;
 GPIOB->ODR = GPIOB->ODR \& \sim ((1 << sw1));
 GPIOC \rightarrow ODR = GPIOC \rightarrow ODR \& \sim ((1 << sw2));
 TIM3 -> CCR2 = PWM_dn;
 GPIOC \rightarrow ODR = GPIOC \rightarrow ODR / ((1 <  sw3));
 break;
case 110://1,3
```

```
TIM3 -> CCR2 = 0;
   TIM3 -> CCR3 = 0;
   GPIOB->ODR = GPIOB->ODR \& \sim ((1 << sw1));
   GPIOC \rightarrow ODR = GPIOC \rightarrow ODR \& \sim ((1 < < sw2));
   TIM3->CCR1 = PWM\_dn;
   GPIOC \rightarrow ODR = GPIOC \rightarrow ODR / ((1 <  sw3));
   if(PWM\_dn < 10000) PWM\_dn += 1;//press black nucleo button for acceleration
  break;
  default: //because of some noise
   TIM3 -> CCR1 = 0;
   TIM3->CCR2=0;
   TIM3 -> CCR3 = 0;
void SystemClock Config(void)
{
RCC_OscInitTypeDef RCC_OscInitStruct;
 RCC_ClkInitTypeDef RCC_ClkInitStruct;
 __HAL_RCC_PWR_CLK_ENABLE();
 __HAL_PWR_VOLTAGESCALING_CONFIG(PWR_REGULATOR_VOLTAGE_SCALE2);
RCC OscInitStruct.OscillatorType = RCC OSCILLATORTYPE HSI;
RCC_OscInitStruct.HSIState = RCC_HSI_ON;
RCC OscInitStruct.HSICalibrationValue = 16;
RCC_OscInitStruct.PLL.PLLState = RCC_PLL_ON;
RCC_OscInitStruct.PLL.PLLSource = RCC_PLLSOURCE_HSI;
RCC_OscInitStruct.PLL.PLLM = 16;
RCC_OscInitStruct.PLL.PLLN = 336;
RCC_OscInitStruct.PLL.PLLP = RCC_PLLP_DIV4;
RCC OscInitStruct.PLL.PLLQ = 7;
if (HAL_RCC_OscConfig(&RCC_OscInitStruct) != HAL_OK) _Error_Handler(__FILE__, __LINE__);
```

```
RCC_ClkInitStruct.ClockType =
RCC_CLOCKTYPE_HCLK|RCC_CLOCKTYPE_SYSCLK|RCC_CLOCKTYPE_PCLK1|RCC_CLOCKTYP
E PCLK2;
RCC_ClkInitStruct.SYSCLKSource = RCC_SYSCLKSOURCE_PLLCLK;
 RCC ClkInitStruct.AHBCLKDivider = RCC SYSCLK DIV1;
 RCC_ClkInitStruct.APB1CLKDivider = RCC_HCLK_DIV2;
 RCC_ClkInitStruct.APB2CLKDivider = RCC_HCLK_DIV1;
if (HAL RCC ClockConfig(&RCC ClkInitStruct, FLASH LATENCY 2) != HAL OK)
_Error_Handler(__FILE__, __LINE__);
HAL_SYSTICK_Config(HAL_RCC_GetHCLKFreq()/1000);
 HAL_SYSTICK_CLKSourceConfig(SYSTICK_CLKSOURCE_HCLK);
HAL NVIC SetPriority(SysTick IRQn, 0, 0);
static void MX_TIM3_Init(void)
{
TIM_ClockConfigTypeDef sClockSourceConfig;
TIM MasterConfigTypeDef sMasterConfig;
TIM_OC_InitTypeDef sConfigOC;
htim3.Instance = TIM3;
 htim3.Init.Prescaler = 1;//was 1;2 is good
htim3.Init.CounterMode = TIM COUNTERMODE UP;
htim3.Init.Period = 10000;
htim3.Init.ClockDivision = TIM_CLOCKDIVISION_DIV1;//was TIM_CLOCKDIVISION_DIV1;
if (HAL_TIM_Base_Init(&htim3) != HAL_OK) _Error_Handler(__FILE__, __LINE__);
 sClockSourceConfig.ClockSource = TIM_CLOCKSOURCE_INTERNAL;
if (HAL_TIM_ConfigClockSource(&htim3, &sClockSourceConfig) != HAL_OK) _Error_Handler(__FILE__,
__LINE__);
if (HAL_TIM_PWM_Init(&htim3) != HAL_OK) _Error_Handler(__FILE__, __LINE__);
sMasterConfig.MasterOutputTrigger = TIM_TRGO_RESET;
 sMasterConfig.MasterSlaveMode = TIM_MASTERSLAVEMODE_DISABLE;
if (HAL_TIMEx_MasterConfigSynchronization(&htim3, &sMasterConfig) != HAL_OK)
_Error_Handler(__FILE__, __LINE__);
 sConfigOC.OCMode = TIM_OCMODE_PWM1;
```


```
sConfigOC.Pulse = 0;
 sConfigOC.OCPolarity = TIM_OCPOLARITY_HIGH;
 sConfigOC.OCFastMode = TIM_OCFAST_ENABLE;//was TIM_OCFAST_DISABLE;
if (HAL TIM PWM ConfigChannel(&htim3, &sConfigOC, TIM CHANNEL 1) != HAL OK)
_Error_Handler(__FILE__, __LINE__);
if (HAL_TIM_PWM_ConfigChannel(&htim3, &sConfigOC, TIM_CHANNEL_2) != HAL_OK)
_Error_Handler(__FILE__, __LINE__);
if (HAL TIM PWM ConfigChannel(&htim3, &sConfigOC, TIM CHANNEL 3) != HAL OK)
_Error_Handler(__FILE__, __LINE__);
HAL_TIM_MspPostInit(&htim3);
static void MX USART2 UART Init(void)
huart2.Instance = USART2;
huart2.Init.BaudRate = 115200;
huart2.Init.WordLength = UART_WORDLENGTH_8B;
huart2.Init.StopBits = UART STOPBITS 1;
huart2.Init.Parity = UART_PARITY_NONE;
huart2.Init.Mode = UART MODE TX RX;
 huart2.Init.HwFlowCtl = UART_HWCONTROL_NONE;
huart2.Init.OverSampling = UART_OVERSAMPLING_16;
if (HAL_UART_Init(&huart2) != HAL_OK) _Error_Handler(__FILE__, __LINE__);
static void MX_GPIO_Init(void)
GPIO_InitTypeDef GPIO_InitStruct;
 __HAL_RCC_GPIOC_CLK_ENABLE();
 __HAL_RCC_GPIOH_CLK_ENABLE();
 __HAL_RCC_GPIOA_CLK_ENABLE();
 __HAL_RCC_GPIOB_CLK_ENABLE();
HAL GPIO WritePin(LD2 GPIO Port, LD2 Pin, GPIO PIN RESET);
HAL_GPIO_WritePin(GPIOB, GPIO_PIN_6, GPIO_PIN_RESET);
```

```
HAL_GPIO_WritePin(GPIOC, GPIO_PIN_1, GPIO_PIN_RESET);
HAL GPIO WritePin(GPIOC, GPIO_PIN_7, GPIO_PIN_RESET);
GPIO InitStruct.Pin = B1 Pin|GPIO PIN 5|GPIO PIN 6|GPIO PIN 8:
//GPIO InitStruct.Mode = GPIO MODE IT FALLING;
//GPIO_InitStruct.Mode = GPIO_MODE_IT_RISING;
 GPIO_InitStruct.Mode = GPIO_MODE_IT_RISING_FALLING;
GPIO_InitStruct.Pull = GPIO_NOPULL;//GPIO_NOPULL;
HAL GPIO Init(GPIOC, &GPIO InitStruct);
GPIO InitStruct.Pin = LD2 Pin;
GPIO InitStruct.Mode = GPIO MODE OUTPUT PP;
 GPIO_InitStruct.Pull = GPIO_NOPULL;
GPIO InitStruct.Speed = GPIO SPEED FREQ LOW;
HAL_GPIO_Init(LD2_GPIO_Port, &GPIO_InitStruct);
 GPIO_InitStruct.Pin = GPIO_PIN_1|GPIO_PIN_7;//C1,C7
 GPIO InitStruct.Mode = GPIO MODE OUTPUT PP;
GPIO InitStruct.Pull = GPIO PULLDOWN;
 GPIO InitStruct.Speed = GPIO SPEED FREQ HIGH;
 HAL_GPIO_Init(GPIOC, &GPIO_InitStruct);//C1,C7
GPIO InitStruct.Pin = GPIO PIN 6;//B6
 GPIO_InitStruct.Mode = GPIO_MODE_OUTPUT_PP;
 GPIO InitStruct.Pull = GPIO PULLDOWN;
GPIO_InitStruct.Speed = GPIO_SPEED_FREQ_HIGH;
HAL GPIO Init(GPIOB, &GPIO InitStruct);//B6
HAL_NVIC_SetPriority(EXTI9_5_IRQn, 0, 0);
HAL_NVIC_EnableIRQ(EXTI9_5_IRQn);
}
void _Error_Handler(char * file, int line)
{ while(1); }
#ifdef USE FULL ASSERT
void assert_failed(uint8_t* file, uint32_t line){}
#endif
```


main.h


```
#ifndef __MAIN_H
#define __MAIN_H
#define B1_Pin GPIO_PIN_13
#define B1_GPIO_Port GPIOC
#define USART_TX_Pin GPIO_PIN_2
#define USART_TX_GPIO_Port GPIOA
#define USART_RX_Pin GPIO_PIN_3
#define USART_RX_GPIO_Port GPIOA
#define LD2_Pin GPIO_PIN_5
#define LD2_GPIO_Port GPIOA
#define TMS_Pin GPIO_PIN_13
#define TMS_GPIO_Port GPIOA
#define TCK Pin GPIO PIN 14
#define TCK_GPIO_Port GPIOA
#define SWO_Pin GPIO_PIN_3
#define SWO_GPIO_Port GPIOB
#define sw1 6 //switch1:GPIO_Port_B6 works with TIM3->CCR1
#define sw2 7 //switch2:GPIO_Port_C7 works with TIM3->CCR2
#define sw3 1 //switch3:GPIO Port C1 works with TIM3->CCR3
void Error Handler(char *, int);
#define Error_Handler() _Error_Handler(__FILE__, __LINE__)
#endif /* __MAIN_H */
```


The whole wiring finally:















You can buy several driver-boards:


Works with U=3V and more

Works with U=5V and more

Works with U=11V and more









Three-Phase Motor Control without HALL sensors


We used HALL sensors to detect the position of the rotor with its permanent magnets. A second way is to use induction to detect rotor positions.




If we **switch off** the fast running CDROM-motor and measure the signals with respect to GND on pin A, B and C we get this picture:




One can use many other BLDC-motors like HDD-motors. The principle to determine rotor positions without HALL-sensors will be always the same, and the oscilloscope diagrams too:



This HDD-motor has four times the three coils, and if we **switch off** the fast running HDD-motor and measure the signals between GND, 1, GND, 2 and GND, 3 we get this picture:





We compare these oscilloscope pictures with an oscilloscope picture of one HALL-sensor and a motor rotation of 50rps = 3000rpm:





We see that we have to generate edges at zero points A0, B0 and C0 to control the BLDC-motor with the same C-program of our NUCLEO-board.


Again LM339 generates rectangular signals as external interrupts for the NUCLEO-board, but the circuit changes:














If the CDROM-motor is running, he runs in the same silent way as controlled with HALL-sensors.

The start is a problem if a CD is present. The motor starts not as smooth as with HALL-sensors. If we switch on the motor without a CD, the motor starts immediately, but with any mass present, the motor needs a more or less hefty push.

The following change in C-code improves the start behavior a little bit:

```
uint16_t PWM_dn = 10000;
void HAL_GPIO_EXTI_Callback(uint16_t GPIO_Pin) {
    hall1 = HAL_GPIO_ReadPin(GPIOC, GPIO_PIN_5);
    hall2 = HAL_GPIO_ReadPin(GPIOC, GPIO_PIN_6);
    hall3 = HAL_GPIO_ReadPin(GPIOC, GPIO_PIN_8);
    new_step = 100*hall1 + 10*hall2 + hall3;
    if(start){
        switch (new_step){
            case 10://1,2

            TIM3->CCR2 = 0;
            TIM3->CCR3 = 0;
            GPIOB->ODR & ~((1<<sw1));
        }
}</pre>
```

```
GPIOC->ODR = GPIOC->ODR & \sim((1<<sw3));
     TIM3->CCR1 = PWM_dn;
     GPIOC \rightarrow ODR = GPIOC \rightarrow ODR \mid ((1 << sw2));
     break;
    case 1://3,1
     TIM3->CCR1=0;
     TIM3->CCR2=0;
     GPIOC->ODR = GPIOC->ODR & \sim((1<<sw2));
     GPIOC->ODR = GPIOC->ODR & \sim((1<<sw3));
     TIM3->CCR3 = PWM_dn;
     GPIOB->ODR = GPIOB->ODR | ((1<<sw1));
     break;
    case 100://2,3
     TIM3->CCR1=0;
     TIM3->CCR3=0;
     GPIOB->ODR = GPIOB->ODR & \sim((1<<sw1));
     GPIOC->ODR = GPIOC->ODR & \sim((1<<sw2));
     TIM3->CCR2 = PWM_dn;
     GPIOC \rightarrow ODR = GPIOC \rightarrow ODR \mid ((1 << sw3));
     if(PWM_dn > 8000) {PWM_dn -= 1;} else {start = !start; PWM_dn = 3000;}
     break;
    default: //because of some noise
     TIM3->CCR1=0;
     TIM3->CCR2=0;
     TIM3->CCR3=0;
   }
} else {
  switch (new_step){
    case 10://1,2
     TIM3->CCR2=0;
     TIM3->CCR3=0;
```

```
GPIOB->ODR = GPIOB->ODR & \sim((1<sw1));
GPIOC->ODR = GPIOC->ODR & \sim((1<<sw3));
TIM3->CCR1 = PWM dn;
GPIOC->ODR = GPIOC->ODR \mid ((1<<sw2));
break:
case 11://3,2
TIM3->CCR1=0;
TIM3->CCR2=0;
GPIOB->ODR = GPIOB->ODR & \sim((1<<sw1));
GPIOC->ODR = GPIOC->ODR & \sim((1<<sw3));
TIM3->CCR3 = PWM_dn;
GPIOC->ODR = GPIOC->ODR \mid ((1<<sw2));
break;
case 1://3,1
TIM3->CCR1=0;
TIM3->CCR2=0;
GPIOC->ODR = GPIOC->ODR & \sim((1<<sw2));
GPIOC->ODR = GPIOC->ODR & \sim((1<<sw3));
TIM3->CCR3 = PWM_dn;
GPIOB->ODR = GPIOB->ODR | ((1<<sw1));
break;
case 101://2,1
TIM3->CCR1=0;
TIM3->CCR3=0;
GPIOC->ODR = GPIOC->ODR & \sim((1<<sw2));
GPIOC->ODR = GPIOC->ODR & \sim((1<<sw3));
TIM3->CCR2 = PWM_dn;
GPIOB->ODR = GPIOB->ODR \mid ((1<<sw1));
break;
case 100://2,3
TIM3->CCR1=0;
```

```
TIM3->CCR3=0;
 GPIOB->ODR = GPIOB->ODR & \sim((1<<sw1));
 GPIOC->ODR = GPIOC->ODR & \sim((1<<sw2));
 TIM3->CCR2 = PWM_dn;
 GPIOC->ODR = GPIOC->ODR | ((1<<sw3));
 break:
case 110://1,3
 TIM3->CCR2=0;
 TIM3->CCR3=0;
 GPIOB->ODR = GPIOB->ODR & \sim((1<<sw1));
 GPIOC->ODR = GPIOC->ODR & \sim((1<<sw2));
 TIM3->CCR1 = PWM_dn;
 GPIOC->ODR = GPIOC->ODR | ((1<<sw3));
 if(PWM_dn < 10000) PWM_dn += 1;
break;
default: //because of some noise
 TIM3->CCR1=0;
 TIM3->CCR2=0;
 TIM3->CCR3=0;
}
```

Some Applications


}


}

Since BEMF based on induction and induction needs motion we cannot expect, that the motor starts without any push.


In the following we see some other motors we used together with the same program.

The first one is a hard drive motor and we used this device to conduct an experiment to show the power of an angular momentum.











And here are two different floppy drive motors. A relatively small impulse starts both immediately.





... have fun with STM32!

edgarmarx@t-online.de