NO.24 EXCESSIVE BLACK SMOKE [SKYACTIV-D 1.5]

id0103q2899100

24	EXCESSIVE BLACK SMOKE
DESCRIPTION	• Compared to previously, black smoke in the exhaust gas abnormally high.
POSSIBLE CAUSE	• PCM DTC is stored. • DPF (in catalytic converter) deficiency

Diagnostic Procedure

STEP	INSPECTION	RESULTS	ACTION
1	**VERIFY PCM DTC** • Retrieve PCM DTCs using the M-MDS. (See ON-BOARD DIAGNOSTIC TEST [SKYACTIV-D 1.5].) • Are any DTCs present?	Yes	Go to the applicable DTC inspection. (See DTC TABLE [SKYACTIV-D 1.5].)
		No	Go to the next step.
2	**INSPECT DPF (IN CATALYTIC CONVERTER) FOR MALFUNCTION DUE TO DEFICIENCY** • Inspect the DPF. (See DIESEL PARTICULATE FILTER INSPECTION [SKYACTIV-D 1.5].) • Is the DPF normal?	Yes	Go to the next step.
		No	DPF deficiency in the catalytic converter can be considered. Replace the catalytic converter, then go to the next step. (See EXHAUST SYSTEM REMOVAL/INSTALLATION [SKYACTIV-D 1.5].)
3	Verify the test results. • If normal, return to the diagnostic index to service any additional symptoms. (See SYMPTOM DIAGNOSTIC INDEX [SKYACTIV-D 1.5].) • If a malfunction remains, inspect the related Service Information and perform the repair or diagnosis. — If the vehicle is repaired, troubleshooting is completed. — If the vehicle is not repaired or additional diagnostic information is not available, replace the PCM. (See PCM REMOVAL/INSTALLATION [SKYACTIV-D 1.5].)		