## NO.25 FUEL ODOR (IN ENGINE COMPARTMENT) [SKYACTIV-D 1.5]

id0103q2899200

| 25 | FUEL ODOR (IN ENGINE COMPARTMENT) |
|---|---|
| DESCRIPTION | • Fuel odor from inside/outside of cabin or engine compartment. |
| POSSIBLE CAUSE | • PCM DTC is stored.<br>• Fuel system malfunction (leak in supply system) |

### Diagnostic Procedure

| STEP | INSPECTION | RESULTS | ACTION |
|---|---|---|---|
| 1 | **VERIFY PCM DTC**<br>• Retrieve PCM DTCs using the M-MDS. (See ON-BOARD DIAGNOSTIC TEST [SKYACTIV-D 1.5].)<br>• Are any DTCs present? | Yes | Go to the applicable DTC inspection. (See DTC TABLE [SKYACTIV-D 1.5].) |
| | | No | Go to the next step. |
| 2 | **INSPECT FOR FUEL LEAKAGE FROM FUEL SYSTEM**<br>• Visually inspect the following:<br>— Fuel leakage from the fuel tank, fuel pump, hose, pipe, fuel injector, supply pump, common rail<br>— Cracking and damage in fuel hose and pipe<br>— Clamp installation condition for each hose and pipe<br>— Fuel pipe securing condition due to deterioration such as rubber of clamp<br>• Are all items normal? | Yes | Go to the next step. |
| | | No | Repair or replace the malfunctioning part according to the inspection results, then go to the next step. |
| 3 | Verify the test results.<br>• If normal, return to the diagnostic index to service any additional symptoms. (See SYMPTOM DIAGNOSTIC INDEX [SKYACTIV-D 1.5].)<br>• If a malfunction remains, inspect the related Service Information and perform the repair or diagnosis.<br>— If the vehicle is repaired, troubleshooting is completed.<br>— If the vehicle is not repaired or additional diagnostic information is not available, replace the PCM. (See PCM REMOVAL/INSTALLATION [SKYACTIV-D 1.5].) | | |