DTC U0001:88/U0100:00/U0101:00/U0131:00/U0151:00/U0155:00/U0235:00 [DSC HU/CM]

id040262926800

DTC	**U0001:88** **U0100:00** **U0101:00** **U0131:00** **U0151:00** **U0155:00** **U0235:00**	**CAN line**
DETECTION CONDITION		• U0001:88 — Open or short circuit in CAN system wiring harness is detected • U0100:00 — Communication error to PCM is detected in CAN communication • U0101:00 — Communication error to TCM is detected in CAN communication • U0131:00 — Communication error to EPS control module is detected in CAN communication • U0151:00 — Communication error to SAS control module is detected in CAN communication • U0155:00 — Communication error to instrument cluster is detected in CAN communication • U0235:00 — Communication error to laser sensor is detected in CAN communication
FAIL-SAFE FUNCTION		Refer to DTC TABLE. (See DTC TABLE [DSC HU/CM].)
POSSIBLE CAUSE		• CAN communication line malfunction • CAN communication line malfunction with PCM • CAN communication line malfunction with TCM • CAN communication line malfunction with EPS control module • CAN communication line malfunction with SAS control module • CAN communication line malfunction with instrument cluster • CAN communication line malfunction with laser sensor • Instrument cluster malfunction
SYSTEM WIRING DIAGRAM		—

Diagnostic Procedure

- Perform inspection according to the diagnostic procedure in MULTIPLEX COMMUNICATION SYSTEM. (See CONTROLLER AREA NETWORK (CAN) MALFUNCTION DIAGNOSIS FLOW [SKYACTIV-G 1.3, SKYACTIV-G 1.5 (R.H.D.)].) (See CONTROLLER AREA NETWORK (CAN) MALFUNCTION DIAGNOSIS FLOW [SKYACTIV-G 1.5 (L.H.D.)].) (See CONTROLLER AREA NETWORK (CAN) MALFUNCTION DIAGNOSIS FLOW [SKYACTIV-D 1.5].)