DTC U0420:00/U0420:82 [LASER SENSOR]

id0402c4855200

DTC	**U0420:00** **U0420:82**	**Signal error from EPS control module**
DETECTION CONDITION		• Error detected in signal from EPS control module via CAN communication
FAIL-SAFE FUNCTION		• Smart City Brake Support (SCBS) warning light (amber) Illuminates • Smart City Brake Support (SCBS) control disabled
POSSIBLE CAUSE		• EPS control module malfunction
SYSTEM WIRING DIAGRAM		—

Diagnostic Procedure

Step	Inspection		Action
1	**VERIFY EPS CONTROL MODULE DTC** • Using the M-MDS, perform the EPS control module DTC inspection. (See DTC INSPECTION [EPS CONTROL MODULE].) • Are any DTCs present?	Yes	Go to applicable DTC inspection. (See DTC TABLE [EPS CONTROL MODULE].) DTC troubleshooting completed, then go to the next step.
		No	Go to the next step.
2	**VERIFY DTC TROUBLESHOOTING COMPLETED** • Using the M-MDS, clear the DTC from the laser sensor. (See CLEARING DTC [LASER SENSOR].) • Using the M-MDS, perform the laser sensor DTC inspection. (See DTC INSPECTION [LASER SENSOR].) • Is the same DTC present?	Yes	Perform the following procedures: • Verify that the steering angle sensor is equipped, and its wiring harness connects with start stop unit (See STEERING ANGLE SENSOR REMOVAL/INSTALLATION.) • Using the M-MDS, select the PID item STR_AB_EST for EPS control module. • Verify the monitor value with steering wheel position 0 ° (vehicle wheels straight-ahead). — If monitor value is ± 20 ° or less, replace the steering column, then go to the next step. (See STEERING WHEEL AND COLUMN REMOVAL/INSTALLATION.) — If monitor value is ± 20 ° or more, verify that the Smart City Brake Support (SCBS) warning light (amber) blacks out when vehicle is driven for approx. 5 min after the steering angle signal is reset. (See START STOP UNIT CONFIGURATION (USING AS-BUILT DATA).) If the malfunction recurs, replace the steering column, then go to the next step. (See STEERING WHEEL AND COLUMN REMOVAL/INSTALLATION.)
		No	Go to the next step.
3	**VERIFY NO DTC IS PRESENT** • Are any DTCs present?	Yes	Go to applicable DTC inspection. (See DTC TABLE [LASER SENSOR].)
		No	DTC troubleshooting completed.