DTC U0001:00/U0100:00/U0121:00/U0131:00/U0155:00 [LASER SENSOR]

id0402c4894900

DTC	**U0001:00**	**CAN line**
	U0100:00	
	U0121:00	
	U0131:00	
	U0155:00	
DETECTION CONDITION		• U0001:00 — Open or short circuit in CAN system wiring harness is detected • U0100:00 — Communication error to PCM is detected in CAN communication • U0121:00 — Communication error to DSC HU/CM is detected in CAN communication • U0131:00 — Communication error to EPS control module is detected in CAN communication • U0155:00 — Communication error to instrument cluster is detected in CAN communication
FAIL-SAFE FUNCTION		• Smart City Brake Support (SCBS) warning light (amber) Illuminates • Smart City Brake Support (SCBS) control disabled
POSSIBLE CAUSE		• CAN communication line malfunction • CAN communication line malfunction with PCM • CAN communication line malfunction with DSC HU/CM • CAN communication line malfunction with EPS control module • CAN communication line malfunction with instrument cluster • Instrument cluster malfunction
SYSTEM WIRING DIAGRAM		—

Diagnostic Procedure

- Perform inspection according to the diagnostic procedure in MULTIPLEX COMMUNICATION SYSTEM. (See CONTROLLER AREA NETWORK (CAN) MALFUNCTION DIAGNOSIS FLOW [SKYACTIV-G 1.3, SKYACTIV-G 1.5 (R.H.D.)].) (See CONTROLLER AREA NETWORK (CAN) MALFUNCTION DIAGNOSIS FLOW [SKYACTIV-G 1.5 (L.H.D.)].) (See CONTROLLER AREA NETWORK (CAN) MALFUNCTION DIAGNOSIS FLOW [SKYACTIV-D 1.5].)