NO.4 A MALFUNCTION IN THE SYSTEM EVEN THOUGH THE ABS WARNING LIGHT AND BRAKE SYSTEM WARNING LIGHT ARE NOT ILLUMINATED [ANTILOCK BRAKE SYSTEM (ABS)]

id040308109300

4	**A malfunction in the system even though the ABS warning light and brake system warning light are not illuminated**
POSSIBLE CAUSE	• Mechanical malfunction in system.

Diagnostic procedure

STEP	INSPECTION		ACTION
1	**CONFIRM ABS HU/CM DTC** • Retrieve the ABS HU/CM DTC using the M-MDS (IDS). (See DTC INSPECTION [ABS HU/CM].) • Are any DTCs present?	Yes	Go to the applicable DTC inspection. (See DTC TABLE [ABS HU/CM].)
		No	Go to the next step.
2	**VERIFY SOLENOID VALVE OPERATION** • Switch the ignition off. • Connect the M-MDS to the DLC-2. • Switch the ignition ON (engine off). • Access the active command mode for the solenoid valve using the M-MDS. (See SIMULATION INSPECTION [ABS HU/CM].) • Does the solenoid valve operate?	Yes	Inspect the conventional brake system. If there is a malfunction: • Repair or replace any malfunctioning parts according to the inspection result.
		No	Repair or replace any malfunctioning parts according to the inspection result.