NO.8 SMART BRAKE SUPPORT/SMART CITY BRAKE SUPPORT (SBS/SCBS) INDICATOR LIGHT (AMBER) STAY ON [DYNAMIC STABILITY CONTROL (DSC)]

id0403b2897900

8	Smart Brake Support/Smart City Brake Support (SBS/SCBS) indicator light (amber) stay on
POSSIBLE CAUSE	• Laser sensor internal malfunction. • DSC HU/CM internal malfunction. • DSC HU/CM detects a malfunction (input and output device malfunction). • PCM and/or instrument cluster internal malfunction.

Diagnostic procedure

STEP	INSPECTION		ACTION
1	**CONFIRM LASER SENSOR DTC** • Retrieve the laser sensor DTC using the M-MDS. (See DTC INSPECTION [LASER SENSOR].) • Are any DTCs present?	Yes	Go to the applicable DTC inspection. (See DTC INSPECTION [LASER SENSOR].)
		No	Go to the next step.
2	**CONFIRM DSC HU/CM DTC** • Retrieve the DSC HU/CM DTC using the M-MDS. (See DTC INSPECTION [DSC HU/CM].) • Are any DTCs present?	Yes	Go to the applicable DTC inspection. (See DTC INSPECTION [DSC HU/CM].)
		No	Go to the next step.
3	**CONFIRM PCM DTC** • Retrieve the PCM DTC using the M-MDS. (See ON-BOARD DIAGNOSTIC TEST [SKYACTIV-G 1.3, SKYACTIV-G 1.5].) (See ON-BOARD DIAGNOSTIC TEST [SKYACTIV-D 1.5].) • Are any DTCs present?	Yes	Go to the applicable DTC inspection. (See DTC TABLE [SKYACTIV-G 1.3, SKYACTIV-G 1.5].) (See DTC TABLE [SKYACTIV-D 1.5].)
		No	Retrieve the instrument cluster DTC using the M-MDS. (See DTC INSPECTION [INSTRUMENT CLUSTER].) • If any DTCs are present, go to the applicable DTC inspection. (See DTC TABLE [INSTRUMENT CLUSTER].) • If there is not a DTC, replace the instrument cluster. (See INSTRUMENT CLUSTER REMOVAL/INSTALLATION.)