## DTC P0872:00 [TCM (CW6A-EL)]

id0502p4904700

**Note**
- Oil pressure switch No.3 is built into oil pressure switch A.
- If there is a malfunction in oil pressure switch No.3, replace oil pressure switch A.

| | |
|---|---|
| **DTC P0872:00** | **Oil pressure switch No.3 (Oil pressure switch A) stuck on** |
| **DETECTION CONDITION** | • Under the following conditions, oil pressure switch No.3 stuck-on detected by combination of gear ratio malfunction and oil pressure switch pattern malfunction:<br>— Engine is running.<br>— ATF temperature is **20 °C {68 °F} or more**.<br>— There is no difference between vehicle speed signal from ABS HU/CM (with ABS)/DSC HU/CM (with DSC) and output shaft speed sensor signal.<br>— Turbine/input shaft speed sensor and output shaft speed sensor DTC is not recorded. |
| **FAIL-SAFE FUNCTION** | • Limits engine torque.<br>• Inhibits learning control.<br>• Inhibits manual mode.<br>• Inhibits i-stop control.<br>• Inhibits AAS. |
| **POSSIBLE CAUSE** | • Oil pressure switch No.3 malfunction |
| **SYSTEM WIRING DIAGRAM** | Not applicable |

**Diagnostic procedure**

| STEP | INSPECTION | | ACTION |
|---|---|---|---|
| 1 | **VERIFY DTC OUTPUT STATUS**<br>• Is the DTC P1738:00 also present? | Yes | Go to the applicable DTC inspection.<br>(See DTC P1738:00 [TCM (CW6A-EL)].) |
| | | No | Go to the next step. |
| 2 | **RECORD VEHICLE STATUS WHEN DTC WAS DETECTED TO UTILIZE WITH REPEATABILITY VERIFICATION**<br><br>**Note**<br>• Recording can be facilitated using the screen capture of the PC function.<br><br>• Record the freeze frame data/snap shot data. | — | Go to the next step. |
| 3 | **VERIFY RELATED SERVICE INFORMATION AVAILABILITY**<br>• Verify related Service Information availability.<br>• Is any related Service Information available? | Yes | Perform repair or diagnosis according to the available Service Information.<br>• If the vehicle is not repaired, go to the next step. |
| | | No | Go to the next step. |
| 4 | **PERFORM ON-BOARD DIAGNOSTIC TEST**<br>• Perform the following procedure to ensure that the DTC has been resolved:<br>1. Start the engine.<br>2. Verify that the ATF temperature is **55 °C {131 °F} or more**.<br>• Perform the on-board diagnostic test.<br>(See ON-BOARD DIAGNOSTIC TEST MODE [TCM (CW6A-EL)].)<br>• Is the DTC P0872:00 present? | Yes | Replace the oil pressure switch A, then go to the next step.<br>(See OIL PRESSURE SWITCH REPLACEMENT [CW6A-EL])<br>• Drive the vehicle to check it, and if there is no problem then the DTC troubleshooting is complete. |
| | | No | No DTCs are displayed:<br>If a DTC other than the one indicated on the left is displayed:<br>• Go to the applicable DTC inspection.<br>(See ON-BOARD DIAGNOSTIC SYSTEM DTC TABLE [TCM (CW6A-EL)].) |

| STEP | INSPECTION | | ACTION |
|---|---|---|---|
| 5 | **RE-PERFORM ON-BOARD DIAGNOSTIC TEST**<br>• Perform the following procedure to ensure that the DTC has been resolved:<br>1. Start the engine.<br>2. Verify that the ATF temperature is **55 °C {131 °F} or more**.<br>• Perform the on-board diagnostic test. (See ON-BOARD DIAGNOSTIC TEST MODE [TCM (CW6A-EL)].)<br>• Are any DTCs present? | Yes | Go to the applicable DTC inspection. (See ON-BOARD DIAGNOSTIC SYSTEM DTC TABLE [TCM (CW6A-EL)].) |
| | | No | DTC troubleshooting completed. |