DTC U0073:00, U0100:00, U0121:00, U0131:00, U0155:00, U0214:00 [TCM (CW6A-EL)]

id0502p4905900

DTC U0073:00	CAN system communication error (HS CAN)
DETECTION CONDITION	• Under the following condition, a communication error (HS CAN) occurs: — Battery voltage is **10 V or more**.
FAIL-SAFE FUNCTION	• Inhibits learning control. • Inhibits i-stop control. • Inhibits AAS.
POSSIBLE CAUSE	• CAN bus communication line malfunction (HS CAN) • TCM malfunction
SYSTEM WIRING DIAGRAM	Not applicable

DTC U0100:00	Communication error to PCM (HS CAN)
DETECTION CONDITION	• Under the following condition, the TCM cannot receive the signal from PCM (HS CAN): — Battery voltage is **10 V or more**.
FAIL-SAFE FUNCTION	• Inhibits learning control. • Inhibits i-stop control. • Inhibits AAS.
POSSIBLE CAUSE	• CAN communication line malfunction between PCM and TCM (HS CAN) • TCM malfunction
SYSTEM WIRING DIAGRAM	Not applicable

DTC U0121:00	Communication error to ABS HU/CM (with ABS)/DSC HU/CM (with DSC)
DETECTION CONDITION	• Under the following condition, the TCM cannot receive the signal from ABS HU/CM (with ABS)/DSC HU/CM (with DSC): — Battery voltage is **10 V or more**.
FAIL-SAFE FUNCTION	• Inhibits learning control. • Inhibits i-stop control. • Inhibits AAS.
POSSIBLE CAUSE	• CAN communication line malfunction between TCM and ABS HU/CM (with ABS)/DSC HU/CM (with DSC) • TCM malfunction
SYSTEM WIRING DIAGRAM	Not applicable

DTC U0131:00	Communication error to EPS control module
DETECTION CONDITION	• Under the following condition, the TCM cannot receive the signal from EPS control module: — Battery voltage is **10 V or more**.
FAIL-SAFE FUNCTION	• Inhibits learning control. • Inhibits i-stop control.
POSSIBLE CAUSE	• CAN communication line malfunction between TCM and EPS control module • TCM malfunction
SYSTEM WIRING DIAGRAM	Not applicable

DTC U0155:00	Communication error to instrument cluster
DETECTION CONDITION	• Under the following condition, the TCM cannot receive the signal from instrument cluster: — Battery voltage is **10 V or more**.
FAIL-SAFE FUNCTION	• Inhibits learning control. • Inhibits manual mode. • Inhibits i-stop control.

DTC U0155:00	Communication error to instrument cluster
POSSIBLE CAUSE	• CAN communication line malfunction between TCM and instrument cluster • TCM malfunction
SYSTEM WIRING DIAGRAM	Not applicable

DTC U0214:00	Communication error to start stop unit
DETECTION CONDITION	• Under the following condition, the TCM cannot receive the signal from start stop unit: — Battery voltage is **10 V or more**.
FAIL-SAFE FUNCTION	• Inhibits direct mode.
POSSIBLE CAUSE	• CAN communication line malfunction between TCM and start stop unit • TCM malfunction
SYSTEM WIRING DIAGRAM	Not applicable

Diagnostic Procedure

- Inspect according to the diagnostic procedure in ON-BOARD DIAGNOSTIC [MULTIPLEX COMMUNICATION SYSTEM]. (See FOREWORD [SKYACTIV-G 1.3, SKYACTIV-G 1.5 (R.H.D.)].) (See FOREWORD [SKYACTIV-G 1.5 (L.H.D.)].)