DTC P2712:00 [TCM (CW6A-EL)]

id0502p4960500

DTC P2712:00	**Oil pump shift valve stuck**
DETECTION CONDITION	• Under the following conditions, oil pressure switch No.1 OFF output continues for **10 s**: — During i-stop operation — Selector lever position is D or N position. — During electric AT oil pump operation — Oil pressure switch, low clutch and transaxle range sensor are normal. — Rate of speed change normal
FAIL-SAFE FUNCTION	• Inhibits i-stop control.
POSSIBLE CAUSE	• Oil pump shift valve (hydraulic passage switching valve in control valve body) stuck • ATF leakage from low clutch circuit
SYSTEM WIRING DIAGRAM	Not applicable

Diagnostic procedure

STEP	INSPECTION		ACTION
1	**VERIFY RELATED SERVICE INFORMATION AVAILABILITY** • Verify related Service Information availability. • Is any related Service Information available?	Yes	Perform repair or diagnosis according to the available Service Information. • If the vehicle is not repaired, go to the next step.
		No	Go to the next step.
2	**VERIFY DTC TROUBLESHOOTING COMPLETED** • Clear the DTC using the M-MDS. (See ON-BOARD DIAGNOSTIC SYSTEM DTC INSPECTION [TCM (CW6A-EL)].) • Perform the following procedure to ensure that the DTC has been resolved: 1. Operates the i-stop. • Perform the DTC inspection using the M-MDS. (See ON-BOARD DIAGNOSTIC SYSTEM DTC INSPECTION [TCM (CW6A-EL)].) • Are any DTCs present?	Yes	Go to the next step.
		No	DTC troubleshooting completed.
3	**VERIFY THAT THE TIME LAG HAS NOT INCREASED** • Perform the "Time Lag Test". (See MECHANICAL SYSTEM TEST [CW6A-EL].) • Is the time lag when selecting N to D larger than the specification?	Yes	Replace the automatic transaxle. (See AUTOMATIC TRANSAXLE REMOVAL/INSTALLATION [CW6A-EL].)
		No	Replace the control valve body. (See CONTROL VALVE BODY REMOVAL/INSTALLATION [CW6A-EL].)